

Expiration Date: **6/25/2009**

Certificate Number: 7020062508MO113731

Training Date: **6/25/2008**

Missouri State Certificate for Asbestos Related Occupations

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


Berkeley R. Hall

has successfully completed the requirements for certification as a INSPECTOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/17/2008

Date


Director of Air Pollution Control Program



Cert # MO1113731
E.A.R. 6/25/09

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School
2803 E. 51st Street

Inspector: Berkeley Hall
Inspection Date: 12/9/08

Building: 001 Room: T-5 Drawing Group Code: 16 USA: - 0" OD Quantity: 1 SF
Floor: T Tunnel Material: Debris
Record No.: **6400031** Comment: (1992) Debris is wrapped paper pipe covering

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		<input checked="" type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input checked="" type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 106 Drawing Group Code: 07 USA: 71 4" OD Quantity: 3 EA
Floor: G Classroom Material: Insulation, MJP on Tar Lined Pipe
Record No.: **6400369** Comment: (1992) Domestic hot water-above ceiling

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		<input checked="" type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 106 Drawing Group Code: 07 USA: 73 4" OD Quantity: 7 EA
Floor: G Classroom Material: Insulation, MJP on Tar Lined Pipe
Record No.: **6400368** Comment: (1992) Domestic cold water-above ceiling

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		<input checked="" type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School
2803 E. 51st Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: 107	Drawing Group Code: 07	USA: 73	4" OD Quantity: 5 EA
Floor: G Classroom	Material: Insulation, MJP on Tar Lined Pipe		
Record No.: 6400312	Comment: (1992) Domestic cold water-above ceiling		
Room 104			
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
	<input checked="" type="radio"/> Friable <input type="radio"/> Covering		
	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	Justification:		
	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		
	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____			<input type="radio"/> Potential for Damage
			<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 107	Drawing Group Code: 07	USA: 71	4" OD Quantity: 5 EA
Floor: G Classroom	Material: Insulation, MJP on Tar Lined Pipe		
Record No.: 6400313	Comment: (1992) Domestic hot water-above ceiling		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
	<input checked="" type="radio"/> Friable <input type="radio"/> Covering		
	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	Justification:		
	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		
	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____			<input type="radio"/> Potential for Damage
			<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 114	Drawing Group Code: 10	USA: 22	0" OD Quantity: 140 SF
Floor: G Boiler Room	Material: Brick, Fire		
Record No.: 6400092	Comment: (1992) -		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
	<input type="radio"/> Friable <input type="radio"/> Covering		
	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	Justification:		
	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		
	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____			<input type="radio"/> Potential for Damage
			<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School
2803 E. 51st Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: 114	Drawing Group Code: 09	USA: 34	0" OD Quantity: 1 EA
Floor: G Boiler Room	Material: Insulation, Fire Door		
Record No.: 6400141	Comment: (1992) -		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input checked="" type="radio"/> Not Assessable		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering		
Justification:	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
<input type="radio"/> Blistering	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Physical Damage	<input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 128	Drawing Group Code: 02	USA: 07	0" OD Quantity: 25 SF
Floor: G Vestibule	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6400435	Comment: (1992)		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering		
Justification:	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
<input type="radio"/> Blistering	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Physical Damage	<input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 129	Drawing Group Code: 09	USA: 62	0" OD Quantity: 4 EA
Floor: G Corridor	Material: Insulation, Fire Door		
Record No.: 6400306	Comment: (1992) -		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input checked="" type="radio"/> Not Assessable		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering		
Justification:	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
<input type="radio"/> Blistering	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Physical Damage	<input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School
2803 E. 51st Street

Inspector: _____

Inspection Date: _____

Building: 001	Room: 296-210	Drawing Group Code: 07	USA: 73	4" OD Quantity: 2 EA
Floor: 1	Classroom	Material: Insulation, MJP on Tar Lined Pipe		
Record No.: 6400339	Comment: (1992) Domestic cold water-above ceiling			
Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input checked="" type="radio"/> Friable <input type="radio"/> Covering		
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged		
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage		
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage		

Building: 001	Room: 206	Drawing Group Code: 07	USA: 71	4" OD Quantity: 2 EA
Floor: 1	Classroom	Material: Insulation, MJP on Tar Lined Pipe		
Record No.: 6400370	Comment: (1992) Domestic hot water-above ceiling			
Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable		
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input checked="" type="radio"/> Friable <input type="radio"/> Covering		
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged		
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage		
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage		

Building: 001	Room: 207	Drawing Group Code: 09	USA: 62	0" OD Quantity: 4 EA
Floor: 1	Corridor	Material: Insulation, Fire Door		
Record No.: 6400371	Comment: (1992) -			
Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input checked="" type="radio"/> Not Assessable		
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering		
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged		
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage		
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage		

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School

Inspector: _____

2803 E. 51st Street

Inspection Date: _____

Building: 001 Room: 208 Drawing Group Code: 07 USA: 73 4" OD Quantity: 2 EA
 Floor: 1 Classroom Material: Insulation, MJP on Tar Lined Pipe
 Record No.: **6400334** Comment: (1992) Domestic cold water-above ceiling

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input checked="" type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	

Building: 001 Room: 208 Drawing Group Code: 07 USA: 71 4" OD Quantity: 2 EA
 Floor: 1 Classroom Material: Insulation, MJP on Tar Lined Pipe
 Record No.: **6400380** Comment: (1992) Domestic hot water-above ceiling

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input checked="" type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	

Building: 001 Room: A-1 Drawing Group Code: 13 USA: 58 0" OD Quantity: 1 SF
 Floor: 1 Attic Material: Cloth, Vibration Joint
 Record No.: **6400300** Comment: (1992) Green

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	

KCMSD 2008 Triennial Re-inspection

640 / Graceland Elementary School
2803 E. 51st Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 300	Drawing Group Code: 09	USA: 62 0" OD Quantity: 2 EA
Floor: 2 Corridor	Material: Insulation, Fire Door	
Record No.: 6400349	Comment: (1992) -	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input checked="" type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		

Building: 001 Room: 305	Drawing Group Code: 07	USA: 74 10" OD Quantity: 8 EA
Floor: 2 Library	Material: Insulation, MJP on Non-Suspect Pipe	
Record No.: 6400357	Comment: (1992) Roof drain pipe	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input checked="" type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		

Building: 001 Room: 312	Drawing Group Code: 07	USA: 74 10" OD Quantity: 3 EA
Floor: 2 Classroom	Material: Insulation, MJP on Non-Suspect Pipe	
Record No.: 6400361	Comment: (1992) Roof drain pipe	

Behind Freshed Plaster wall

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input checked="" type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		