

Expiration Date: **6/25/2009**

Certificate Number: 7020062508MO113731

Training Date: **6/25/2008**

Missouri State Certificate for Asbestos Related Occupations

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


Berkeley R. Hall

has successfully completed the requirements for certification as a INSPECTOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/17/2008

Date


Director of Air Pollution Control Program



Conf # MO 11 13731
 Exp. 6/25/09

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
 1300 E. 75th Street

Inspector: Bon Peter
 Inspection Date: 12-9-08

Building: 001 Room: 004	Drawing Group Code: 11	USA: 11	0" OD Quantity: 4 SF
Floor: T Mechanical Room	Material: Mastic, Floor Tile		
Record No.: 8300245	Comment: (1992) -		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable	
		<input type="radio"/> Friable <input type="radio"/> Covering	
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure	
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input checked="" type="radio"/> Intact and Undamaged	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Cracking <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Damage	
<input type="radio"/> Vibration		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Other: _____			

Building: 001 Room: 101	Drawing Group Code: 09	USA: 22	0" OD Quantity: 1 EA
Floor: G Art Room	Material: Insulation, Fire Door		
Record No.: 8300351	Comment: (1992) -		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input checked="" type="radio"/> Not Assessable	
		<input type="radio"/> Friable <input checked="" type="radio"/> Covering	
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Cracking <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Damage	
<input type="radio"/> Vibration		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Other: _____			

Building: 001 Room: 101A	Drawing Group Code: 09	USA: 22	0" OD Quantity: 1 EA
Floor: G Storage	Material: Insulation, Fire Door		
Record No.: 8300350	Comment: (1992) -		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input checked="" type="radio"/> Not Assessable	
		<input type="radio"/> Friable <input checked="" type="radio"/> Covering	
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Cracking <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		<input type="radio"/> Potential for Damage	
<input type="radio"/> Vibration		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Other: _____			

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 103 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Girl's Restroom Material: Insulation, Fire Door
 Record No.: **8300281** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 104 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Classroom Material: Insulation, Fire Door
 Record No.: **8300329** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 105 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
 Floor: G Vestibule Material: Insulation, Fire Door
 Record No.: **8300315** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 106 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
 Floor: G Corridor Material: Insulation, Fire Door

Record No.: **8300311** Comment: (1992) North end

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: _____

Building: 001 Room: 106A Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Storage Material: Insulation, Fire Door

Record No.: **8300156** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: _____

Building: 001 Room: 106B Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Storage Material: Insulation, Fire Door

Record No.: **8300029** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: _____

KCMUSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 106C Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Janitor's Closet Material: Insulation, Fire Door

Record No.: **8300092** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Friable Not Assessable
 Not Found Definitely Not Present Non-friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Intact and Undamaged Enclosure
 Missing TSI Jackeling Student Accessible Damaged (<10%)
 Physical Damage Activity / Movement Significantly Damaged (>10%)
 Deterioration Forced Airstream Potential for Damage
 Water Damage <10% Exposed Surface Area Potential for Significant Damage
 Loose >10% Exposed Surface Area Potential for Significant Damage

Justification:

Blistering
 Cracking
 Vibration
 Other: _____

Building: 001 Room: 107 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA

Floor: G Corridor Material: Insulation, Fire Door

Record No.: **8300305** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Friable Not Assessable
 Not Found Definitely Not Present Non-friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Intact and Undamaged Enclosure
 Missing TSI Jackeling Student Accessible Damaged (<10%)
 Physical Damage Activity / Movement Significantly Damaged (>10%)
 Deterioration Forced Airstream Potential for Damage
 Water Damage <10% Exposed Surface Area Potential for Significant Damage
 Loose >10% Exposed Surface Area Potential for Significant Damage

Justification:

Blistering
 Cracking
 Vibration
 Other: _____

Building: 001 Room: 108A Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA

Floor: G Vestibule Material: Insulation, Fire Door

Record No.: **8300440** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Friable Not Assessable
 Not Found Definitely Not Present Non-friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Intact and Undamaged Enclosure
 Missing TSI Jackeling Student Accessible Damaged (<10%)
 Physical Damage Activity / Movement Significantly Damaged (>10%)
 Deterioration Forced Airstream Potential for Damage
 Water Damage <10% Exposed Surface Area Potential for Significant Damage
 Loose >10% Exposed Surface Area Potential for Significant Damage

Justification:

Blistering
 Cracking
 Vibration
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 109 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
 Floor: G Passage Material: Insulation, Fire Door

Record No.: **8300196** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 112 Drawing Group Code: 09 USA: 22 0" OD Quantity: 3 EA
 Floor: G Kitchen Material: Insulation, Fire Door

Record No.: **8300063** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Friable Not Assessable
 Non-friable Covering
 Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 113 Drawing Group Code: 09 USA: 22 0" OD Quantity: 4 EA
 Floor: G Cafeteria Material: Insulation, Fire Door

Record No.: **8300182** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Friable Not Assessable
 Non-friable Covering
 Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

1300 E. 75th Street

Inspector: _____
 Inspection Date: _____

Building: 001 Room: 114 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Special Education Material: Insulation, Fire Door

Record No.: **8300058** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

Building: 001 Room: 115 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Classroom Material: Insulation, Fire Door

Record No.: **8300184** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

Building: 001 Room: 116 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Passage Material: Insulation, Fire Door

Record No.: **8300288** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 117A

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: G Storage

Material: Insulation, Fire Door

Record No.: **8300166**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Building: 001 Room: 118

Drawing Group Code: 13

USA: 05

0" OD Quantity: 2 SF

Floor: G Mechanical Room

Material: Cloth, Vibration Joint

Record No.: **8300512**

Comment: (1992) Rubber

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Building: 001 Room: 118

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: G Mechanical Room

Material: Insulation, Fire Door

Record No.: **8300287**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 119 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Gym Balcony Material: Insulation, Fire Door

Record No.: **8300292** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 120 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Gym Balcony Material: Insulation, Fire Door

Record No.: **8300171** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 121 Drawing Group Code: 13 USA: 05 0" OD Quantity: 2 SF

Floor: G Mechanical Room Material: Cloth, Vibration Joint

Record No.: **8300425** Comment: (1992) Rubber

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 121

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: G Mechanical Room

Material: Insulation, Fire Door

Record No.: **8300069**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

- Missing TSI Jacketing Student Accessible
- Physical Damage Activity / Movement
- Deterioration Forced Airstream
- Cracking Water Damage <10% Exposed Surface Area
- Vibration Loose >10% Exposed Surface Area
- Other: _____

Building: 001 Room: 122

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: G Storage

Material: Insulation, Fire Door

Record No.: **8300049**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

- Missing TSI Jacketing Student Accessible
- Physical Damage Activity / Movement
- Deterioration Forced Airstream
- Cracking Water Damage <10% Exposed Surface Area
- Vibration Loose >10% Exposed Surface Area
- Other: _____

Building: 001 Room: 123

Drawing Group Code: 09

USA: 22

0" OD Quantity: 2 EA

Floor: G Gym

Material: Insulation, Fire Door

Record No.: **8300169**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

- Blistering Missing TSI Jacketing Student Accessible
- Cracking Physical Damage Activity / Movement
- Vibration Deterioration Forced Airstream
- Other: _____ Water Damage <10% Exposed Surface Area
- Other: _____ Loose >10% Exposed Surface Area

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 125 Drawing Group Code: 13 USA: 05 0" OD Quantity: 1 SF

Floor: G Storage Material: Cloth, Vibration Joint

Record No.: **8300390** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable

Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area) Friable Covering

Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible Intact and Undamaged
- Physical Damage Activity / Movement Damaged (<10%)
- Deterioration Forced Airstream Significantly Damaged (>10%)
- Cracking Water Damage <10% Exposed Surface Area Potential for Damage
- Vibration Loose >10% Exposed Surface Area Potential for Significant Damage
- Other: _____

Building: 001 Room: 129 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Office Material: Insulation, Fire Door

Record No.: **8300168** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable

Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area) Friable Covering

Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible Intact and Undamaged
- Physical Damage Activity / Movement Damaged (<10%)
- Deterioration Forced Airstream Significantly Damaged (>10%)
- Cracking Water Damage <10% Exposed Surface Area Potential for Damage
- Vibration Loose >10% Exposed Surface Area Potential for Significant Damage
- Other: _____

Building: 001 Room: 130 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: G Office Material: Insulation, Fire Door

Record No.: **8300167** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable

Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area) Friable Covering

Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible Intact and Undamaged
- Physical Damage Activity / Movement Damaged (<10%)
- Deterioration Forced Airstream Significantly Damaged (>10%)
- Cracking Water Damage <10% Exposed Surface Area Potential for Damage
- Vibration Loose >10% Exposed Surface Area Potential for Significant Damage
- Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: M-100 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Teacher's Lounge Material: Insulation, Fire Door
 Record No.: **8300409** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: M-100A Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Restroom Material: Insulation, Fire Door
 Record No.: **8300298** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: M-101 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Restroom Material: Insulation, Fire Door
 Record No.: **8300296** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: M-103 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: G Speech Room Material: Insulation, Fire Door
 Record No.: **8300047** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: S-4 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
 Floor: G Stairs Material: Insulation, Fire Door
 Record No.: **8300020** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 200 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 1 Computer Lab Material: Insulation, Fire Door
 Record No.: **8300247** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 201 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Classroom Material: Insulation, Fire Door

Record No.: **8300081** Comment: (1992) -

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)
 Definitely Not Present

Assessment: Not Assessable

- Friable Covering
 Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

- Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 202 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Computer Lab Material: Insulation, Fire Door

Record No.: **8300498** Comment: (1992) -

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)
 Definitely Not Present

Assessment: Not Assessable

- Friable Covering
 Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

- Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 203 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA

Floor: 1 Corridor Material: Insulation, Fire Door

Record No.: **8300446** Comment: (1992) -

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)
 Definitely Not Present

Assessment: Not Assessable

- Friable Covering
 Non-friable Enclosure

Justification:

- Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

- Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 205 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 1 Vestibule Material: Insulation, Fire Door
 Record No.: **8300341** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 206 Drawing Group Code: 09 USA: 22 0" OD Quantity: 4 EA
 Floor: 1 Auditorium Material: Insulation, Fire Door
 Record No.: **8300465** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 209 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 1 Classroom Material: Insulation, Fire Door
 Record No.: **8300162** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible
 Cracking Physical Damage Activity / Movement
 Vibration Water Damage Forced Airstream
 Loose <10% Exposed Surface Area
 >10% Exposed Surface Area
 Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School

Inspector: _____

1300 E. 75th Street

Inspection Date: _____

Building: 001 Room: 210

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: 1 Office

Material: Insulation, Fire Door

Record No.: **8300422**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Building: 001 Room: 211

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: 1 Classroom

Material: Insulation, Fire Door

Record No.: **8300075**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Building: 001 Room: 212

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: 1 Office

Material: Insulation, Fire Door

Record No.: **8300308**

Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

KCMUSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 213 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Classroom Material: Insulation, Fire Door

Record No.: **8300091** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable
 Not Found Definitely Not Present
 Friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Non-friable Enclosure

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Potential for Significant Damage
 Other: _____

Building: 001 Room: 215 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Classroom Material: Insulation, Fire Door

Record No.: **8300085** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable
 Not Found Definitely Not Present
 Friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Non-friable Enclosure

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Potential for Significant Damage
 Other: _____

Building: 001 Room: 216 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Waiting Room Material: Insulation, Fire Door

Record No.: **8300530** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) **Assessment:** Not Assessable
 Not Found Definitely Not Present
 Friable Covering
 Comment Fit Material? Yes No (Explain In Comment Area) Non-friable Enclosure

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001	Room: 216A	Drawing Group Code: 09	USA: 22	0" OD Quantity: 1 EA
Floor: 1	Closest	Material: Insulation, Fire Door		
Record No.: 8300310	Comment: (1992) -			

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes Not Found Definitely Not Present

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable

Friable Covering

Non-friable Enclosure

Intact and Undamaged

Damaged (<10%) Significantly Damaged (>10%)

Potential for Damage Potential for Significant Damage

Building: 001	Room: 217	Drawing Group Code: 09	USA: 22	0" OD Quantity: 2 EA
Floor: 1	Office	Material: Insulation, Fire Door		
Record No.: 8300276	Comment: (1992) -			

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes Not Found Definitely Not Present

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable

Friable Covering

Non-friable Enclosure

Intact and Undamaged

Damaged (<10%) Significantly Damaged (>10%)

Potential for Damage Potential for Significant Damage

Building: 001	Room: 218	Drawing Group Code: 09	USA: 22	0" OD Quantity: 1 EA
Floor: 1	Office	Material: Insulation, Fire Door		
Record No.: 8300387	Comment: (1992) -			

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes Not Found Definitely Not Present

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable

Friable Covering

Non-friable Enclosure

Intact and Undamaged

Damaged (<10%) Significantly Damaged (>10%)

Potential for Damage Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 219 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Office Material: Insulation, Fire Door

Record No.: **8300375** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Non-friable Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 220 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Nurse's Office Material: Insulation, Fire Door

Record No.: **8300470** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Physical Damage Deterioration Cracking Vibration Loose Other: _____

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Non-friable Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 221A Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA

Floor: 1 Restroom Material: Insulation, Fire Door

Record No.: **8300160** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Blistering Physical Damage Deterioration Cracking Vibration Loose Other: _____

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Non-friable Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 222 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 1 Work Area Material: Insulation, Fire Door

Record No.: **8300264** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fil Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible

Cracking Physical Damage Activity / Movement

Vibration Water Damage Forced Airstream

Other: Loose <10% Exposed Surface Area >10% Exposed Surface Area

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 223 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 1 Restroom Material: Insulation, Fire Door

Record No.: **8300524** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fil Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible

Cracking Physical Damage Activity / Movement

Vibration Water Damage Forced Airstream

Other: Loose <10% Exposed Surface Area >10% Exposed Surface Area

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 224 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
Floor: 1 Corridor Material: Insulation, Fire Door

Record No.: **8300525** Comment: (1992) North end

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fil Material? Yes No (Explain In Comment Area)

Justification:

Blistering Missing TSI Jacketing Student Accessible

Cracking Physical Damage Activity / Movement

Vibration Water Damage Forced Airstream

Other: Loose <10% Exposed Surface Area >10% Exposed Surface Area

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 300 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 2 Math Room Material: Insulation, Fire Door
 Record No.: **8300393** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 301 Drawing Group Code: 09 USA: 22 0" OD Quantity: 2 EA
 Floor: 2 Corridor Material: Insulation, Fire Door
 Record No.: **8300246** Comment: (1992) East end

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 302 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 2 Science Lab Material: Insulation, Fire Door
 Record No.: **8300275** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jacketing Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 304

Drawing Group Code: 09

USA: 22

0" OD Quantity: 3 EA

Floor: 2 Library

Material: Insulation, Fire Door

Record No.: **8300248**

Comment: (1992) -

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit. Material? Yes No (Explain in Comment Area)
 Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Cracking
- Vibration
- Loose

- Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 305

Drawing Group Code: 09

USA: 22

0" OD Quantity: 1 EA

Floor: 2 Work Area

Material: Insulation, Fire Door

Record No.: **8300429**

Comment: (1992) -

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit. Material? Yes No (Explain in Comment Area)
 Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Cracking
- Vibration
- Loose
- Other:

- Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 306

Drawing Group Code: 09

USA: 22

0" OD Quantity: 2 EA

Floor: 2 Corridor

Material: Insulation, Fire Door

Record No.: **8300138**

Comment: (1992) North end

- Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit. Material? Yes No (Explain in Comment Area)
 Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Cracking
- Vibration
- Loose
- Other:

- Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 307 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Classroom Material: Insulation, Fire Door

Record No.: **8300220** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

Building: 001 Room: 309 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Classroom Material: Insulation, Fire Door

Record No.: **8300129** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

Building: 001 Room: 310 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Boy's Restroom Material: Insulation, Fire Door

Record No.: **8300352** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking <10% Exposed Surface Area
 Vibration >10% Exposed Surface Area
 Loose Potential for Significant Damage
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 311 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Classroom Material: Insulation, Fire Door

Record No.: **8300052** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Friable Not Assessable
 Non-friable Covering
 Intact and Undamaged Enclosure
 Damaged (<10%) Significantly Damaged (>10%)
 Potential for Damage Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 312 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Girl's Restroom Material: Insulation, Fire Door

Record No.: **8300014** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Friable Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 313 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Classroom Material: Insulation, Fire Door

Record No.: **8300356** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Assessment: Friable Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 315 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Classroom Material: Insulation, Fire Door

Record No.: **8300112** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 316 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Storage Material: Insulation, Fire Door

Record No.: **8300068** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: 317 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
Floor: 2 Stairs to Attic Material: Insulation, Fire Door

Record No.: **8300071** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:

Missing TSI Jackeling Student Accessible

Physical Damage Activity / Movement

Deterioration Forced Airstream

Cracking Water Damage <10% Exposed Surface Area

Vibration Loose >10% Exposed Surface Area

Other: _____

Assessment: Not Assessable Friable Covering Non-friable Enclosure Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

830 / Marborough School
1300 E. 75th Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 318 Drawing Group Code: 09 USA: 22 0" OD Quantity: 1 EA
 Floor: 2 Water-Closet Material: Insulation, Fire Door
 Record No.: **83000054** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: A-5 Drawing Group Code: 13 USA: 05 0" OD Quantity: 2 SF
 Floor: A Attic Space Material: Cloth, Vibration Joint

Record No.: **8300161** Comment: (1992) Rubber

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Comment Fit Material? Yes No (Explain In Comment Area)

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Loose >10% Exposed Surface Area
 Other: _____