

Expiration Date: 10/28/2009

Certificate Number: 7020102108MOSR11347

Training Date: 10/21/2008

Missouri State Certificate for Asbestos Related Occupations

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


Patricia J. Garcia

has successfully completed the requirements for certification as a SUPERVISOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/28/2008

Date


Director of Air Pollution Control Program



CERTIFICATION NUMBER: 7020102108MOSR11347

THIS CERTIFIES

Patricia J. Garcia

HAS COMPLETED THE CERTIFICATION REQUIREMENTS FOR

Supervisor

APPROVED: 10/28/2008

EXPIRES: 10/28/2009

 Missouri
Department of
Natural Resources


Director of Air Pollution Control Program



KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center
5915 Park

Inspector: Pat Garcia
Inspection Date: 10-29-08

Building: 001 Room: B-7 Drawing Group Code: 08 USA: 28 0" OD Quantity: 2 LF
 Floor: B Storage Material: Wiring
 Record No.: **6700295** Comment: (1992) On spotlight

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 001 Drawing Group Code: 02 USA: 06 0" OD Quantity: 600 SF
 Floor: G Classroom Material: Tile, Vinyl Floor, 9X9
 Record No.: **6700040** Comment: (1992) Brown

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 007 Drawing Group Code: 02 USA: 23 0" OD Quantity: 330 SF
 Floor: G Office Material: Tile, Vinyl Floor, 9X9
 Record No.: **6700361** Comment: (1992) Gray

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification:
 Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: Broken and missing tiles

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center

Inspector: Patricia Garcia

5915 Park

Inspection Date: 10/29/08

Building: 001 Room: 008 Drawing Group Code: 02 USA: 23 0" OD Quantity: 260 SF
 Floor: G Office Material: Tile, Vinyl Floor, 9X9
 Record No.: 6700387 Comment: (1992) Gray

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Comment Fit Material? Yes No (Explain In Comment Area)
 Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 018 Drawing Group Code: 02 USA: 22 0" OD Quantity: 45 SF
 Floor: G Vestibule Material: Tile, Vinyl Floor, 9X9
 Record No.: 6700349 Comment: (1992) Brown

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Comment Fit Material? Yes No (Explain In Comment Area)
 Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: UNUSUAL CARPET
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Building: 001 Room: 019 Drawing Group Code: 02 USA: 22 0" OD Quantity: 300 SF
 Floor: G Teacher's Lounge Material: Tile, Vinyl Floor, 9X9
 Record No.: 6700353 Comment: (1992) Brown

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present
 Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Comment Fit Material? Yes No (Explain In Comment Area)
 Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: UNUSUAL CARPET
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center
5915 Park

Inspector: _____
Inspection Date: _____

Building: 001 Room: 020	Drawing Group Code: 10	USA: 29	0" OD Quantity: 5 SF
Floor: G Boiler Room	Material: Gasket		
Record No.: 6700298	Comment: (1992) White-stored on west wall		

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 020	Drawing Group Code: 09	USA: 33	0" OD Quantity: 1 EA
Floor: G Boiler Room	Material: Insulation, Fire Door		
Record No.: 6700300	Comment: (1992) -		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input checked="" type="radio"/> Not Assessable
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 020	Drawing Group Code: 05	USA: 34	0" OD Quantity: 600 SF
Floor: G Boiler Room	Material: Insulation, Poured-In		
Record No.: 6700301	Comment: (1992) Tar based material-on top of boiler		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center
5915 Park

Inspector: _____
Inspection Date: _____

Building: 001 Room: 020C	Drawing Group Code: 09	USA: 33 0" OD Quantity: 1 EA
Floor: G Catwalk Above	Material: Insulation, Fire Door	
Record No.: 6700304	Comment: (1992) -	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input checked="" type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 021	Drawing Group Code: 10	USA: 30 0" OD Quantity: 4 LF
Floor: G Fan Room	Material: Rope	
Record No.: 6700309	Comment: (1992) Mechanical packing-4 boxes	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 021	Drawing Group Code: 02	USA: 21 0" OD Quantity: 30 SF
Floor: G Fan Room	Material: Tile, Vinyl Floor, 9X9	
Record No.: 6700312	Comment: (1992) Carmel	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center

Inspector: Patricia Carlson

5915 Park

Inspection Date: 10/22/08

Building: 001 Room: 021G	Drawing Group Code: 13	USA: 31	0" OD Quantity: 3 SF
Floor: G Platform Above	Material: Cloth, Vibration Joint		
Record No.: 6700306	Comment: (1992) Canvas-1 unit		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification:	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input checked="" type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: 103	Drawing Group Code: 02	USA: 24	0" OD Quantity: 650 SF
Floor: 1 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6700448	Comment: (1992) Green		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification:	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>9x9 TILE UNDER CARPET & 12"X12" FLOOR TILE (WHITE)</u>	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 106	Drawing Group Code: 02	USA: 24	0" OD Quantity: 650 SF
Floor: 1 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6700425	Comment: (1992) Green		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification:	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>9' x 9" UNDER CARPET & 12" X 12" FLOOR TILE (WHITE)</u>	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center
5915 Park

Inspector: PATRICIA GARCIA
Inspection Date: 10/29/08

Building: 001 Room: 107	Drawing Group Code: 02	USA: 24	0" OD Quantity: 650 SF
Floor: 1 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6700468	Comment: (1992) Green		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>9" X 9" UNDER CARPET & 12" X 12" WHITE FLOOR TILE</u>	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 111	Drawing Group Code: 02	USA: 06	0" OD Quantity: 120 SF
Floor: 1 Office	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6700094	Comment: (1992) Brown		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>UNDER CARPET; FLOOR TILE GREEN 9" X 9" VS. BROWN</u>	<input checked="" type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 112	Drawing Group Code: 02	USA: 06	0" OD Quantity: 150 SF
Floor: 1 Office	Material: Tile, Vinyl Floor, 9X9		
Record No.: 6700098	Comment: (1992) Brown		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
Justification: <input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>COLOR OF 9" X 9" FLOOR TILE IS GREEN VS. BROWN</u>	<input checked="" type="radio"/> Potential for Damage
	<input checked="" type="radio"/> Potential for Significant Damage

NOT UNDER CARPET

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center

Inspector: PATRICIA GARCIA

5915 Park

Inspection Date: 10/29/08

Building: 001 Room: 205 Floor: 2 Classroom Record No.: 6700227 Comment: (1992) White	Drawing Group Code: 02 USA: 07 0" OD Quantity: 225 SF Material: Tile, Vinyl Floor, 9X9	
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area) <input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:		
<input type="radio"/> Blistering <input type="radio"/> Cracking <input type="radio"/> Vibration <input type="radio"/> Other: <u>RM NOW NURSERY STATION</u>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Student Accessible <input checked="" type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input checked="" type="radio"/> >10% Exposed Surface Area
Assessment:		
<input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input checked="" type="radio"/> Potential for Significant Damage		

Building: 001 Room: 222 Floor: 2 Classroom Record No.: 6700250 Comment: (1992) Gray	Drawing Group Code: 02 USA: 08 0" OD Quantity: 230 SF Material: Tile, Vinyl Floor, 9X9	
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area) <input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:		
<input type="radio"/> Blistering <input type="radio"/> Cracking <input type="radio"/> Vibration <input type="radio"/> Other: <u>9"X9" UNDUL CARPET</u>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Student Accessible <input checked="" type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area
Assessment:		
<input type="radio"/> Not Assessable <input type="radio"/> Friable <input checked="" type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage		

Building: 001 Room: 222A Floor: 2 Restroom Record No.: 6700249 Comment: (1992) Gray	Drawing Group Code: 02 USA: 08 0" OD Quantity: 30 SF Material: Tile, Vinyl Floor, 9X9	
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area) <input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:		
<input type="radio"/> Blistering <input type="radio"/> Cracking <input type="radio"/> Vibration <input type="radio"/> Other:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Student Accessible <input checked="" type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input checked="" type="radio"/> >10% Exposed Surface Area
Assessment:		
<input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input checked="" type="radio"/> Potential for Significant Damage		

KCMSD 2008 Triennial Re-inspection

670 / Pershing Early Childhood Center

Inspector: _____

5915 Park

Inspection Date: _____

Building: 001 Room: C221	Drawing Group Code: 09	USA: 33	0" OD	Quantity: 1 EA
Floor: 2 Chase	Material: Insulation, Fire Door			
Record No.: 6700540	Comment: (1992) -			
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable		
<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present		<input type="radio"/> Friable <input type="radio"/> Covering		
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Intact and Undamaged		
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage	
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Other: _____				

Building: 001 Room: A-1	Drawing Group Code: 13	USA: 10	0" OD	Quantity: 3 SF
Floor: A Attic Space	Material: Cloth, Vibration Joint			
Record No.: 6700259	Comment: (1992) Canvas-1 unit			
Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable		
<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input checked="" type="radio"/> Intact and Undamaged		
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input checked="" type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage	
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage	
<input type="radio"/> Other: <u>6 SF. of cloth, vibration joint.</u>				