



EXP. 10/28/09

## KCMSD 2008 Triennial Re-inspection

ATRICA COROCIE Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Room: 001 Drawing Group Code: 02 USA: 25 0" OD Quantity: 1574 SF Floor: Library Material: Tile, Vinvl Floor, Border/Trim Comment: (1992) Possible-unable to identify color or size Record 7200482 No.: 0 Yes  $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable Not Found O **Definitely Not Present** O Friable O Covering Comment Fit Material? 0 No (Explain In Comment Area) Ο Non-friable 0 Enclosure 0 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 Physical Damage **Activity / Movement**  $\circ$ Damaged (<10%) 0 0 0 О Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 0 0 О Cracking <10% Exposed Surface Area Potential for Damage Water Damage  $\circ$ >10% Exposed Surface Area О Potential for Significant Damage Vibration Loose 0 Other: LIBRURY CARPON a ROMONIOUN IN 1998-1999 Building: 001 Room: 002 Drawing Group Code: 09 USA: 32 0" OD Quantity: 1 EA Floor: Т **Boiler Room** Material: Insulation, Fire Door Comment: (1992) -Record 7200374 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** Friable Covering 0 No (Explain In Comment Area) Comment Fit Material? Yes O Non-friable O Enclosure 0 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 0 0 Blistering Deterioration 0 Forced Airstream Significantly Damaged (>10%) О Cracking О <10% Exposed Surface Area Potential for Damage Water Damage  $\circ$ О Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 004 Drawing Group Code: 02 USA: 25 0" OD Quantity: 252 SF Floor: Vestibule Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Possible-unable to identify color or size 7200501 No.: 0 Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: 0 Not Assessable Not Found O **Definitely Not Present** О O Friable Covering 0 Comment Fit Material? No (Explain In Comment Area) 0 Non-friable O Enclosure 0 0 Missing TSI Jacketing  $\circ$ Student Accessible Intact and Undamaged Justification: 0 О **Physical Damage** O **Activity / Movement** Damaged (<10%) 0  $\circ$ 0 Blistering Deterioration О Forced Airstream Significantly Damaged (>10%) Ο 0 O Cracking Water Damage <10% Exposed Surface Area Potential for Damage 0 Potential for Significant Damage Vibration >10% Exposed Surface Area Loose

AREA RUMODOWN IN 1995-1999

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Room: 125 Drawing Group Code: 09 USA: 32 0" OD Quantity: 6 EA Floor: Corridor Material: Insulation, Fire Door Record Comment: (1992) -7200111 No.. No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present $\bigcirc$ Friable Covering O No (Explain In Comment Area) Comment Fit Material? О $\bigcirc$ Enclosure Non-friable Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: O 0 Damaged (<10%) **Physical Damage** Activity / Movement 0 0 Forced Airstream Significantly Damaged (>10%) Blistering Deterioration <10% Exposed Surface Area Potential for Damage Cracking $\circ$ Water Damage Potential for Significant Damage $\bigcirc$ Vibration Loose >10% Exposed Surface Area Other: Building: 001 USA: 32 0"OD Quantity: 3 EA Room: 132 Drawing Group Code: 09 Floor: Vestibule Material: Insulation, Fire Door Comment: (1992) -Record 7200311 No.. No (Give approximate quantity in Comment Area) 0 Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present $\circ$ Friable Covering Comment Fit Material? O No (Explain In Comment Area) Ο O **Enclosure** Non-friable Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ 0 0 Damaged (<10%) Physical Damage Activity / Movement $\bigcirc$ O Forced Airstream $\circ$ Significantly Damaged (>10%) Deterioration Blistering $\circ$ Potential for Damage 0 <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area 0 Vibration Loose Other: USA: 05 4" OD Quantity: 6 LF Building: 001 Room: C124 Drawing Group Code: 06 Floor: Chase Material: Insulation, Pipe, Paper Record Comment: (1992) -7200141 No.: Yes No (Give approximate quantity in Comment Area) 0 Quantity Within 20%? Assessment: 0 Not Assessable Not Found O **Definitely Not Present** Friable $\bigcirc$ Covering $\circ$ No (Explain In Comment Area) Comment Fit Material? 0 0 Enclosure Non-friable 0 0 Missing TSI Jacketing $\circ$ Intact and Undamaged Student Accessible

 $\bigcirc$ 

0

0

Activity / Movement

<10% Exposed Surface Area

>10% Exposed Surface Area

Forced Airstream

0

0

 $\circ$ 

Damaged (<10%)

Potential for Damage

Significantly Damaged (>10%)

Potential for Significant Damage

0

Justification:

Blistering

Cracking

Vibration

Other:

 $\bigcirc$ 

0

0

 $\bigcirc$ 

**Physical Damage** 

Deterioration

Loose

Water Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes 0" OD Quantity: 677 SF USA: 26 Drawing Group Code: 02 Building: 001 Room: 201 Material: Tile, Vinyl Floor, 9X9 Floor: Classroom Comment: (1992) Beige Record 7200223 No.: No (Give approximate quantity in Comment Area) Assessment: O $\circ$ Quantity Within 20%? Not Assessable Not Found O Definitely Not Present 0 О Friable Covering 0 0 No (Explain In Comment Area) **Comment Fit Material?** Yes 0 0 Non-friable Enclosure 0 Intact and Undamaged Missing TSI Jacketing 0 0 Student Accessible Justification: 0 Damaged (<10%) $\circ$ 0 **Physical Damage** 'Activity / Movement $\circ$ Significantly Damaged (>10%) Forced Airstream 0 Deterioration Blistering Potential for Damage 0 <10% Exposed Surface Area $\bigcirc$ Water Damage 0 Cracking Potential for Significant Damage >10% Exposed Surface Area Loose Vibration Other: Drawing Group Code: 02 USA: 25 0" OD Quantity: 125 SF Building: 001 Room: 201 Material: Tile, Vinyl Floor, Border/Trim Floor: 2 Classroom Comment: (1992) Dark brown Record 7200222 No.. No (Give approximate quantity in Comment Area) Yes O Assessment: Quantity Within 20%? $\circ$ Not Assessable Not Found O Definitely Not Present Ο О Covering Friable No (Explain In Comment Area) Comment Fit Material? $\circ$ $\circ$ 0 Enclosure Non-friable O Intact and Undamaged 0 Student Accessible Missing TSI Jacketing Justification: 0 Damaged (<10%) 0 Activity / Movement 0 **Physical Damage** Significantly Damaged (>10%) $\bigcirc$ $\circ$ Deterioration Forced Airstream Blistering 0 Potential for Damage $\circ$ <10% Exposed Surface Area Water Damage Cracking Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: 0"OD Quantity: 592 SF Drawing Group Code: 02 USA: 08 Room: 202 Building: 001 Material: Tile, Vinyl Floor, 9X9 Floor: 2 Classroom Comment: (1992) Off-white/green Record 7200091 No.: No (Give approximate quantity in Comment Area) 0 Yes Assessment: Quantity Within 20%? 0 Not Assessable Not Found O **Definitely Not Present** $\circ$ $\circ$ $\bigcirc$ Covering Friable Comment Fit Material? O No (Explain In Comment Area) 0 Enclosure Non-friable Student Accessible Intact and Undamaged Missing TSI Jacketing Justification: $\circ$ Damaged (<10%) Activity / Movement $\bigcirc$ Physical Damage 0 Significantly Damaged (>10%) 0 Deterioration Forced Airstream Blistering 0 Potential for Damage 0 <10% Exposed Surface Area Water Damage $\circ$ Cracking Potential for Significant Damage >10% Exposed Surface Area $\bigcirc$

О

Vibration

Other:

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes USA: 10 0" OD Quantity: 116 SF Drawing Group Code: 02 Building: 001 Room: 202 Material: Tile, Vinyl Floor, Border/Trim Floor: Classroom Comment: (1992) Green Record 7200090 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\circ$ Not Assessable 0 Not Found O Definitely Not Present $\bigcirc$ Covering Friable O No (Explain In Comment Area) Comment Fit Material? Non-friable O **Enclosure** Student Accessible Intact and Undamaged Missing TSI Jacketing Justification: 0 Damaged (<10%) 0 **Activity / Movement Physical Damage** 0 Significantly Damaged (>10%) 0 Forced Airstream Deterioration Blistering Potential for Damage <10% Exposed Surface Area Ο $\circ$ Water Damage Cracking Potential for Significant Damage >10% Exposed Surface Area 0 Loose Vibration 0 Other: 0" OD Quantity: 11 SF USA: 10 Drawing Group Code: 02 Building: 001 Room: 202B Floor: Material: Tile, Vinyl Floor, Border/Trim Storage Comment: (1992) Green Record 7200065 arca Kept hocked No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present 0 Friable Covering

Justification  Blistering Cracking Vibration	n: 0 0 0	Missing TSI Jacketing Physical Damage Deterioration Water Damage Loose	Student Accessible Activity / Movement Forced Airstream <10% Exposed Surface Area >10% Exposed Surface Area	<ul> <li>Intact and Undamaged</li> <li>Damaged (&lt;10%)</li> <li>Significantly Damaged (&gt;10%)</li> <li>Potential for Damage</li> <li>Potential for Significant Damage</li> </ul>
Other:				
Floor: 2 Record 7200	Room: 203 Classroom	ont: (1992) Beige	Drawing Group Code: 02 Material: Tile, Vinyl Floor, 9X	USA: 26 0" OD Quantity: 699 SF
Quantity Within	20%?	O Not Found	approximate quantity in Comment Area)  Definitely Not Present in In Comment Area)	Assessment: Not Assessable Friable Covering Non-friable Enclosure

Student Accessible

Activity / Movement

<10% Exposed Surface Area

>10% Exposed Surface Area

Forced Airstream

O

0

Non-friable

Intact and Undamaged

Intact and Undamaged

Potential for Damage

Significantly Damaged (>10%)

Potential for Significant Damage

Damaged (<10%)

 $\bigcirc$ 

O

**Enclosure** 

No (Explain In Comment Area)

Missing TSI Jacketing O Student Accessible

 $\circ$ 

O

0

Justification:

Blistering

Cracking

Vibration

Other:

Comment Fit Material?

0

Missing TSI Jacketing

Physical Damage

Deterioration

Loose

Water Damage

 $\circ$ 

0

 $\circ$ 

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Drawing Group Code: 02 USA: 25 0" OD Quantity: 125 SF Building: 001 Room: 203 Floor: Material: Tile, Vinyl Floor, Border/Trim Classroom Record Comment: (1992) Dark brown 7200230 No.: No (Give approximate quantity in Comment Area) Yes Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present 0 $\bigcirc$ Friable Covering Yes O No (Explain In Comment Area) Comment Fit Material? O Enclosure Non-friable Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: O Damaged (<10%) $\bigcirc$ **Physical Damage** Activity / Movement О Significantly Damaged (>10%) 0 $\bigcirc$ Deterioration Forced Airstream Blistering Potential for Damage $\circ$ <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: USA: 13 0" OD Quantity: 649 SF Building: 001 Room: 204 Drawing Group Code: 02 Floor: Classroom Material: Tile, Vinyl Floor, 9X9 Comment: (1992) Beige Record 7200071 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable 0 Not Found O Definitely Not Present $\circ$ $\bigcirc$ Covering Friable Yes 🔘 No (Explain In Comment Area) Comment Fit Material? Non-friable Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 O Damaged (<10%) Physical Damage Activity / Movement 0 Significantly Damaged (>10%) 0 $\bigcirc$ Forced Airstream Deterioration Blistering Potential for Damage $\circ$ О <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage Loose >10% Exposed Surface Area Vibration Other: 0" OD Quantity: 120 SF Drawing Group Code: 02 USA: 12 Room: 204 Building: 001 Floor: 2 Classroom Material: Tite, Vinyl Floor, Border/Trim Comment: (1992) Dark brown Record 7200070 No.. 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable 0 Not Found O Definitely Not Present Friable O Covering No (Explain In Comment Area) Comment Fit Material? Non-friable **Enclosure** Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: О Damaged (<10%) 0 Physical Damage Activity / Movement $\bigcirc$ Significantly Damaged (>10%) 0 Forced Airstream $\circ$ Deterioration **Blistering** Potential for Damage $\circ$ 0 0 Water Damage <10% Exposed Surface Area Cracking Potential for Significant Damage >10% Exposed Surface Area 0 0

Vibration

Other:

### 720 / Pinkerton Elementary School Inspector: Inspection Date: 6409 Agnes Building: 001 Room: 204A Drawing Group Code: 02 USA: 12 0" OD Quantity: 21 SF Floor: 2 Storage Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200074 No.: Area Kept Locked Quantity Within 20%? 0 No (Give approximate quantity in Comment Area) Assessment: Not Assessable 0 Not Found O Definitely Not Present 0 Friable 0 Covering Comment Fit Material? No (Explain In Comment Area) Non-friable ()**Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 Blistering Deterioration Forced Airstream О Significantly Damaged (>10%) $\circ$ $\bigcirc$ $\bigcirc$ Cracking Potential for Damage Water Damage <10% Exposed Surface Area 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Drawing Group Code: 02 Room: 205 USA: 36 0" OD Quantity: 5 SF Floor: 2 Corridor Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Brown 7200250 No.: 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present $\bigcirc$ Friable Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable Enclosure Missing TSI Jacketing Student Accessible Justification: Intact and Undamaged 0 **Physical Damage** Activity / Movement Damaged (<10%) Blistering $\circ$ Deterioration $\circ$ Forced Airstream $\bigcirc$ Significantly Damaged (>10%) 0 Cracking $\circ$ $\circ$ Water Damage <10% Exposed Surface Area Potential for Damage Ο Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: USA: 26 Building: 001 Room: 205 Drawing Group Code: 02 0" OD Quantity: 1420 SF Floor: 2 Corridor Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige (1996) 1020 SF. 7200245 No.: Quantity Within 20%? No (Give approximate quantity in Comment Area) Assessment: Not Assessable 0 Not Found O **Definitely Not Present** О Friable Covering Comment Fit Material? 0 No (Explain In Comment Area) Non-friable Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 **Physical Damage** Activity / Movement О Damaged (<10%) Blistering $\bigcirc$ $\bigcirc$ $\bigcirc$ Deterioration Forced Airstream Significantly Damaged (>10%) О Cracking 0 O Water Damage <10% Exposed Surface Area Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Drawing Group Code: 02 USA: 27 0" OD Quantity: 193 SF Building: 001 Room: 205 Floor: Corridor Material: Tile, Vinyl Floor, 9X9 Comment: (1992) Red (1996) 150 SF. Record 7200246 No (Give approximate quantity in Comment Area) Assessment: O Quantity Within 20%? Not Assessable Not Found O Definitely Not Present $\circ$ 0 O Friable Covering Comment Fit Material? No (Explain In Comment Area) Non-friable 0 **Enclosure** Intact and Undamaged Student Accessible Missing TSI Jacketing Justification: О Damaged (<10%) 0 **Activity / Movement Physical Damage** Significantly Damaged (>10%) $\circ$ $\bigcirc$ Forced Airstream Deterioration Blistering $\bigcirc$ Potential for Damage $\bigcirc$ 0 Water Damage <10% Exposed Surface Area Cracking Potential for Significant Damage 0 >10% Exposed Surface Area 0 Vibration Loose Other: USA: 34 0" OD Quantity: 4 SF Drawing Group Code: 02 Building: 001 Room: 205 Floor: Material: Tile, Vinyl Floor, 9X9 Corridor Comment: (1992) Brick Record 7200247 No.: No (Give approximate quantity in Comment Area) 0 Assessment: O Quantity Within 20%? Not Assessable Not Found O Definitely Not Present 0 Friable Ο Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable $\circ$ Enclosure Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: О Damaged (<10%) $\bigcirc$ **Physical Damage** Activity / Movement $\bigcirc$ Significantly Damaged (>10%) 0 Forced Airstream 0 Deterioration Blistering $\circ$ <10% Exposed Surface Area Potential for Damage 0 0 Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area $\bigcirc$ 0 Vibration Loose Other: USA: 28 0" OD Quantity: 3 SF Drawing Group Code: 02 Room: 205 Building: 001 Floor: Material: Tile, Vinyl Floor, 9X9 Corridor Comment: (1992) Cream Record 7200249 No.: No (Give approximate quantity in Comment Area) $\circ$ Assessment: O Quantity Within 20%? Not Assessable Not Found O Definitely Not Present 0 $\bigcirc$ O Friable Covering Yes O No (Explain In Comment Area) Comment Fit Material? 0 Enclosure Non-friable Intact and Undamaged O Student Accessible Missing TSI Jacketing Justification: O Damaged (<10%) 0 Physical Damage **Activity / Movement** Ο Significantly Damaged (>10%) $\bigcirc$ 0 Forced Airstream

0

0

Blisterina

Cracking

Vibration Other:

Deterioration

Loose

Water Damage

 $\circ$ 

O

<10% Exposed Surface Area

>10% Exposed Surface Area

Potential for Damage

Potential for Significant Damage

### 720 / Pinkerton Elementary School Inspector: 6409 Agnes Inspection Date: Building: 001 Room: 205 Drawing Group Code: 02 USA: 35 0" OD Quantity: 28 SF Floor: Corridor Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Carmel 7200248 No.: Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: 0 Not Assessable Not Found O Definitely Not Present О 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) Non-friable O Enclosure Missing TSI Jacketing Student Accessible Justification: Intact and Undamaged 0 0 **Physical Damage** Activity / Movement Damaged (<10%) 0 Blistering Deterioration Forced Airstream О Significantly Damaged (>10%) $\circ$ $\bigcirc$ Cracking О <10% Exposed Surface Area Water Damage Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 205 USA: 25 Drawing Group Code: 02 0" OD Quantity: 250 SF Floor: 2 Corridor Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200244 No.: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable $\circ$ Not Found O **Definitely Not Present** О 0 Friable Covering Comment Fit Material? $\circ$ No (Explain In Comment Area) Non-friable Enclosure 0 Missing TSI Jacketing Justification: Student Accessible Intact and Undamaged 0 О Physical Damage Activity / Movement Damaged (<10%) Blistering 0 Deterioration O Forced Airstream Ο Significantly Damaged (>10%) 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage О Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: USA: 08 Building: 001 Room: 206 Drawing Group Code: 02 0" OD Quantity: 592 SF Floor: 2 Classroom Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Off-white/green 7200147 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\circ$ Not Assessable 0 Not Found O Definitely Not Present 0 Friable 0 Covering Comment Fit Material? Yes O No (Explain In Comment Area) Non-friable O **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: О **Physical Damage** Activity / Movement О Damaged (<10%) $\bigcirc$ Deterioration $\bigcirc$ $\bigcirc$ Blistering Forced Airstream Significantly Damaged (>10%) 0 Cracking 0 Water Damage O <10% Exposed Surface Area Potential for Damage

>10% Exposed Surface Area

Potential for Significant Damage

0

Vibration

Other:

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes USA: 10 0" OD Quantity: 116 SF Drawing Group Code: 02 Building: 001 Room: 206 Floor: Material: Tile, Vinvl Floor, Border/Trim Classroom Comment: (1992) Green Record 7200146 No.: No (Give approximate quantity in Comment Area) 0 Assessment: Quantity Within 20%? Not Assessable 0 Not Found O Definitely Not Present 0 Friable Covering O No (Explain In Comment Area) Comment Fit Material? Ο Non-friable Enclosure Missing TSI Jacketing Intact and Undamaged Student Accessible Justification: Damaged (<10%) 0 Physical Damage Activity / Movement Significantly Damaged (>10%) $\circ$ Deterioration Forced Airstream Blistering Potential for Damage <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: USA: 10 O" OD Quantity: 11 SF Drawing Group Code: 02 Building: 001 Room: 206B Floor: Material: Tile, Vinyl Floor, Border/Trim 2 Storage Comment: (1992) Green Record 7200154 Area Kept horked No.: No (Give approximate quantity in Comment Area) Assessment: Quantity Within 20%? Not Assessable Not Found O Definitely Not Present 0 0 Friable Covering Comment Fit Material? 0 No (Explain In Comment Area) 0 Non-friable Enclosure Student Accessible Intact and Undamaged Missing TSI Jacketing Justification: Damaged (<10%) 0 Activity / Movement Physical Damage Significantly Damaged (>10%) $\bigcirc$ Forced Airstream Deterioration Blistering Potential for Damage 0 <10% Exposed Surface Area Water Damage Cracking Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: Drawing Group Code: 02 0" OD Quantity: 11 SF USA: 10 Building: 001 Room: 206C Material: Tile, Vinyl Floor, Border/Trim Floor: 2 Storage Comment: (1992) Green Record 7200156 No.: Yes O No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: 0 Not Assessable 0 Not Found O Definitely Not Present 0 0 Friable Covering No (Explain In Comment Area) Comment Fit Material? $\circ$ Enclosure Non-friable Intact and Undamaged $\circ$ Missing TSI Jacketing Student Accessible Justification: 0 Damaged (<10%) 0 Physical Damage Activity / Movement Significantly Damaged (>10%) Blistering 0 Deterioration Forced Airstream Potential for Damage <10% Exposed Surface Area</p> 0 Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area $\circ$ Loose Vibration

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes 0" OD Quantity: 80 SF Building: 001 Room: 207 Drawing Group Code: 02 USA: 26 Floor: 2 Vestibule Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige 7200266 No.: Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) Assessment: O Not Assessable $\circ$ Not Found O Definitely Not Present 0 Friable 0 Covering Yes O No (Explain In Comment Area) Comment Fit Material? Non-friable $\circ$ Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 **Physical Damage** О Damaged (<10%) Activity / Movement 0 0 Significantly Damaged (>10%) Blistering Deterioration Forced Airstream $\bigcirc$ Cracking 0 Water Damage $\circ$ <10% Exposed Surface Area Potential for Damage О Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 207 Drawing Group Code: 02 USA: 25 0"OD Quantity: 22 SF Floor: 2 Vestibule Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200265 No.: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Yes Assessment: O Not Assessable Ο Not Found O Definitely Not Present 0 0 Friable Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable $\circ$ Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ Deterioration $\circ$ О Blistering Forced Airstream Significantly Damaged (>10%) O Cracking 0 Water Damage О <10% Exposed Surface Area Potential for Damage 0 Potential for Significant Damage Vibration Loose >10% Exposed Surface Area Other: Building: 001 Room: 210 Drawing Group Code: 09 USA: 32 O" OD Quantity: 2 EA Floor: 2 Vestibule Material: Insulation, Fire Door Record Comment: (1992) -7200288 No.: 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Yes Assessment: Not Assessable $\circ$ Not Found **Definitely Not Present** O Friable Covering 0 Comment Fit Material? No (Explain In Comment Area) Ο Non-friable Enclosure 0 Missing TSI Jacketing 0 Student Accessible Intact and Undamaged Justification: O $\circ$ **Physical Damage** 0 **Activity / Movement** Damaged (<10%) Blistering $\circ$ Deterioration $\circ$ Forced Airstream О Significantly Damaged (>10%) 0 0 0 Potential for Damage Cracking Water Damage <10% Exposed Surface Area Vibration Loose >10% Exposed Surface Area Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Drawing Group Code: 02 USA: 26 Room: 210 0" OD Quantity: 58 SF Floor: Vestibule Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige 7200287 No.: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable Not Found O Definitely Not Present O Friable О Covering O No (Explain In Comment Area) Comment Fit Material? Enclosure Non-friable Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 O Physical Damage **Activity / Movement** Damaged (<10%) 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 () $\circ$ Cracking Potential for Damage Water Damage <10% Exposed Surface Area $\circ$ Potential for Significant Damage Vibration Loose >10% Exposed Surface Area Other: Room: 210 Drawing Group Code: 02 USA: 25 Building: 001 0" OD Quantity: 38 SF Floor: 2 Vestibule Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200286 No.: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable O Not Found O Definitely Not Present O Friable 0 Covering Yes O Comment Fit Material? No (Explain In Comment Area) Non-friable О Enclosure $\bigcirc$ Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage** Damaged (<10%) Activity / Movement 0 $\bigcirc$ Blistering Deterioration 0 Forced Airstream Significantly Damaged (>10%) 0 0 0 Potential for Damage Cracking Water Damage <10% Exposed Surface Area 0 О >10% Exposed Surface Area $\circ$ Potential for Significant Damage Vibration Loose Other: USA: 38 Building: 001 Room: 211 Drawing Group Code: 13 0" OD Quantity: 28 SF Floor: 2 Mechanical Room Material: Cloth, Vibration Joint Record Comment: (1992) Rubberized canvas-4 square; non-suspect 7200291 No.: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable 0 Not Found O **Definitely Not Present** O Friable Covering Yes O Comment Fit Material? No (Explain In Comment Area) Non-friable O **Enclosure** Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: 0 0 **Physical Damage** Activity / Movement Damaged (<10%) O $\bigcirc$ Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 О О <10% Exposed Surface Area Potential for Damage Cracking Water Damage $\circ$ Vibration Loose >10% Exposed Surface Area Potential for Significant Damage

### 720 / Pinkerton Elementary School Inspector: 6409 Agnes Inspection Date: Drawing Group Code: 07 Building: 001 Room: C201 USA: 02 0" OD Quantity: 10 EA Floor: 2 Chase Material: Insulation, MJP on Corr. Pipe Covering Record Comment: (1992) Above drop ceiling 7200239 No.: Quantity Within 20%? O Yes No (Give approximate quantity in Comment Area) Assessment: Not Assessable Not Found O Definitely Not Present 0 Friable O Covering 0 Comment Fit Material? Yes $\circ$ No (Explain In Comment Area) $\circ$ О Non-friable **Enclosure** $\bigcirc$ $\bigcirc$ Missing TSI Jacketing $\circ$ Student Accessible Intact and Undamaged Justification: 0 0 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 0 О Blistering $\bigcirc$ Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 0 Cracking Water Damage O <10% Exposed Surface Area Potential for Damage 0 0 Vibration Loose >10% Exposed Surface Area O Potential for Significant Damage Other: Building: 001 Room: C201 Drawing Group Code: 06 USA: 03 6" OD Quantity: 25 LF Floor: 2 Chase Material: Insulation, Pipe, Corrigated Record Comment: (1992) Above drop ceiling-unable to touch material 7200033 No.: 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Yes $\circ$ Assessment: $\bigcirc$ Not Assessable Not Found O **Definitely Not Present** 0 О Friable Covering $\circ$ Comment Fit Material? Yes O No (Explain In Comment Area) O Non-friable О Enclosure 0 Missing TSI Jacketing 0 Student Accessible Intact and Undamaged Justification: 0 0 0 **Physical Damage Activity / Movement** Damaged (<10%) $\bigcirc$ $\bigcirc$ Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 Cracking О Water Damage $\circ$ <10% Exposed Surface Area 0 Potential for Damage 0 0 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage О Other: Building: 001 USA: 02 Room: C203 Drawing Group Code: 07 6" OD Quantity: 20 EA Floor: 2 Chase Material: Insulation, MJP on Corr. Pipe Covering Record Comment: (1992) -7200240 No.: Quantity Within 20%? 0 0 Yes No (Give approximate quantity in Comment Area) Assessment: (·) Not Assessable Not Found O **Definitely Not Present** $\circ$ Friable О Covering 0 Comment Fit Material? $\circ$ No (Explain In Comment Area) 0 Non-friable $\circ$ Enclosure 0 0 Missing TSI Jacketing $\circ$ Student Accessible Intact and Undamaged Justification: $\bigcirc$ $\circ$ Physical Damage $\circ$ **Activity / Movement** Damaged (<10%) Blistering 0 Deterioration 0 Forced Airstream О Significantly Damaged (>10%) 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes USA: 06 Building: 001 Drawing Group Code: 07 4" OD Quantity: 8 EA Room: C203 Floor: 2 Chase Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) -7200242 No.: $\circ$ Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** 0 Friable O Covering 0 0 No (Explain In Comment Area) Comment Fit Material? Yes 0 О Non-friable Enclosure O $\circ$ Missing TSI Jacketing $\circ$ Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage Activity / Movement** 0 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 $\circ$ $\circ$ $\bigcirc$ Potential for Damage Cracking <10% Exposed Surface Area Water Damage 0 >10% Exposed Surface Area $\circ$ Potential for Significant Damage Vibration Loose Other: Building: 001 Room: C203 Drawing Group Code: 06 USA: 03 6" OD Quantity: 40 LF Floor: 2 Chase Material: Insulation, Pipe, Corrigated Record Comment: (1992) Above drop ceiling 7200035 No.: О Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable Not Found O **Definitely Not Present** 0 0 Friable Covering 0 Comment Fit Material? Yes $\circ$ No (Explain In Comment Area) $\bigcirc$ 0 Enclosure Non-friable 0 0 0 Student Accessible Missing TSI Jacketing Intact and Undamaged Justification: 0 0 **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ 0 $\bigcirc$ Blistering Deterioration Forced Airstream Significantly Damaged (>10%) $\circ$ 0 0 <10% Exposed Surface Area 0 Potential for Damage Cracking Water Damage 0 Potential for Significant Damage О Vibration 0 >10% Exposed Surface Area Loose Other: Room: C203 Building: 001 Drawing Group Code: 06 USA: 07 4" OD Quantity: 15 LF Floor: 2 Chase Material: Insulation, Pipe, Paper Record Comment: (1992) -7200241 No.: $\circ$ Yes No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable Not Found **Definitely Not Present** 0 Friable Ο Covering 0 Yes O No (Explain In Comment Area) Comment Fit Material? $\bigcirc$ Non-friable $\circ$ Enclosure 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 ()Forced Airstream Significantly Damaged (>10%) Blistering Deterioration 0 О Cracking 0 0 <10% Exposed Surface Area Potential for Damage Water Damage $\circ$ Potential for Significant Damage 0 >10% Exposed Surface Area Vibration Loose

### 720 / Pinkerton Elementary School Inspector: Inspection Date: 6409 Agnes 6" OD Quantity: 10 EA Building: 001 Room: C203A Drawing Group Code: 07 USA: 02 Floor: Chase Material: Insulation, MJP on Corr. Pipe Covering Record Comment: (1992) Above drop ceiling 7200034 No: 0 Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found **Definitely Not Present** О O Friable Covering 0 Comment Fit Material? No (Explain In Comment Area) 0 O Enclosure Non-friable 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 $\bigcirc$ $\bigcirc$ Potential for Damage Cracking Water Damage <10% Exposed Surface Area 0 0 Potential for Significant Damage Vibration >10% Exposed Surface Area Loose Other: Drawing Group Code: 07 4" OD Quantity: 8 EA USA: 06 Building: 001 Room: C203A Floor: 2 Chase Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) Above drop ceiling-domestic hot water 7200038 No.: 0 Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** 0 Friable $\cap$ Covering 0 No (Explain In Comment Area) Comment Fit Material? $\bigcirc$ Non-friable Ο Enclosure 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) Physical Damage **Activity / Movement** $\bigcirc$ Blistering 0 Deterioration $\circ$ Forced Airstream Significantly Damaged (>10%) $\bigcirc$ $\bigcirc$ $\circ$ 0 Potential for Damage Cracking <10% Exposed Surface Area Water Damage 0 0 >10% Exposed Surface Area Potential for Significant Damage Vibration Loose Other: Building: 001 Room: C203A Drawing Group Code: 07 USA: 04 4" OD Quantity: 4 EA Floor: Chase 2 Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) Domestic cold water 7200238 No.: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found **Definitely Not Present** 0 Ο Friable Covering 0 Yes O Comment Fit Material? No (Explain In Comment Area) 0 O Non-friable **Enclosure** 0 O Missing TSI Jacketing $\circ$ Student Accessible Intact and Undamaged Justification: 0 О **Physical Damage Activity / Movement** Damaged (<10%) 0 0 $\bigcirc$ Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 0 <10% Exposed Surface Area 0 Potential for Damage Cracking Water Damage 0 Vibration $\circ$ Loose >10% Exposed Surface Area Potential for Significant Damage

### 720 / Pinkerton Elementary School Inspector: 6409 Agnes Inspection Date: Building: 001 Room: C203A Drawing Group Code: 06 USA: 03 6" OD Quantity: 20 LF Floor: Chase Material: Insulation, Pipe, Corrigated Record Comment: (1992) Above drop ceiling 7200036 No (Give approximate quantity in Comment Area) Quantity Within 20%? Yes Assessment: Not Assessable Not Found **Definitely Not Present** 0 Friable Covering 0 Comment Fit Material? No (Explain In Comment Area) O Non-friable О Enclosure 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 О 0 **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ $\circ$ $\circ$ Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage 0 0 Vibration Loose >10% Exposed Surface Area Ο Potential for Significant Damage Other: Drawing Group Code: 06 Building: 001 Room: C203A USA: 05 4" OD Quantity: 20 LF Floor: Chase Material: Insulation, Pipe, Paper Record Comment: (1992) Domestic cold water 7200237 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found **Definitely Not Present** Ο Friable Covering **Comment Fit Material?** No (Explain In Comment Area) $\circ$ Non-friable Ο **Enclosure** $\circ$ Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 Ο 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 0 0 $\circ$ Blistering Deterioration Significantly Damaged (>10%) Forced Airstream O 0 0 О Cracking Water Damage <10% Exposed Surface Area Potential for Damage 0 Vibration $\circ$ Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: C203A Drawing Group Code: 06 USA: 07 4" OD Quantity: 15 LF Floor: Chase Material: Insulation, Pipe, Paper Comment: (1992) Above drop ceiling-domestic hot water Record 7200037 No.: 0 Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** 0 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) Ο $\circ$ Non-friable **Enclosure** 0 Ο Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\bigcirc$ **Physical Damage** $\circ$ $\circ$ Damaged (<10%) Activity / Movement 0 O Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 0 $\circ$ 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage $\bigcirc$ >10% Exposed Surface Area Vibration Loose Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Drawing Group Code: 07 USA: 02 6" OD Quantity: 3 EA Building: 001 Room: C211 Floor: Material: Insulation, MJP on Corr. Pipe Covering Chase Comment: (1992) -Record 7200293 No.: 0 No (Give approximate quantity in Comment Area) Yes Assessment: O Quantity Within 20%? Not Assessable Not Found O Definitely Not Present 0 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) $\circ$ Enclosure Non-friable $\bigcirc$ Intact and Undamaged 0 Missing TSI Jacketing $\circ$ Student Accessible Justification: 0 Damaged (<10%) $\circ$ Activity / Movement **Physical Damage** $\circ$ Significantly Damaged (>10%) 0 Deterioration Forced Airstream Blistering Potential for Damage $\circ$ <10% Exposed Surface Area О 0 O Cracking Water Damage Potential for Significant Damage 0 >10% Exposed Surface Area Loose Vibration Other: USA: 03 6" OD Quantity: 25 LF Drawing Group Code: 06 Building: 001 Room: C211 Floor: 2 Chase Material: Insulation, Pipe, Corrigated Record Comment: (1992) -7200292 No.: $\circ$ No (Give approximate quantity in Comment Area) $\circ$ Yes Quantity Within 20%? Assessment: 0 Not Assessable Not Found O Definitely Not Present 0 0 Friable Covering No (Explain In Comment Area) Comment Fit Material? $\bigcirc$ Non-friable $\bigcirc$ Enclosure 0 Intact and Undamaged 0 Missing TSI Jacketing $\circ$ Student Accessible Justification: 0 Damaged (<10%) $\bigcirc$ Activity / Movement **Physical Damage** $\circ$ Significantly Damaged (>10%) $\circ$ Deterioration $\circ$ Forced Airstream Blistering 0 $\circ$ <10% Exposed Surface Area $\circ$ Potential for Damage 0 Water Damage Cracking Potential for Significant Damage >10% Exposed Surface Area $\bigcirc$ Vibration Loose Other: USA: 04 0" OD Quantity: 2 EA Room: PC205A Drawing Group Code: 07 Building: 001 Floor: Material: Insulation, MJP on Wrapped Pipe Covering Pipe Chase Record Comment: (1992) -7200253 No.: No (Give approximate quantity in Comment Area) $\circ$ Yes Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** О 0 Friable Covering 0 0 No (Explain In Comment Area) Comment Fit Material? 0 $\bigcirc$ Non-friable Enclosure 0 $\bigcirc$ Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: 0 Damaged (<10%) 0 Physical Damage $\circ$ **Activity / Movement** 0 Significantly Damaged (>10%) 0 $\bigcirc$ 0 Deterioration Forced Airstream Blistering 0 0 $\circ$ <10% Exposed Surface Area Potential for Damage 0 Water Damage Cracking

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

 $\circ$ 

Loose

0

720 / Pinkerton E	.ieme	intary School		inspe	ector
6409 Agnes				Inspe	ection Date:
Building: 001 Room:	PC20	5A		Drawing Group Code: 07	USA: 06 4" OD Quantity: 2 EA
Floor: 2 Pipe C		<del></del>		Material: Insulation, MJP on \	
		nt: (1992) -		material insulation, Mai on V	Wapped Fipe Governing
Record 7200255	50//////	(100 <u>2</u> )			
Quantity Within 20%?	0	Yes O No (Give a	ppro	ximate quantity in Comment Area)	Assessment: O Not Assessable
		Not Found	O	Definitely Not Present	O Friable O Covering
Comment Fit Material?	0	Yes O No (Explain	a In C	Comment Area)	O Non-friable O Enclosure
luctification:	0	Missing TSI Jacketing	0	Student Accessible	O Intact and Undamaged
Justification:	Ŏ	Physical Damage	Ō	Activity / Movement	O Damaged (<10%)
O Blistering	Ō	Deterioration	0	Forced Airstream	O Significantly Damaged (>10%)
O Cracking	Ō	Water Damage	Õ	<10% Exposed Surface Area	O Potential for Damage
O Vibration	Ö	Loose	Õ	>10% Exposed Surface Area	O Potential for Significant Damage
Other:	_		~	10 mily occur was income in the	Ţ Ţ
Other.					
Building: 001 Room:	PC20			Drawing Group Code: 06	USA: 05 0" OD Quantity: 20 LF
Floor: 2 Pipe C		<b>0</b> / (		Material: Insulation, Pipe, Par	
		unt: /1002\		material institution, ripe, rap	<b>95</b> 1
Record 7200252	comme	ent: (1992) -			
Quantity Within 20%?	0	Yes O No (Give a	ppro	ximate quantity in Comment Area)	Assessment: O Not Assessable
	_	Not Found		•	O Friable O Covering
Comment Fit Material?	O	Yes O No (Explain	n In (	Comment Area)	O Non-friable O Enclosure
Justification:	0	Missing TSI Jacketing	0	Student Accessible	O Intact and Undamaged
วนธิเทษสมอาเ	0	Physical Damage	0	Activity / Movement	O Damaged (<10%)
O Blistering	Ō	Deterioration	0	Forced Airstream	O Significantly Damaged (>10%)
O Cracking	ŏ	Water Damage	Ō	<10% Exposed Surface Area	O Potential for Damage
O Vibration	Ŏ	Loose	Ō	>10% Exposed Surface Area	O Potential for Significant Damage
_		-000	_	, <b>, , , , , , , , , , , , , , , , , , </b>	•
Other:		· · · · · · · · · · · · · · · · · · ·			
<b>_</b>				Drawley Ores Order 20	HOAL OZ OHOD OVOGANO CO LE
Building: 001 Room:		5A		Drawing Group Code: 06	USA: 07 0" OD Quantity: 20 LF
Floor: 2 Pipe C		•		Material: Insulation, Pipe, Pa	per
Record No.: 7200254	Comme	ent: (1992) -			
Quantity Within 20%?	0		-	ximate quantity in Comment Area)	Assessment: O Not Assessable
	_	Not Found		Definitely Not Present	O Friable O Covering
Comment Fit Material?	0	Yes O No (Explai	n In (	Comment Area)	O Non-friable O Enclosure
Justification:	0	Missing TSI Jacketing	0	Student Accessible	O Intact and Undamaged
Justilication.	Ō	Physical Damage	0	Activity / Movement	O Damaged (<10%)
○ Blistering	Ŏ	Deterioration	Ō	Forced Airstream	O Significantly Damaged (>10%)
O Cracking	Ŏ	Water Damage	Ō	<10% Exposed Surface Area	O Potential for Damage
O Vibration	Õ	Loose	Ō	>10% Exposed Surface Area	O Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 0" OD Quantity: 751 SF USA: 26 6409 Agnes Drawing Group Code: 02 Material: Tile, Vinyl Floor, 9X9 Room: 301 Building: 001 Classroom Comment: (1992) Beige Floor: Assessment: O Not Assessable 7200181 Record No (Give approximate quantity in Comment Area) Covering No.: Not Found O Definitely Not Present Friable 0 Yes Enclosure Quantity Within 20%? $\bigcirc$ Non-friable 0 O No (Explain In Comment Area) Intact and Undamaged Damaged (<10%) Student Accessible Comment Fit Material? Missing TSI Jacketing Significantly Damaged (>10%) Activity / Movement O Potential for Damage Physical Damage Justification: Forced Airstream 0 Potential for Significant Damage <10% Exposed Surface Area Deterioration 0 >10% Exposed Surface Area Blistering 0 Water Damage 0 Cracking 0 Loose $\circ$ Vibration 0 Other: 0" OD Quantity: 15 SF USA: 28 Drawing Group Code: 02 Material: Tile, Vinyl Floor, 9X9 Room: 301 Building: 001 Classroom Comment: (1992) Cream Floor: Assessment: O Not Assessable 7200182 Record No (Give approximate quantity in Comment Area) Covering No.: O Friable Not Found O Definitely Not Present 0 Enclosure Quantity Within 20%? Non-friable 0 No (Explain In Comment Area) Intact and Undamaged 0 Student Accessible Comment Fit Material? Damaged (<10%) О Significantly Damaged (>10%) Missing TSI Jacketing Activity / Movement $\circ$ Potential for Damage Justification: Physical Damage Forced Airstream 0 Potential for Significant Damage <10% Exposed Surface Area Deterioration 0 >10% Exposed Surface Area Blistering Water Damage $\circ$ Cracking 0 Loose Vibration 0 Other: 0" OD Quantity: 85 SF USA: 25 Drawing Group Code: 02 Material: Tile, Vinyl Floor, Border/Trim Room: 301 Building: 001 Classroom Comment: (1992) Dark brown 3 Floor: Not Assessable Assessment: O 7200180 Record No (Give approximate quantity in Comment Area) Covering No.: Ο Not Found O Definitely Not Present Friable 0 Yes Enclosure 0 Quantity Within 20%? Non-friable O No (Explain In Comment Area) $\circ$ Intact and Undamaged Comment Fit Material? Damaged (<10%) Student Accessible 0 Significantly Damaged (>10%) Missing TSI Jacketing Activity / Movement 0 Potential for Damage Physical Damage Justification: Forced Airstream 0 Potential for Significant Damage O <10% Exposed Surface Area Deterioration 0 >10% Exposed Surface Area Blistering Water Damage $\bigcirc$ 0 Cracking 0 Loose $\bigcirc$ Vibration 0 Other:

### 720 / Pinkerton Elementary School Inspector: 6409 Agnes Inspection Date: Building: 001 Room: 302 Drawing Group Code: 02 USA: 08 0" OD Quantity: 593 SF Floor: Classroom Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Off-white/green 7200522 No.: Quantity Within 20%? No (Give approximate quantity in Comment Area) Assessment: Not Assessable Not Found O **Definitely Not Present** 0 Friable О Covering Comment Fit Material? No (Explain In Comment Area) Non-friable Enclosure 0 Justification: Missing TSI Jacketing Student Accessible Intact and Undamaged 0 **Physical Damage** Activity / Movement $\circ$ Damaged (<10%) ()Blistering $\bigcirc$ Deterioration Forced Airstream O Significantly Damaged (>10%) Cracking 0 Water Damage <10% Exposed Surface Area Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 302 Drawing Group Code: 02 0"OD Quantity: 116 SF USA: 10 Floor: Classroom Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Green 7200521 No.: Quantity Within 20%? Yes $\circ$ No (Give approximate quantity in Comment Area) Assessment: O Not Assessable Not Found O **Definitely Not Present** 0 Friable О Covering Comment Fit Material? 0 No (Explain In Comment Area) Non-friable $\bigcirc$ Enclosure Justification: 0 Missing TSI Jacketing Student Accessible Intact and Undamaged **Physical Damage** Activity / Movement $\circ$ Damaged (<10%) Blistering $\circ$ 0 Deterioration 0 Forced Airstream Significantly Damaged (>10%) $\circ$ Cracking 0 Water Damage Ο <10% Exposed Surface Area Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 302B Drawing Group Code: 02 USA: 10 0" OD Quantity: 9 SF Floor: Storage Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Green 7200529 No.: Quantity Within 20%? No (Give approximate quantity in Comment Area) О Assessment: $\circ$ Not Assessable 0 Not Found **Definitely Not Present** $\circ$ Friable 0 Comment Fit Material? 0 Covering No (Explain In Comment Area) Non-friable Enclosure 0 Justification: Missing TSI Jacketing Student Accessible Intact and Undamaged $\circ$ Physical Damage Activity / Movement Ο Damaged (<10%) Blisterina 0 Deterioration 0 Forced Airstream O Significantly Damaged (>10%) 0 Cracking $\circ$ Water Damage 0 <10% Exposed Surface Area Potential for Damage $\bigcirc$ Vibration Loose >10% Exposed Surface Area Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School 6409 Agnes Inspection Date: Building: 001 Room: 303 Drawing Group Code: 02 USA: 26 0" OD Quantity: 614 SF Floor: Classroom Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige 7200189 No.: Quantity Within 20%? No (Give approximate quantity in Comment Area) Assessment: Not Assessable 0 Not Found O **Definitely Not Present** 0 Friable O Covering **Comment Fit Material?** Yes 0 No (Explain In Comment Area) Non-friable O **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage Activity / Movement** Damaged (<10%) 0 $\bigcirc$ Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 Cracking 0 Water Damage <10% Exposed Surface Area Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Drawing Group Code: 02 Room: 303 USA: 25 0" OD Quantity: 82 SF Floor: 3 Classroom Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200188 No.: 0 Quantity Within 20%? No (Give approximate quantity in Comment Area) Assessment: O Not Assessable 0 Not Found O **Definitely Not Present** 0 Friable O Covering No (Explain In Comment Area) Comment Fit Material? 0 0 Non-friable Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage Activity / Movement** Damaged (<10%) Blistering $\bigcirc$ $\bigcirc$ $\circ$ Deterioration Forced Airstream Significantly Damaged (>10%) 0 Cracking 0 Water Damage $\circ$ <10% Exposed Surface Area Potential for Damage 0 Vibration Potential for Significant Damage Loose >10% Exposed Surface Area Other: Building: 001 Room: 304 Drawing Group Code: 02 USA: 14 0" OD Quantity: 5 SF Floor: 3 Classroom Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Cream 7200509 No.: Quantity Within 20%? Yes 0 No (Give approximate quantity in Comment Area) Assessment: O Not Assessable $\circ$ Not Found **Definitely Not Present** О Friable О Covering Comment Fit Material? O No (Explain In Comment Area) Non-friable $\circ$ Enclosure 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ Activity / Movement О **Physical Damage** Damaged (<10%) Blistering $\bigcirc$ $\circ$ $\circ$ Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Drawing Group Code: 02 USA: 13 0" OD Quantity: 630 SF Building: 001 Room: 304 Floor: Classroom Material: Tile, Vinvi Floor, 9X9 Record Comment: (1992) Beige 7200519 No: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable О Not Found O **Definitely Not Present** 0 0 Friable Covering 0 No (Explain In Comment Area) Comment Fit Material? О **Enclosure** Non-friable Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage** Activity / Movement O 0 Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 $\bigcirc$ $\circ$ Potential for Damage Cracking <10% Exposed Surface Area Water Damage >10% Exposed Surface Area Potential for Significant Damage Vibration Loose Other: Room: 304 Drawing Group Code: 02 USA: 12 0" OD Quantity: 124 SF Building: 001 Floor: 3 Classroom Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200518 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable $\circ$ Not Found O Definitely Not Present 0 О Friable Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable $\circ$ Enclosure Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: О 0 Physical Damage Activity / Movement Damaged (<10%) 0 $\bigcirc$ O Blistering Deterioration Forced Airstream Significantly Damaged (>10%) О 0 <10% Exposed Surface Area Potential for Damage Cracking Water Damage Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: Room: 304A Building: 001 Drawing Group Code: 02 USA: 12 0" OD Quantity: 21 SF Floor: 3 Storage Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200534 О No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 **Definitely Not Present** Not Found O $\circ$ $\bigcirc$ Friable Covering $\circ$ No (Explain In Comment Area) Comment Fit Material? Non-friable 0 Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ 0 Damaged (<10%) Physical Damage Activity / Movement $\bigcirc$ O Significantly Damaged (>10%) Forced Airstream Blistering Deterioration 0 0 <10% Exposed Surface Area Potential for Damage Cracking Water Damage

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

### 720 / Pinkerton Elementary School Inspector: Inspection Date: 6409 Agnes Building: 001 Room: 305 Drawing Group Code: 02 USA: 28 0" OD Quantity: 17 SF Floor: 3 Corridor Material: Tile, Vinvl Floor, 9X9 Record Comment: (1992) Cream 7200167 No.: Quantity Within 20%? Yes 0 No (Give approximate quantity in Comment Area) Assessment: $\bigcirc$ Not Assessable Not Found O **Definitely Not Present** 0 Friable 0 Covering Comment Fit Material? 0 No (Explain In Comment Area) Non-friable O Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 **Physical Damage** Damaged (<10%) Activity / Movement 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) $\circ$ $\bigcirc$ $\circ$ Cracking Water Damage <10% Exposed Surface Area Potential for Damage O Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 305 Drawing Group Code: 02 0" OD Quantity: 187 SF USA: 27 Floor: 3 Corridor Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Red 7200166 Quantity Within 20%? Yes 0 No (Give approximate quantity in Comment Area) Assessment: 0 Not Assessable $\circ$ Not Found Definitely Not Present O Friable $\bigcirc$ Covering Comment Fit Material? 0 No (Explain In Comment Area) Non-friable Enclosure $\circ$ Missing TSI Jacketing Student Accessible Justification: Intact and Undamaged 0 Physical Damage О Activity / Movement Damaged (<10%) 0 0 Blistering Deterioration O Forced Airstream Significantly Damaged (>10%) 0 Cracking 0 $\circ$ 0 Water Damage <10% Exposed Surface Area Potential for Damage 0 0 Vibration Potential for Significant Damage Loose >10% Exposed Surface Area Other: Building: 001 Room: 305 Drawing Group Code: 02 USA: 26 0" OD Quantity: 938 SF Floor: 3 Corridor Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige (1996) 730 SF. 7200165 No.: Quantity Within 20%? No (Give approximate quantity in Comment Area) Assessment: $\circ$ Not Assessable 0 Not Found **Definitely Not Present** 0 Friable O Covering Comment Fit Material? Yes O No (Explain In Comment Area) 0 Non-friable Enclosure 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 О **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ Blistering $\bigcirc$ $\bigcirc$ Deterioration Forced Airstream Significantly Damaged (>10%) $\circ$ Cracking 0 0 Water Damage <10% Exposed Surface Area Potential for Damage 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School 6409 Agnes Inspection Date: Room: 305 Building: 001 Drawing Group Code: 02 USA: 36 0" OD Quantity: 9 SF Floor: 3 Corridor Material: Tile, Vinyl Floor, 9X9 Comment: (1992) Dark brown under drinking fountain Record 7200168 No.: No (Give approximate quantity in Comment Area) Yes Quantity Within 20%? Assessment: O Not Assessable Not Found O **Definitely Not Present** 0 Friable Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable 0 Enclosure Intact and Undamaged Missing TSI Jacketing Student Accessible Justification: 0 Physical Damage Activity / Movement Damaged (<10%) Blistering 0 Deterioration Forced Airstream $\circ$ Significantly Damaged (>10%) **Potential for Damage** $\bigcirc$ $\bigcirc$ <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage Vibration >10% Exposed Surface Area Loose Other: Drawing Group Code: 02 0" OD Quantity: 281 SF Building: 001 Room: 305 USA: 25 Floor: 3 Corridor Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200164 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: O Not Assessable Not Found O **Definitely Not Present** 0 Friable О Covering O No (Explain In Comment Area) Comment Fit Material? Non-friable 0 Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage Activity / Movement** 0 0 Deterioration Forced Airstream Significantly Damaged (>10%) Blistering 0 $\bigcirc$ Potential for Damage Cracking Water Damage <10% Exposed Surface Area Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 306 Drawing Group Code: 02 USA: 08 0" OD Quantity: 705 SF Floor: Classroom Material: Tile Vinvl Floor, 9X9

Quantity Within 20%?  Comment Fit Material?	•	O Not Found	approximate quantity in Comment Area)  Definitely Not Present In In Comment Area)	Assessment: O Not Assessable O Friable O Covering Non-friable O Enclosure
Justification:	0	Missing TSI Jacketing Physical Damage	<ul><li>Student Accessible</li><li>Activity / Movement</li></ul>	Intact and Undamaged  Damaged (<10%)
O Blistering	0	Deterioration	O Forced Airstream	<ul><li>Significantly Damaged (&gt;10%)</li></ul>
O Cracking	0	Water Damage	<10% Exposed Surface Area	Potential for Damage
O Vibration	0	Loose	>10% Exposed Surface Area	O Potential for Significant Damage

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Room: 306 Drawing Group Code: 02 USA: 10 0" OD Quantity: 116 SF Floor: Classroom Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Green 7200512 No.: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 Not Found O Definitely Not Present $\circ$ О Friable Covering Comment Fit Material? No (Explain In Comment Area) О Non-friable **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: О 0 **Physical Damage** Activity / Movement Damaged (<10%) O Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage 0 $\circ$ Vibration >10% Exposed Surface Area Potential for Significant Damage Loose Other: Room: 306C Building: 001 Drawing Group Code: 02 USA: 10 0" OD Quantity: 11 SF Floor: Storage Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Green 7200049 No.: f Locked n No (Give approximate quantity in Comment Area) $\circ$ Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present $\bigcirc$ $\bigcirc$ Friable Covering Comment Fit Material? No (Explain In Comment Area) O Non-friable **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ **Physical Damage** Activity / Movement $\circ$ Damaged (<10%) Blistering 0 $\circ$ Significantly Damaged (>10%) Deterioration Forced Airstream 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage $\circ$ Vibration Potential for Significant Damage Loose >10% Exposed Surface Area Other: Building: 001 Room: 306D USA: 10 Drawing Group Code: 02 0" OD Quantity: 9 SF Floor: 3 Material: Tile, Vinyl Floor, Border/Trim Storage Record Comment: (1992) Green 7200080 No.: Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable 0 Not Found O **Definitely Not Present** O Friable $\circ$ Covering Comment Fit Material? No (Explain In Comment Area) Non-friable Enclosure Missing TSI Jacketing Student Accessible Justification: Intact and Undamaged 0 **Physical Damage** О Activity / Movement Damaged (<10%) 0 $\bigcirc$ 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) $\bigcirc$ $\bigcirc$ $\circ$ Cracking Water Damage <10% Exposed Surface Area Potential for Damage

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

Loose

О

### 720 / Pinkerton Elementary School Inspector: Inspection Date: 6409 Agnes Building: 001 USA: 32 Room: 307 Drawing Group Code: 09 0" OD Quantity: 2 EA Floor: Vestibule Material: Insulation, Fire Door Record Comment: (1992) -7200213 No: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) О Non-friable Enclosure Missing TSI Jacketing 0 Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage Activity / Movement** 0 0 Blistering Deterioration 0 Forced Airstream Significantly Damaged (>10%) 0 0 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage Vibration >10% Exposed Surface Area Potential for Significant Damage Loose Other: Building: 001 Drawing Group Code: 02 Room: 307 USA: 27 0" OD Quantity: 2 SF Floor: 3 Vestibule Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Red 7200206 No.: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: 0 Not Assessable Not Found **Definitely Not Present** О $\bigcirc$ Covering Friable No (Explain In Comment Area) Comment Fit Material? Non-friable **Enclosure** Missing TSI Jacketing Justification: Student Accessible Intact and Undamaged 0 О **Physical Damage** Activity / Movement Damaged (<10%) Blistering О Deterioration О Forced Airstream $\circ$ Significantly Damaged (>10%) 0 0 $\bigcirc$ Cracking Water Damage <10% Exposed Surface Area Potential for Damage Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: 307 Drawing Group Code: 02 USA: 26 0" OD Quantity: 73 SF Floor: 3 Vestibule Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige 7200205 No.: $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\circ$ Not Assessable 0 Not Found O **Definitely Not Present** 0 Friable O Covering Comment Fit Material? $\circ$ No (Explain In Comment Area) Non-friable Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 **Physical Damage Activity / Movement** О Damaged (<10%) 0 0 $\bigcirc$ Blistering Deterioration Forced Airstream Significantly Damaged (>10%) $\bigcirc$ $\circ$ $\circ$ Cracking Water Damage <10% Exposed Surface Area Potential for Damage

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

О

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Room: 307 Drawing Group Code: 02 USA: 25 0" OD Quantity: 38 SF Floor: Vestibule Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200204 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable 0 Not Found O **Definitely Not Present** 0 О Friable Covering $\circ$ No (Explain In Comment Area) Comment Fit Material? Non-friable O **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage** Activity / Movement 0 O O Blistering Significantly Damaged (>10%) Deterioration Forced Airstream 0 $\bigcirc$ 0 Potential for Damage Cracking Water Damage <10% Exposed Surface Area 0 0 Potential for Significant Damage Vibration Loose >10% Exposed Surface Area Other: Building: 001 Room: 310 Drawing Group Code: 09 USA: 32 0"OD Quantity: 2 EA Floor: Vestibule Material: Insulation, Fire Door Record Comment: (1992) -7200202 No.: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable $\circ$ Not Found **Definitely Not Present** $\bigcirc$ Friable Covering Comment Fit Material? No (Explain In Comment Area) 0 O Enclosure Non-friable Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 **Physical Damage** Activity / Movement $\circ$ Damaged (<10%) $\bigcirc$ $\bigcirc$ Significantly Damaged (>10%) Deterioration Forced Airstream Blistering 0 0 0 Cracking <10% Exposed Surface Area Potential for Damage Water Damage 0 $\bigcirc$ Potential for Significant Damage Vibration Loose >10% Exposed Surface Area Other: Drawing Group Code: 02 USA: 26 0" OD Quantity: 53 SF Building: 001 Room: 310 Floor: Vestibule Material: Tile, Vinyl Floor, 9X9 Record Comment: (1992) Beige 7200201 No.: Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: 0 Not Assessable Not Found O **Definitely Not Present** 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) 0 Non-friable **Enclosure** Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 Ο **Physical Damage** Activity / Movement Damaged (<10%) 0 0 0 Blisterina Forced Airstream Significantly Damaged (>10%) Deterioration $\circ$ 0 0 Potential for Damage Cracking Water Damage <10% Exposed Surface Area

>10% Exposed Surface Area

Potential for Significant Damage

Vibration

Other:

 $\bigcirc$ 

Loose

 $\bigcirc$ 

### 720 / Pinkerton Elementary School Inspector: Inspection Date: 6409 Agnes Building: 001 Room: 310 Drawing Group Code: 02 USA: 25 0" OD Quantity: 25 SF Floor: Vestibule Material: Tile, Vinyl Floor, Border/Trim Record Comment: (1992) Dark brown 7200538 No: Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present O Friable 0 Covering Comment Fit Material? No (Explain In Comment Area) Non-friable $\bigcirc$ Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Physical Damage Activity / Movement Damaged (<10%) Blistering Ο Deterioration О Forced Airstream 0 Significantly Damaged (>10%) 0 Cracking 0 $\bigcirc$ Water Damage <10% Exposed Surface Area Potential for Damage Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Room: C302 Drawing Group Code: 16 USA: 22 0" OD Quantity: 2 SF Floor: Chase Material: Debris Record Comment: (1992) Limited access-may contain other suspect materials 7200535 No.: 0 Yes 0 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: $\bigcirc$ Not Assessable Not Found Definitely Not Present 0 $\bigcirc$ Covering Friable Comment Fit Material? Yes O No (Explain In Comment Area) Ο Non-friable Enclosure 0 0 Missing TSI Jacketing 0 Student Accessible Justification: Intact and Undamaged О О **Physical Damage** Activity / Movement Damaged (<10%) Blistering 0 Deterioration $\circ$ Forced Airstream Ο Significantly Damaged (>10%) 0 0 $\circ$ 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage 0 0 Vibration Loose >10% Exposed Surface Area Potential for Significant Damage Other: Building: 001 Drawing Group Code: 07 Room: C303 USA: 06 4" OD Quantity: 5 EA Floor: 3 Chase Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) -7200210 No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present 0 Friable O Covering 0 Yes O No (Explain In Comment Area) Comment Fit Material? 0 0 Non-friable **Enclosure** 0 0 Missing TSI Jacketing О Student Accessible Intact and Undamaged Justification: 0 **Physical Damage** О Activity / Movement $\circ$ Damaged (<10%) 0 $\bigcirc$ 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 0 O 0 Cracking Water Damage <10% Exposed Surface Area Potential for Damage

Vibration

Other:

Loose

 $\circ$ 

>10% Exposed Surface Area

Potential for Significant Damage

О

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Building: 001 Room: C303 Drawing Group Code: 06 USA: 07 4" OD Quantity: 15 LF Floor: Chase Material: Insulation, Pipe, Paper Record Comment: (1992) -7200209 No.: 0 No (Give approximate quantity in Comment Area) Yes Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present $\circ$ 0 Friable Covering Comment Fit Material? Yes O No (Explain In Comment Area) О Non-friable Enclosure $\circ$ О 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 0 **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ О Significantly Damaged (>10%) Forced Airstream Blistering Deterioration 0 0 Cracking 0 $\circ$ <10% Exposed Surface Area Potential for Damage Water Damage Potential for Significant Damage 0 $\circ$ Vibration Loose >10% Exposed Surface Area Other: 4" OD Quantity: 2 EA Building: 001 Drawing Group Code: 07 USA: 06 Room: C304B Floor: Chase Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) -7200083 No.: Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present $\circ$ 0 Friable Covering Comment Fit Material? No (Explain In Comment Area) 0 Non-friable Enclosure 0 0 Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: $\circ$ Damaged (<10%) $\circ$ **Physical Damage** $\circ$ **Activity / Movement** 0 0 Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 0 0 0 Potential for Damage Cracking Water Damage <10% Exposed Surface Area $\bigcirc$ $\circ$ Potential for Significant Damage Vibration Loose >10% Exposed Surface Area Other: Building: 001 Room: C304B Drawing Group Code: 06 USA: 07 4" OD Quantity: 12 LF Floor: 3 Chase Material: Insulation, Pipe, Paper Record Comment: (1992) -7200082 No.: No (Give approximate quantity in Comment Area) $\circ$ Yes 0 Quantity Within 20%? Assessment: $\circ$ Not Assessable Not Found O Definitely Not Present 0 Friable 0 Covering Comment Fit Material? No (Explain In Comment Area) 0 Non-friable $\circ$ **Enclosure** 0 $\circ$ Missing TSI Jacketing $\circ$ Student Accessible Intact and Undamaged Justification: 0 О Damaged (<10%) Physical Damage **Activity / Movement** 0 0 0 Significantly Damaged (>10%) Blisterina Deterioration Forced Airstream $\circ$ 0 $\bigcirc$ $\circ$ Potential for Damage <10% Exposed Surface Area Cracking Water Damage Potential for Significant Damage Vibration Loose >10% Exposed Surface Area

### Inspector: 720 / Pinkerton Elementary School Inspection Date: 6409 Agnes Drawing Group Code: 07 USA: 06 4" OD Quantity: 4 EA Building: 001 Room: C305 Floor: Chase Material: Insulation, MJP on Wrapped Pipe Covering Record Comment: (1992) -7200212 No 1 $\circ$ Yes No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O **Definitely Not Present** 0 Friable Covering 0 No (Explain In Comment Area) Comment Fit Material? 0 Non-friable Enclosure 0 ()Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: 0 0 Damaged (<10%) **Physical Damage Activity / Movement** 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 $\bigcirc$ $\circ$ $\circ$ Potential for Damage Cracking <10% Exposed Surface Area Water Damage >10% Exposed Surface Area 0 Potential for Significant Damage Vibration Loose Other: Building: 001 USA: 07 Drawing Group Code: 06 4"OD Quantity: 3 LF Room: C305 Floor: 3 Chase Material: Insulation, Pipe, Paper Record Comment: (1992) -7200211 No.: $\circ$ Yes $\circ$ No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable Not Found O Definitely Not Present 0 O Friable Covering 0 0 No (Explain In Comment Area) Comment Fit Material? $\bigcirc$ 0 Enclosure Non-friable 0 0 Missing TSI Jacketing 0 Student Accessible Intact and Undamaged Justification: 0 О **Physical Damage** Activity / Movement Damaged (<10%) $\bigcirc$ 0 0 Blistering Deterioration Forced Airstream Significantly Damaged (>10%) 0 $\bigcirc$ $\circ$ <10% Exposed Surface Area 0 Potential for Damage Cracking Water Damage 0 Potential for Significant Damage >10% Exposed Surface Area Vibration Loose Other: Building: 001 Room: A-6 Drawing Group Code: 13 USA: 33 0"OD Quantity: 4 SF Floor: Attic Space Material: Cloth, Vibration Joint Record Comment: (1992) Round canvas 7200219 No.: No (Give approximate quantity in Comment Area) Quantity Within 20%? Assessment: Not Assessable $\circ$ Not Found **Definitely Not Present** Friable О Covering 0 Comment Fit Material? No (Explain In Comment Area) $\bigcirc$ Non-friable 0 Enclosure Missing TSI Jacketing Student Accessible Intact and Undamaged Justification: O 0 **Physical Damage** Activity / Movement Damaged (<10%) 0 $\bigcirc$ Significantly Damaged (>10%) Blistering Deterioration Forced Airstream 0 0 0 <10% Exposed Surface Area Potential for Damage Cracking Water Damage Potential for Significant Damage Vibration $\circ$ Loose >10% Exposed Surface Area