

Expiration Date: 10/28/2009

Certificate Number: 7020102108MOSR11347

Training Date: 10/21/2008

**Missouri State Certificate for Asbestos Related Occupations**

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


**Patricia J. Garcia**

has successfully completed the requirements for certification as a SUPERVISOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/28/2008

Date

  
Director of Air Pollution Control Program



CERTIFICATION NUMBER: 7020102108MOSR11347

THIS CERTIFIES

**Patricia J. Garcia**

HAS COMPLETED THE CERTIFICATION REQUIREMENTS FOR

**Supervisor**

APPROVED: 10/28/2008

EXPIRES: 10/28/2009



Missouri  
Department of  
Natural Resources

  
Director of Air Pollution Control Program



### KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: RC Garcia  
Inspection Date: 11/04/09

Building: 001 Room: C2-62 Drawing Group Code: USA: - 0" OD Quantity: 0 -  
Floor: Chase Material: Inaccessible suspect location  
Record No.: **4151369** Comment: (1992) No suspect material found

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

Comment Fit Material?  Yes  No (Explain In Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

Building: 001 Room: G-12 Drawing Group Code: 02 USA: 19 0" OD Quantity: 600 SF  
Floor: G ROTC Material: Tile, Vinyl Floor, 9X9  
Record No.: **4150670** Comment: (1992) Medium warm gray

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

Comment Fit Material?  Yes  No (Explain In Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

Building: 001 Room: G-13 Drawing Group Code: 06 USA: 15 6" OD Quantity: 6 EA  
Floor: G Office Material: Insulation, MJP on Non-Suspect Pipe  
Record No.: **4151657** Comment: (1992)

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

Comment Fit Material?  Yes  No (Explain In Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

# KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: Amir Garcia  
Inspection Date: 11/04/08

Building: 001 Room: G-13	Drawing Group Code: 02	USA: 20	0" OD Quantity: 420 SF
Floor: G Office	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>4150663</b>	Comment: (1992) Dark brown		

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: G-13	Drawing Group Code: 02	USA: 21	0" OD Quantity: 20 SF
Floor: G Office	Material: Tile, Vinyl Floor, Border/Trim		
Record No.: <b>4150664</b>	Comment: (1992) Dark medium brown (1996) Carpet over floor tile - concrete floor.		

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: G-56A	Drawing Group Code: 13	USA: 18	0" OD Quantity: 35 SF
Floor: G Fan Room	Material: Cloth, Vibration Joint		
Record No.: <b>4150833</b>	Comment: (1992) -		

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input checked="" type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)
<input checked="" type="radio"/> Vibration <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input checked="" type="radio"/> Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: Patricia G...  
Inspection Date: 11/04/08

Building: 001 Room: G-56B	Drawing Group Code: 13	USA: 18	0" OD Quantity: 35 SF
Floor: G Fan Room	Material: Cloth, Vibration Joint		
Record No.: <b>4150836</b>	Comment: (1992) -		

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input checked="" type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: G-68	Drawing Group Code: 02	USA: 34	0" OD Quantity: 144 SF
Floor: G Corridor	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>4151260</b>	Comment: (1992) Light ivory (beige)		

Quantity Within 20%?	<input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material?	<input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: G-74	Drawing Group Code: 02	USA: 35	0" OD Quantity: 84 SF
Floor: G Office	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>4151235</b>	Comment: (1992) Extra light taupe		

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input checked="" type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input checked="" type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input checked="" type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage

9 SF OF FLOOR TILE MISSING; MASTIC EXPOSED  
WINDAGE OF WATER INTRUSION

# KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: Patricia Garcia  
Inspection Date: 11/04/08

Building: 001 Room: G-77	Drawing Group Code: 07	USA: 27 4" OD Quantity: 1 EA
Floor: G Printing Classroom	Material: Insulation, MJP on Non-Suspect Pipe	
Record No.: <b>4151241</b> Comment: (1992) -		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable	
<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering	
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>	<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		
<input type="radio"/> Other: _____		

Building: 001 Room: G-77	Drawing Group Code: 07	USA: 29 4" OD Quantity: 1 EA
Floor: G Printing Classroom	Material: Insulation, MJP on Tar Lined Pipe	
Record No.: <b>4151243</b> Comment: (1992) -		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable	
<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering	
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>	<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area		
<input type="radio"/> Other: _____		

Building: 001 Room: 1-87	Drawing Group Code: 02	USA: 34 0" OD Quantity: 88 SF
Floor: 1 Stairs	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>4151293</b> Comment: (1992) Light ivory (beige)		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable	
<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering	
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>	<input checked="" type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input checked="" type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input checked="" type="radio"/> >10% Exposed Surface Area		
<input type="radio"/> Other: <u>PAINTED OVER IN GRAY</u>		

# KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: Patricia Carrera  
Inspection Date: 11/04/08

Building: 001	Room: 2-54	Drawing Group Code: 06	USA: 03	4" OD Quantity: 6 LF
Floor: 2	Gymnasium	Material: Insulation, Pipe, Magnesia		
Record No.: <b>4150269</b>	Comment: (1992) Metal wrapped remaining & TSI removed			
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable		
		<input type="radio"/> Friable <input type="radio"/> Covering		
		<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Intact and Undamaged		
		<input type="radio"/> Damaged (<10%)		
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Potential for Damage		
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area				
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area				
<input type="radio"/> Other: _____				

Building: 001	Room: 2-58	Drawing Group Code: 02	USA: 34	0" OD Quantity: 88 SF
Floor: 2	Stairs	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>4150885</b>	Comment: (1992) Light ivory (beige)			
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable		
		<input type="radio"/> Friable <input type="radio"/> Covering		
		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Intact and Undamaged		
		<input type="radio"/> Damaged (<10%)		
Justification: <input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible		<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement		<input checked="" type="radio"/> Potential for Damage		
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area				
<input type="radio"/> Vibration <input type="radio"/> Loose <input checked="" type="radio"/> >10% Exposed Surface Area				
<input type="radio"/> Other: <u>PAINTED OVER IN GRAY</u>				

Building: 001	Room: 3-18A	Drawing Group Code: 02	USA: 05	0" OD Quantity: 92 SF
Floor: 3	Vestibule	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>4151136</b>	Comment: (1992) Medium green-response action showed this removed (1996) Green floor tile present.			
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable		
		<input type="radio"/> Friable <input type="radio"/> Covering		
		<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Intact and Undamaged		
		<input type="radio"/> Damaged (<10%)		
Justification: <input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Potential for Damage		
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area				
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area				
<input type="radio"/> Other: _____				

# KCMSD 2008 Triennial Re-inspection

415 / Westport High School  
315 E. 39th Street

Inspector: PATRICK GURCH  
Inspection Date: 11/04/08

Building: 001 Room: A-7 Floor: A Main Attic	Drawing Group Code: 09 USA: 37 0" OD Quantity: 1 EA Material: Insulation, Fire Door	
Record No.: <span style="border: 1px solid black; padding: 2px;">4151200</span> Comment: (1992) Into elevator room		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable <input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
<b>Justification:</b>		
<input type="radio"/> Blistering <input type="radio"/> Cracking <input type="radio"/> Vibration <input type="radio"/> Other: _____	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Student Accessible <input checked="" type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area

Building: 001 Room: A-7 Floor: A Main Attic	Drawing Group Code: 10 USA: 25 0" OD Quantity: 2 SF Material: Lining, Brake	
Record No.: <span style="border: 1px solid black; padding: 2px;">4151199</span> Comment: (1992) Elevator room		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable <input checked="" type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input checked="" type="radio"/> Potential for Significant Damage
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
<b>Justification:</b>		
<input type="radio"/> Blistering <input type="radio"/> Cracking <input type="radio"/> Vibration <input type="radio"/> Other: _____	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Student Accessible <input checked="" type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area

AREA LOCATED