

Expiration Date: 10/28/2009

Certificate Number: 7020102108MOSR11347

Training Date: 10/21/2008

**Missouri State Certificate for Asbestos Related Occupations**

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


**Patricia J. Garcia**

has successfully completed the requirements for certification as a SUPERVISOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/28/2008

Date

*James L. Karameruh*  
Director of Air Pollution Control Program



CERTIFICATION NUMBER: 7020102108MOSR11347

THIS CERTIFIES

Patricia J. Garcia

HAS COMPLETED THE CERTIFICATION REQUIREMENTS FOR

Supervisor

APPROVED: 10/28/2008

EXPIRES: 10/28/2009



Missouri  
Department of  
Natural Resources

*James L. Karameruh*  
Director of Air Pollution Control Program



CENT # MOSK 11347  
EXP. 10/28/09

### KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Garcia  
Inspection Date: 11/05/09

Building: 001 Room: 101 Drawing Group Code: USA: - 0" OD Quantity: 100 SF  
 Floor: Corridor Material: Mastic, Floor Tile  
 Record No.: **9200602** Comment: (1992) Sandwiched under masonry block walls.

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Comment Fit Material?  Yes  No (Explain in Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

Building: 001 Room: 101 Drawing Group Code: USA: - 0" OD Quantity: 100 SF  
 Floor: Corridor Material: Tile, Vinyl Floor, 9X9  
 Record No.: **9200598** Comment: (1992) Sandwiched under masonry block walls.

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Comment Fit Material?  Yes  No (Explain in Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

Building: 001 Room: 110 Drawing Group Code: USA: - 0" OD Quantity: 75 SF  
 Floor: Corridor Material: Mastic, Floor Tile  
 Record No.: **9200603** Comment: (1992) Sandwiched under masonry block walls.

Quantity Within 20%?  Yes  No (Give approximate quantity in Comment Area)  
 Not Found  Definitely Not Present

Comment Fit Material?  Yes  No (Explain in Comment Area)

Justification:  Missing TSI Jacketing  Student Accessible  
 Physical Damage  Activity / Movement  
 Blistering  Deterioration  Forced Airstream  
 Cracking  Water Damage  <10% Exposed Surface Area  
 Vibration  Loose  >10% Exposed Surface Area  
 Other: \_\_\_\_\_

Assessment:  Not Assessable  
 Friable  Covering  
 Non-friable  Enclosure  
 Intact and Undamaged  
 Damaged (<10%)  
 Significantly Damaged (>10%)  
 Potential for Damage  
 Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School

Inspector: Patricia Garcia

8820 E. 27th Street

Inspection Date: 1/15/09

Building: 001	Room: 110	Drawing Group Code:	USA: -	0" OD	Quantity: 75 SF
Floor:	Corridor	Material: Tile, Vinyl Floor, 9X9			
Record No.:	9200599 Comment: (1992) Sandwiched under masonry block walls.				
Quantity Within 20%?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		
			<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:			<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement <input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream <input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area <input type="radio"/> Other: _____		
			<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable <input type="radio"/> Friable <input checked="" type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage		

Building: 001	Room: 112	Drawing Group Code:	USA: -	0" OD	Quantity: 100 SF
Floor:	Corridor	Material: Mastic, Floor Tile			
Record No.:	9200604 Comment: (1992) Sandwiched under masonry block walls.				
Quantity Within 20%?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		
			<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:			<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement <input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream <input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area <input type="radio"/> Other: _____		
			<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable <input type="radio"/> Friable <input checked="" type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage		

Building: 001	Room: 112	Drawing Group Code:	USA: -	0" OD	Quantity: 100 SF
Floor:	Corridor	Material: Tile, Vinyl Floor, 9X9			
Record No.:	9200600 Comment: (1992) Sandwiched under masonry block walls.				
Quantity Within 20%?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		
			<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material?			<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		
Justification:			<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement <input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream <input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area <input type="radio"/> Other: _____		
			<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable <input type="radio"/> Friable <input checked="" type="radio"/> Covering <input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure <input checked="" type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage		

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Green  
Inspection Date: 11/05/02

Building: 001 Room: 215	Drawing Group Code:	USA: - 0" OD Quantity: 150 SF
Floor: Corridor	Material: Mastic, Floor Tile	
Record No.: <b>9200605</b>	Comment: (1992) Sandwiched under masonry block walls.	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		

Building: 001 Room: 215	Drawing Group Code:	USA: - 0" OD Quantity: 150 SF
Floor: Corridor	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200601</b>	Comment: (1992) Sandwiched under masonry block walls.	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input checked="" type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		

Building: 001 Room: 005	Drawing Group Code: 10	USA: 12 0" OD Quantity: 3 SF
Floor: T Boiler Room	Material: Brick, Fire	
Record No.: <b>9200512</b>	Comment: (1992) Stored	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
<input type="radio"/> Other: _____		

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia C. Gardner  
Inspection Date: 11/05/08

Building: 001 Room: 005	Drawing Group Code: 10	USA: 12 0" OD Quantity: 260 SF															
Floor: T Boiler Room	Material: Brick, Fire																
Record No.: <b>9200511</b> Comment: (1992) -																	
<p>Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 100px;"><input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Physical Damage</td> <td><input type="radio"/> Student Accessible</td> </tr> <tr> <td><input type="radio"/> Cracking</td> <td><input type="radio"/> Deterioration</td> <td><input type="radio"/> Activity / Movement</td> </tr> <tr> <td><input type="radio"/> Vibration</td> <td><input type="radio"/> Water Damage</td> <td><input type="radio"/> Forced Airstream</td> </tr> <tr> <td><input type="radio"/> Other: _____</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> &lt;10% Exposed Surface Area</td> </tr> <tr> <td></td> <td><input type="radio"/> &gt;10% Exposed Surface Area</td> <td></td> </tr> </table>			<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input type="radio"/> Activity / Movement	<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input type="radio"/> Forced Airstream	<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> >10% Exposed Surface Area	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible															
<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input type="radio"/> Activity / Movement															
<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input type="radio"/> Forced Airstream															
<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> <10% Exposed Surface Area															
	<input type="radio"/> >10% Exposed Surface Area																
<p><b>Assessment:</b> <input type="radio"/> Not Assessable</p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Friable</td> <td><input type="radio"/> Covering</td> </tr> <tr> <td><input type="radio"/> Non-friable</td> <td><input type="radio"/> Enclosure</td> </tr> <tr> <td><input type="radio"/> Intact and Undamaged</td> <td></td> </tr> <tr> <td><input type="radio"/> Damaged (&lt;10%)</td> <td></td> </tr> <tr> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td></td> </tr> <tr> <td><input type="radio"/> Potential for Damage</td> <td></td> </tr> <tr> <td><input type="radio"/> Potential for Significant Damage</td> <td></td> </tr> </table>			<input type="radio"/> Friable	<input type="radio"/> Covering	<input type="radio"/> Non-friable	<input type="radio"/> Enclosure	<input type="radio"/> Intact and Undamaged		<input type="radio"/> Damaged (<10%)		<input type="radio"/> Significantly Damaged (>10%)		<input type="radio"/> Potential for Damage		<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Friable	<input type="radio"/> Covering																
<input type="radio"/> Non-friable	<input type="radio"/> Enclosure																
<input type="radio"/> Intact and Undamaged																	
<input type="radio"/> Damaged (<10%)																	
<input type="radio"/> Significantly Damaged (>10%)																	
<input type="radio"/> Potential for Damage																	
<input type="radio"/> Potential for Significant Damage																	

Building: 001 Room: 006	Drawing Group Code: 10	USA: 12 0" OD Quantity: 3 SF															
Floor: T Boiler Room	Material: Brick, Fire																
Record No.: <b>9200522</b> Comment: (1992) Stored																	
<p>Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 100px;"><input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Physical Damage</td> <td><input type="radio"/> Student Accessible</td> </tr> <tr> <td><input type="radio"/> Cracking</td> <td><input type="radio"/> Deterioration</td> <td><input type="radio"/> Activity / Movement</td> </tr> <tr> <td><input type="radio"/> Vibration</td> <td><input type="radio"/> Water Damage</td> <td><input type="radio"/> Forced Airstream</td> </tr> <tr> <td><input type="radio"/> Other: _____</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> &lt;10% Exposed Surface Area</td> </tr> <tr> <td></td> <td></td> <td><input type="radio"/> &gt;10% Exposed Surface Area</td> </tr> </table>			<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input type="radio"/> Activity / Movement	<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input type="radio"/> Forced Airstream	<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> <10% Exposed Surface Area			<input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible															
<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input type="radio"/> Activity / Movement															
<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input type="radio"/> Forced Airstream															
<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> <10% Exposed Surface Area															
		<input type="radio"/> >10% Exposed Surface Area															
<p><b>Assessment:</b> <input type="radio"/> Not Assessable</p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Friable</td> <td><input type="radio"/> Covering</td> </tr> <tr> <td><input type="radio"/> Non-friable</td> <td><input type="radio"/> Enclosure</td> </tr> <tr> <td><input type="radio"/> Intact and Undamaged</td> <td></td> </tr> <tr> <td><input type="radio"/> Damaged (&lt;10%)</td> <td></td> </tr> <tr> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td></td> </tr> <tr> <td><input type="radio"/> Potential for Damage</td> <td></td> </tr> <tr> <td><input type="radio"/> Potential for Significant Damage</td> <td></td> </tr> </table>			<input type="radio"/> Friable	<input type="radio"/> Covering	<input type="radio"/> Non-friable	<input type="radio"/> Enclosure	<input type="radio"/> Intact and Undamaged		<input type="radio"/> Damaged (<10%)		<input type="radio"/> Significantly Damaged (>10%)		<input type="radio"/> Potential for Damage		<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Friable	<input type="radio"/> Covering																
<input type="radio"/> Non-friable	<input type="radio"/> Enclosure																
<input type="radio"/> Intact and Undamaged																	
<input type="radio"/> Damaged (<10%)																	
<input type="radio"/> Significantly Damaged (>10%)																	
<input type="radio"/> Potential for Damage																	
<input type="radio"/> Potential for Significant Damage																	

Building: 001 Room: 006	Drawing Group Code:	USA: 11 0" OD Quantity: 36 SF														
Floor: T Boiler Room	Material: Insulation, Kiln															
Record No.: <b>9200517</b> Comment: (1992) -																
<p>Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 100px;"><input type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Physical Damage</td> <td><input type="radio"/> Student Accessible</td> </tr> <tr> <td><input type="radio"/> Cracking</td> <td><input type="radio"/> Deterioration</td> <td><input checked="" type="radio"/> Forced Airstream</td> </tr> <tr> <td><input type="radio"/> Vibration</td> <td><input type="radio"/> Water Damage</td> <td><input checked="" type="radio"/> &lt;10% Exposed Surface Area</td> </tr> <tr> <td><input type="radio"/> Other: _____</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> &gt;10% Exposed Surface Area</td> </tr> </table>			<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input checked="" type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area		
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible														
<input type="radio"/> Cracking	<input type="radio"/> Deterioration	<input checked="" type="radio"/> Forced Airstream														
<input type="radio"/> Vibration	<input type="radio"/> Water Damage	<input checked="" type="radio"/> <10% Exposed Surface Area														
<input type="radio"/> Other: _____	<input type="radio"/> Loose	<input type="radio"/> >10% Exposed Surface Area														
<p><b>Assessment:</b> <input type="radio"/> Not Assessable</p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Friable</td> <td><input checked="" type="radio"/> Covering</td> </tr> <tr> <td><input checked="" type="radio"/> Non-friable</td> <td><input type="radio"/> Enclosure</td> </tr> <tr> <td><input checked="" type="radio"/> Intact and Undamaged</td> <td></td> </tr> <tr> <td><input type="radio"/> Damaged (&lt;10%)</td> <td></td> </tr> <tr> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td></td> </tr> <tr> <td><input checked="" type="radio"/> Potential for Damage</td> <td></td> </tr> <tr> <td><input type="radio"/> Potential for Significant Damage</td> <td></td> </tr> </table>			<input type="radio"/> Friable	<input checked="" type="radio"/> Covering	<input checked="" type="radio"/> Non-friable	<input type="radio"/> Enclosure	<input checked="" type="radio"/> Intact and Undamaged		<input type="radio"/> Damaged (<10%)		<input type="radio"/> Significantly Damaged (>10%)		<input checked="" type="radio"/> Potential for Damage		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Friable	<input checked="" type="radio"/> Covering															
<input checked="" type="radio"/> Non-friable	<input type="radio"/> Enclosure															
<input checked="" type="radio"/> Intact and Undamaged																
<input type="radio"/> Damaged (<10%)																
<input type="radio"/> Significantly Damaged (>10%)																
<input checked="" type="radio"/> Potential for Damage																
<input type="radio"/> Potential for Significant Damage																

(KILN INSULABLE)

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Danica Garcia  
Inspection Date: 11/05/08

Building: 001 Room: 101	Drawing Group Code: 02	USA: 49	0" OD Quantity: 189 SF
Floor: 1 Corridor	Material: Tile, Vinyl Floor, 12X12		
Record No.: <b>9200227</b>	Comment: (1992) Off-white		

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 103	Drawing Group Code: 02	USA: 18	0" OD Quantity: 3 SF
Floor: 1 Dishwashing	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200503</b>	Comment: (1992) Brown		

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>EPOXY COATING</u>	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 103	Drawing Group Code: 02	USA: 17	0" OD Quantity: 20 SF
Floor: 1 Dishwashing	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200502</b>	Comment: (1992) Light gray		

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking <input type="radio"/> Deterioration <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration <input type="radio"/> Water Damage <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: <u>EPOXY COATING</u>	<input type="radio"/> Potential for Damage
	<input type="radio"/> Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Conner  
Inspection Date: 11/20/08

Building: 001 Room: 103	Drawing Group Code: 02	USA: 16 0" OD Quantity: 75 SF
Floor: 1 Dishwashing	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200501</b>	Comment: (1992) Light tan	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage

EPOXY COATING

Building: 001 Room: 103	Drawing Group Code: 02	USA: 14 0" OD Quantity: 110 SF
Floor: 1 Dishwashing	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200500</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage

EPOXY COATING

Building: 001 Room: 104	Drawing Group Code: 02	USA: 14 0" OD Quantity: 387 SF
Floor: 1 Kitchen	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200490</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<b>Assessment:</b> <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage

EPOXY COATING

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Deanna G... ..  
Inspection Date: 11/01/08

Building: 001 Room: 104	Drawing Group Code: 02	USA: 15 0" OD Quantity: 1 SF
Floor: 1 Kitchen	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200494</b>	Comment: (1992) Purple	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage

EPOXY COATING

Building: 001 Room: 107	Drawing Group Code: 02	USA: 14 0" OD Quantity: 140 SF
Floor: 1 Serving	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200505</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage

EPOXY COATING

Building: 001 Room: 110A	Drawing Group Code: 02	USA: 28 0" OD Quantity: 60 SF
Floor: 1 Stairs	Material: Sheetting, Linoleum/Vinyl	
Record No.: <b>9200376</b>	Comment: (1992) Tan/yellow-on walls	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	Assessment: <input type="radio"/> Not Assessable
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
		<input type="radio"/> Potential for Significant Damage





# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: PATRICIA GARDNER  
Inspection Date: 11/05/08

Building: 001 Room: 121	Drawing Group Code: 02	USA: 49 0" OD Quantity: 288 SF
Floor: 1 Corridor	Material: Tile, Vinyl Floor, 12X12	
Record No.: <b>9200279</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 122C	Drawing Group Code: 02	USA: 49 0" OD Quantity: 9 SF
Floor: 1 Vestibule	Material: Tile, Vinyl Floor, 12X12	
Record No.: <b>9200272</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 122D	Drawing Group Code: 02	USA: 49 0" OD Quantity: 9 SF
Floor: 1 Vestibule	Material: Tile, Vinyl Floor, 12X12	
Record No.: <b>9200271</b>	Comment: (1992) Off-white	

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain in Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: PATRICIA GARCIA  
Inspection Date: 11/05/08

Building: 001 Room: 123	Drawing Group Code: 02	USA: 58	0" OD Quantity: 40 SF
Floor: 1 Gym	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200262</b>	Comment: (1992) Light brown		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)			<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)			<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing	<input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
	<input type="radio"/> Physical Damage	<input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input checked="" type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____			<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: 123	Drawing Group Code: 02	USA: 57	0" OD Quantity: 4337 SF
Floor: 1 Gym	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200259</b>	Comment: (1992) Light brown		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)			<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)			<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing	<input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
	<input type="radio"/> Physical Damage	<input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input checked="" type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____			<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: 123A	Drawing Group Code: 02	USA: 57	0" OD Quantity: 100 SF
Floor: 1 Physical Education O	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200263</b>	Comment: (1992) Light brown		
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)			<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)			<input type="radio"/> Friable <input type="radio"/> Covering
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing	<input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
	<input type="radio"/> Physical Damage	<input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Water Damage	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Loose	<input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Damage
<input type="radio"/> Other: <u>AT TIMES; AREA LOCATED</u>			<input type="radio"/> Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Gurem  
Inspection Date: 11/10/08

Building: 001 Room: 123B	Drawing Group Code: 02	USA: 57 0" OD Quantity: 100 SF
Floor: 1 Storage	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200284</b>	Comment: (1992) Light brown	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input checked="" type="radio"/> Deterioration <input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input checked="" type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking <input checked="" type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration <input checked="" type="radio"/> Loose		<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<u>Area NOT LOCUS</u>	<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: 124	Drawing Group Code: 02	USA: 57 0" OD Quantity: 21 SF
Floor: 1 Vestibule	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200275</b>	Comment: (1992) Light brown	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration <input type="radio"/> Loose		<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____		<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 125	Drawing Group Code: 02	USA: 57 0" OD Quantity: 21 SF
Floor: 1 Vestibule	Material: Tile, Vinyl Floor, 9X9	
Record No.: <b>9200266</b>	Comment: (1992) Light brown	

Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
<b>Justification:</b>	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration <input type="radio"/> Loose		<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____		<input type="radio"/> Potential for Significant Damage

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Garcia  
Inspection Date: 11/05/02

Building: 001 Room: 223	Drawing Group Code: 02	USA: 27	0" OD Quantity: 492 SF
Floor: 2 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200146</b>	Comment: (1992) Dark red/white & tan		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable	
		<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering	
		<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>		<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area			
<input type="radio"/> Other: _____			

Building: 001 Room: 223	Drawing Group Code: 02	USA: 42	0" OD Quantity: 212 SF
Floor: 2 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200147</b>	Comment: (1992) Light brown (1996) Duplicate of record 9200148.		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable	
		<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering	
		<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>		<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area			
<input type="radio"/> Other: _____			

Building: 001 Room: 223	Drawing Group Code: 02	USA: 42	0" OD Quantity: 212 SF
Floor: 2 Classroom	Material: Tile, Vinyl Floor, 9X9		
Record No.: <b>9200148</b>	Comment: (1992) Light brown		
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		<b>Assessment:</b> <input type="radio"/> Not Assessable	
		<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Friable <input type="radio"/> Covering	
		<input type="radio"/> Non-friable <input type="radio"/> Enclosure	
<b>Justification:</b>		<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible		<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement		<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream		<input type="radio"/> Potential for Damage	
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area		<input type="radio"/> Potential for Significant Damage	
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area			
<input type="radio"/> Other: _____			

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Garcia  
Inspection Date: 4/10/08

Building: 001 Room: 223A	Drawing Group Code: 02	USA: 27 0" OD Quantity: 24 SF											
Floor: 2 Closet	Material: Tile, Vinyl Floor, 9X9												
Record No.: <b>9200154</b>	Comment: (1992) Dark red/white & tan												
<p>Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 150px;"><input type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Deterioration</td> <td><input type="radio"/> Water Damage</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> Missing TSI Jacketing</td> <td><input type="radio"/> Physical Damage</td> <td><input type="radio"/> Student Accessible</td> <td><input type="radio"/> Activity / Movement</td> <td><input type="radio"/> Forced Airstream</td> <td><input type="radio"/> &lt;10% Exposed Surface Area</td> <td><input type="radio"/> &gt;10% Exposed Surface Area</td> </tr> </table> <p><input type="radio"/> Other: _____</p>			<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area			
<p><b>Assessment:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Friable</td> <td><input type="radio"/> Non-friable</td> <td><input type="radio"/> Intact and Undamaged</td> <td><input type="radio"/> Damaged (&lt;10%)</td> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td><input type="radio"/> Potential for Damage</td> <td><input type="radio"/> Potential for Significant Damage</td> </tr> </table>			<input type="radio"/> Friable	<input type="radio"/> Non-friable	<input type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input type="radio"/> Potential for Significant Damage				
<input type="radio"/> Friable	<input type="radio"/> Non-friable	<input type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input type="radio"/> Potential for Significant Damage							

Building: 001 Room: A-2	Drawing Group Code: 13	USA: 53 0" OD Quantity: 16 SF										
Floor: 2 Attic Space	Material: Cloth, Vibration Joint											
Record No.: <b>9200290</b>	Comment: (1992) White-(2) each (1996) 3 EA - 20 SF.											
<p>Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 150px;"><input type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Deterioration</td> <td><input type="radio"/> Water Damage</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> Missing TSI Jacketing</td> <td><input type="radio"/> Physical Damage</td> <td><input checked="" type="radio"/> Activity / Movement</td> <td><input checked="" type="radio"/> Forced Airstream</td> <td><input type="radio"/> &lt;10% Exposed Surface Area</td> <td><input checked="" type="radio"/> &gt;10% Exposed Surface Area</td> </tr> </table> <p><input type="radio"/> Other: _____</p>			<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input checked="" type="radio"/> Activity / Movement	<input checked="" type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> >10% Exposed Surface Area			
<p><b>Assessment:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input checked="" type="radio"/> Friable</td> <td><input checked="" type="radio"/> Non-friable</td> <td><input checked="" type="radio"/> Intact and Undamaged</td> <td><input type="radio"/> Damaged (&lt;10%)</td> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td><input type="radio"/> Potential for Damage</td> <td><input checked="" type="radio"/> Potential for Significant Damage</td> </tr> </table>			<input checked="" type="radio"/> Friable	<input checked="" type="radio"/> Non-friable	<input checked="" type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input checked="" type="radio"/> Potential for Significant Damage			
<input checked="" type="radio"/> Friable	<input checked="" type="radio"/> Non-friable	<input checked="" type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input checked="" type="radio"/> Potential for Significant Damage						

Building: 001 Room: A-2	Drawing Group Code: 07	USA: 45 10" OD Quantity: 2 EA											
Floor: 2 Attic Space	Material: Insulation, MJP on Tar Lined Pipe												
Record No.: <b>9200297</b>	Comment: (1992) Above permanent ceiling												
<p>Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)</p> <p style="margin-left: 150px;"><input type="radio"/> Not Found <input type="radio"/> Definitely Not Present</p> <p>Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)</p> <p><b>Justification:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Blistering</td> <td><input type="radio"/> Deterioration</td> <td><input type="radio"/> Water Damage</td> <td><input type="radio"/> Loose</td> <td><input type="radio"/> Missing TSI Jacketing</td> <td><input type="radio"/> Physical Damage</td> <td><input type="radio"/> Student Accessible</td> <td><input type="radio"/> Activity / Movement</td> <td><input type="radio"/> Forced Airstream</td> <td><input type="radio"/> &lt;10% Exposed Surface Area</td> <td><input type="radio"/> &gt;10% Exposed Surface Area</td> </tr> </table> <p><input type="radio"/> Other: _____</p>			<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Blistering	<input type="radio"/> Deterioration	<input type="radio"/> Water Damage	<input type="radio"/> Loose	<input type="radio"/> Missing TSI Jacketing	<input type="radio"/> Physical Damage	<input type="radio"/> Student Accessible	<input type="radio"/> Activity / Movement	<input type="radio"/> Forced Airstream	<input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> >10% Exposed Surface Area			
<p><b>Assessment:</b></p> <table style="width: 100%; border: none;"> <tr> <td><input type="radio"/> Friable</td> <td><input type="radio"/> Non-friable</td> <td><input type="radio"/> Intact and Undamaged</td> <td><input type="radio"/> Damaged (&lt;10%)</td> <td><input type="radio"/> Significantly Damaged (&gt;10%)</td> <td><input type="radio"/> Potential for Damage</td> <td><input checked="" type="radio"/> Potential for Significant Damage</td> </tr> </table>			<input type="radio"/> Friable	<input type="radio"/> Non-friable	<input type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input checked="" type="radio"/> Potential for Significant Damage				
<input type="radio"/> Friable	<input type="radio"/> Non-friable	<input type="radio"/> Intact and Undamaged	<input type="radio"/> Damaged (<10%)	<input type="radio"/> Significantly Damaged (>10%)	<input type="radio"/> Potential for Damage	<input checked="" type="radio"/> Potential for Significant Damage							

# KCMSD 2008 Triennial Re-inspection

920 / West Rock Creek Elementary School  
8820 E. 27th Street

Inspector: Patricia Garner  
Inspection Date: 11/05/08

Building: 001	Room: A-2	Drawing Group Code: 07	USA: 45	6" OD	Quantity: 1 EA
Floor: 2	Attic Space	Material: Insulation, MJP on Tar Lined Pipe			
Record No.: <b>9200296</b>	Comment: (1992) Above permanent ceiling-quantities only what is visible				
Quantity Within 20%? <input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)			<b>Assessment:</b> <input checked="" type="radio"/> Not Assessable		
			<input type="radio"/> Friable <input type="radio"/> Covering		
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)			<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
<b>Justification:</b>			<input type="radio"/> Intact and Undamaged		
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible			<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement			<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input type="radio"/> Forced Airstream			<input type="radio"/> Potential for Damage		
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area			<input type="radio"/> Potential for Significant Damage		
<input type="radio"/> Vibration <input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area					
<input type="radio"/> Other: _____					

Building: 001	Room: A-3	Drawing Group Code: 13	USA: 53	0" OD	Quantity: 8 SF
Floor: 2	Attic Space	Material: Cloth, Vibration Joint			
Record No.: <b>9200294</b>	Comment: (1992) White-(3) each				
Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)			<b>Assessment:</b> <input type="radio"/> Not Assessable		
			<input checked="" type="radio"/> Friable <input checked="" type="radio"/> Covering		
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)			<input type="radio"/> Non-friable <input type="radio"/> Enclosure		
<b>Justification:</b>			<input checked="" type="radio"/> Intact and Undamaged		
<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible			<input type="radio"/> Damaged (<10%)		
<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement			<input type="radio"/> Significantly Damaged (>10%)		
<input type="radio"/> Blistering <input type="radio"/> Deterioration <input checked="" type="radio"/> Forced Airstream			<input type="radio"/> Potential for Damage		
<input type="radio"/> Cracking <input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area			<input checked="" type="radio"/> Potential for Significant Damage		
<input checked="" type="radio"/> Vibration <input type="radio"/> Loose <input checked="" type="radio"/> >10% Exposed Surface Area					
<input type="radio"/> Other: _____					