



Under slab plumbing was completed, inspected and tested last week.



Drain rock is being placed on the east side of the new classroom addition.



A close up view of the plumbing under the main bathrooms.



Backfill placement and grading is progressing.



Compaction are underway within the classroom area.



Perimeter foundation insulation and the capillary break are both shown in this photo.