	FPC Item Summary			
Todd Elementary				
Item #	ARCHITECTURAL ITEMS	Cost	Priority	
2	Add fall protection to existing dome skylights			
	(21 locations).	\$29,400	IA	
13	Add missing handrails at interior ramps (wall			
16	or post mounted).	\$168,000	IA	
16	Remove and replace corridor partition/doors with wood louvers and gypsum infills (at			
	Storage/Custodial Rms) with rated CMU			
	construction and doors. Extend demising			
	walls to underside of roof deck. (3 locations).	\$97,450	IB	
17	Additional storm drainage and piping near	70.7.00		
	Library.	\$35,000	П	
19	Repair leaks at Corridor windows (near			
	interior courtyards).	\$17,500	П	
20	Replace EPDM roof areas (1995).	\$619,000	П	
21	Replace TPO roof areas (2002).	\$2,352,000	П	
22	Install missing gutters and downspouts at			
	pitched roof. Reconnect existing loose or missing downspouts.	Ć40E 000	.,	
24	Security vestibule upgrades (transaction	\$105,000	II	
24	window and security film over existing			
	glazing.	\$32,900	П	
29	Replace caulking at masonry control joints and	, - ,		
	expansion joints.	\$30,800	Ш	
30	Tuckpoint mortar joints and replace damaged			
	brick.	\$112,000	Ш	
	ARCHITECTURAL TOTAL	\$3,599,050		
_	HVAC ITEMS	Cost	Priority	
1	Replace six older type rooftop exhaust fans to			
	restore to proper operation, and provide adequate ventilation in the bathroom areas.	ć120 000	1.0	
2	Provide a relief air path from classroom 111,	\$120,000	IA	
	which was subdivided from classroom 110.	\$10,000	IA	
3	Ensure that all rooftop exhaust fans are	710,000	1/4	
-	turned on during occupied times. It was			
	observed during our walkthrough that several			
	of the bathroom fans did not appear to be on.			
	Upgrade controls as required.	\$50,000	IA	

4	Cap all unused ducts in room 155 storage		
6	room as required by code. Provide humidity controls on the two unit	\$5,000	IA
	ventilators in the library to alleviate the musty odor as discussed.	\$15,000	IB
	HVAC TOTAL	\$200,000	16
	PLUMBING ITEMS	Cost	Priority
1	Provide a separate drinking fountain basin in		
	room 217, and remove the bubbler from the		
_	classroom sink as required by code.	\$5,000	IA
2	Provide a natural gas leak detection system in	4	
4	the boiler room area.	\$50,000	IB
4	Replace seven waterless urinals with new low flow urinals as discussed.	¢42.000	
	PLUMBING TOTAL	\$42,000 \$97,000	III
	ELECTRICAL ITEMS	Cost	Priority
1	Provide exit lighting, fire alarm pull stations,	COST	THOTICY
	and raise the light fixture in the small		
	courtyard.	\$15,000	IA
2	Retrofit the original Metropolitan circuit		
	breaker panel in the slop sink and fill all		
	missing spaces as required by code.	\$20,000	IA
3	Replace the non-functional exit signs in the		
	larger courtyard, as well as adding pull		
4	stations and one horn/strobe unit.	\$15,000	IA
4	In the other larger courtyard, replace the non- functional exit signs, and add two fire alarm		
	pull stations as required.	\$12,500	IA
5	In the front courtyard provide pull stations and	\$12,500	IA
3	replace the non-functional exit signs as		
	required.	\$10,000	IA
8	Retrofit the original Frank Adams circuit	. ,	
	breaker panels, for which replacement parts		
	are no longer available. Assume six panels		
	total.	\$120,000	II
11	Provide hardwired carbon monoxide detectors		
	tied into the building's fire alarm system to		
	replace the current battery and line voltage detectors.	647.500	
27		\$17,500	II
۷1	Replace the screw in fuse type panel in the repair garage with a new 100 amp circuit		
	breaker panel.	\$15,000	III
	•	713,000	

34	Provide surge suppression at the main switchgear location to eliminate power surges. ELECTRICAL TOTAL TODD ELEMENTARY SCHOOL TOTALS ARCHITECTURAL TOTAL HVAC TOTAL PLUMBING TOTAL ELECTRICAL TOTAL BUILDING TOTAL	\$30,000 \$255,000 \$3,599,050 \$200,000 \$97,000 \$255,000 \$4,151,050	III
	Middle School/ High School		
3	ARCHITECTURAL ITEMS Replace guardrail at exterior Auditorium ramp	Cost	Priority
_	with proper height and baluster spacing at High School.	\$25,200	IA
4	Firestop/seal penetrations and top of wall in Auditorium Mechanical Rm., Switchgear Rm. and Art Rm. at High School.	\$24,500	IA
6	Provide required rated separation between Maresca Center and Corridor with doors/partition (near Rm. 102) at High School.	Ć22.750	1.0
9	Repair missing spray applied fireproofing over structural steel columns/braces in Mechanical Room at Middle School.	\$22,750 \$3,500	IA IA
10	Firestop/seal penetrations and top of wall in Electrical Rm. (near Rm. 218) at Middle	73,300	IA
15	School. Remove corridor lockers where egress width is reduced to less than 8'-0" wide when locker	\$4,750	IA
16	doors are open at High School. Remove manual hold open devices at	\$21,000	IA
	Gymnasium Corridor doors (replace door closer or add magnetic holders).	\$4,480	IA
17	Remove floor stops (w/ padlocks) in Boys/Girls toilet rooms at High School (near Rm. 120).	\$700	IA
21	Replace guardrail/ballusters and handrails in interior stairwells (four locations) at High School.	\$138,600	IB

Replace damaged, coated or bulging brick and tuckpoint mortar joints (both sides) at fuel tank/electrical enclosure. Tuckpoint mortar joints and replace damaged brick at High School. Replace exterior concrete stairs/handrails at parking lot (3) and upper level tennis courts. (excludes MS entry and MS Cafeteria stairs). Replace EPDM roof areas (2002) and modify masonry/flashing (excludes Gym) at Middle School. Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. Replace carpet in Music Rm. 90 at Middle School. Replace Auditorium seating (200 seats) at Middle School. Replace Auditorium seating (200 seats) at Middle School. Replace Auditorium seating (200 seats) at High School. Infill Light Well ARCHITECTURAL TOTAL: S8,933,888 Cost Priority The WAC ITEMS S8,933,888 Cost Priority It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to operation.				
Replace exterior concrete stairs/handrails at parking lot (3) and upper level tennis courts. (excludes MS entry and MS Cafeteria stairs). \$490,000 II Replace EPDM roof areas (2002) and modify masonry/flashing (excludes Gym) at Middle School. \$2,181,725 II Replace damaged/clogged roof leader and scupper (near loading dock) at Middle School. \$2,450 II \$2,450 II Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. \$4,898,775 II \$28 Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. \$32,900 II \$33 Replace carpet in Music Rm. 90 at Middle School. \$23,758 III \$34,898,775 II \$35,758 III \$35,758 III \$35,759	22	tuckpoint mortar joints (both sides) at fuel tank/electrical enclosure. Tuckpoint mortar joints and replace damaged brick at High	\$265,000	II
Replace EPDM roof areas (2002) and modify masonry/flashing (excludes Gym) at Middle School. Replace damaged/clogged roof leader and scupper (near loading dock) at Middle School. Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. Replace Carpet in Music Rm. 90 at Middle School. Replace Auditorium seating (200 seats) at High School. Infill Light Well ARCHITECTURAL TOTAL: ARCHITECTURAL TOTAL: Separate Auditorium seating (200 seats) at High School. It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to	23	parking lot (3) and upper level tennis courts.		
Replace damaged/clogged roof leader and scupper (near loading dock) at Middle School. Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. Replace carpet in Music Rm. 90 at Middle School. Replace Auditorium seating (200 seats) at Middle School. Replace Auditorium seating (200 seats) at Middle School. Provide single key system (replace 200 cores) at High School. Infill Light Well ARCHITECTURAL TOTAL: ARCHITECTURAL TOTAL: S8,933,888 HVAC ITEMS It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to	24	Replace EPDM roof areas (2002) and modify masonry/flashing (excludes Gym) at Middle		
Replace EPDM roof areas (1998), skylights and modify masonry/flashing (excludes Gym) at High School. \$4,898,775 II Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. \$32,900 II Replace carpet in Music Rm. 90 at Middle School. \$23,758 III Replace Auditorium seating (200 seats) at Middle School. \$107,800 III Provide single key system (replace 200 cores) at High School. \$42,000 III ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Cost Priority It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to	25	Replace damaged/clogged roof leader and	\$2,181,725	II
modify masonry/flashing (excludes Gym) at High School. \$4,898,775 II 28 Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. \$32,900 II 33 Replace carpet in Music Rm. 90 at Middle School. \$23,758 III 37 Replace Auditorium seating (200 seats) at Middle School. \$107,800 III 38 Provide single key system (replace 200 cores) at High School. \$42,000 III - Infill Light Well \$644,000 - ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Cost Priority 1 It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA 2 Replace the non-functional exhaust fan in the main electrical meter room to restore to			\$2,450	II
Security vestibule upgrades (transaction window and security film over existing glazing at High School and Middle School. \$32,900 II Replace carpet in Music Rm. 90 at Middle School. \$23,758 III Replace Auditorium seating (200 seats) at Middle School. \$107,800 III Provide single key system (replace 200 cores) at High School. \$44,000 III Infill Light Well \$644,000 - \$8,933,888 HVAC ITEMS It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to	26	modify masonry/flashing (excludes Gym) at		
at High School and Middle School. Replace carpet in Music Rm. 90 at Middle School. \$23,758 III Replace Auditorium seating (200 seats) at Middle School. Provide single key system (replace 200 cores) at High School. Infill Light Well ARCHITECTURAL TOTAL: Yespan, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to	28	Security vestibule upgrades (transaction	\$4,898,775	II
School. \$23,758 III Replace Auditorium seating (200 seats) at Middle School. \$107,800 III Provide single key system (replace 200 cores) at High School. \$42,000 III Infill Light Well \$644,000 - \$8,933,888	33	at High School and Middle School.	\$32,900	II
Replace Auditorium seating (200 seats) at Middle School. \$107,800 III Provide single key system (replace 200 cores) at High School. \$42,000 III Infill Light Well \$644,000 - ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Cost Priority It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to	33	·	\$23.758	
Middle School. \$107,800 III Provide single key system (replace 200 cores) at High School. \$42,000 III Infill Light Well \$644,000 - ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Cost Priority It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to	37		723,730	""
38 Provide single key system (replace 200 cores) at High School. \$42,000 III - Infill Light Well \$644,000 - ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Cost Priority 1 It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA 2 Replace the non-functional exhaust fan in the main electrical meter room to restore to			\$107.800	ııı l
at High School. Infill Light Well ARCHITECTURAL TOTAL: \$8,933,888 HVAC ITEMS Scost HVAC ITEMS It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to	38	Provide single key system (replace 200 cores)	7 = 0 : 7 = 0	
ARCHITECTURAL TOTAL: HVAC ITEMS It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. Replace the non-functional exhaust fan in the main electrical meter room to restore to		at High School.	\$42,000	III
HVAC ITEMS It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. 2 Replace the non-functional exhaust fan in the main electrical meter room to restore to	-	Infill Light Well	\$644,000	-
It was reported that the building exhaust fans were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to		ARCHITECTURAL TOTAL:	\$8,933,888	
were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control system items, which are all priced individually, but should be addressed as a whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to		HVAC ITEMS	Cost	Priority
whole. \$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to	1	were controlled by an old day/night control system, that no longer works. This system should be repaired or replaced, as these fans are required to operate whenever the school is occupied. This is one of a few control		
\$50,000 IA Replace the non-functional exhaust fan in the main electrical meter room to restore to		individually, but should be addressed as a		
2 Replace the non-functional exhaust fan in the main electrical meter room to restore to		whole.	\$50.000	IA
operation. \$20,000 IA	2	·	430,000	,,
		operation.	\$20,000	IA

3	Uncover the combustion air intake louver in the boiler room, and provide a motorized damper to automatically close the damper when the boilers are not firing.	\$20,000	IA
4	Provide an exhaust fan in the copy room adjacent to the nurses office, and vent directly to the exterior. The current fan exhausts into the hallway currently.	\$20,000	IA
5	Provide a new transfer grille in the art room 121 storage room to restore to original operation. Original grille has been permanently covered over.		
8	Repair the insulation on the MS cafeteria ductwork to eliminate condensation from dripping down onto the ceiling and then on down to the walls and floor.	\$10,000	IA
10	Repair the insulation on the duct above the ceiling in HS room 110, which also drips onto the ceiling, and eventually down into the	\$25,000	II
11	space. Provide a Variable Frequency Drive (VFD) on the MS Cafeteria chilled water A/C unit supply fan, add a humidity sensor, and add controls to allow for the unit to better dehumidify the cafeteria, which is reported to get cool and	\$15,000	II
12	humid. Repair the chilled water pipe insulation in the MS/HS, especially at valves or saddles, where condensation forms and leaks down onto the	\$35,000	II
15	hung ceiling tiles. Replace 15 original rooftop exhaust fans, which are at or nearing end of life expectancy,	\$100,000	II
18	to restore to proper operation. Replace 7 older Carrier rooftop HVAC units, which are nearing the end of their life expectancy. New units will also improve comfort conditions and system energy efficiency. The units on the gyms will be replaced as part of the current gym roof	\$300,000	II
	replacement.	\$1,400,000	Ш

21	Upgrade the entire Automatic Temperature Control (ATC) system which currently consists of an older JCI Metasys panel as well as original pneumatic controls. Provide a new full DDC System to improve overall comfort levels, as well as eliminating the resultant over and under heating conditions. Provide new temperature sensors with a three degree adjustment band and an override feature.		
		\$750,000	Ш
22	Provide Rawal Valves and new humidity controls for the HS Cafeteria rooftop unit to	. ,	
	reduce the humidity in the space.	\$25,000	Ш
	HVAC TOTAL	\$2,770,000	
	PLUMBING ITEMS	Cost	Priority
1	Provide air gaps on all kitchen equipment drains as required by code.	\$20,000	IA
2	Perform maintenance on the acid neutralizing pit in the HS electrical room adjacent to room 110, to reduce odors and restore system to	,	
	proper operation.	\$20,000	IA
6	Repair or provide a new domestic hot water recirculation system and pumps for the Middle School to allow for hot water in the building in a timely manner as required by code.	4400 000	
7		\$100,000	IA
7	Provide a natural gas leak detection system in the boiler room area.	\$50,000	IB
12	Provide trap seals on floor drains that continuously dry out as discussed.	\$10,000	Ш
14	Replace nine waterless urinals with new low		
	flow urinals.	\$54,000	Ш
	PLUMBING TOTAL	\$254,000	
	ELECTRIC ITEMS	Cost	Priority
1	The HS has a combination off bell/strobe units as well as horn/stroke units, which is not allowed by code. Convert all existing bell/strobe units over to the more prevalent horn/strobe unit configuration. Assume 50		
	units,	\$75,000	IA
5	Provide exit and emergency lighting in the HS chorus room, as it is classified as an area of	773,000	IΛ
	assembly, and requires same.	\$10,000	IA

6	Provide exit lighting, emergency lighting, horn/strobe units and fire alarm pull stations in the library courtyard.	\$18,000	IA
7	Firestop all penetrations in the MS second	Ψ10,000	,,,
	floor electrical room as required by code.	\$5,000	IA
9	Provide magnetic hold open devices on large group spaces including the theatre, libraries, band/chorus rooms, gymnasiums, student cafeterias, etc., to allow for lockdowns as discussed. Assume 20 doors total.	\$120,000	II
22	Provide hardwired carbon monoxide detectors tied into the building's fire alarm system to replace the current battery and line voltage	Ų123,000	
	detectors.	\$25,000	П
29	Provide surge suppression at the main switchgear location to eliminate power		
	surges.	\$30,000	Ш
	ELECTRICAL TOTAL	\$283,000	
	HIGH SCHOOL/MIDDLE SCHOOL TOTALS		
	ARCHITECTURAL TOTAL	\$8,933,888	
	HVAC TOTAL	\$2,770,000	
	PLUMBING TOTAL	\$254,000	
	ELECTRICAL TOTAL	\$283,000	
	BUILDING TOTAL	\$12,240,888	
	Todd/MS/HS Total	\$16,391,938	

BBS Architectual Recommended Additions					
	Todd Elementary				
9	Renovate and enlarge Nurse's Office toilet for				
	ADA accessibility.	\$77,000	IA		
11	Renovate and enlarge Toilet Rms (near Rm.				
	156 and 125) for ADA .	\$208,325	IA		
12	Provide District-Wide portable lift for ADA				
	accessibility.	\$77,000	IA		
	Todd Addition Totals	\$362,325			
	Middle School/ High School				
7	Create alcove and reverse door swing toward				
	corridor in spaces over 1000 sf at Classrooms				
	101/102 and 209/210 (with folding partitions)				
	at Middle School.	\$165,250	IA		

18	Create alcove and reverse door swing toward corridor in spaces over 1000 sf at Classrooms	\$247,800	IA
19	Enlarge and renovate student toilet rooms for		
	ADA accessibility at High School (four		
	locations).	\$1,479,800	IA
	MS/HS Addition Totals	\$1,892,850	
	BBS Addition Total	\$2,255,175	
	Project Total w/ BBS Recommendations	\$18,647,113	