

## ASBESTOS MATERIALS

The following materials either tested positive or are presumed to be asbestos-containing. Materials that had mixed results are considered positive. Materials not sampled or not listed in this report may contain asbestos and should be tested to verify asbestos content prior to impact, demolition, renovation, etc.

(+) Tested Positive, (M) Mixed Results, (P) Presumed Positive

| <b>Errol Hassell Main Building (EH1)</b> |   |                         |                 |
|--|---|-------------------------|-----------------|
| <b>Result</b>                            | <b>Material</b>   | <b>Location</b>         | <b>Quantity</b> |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. [ID: 24525]   | Level 1 / B100          | 138 sf          |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. [ID: 24526]   | Level 1 / B102          | 235 sf          |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. [ID: 24527]   | Level 1 / B104          | 240 sf          |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. [ID: 24528]   | Level 1 / B110          | 240 sf          |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. [ID: 24529]   | Level 1 / B112          | 237 sf          |
| P  | Sheet Flooring Material and Mastic / Visible-PACM / /, Cmmt: Flooring encapsulated 7/15/00. Cracked at door [ID: 24530]   | Level 1 / B114          | 140 sf          |
| P  | Floor Tile and Mastic / Visible-Positive 712x127 HSA 99, Cmmt: Abated July 2002 [ID: 24674]   | Level 1 / Cafeteria     | 0 sf            |
| P  | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Abated 25 sf June 2013 front of stage. One broken tile near stage stairs and 2 at east entry- consider repair 6/14 inspection. [ID: 24675] | Level 1 / Gym           | 4175 sf         |
| P  | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24676]   | Level 1 / Gym Office    | 92 sf           |
| P  | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: minor cracking through center of room [ID: 24677]  | Level 1 / Gym Storage   | 78 sf           |
| P  | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24678]   | Level 1 / Health Room   | 123 sf          |
| P  | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Abated July 2002 [ID: 24679]   | Level 1 / Main Corridor | 0 sf            |

| Errol Hassell Main Building (EH1) |  |                             |          |
|-----------------------------------|--|-----------------------------|----------|
| Result                            | Material   | Location                    | Quantity |
| +                                 | Mastic / Layer 3 / Black / Tested Positive, Cmmt: Chrysotile 10 % (0014605-003) Abated Summer 2013 [ID: 29193]         | Level 1 / Main Office       | 0 sf     |
| +                                 | Floor Tile / Layer 2 / Brown / Tested Positive, Cmmt: Abated Summer 2013 [ID: 29192]                                   | Level 1 / Main Office       | 0 sf     |
| P                                 | Floor Tile and Mastic / Non-Visible PACM / / HSA 99, Cmmt: Abated 308 SF June 2013 [ID: 24680]                         | Level 1 / Main Office       | 0 sf     |
| +                                 | Cove Base Mastic / Brown / Tested Positive, Cmmt: Abated 70 LF June 2013 [ID: 29089]                                   | Level 1 / Principal Office  | 0 sf     |
| P                                 | Floor Tile and Mastic / Non-Visible PACM / / HSA 99, Cmmt: Abated 250 SF June 2013 (Concrete under carpet) [ID: 24681] | Level 1 / Principal Office  | 0 sf     |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24682]  | Level 1 / Restroom Boys 2   | 310 sf   |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24683]  | Level 1 / Restroom Girls 2  | 310 sf   |
| P                                 | Sheet Flooring Material and Mastic / Visible-PACM / / [ID: 24684]  | Level 1 / Restroom Unisex 1 | 54 sf    |
| P                                 | Sheet Flooring Material and Mastic / Visible-PACM / / [ID: 24685]  | Level 1 / Restroom Unisex 2 | 28 sf    |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Abated July 2002 [ID: 24686]                        | Level 1 / Staff             | 0 sf     |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24687]  | Level 1 / Storage 1         | 242 sf   |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99 [ID: 24688]  | Level 1 / Storage 2         | 210 sf   |
| P                                 | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Abated July 2002 [ID: 24689]                        | Level 1 / Work Room 1       | 0 sf     |

## MATERIALS THAT TESTED NEGATIVE

The following materials tested negative. Although no asbestos was detected, it is possible that further sampling could indicate asbestos content. It may be prudent to test prior to impact, demolition, renovation, etc.

| Errol Hassell Main Building (EH1) |                                       |
|-----------------------------------|---------------------------------------|
| Material                          | Location                              |
| Ceramic Tile/Grout                | Kitchen dishwasher area; ceramic cove |

| <b>Errol Hassell Main Building (EH1)</b>  |  |
|---|--|
| <b>Material</b>   | <b>Location</b>                                |
| Gypsum Wallboard/Joint Compound   | Kitchen dishwasher area; gypsum/joint compound |
| Gypsum Wallboard/Joint Compound   | Kitchen dishwasher area; gypsum/joint compound |
| Hard Fitting / Tested Negative, Cmnt: Non-Detect (19766.030-0022 phase 4) [ID: 28639]                             | Level 1 / A Hall                               |
| Roofing Debris / Tested Negative, Cmnt: Non-Detect (19766.030-0021 phase 4) [ID: 28638]                           | Level 1 / A108                                 |
| Hard Fitting / Tested Negative, Cmnt: Non-Detect (19766.030-0012 phase 4) [ID: 28631]                             | Level 1 / A112                                 |
| Lay-in Ceiling Tile / Tested Negative, Cmnt: Non-Detect (19766.030-0001, -0002 phase 4) [ID: 28626]               | Level 1 / A112                                 |
| Duct Felt Tape / Tested Negative, Cmnt: Non-Detect (19766.030-0003, -0011 phase 4) [ID: 28627]                    | Level 1 / A112                                 |
| Chalk Board Mastic / Tan / Tested Negative, Cmnt: non-detect [ID: 26098]  | Level 1 / A122                                 |
| Gypsum Wallboard/Joint Compound / Tested Negative, Cmnt: Non-Detect (19766.030-0017 phase 4) [ID: 28636]          | Level 1 / B108                                 |
| Lay-in Ceiling Tile / Tested Negative, Cmnt: Non-Detect (19766.030-0015 phase 4) [ID: 28634]                      | Level 1 / East Hall                            |
| Lay-in Ceiling Tile / Tested Negative, Cmnt: Non-Detect (19766.030-0016 phase 4) [ID: 28635]                      | Level 1 / Kitchen                              |
| Wall Vinyl / Tested Negative, Cmnt: Non-Detect (19766.030-0014 phase 4) [ID: 28633]                               | Level 1 / Library                              |
| Gypsum Wallboard/Joint Compound / Tested Negative, Cmnt: Non-Detect (19766.030-0004, -0008 phase 4) [ID: 28628]   | Level 1 / Library                              |
| Lay-in Ceiling Tile / Tested Negative, Cmnt: Non-Detect (19766.030-0005, -0006, -0009, -0010 phase 4) [ID: 28629] | Level 1 / Library                              |
| Carpet Mastic / Tested Negative, Cmnt: Non-Detect (19766.030-0007 phase 4) [ID: 28630]                            | Level 1 / Library                              |
| Carpet Adhesive / Layer 1 / Tan / Tested Negative, Cmnt: Non-Detect (0014605-004) [ID: 29191]                     | Level 1 / Main Office                          |
| Gypsum Wallboard/Joint Compd.   | Restrooms 1                                    |
| Ceramic Wall Tile Grout/Glue  | Restrooms 1                                    |
| Caulking, White   | Restrooms 1                                    |
| Ceramic Floor Tile Grout/Glue   | Restrooms 1                                    |
| Gypsum Wallboard/Joint Compd.   | Restrooms 3                                    |



| Errol Hassell Main Building (EH1)   |             |
|---|-------------|
| Material  | Location    |
| Ceramic Floor Tile Grout/Glue   | Restrooms 3 |
| Ceramic Wall Tile Grout/Glue  | Restrooms 3 |
| Caulking, White   | Restrooms 3 |
| Roof Mastic (under flashing) / Tested Negative, Cmmt: Non-Detect (19766.030-0013 phase 4) [ID: 28632] | Roof        |

## ASBESTOS SUMMARY

The following shows asbestos activities and projects. For more detailed information or related documents see the individual activity information in the database.

### January 2004 to December 2012 -

Activity: Database Update - Location: EH1

EH1 Import Historical Materials without samples

### January 2004 to December 2012 - 19766.030 p04

Activity: Database Update - Location: EH1 p04

EH1 Import Historical materials with Samples

### November 2019 to December 2019 - TRC #369880

Activity: Inspection/Survey - Location: Errol Hassell Elementary School Restrooms

- \_ Floor plan
- \_ Results received
- \_ Results in Verdant
- \_ Daily log
- \_ Consultant Invoice
- \_ Contractor Invoice
- \_ DEQ Notification
- \_ Disposal Manifest
- \_ Lab samples in Verdant
- \_ TEM Air clearance samples
- \_ Consultant Close out documents in Verdant
- \_ BOLI Form
- \_ Certified Payroll dates

**February 2020 to February 2020 - EH12020-1**

Activity: Sampling - Location: EH1

Sampled deteriorated wall materials at the dishwasher in the kitchen. No asbestos detected.

X Floor Plan

X Results in Verdant

Consultant Invoice

**ACTIVITIES**

The following shows historic activities and projects. For more detailed information or related documents see the individual activity information in the database.

| Activity Type     | Location                                  | Start Date | Related Documents |
|-------------------|---|------------|-------------------|
| Sampling          | EH1                                       | 02/27/2020 | Yes               |
| Inspection/Survey | Errol Hassell Elementary School Restrooms | 11/21/2019 | Yes               |
| Database Update   | EH1                                       | 01/01/2004 | No                |
| Database Update   | EH1 p04                                   | 01/01/2004 | No                |

## ASBESTOS MATERIALS

The following materials either tested positive or are presumed to be asbestos-containing. Materials that had mixed results are considered positive. Materials not sampled or not listed in this report may contain asbestos and should be tested to verify asbestos content prior to impact, demolition, renovation, etc.

(+) Tested Positive, (M) Mixed Results, (P) Presumed Positive

| <b>Errol Hassell Modular Building (EH2)</b> |   |                            |                 |
|---|---|----------------------------|-----------------|
| <b>Result</b>                               | <b>Material</b>   | <b>Location</b>            | <b>Quantity</b> |
| P   | Sheet Flooring Material and Mastic / Visible-PACM // [ID: 24690]  | Level 1 / Custodial        | 62 sf           |
| P   | Sheet Flooring Material and Mastic / Visible-PACM //, Cmmt: Encapsulated? Appears to be new sheet flooring [ID: 24691]        | Level 1 / Entry            | 160 sf          |
| P   | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: minor tile separation [ID: 24692]                          | Level 1 / M100             | 236 sf          |
| P   | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Appears to be new yellow tile. Encapsulated? [ID: 24693]   | Level 1 / M102             | 240 sf          |
| P   | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: minor tile cracking and separation [ID: 24694]             | Level 1 / M104             | 234 sf          |
| P   | Floor Tile and Mastic / Visible-Positive / 12 x 12 / HSA 99, Cmmt: Encapsulated? Appears to be new sheet flooring [ID: 24695] | Level 1 / M106             | 312 sf          |
| P   | Sheet Flooring Material and Mastic / Visible-PACM // [ID: 24696]  | Level 1 / Restroom Boys 1  | 180 sf          |
| P   | Sheet Flooring Material and Mastic / Visible-PACM //, Cmmt: Encapsulated? Appears to be new sheet flooring [ID: 24697]        | Level 1 / Restroom Girls 1 | 180 sf          |
| P   | Sheet Flooring Material and Mastic / Visible-PACM //, Cmmt: Encapsulated? Appears to be new sheet flooring [ID: 24698]        | Level 1 / Restroom Hall    | 70 sf           |

## MATERIALS THAT TESTED NEGATIVE

The following materials tested negative. Although no asbestos was detected, it is possible that further sampling could indicate asbestos content. It may be prudent to test prior to impact, demolition, renovation, etc.

| <b>Errol Hassell Modular Building (EH2)</b>  |                     |
|--|---------------------|
| <b>Material</b>  | <b>Location</b>     |
| Gypsum Wallboard/Joint Compound / Tested Negative, Cmmt: Non-Detect (19766.030-0018 phase 4) [ID: 28637] | Level 1 / Custodial |

| <b>Errol Hassell Modular Building (EH2)</b> |                           |
|---|---------------------------|
| <b>Material</b>                             | <b>Location</b>           |
| Built-up Roofing with Rock Overlay          | Modular Building Roof     |
| Silver Roof Paint                           | Modular Building Roof     |
| White/Gray Roof Caulking                    | Modular Building Roof     |
| Black Roof Caulking                         | Modular Building Roof     |
| Gypsum Wallboard/Joint Compd.               | Modular Restrooms         |
| RFP Glue                                    | Modular Restrooms         |
| Caulking, White                             | Modular Restrooms         |
| Sheet Vinyl Flooring (Stone Pattern)        | Modular Restrooms (Boys)  |
| 6" Beige Cove Base & Associated Glue        | Modular Restrooms (Boys)  |
| Sheet Vinyl Flooring (Marble Pattern)       | Modular Restrooms (Girls) |

## **ASBESTOS SUMMARY**

The following shows asbestos activities and projects. For more detailed information or related documents see the individual activity information in the database.

### **January 2004 to December 2012 -**

Activity: Database Update - Location: EH2

EH2 Import Historical Materials without samples

### **January 2004 to December 2012 - 19766.030 p04**

Activity: Database Update - Location: EH2 p04

EH2 Import Historical materials with Samples

**November 2019 to December 2019 - TRC #369880**

Activity: Inspection/Survey - Location: Errol Hassell Elementary School Restrooms

- \_ Floor plan
- \_ Results received
- \_ Results in Verdant
- \_ Daily log
- \_ Consultant Invoice
- \_ Contractor Invoice
- \_ DEQ Notification
- \_ Disposal Manifest
- \_ Lab samples in Verdant
- \_ TEM Air clearance samples
- \_ Consultant Close out documents in Verdant
- \_ BOLI Form
- \_ Certified Payroll dates

**August 2020 to August 2020 - TRC #406451**

Activity: Sampling - Location: Modular Building Roof

- \_ Floor plan
- \_ Results received
- \_ Results in Verdant
- \_ Daily log
- \_ Consultant Invoice
- \_ Contractor Invoice
- \_ DEQ Notification
- \_ Disposal Manifest
- \_ Lab samples in Verdant
- \_ TEM Air clearance samples
- \_ Consultant Close out documents in Verdant
- \_ BOLI Form
- \_ Certified Payroll dates

**ACTIVITIES**

The following shows historic activities and projects. For more detailed information or related documents see the individual activity information in the database.

| Activity Type     | Location                                  | Start Date | Related Documents |
|-------------------|---|------------|-------------------|
| Sampling          | Modular Building Roof                     | 08/11/2020 | Yes               |
| Inspection/Survey | Errol Hassell Elementary School Restrooms | 11/21/2019 | Yes               |
| Database Update   | EH2                                       | 01/01/2004 | No                |
| Database Update   | EH2 p04                                   | 01/01/2004 | No                |



