

Yellow Springs

Exempted Village School District

FACILITIES TASK FORCE MEETING









PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT

KEY AREAS

1988 Modular Building Area



- Age 31 years
- IAQ
- Structure (wood), crawlspace



Modular Building Institute (MBI) recommends:

- If the need is truly 1-5 years
- Over 1-5 years, additions or renovations
- Prior to 1990 are not as energy efficient, quiet or accommodating
- Process to "phase out" any over 20 years old.




YELLOW SPRINGS MIDDLE SCHOOL AND HIGH SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

1988 BUILDING AREA





PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT


OBSERVATIONS





PHYSICAL ASSESSMENT

OBSERVATIONS





PHYSICAL ASSESSMENT

OBSERVATIONS







PHYSICAL ASSESSMENT

OBSERVATIONS

BUILDING ACCESSIBILITY







PHYSICAL ASSESSMENT

OBSERVATIONS

HAZARDOUS MATERIAL






PHYSICAL ASSESSMENT

OBSERVATIONS

FURNISHINGS






- Most of overall plumbing system is beyond useful life
- Overall HVAC system has exceeded useful life, 2002 units should be replaced within 5-10 years



PHYSICAL ASSESSMENT

OBSERVATIONS

HVAC AND PLUMBING





PHYSICAL ASSESSMENT

OBSERVATIONS

ELECTRICAL

- Fire alarm functional, but outdated
- Majority of panel boards are too old for replacement parts.
- Lighting mostly fluorescent, becoming expensive with LED trend.
 - Emergency and exit lights aged past being reliable



- Replacement parts not available, manufacturer is out of business
- Clock system provide new
 - No synchronous clock system within building
- Telephone System replace with new
 - Functions, but consistently drops out multiple times per month
- Horizontal cabling infrastructure upgrade
 - Currently mixture of Category 5E and 6. Upgrade to shielded 6 and 6A to support higher bandwidths for network and wireless devices
- Fiber backbone cabling infrastructure replace with new
 - Currently only supports 1 Gb backbone, should upgrade to support 10 Gb backbone for higher bandwidths/speeds
- Pathways for horizontal data cabling replace
 - Majority of pathways are exposed and not properly supported



PHYSICAL ASSESSMENT

OBSERVATIONS

TECHNOLOGY

- Classroom AV Cabling replace
 - Currently supports only analog VGA; newer computers will be outfitted with HDME and no longer support analog VGA
- Classroom displays replace
 - Mixture of discontinued LCD projectors and Ultra-Shortthrow projectors. LCD projectors should be replaced with Ultra-Short-throw projectors at a minimum
- Classrooms sound systems provide
 - No classroom sound systems exist currently for teacher or PC audio to be amplified
- Network switching replace/upgrade
 - Network switches only support a 1 Gb backbone, need to support 10 Gb backbone
 - No UPS's installed for power backup
- Access control provide
 - No access control system at the building, a new system should be installed with card readers at exterior doors



PHYSICAL ASSESSMENT

OBSERVATIONS

TECHNOLOGY



Drainage issues, bicycle storage area blocks pathways to main entrances, no separation of pedestrian an vehicular traffic, lack of adequate storm system to manage runoff.




YELLOW SPRINGS MIDDLE SCHOOL AND HIGH SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

SITE





MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS





MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

KEY AREAS





MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS






MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS





■MILLS LAWN
■SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS



News Studio 248







PHYSICAL ASSESSMENT


OBSERVATIONS















MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

BUILDING ACCESSIBILITY







1952 \$220,000+ 1957 \$105,000+ **2002** \$95,000+

Insulations, fluorescent lamps and ballasts, hard plaster, acoustical panels, lab tables/countertops, flooring, mastics, door/window components, etc.



MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

HAZARDOUS MATERIALS





MILLS LAWN ELEMENTARY

PHYSICAL ASSESSMENT

OBSERVATIONS

FURNISHINGS







MILLS LAWN ELEMENTARY

PHYSICAL ASSESSMENT

OBSERVATIONS

HVAC AND PLUMBING

- No fire protection system (sprinklers) exist
- Most of overall plumbing system is beyond useful life
- Overall HVAC system has exceeded useful life, 2002 units should be replaced within 5-10 years





- Majority of panel boards are original and/or in poor condition.
- HVAC upgrades will likely require electrical service replacement.
- Lighting and emergency/exit lighting should be upgraded to LED.
 - Receptacles and switches throughout due for replacement



MILLS LAWN ELEMENTARY

PHYSICAL ASSESSMENT

OBSERVATIONS

ELECTRICAL



- Replacement parts not available, manufacturer is out of business
- Clock system provide new
 - No synchronous clock system within building
- Telephone System replace with new
 - Functions, but consistently drops out multiple times per month
- Horizontal cabling infrastructure upgrade
 - Currently mixture of Category 5E and 6. Upgrade to shielded 6 and 6A to support higher bandwidths for network and wireless devices
- Fiber backbone cabling infrastructure replace with new
 - Currently only supports 1 Gb backbone, should upgrade to support 10 Gb backbone for higher bandwidths/speeds
- Pathways for horizontal data cabling replace
 - Majority of pathways are exposed and not properly supported



MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

TECHNOLOGY

- Classroom AV Cabling replace
 - Currently supports only analog VGA; newer computers will be outfitted with HDME and no longer support analog VGA
- Classroom displays replace
 - Mixture of discontinued LCD projectors and Ultra-Shortthrow projectors. LCD projectors should be replaced with Ultra-Short-throw projectors at a minimum
- Classrooms sound systems provide
 - No classroom sound systems exist currently for teacher or PC audio to be amplified
- Network switching replace/upgrade
 - Network switches only support a 1 Gb backbone, need to support 10 Gb backbone
 - No UPS's installed for power backup
- Access control/Intrusion detection provide
 - No access control system at the building, a new system should be installed with card readers at exterior doors
 - Some intrusion detection exists, but a new system throughout is warranted



MILLS LAWN SCHOOL

PHYSICAL ASSESSMENT

OBSERVATIONS

TECHNOLOGY



Inadequate student drop-off/pick-up (Limestone and Elm), drainage issues, accessible routes, fall protection at play equipment



MILLS LAWN ELEMENTARY

PHYSICAL ASSESSMENT

OBSERVATIONS

SITE

105 106 107 109 110 Horveth 111 Garyering

SUMMARY

	YSHS/MMS	Mills Lawn School
Total Area (SF)	74,229	47,324
Total Renovation Costs	???	???
Total Cost/SF (New)	\$239.28	\$239.07
Replacement Costs (Same SF)	\$17,761.515	\$11,313,749
Renovate:Replace	???%	???%

205

118

KIVA

304

Lowry

203

Holly.

302

Date:



YELLOW SPRINGS SCHOOLS

PHYSICAL ASSESSMENT

OBSERVATIONS

SUMMARY