Reconciliation of Life Safety, Building Envelope, & Paving Studies

	Pro	jects ROM	Projects ROM			
Life Safety Study	\$	185,000	\$	12,274,980		
Roof Study	\$	290,000	\$	6,612,757		
Exterior Wall Study	\$	110,000	\$	174,105		
Paving Assessment	\$	-	\$	59 <i>,</i> 820		
Central Total	\$	585,000	\$	19,121,662		

2018 Summer

ts ROM Comments

Additional

Report as presented to BOE Preventive maintenance paid out of operational funds Majority of work included in life safety study Majority of work included in life safety study

Life Safety Study	\$ 535,000	\$ 10,473,114
Roof Study	\$ 380,000	\$ 5,100,080
Exterior Wall Study	\$ -	\$ 334,674
Paving Assessment	\$ -	\$ 536,488
South Total	\$ 915,000	\$ 16,444,356

Report as presented to BOE

Preventive maintenance paid out of operational funds Majority of work included in life safety study Majority of work included in life safety study

Life Safety Study Roof Study	ې د	720,000 670,000	ې د	22,748,094 11,712,837
Exterior Wall Study	\$	110,000	\$	508,779
Paving Assessment	\$	-	\$	596,308
District Total	\$	1,500,000	\$	35,566,018

Report as presented to BOE

Preventive maintenance paid out of operational funds

Majority of work included in life safety study

Majority of work included in life safety study

PAVING ASSET MANAGEMENT PROGRAM

Hinsdale Township High School District 86

ARCON Project #: 17071

ID BUILDING NAME

- HC HINSDALE CENTRAL HIGH SCHOOL 5500 S. GRANT STREET HINSDALE, ILLINOIS 60521
- HS HINSDALE SOUTH HIGH SCHOOL 7401 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561

(1) PAVING CONDITION SUMMARY

ID BUILDING NAME

TC DISTRICT 86 TRANSITION CENTER 7302 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561

DRAFT V.1

NOTES:

Building P1 P2 Р3 Ρ4 ID Priority 1 Priority 2 Priority 3 Priority 4 Totals HC 9,550 44,570 116,920 130,400 301,440 HS 121,050 105,271 0 124,120 350,441 TC 15,520 15,520 Ω 0 Ω _ sq.ft. 130,600 149,841 116,920 270,040 667,401 20% 22% 18% 40% 100% %

PRIORITY 1 (P1): REPLACE 1-2 YEARS PRIORITY 2 (P2): REPLACE 3-5 YEARS PRIORITY 3 (P3): REPLACE 6-9 YEARS PRIORITY 4 (P4): REPLACE 10+ YEARS SEALCOAT EVERY 2-3 YEARS

(3) PRIORITY DESCRIPTION

(2) EXPENDITURES SUMMARY

Building										
ID	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027+
HC	\$0	\$244,305	\$0	\$496,400	\$207,588	\$0	\$30,351	\$1,099,330	\$0	\$1,423,350
HS	\$0	\$854,287	\$185,603	\$62,260	\$1,076,089	\$48,285	\$0	\$264,210	\$14,817	\$1,377,959
TC	\$0	\$10,072	\$0	\$0	\$11,329	\$0	\$0	\$12,744	\$0	\$172,300
TOTALS	\$0	\$1,108,663	\$185,603	\$558,660	\$1,295,007	\$48,285	\$30,351	\$1,376,285	\$14,817	\$2,973,609

(4) COSTS INCLUDE A 4% INFLATION FROM YEAR TO YEAR BASED UPON CURRENT BUDGET ESTIMATES



HINSDALE CENTRAL HIGH SCHOOL PROGRAM SUMMARY

ID #	PAVING AREA	DESCRIPTION/ ADJACENCY	SQ.FT.	PRIORITY	PRIORITY 1 (P1) 2018 2019 2020	PRIORITY 2 (P2) 2021	2022	2023	PRIORIT 2024	TY 3 (P3) 2025	2026	PRIORITY 4 (P4) 2027	RECOMMENDATION / WORK ITEM
HC1	PA1	Northeast Drive	7,900	P1	\$71,429		\$5,767			\$6,487		Replacement	in 1-2 years; Seal coating is recommended every 2-3 years after
HC2	PA2	East Parking Lot - Baseball Field	84,000	P3	\$54,513		\$61,319			\$687,022		Replacement	in 6-10 years; Seal coating is recommended every 2-3 years before and after
HC3	PA3	Aprons - E Parking Lot	3,000	P2		\$61,418						Replacement	of concrete apron in 3-5 years
HC4	PA4	South Entry Apron	1,650	P1	\$12,375		\$1,204			\$1,355		Replacement	in 1-2 years; Seal coating is recommended every 2-3 years
HC5	PA5	South Parking Lot - Baseball Field	32,920	P3	\$21,364		\$24,031			\$297,390		Replacement	in 6-10 years; Seal coating is recommended every 2-3 years before and after
HC6	PA6	South Parking Lot - Pool	46,960	P4	\$30,475		\$34,280			\$38,561		\$462,872 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC7	PA7	South Access Drive	7,300	P4	\$4,737		\$5,329			\$5,994		\$81,043 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC8	PA8	North Receiving Lot	8,500	P4	\$5,516		\$26,279.70			\$6,980		\$94,366 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC9	PA9	Apron - S Parking Lot Pool	130	P2		\$2,661						Replacement	of concrete apron in 3-5 years
HC10	PA10	NOT USED											
HC11	PA11	East Entry Parking Lot	18,560	P4	\$12,045		\$13,549			\$15,240		\$206,050 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC12	PA12	Apron - N/S East Entry Parking Lot	400	P2		\$8,189						Replacement	of concrete apron in 3-5 years
HC13	PA13	Apron - E/W North Parking Lot	1,500	P2		\$30,709						Replacement	of concrete apron in 3-5 years
HC14	PA14	North Parking Lot	23,920	P4	\$15,523		\$17,461			\$19,642		\$265,556 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC15	PA15	NOT USED											
HC16	PA16	Stadium Drive	18,840	P2		\$165,301			\$14,875			\$16,733 Replacement	in 3-5 years, Seal coating is recommended every 2-3 years after
HC17	PA17	West Asphalt Drives	8,100	P2		\$71,069			\$6,395			\$7,194 Replacement	in 3-5 years, Seal coating is recommended every 2-3 years after
HC18	PA18	Athletic Loop	25,160	P4	\$16,328		\$18,367			\$20,660		\$279,322 Replacement	in 10+ years; Seal coating is recommended every 2-3 years before and after
HC19	PA19	Apron - S Athletic Loop	1,100	P2		\$22,520						Replacement	of concrete apron in 3-5 years
HC20	PA20	West Admin Parking Lot	6,000	P2		\$70,192			\$4,737			\$5,329 Replacement	in 3-5 years, Seal coating is recommended every 2-3 years after
HC21	PA21	Northeast Parking Lot	5,500	P2		\$64.342			\$4,343			\$4,885 Replacement	in 3-5 years, Seal coating is recommended every 2-3 years after

301,440 sq.ft. \$0 \$244,305 \$496,400 \$207,588 \$0 \$30,351 \$1,099,330 \$0 \$1,423,350 \$0

HINSDALE SOUTH HIGH SCHOOL PROGRAM SUMMARY

ID					PRIORITY	1 (P1)	I	PRIORITY 2 (P2)	1		PRIORITY	3 (P3)	P	RIORITY 4 (P4)
#	PAVING AREA	DESCRIPTION/ ADJACENCY	SQ.FT.	PRIORITY	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027
HS1	PA1	North Parking Lot	112,400	P4		\$72,943		_	\$82,051		_	\$92,296		\$1,247,846 Replacen
HS2	PA2	Aprons E/W- North Parking Lot	1,450	P2					\$30,873					Replacen
HS3	PA3	NOT USED												
HS4	PA4	West Service Drive	40,000	P2		\$25,958			\$364,996			\$32,846		Replacen
HS5	PA5	Front Entry Drop-Off	17,350	P1			\$185,603			\$13,172			\$14,817	Replacen
HS6	PA6	West Front Entry Parking Lot	11,720	P4		\$7,606			\$8,556			\$9,624		\$130,113 Replacen
HS7	PA7	Apron S - Front Entry Parking Lot	1,560	P2						\$19,612				Replacen
HS8	PA8	Apron N - Front Entry Parking Lot	1,225	P2						\$15,500				Replacen
HS9	PA9	East Stadium Parking Lot	103,700	P1		\$712,774			\$75,700			\$85,152		Replacen
HS10	PA10	Apron N - East Stadium Parking Lot	7,096	P2				\$62,260						Replacen
HS11	PA11	North Stadium Lot	19,520	P2		\$12,668			\$178,118			\$16,029		Replacen
HS12	PA12	West Drive	22,300	P2		\$14,472			\$211,698			\$18,311		Replacen
HS13	PA13	Stadium Loop	12,120	P2		\$7,865			\$124,099			\$9,952		Replacen
														\$0
			350,441 s	sq.ft.	\$0	\$854,287	\$185,603	\$62,260	\$1,076,089	\$48,285	\$0	\$264,210	\$14,817	\$1,377,959
<u>DISTRIC</u>	CT 86 TRANSITION	I CENTER PROGRAM SUMMARY												

ID #	PAVING AREA	DESCRIPTION/ ADJACENCY	SQ.FT.	PRIORITY	PRIORITY 2018	1 (P1) 2019	2020	PRIORITY 2 (P2) 2021	2022	2023	PRIORITY 2024	3 (P3) 2025	2026	PRIORITY 4 (P4) 2027
HS1	PA1	North Parking Lot	15,520	P4		\$10,072			\$11,329			\$12,744		\$172,300 Replacem
			15,520 s	sq.ft.	\$0	\$10,072	\$0	\$0	\$11,329	\$0	\$0	\$12,744	ţ	\$0 \$172,300

RECOMMENDATION / WORK ITEM

cement in 10+ years; Seal coating is recommended every 2-3 years before and after cement of concrete aprons in 3-5 years cement in 3-5 years; Seal coating is recommended every 2-3 years before and after

cement in 1-2 years; Seal coating is recommended every 2-3 years after cement in 10+ years; Seal coating is recommended every 2-3 years before and after cement of concrete aprons in 3-5 years cement of concrete aprons in 3-5 years cement in 1-2 years; Seal coating is recommended every 2-3 years after cement of concrete aprons in 3-5 years cement in 3-5 years; Seal coating is recommended every 2-3 years before and after cement in 3-5 years; Seal coating is recommended every 2-3 years before and after cement in 3-5 years; Seal coating is recommended every 2-3 years before and after

RECOMMENDATION / WORK ITEM

cement in 10+ years; Seal coating is recommended every 2-3 years before and after

ROOF ASSET MANAGEMENT PROGRAM

Hinsdale Township High School District 86

ARCON Project #: 17070

- ID BUILDING NAME
- HC HINSDALE CENTRAL HIGH SCHOOL 5500 S. GRANT STREET HINSDALE, ILLINOIS 60521
- HS HINSDALE SOUTH HIGH SCHOOL 7401 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561

HINSDALE, ILLINOIS 60521 TR THE TRANSITION CENTER 7302 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561

BUILDING NAME

ADMINISTRATION BUILDING

5500 S. GRANT STREET

ID

AD

(1) ROOF CONDITION SUMMARY

Building ID	P1 Priority 1	P2 Priority 2	P3 Priority 3	P4 Priority 4	P5 Priority 5	Totals
HC	8,447	112,755	90,844	25,018	25,490	262,554 sq.ft.
HS	12,596	164,156	4,614	32,183	11,275	224,824 sq.ft.
AD	0	0	0	4,612	0	4,612 sq.ft.
TR	0	0	0	0	11,744	11,744 sq.ft.
sq.ft.	21,043	276,911	95,458	61,813	48,509	503,734 sq.ft.
%	4%	55%	19%	12%	10%	100%

(2) EXPENDITURES SUMMARY

Building ID	2018	2019	2020	2021	2022	2023-2027	Totals
HC	\$295,500	\$1,331,129	\$5,949	\$1,418,030	\$1,353,685	\$2,561,712	\$6,966,005
HS	\$385,500	\$3,379,054	\$5,949	\$887 <i>,</i> 355	\$793,164	\$92 <i>,</i> 306	\$5,543,328
AD	\$0	\$0	\$0	\$0	\$0	\$0	\$0
TR	\$0	\$0	\$0	\$0	\$0	\$0	\$0
TOTALS	\$681,000	\$4,710,182	\$11,898	\$2,305,385	\$2,146,849	\$2,654,019	\$12,509,333

DRAFT V.1

REPLACEMEN YEARS	T (3) PRIORITY DESCRIPTION
2018	PRIORITY 1 (P1): EMERGENCY OR CURRENTLY EXPERIENCING ISSUES, REPLACEMENT WITHI
2019 - 2022	PRIORITY 2 (P2): POOR OR SEVERELY AGED CONDITION AND / OR BASED ON AGE OF ROOF,
2023 - 2027	PRIORITY 3 (P3): FAIR CONDITION, EXPERIENCING TYPICAL AGING AND / OR BASED ON AGE
2028 - 2037	PRIORITY 4 (P4): GOOD CONDITION, EXPERIENCING EARLY STAGES OF AGING AND / OR BAS
2038 - 2042	PRIORITY 5 (P5): NEW, ROOF HAS BEEN REPLACED WITHIN THE PAST 5 YEARS, PREVENTIVE

(4) SUMMARY OF ROOF MEMBRANE TYPES IN INVENTORY

%	ID	ROOF TYPE
85.70%	ABUR-G	ASPHALT BUILT-UP ROOF MEMBRANE W/ GRAVEL SUR
2.30%	AS-L	ASPHALT SHINGLES, LAMINATED
0.36%	EPDM-A	EPDM ADHERED ROOF MEMBRANE
2.23%	MB GR	MODIFIED BITUMEN ROOF MEMBRANE W/ GRANULE S
0.37%	MB-GR-A	MODIFIED BITUMEN ROOF MEMBRANE W/ GRANULES
0.04%	MB-S	MODIFIED BITUMEN ROOF MEMBRANE W/ NO SURFAC
5.06%	PVC-A	PVC ADHERED ROOF MEMBRANE
0.02%	SS-COPPER	STANDING SEAM - COPPER
3.92%	TPO-A	TPO ADHERED ROOF MEMBRANE

100.00% 9

(5) COSTS INCLUDE A 4% INFLATION FROM YEAR TO YEAR BASED UPON CURRENT BUDGET ESTIMATES



HIN ONE (1) YEAR F, PLAN FOR REPLACEMENT IN 2-5 YEARS GE OF ROOF, PLAN FOR REPLACEMENT IN 6-10 YEARS ASED ON AGE OF ROOF, PLAN FOR REPLACEMENT IN 10 + YEARS VE MAINTENANCE

RFACING

E SURFACING ES AND ALUMINUM SURFACING ACING

high schoo central hinsdale

HINSDALE CENTRAL HIGH SCHOOL PROGRAM SUMMARY

ID	ROOF AREA	ROOF AREA	OCCUPANCY	ROOF			ROOF	ITEM	(P1)		(P2)			(P3)	
#	ROUF AREA	TAG	BELOW	YEAR	SQ.FT.	PRIORITY (NOTE 3)	TYPE (NOTE 4)	TYPE	2018	2019	2020 (NOTE)	2021	2022	2023-2027	RECOMMENDATION / WORK ITEM
C1	Α	1.0	Music/Storage	1996	3,780	P2	ABUR-G	Roof			(NOTE :	\$119,573		201	8-2020 preventive maintenance, monitor condition, replacement 2021
C2	В	2.1	Music	1996	2,948	P2	ABUR-G	Roof				\$93,254			8-2020 preventive maintenance, monitor condition, replacement 2021
3	С	2.2	Buildings/Grounds	1996	1,090	P2	ABUR-G	Roof				\$34,480			8-2020 preventive maintenance, monitor condition, replacement 2021
4	D	3.1	Corridor	1996	941	P2	ABUR-G	Roof				\$29,767		201	8-2020 preventive maintenance, monitor condition, replacement 2021
5	D	3.2	Canopy	1996	280	P2	ABUR-G	Roof				\$8,857			8-2020 preventive maintenance, monitor condition, replacement 2021
6	E	4.0	Auditorium	1996	11,797	P2	ABUR-G	Roof				\$373,174		201	8-2020 preventive maintenance, monitor condition, replacement 2021
7	EE	5.0	Foyer	1996	830	P2	ABUR-G	Roof				\$26,255			8-2020 preventive maintenance, monitor condition, replacement 2021
3	F	6.0	Classroom/Office	1996	7,860	P2	ABUR-G	Roof				\$248,635		201	8-2020 preventive maintenance, monitor condition, replacement 2021
)	G	7.1	Corridor	1996	468	P2	ABUR-G	Roof				\$14,804		201	8-2020 preventive maintenance, monitor condition, replacement 2021
0	Ι	7.2	Canopy	1996	782	P2	ABUR-G	Roof				\$24,737		201	8-2020 preventive maintenance, monitor condition, replacement 2021
1	FF	8.0	Pool Storage	1997	612	P3	ABUR-G	Roof				· · ·	\$20,134	201	8-2021 preventive maintenance, monitor condition, replacement 2022
2	J	9.1	Locker Rooms	1996	1,537	P2	ABUR-G	Roof				\$48,620		201	8-2020 preventive maintenance, monitor condition, replacement 2021
3	J	9.2	Locker Rooms	1996	139	P2	ABUR-G	Roof				\$4,397		201	8-2020 preventive maintenance, monitor condition, replacement 2021
4	К	10.0	Pool	1997	8,337	P3	ABUR-G	Roof					\$274,273	201	8-2021 preventive maintenance, monitor condition, replacement 2022
5	L	11.0	Gymnasium	2015	24,051	P5	PVC-A	Roof						201	8-2027 preventive maintenance, monitor condition
5	L	12.0	Mech. Penthouse	2015	1,103	P5	PVC-A	Roof						201	8-2027 preventive maintenance, monitor condition
7	L	13.0	Mech. Penthouse	2015	128	P5	PVC-A	Roof						201	8-2027 preventive maintenance, monitor condition
3	L	14.0	Mech. Penthouse	2015	208	P5	PVC-A	Roof							8-2027 preventive maintenance, monitor condition
)	M	15.0	Wrestling Room	1998	5,721	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
)	N	16.0	Kitchen	2001	2,585	P3	ABUR-G	Roof							8-2025 preventive maintenance, monitor condition, replacement 2026
<u> </u>	0	17.0	Cafeteria	2001	4,904	P3	ABUR-G	Roof							8-2025 preventive maintenance, monitor condition, replacement 2026
2	BB	18.0	Library	2003	13,840	P4	ABUR-G	Roof							8-2027 preventive maintenance, monitor condition
3	P	19.0	Vestibule	2003	863	P4	ABUR-G	Roof							8-2027 preventive maintenance, monitor condition
1	Q	20.1	Classrooms	1997	6,746	P2	ABUR-G	Roof					\$221,932		8-2021 preventive maintenance, monitor condition, replacement 2022
;	R	20.2	Classrooms	1997	25,134	P2	ABUR-G	Roof					\$826,866		8-2021 preventive maintenance, monitor condition, replacement 2022
	Q	21.1	Elevator	1997	65	P2	ABUR-G	Roof					\$2,138		8-2021 preventive maintenance, monitor condition, replacement 2022
	Q	21.2	Elevator	1997	58	P2	ABUR-G	Roof					\$1,908		8-2021 preventive maintenance, monitor condition, replacement 2022
		22.0	Classrooms	1991	2,223	P2	ABUR-G	Roof		\$65,015			<i>\</i> 1,000		8 preventive maintenance, monitor condition, replacement 2019
		23.0	Field House	1993	29,808	P2	ABUR-G	Roof		\$871,779					8 preventive maintenance, monitor condition, replacement 2019
)	S	24.0	Classrooms	2003	4,068	P4	ABUR-G	Roof		<i>Ş</i> 071,775					8-2027 preventive maintenance, monitor condition
	T	25.1	Classrooms	1998	15,810	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
2	U	25.2	Classrooms	1998	5,557	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
- }	КК	26.0	Fitness Center	2008	4,757	P4	TPO-A	Roof							8-2027 preventive maintenance, monitor condition
ļ	GG	27.0	Storage	1993	1,546	P2	ABUR-G	Roof		\$45,215					8 preventive maintenance, monitor condition, replacement 2019
;	HH	28.0	Storage/Lck. Rm.	1996	3,415	P2	ABUR-G	Roof		Ş 4 5,215		\$108,027			8-2020 preventive maintenance, monitor condition, replacement 2015
5	V	29.0	Stair/Office	1998	775	P3	EPDM-A	Roof				Ş100,027			8-2022 preventive maintenance, monitor condition, replacement 2023
, 7	Ŵ	30.0	Classrooms	1998	25,111	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
3	W	31.0	Elev./Corridor	1998	462	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
)	W	32.0	Canopy	1998	65	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
)	AA	33.0	Classrooms	1994	1,845	P2	MB-GR-A	Roof		\$53,960					8 preventive maintenance, monitor condition, replacement 2019
	 CC	34.0	Stairs	2003	315	P4	ABUR-G	Roof		<i>233,300</i>					8-2027 preventive maintenance, monitor condition
2	<u> </u>	35.0	Classrooms	1988	4,378	P1	ABUR-G	Roof	\$140,000						acement 2018
	DD	36.0	Classroom	1988	624	P3	ABUR-G	Roof	\$140,000						8-2022 preventive maintenance, monitor condition, replacement 2023
) 	<u> </u>	36.0	Classrooms/Office	1998	3,978	P3 P1	ABUR-G	Roof	\$140,000						acement 2018
+ ;	× Y	37.0	Canopy	2008	1,175	P1 P4	ABUR-G	Roof	ə140,000						8-2027 preventive maintenance, monitor condition
) 5	Z	38.0	17	1988	9,435		ABUR-G	Roof		\$275,940					8 preventive maintenance, monitor condition 8 preventive maintenance, monitor condition, replacement 2019
			Classrooms			P2				şz15,940		6276 277			
7	Mechanical	40.0	Mechanical	2001	8,737	P3	TPO-A SS-COPPER	Roof	\$5,000			\$276,377			8-2020 preventive maintenance, monitor condition, replacement 2021
3)	Canopy	A	Canopy	2001 2001	44 47	P1 P1	SS-COPPER SS-COPPER	Roof Roof	\$5,000 \$5,000						acement 2018
	Canopy	B	Canopy						\$ <u></u> 5,000						acement 2018
) -	Canopy	C	Canopy	2001	68	P3	AS-L	Roof							8-2025 preventive maintenance, monitor condition, replacement 2026
	Canopy/H	D	Canopy	2001	986	P3	ABUR-G	Roof						. ,	8-2025 preventive maintenance, monitor condition, replacement 2026
	Canopy	E	Сапору	2001	190	P3	ABUR-G	Roof							8-2025 preventive maintenance, monitor condition, replacement 2026
	Canopy	F	Canopy	2001	190	P3	MB-S	Roof							8-2025 preventive maintenance, monitor condition, replacement 2026
	Canopy	G	Canopy	2001	370	P3	ABUR-G	Roof				A			8-2025 preventive maintenance, monitor condition, replacement 2026
3	Canopy	H	Canopy	2001	28	P2	MB-S	Roof				\$886			8-2020 preventive maintenance, monitor condition, replacement 2021
1	Maintenance	41.0	Maintenance		4,430	P3	ABUR-G	Roof							8-2022 preventive maintenance, monitor condition, replacement 2023
5	Maintenance	42.0	Maintenance		4,910	P3	ABUR-G	Roof						\$167,992 201	8-2022 preventive maintenance, monitor condition, replacement 2023
5	Stadium Press		Stadium Press Box		400	P3	EPDM-A	Roof		\$13,500				201	8 preventive maintenance, monitor condition, replacement 2019
-	Box				100				· · · ·						
	All	All							\$5,500	\$5,720	\$5,949	\$6,187	\$6,434	\$33,458 gen	eral preventive maintenance
		TOTALS			252,814 sc	ı.ft.			\$295,500	\$1,331,129	\$5,949	\$1,418,030	\$1,353,685	\$2,561,712	



ROOF PRIORITY LEGEND

PRIORITY 1 (P1) - 1 YEAR
PRIORITY 2 (P2) - 2-5 YEARS
PRIORITY 3 (P3) - 6-10 YEARS
PRIORITY 4 (P4) - 10+ YEARS
PRIORITY 5 (P5) - NEW

NOTE:

REFER TO SPREADSHEET DOCUMENT FOR DETAILED DESCRIPTION OF THE ABOVE



2050 south finley road. suite 40 lombard. illinois 60148 p: 530.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521



REVIS	SIONS	
No.	Date	By
		_
_		
_		
-		
Dent		
170 Issue	Date:	2017
170 Issue Nov	70	2017
170 Issue Nov Drav	70 • Date: rember 12, 2 vn by:	N





HINSDALE CENTRAL HIGH SCHOOL





REVISIONS



construction managers roof & masonry consultants landscape architects

2050 south linley road, suite 40 lombard, illinois 60148 p: 530.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







roof & m

2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant St. Hinsdale, Illinois 60521



By



HINSDALE CENTRAL KEY PLAN



18.0



construction managers roof & masonry consultants landscape architects

2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







。 19.





2050 south linley road, suite 40 lombard, illinois 60148 p: 530.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 5t. Hinsdale, Illinois 60521







HINSDALE CENTRAL KEY PLAN





HINSDALE CENTRAL KEY PLAN



architects construction managers roof & masonry consultants landscape architect

2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 5. Grant 51. Hinsdale, Illinois 60521



By







2050 south finley road, suite 40 lombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







HINSDALE CENTRAL KEY PLAN

south high schoo hinsdale

HINSDALE SOUTH HIGH SCHOOL PROGRAM SUMMARY

ID	ROOF AREA	ROOF AREA	OCCUPANCY	ROOF			ROOF	ITEM	(P1)		(P2)			(P3)	
#	NOOT ANEA	TAG	BELOW	YEAR	SQ.FT.	PRIORITY	TYPE	TYPE	2018	2019	2020	2021	2022	2023-2027	RECOMMENDATION / WORK ITEM
						(NOTE 3)	(NOTE 4)				(NOTE 5,)			
HS1	A	1.0	Buildings/Grounds	1998	1,720	P3	ABUR-G	Roof						\$58,848	8 2018-2022 preventive maintenance, monitor condition, replacement 2023
HS2	В	2.0	Buildings/Grounds	1988	3,765	P2	ABUR-G	Roof		\$110,113					2018 preventive maintenance, monitor condition, replacement 2019
HS3	С	3.0	Pool	1988	12,909	P2	ABUR-G	Roof		\$377,543					2018 preventive maintenance, monitor condition, replacement 2019
HS4	D	4.0	Balcony	1988	3,968	P2	ABUR-G	Roof		\$116,050					2018 preventive maintenance, monitor condition, replacement 2019
HS5	E	5.0	Gymnasium	1996	27,856	P2	ABUR-G	Roof				\$881,168			2018-2020 preventive maintenance, monitor condition, replacement 2021
HS6	Canopy #1	6.0	Canopy	1988	57	P2	ABUR-G	Roof		\$1,667					2018 preventive maintenance, monitor condition, replacement 2019
HS7	Canopy #2	7.1	Canopy	2012	1,300	P4	ABUR-G	Roof							2018-2027 preventive maintenance, monitor condition
HS31	E	7.2	Gym Lobby	2012	4,000	P4	TPO-A	Roof							2018-2027 preventive maintenance, monitor condition
HS8	F	8.1	Auditorium	1994	21,433	P2	ABUR-G	Roof		\$626,839					2018 preventive maintenance, monitor condition, replacement 2019
HS9	G	8.2	Stage	1994	1,850	P2	ABUR-G	Roof		\$54,106					2018 preventive maintenance, monitor condition, replacement 2019
HS10	Т	9.0	Ind. Tech, Spec.Ed.	1993	7,096	P1	ABUR-G	Roof	\$210,000						replacement 2018
HS11	U	10.0	Auto Shop / Storage	1993	5,500	P1	ABUR-G	Roof	\$170,000						replacement 2018
HS12	J	11.0	Classrooms	1997	8,056	P2	ABUR-G	Roof					\$265,029		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS13	J	12.0	Classrooms	1997	11,422	P2	ABUR-G	Roof					\$375,764		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS14	J	13.1	Classrooms/Library	2016	11,250	P5	MB GR	Roof							2018-2027 preventive maintenance, monitor condition
HS15	J	13.2	Main Entry	2012	2,275	P4	TPO-A	Roof							2018-2027 preventive maintenance, monitor condition
HS16	J	14.0	Stair	1997	783	P2	ABUR-G	Roof					\$25,759		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS17	М	15.1	Library/Comp. Lab	1997	700	P2	ABUR-G	Roof					\$23,029		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS18	М	15.2	Library/Comp. Lab	1997	570	P2	ABUR-G	Roof					\$18,752		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS19	К	16.0	Library/Comp. Lab	1997	1,449	P2	ABUR-G	Roof					\$47,670		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS20	L	17.1	Storage	1997	578	P2	ABUR-G	Roof					\$19,015		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS21	L	17.2	Storage	1997	272	P2	ABUR-G	Roof					\$8.948		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS22	N	17.3	Prep Room	2003	265	P4	ABUR-G	Roof							2018-2027 preventive maintenance, monitor condition
HS23	N	18.0	Science Labs	2003	11,130	P4	ABUR-G	Roof							2018-2027 preventive maintenance, monitor condition
HS24	0	19.0	Science Labs/CR	2006	8,030	P4	ABUR-G	Roof							2018-2027 preventive maintenance, monitor condition
HS25	R	20.0	Storage	1999	2,410	P3	ABUR-G	Roof		\$70,484					2018 preventive maintenance, monitor condition, replacement 2019
HS26	Р	21.0	Classrooms	2006	3,009	P4	ABUR-G	Roof		1 - 7 -					2018-2027 preventive maintenance, monitor condition
HS27	I	22.0	Classrooms	1992	13.972	P2	ABUR-G	Roof		\$408.632					2018 preventive maintenance, monitor condition, replacement 2019
HS28	0	23.0	Lcker Rm/ Offices	1993	6,582	P2	ABUR-G	Roof		\$192,500					2018 preventive maintenance, monitor condition, replacement 2019
HS29	<u> </u>	24.0	Field House	1993	29,808	P2	ABUR-G	Roof		\$871,779					2018 preventive maintenance, monitor condition, replacement 2019
HS30	 H	25.0	Kitchen/Cafeteria	1990	17,690	P2	ABUR-G	Roof		\$517,370					2018 preventive maintenance, monitor condition, replacement 2019
HS32		26.0	Classroom	1992	383	P2	ABUR-G	Roof		\$11,201					2018 preventive maintenance, monitor condition, replacement 2019
HS33		27.0	Elevator	1992	53	P2	ABUR-G	Roof		\$1,550					2018 preventive maintenance, monitor condition, replacement 2019
HS34	Canopy	A	Canopy	1997	84	P3	ABUR-G	Roof		,,			\$2,763		2018-2021 preventive maintenance, monitor condition, replacement 2022
HS35	Canopy	В	Canopy	2016	25	P5	ABUR-G	Roof					Υ <u></u> 2,703		2018-2027 preventive maintenance, monitor condition
HS36	Carlopy	28.0	Maintenance	2010	2,174	P4	ABUR-G	Roof							2018-2027 preventive maintenance, monitor condition
HS37	Stadium Press	20.0	Stadium Press Box	2007	400	P3	EPDM-A	Roof		\$13,500					2018 preventive maintenance, monitor condition, replacement 2019
	Box	All							\$5,500	\$5,720	\$5,949	\$6,187	\$6,434	\$33,458	8 general preventive maintenance
		τοτικ			224 424 -	~ ft			6305 F00	62 270 OF 4	ćE 040	6007 255	6702 464	602.20	c
		TOTALS			224,424 s	q.rt.			\$385,500	\$3,379,054	\$5,949	\$887,355	\$793,164	\$92,306	σ



HINSDALE SOUTH HIGH SCHOOL



architects construction managers roof & masonry consultants landscape architects

2050 south finley road. suite 40 lombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant St. Hinsdale, Illinois 60521



	-	
No.	Date	By
-		
-		
_		
	70 Date: ember 12,	, 2017
Drav	m by: MAH	1
Shee	t Title	0.0-575
	ROOF PL	
	SOUTH	H.S.
Shee	t Number	

















2050 south finley road, suite 40 lombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







HINSDALE SOUTH KEY PLAN





2050 south linley road, suite 40 lombard, illinois 60148 p: 530.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







HINSDALE SOUTH KEY PLAN

ADMINISTRATION BUILDING PROGRAM SUMMARY

ID # AD1	ROOF AREA	ROOF AREA TAG 1.0 TOTALS	OCCUPANCY BELOW Offices	ROOF YEAR 2004	SQ.FT. 4,612 4,612 s	PRIORITY (NOTE 3) P4 q.ft.	ROOF TYPE <i>(NOTE 4)</i> ABUR-G	ITEM TYPE Roof	(P1) 2018	2019	50	(P2) 2020 (NOTE 5) \$0	2021 \$0	2022	(P3) 2023-2027	RECOMMENDATION / WORK ITEM 2017-2026 preventive maintenance, monitor condition \$0
<u>TRANIST</u>	TRANISTION CENTER PROGRAM SUMMARY															
ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ROOF YEAR	SQ.FT.	PRIORITY (NOTE 3)	ROOF TYPE (NOTE 4)	ITEM TYPE	(P1) 2018	2019		(P2) 2020 <i>(NOTE 5)</i>	2021	2022	(P3) 2023-2027	RECOMMENDATION / WORK ITEM
TR1		1.1	Offices/Classrooms	2016	1,554	P5	AS-L	Roof				(2017-2026 preventive maintenance, monitor condition
TR2		1.2	Offices/Classrooms	2016	2,910	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR3		1.3	Offices/Classrooms	2016	2,910	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR4		2.1	Offices/Classrooms	2016	1,560	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR5		2.2	Offices/Classrooms	2016	1,560	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR6		3.1	Mech/Classrooms	2016	510	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR7		3.2	Offices/Classrooms	2016	510	P5	AS-L	Roof								2017-2026 preventive maintenance, monitor condition
TR8		4.0	Corridor	2016	230	P5	EPDM-A	Roof								2017-2026 preventive maintenance, monitor condition
		TOTALS			11,744 s	q.ft.			\$0) \$	50	\$0	\$0	\$C	:	\$0





ROOF PRIORITY LEGEND



NOTE:

REFER TO SPREADSHEET DOCUMENT FOR DETAILED DESCRIPTION OF THE ABOVE



ADMINISTRATION CENTER



2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant St. Hinsdale, Illinois 60521



No.	Date	By
_		
-		
		-

Issue Date: November 12, 2017

Drawn by: MAH

Sheet Title ROOF PLAN

Sheet Number





N

ROOF PRIORITY LEGEND



NOTE:

REFER TO SPREADSHEET DOCUMENT FOR DETAILED DESCRIPTION OF THE ABOVE



2050 south finley road. suite 40 Iombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521



REVIS	SIONS	
No.	Date	Ву
170		
	ember 12,	2017
Drav MA	vn by: AH	



EXTERIOR WALL ASSET MANAGEMENT PROGRAM

Hinsdale Township High School District 86

ARCON Project #: 17070

ID	BUILDING NAME	ID	BUILDING NAME
нс	HINSDALE CENTRAL HIGH SCHOOL 5500 S. GRANT STREET HINSDALE, ILLINOIS 60521	AD	ADMINISTRATION BUILDING 5500 S. GRANT STREET HINSDALE, ILLINOIS 60521
HS	HINSDALE SOUTH HIGH SCHOOL 7401 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561	тс	THE TRANSITION CENTER 7302 CLARENDON HILLS ROAD DARIEN, ILLINOIS 60561



DRAFT V.1

(2) EXPENDITURES SUMMARY

	Building								
_	ID	Base Cost	2018	2019	2020	2021	2022	2023-2027	Totals
	HC	\$896,155	\$99,840	\$0	\$0	\$0	\$0	\$0	\$99,840
_	HS	\$1,170,719	\$0	\$0	\$0	\$0	\$0	\$0	\$99,840
TOTALS		\$2,066,874	\$99,840	\$0	\$0	\$0	\$0	\$0	\$199,680



high schoo central hinsdale

HINSDALE CENTRAL HIGH SCHOOL PROGRAM SUMMARY

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	2022	(P3) 2023-202
	Α	Roof Area 1.0	Music/Storage									
				Ith Elevation			4000					
	A	RA1.0	Music/Storage	Paint lintels	66 SF		\$660					
	A	RA1.0 RA1.0	Music/Storage Music/Storage	Replace sealant at louver Replace cracked brick and point	10 LF 25 SF		\$200 \$2,125					
	A	NAL:0	-	est Elevation	23 31		<i>32,123</i>					
W-06	A	RA1.0	Music/Storage	Paint lintels	45 SF		\$450					
W-26	А	RA1.0	Music/Storage	Install new guardrail and handrail	10 LF		\$1,000					
W-27	Α	RA1.0	Music/Storage	Replace Guardrail	24 LF		\$1,200					
	В	Roof Area 2.1										
W-05	В	RA2.1	Music	est Elevation Grind and point deteriorated masonry	15 SF		\$225					
	B	RA2.1	Music	Paint lintels	15 SF		\$150					
	B	RA2.1	Music	Replace cracked brick and point	40 SF		\$3,400					
W-28	В	RA2.1	Music	Replace brick	50 units		\$1,750					
	С	Roof Area 2.2	Buildings/Grounds									
	-			st Elevation								
W-04	C C	RA2.2 RA2.2	Buildings/Grounds	Replace wall sealant	15 LF 680 SF		\$375 \$10,200					
W-05	D	RA2.2 Roof Area 3.1	Buildings/Grounds Corridor	Grind and point deteriorated masonry	000 35		,200,200					
	-			rth Elevation								
W-03	D	RA3.1	Corridor	Replace window sealant	30 LF		\$600				·	
W-05	D	RA3.1	Corridor	Grind and point deteriorated masonry	1,800 SF		\$27,000					
	D	Roof Area 3.2		di Ele ette e								
W-21	D	RA3.2	Canopy	rth Elevation Paint bottom of canopy	300 SF		\$10,500					
VV-21	E	Roof Area 4.0			500 SF		\$10,500					
	_			rth Elevation								
W-50	E	RA4.0	Auditorium	Grind and point deteriorated masonry	3,250 SF		\$48,750					
-	E	RA4.0	Auditorium	Provide new sealant at coping stone joints	33 LF		\$813					
W-61	E	RA4.0	Auditorium	Provide new masonry control joints	50 LF		\$2,500					
W-05	E	RA4.0	Ea Auditorium	st Elevation Grind and point deteriorated masonry	50 SF		\$750					
	E	RA4.0	Auditorium	Replace cracked brick and point	55 SF		\$4,675					
-	E	RA4.0	Auditorium	Provide new sealant at coping stone joints	22 LF		\$543					
			Sou	ith Elevation								
	E	RA4.0	Auditorium	Replace wall sealant	40 LF		\$1,000					
-	E	RA4.0	Auditorium	Grind and point deteriorated masonry	125 SF		\$1,875					
-	E	RA4.0 RA4.0	Auditorium Auditorium	Paint lintels Paint guardrail and handrail	190 SF 70 LF		\$1,900 \$1,400					
	E	RA4.0	Auditorium	Replace concrete stair	12 Risers		\$6,000					
	E	RA4.0	Auditorium	Replace guardrail	30 LF		\$1,500					
W-26	E	RA4.0	Auditorium	Install new guardrail and handrail	10 LF		\$1,000					
W-60	E	RA4.0	Auditorium	Provide new sealant at coping stone joints	33 LF		\$813					
14/ 50	_	5440		est Elevation	2.425.65		624.075					
W-50 W-60		RA4.0 RA4.0	Auditorium Auditorium	Grind and point deteriorated masonry Provide new sealant at coping stone joints	2,125 SF 22 LF		\$31,875 \$538					
VV 00	EE	Roof Area 5.0			22 Li		<i>2330</i>					
				rth Elevation								
W-05	EE	RA5.0	Foyer	Grind and point deteriorated masonry	50 SF		\$750					
14/ 02		DAFO		st Elevation	50.15		¢1.000					
	EE	RA5.0 RA5.0	Foyer Foyer	Replace window sealant Grind and point deteriorated masonry	50 LF 20 SF		\$1,000 \$300					
	EE	RA5.0	Foyer	Replace cracked brick and point	45 SF		\$300					
	EE	RA5.0	Foyer	Remove vines from soffit	50 SF		\$750					
	EE	RA5.0	Foyer	Add drip caps above door	22 LF		\$330				·	
W-23	EE	RA5.0	Foyer	Replace exterior door	6 ea.		\$18,000					
		BAE 0		Ith Elevation	20.05		<u> </u>					
W-05	EE F	RA5.0	Foyer Classrooms/Offices	Grind and point deteriorated masonry	20 SF		\$300					
	F	KOUT ATEd 0.0		st Elevation								
W-05	F	RA6.0	Classrooms/Offices	Grind and point deteriorated masonry	40 SF		\$600					
W-06	F	RA6.0	Classrooms/Offices	Paint lintels	55 SF		\$550					
W-11		RA6.0	Classrooms/Offices	Replace cracked brick and point	25 SF		\$2,125					
W-15	F	RA6.0	Classrooms/Offices	Replace sealant at door	35 LF		\$700					
W-05	F	RA6.0	Classrooms/Offices	est Elevation Grind and point deteriorated masonry	103 SF		\$1,545					
W-05 W-06		RA6.0	Classrooms/Offices	Paint lintels	88 SF		\$1,545					
W-11		RA6.0	Classrooms/Offices	Replace cracked brick and point	25 SF		\$2,125					
W-15		RA6.0	Classrooms/Offices	Replace sealant at door	30 LF		\$600					
W-25		RA6.0	Classrooms/Offices	Replace guardrail	30 LF		\$1,500					
W-27	F	RA6.0	Classrooms/Offices	Replace Guardrail	96 LF		\$4,800					

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY	BASE COST	(P1) 2018	2019	(P2) 2020 2021	2022	(P3) 2023-20
W-29	F	RA6.0	Classrooms/Offices	Replace exterior concrete slab	280 SF	(NOTE 3)	\$2,240			(NOTE 5)		
	G	Roof Area 7.		ast Elevation								
	-			ast Elevation			4					
W-40	G	RA7.1	Corridor	Replace damaged limestone panel	25 SF		\$1,500					
		Roof Area 7.2										
	FF	Roof Area 8.0	0 Pool Storage									
			E	ast Elevation								
W-05	FF	RA8.0	Pool Storage	Grind and point deteriorated masonry	125 SF		\$1,875					
			Sc	outh Elevation								
W-05	FF	RA8.0	Pool Storage	Grind and point deteriorated masonry	5 SF		\$75					
	J	Roof Area 9.3	1 Locker Rooms									
	J	Roof Area 9.2	2 Locker Rooms									-
	К	Roof Area 10.										
				East Elevation								
W-04	К	RA10.0	Pool	Replace wall sealant	60 LF		\$1,500					
	K	RA10.0	Pool	Grind and point deteriorated masonry	15 SF		\$225					
	K	RA10.0	Pool	Remove mortar and install movement joint	35 LF		\$1,750					
	K				100 SF		\$1,500					
		RA10.0	Pool	Grind and point deteriorated masonry	25 LF							
W-61	К	RA10.0	Pool	Provide new masonry control joints	25 LF		\$1,250					
				buth Elevation								
	К	RA10.0	Pool	Grind and point deteriorated masonry	150 SF		\$2,250					
-	К	RA10.0	Pool	Grind and point deteriorated masonry	1,700 SF		\$25,500					
	К	RA10.0	Pool	Remove and replace sealant at existing masonry control joint	18 LF		\$900					
W-60	К	RA10.0	Pool	Provide new sealant at coping stone joints	200 LF		\$5,000					
W-61	К	RA10.0	Pool	Provide new masonry control joints	18 LF		\$900					
			Ν	Vest Elevation								
W-50	К	RA10.0	Pool	Grind and point deteriorated masonry	1,900 SF		\$28,500					-
W-61	К	RA10.0	Pool	Provide new masonry control joints	18 LF		\$900				-	
	L		.0 Gymnasium	, ,			,					
	-	NOOT AICU III		orth Elevation								
W-61	1	RA11.0	Gymnasium	Provide new masonry control joints	175 LF		\$4,800	\$4,992				
W-61	1	RA11.0			2,660 SF		\$48,000	\$49,992				
VV-02	L	RAII.U	Gymnasium	Grind and point deteriorated masonry	2,000 SF		\$48,000	\$49,920				
				buth Elevation	400.15		44.000	44.000				
	L	RA11.0	Gymnasium	Provide new masonry control joints	100 LF		\$4,800	\$4,992				
W-62	L	RA11.0	Gymnasium	Grind and point deteriorated masonry	1,825 SF		\$38,400	\$39,936				
				Vest Elevation								
W-61		RA11.0	Gymnasium	Provide new masonry control joints	18 LF		\$900					
	L	Roof Area 12.	.0 Mech. Penthouse									
			N	Vest Elevation								
W-11	L	RA12.0	Mech. Penthouse	Replace cracked brick and point	60 SF		\$5,100					
W-43	L	RA12.0	Mech. Penthouse	Tuckpoint bed between windows	25 LF		\$1,250					
	L	Roof Area 13.	.0 Mech. Penthouse									
	L	Roof Area 14.	.0 Mech. Penthouse								-	
	М	Roof Area 15.	.0 Wrestling Room								-	
				outh Elevation								
W-50	М	RA15.0	Wrestling Room	Grind and point deteriorated masonry	1,000 SF		\$15,000					
		10 12010		Vest Elevation	1,000 0.		<i>\</i> 20)000					
W-50	M	RA15.0	Wrestling Room	Grind and point deteriorated masonry	1,400 SF		\$21,000					
	M	RA15.0	Wrestling Room	Remove and replace sealant at existing masonry control joint			\$800					
			-									
W-54		RA15.0	Wrestling Room	Replace with new window insert panels	8 SF		\$1,000					
W-55		RA15.0	Wrestling Room	Provide new sealant at limestone sill joints	20 LF		\$500					
W-56		RA15.0	Wrestling Room	Remove and replace steel lintel	54 LF		\$12,420					
W-57		RA15.0	Wrestling Room	Provide new window sealant	114 LF		\$2,280					
W-59		RA15.0	Wrestling Room	Investigate / replace steel lintel	90 LF		\$20,250					
	N	Roof Area 16.	.0 Kitchen									
			E	ast Elevation								
W-50	N	RA16.0	Kitchen	Grind and point deteriorated masonry	650 SF		\$9,750					
			Sc	outh Elevation							-	
W-50	Ν	RA16.0	Kitchen	Grind and point deteriorated masonry	550 SF		\$8,250				-	
			N	Vest Elevation								-
W-50	N	RA16.0	Kitchen	Grind and point deteriorated masonry	290 SF		\$4,350				-	
	0	Roof Area 17.					+ ./					
	BB	Roof Area 18.										
	55	1001 Alea 10.		Vest Elevation								
14/ 22	DD	DA19.0			715		610F					
W-22		RA18.0	Library	Missing drip caps above door	7 LF		\$105					
	Р	Roof Area 19.										
				Vest Elevation								
W-22		RA19.0	Vestibule	Missing drip caps above door	7 LF		\$105					
	Q	Roof Area 20.	.1 Classrooms									
			E	ast Elevation								
W-05	Q	RA20.1	Classrooms	Grind and point deteriorated masonry	20 SF		\$300					
			Sc	outh Elevation								
W-04	Q	RA20.1	Classrooms	Replace wall sealant	8 LF		\$200					
W-06		RA20.1	Classrooms	Paint lintels	110 SF		\$1,100					

ID #	ROOF AREA	ROOF AREA TAG	OCCUPAN BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	2022	(P3) 2023-20
W-10	Q	RA20.1	Classrooms	Replace sealant at louver	30 LF	1 /	\$600					
W-11	Q	RA20.1	Classrooms	Replace cracked brick and point	35 SF		\$2,975					
W-13	Q	RA20.1	Classrooms	Repair damaged concrete foundation	15 LF		\$1,125					
W-14	Q	RA20.1	Classrooms	Paint guardrail and handrail	70 LF		\$1,400					
-	Q	RA20.1	Classrooms	Remove mortar and install movement joint	27 LF		\$1,350					
W-25	Q	RA20.1	Classrooms	Replace guardrail	30 LF		\$1,500					
-	Q	RA20.1	Classrooms	Replce Lintel	50 LF		\$11,250					
W-31	Q	RA20.1	Classrooms	Replace window screen	10 SF		\$250					
	R	Roof Area 20.2	2 Classrooms									
11/ 04		D420.2	Classical	North Elevation	40.15		6250					
	R	RA20.2	Classrooms	Replace wall sealant	10 LF		\$250					
W-11	R	RA20.2	Classrooms	Replace cracked brick and point East Elevation	30 SF		\$2,550					
W-03	R	RA20.2	Classrooms	Replace window sealant	1,190 LF		\$23,800					
	R	RA20.2	Classrooms	Replace cracked brick and point	120 SF		\$10,200					
	R	RA20.2	Classrooms	Grind and point, cut brick, install masonry movement joint	35 LF		\$1,750					
	R	RA20.2	Classrooms	Replace louver	16 SF		\$800					
-	R	RA20.2	Classrooms	Replace sealant at sill	28 LF		\$700					
		-		South Elevation	-							
W-03	R	RA20.2	Classrooms	Replace window sealant	1,215 LF		\$24,300					
W-04	R	RA20.2	Classrooms	Replace wall sealant	8 LF		\$200					
W-06	R	RA20.2	Classrooms	Paint lintels	245 SF		\$2,450					
-	R	RA20.2	Classrooms	Replace sealant at louver	60 LF		\$1,200					
	R	RA20.2	Classrooms	Repair damaged concrete foundation	20 LF		\$1,500					
-	R	RA20.2	Classrooms	Paint guardrail and handrail	140 LF		\$2,800					
	R	RA20.2	Classrooms	Replace guardrail	30 LF		\$1,500					
W-29	R	RA20.2	Classrooms	Repair exterior concrete slab	150 SF		\$1,200					
			0	West Elevation	150.15		40.000					
-	R	RA20.2 RA20.2	Classrooms Classrooms	Replace window sealant Replace wall sealant	450 LF 27 LF		\$9,000 \$675					
-	R	RA20.2	Classrooms	Replace sealant at louver	30 LF		\$600					
	R	RA20.2	Classrooms	Replace louver	2 ea.		\$100					
	Q	Roof Area 21.1			2 00.		ŶĨŨŨ					
	Q	Roof Area 21.2										
				South Elevation								
W-05	Q	RA21.2	Elevator	Grind and point deteriorated masonry	50 SF		\$750					
		Roof Area 22.0) Classrooms									
			0	West Elevation			<u> </u>					
	<u> </u>	RA22.0	Classrooms	Replace window sealant	14 LF		\$280					
	<u> </u> 	RA22.0 RA22.0	Classrooms Classrooms	Paint lintels Replace cracked brick and install new sealant joint	25 SF 1 LF		\$250 \$85					
VV-03		Roof Area 23.0			10		202					
		1001 Alea 2010		North Elevation								
W-03	11	RA23.0	Field House	Replace window sealant	120 LF		\$2,400					
				East Elevation								
W-04	11	RA23.0	Field House	Replace wall sealant	40 LF		\$1,000					
W-06	11	RA23.0	Field House	Paint lintels	25 SF		\$250					
W-10	11	RA23.0	Field House	Replace sealant at louver	20 SF		\$400					
W-11		RA23.0	Field House	Replace cracked brick and point	20 SF		\$1,700					
W-15		RA23.0	Field House	Replace sealant at door	30 LF		\$600					
W-22		RA23.0	Field House	Missing drip caps above door	8 LF		\$120					
W-43	11	RA23.0	Field House	Tuckpoint bed between windows	100 LF		\$5,000					
14/ 04	11	DA33.0	Field House	South Elevation	125.15		60 10F					
W-04 W-10		RA23.0 RA23.0	Field House Field House	Replace wall sealant Replace sealant at louver	125 LF 20 LF		\$3,125 \$400					
W-44		RA23.0	Field House	Remove brick, flash, and raise weeps and flash 8"	140 LF		\$31,500					
				West Elevation	2.0 6							
W-03]]	RA23.0	Field House	Replace window sealant	60 LF		\$1,200					
W-04		RA23.0	Field House	Replace wall sealant	23 LF		\$575					
W-09	11	RA23.0	Field House	Replace cracked brick and install new sealant joint	10 LF		\$850					
W-10	11	RA23.0	Field House	Replace sealant at louver	60 LF		\$1,200					
	11	RA23.0	Field House	Replace cracked brick and point	30 SF		\$2,550					
W-16		RA23.0	Field House	Remove mortar and install movement joint	10 LF		\$500					
W-22		RA23.0	Field House	Missing drip caps above door	21 LF		\$315					
	S	Roof Area 24.0) Classrooms									
W/ 02	c	RA24.0	Classrooms	South Elevation	75 SF		\$3,750					
W-02 W-65	S S	RA24.0 RA24.0	Classrooms Classrooms	Repair damaged concrete canopy Remove and replace sealant at existing masonry control joint			\$3,750					
10.02	T	Roof Area 25.1			20 LI		~±,000					
				North Elevation								
W-16	т	RA25.1	Classrooms	Remove mortar and install movement joint	54 LF		\$2,700					
				East Elevation								
	Т	RA25.1	Classrooms	Replace window sealant	80 LF		\$1,600					
W-04	Т	RA25.1	Classrooms	Replace wall sealant	135 LF		\$3,375					

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF BASE PRIORITY COST	(P1) 2018	2019	(P2) 2020 2021	2022 20	(P3) 2023-20
	T	RA25.1	Classrooms	Paint lintels	260 SF	(NOTE 3) \$2,600			(NOTE 5)		
W-11	1	RA25.1	Classrooms	Replace cracked brick and point Vest Elevation	25 SF	\$2,125					
W-04	Т	RA25.1	Classrooms	Replace wall sealant	60 LF	\$1,500	1				
	U	Roof Area 25.2				+-)					
			Ν	orth Elevation							
W-04	U	RA25.2	Classrooms	Replace wall sealant	30 LF	\$750					
11/ 46		D 4 3 5 3		East Elevation	20.15	Ć4 500					
W-16 W-33	U	RA25.2 RA25.2	Classrooms Classrooms	Remove mortar and install movement joint Patch hole in brick, point	30 LF 55 SF	\$1,500 \$5,500					
W-55	0	NAZJ.Z		Vest Elevation	55 51	\$3,500					
W-03	U	RA25.2	Classrooms	Replace window sealant	300 LF	\$6,000	1				
W-04	U	RA25.2	Classrooms	Replace wall sealant	42 LF	\$1,050					
W-16		RA25.2	Classrooms	Remove mortar and install movement joint	30 LF	\$1,500					
	КК	Roof Area 26.0) Fitness Center								
W-22	КК	RA26.0	Fitness Center	outh Elevation Missing drip caps above door	8 LF	\$120					
	КК	RA26.0	Fitness Center	Patch hole in brick, point	25 SF	\$2,500					
	KK	RA26.0	Fitness Center	Tuckpoint bed between windows	25 SF	\$1,250					
	GG	Roof Area 27.0) Storage								
				East Elevation							
	GG	RA27.0	Storage	Replace wall sealant	30 LF	\$750					
W-06	GG HH	RA27.0	Storage Storage/Locker Ro	Paint lintels	25 SF	\$250					
		NOOT ATEd 20.0	-	orth Elevation							
W-11	НН	RA28.0		om Replace cracked brick and point	35 SF	\$2,975					
			E	East Elevation							
	HH	RA28.0	Storage/Locker Roo	om Replace wall sealant	15 LF	\$375					
	HH	RA28.0	-	om Replace cracked brick and point	10 LF	\$1,000					
W-19	HH	RA28.0	-	om Grind and point, cut brick, install masonry movement joint	20 SF	\$1,000	1				
	HH	Roof Area 29.0	Storage/Locker Ro	om Vest Elevation							
W-05	НН	RA29.0		om Grind and point deteriorated masonry	100 LF	\$1,500	1				
	W	Roof Area 30.0	-								
			N	orth Elevation							
	W	RA30.0	Classrooms	Replace window sealant	230 LF	\$4,600					
-	W	RA30.0	Classrooms	Grind and point deteriorated masonry	45 SF	\$675					
	W	RA30.0 RA30.0	Classrooms Classrooms	Paint lintels Replace sealant at louver	14 SF 25 LF	\$140 \$500					
-	W	RA30.0	Classrooms	Replace cracked brick and point	40 SF	\$3,400					
	W	RA30.0	Classrooms	Replace sealant at door	25 LF	\$500					
W-16	W	RA30.0	Classrooms	Remove mortar and install movement joint	60 LF	\$3,000					
-	W	RA30.0	Classrooms	Missing drip caps above door	18 LF	\$270					
	W	RA30.0	Classrooms	Patch hole in brick, point	25 SF	\$2,500					
W-34 W-36	W	RA30.0 RA30.0	Classrooms Classrooms	Replace sealant at head	500 LF 1,000 SF	\$10,000 \$15,000					
VV-30	vv	KA30.0		Paint granite panels outh Elevation	1,000 3F	\$13,000)				
W-11	W	RA30.0	Classrooms	Replace cracked brick and point	25 SF	\$2,125					
W-34	W	RA30.0	Classrooms	Replace sealant at head	85 LF	\$1,700					
W-40		RA30.0	Classrooms	Replace damaged limestone panel	20 SF	\$1,200					
W-43		RA30.0	Classrooms	Tuckpoint bed between windows	15 LF	\$750					
W-45 W-64		RA30.0 RA30.0	Classrooms Classrooms	Replace sealant at sill Remove and replace sealant at existing masonry control joint	17 LF 76 LF	\$425 \$1,520	1				
vv-04	٧V	11430.0		Vest Elevation	70 LF	\$1,520					
W-05	W	RA30.0	Classrooms	Grind and point deteriorated masonry	50 SF	\$750					
W-16	W	RA30.0	Classrooms	Remove mortar and install movement joint	25 SF	\$1,250					
W-33		RA30.0	Classrooms	Patch hole in brick, point	120 SF	\$12,000)				
	W	Roof Area 31.0		The second s							
W-06	\M/	RA31.0	Classrooms	East Elevation Paint lintels	24 SF	\$240					
W-15		RA31.0	Classrooms	Replace sealant at door	35 LF	\$700					
W-41		RA31.0	Classrooms	Paint frame	120 SF	\$1,800	1				
W-43		RA31.0	Classrooms	Tuckpoint bed between windows	20 LF	\$1,000					
				Vest Elevation							
W-06		RA31.0	Classrooms	Paint lintels	24 SF	\$240					
	W	Roof Area 32.0		Fost Flowation							
W-10	W	RA32.0	Canopy	East Elevation Replace sealant at louver	10 LF	\$200					
** 10				outh Elevation	10 11	Ş200					
W-06	W	RA32.0	Canopy	Paint lintels	20 SF	\$200					
W-12	W	RA32.0	Canopy	Remove mortar at door frame and replace with sealant	4 LF	\$80					
	AA	Roof Area 33.0									
14/ 05	A A	DA33.0		East Elevation		د					
W-05	AA	RA33.0	Classrooms	Grind and point deteriorated masonry	5 SF	\$75					

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 (NOTE)	2021	2022	(P3) 2023-2
W-15	AA	RA33.0	Classrooms	Replace sealant at door	25 LF		\$500				,		
W-22	AA	RA33.0	Classrooms	Add drip caps above door	4 LF		\$60						
	CC	Roof Area 34.	0 Stair										
	Х	Roof Area 35.	0 Classrooms										
			We	st Elevation									
W-03	Х	RA35.0	Classrooms	Replace window sealant	20 LF		\$400						
	Х	RA35.0	Classrooms	Replace sealant at door	30 LF		\$600						
W-11	х	RA35.0	Classrooms	Replace cracked brick and point	75 SF		\$6,375						
	DD	Roof Area 36.	0 Classrooms										
				st Elevation									
W-06	DD	RA36.0	Classrooms	Paint lintels	32 SF		\$320						
W-43	DD	RA36.0	Classrooms	Tuckpoint bed between windows	20 LF		\$1,000						
	Х	Root Area 37.	0 Classrooms/Offices	th Flouration									
14/ 04		DA27.0		th Elevation	100 15		62 500						
	X	RA37.0 RA37.0	Classrooms/Offices Classrooms/Offices	Replace wall sealant	100 LF 25 SF		\$2,500 \$2,125						
VV-11	^	RA37.0		Replace cracked brick and point st Elevation	25 SF		ŞZ,125						
W-03	v	RA37.0	Classrooms/Offices	Replace window sealant	40 LF		\$800						
	<u>x</u>	RA37.0	Classrooms/Offices	Replace will sealant	40 LF 40 LF		\$1,000						
	X	RA37.0	Classrooms/Offices	Paint lintels	32 SF		\$320						
	X	RA37.0	Classrooms/Offices	Tuckpoint bed between windows	20 LF		\$1,000						
-	X	RA37.0	Classrooms/Offices	Grind and point deteriorated masonry	360 SF		\$5,400						
-	X	RA37.0	Classrooms/Offices	Grind and point at limestone band	70 LF		\$2,450						
-	x	RA37.0	Classrooms/Offices	Remove and replace sealant at existing masonry control joint			\$300						
-				Redo existing masonry joint and cover with metal expansion			çooo						
W-53	Х	RA37.0	Classrooms/Offices	joint	6 LF		\$1,020						
W-63	х	RA37.0	Classrooms/Offices	Remove sealant and replace with expansion joint cover	20 LF		\$7,500						
	Y	Roof Area 38.	,	Remove sediant and replace with expansion joint cover	20 11		<i>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</i>						
	•	Noor Area sor		st Elevation									
W-06	Y	RA38.0	Canopy	Paint lintels	26 SF		\$260						
W-16	Y	RA38.0	Canopy	Remove mortar and install movement joint	15 LF		\$750						
	Z	Roof Area 39.	0 Classrooms				·					·	
			Nor	th Elevation									
W-03	Z	RA39.0	Classrooms	Replace window sealant	55 LF		\$1,100					-	
W-04	Z	RA39.0	Classrooms	Replace wall sealant	2 LF		\$50						
W-05	Z	RA39.0	Classrooms	Grind and point deteriorated masonry	500 SF		\$7,500						
W-11	7	RA39.0	Classrooms	Replace cracked brick and point	25 SF		\$2,125						
	Z	NA39.0	610351 001115				45 000						
W-32		RA39.0	Classrooms	Replace louver	100 SF		\$5,000						
W-32			Classrooms	Replace louver st Elevation	100 SF		\$5,000						
W-03	Z		Classrooms		300 LF		\$6,000						
W-03	Z	RA39.0	Classrooms Ea:	st Elevation	300 LF 230 SF		\$6,000 \$3,450						
W-03 W-05 W-16	Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms	st Elevation Replace window sealant	300 LF 230 SF 27 LF		\$6,000 \$3,450 \$1,350						
W-03 W-05 W-16 W-34	Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head	300 LF 230 SF 27 LF 81 LF		\$6,000 \$3,450 \$1,350 \$1,620						
W-03 W-05 W-16 W-34 W-38	Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue	300 LF 230 SF 27 LF 81 LF 81 LF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100						
W-03 W-05 W-16 W-34	Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel	300 LF 230 SF 27 LF 81 LF		\$6,000 \$3,450 \$1,350 \$1,620						
W-03 W-05 W-16 W-34 W-38 W-40	Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Sou	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200						
W-03 W-05 W-16 W-34 W-38 W-40	Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Sou	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04	Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000 \$675						
W-03 W-05 W-16 W-34 W-38 W-40	Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-40	Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classr	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000 \$675 \$2,100						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-40	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000 \$675 \$2,100						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Other and the second seco	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Otelssrooms Classrooms Otelssrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA	Classrooms Ea: Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms We Classrooms Classrooms O Mechanical Canopy Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 Roof Area 40. Roof Area B Roof Area C	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Claspy Classrooms Claspy Clanopy Clanopy Clanopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-05 W-09	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 ROOF Area 40. Roof Area 40. Roof Area 50. Roof Area 60. Roof Area 70. Roof Area 70.	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms O Mechanical Canopy Canopy Canopy Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000 \$675 \$2,100 \$3,300 \$850						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-04 W-05	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 ROOF Area 40. Roof Area 40. Roof Area 20. Roof Area 20. Roof Area 10. RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 RA39.0 Roof Area 40. Roof Area 10.	Classrooms O Mechanical Canopy Cano	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300						
W-03 W-05 W-16 W-34 W-38 W-04 W-05 W-05 W-09	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA30 RA30 RA30 RA30 RA30 RA30 RA30 RA3	Classrooms O Mechanical Canopy Can	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint Paint bottom of canopy	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF 1,000 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300 \$850 \$35,000						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-05 W-09	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 Roof Area 40. Roof Area 50 RA0 RA0 RA0 RA0 RA0 RA0 RA0 RA0	Classrooms O Mechanical Canopy Canopy Canopy Canopy Canop	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,000 \$675 \$2,100 \$3,300 \$850						
W-03 W-05 W-16 W-34 W-38 W-04 W-05 W-05 W-09	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA59.0 Roof Area 40. Roof Area 40. Roof Area 2 Roof Area 0 Roof Area 0 Roof Area 1 Roof Area 2 RA 1 Roof Area 4 Roof Area 4 Roof Area 5 Roof Area 5	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms O Mechanical Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint Paint bottom of canopy	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF 1,000 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300 \$850 \$35,000						
W-03 W-05 W-16 W-34 W-38 W-04 W-05 W-05 W-09	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 Roof Area 40. Roof Area 5 Roof Area 6 Roof Area 7 Roof Area 8 Roof Area 7 Roof Area 8 Roof Area 7 Roof Area 8	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms O Mechanical Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint Paint bottom of canopy	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF 1,000 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300 \$850 \$35,000						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-05 W-09 W-02	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 RA5 Roof Area 0 Roof Area 1 Roof Area 2 Roof Area 4 Roof Area 5 Roof Area 6 Roof Area 6	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms O Mechanical Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint Paint bottom of canopy Repair damaged concrete canopy	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF 1,000 SF 75 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,200 \$10,200 \$10,000 \$675 \$2,100 \$3,300 \$850 \$33,300 \$35,000 \$3,750						
W-03 W-05 W-16 W-34 W-38 W-40 W-03 W-04 W-05 W-09 W-09 W-21	Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	RA39.0 Roof Area 40. Roof Area 5 Roof Area 6 Roof Area 7 Roof Area 8 Roof Area 7 Roof Area 8 Roof Area 7 Roof Area 8	Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms Classrooms O Mechanical Canopy	st Elevation Replace window sealant Grind and point deteriorated masonry Remove mortar and install movement joint Replace sealant at head Replace limestone panel - structural issue Replace damaged limestone panel th Elevation Replace window sealant Replace wall sealant Replace damaged limestone panel st Elevation Grind and point deteriorated masonry Replace cracked brick and install new sealant joint Paint bottom of canopy	300 LF 230 SF 27 LF 81 LF 81 LF 170 SF 500 LF 27 LF 35 SF 220 SF 10 SF 1,000 SF		\$6,000 \$3,450 \$1,350 \$1,620 \$8,100 \$10,000 \$675 \$2,100 \$3,300 \$850 \$35,000	\$99,840	\$0	\$0	\$0	\$0	

\$0





2050 south finley road, suite 40 lombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521



	SIONS	
No.	Date	By
	70 Date: rember 12,	2017
Drav	m by: MAH	ξ
	oof PLAN MASON	
	mason	











manager roof & ma

2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant St. Hinsdale, Illinois 60521



	Date	
No.	Date	By
_		
_		
-		-
-		
Proje 170	ect Number: 70	
	Date: ember 12,	2017
Drav	m by: MAH	i.
	t Title DOF PLAN MASON	
	t Number	





2050 south linley road, suite 40 lombard, illinois 60148 p: 530.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521













2050 south finley road, suite 40 lombard, illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH HIGH SCHOOL 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant 51. Hinsdale, Illinois 60521







south high schoo hinsdale

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	2022	(P3) 2023-2027	RECOMMENDATION / WORK ITEM
HINSDAL	E SOUTH HIGH	I SCHOOL PROGRA	M SUMMARY										
ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	2022	(P3) 2023-2027	RECOMMENDATION / WORK ITEM
	А	Roof Area 1.0	Buildings/Grounds										
			Nor	th Elevation									
W-06		RA 1.0	Buildings/Grounds	Paint lintels	180 SF		\$1,800						
W-16	A	RA 1.0	Buildings/Grounds Eas	Remove mortar and install movement joint t Elevation	25 LF		\$1,250						
W-05		RA 1.0	Buildings/Grounds	Grind and point deteriorated masonry	75 SF		\$1,125						
W-06		RA 1.0	Buildings/Grounds	Paint lintels	180 SF		\$1,800						
W-11 W-16		RA 1.0 RA 1.0	Buildings/Grounds Buildings/Grounds	Replace cracked brick and point Remove mortar and install movement joint	<u>10 ea.</u> 105 LF		\$850 \$5,250						
VV-10	A	KA 1.0		th Elevation	103 LF		Ş3,230						
W-11	A	RA 1.0	Buildings/Grounds	Replace cracked brick and point	10 ea.		\$850						
W-12		RA 1.0	Buildings/Grounds	Remove mortar at door frame and replace with sealant	25 LF		\$1,250						
W-15 W-16		RA 1.0 RA 1.0	Buildings/Grounds	Replace sealant at door	20 LF 105 LF		\$400 \$5,250						
VV-10	B		Buildings/Grounds Buildings/Grounds	Remove mortar and install movement joint	105 LF		\$5,250						
				th Elevation									
W-05		RA 2.0	Buildings/Grounds	Grind and point deteriorated masonry	200 SF		\$3,000						
W-15	В	RA 2.0	Buildings/Grounds	Replace sealant at door th Elevation	20 LF		\$400						
W-05	В	RA 2.0	Buildings/Grounds	Grind and point deteriorated masonry	150 SF		\$2,250						
W-06		RA 2.0	Buildings/Grounds	Paint lintels	140 SF		\$1,400						
W-10		RA 2.0	Buildings/Grounds	Replace sealant at louver	50 LF		\$1,000						
	С	Roof Area 3.0		th Elevation									
W-01	С	RA 3.0	Pool	Remove vegetation growing on exterior façade	4,560 SF		\$2,736						
W-05	С	RA 3.0	Pool	Grind and point deteriorated masonry	300 SF		\$4,500						
W-06	С	RA 3.0	Pool	Paint lintels	182 SF		\$1,820						
W-05	C	RA 3.0	Pool	t Elevation Grind and point deteriorated masonry	400 SF		\$6,000						
W-06		RA 3.0	Pool	Paint lintels	142 SF		\$1,420						
W-50		RA 3.0	Pool	Grind and point deteriorated masonry	1,455 SF		\$21,825						
W-64	С	RA 3.0	Pool	Provide new metal cap at chimney	1 ea.		\$1,200						
W-06	C	RA 3.0	Pool	ch Elevation Paint lintels	160 SF		\$1,600						
W-09	C	RA 3.0	Pool	Replace cracked brick and install new sealant joint	100 ea.		\$8,500						
W-13		RA 3.0	Pool	Repair damaged concrete foundation	15 LF		\$2,250						
W-14	-	RA 3.0 RA 3.0	Pool	Paint guardrail and handrail	300 LF 30 LF		\$1,500 \$600						
W-15	D	Roof Area 4.0	Pool Balcony	Replace sealant at door	50 Li		\$600						
				th Elevation									
W-01		RA 4.0	Balcony	Remove vegetation growing on exterior façade	1,457 SF		\$874						
W-18	U	RA 4.0	Balcony Eas	Remove vines from soffit t Elevation	230 SF		\$3,450						
W-01	D	RA 4.0	Balcony	Remove vegetation growing on exterior façade	1,034 SF		\$620						
W-18	D	RA 4.0	Balcony	Remove vines from soffit	270 SF		\$4,050						
	E	Roof Area 5.0		th Elevation									
W-01	E	RA 5.0	Gymnasium	Remove vegetation growing on exterior façade	260 SF		\$156						
W-05		RA 5.0	Gymnasium	Grind and point deteriorated masonry	5,160 SF		\$77,400						
W-18	E	RA 5.0	Gymnasium	Remove vines from soffit	SF		\$0						
W-13	F	RA 5.0	Gymnasium	t Elevation Repair damaged concrete foundation	20 SF		\$3,000						
W-50		RA 5.0	Gymnasium	Grind and point deteriorated masonry	396 SF		\$5,940						
				h Elevation									
W-09 W-50		RA 5.0	Gymnasium	Replace cracked brick and install new sealant joint	100 SF 4,356 SF		\$8,500 \$65,340						
W-50 W-71		RA 5.0 RA 5.0	Gymnasium Gymnasium	Grind and point deteriorated masonry Provide new masonry control joint	4,356 SF 25 LF		\$65,340 \$1,250						
W-72		RA 5.0	Gymnasium	Provide new sealant at louvers	130 LF		\$3,250						
	Canopy #1	Roof Area 6.0											
W-01	Canopy #1	RA 6.0	Canopy	th Elevation Remove vegetation growing on exterior façade	100 SF		\$60						
** 01	Canopy #1				100 31		νυν						
			We	st Elevation									
W-04	Canopy #2	RA 7.1	Canopy	Replace wall sealant	170 LF		\$4,250						
	E	Roof Area 7.2		th Elevation									
W-05	E	RA 7.2	Gym Lobby	Grind and point deteriorated masonry	360 SF		\$5,400						
					00 000 00 000 00 00 00		-						

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF PRIORITY (NOTE 3)	BASE COST	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	2022	(P3) 2023-2027	RECOMMENDATION / WORK ITEM
W-06 E W-11 E		RA 7.2 RA 7.2	Gym Lobby Gym Lobby	Paint lintels Replace cracked brick and point	152 SF 20 SF		\$1,520 \$1,700						
WII I	L	NA 7.2		est Elevation	20 31		<i>Ş1,700</i>						
W-05 E		RA 7.2	Gym Lobby	Grind and point deteriorated masonry	50 SF		\$750						
W-50 E	F	RA 7.2	Gym Lobby 1 Auditorium	Grind and point deteriorated masonry	440 SF		\$6,600						
_	<u> </u>	noor Area of		rth Elevation									
W-04 F		RA 8.1	Auditorium	Replace wall sealant	140 LF		\$3,500						
W-50 F W-57 F		RA 8.1 RA 8.1	Auditorium Auditorium	Grind and point deteriorated masonry Replace window sealant	520 SF 325 LF		\$7,800 \$8,125						
W-62 F		RA 8.1	Auditorium	Provide new flashing at window lintels	306 LF		\$30,600						
W-63 F		RA 8.1	Auditorium	Provide new flashing at unit vent louvers	432 LF		\$43,200						
W-50 F	r	RA 8.1	Ea Auditorium	Ist Elevation Grind and point deteriorated masonry	2,080 SF		\$31,200						
W-50 I	1	NA 8.1		est Elevation	2,000 51		\$31,200						
W-50 F	F	RA 8.1	Auditorium	Grind and point deteriorated masonry	340 SF		\$5,100						
	J	Roof Area 8.	-	th Floreston									
W-04 J	1	RA 8.2	Stage	rth Elevation Replace wall sealant	200 LF		\$5,000						
W-05 J	J	RA 8.2	Stage	Grind and point deteriorated masonry	750 SF		\$11,250						
W-16 J	J	RA 8.2	Stage	Remove mortar and install movement joint	105 LF		\$5,250						
W-04 J	1	RA 8.2		Ist Elevation Replace wall sealant	170 LF		\$4,250						
<u>vv-04</u> J		NA 0.2	Stage We	est Elevation	1/0 LF		لر∠,+ب						
W-04 J	J	RA 8.2	Stage	Replace wall sealant	170 LF		\$4,250						
W-15 J		RA 8.2	Stage	Replace sealant at door	25 LF		\$500						
W-16 J) T	RA 8.2 Roof Area 9.1	Stage D Ind. Tech, Spec Ed	Remove mortar and install movement joint	105 LF		\$5,250						
_	<u> </u>	noor Area Si		ist Elevation									
W-04 1	Т	RA 9.0	Ind. Tech, Spec Ed	Replace wall sealant	160 LF		\$4,000						
W-05 1	T	RA 9.0	Ind. Tech, Spec Ed	Grind and point deteriorated masonry	800 SF		\$12,000						
	0	ROOI Area 10.	0 Auto Shop / Storage Ea	: Ist Elevation									
W-10 l	U	RA 10.0		Replace sealant at louver	3 LF		\$60						
				uth Elevation			40.005						
W-04 l W-06 l		RA 10.0 RA 10.0	Auto Shop / Storage Auto Shop / Storage	Replace wall sealant Paint lintels	145 LF 210 SF		\$3,625 \$2,100						
W-08 U		RA 10.0		Install flashing and weeps at lintels	90 LF		\$9,000						
W-11 l		RA 10.0		Replace cracked brick and point	20 SF		\$1,700						
W-12 U	U 	RA 10.0	Auto Shop / Storage 0 Classrooms	Remove mortar at door frame and replace with sealant	25 LF		\$1,250						
-	J	KOUT ATEd 11		rth Elevation									
W-57 J	J	RA 11.0	Classrooms	Replace window sealant	425 LF		\$10,625						
W-62 J	J	RA 11.0 RA 11.0	Classrooms	Provide new flashing at window lintels	306 LF 50 LF		\$30,600 \$5.000						
W-63 J)	RA 11.0	Classrooms We	Provide new flashing at unit vent louvers est Elevation	50 LF		\$5,000						
W-03 J	J	RA 11.0	Classrooms	Replace window sealant	250 LF		\$5,000						
W-04 J	J	RA 11.0	Classrooms	Replace wall sealant	260 LF		\$6,240						
W-20 J W-50 J	1	RA 11.0 RA 11.0	Classrooms Classrooms	Patch and repair concrete at columns and paint Grind and point deteriorated masonry	960 SF 600 SF		\$28,800 \$9,000						
	1		0 Classrooms				- 5,000						
W-03 J]	RA 12.0	Classrooms	Replace window sealant	450 LF		\$9,000						
W-04 J W-11 J	J	RA 12.0 RA 12.0	Classrooms Classrooms	Replace wall sealant Replace cracked brick and point	460 LF 100 SF		\$11,500 \$8,500						
W-11 J W-20 J	J	RA 12.0 RA 12.0	Classrooms	Patch and repair concrete at columns and paint	960 SF		\$28,800						
	J		1 Classrooms/Library										
W-03 J	1	RA 13.1	Ea Classrooms/Library	Ist Elevation Replace window sealant	160 LF		\$3,200						
W-03 J W-04 J	, J	RA 13.1 RA 13.1	Classrooms/Library Classrooms/Library	Replace window sealant Replace wall sealant	200 LF		\$3,200 \$5,000						
W-06 J	J	RA 13.1	Classrooms/Library	Paint lintels	166 SF		\$1,660						
W-11 J		RA 13.1	Classrooms/Library	Replace cracked brick and point	20 SF		\$1,700						
W-20 J W-30 J		RA 13.1 RA 13.1	Classrooms/Library Classrooms/Library	Patch and repair concrete at columns and paint Replace lintel	960 SF 12 ea.		\$28,800 \$2,700						
W-49 J		RA 13.1	Classrooms/Library	•	45 LF		\$675						
W-57 J	J	RA 13.1	Classrooms/Library	Replace window sealant	400 LF		\$10,000						
W-62 J	J	RA 13.1	Classrooms/Library	Provide new flashing at window lintels	132 LF		\$13,200						
W-03 J	J	RA 13.1	Classrooms/Library	est Elevation Replace window sealant	450 LF		\$9,000						
W-04 J	J	RA 13.1	Classrooms/Library	•	460 LF		\$11,500						
W-10 J	J	RA 13.1	Classrooms/Library	•	100 SF		\$2,000						
W-11 J W-20 J	J	RA 13.1 RA 13.1	Classrooms/Library Classrooms/Library		100 SF 960 SF		\$8,500 \$28,800						
<u>vv-∠</u> ∪ J	,	10.13.1	. ,	uth Elevation	300 JF		γ∠0,00U						
W-03 J	J	RA 13.1	Classrooms/Library	Replace window sealant	160 LF		\$3,200						

ID #	ROOF AREA	ROOF AREA TAG	OCCUPANCY BELOW	ITEM DESCRIPTION	QUANTITY	ROOF BASE PRIORITY COST (NOTE 3)	(P1) 2018	2019	(P2) 2020 2021 (NOTE 5)	(P3) 2022 2023-20
	1	Roof Area 13.								
	J	Roof Area 14.		st Elevation						
W-01	1	RA 14.0	Stair	Remove vegetation growing on exterior façade	480 SF	\$288				
	5	10/14.0		th Elevation	400 51	<i>\</i> 200				
W-01	1	RA 14.0	Stair	Remove vegetation growing on exterior façade	1,376 SF	\$826				
	М	Roof Area 15.	1 Library/Comp. Lab							
				st Elevation						
W-57	M	RA15.1	Library/Comp. Lab	Replace window sealant	100 LF	\$2,500				
W-62	M	RA15.1	Library/Comp. Lab	Provide new flashing at window lintels th Elevation	35 LF	\$3,500				
W-57	M	RA15.1	Library/Comp. Lab	Replace window sealant	100 LF	\$2,500				
-	M	RA15.1	Library/Comp. Lab	Provide new flashing at window lintels	35 LF	\$3,500				
	М	Roof Area 15.	2 Library/Comp. Lab							
				th Elevation						
W-03	M	RA15.2	Library/Comp. Lab	Replace window sealant	280 LF	\$5,600				
	К	Roof Area 16.	0 Library/Comp. Lab	th Elevation						
W-57	К	RA15.2	Library/Comp. Lab	Replace window sealant	85 LF	\$2,125				
-	ĸ	RA15.2	Library/Comp. Lab	Provide new flashing at window lintels	30 LF	\$3,000				
		-	<u> </u>	st Elevation		1-7				
W-57	К	RA15.2	Library/Comp. Lab	Replace window sealant	85 LF	\$2,125				
W-62	К	RA15.2	Library/Comp. Lab	Provide new flashing at window lintels	30 LF	\$3,000				
14/ 57	K	DA15 2	Sou Library/Comp. Lab	th Elevation Replace window sealant	05.15	¢2.425				
W-57 W-62	K	RA15.2 RA15.2	Library/Comp. Lab	Provide new flashing at window lintels	85 LF 30 LF	\$2,125 \$3,000				
11 02	L	Roof Area 17.		rovide new hosting at window inters	50 1	\$3,000				
				th Elevation						
W-57	L	RA17.1	Storage	Replace window sealant	100 LF	\$2,500				
W-62	L	RA17.1	Storage	Provide new flashing at window lintels	35 LF	\$3,500				
W-57	1	RA17.1	Storage	Replace window sealant	100 LF	\$2,500				
W-62	L	RA17.1	Storage	Provide new flashing at window lintels	35 LF	\$3,500				
	L	Roof Area 17.	-			1-7				
	N	Roof Area 17.	3 Prep Room							
				st Elevation						
	N	RA17.3 RA17.3	Prep Room Prep Room	Remove vegetation growing on exterior façade Grind and point deteriorated masonry	SF 25 SF	\$0 \$375				
	N	RA17.3	Prep Room	Paint lintels	136 SF	\$1,360				
	N	RA17.3	Prep Room	Add drip caps above door	4 ea.	\$60				
	Ν	Roof Area 18.	0 Science Labs							
				th Elevation						
-	N	RA18.0	Science Labs	Replace window sealant	275 LF	\$5,500				
W-06 W-22	N	RA18.0 RA18.0	Science Labs Science Labs	Paint lintels Add drip caps above door	180 SF 4 ea.	\$1,800 \$60				
W-49		RA18.0	Science Labs	Tuckpoint limestone panels	55 LF	\$825				
		10 12010		th Elevation		ÇÕES.				
W-03	Ν	RA18.0	Science Labs	Replace window sealant	880 LF	\$17,600				
W-05		RA18.0	Science Labs	Grind and point deteriorated masonry	12 LF	\$180				
W-06		RA18.0	Science Labs	Paint lintels	232 SF	\$2,320				
	0	Roof Area 19.	0 Science Labs/CR	th Elevation						
W-01	0	RA19.0	Science Labs/CR	Remove vegetation growing on exterior façade	240 SF	\$144				
	R	Roof Area 20.				· · · · ·				
	Р	Roof Area 21.	0 Classrooms							
				vation - Courtyard						
	P	RA21.0	Classrooms	Replace wall sealant	160 LF	\$4,000				
	P P	RA21.0 RA21.0	Classrooms Classrooms	Paint lintels Remove miscellaneous metal clip	150 SF 7 ea.	\$1,500 \$1,750				
W-10		RA21.0	Classrooms	Replace sealant at louver	51 LF	\$1,730				
W-11		RA21.0	Classrooms	Replace cracked brick and point	45 SF	\$3,825				
W-20		RA21.0	Classrooms	Patch and repair concrete at columns and paint	960 SF	\$28,800				
W-30	Р	RA21.0	Classrooms	Replace lintel	24 ea.	\$5,400				
W-32		RA21.0	Classrooms	Replace louver	18 SF	\$4,500				
W-33		RA21.0	Classrooms	Patch hole in brick, point	8 SF	\$800				
W-46	P	RA21.0 Roof Area 22.	Classrooms 0 Classrooms	Replace sill	31 LF	\$3,100				
		Noor Area 22.		th Elevation						
W-70	<u> </u>	RA22.0	Classrooms	Grind and point and add sealant at limestone band	25 LF	\$625				
				t Elevation						
W-70	1	RA22.0	Classrooms	Grind and point and add sealant at limestone band	40 LF	\$1,000				
W-71	1	RA22.0	Classrooms South Fley	Provide new masonry control joint vation - Courtyard	25 LF	\$1,250				
W-03		RA22.0	Classrooms	Replace window sealant	470 LF	\$9,400				
		-		· · · · ·		<i>+-,</i>				

ID RC	OOF AREA	ROOF AREA	OCCUPANCY	ITEM DESCRIPTION		ROOF	BASE	(P1)		(P2)		(P3)	
#		TAG	BELOW		QUANTITY	PRIORITY	COST	2018	2019	2020 2021	2022	2023-2027	RECOMMENDATION / WORK ITEM
		B 4 2 2 0	0	Declare ellevelest	200.15	(NOTE 3)	¢0.000			(NOTE 5)			
W-04 I W-10 I		RA22.0 RA22.0	Classrooms Classrooms	Replace wall sealant Replace sealant at louver	360 LF 10 LF		\$9,000 \$200						
W-10 I W-20 I		RA22.0	Classrooms	Patch and repair concrete at columns and paint	960 SF		\$200						
W-30 I		RA22.0	Classrooms	Replace lintel	28 LF		\$6,300						
W-46 I		RA22.0	Classrooms	Replace sill	246 LF		\$24,600						
W-47 I		RA22.0	Classrooms	Clean Louver	1 ea.		\$500						
W-57 I		RA22.0	Classrooms	Replace window sealant	420 LF		\$10,500						
W-62 I		RA22.0	Classrooms	Provide new flashing at window lintels	200 LF		\$20,000						
W-63 I		RA22.0	Classrooms	Provide new flashing at unit vent louvers	50 LF		\$5,000						
W-67 I		RA22.0	Classrooms	Install new metal caps over stone columns	2 ea.		\$2,000						
W-70 I		RA22.0	Classrooms	Grind and point and add sealant at limestone band	25 LF		\$625						
W-71 I		RA22.0	Classrooms	Provide new masonry control joint	25 LF		\$1,250						
W-72 I		RA22.0	Classrooms	Provide new sealant at louvers	110 LF		\$2,750						
	Q	Roof Area 23.	0 Locker Room/Office										
				ast Elevation									
W-65 Q		RA23.0	Locker Room/Office	s Cap and seal at drain pipe	1 ea.		\$250						
	S	Roof Area 24.											
			No	orth Elevation									
W-04 S		RA24.0	Field House	Replace wall sealant	175 LF		\$4,375						
W-05 S		RA24.0	Field House	Grind and point deteriorated masonry	2,272 SF		\$34,080						
W-06 S		RA24.0	Field House	Paint lintels	180 SF		\$1,800						
W-08 S		RA24.0	Field House	Install flashing and weeps at lintels	50 LF		\$5,000						
W-10 S		RA24.0	Field House	Replace sealant at louver	18 LF		\$360						
W-71 S		RA24.0	Field House	Provide new masonry control joint	32 LF		\$1,600						
			Ea	ast Elevation									
W-04 S		RA24.0	Field House	Replace wall sealant	175 LF		\$4,375						
W-06 S		RA24.0	Field House	Paint lintels	150 SF		\$1,500						
W-08 S		RA24.0	Field House	Install flashing and weeps at lintels	20 LF		\$2,000						
W-09 S		RA24.0	Field House	Replace cracked brick and install new sealant joint	10 ea.		\$850						
W-10 S		RA24.0	Field House	Replace sealant at louver	16 LF		\$320						
W-68 S		RA24.0	Field House	Provide new termination at bottom of mtl. wall panel	50 LF		\$2,500						
				uth Elevation									
W-04 S		RA24.0	Field House	Replace wall sealant	175 LF		\$4,375						
W-05 S		RA24.0	Field House	Grind and point deteriorated masonry	96 SF		\$1,440						
<u>W-06 S</u>		RA24.0	Field House	Paint lintels	150 SF		\$1,500						
W-08 S		RA24.0	Field House	Install flashing and weeps at lintels	20 LF		\$2,000						
W-68 S		RA24.0	Field House	Vest Elevation	50 LF		\$2,500						
W-69 S		RA24.0	Field House	Provide new termination at bottom of mtl. wall panel Grind and provide new sealant joint	42 LF		\$2,300						
W-09 3 W-71 S		RA24.0	Field House	Provide new masonry control joint	25 LF		\$1,250						
VV-/1 3	Н		0 Kitchen/Cafeteria		20 LF		,23U						
		Nooi Alea 25.		orth Elevation									
W-03 H		RA25.0	Kitchen/Cafeteria	Replace window sealant	262 LF		\$5,240						
W-05 H		RA25.0	Kitchen/Cafeteria	Grind and point deteriorated masonry	1,150 SF		\$17,250						
W-06 H		RA25.0	Kitchen/Cafeteria	Paint lintels	260 SF		\$2,600						
W-10 H		RA25.0	Kitchen/Cafeteria	Replace sealant at louver	216 LF		\$4,320						
W-12 H		RA25.0	Kitchen/Cafeteria	Remove mortar at door frame and replace with sealant	50 LF		\$2,500						
W-19 H		RA25.0	Kitchen/Cafeteria	Grind and point, cut brick, install masonry movement joint	240 SF		\$20,400						
				est Elevation									
W-05 H		RA25.0	Kitchen/Cafeteria	Grind and point deteriorated masonry	SF		\$0						
W-06 H		RA25.0	Kitchen/Cafeteria	Paint lintels	180 SF		\$900						
W-10 H		RA25.0	Kitchen/Cafeteria	Replace sealant at louver	96 LF		\$480						
W-19 H		RA25.0	Kitchen/Cafeteria	Grind and point, cut brick, install masonry movement joint	60 SF		\$5,100						
		Roof Area 26.	· · · · · · · · · · · · · · · · · · ·										
		Roof Area 27.											
	Canopy	Roof Area A											
W-02 Cand		RA A	Canopy	Repair damaged concrete canopy	100 SF		\$25,000						
	Canopy	Roof Area B											
		Roof Area 28.	0 Maintenance										

TOTALS

\$1,170,719 \$0 \$0 \$0 \$0 \$0 \$0 \$0













2050 south finley road. suite 40 lombard. illinois 60148 p: 630.495.1900 www.arconassoc.com

BUILDING AND ENVELOPE CONSULTING

at HINSDALE CENTRAL HIGH SCHOOL 5500 S. Grant St. Hinsdale, Illinois

HINSDALE SOUTH 7401 Clarendon Hills Rd. Darien, Illinois

for the BOARD of EDUCATION Hinsdale Township High School District 86 5500 S. Grant St. Hinsdale, Illinois 60521





