



# **Educational Master Facility Plan - Board Update**

**September 19, 2017** 







### **Process Update**



#### **Process Stakeholders - Core Team**



#### **Recommendations/Outcomes**

District Administrators
Teachers
Community Members
Local Business or Industry Partners
Union Leader
A Board Member
Facilities Leader
+ Ad Hoc Members

- **✓ Applications Available!**
- ✓ Core Team selection after September 20<sup>th</sup>
- **✓ First meeting October 5**<sup>th</sup>





### Deeper Understanding


Discover/Explore

Program

Conceptualize

Game Plan





### July 2017 - June 2018\*





### **PAGE** Phase 1 – Deeper Understanding

#### **Key Activities: Complete!**

- **√** Facility Assessments
- ✓ Listening Tours
  ✓ A Day in the Life: Part 1
  ✓ Student Ideation

#### **Key Activities: Ongoing**


- **Review Existing Data**
- **Activity Logs**
- **Indoor Environmental Quality**
- Surveys
- Qualifying "change"
- Sustainability | UX





### Phase 1 – Facility Assessment

DLR Group cataloged 1,343 items including the recent Decennial HLS Survey items previously identified.







### Phase 1 – Facility Assessment

Accessibility

Electrical

Equipment

Exterior

Finishes

Mechanical


Plumbing

Site


Health Life Safety

TOTAL

Schools				
Carleton Washburne	Crow Island	Hubbard Woods	Greeley School	Skokie School
27	25	16		31
3	5	12		12
25	37	26		40
28	29	31		61
100	63	82		210
16	8	12	12	8
2	9	4	5	9
5		13	7	9
67	22	15	60	70
273	203	211	199	450
















#### **Carleton Washburne**



#### **Quick Facts:**

#### 273 items found


- 67 remaining Health Life Safety
- 27 related to Accessibility
- 21 related to Mechanical, Electrical and Plumbing

#### Items to explore:

Cracks in CMU (Orchestra / Band) Possible Settlement – north hall Accessibility improvements Cause of water damaged tiles







#### **Quick Facts:**

#### 450 items found


- 70 remaining Health Life Safety
- 31 related to Accessibility
- 29 related to Mechanical, Electrical and Plumbing

#### Items to explore:

Masonry / CMU cracking at Gym Slab cracking at auditorium Accessibility improvements Cause of water damaged tiles



### **Crow Island**



#### **Quick Facts:**

#### 203 items found


- 22 remaining Health Life Safety
- 25 related to Accessibility
- 22 related to Mechanical, Electrical and Plumbing

#### Items to explore:

Egress from music room Accessibility Improvements



### **Greeley School**



#### **Quick Facts:**

#### 199 items found


- 60 remaining Health Life Safety
- 15 related to Accessibility
- 20 related to Mechanical, Electrical and Plumbing

#### Items to explore:

Egress from Gym Missing exhaust from Rm 133 Cause of water damaged tiles



### **HW**Hubbard Woods



#### **Quick Facts:**

#### 211 items found

- 15 remaining Health Life Safety
- 16 related to Accessibility
- 28 related to Mechanical, Electrical and Plumbing


#### Items to explore:

Vertical crack in masonry
Loose / missing roofing
Exhaust at boiler room
Cause of water damaged tiles





### A Day in the Life: Student Shadowing









## Schedule / Next Steps



### Phase 1 Community Presentations

#### <u>September 25 – October 3</u>

#### **Tentative Agenda for Each Campus:**

- Future Ready D36 Process Overview
- Audience Polling
- Campus History
- Campus Metrics
- Physical Condition
- Indoor Environmental Quality (IEQ)
- 2017 Day in the Life Summary Findings
- Activity: Three Bold Ideas
- "Live" FAQs





### **Phase 2 Preview: Global Perspectives**



October 24th







### **Questions?**