

Cocciardi and Associates, Inc. (Cocciardi) recently completed asbestos testing within the Scranton School District's Northeast Scranton Intermediate School. The goal of the testing was to confirm the actual location of asbestos-containing plasters on a room-by-room basis. This information will further help the District and their environmental consultant plan necessary response actions to ensure the safety of students and staff.

BACKGROUND: Existing information provided to the District identified plasters within the building as asbestos-containing. Based on further review of this data and reports of significantly damaged plaster in the 1906 wing, it was recommended by the U.S. Environmental Protection Agency (EPA) and Cocciardi that additional testing occur to provide the District with more accurate data on the location of asbestos-containing plaster.

SAMPLING: Sampling and analysis was completed in nearly 80 rooms by EPA/PA Department of Labor & Industry licensed Asbestos Building Inspectors in accordance with current rules for asbestos in schools. Samples were submitted to EMSL Analytical, Inc. in Cinnaminson, NJ for analysis (EMSL maintains current accreditation for asbestos bulk sample analysis).

RESULTS: A review of preliminary test results has found the following:

1. All plasters within the 1931 wing of the building are non-asbestos containing.
2. A total of 5 rooms in the 1906 wing were identified as containing asbestos. *Additional analysis is currently underway for these samples.*

Additionally, Cocciardi will be working with the District on developing an interim action plan to immediately address the above plaster and other potential environmental issues. We are cautiously optimistic that re-occupancy can occur immediately after these remediation efforts.

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:**

Attention: Mike Baltrusaitis
 Cocciardi & Associates Inc.
 1337 Veterans Memorial Drive
 Jessup, PA 18434

Phone: (570) 291-0030**Fax:** (570) 963-0242**Received Date:** 02/14/2020 2:30 PM**Analysis Date:** 02/17/2020 - 02/20/2020**Collected Date:** 02/11/2020**Project:** SSD NE Intermediate - 200115

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized
 Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
001-A-Skim Coat 042004031-0001	Room 001 - Wall A - Plaster	White Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-A-Base Coat 042004031-0001A	Room 001 - Wall A - Plaster	Gray Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-B-Skim Coat 042004031-0002	Room 001 - Wall B - Plaster	White Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-B-Base Coat 042004031-0002A	Room 001 - Wall B - Plaster	Gray Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-C-Skim Coat 042004031-0003	Room 001 - Wall C - Plaster	White Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-C-Base Coat 042004031-0003A	Room 001 - Wall C - Plaster	Gray Non-Fibrous Homogeneous HA: 35		100% Non-fibrous (Other)	None Detected
001-D 042004031-0004	Room 001 - Wall AD - Plaster				N/A
001-E 042004031-0005	Room 001 - Ceiling - Plaster				N/A
003-A-Skim Coat 042004031-0006	Room 003 - Wall A - Plaster	White Non-Fibrous Homogeneous HA: 36		100% Non-fibrous (Other)	None Detected
003-A-Base Coat 042004031-0006A	Room 003 - Wall A - Plaster	Gray Non-Fibrous Homogeneous HA: 36		100% Non-fibrous (Other)	None Detected
003-B-Skim Coat 042004031-0007	Room 003 - Wall B - Plaster	White Non-Fibrous Homogeneous HA: 36		100% Non-fibrous (Other)	None Detected
003-B-Base Coat 042004031-0007A	Room 003 - Wall B - Plaster	Gray Non-Fibrous Homogeneous HA: 36		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
003-C-Skim Coat 042004031-0008	Room 003 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 36	100% Non-fibrous (Other)	None Detected
003-C-Base Coat 042004031-0008A	Room 003 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 36	100% Non-fibrous (Other)	None Detected
003-D 042004031-0009	Room 003 - Wall D - Plaster		HA: 36		N/A
003-E 042004031-0010	Room 003 - Ceiling - Plaster		HA: 36		N/A
005-A-Skim Coat 042004031-0011	Room 005 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-A-Base Coat 042004031-0011A	Room 005 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-B-Skim Coat 042004031-0012	Room 005 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-B-Base Coat 042004031-0012A	Room 005 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-C-Skim Coat 042004031-0013	Room 005 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-C-Base Coat 042004031-0013A	Room 005 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 37	100% Non-fibrous (Other)	None Detected
005-D 042004031-0014	Room 005 - Wall D - Plaster		HA: 37		N/A
005-E 042004031-0015	Room 005 - Ceiling - Plaster		HA: 37		N/A
007-A-Skim Coat 042004031-0016	Room 007 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 38	100% Non-fibrous (Other)	None Detected
007-A-Base Coat 042004031-0016A	Room 007 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 38	100% Non-fibrous (Other)	None Detected
007-B-Skim Coat 042004031-0017	Room 007 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
007-B-Base Coat	Room 007 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 38	100% Non-fibrous (Other)	None Detected
042004031-0017A					
007-C-Skim Coat	Room 007 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 38	100% Non-fibrous (Other)	None Detected
042004031-0018					
007-C-Base Coat	Room 007 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 38	100% Non-fibrous (Other)	None Detected
042004031-0018A					
007-D	Room 007 - Wall D - Plaster		HA: 38		N/A
042004031-0019					
007-E	Room 007 - Ceiling - Plaster		HA: 38		N/A
042004031-0020					
009-A-Skim Coat	Room 009 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0021					
009-A-Base Coat	Room 009 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0021A					
009-B-Skim Coat	Room 009 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0022					
009-B-Base Coat	Room 009 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0022A					
009-C-Skim Coat	Room 009 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0023					
009-C-Base Coat	Room 009 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 39	100% Non-fibrous (Other)	None Detected
042004031-0023A					
009-D	Room 009 - Wall D - Plaster		HA: 39		N/A
042004031-0024					
009-E	Room 009 - Ceiling - Plaster		HA: 39		N/A
042004031-0025					
011-A-Skim Coat	Room 011 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
042004031-0026					

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
011-A-Base Coat 042004031-0026A	Room 011 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
011-B-Skim Coat 042004031-0027	Room 011 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
011-B-Base Coat 042004031-0027A	Room 011 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
011-C-Skim Coat 042004031-0028	Room 011 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
011-C-Base Coat 042004031-0028A	Room 011 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 40	100% Non-fibrous (Other)	None Detected
011-D 042004031-0029	Room 011 - Wall D - Plaster		HA: 40		N/A
011-E 042004031-0030	Room 011 - Ceiling - Plaster		HA: 40		N/A
013-A-Skim Coat 042004031-0031	Room 013 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-A-Base Coat 042004031-0031A	Room 013 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-B-Skim Coat 042004031-0032	Room 013 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-B-Base Coat 042004031-0032A	Room 013 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-C-Skim Coat 042004031-0033	Room 013 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-C-Base Coat 042004031-0033A	Room 013 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
013-D 042004031-0034	Room 013 - Wall D - Plaster		HA: 41		N/A
013-E 042004031-0035	Room 013 - Wall Ceiling - Plaster				N/A

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
019-A-Skim Coat 042004031-0036	Room 019 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 41	100% Non-fibrous (Other)	None Detected
			HA: 42		
019-A-Base Coat 042004031-0036A	Room 019 - Wall A - Plaster	Brown Non-Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
			HA: 42		
019-B-Skim Coat 042004031-0037	Room 019 - Wall B - Plaster	Pink Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 42		
019-B-Base Coat 042004031-0037A	Room 019 - Wall B - Plaster	Brown/Gray Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
			HA: 42		
019-C-Skim Coat 042004031-0038	Room 019 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 42		
019-C-Base Coat 042004031-0038A	Room 019 - Wall C - Plaster	Brown/Gray Non-Fibrous Homogeneous	3% Hair	97% Non-fibrous (Other)	None Detected
			HA: 42		
019-D 042004031-0039	Room 019 - Wall D - Plaster				N/A
			HA: 42		
019-E 042004031-0040	Room 019 - Ceiling - Plaster				N/A
			HA: 42		
020-B-Skim Coat 042004031-0042	Room 020 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 43		
020-B-Base Coat 042004031-0042A	Room 020 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
			HA: 43		
020-C-Skim Coat 042004031-0043	Room 020 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 43		
020-C-Base Coat 042004031-0043A	Room 020 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
			HA: 43		
020-D-Skim Coat 042004031-0044	Room 020 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 43		
020-D-Base Coat 042004031-0044A	Room 020 - Wall D - Plaster	Brown/Gray Non-Fibrous Homogeneous	2% Hair	98% Non-fibrous (Other)	None Detected
			HA: 43		

Initial report from: 02/20/2020 11:52:46



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
020-E 042004031-0045	Room 020 - Ceiling - Plaster		HA: 43		N/A
021-A-Skim Coat 042004031-0046	Room 021 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
021-A-Base Coat 042004031-0046A	Room 021 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	2% Hair HA: 44	98% Non-fibrous (Other)	None Detected
021-B-Skim Coat 042004031-0047	Room 021 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
021-B-Base Coat 042004031-0047A	Room 021 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	3% Hair HA: 44	97% Non-fibrous (Other)	None Detected
021-C-Skim Coat 042004031-0048	Room 021 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
021-C-Base Coat 042004031-0048A	Room 021 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	2% Hair HA: 44	98% Non-fibrous (Other)	None Detected
021-D 042004031-0049	Room 021 - Wall D - Plaster		HA: 44		N/A
021-E 042004031-0050	Room 021 - Ceiling - Plaster		HA: 44		N/A
022-A-Skim Coat 042004031-0051	Room 022 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
022-A-Base Coat 042004031-0051A	Room 022 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Hair HA: 45	97% Non-fibrous (Other)	None Detected
022-B-Skim Coat 042004031-0052	Room 022 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
022-B-Base Coat 042004031-0052A	Room 022 - Wall B - Plaster	Brown/Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
022-D-Skim Coat 042004031-0054	Room 022 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
022-D-Base Coat 042004031-0054A	Room 022 - Wall D - Plaster	Brown/Gray Non-Fibrous Homogeneous	2% Hair HA: 45	98% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
			HA: 45		
022-E 042004031-0055	Room 022 - Ceiling - Plaster				N/A
			HA: 45		
023-A-Skim Coat 042004031-0056	Room 023 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 46		
023-A-Base Coat 042004031-0056A	Room 023 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Hair	97% Non-fibrous (Other)	None Detected
			HA: 46		
023-B-Skim Coat 042004031-0057 Result includes a small amount of inseparable attached material	Room 023 - Wall B - Plaster	White/Beige Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
			HA: 46		
023-B-Base Coat 042004031-0057A	Room 023 - Wall B - Plaster	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 46		
023-C-Skim Coat 042004031-0058	Room 023 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 46		
023-C-Base Coat 042004031-0058A	Room 023 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	3% Hair	97% Non-fibrous (Other)	None Detected
			HA: 46		
023-D 042004031-0059	Room 023 - Wall D - Plaster				N/A
			HA: 46		
023-E 042004031-0060	Room 023 - Ceiling - Plaster				N/A
			HA: 46		
024-A-Plaster 042004031-0061	Room 024 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 47		
024-A-Insulation 042004031-0061A	Room 024 - Wall A - Plaster	Brown Non-Fibrous Homogeneous		30% Vermiculite 45% Non-fibrous (Other)	25% Chrysotile
			HA: 47		
024-C-Plaster 042004031-0063	Room 024 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 47		
024-C-Insulation 042004031-0063A	Room 024 - Wall C - Plaster	Brown Non-Fibrous Homogeneous		30% Vermiculite 50% Non-fibrous (Other)	20% Chrysotile
			HA: 47		
024-E 042004031-0065	Room 024 - Ceiling - Plaster				N/A
			HA: 47		

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
000-A-Skim Coat 042004031-0066	Room 000 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 48	100% Non-fibrous (Other)	None Detected
000-A-Base Coat 042004031-0066A	Room 000 - Wall A - Plaster	Tan Non-Fibrous Homogeneous	3% Hair HA: 48	97% Non-fibrous (Other)	None Detected
000-B-Skim Coat 042004031-0067	Room 000 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 48	100% Non-fibrous (Other)	None Detected
000-C-Joint Compound 042004031-0068	Room 000 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 48	100% Non-fibrous (Other)	None Detected
000-C-Skim Coat 042004031-0068A	Room 000 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 48	100% Non-fibrous (Other)	None Detected
000-C-Base Coat 042004031-0068B	Room 000 - Wall C - Plaster	Brown Non-Fibrous Homogeneous	2% Hair HA: 48	98% Non-fibrous (Other)	None Detected
000-D 042004031-0069	Room 000 - Wall D - Plaster		HA: 48		N/A
000-E 042004031-0070	Room 000 - Ceiling - Plaster		HA: 48		N/A
002-A-Skim Coat 042004031-0071	Room 002 - Wall A - Plaster	Tan/White Non-Fibrous Heterogeneous	HA: 49	100% Non-fibrous (Other)	None Detected
002-A-Base Coat 042004031-0071A	Room 002 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic HA: 49	97% Non-fibrous (Other)	None Detected
002-B-Skim Coat 042004031-0072	Room 002 - Wall B - Plaster	Tan/White Non-Fibrous Heterogeneous	HA: 49	100% Non-fibrous (Other)	None Detected
002-B-Base Coat 042004031-0072A	Room 002 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic HA: 49	97% Non-fibrous (Other)	None Detected
002-C-Skim Coat 042004031-0073	Room 002 - Wall C - Plaster	Tan/White Non-Fibrous Heterogeneous	HA: 49	100% Non-fibrous (Other)	None Detected
002-C-Base Coat 042004031-0073A	Room 002 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic HA: 49	97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
002-C-Tar 042004031-0073B	Room 002 - Wall C - Plaster	Black Non-Fibrous Homogeneous	HA: 49	100% Non-fibrous (Other)	None Detected
002-D-Skim Coat 042004031-0074	Room 002 - Wall D - Plaster	Tan/White Non-Fibrous Heterogeneous	HA: 49	100% Non-fibrous (Other)	None Detected
002-D-Base Coat 042004031-0074A	Room 002 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 49	3% Synthetic 97% Non-fibrous (Other)	None Detected
002-E 042004031-0075	Room 002 - Ceiling - Plaster		HA: 49		N/A
0025-B-Skim Coat 042004031-0077	Room 025 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 50	100% Non-fibrous (Other)	None Detected
0025-B-Base Coat 042004031-0077A	Room 025 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 50	3% Synthetic 97% Non-fibrous (Other)	None Detected
0025-C-Skim Coat 042004031-0078	Room 025 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 50	100% Non-fibrous (Other)	None Detected
0025-C-Base Coat 042004031-0078A	Room 025 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 50	3% Synthetic 97% Non-fibrous (Other)	None Detected
0025-C-Wrap 042004031-0078B	Room 025 - Wall C - Plaster	Tan Fibrous Homogeneous	HA: 50	60% Synthetic 40% Non-fibrous (Other)	None Detected
0025-E 042004031-0080	Room 025 - Ceiling - Plaster		HA: 50		N/A
067-A-Skim Coat 042004031-0081	Room 067 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 51	100% Non-fibrous (Other)	None Detected
067-A-Base Coat 042004031-0081A	Room 067 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 51	3% Synthetic 97% Non-fibrous (Other)	None Detected
067-B-Skim Coat 042004031-0082	Room 067 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 51	100% Non-fibrous (Other)	None Detected
067-B-Base Coat 042004031-0082A	Room 067 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 51	3% Synthetic 97% Non-fibrous (Other)	None Detected
067-C-Skim Coat 042004031-0083	Room 067 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u> % Type
			% Fibrous	% Non-Fibrous	
			HA: 51		
067-C-Base Coat 042004031-0083A	Room 067 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 51		
067-D-Skim Coat 042004031-0084	Room 067 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 51		
067-D-Base Coat 042004031-0084A	Room 067 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 51		
067-E 042004031-0085	Room 067 - Ceiling - Plaster				N/A
			HA: 51		
117-A-Skim Coat 042004031-0086	Room 117 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 52		
117-A-Base Coat 042004031-0086A	Room 117 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 52		
117-B-Skim Coat 042004031-0087	Room 117 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 52		
117-B-Base Coat 042004031-0087A	Room 117 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 52		
117-C-Skim Coat 042004031-0088	Room 117 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 52		
117-C-Base Coat 042004031-0088A	Room 117 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 52		
117-D-Skim Coat 042004031-0089	Room 117 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 52		
117-D-Base Coat 042004031-0089A	Room 117 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 52		
117-E 042004031-0090	Room 117 - Ceiling - Plaster				N/A
			HA: 52		
118-A-Skim Coat 042004031-0091	Room 118 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 53		

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
118-A-Base Coat 042004031-0091A	Room 118 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-B-Skim Coat 042004031-0092	Room 118 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-B-Base Coat 042004031-0092A	Room 118 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-C-Skim Coat 042004031-0093	Room 118 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-C-Base Coat 042004031-0093A	Room 118 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-D-Skim Coat 042004031-0094	Room 118 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-D-Base Coat 042004031-0094A	Room 118 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 53	100% Non-fibrous (Other)	None Detected
118-E 042004031-0095	Room 118 - Ceiling - Plaster		HA: 53		N/A
119-A-Skim Coat 042004031-0096	Room 119 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 54	100% Non-fibrous (Other)	None Detected
119-A-Base Coat 042004031-0096A	Room 119 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 54	3% Synthetic 97% Non-fibrous (Other)	None Detected
119-B-Skim Coat 042004031-0097	Room 119 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 54	100% Non-fibrous (Other)	None Detected
119-B-Base Coat 042004031-0097A	Room 119 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 54	100% Non-fibrous (Other)	None Detected
119-C-Skim Coat 042004031-0098	Room 119 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 54	100% Non-fibrous (Other)	None Detected
119-C-Base Coat 042004031-0098A	Room 119 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 54	100% Non-fibrous (Other)	None Detected
119-D-Skim Coat 042004031-0099	Room 119 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
			HA: 54		
119-D-Base Coat 042004031-0099A	Room 119 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 54		
119-E 042004031-0100	Room 119 - Ceiling - Plaster				N/A
			HA: 54		
121-A-Skim Coat 042004031-0101	Room 121 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-A-Plaster 042004031-0101A	Room 121 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-B-Skim Coat 042004031-0102	Room 121 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-B-Plaster 042004031-0102A	Room 121 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-C-Skim Coat 042004031-0103	Room 121 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-C-Plaster 042004031-0103A	Room 121 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 55		
121-D 042004031-0104	Room 121 - Wall D - Plaster				N/A
			HA: 55		
121-E 042004031-0105	Room 121 - Ceiling - Plaster				N/A
			HA: 55		
123-A-Skim Coat 042004031-0106	Room 123 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 56		
123-A-Plaster 042004031-0106A	Room 123 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 56		
123-B-Skim Coat 042004031-0107	Room 123 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 56		
123-B-Plaster 042004031-0107A	Room 123 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 56		

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
123-C-Skim Coat 042004031-0108	Room 123 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 56	100% Non-fibrous (Other)	None Detected
123-C-Plaster 042004031-0108A	Room 123 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 56	100% Non-fibrous (Other)	None Detected
123-D 042004031-0109	Room 123 - Wall D - Plaster		HA: 56		N/A
123-E 042004031-0110	Room 123 - Ceiling - Plaster		HA: 56		N/A
122-A-Skim Coat 042004031-0111	Room 122 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-A-Plaster 042004031-0111A	Room 122 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-B-Skim Coat 042004031-0112	Room 122 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-B-Plaster 042004031-0112A	Room 122 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-C-Skim Coat 042004031-0113	Room 122 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-C-Plaster 042004031-0113A	Room 122 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 57	100% Non-fibrous (Other)	None Detected
122-D 042004031-0114	Room 122 - Wall D - Plaster		HA: 57		N/A
122-E 042004031-0115	Room 122 - Ceiling - Plaster		HA: 57		N/A
COROB-A-Skim Coat 042004031-0116	Room and Corridor Ground Floor ATB - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 58	100% Non-fibrous (Other)	None Detected
COROB-A-Plaster 042004031-0116A	Room and Corridor Ground Floor ATB - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 58	100% Non-fibrous (Other)	None Detected
COROB-B-Skim Coat 042004031-0117	Room and Corridor Ground Floor ATB - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com/cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
			HA: 58		
COROB-B-Plaster 042004031-0117A	Room and Corridor Ground Floor ATB - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			HA: 58		
COROB-C-Skim Coat 042004031-0118	Room and Corridor Ground Floor ATB - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 58		
COROB-C-Plaster 042004031-0118A	Room and Corridor Ground Floor ATB - Wall C - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			HA: 58		
COROB-D 042004031-0119	Room and Corridor Ground Floor ATB - Wall D - Plaster				N/A
			HA: 58		
COROB-E 042004031-0120	Room and Corridor Ground Floor ATB - Ceiling - Plaster				N/A
			HA: 58		
221-A-Skim Coat 042004031-0121	Room 221 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 59		
221-A-Plaster 042004031-0121A	Room 221 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 59		
221-B 042004031-0122	Room 221 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic	95% Non-fibrous (Other)	None Detected
			HA: 59		
221-C-Skim Coat 042004031-0123	Room 221 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 59		
221-C-Plaster 042004031-0123A	Room 221 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 59		
221-D 042004031-0124	Room 221 - Wall D - Plaster				N/A
			HA: 59		
221-E 042004031-0125	Room 221 - Ceiling - Plaster				N/A
			HA: 59		
223-A-Skim Coat 042004031-0126	Room 223 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 60		
223-A-Plaster 042004031-0126A	Room 223 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
			HA: 60		

Initial report from: 02/20/2020 11:52:46



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
223-B-Skim Coat 042004031-0127	Room 223 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 60	100% Non-fibrous (Other)	None Detected
223-B-Plaster 042004031-0127A	Room 223 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 60	100% Non-fibrous (Other)	<1% Chrysotile
223-C-Skim Coat 042004031-0128	Room 223 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 60	100% Non-fibrous (Other)	None Detected
223-C-Plaster 042004031-0128A	Room 223 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 60	100% Non-fibrous (Other)	<1% Chrysotile
223-D 042004031-0129	Room 223 - Wall D - Plaster		HA: 60		N/A
223-E 042004031-0130	Room 223 - Ceiling - Plaster		HA: 60		N/A
233-A-Skim Coat 042004031-0131	Room 233 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-A-Plaster 042004031-0131A	Room 233 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-B-Skim Coat 042004031-0132	Room 233 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-B-Plaster 042004031-0132A	Room 233 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-C-Skim Coat 042004031-0133	Room 233 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-C-Plaster 042004031-0133A	Room 233 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 61	100% Non-fibrous (Other)	None Detected
233-D 042004031-0134	Room 233 - Wall D - Plaster		HA: 61		N/A
233-E 042004031-0135	Room 233 - Ceiling - Plaster		HA: 61		N/A
234-A-Skim Coat 042004031-0136	Room 234 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
234-A-Plaster	Room 234 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 62	100% Non-fibrous (Other)	None Detected
042004031-0136A					
234-B-Skim Coat	Room 234 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 62	100% Non-fibrous (Other)	None Detected
042004031-0137					
234-B-Plaster	Room 234 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
042004031-0137A					
234-C-Skim Coat	Room 234 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 62	100% Non-fibrous (Other)	None Detected
042004031-0138					
234-C-Plaster	Room 234 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 62	100% Non-fibrous (Other)	None Detected
042004031-0138A					
234-D	Room 234 - Wall D - Plaster		HA: 62		N/A
042004031-0139					
234-E	Room 234 - Ceiling - Plaster		HA: 62		N/A
042004031-0140					
COR2A-A-Skim Coat	Room Corridor A 2nd Floor - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0141					
COR2A-A-Base Coat	Room Corridor A 2nd Floor - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0141A					
COR2A-B-Skim Coat	Room Corridor A 2nd Floor - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0142					
COR2A-B-Base Coat	Room Corridor A 2nd Floor - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0142A					
COR2A-C-Skim Coat	Room Corridor A 2nd Floor - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0143					
COR2A-C-Base Coat	Room Corridor A 2nd Floor - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 63	100% Non-fibrous (Other)	None Detected
042004031-0143A					
COR2A-D	Room Corridor A 2nd Floor - Wall D - Plaster		HA: 63		N/A
042004031-0144					

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
COR2A-E 042004031-0145	Room Corridor A 2nd Floor - Ceiling - Plaster		HA: 63		N/A
COR3A-A-Skim Coat 042004031-0146	Room Corridor A 3rd Floor - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-A-Base Coat 042004031-0146A	Room Corridor A 3rd Floor - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-B-Skim Coat 042004031-0147	Room Corridor A 3rd Floor - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-B-Base Coat 042004031-0147A	Room Corridor A 3rd Floor - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-C-Skim Coat 042004031-0148	Room Corridor A 3rd Floor - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-C-Base Coat 042004031-0148A	Room Corridor A 3rd Floor - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 64	100% Non-fibrous (Other)	None Detected
COR3A-D 042004031-0149	Room Corridor A 3rd Floor - Wall D - Plaster		HA: 64		N/A
COR3A-E 042004031-0150	Room Corridor A 3rd Floor - Ceiling - Plaster		HA: 64		N/A
225-A-Skim Coat 042004031-0151	Room 225 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected
225-A-Base Coat 042004031-0151A	Room 225 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected
225-B-Skim Coat 042004031-0152	Room 225 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected
225-B-Base Coat 042004031-0152A	Room 225 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected
225-C-Skim Coat 042004031-0153	Room 225 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
225-C-Base Coat 042004031-0153A	Room 225 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 65	100% Non-fibrous (Other)	None Detected
225-D 042004031-0154	Room 225 - Wall D - Plaster		HA: 65		N/A
225-E 042004031-0155	Room 225 - Ceiling - Plaster		HA: 65		N/A
227-A-Skim Coat 042004031-0156	Room 227 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-A-Base Coat 042004031-0156A	Room 227 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-B-Skim Coat 042004031-0157	Room 227 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-B-Base Coat 042004031-0157A	Room 227 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-C-Skim Coat 042004031-0158	Room 227 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-C-Base Coat 042004031-0158A	Room 227 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 66	100% Non-fibrous (Other)	None Detected
227-D 042004031-0159	Room 227 - Wall D - Plaster		HA: 66		N/A
227-E 042004031-0160	Room 227 - Ceiling - Plaster		HA: 66		N/A
229-A-Skim Coat 042004031-0161	Room 229 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 67	100% Non-fibrous (Other)	None Detected
229-A-Base Coat 042004031-0161A	Room 229 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 67	100% Non-fibrous (Other)	<1% Chrysotile
229-B-Skim Coat 042004031-0162	Room 229 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 67	100% Non-fibrous (Other)	None Detected
229-B-Base Coat 042004031-0162A	Room 229 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
			HA: 67		
229-C-Skim Coat 042004031-0163	Room 229 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 67		
229-C-Base Coat 042004031-0163A	Room 229 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
			HA: 67		
229-D 042004031-0164	Room 229 - Wall D - Plaster				N/A
			HA: 67		
229-E 042004031-0165	Room 229 - Ceiling - Plaster				N/A
			HA: 67		
231-A-Skim Coat 042004031-0166	Room 231 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-A-Base Coat 042004031-0166A	Room 231 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-B-Skim Coat 042004031-0167	Room 231 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-B-Base Coat 042004031-0167A	Room 231 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-C-Skim Coat 042004031-0168	Room 231 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-C-Base Coat 042004031-0168A	Room 231 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 68		
231-D 042004031-0169	Room 231 - Wall D - Plaster				N/A
			HA: 68		
231-E 042004031-0170	Room 231 - Ceiling - Plaster				N/A
			HA: 68		
325-A-Skim Coat 042004031-0171	Room 325 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 69		
325-A-Base Coat 042004031-0171A	Room 325 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
			HA: 69		

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
325-B-Skim Coat 042004031-0172	Room 325 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 69	100% Non-fibrous (Other)	None Detected
325-B-Base Coat 042004031-0172A	Room 325 - Wall B - Plaster	Gray Fibrous Homogeneous	HA: 69 3% Synthetic	97% Non-fibrous (Other)	None Detected
325-C-Skim Coat 042004031-0173	Room 325 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 69	100% Non-fibrous (Other)	None Detected
325-C-Base Coat 042004031-0173A	Room 325 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 69 3% Synthetic	97% Non-fibrous (Other)	None Detected
325-D-Skim Coat 042004031-0174	Room 325 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 69	100% Non-fibrous (Other)	None Detected
325-D-Base Coat 042004031-0174A	Room 325 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 69 3% Synthetic	97% Non-fibrous (Other)	None Detected
325-E-Skim Coat 042004031-0175	Room 325 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 69	100% Non-fibrous (Other)	None Detected
325-E-Base Coat 042004031-0175A	Room 325 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 69 3% Synthetic	97% Non-fibrous (Other)	None Detected
327-A-Skim Coat 042004031-0176	Room 327 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
327-A-Base Coat 042004031-0176A	Room 327 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 70 3% Synthetic	97% Non-fibrous (Other)	None Detected
327-B-Skim Coat 042004031-0177	Room 327 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
327-B-Base Coat 042004031-0177A	Room 327 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 70 3% Synthetic	97% Non-fibrous (Other)	None Detected
327-C-Skim Coat 042004031-0178	Room 327 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
327-C-Base Coat 042004031-0178A	Room 327 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 70 3% Synthetic	97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042004031**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
327-D-Skim Coat 042004031-0179	Room 327 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
327-D-Base Coat 042004031-0179A	Room 327 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 70	3% Synthetic 97% Non-fibrous (Other)	None Detected
327-E-Skim Coat 042004031-0180	Room 327 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
327-E-Base Coat 042004031-0180A	Room 327 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 70	100% Non-fibrous (Other)	None Detected
329-A-Skim Coat 042004031-0181	Room 329 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-A-Base Coat 042004031-0181A	Room 329 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-B-Skim Coat 042004031-0182	Room 329 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-B-Base Coat 042004031-0182A	Room 329 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 71	3% Synthetic 97% Non-fibrous (Other)	None Detected
329-C-Skim Coat 042004031-0183	Room 329 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-C-Base Coat 042004031-0183A	Room 329 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-D-Skim Coat 042004031-0184	Room 329 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-D-Base Coat 042004031-0184A	Room 329 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 71	3% Synthetic 97% Non-fibrous (Other)	None Detected
329-E-Skim Coat 042004031-0185	Room 329 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected
329-E-Base Coat 042004031-0185A	Room 329 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 71	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
333-A-Skim Coat 042004031-0186	Room 333 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-A-Base Coat 042004031-0186A	Room 333 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-B-Skim Coat 042004031-0187	Room 333 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-B-Base Coat 042004031-0187A	Room 333 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 72	97% Non-fibrous (Other)	None Detected
333-C-Skim Coat 042004031-0188	Room 333 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-C-Base Coat 042004031-0188A	Room 333 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 72	97% Non-fibrous (Other)	None Detected
333-D-Skim Coat 042004031-0189	Room 333 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-D-Base Coat 042004031-0189A	Room 333 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 72	97% Non-fibrous (Other)	None Detected
333-E-Skim Coat 042004031-0190	Room 333 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
333-E-Base Coat 042004031-0190A	Room 333 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 72	100% Non-fibrous (Other)	None Detected
334-A-Skim Coat 042004031-0191	Room 334 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-A-Base Coat 042004031-0191A	Room 334 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	95% Non-fibrous (Other)	2% Chrysotile
334-B-Skim Coat 042004031-0192	Room 334 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-B-Base Coat 042004031-0192A	Room 334 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
334-C-Skim Coat 042004031-0193	Room 334 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-C-Base Coat 042004031-0193A	Room 334 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
334-D-Skim Coat 042004031-0194	Room 334 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-D-Base Coat 042004031-0194A	Room 334 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-E-Skim Coat 042004031-0195	Room 334 - Ceiling - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
334-E-Base Coat 042004031-0195A	Room 334 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
335-A-Skim Coat 042004031-0196	Room 335 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-A-Base Coat 042004031-0196A	Room 335 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-B-Skim Coat 042004031-0197	Room 335 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-B-Base Coat 042004031-0197A	Room 335 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-C-Skim Coat 042004031-0198	Room 335 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-C-Base Coat 042004031-0198A	Room 335 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-D-Skim Coat 042004031-0199	Room 335 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-D-Base Coat 042004031-0199A	Room 335 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
335-E 042004031-0200	Room 335 - Ceiling - Plaster				N/A
337-A-Skim Coat 042004031-0201	Room 337 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
337-A-Base Coat 042004031-0201A	Room 337 - Wall A - Plaster	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
337-B-Skim Coat 042004031-0202	Room 337 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
337-B-Base Coat 042004031-0202A	Room 337 - Wall B - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
337-C-Skim Coat 042004031-0203	Room 337 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
337-C-Base Coat 042004031-0203A	Room 337 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 11:52:46



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
337-D-Skim Coat 042004031-0204	Room 337 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
337-D-Base Coat 042004031-0204A	Room 337 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
337-E 042004031-0205	Room 337 - Ceiling - Plaster				N/A
336-A-Skim Coat 042004031-0206	Room 336 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
336-A-Base Coat 042004031-0206A	Room 336 - Wall A - Plaster	Gray Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
336-B-Skim Coat 042004031-0207	Room 336 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
336-B-Base Coat 042004031-0207A	Room 336 - Wall B - Plaster	Gray Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	<1% Chrysotile
336-C-Skim Coat 042004031-0208	Room 336 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
336-C-Base Coat 042004031-0208A	Room 336 - Wall C - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
336-D-Skim Coat 042004031-0209	Room 336 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
336-D-Base Coat 042004031-0209A	Room 336 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
336-E-Skim Coat 042004031-0210	Room 336 - Ceiling - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
336-E-Base Coat 042004031-0210A	Room 336 - Ceiling - Plaster	Gray Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042004031

Customer ID: COCC45

Customer PO:

Project ID:

Preliminary Report

Actual results may differ

Analyst(s)

Amy Johnson (8)

Kelly Thomas (86)

Laura Kantor (18)

Michelle Quach (78)

Nicholas Montoya-Orozco (47)

Paige Havener (40)

Will DiBella (10)

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367, LA #04127

Initial report from: 02/20/2020 11:52:46

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:**

Attention: Mike Baltrusaitis
 Cocciardi & Associates Inc.
 1337 Veterans Memorial Drive
 Jessup, PA 18434

Phone: (570) 291-0030**Fax:** (570) 963-0242**Received Date:** 02/13/2020 10:30 AM**Analysis Date:** 02/17/2020 - 02/19/2020**Collected Date:** 02/06/2020**Project:** SSD Northeast Intermediate 200115

**Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized
 Light Microscopy**

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos % Type</u>
			% Fibrous	% Non-Fibrous	
301-A-Skim Coat <small>042003862-0001</small>	Room 301 - Wall A - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
301-A-Base Coat <small>042003862-0001A</small>	Room 301 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 1	95% Non-fibrous (Other)	None Detected
301-B-Skim Coat <small>042003862-0002</small>	Room 301 - Wall B - Plaster	White/Peach Non-Fibrous Heterogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
301-B-Base Coat <small>042003862-0002A</small>	Room 301 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 1	95% Non-fibrous (Other)	None Detected
301-C-Skim Coat <small>042003862-0003</small>	Room 301 - Wall C - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
301-C-Base Coat <small>042003862-0003A</small>	Room 301 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 1	95% Non-fibrous (Other)	None Detected
301-D-Skim Coat <small>042003862-0004</small>	Room 301 - Wall D - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
301-D-Base Coat <small>042003862-0004A</small>	Room 301 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 1	95% Non-fibrous (Other)	None Detected
301-E-Skim Coat <small>042003862-0005</small>	Room 301 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
301-E-Base Coat <small>042003862-0005A</small>	Room 301 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 1	100% Non-fibrous (Other)	None Detected
302-A-Skim Coat <small>042003862-0006</small>	Room 302 - Wall A - Plaster	Tan/White Non-Fibrous Heterogeneous	HA: 2	100% Non-fibrous (Other)	None Detected
302-A-Base Coat <small>042003862-0006A</small>	Room 302 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 2	95% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
302-B-Skim Coat 042003862-0007	Room 302 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 2	100% Non-fibrous (Other)	None Detected
302-B-Base Coat 042003862-0007A	Room 302 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 2 5% Synthetic	95% Non-fibrous (Other)	None Detected
302-C-Skim Coat 042003862-0008	Room 302 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 2	100% Non-fibrous (Other)	None Detected
302-C-Base Coat 042003862-0008A	Room 302 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 2 5% Synthetic	95% Non-fibrous (Other)	None Detected
302-D-Skim Coat 042003862-0009	Room 302 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 2	100% Non-fibrous (Other)	None Detected
302-D-Base Coat 042003862-0009A	Room 302 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 2 5% Synthetic	95% Non-fibrous (Other)	None Detected
302-E-Skim Coat 042003862-0010	Room 302 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 2	100% Non-fibrous (Other)	None Detected
302-E-Base Coat 042003862-0010A	Room 302 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 2 5% Synthetic	95% Non-fibrous (Other)	None Detected
303-A-Skim Coat 042003862-0011	Room 303 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 3	100% Non-fibrous (Other)	None Detected
303-A-Base Coat 042003862-0011A	Room 303 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 3 5% Synthetic	95% Non-fibrous (Other)	None Detected
303-B-Skim Coat 042003862-0012	Room 303 - Wall B - Plaster	Tan/White Non-Fibrous Homogeneous	HA: 3	100% Non-fibrous (Other)	None Detected
303-B-Base Coat 042003862-0012A	Room 303 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 3 5% Synthetic	95% Non-fibrous (Other)	None Detected
303-C-Skim Coat 042003862-0013	Room 303 - Wall C - Plaster	Tan/White Non-Fibrous Homogeneous	HA: 3	100% Non-fibrous (Other)	None Detected
303-C-Base Coat 042003862-0013A	Room 303 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 3 5% Synthetic	95% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
303-D-Skim Coat 042003862-0014	Room 303 - Wall D - Plaster	Tan/White Non-Fibrous Homogeneous	HA: 3	100% Non-fibrous (Other)	None Detected
303-D-Base Coat 042003862-0014A	Room 303 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 3 5% Synthetic	95% Non-fibrous (Other)	None Detected
303-E-Skim Coat 042003862-0015	Room 303 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 3	100% Non-fibrous (Other)	None Detected
303-E-Base Coat 042003862-0015A	Room 303 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 3 5% Synthetic	95% Non-fibrous (Other)	None Detected
304-A-Skim Coat 042003862-0016	Room 304 - Wall A - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 4	100% Non-fibrous (Other)	None Detected
304-A-Base Coat 042003862-0016A	Room 304 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 4 5% Synthetic	95% Non-fibrous (Other)	None Detected
304-B-Skim Coat 042003862-0017	Room 304 - Wall B - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 4	100% Non-fibrous (Other)	None Detected
304-B-Base Coat 042003862-0017A	Room 304 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 4 5% Synthetic	95% Non-fibrous (Other)	None Detected
304-C-Skim Coat 042003862-0018	Room 304 - Wall C - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 4	100% Non-fibrous (Other)	None Detected
304-C-Base Coat 042003862-0018A	Room 304 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 4 5% Synthetic	95% Non-fibrous (Other)	None Detected
304-D-Skim Coat 042003862-0019	Room 304 - Wall D - Plaster	White/Blue Non-Fibrous Heterogeneous	HA: 4	100% Non-fibrous (Other)	None Detected
304-D-Base Coat 042003862-0019A	Room 304 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 4 5% Synthetic	95% Non-fibrous (Other)	None Detected
304-E-Skim Coat 042003862-0020	Room 304 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 4	100% Non-fibrous (Other)	None Detected
304-E-Base Coat 042003862-0020A	Room 304 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 4 5% Synthetic	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
305-A-Skim Coat 042003862-0021	Room 305 - Wall A - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-A-Base Coat 042003862-0021A	Room 305 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 5	95% Non-fibrous (Other)	None Detected
305-B-Skim Coat 042003862-0022	Room 305 - Wall B - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-B-Base Coat 042003862-0022A	Room 305 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-C-Skim Coat 042003862-0023	Room 305 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-C-Base Coat 042003862-0023A	Room 305 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 5	95% Non-fibrous (Other)	None Detected
305-D-Skim Coat 042003862-0024	Room 305 - Wall D - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-D-Base Coat 042003862-0024A	Room 305 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-E-Skim Coat 042003862-0025	Room 305 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
305-E-Base Coat 042003862-0025A	Room 305 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 5	100% Non-fibrous (Other)	None Detected
306-A-Skim Coat 042003862-0026	Room 306 - Wall A - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
306-A-Base Coat 042003862-0026A	Room 306 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 6	95% Non-fibrous (Other)	None Detected
306-B-Skim Coat 042003862-0027	Room 306 - Wall B - Plaster	White/Green Non-Fibrous Homogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
306-B-Base Coat 042003862-0027A	Room 306 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 6	95% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
306-C-Skim Coat 042003862-0028	Room 306 - Wall C - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
306-C-Base Coat 042003862-0028A	Room 306 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 6 5% Synthetic	95% Non-fibrous (Other)	None Detected
306-D-Skim Coat 042003862-0029	Room 306 - Wall D - Plaster	White/Green Non-Fibrous Heterogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
306-D-Base Coat 042003862-0029A	Room 306 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 6 5% Synthetic	95% Non-fibrous (Other)	None Detected
306-E-Skim Coat 042003862-0030	Room 306 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
306-E-Base Coat 042003862-0030A	Room 306 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 6	100% Non-fibrous (Other)	None Detected
309-A-Skim Coat 042003862-0031	Room 309 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
309-A-Base Coat 042003862-0031A	Room 309 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 7 3% Hair	97% Non-fibrous (Other)	None Detected
309-B-Skim Coat 042003862-0032	Room 309 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
309-B-Base Coat 042003862-0032A	Room 309 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 7 4% Hair	96% Non-fibrous (Other)	None Detected
309-C-Skim Coat 042003862-0033	Room 309 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
309-C-Base Coat 042003862-0033A	Room 309 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 7 2% Hair	98% Non-fibrous (Other)	None Detected
309-D-Skim Coat 042003862-0034	Room 309 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
309-D-Base Coat 042003862-0034A	Room 309 - Wall D - Plaster	Gray Fibrous Homogeneous	HA: 7 3% Cellulose	97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
309-E-Skim Coat 042003862-0035	Room 309 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
309-E-Base Coat 042003862-0035A	Room 309 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 7	100% Non-fibrous (Other)	None Detected
313-A-Skim Coat 042003862-0036	Room 313 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-A-Base Coat 042003862-0036A	Room 313 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-B-Skim Coat 042003862-0037	Room 313 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-B-Base Coat 042003862-0037A	Room 313 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 8	2% Hair 98% Non-fibrous (Other)	None Detected
313-C-Skim Coat 042003862-0038	Room 313 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-C-Base Coat 042003862-0038A	Room 313 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 8	3% Hair 97% Non-fibrous (Other)	None Detected
313-D-Skim Coat 042003862-0039	Room 313 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-D-Base Coat 042003862-0039A	Room 313 - Wall D - Plaster	Gray Fibrous Homogeneous	HA: 8	4% Cellulose 96% Non-fibrous (Other)	None Detected
313-E-Skim Coat 042003862-0040	Room 313 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
313-E-Base Coat 042003862-0040A	Room 313 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 8	100% Non-fibrous (Other)	None Detected
315-A-Skim Coat 042003862-0041	Room 315 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
315-A-Base Coat 042003862-0041A	Room 315 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 9	3% Hair 97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
315-B-Skim Coat 042003862-0042	Room 315 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
315-B-Base Coat 042003862-0042A	Room 315 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	2% Hair HA: 9	98% Non-fibrous (Other)	None Detected
315-C-Skim Coat 042003862-0043	Room 315 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
315-C-Base Coat 042003862-0043A	Room 315 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	2% Hair HA: 9	98% Non-fibrous (Other)	None Detected
315-D-Skim Coat 042003862-0044	Room 315 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
315-D-Base Coat 042003862-0044A	Room 315 - Wall D - Plaster	Gray Fibrous Homogeneous	3% Cellulose HA: 9	97% Non-fibrous (Other)	None Detected
315-E-Skim Coat 042003862-0045	Room 315 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
315-E-Base Coat 042003862-0045A	Room 315 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 9	100% Non-fibrous (Other)	None Detected
316-A-Skim Coat 042003862-0046	Room 316 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-A-Base Coat 042003862-0046A	Room 316 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	3% Hair HA: 10	97% Non-fibrous (Other)	None Detected
316-B-Skim Coat 042003862-0047	Room 316 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-B-Base Coat 042003862-0047A	Room 316 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-C-Skim Coat 042003862-0048	Room 316 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-C-Base Coat 042003862-0048A	Room 316 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	3% Hair HA: 10	97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
316-D-Skim Coat 042003862-0049	Room 316 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-D-Base Coat 042003862-0049A	Room 316 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-E-Skim Coat 042003862-0050	Room 316 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
316-E-Base Coat 042003862-0050A	Room 316 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 10	100% Non-fibrous (Other)	None Detected
319-A-Skim Coat 042003862-0051	Room 319 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-A-Base Coat 042003862-0051A	Room 319 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-B-Skim Coat 042003862-0052	Room 319 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-B-Base Coat 042003862-0052A	Room 319 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-C-Skim Coat 042003862-0053	Room 319 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-C-Base Coat 042003862-0053A	Room 319 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-D-Skim Coat 042003862-0054	Room 319 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-D-Base Coat 042003862-0054A	Room 319 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 11	5% Cellulose 95% Non-fibrous (Other)	None Detected
319-E-Skim Coat 042003862-0055	Room 319 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 11	100% Non-fibrous (Other)	None Detected
319-E-Base Coat 042003862-0055A	Room 319 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 11	5% Cellulose 95% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
321-A-Skim Coat 042003862-0056	Room 321 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-A-Base Coat 042003862-0056A	Room 321 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-B-Skim Coat 042003862-0057	Room 321 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-B-Base Coat 042003862-0057A	Room 321 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-C-Skim Coat 042003862-0058	Room 321 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-C-Base Coat 042003862-0058A	Room 321 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 12	5% Cellulose 95% Non-fibrous (Other)	None Detected
321-D-Skim Coat 042003862-0059	Room 321 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-D-Base Coat 042003862-0059A	Room 321 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 12	5% Cellulose 95% Non-fibrous (Other)	None Detected
321-E-Skim Coat 042003862-0060	Room 321 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 12	100% Non-fibrous (Other)	None Detected
321-E-Base Coat 042003862-0060A	Room 321 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 12	5% Cellulose 95% Non-fibrous (Other)	None Detected
201-A-Skim Coat 042003862-0061	Room 201 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-A-Base Coat 042003862-0061A	Room 201 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-B-Skim Coat 042003862-0062	Room 201 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-B-Base Coat 042003862-0062A	Room 201 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
201-C-Skim Coat 042003862-0063	Room 201 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-C-Base Coat 042003862-0063A	Room 201 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-D-Skim Coat 042003862-0064	Room 201 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-D-Base Coat 042003862-0064A	Room 201 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	3% Cellulose HA: 13	97% Non-fibrous (Other)	None Detected
201-E-Skim Coat 042003862-0065	Room 201 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 13	100% Non-fibrous (Other)	None Detected
201-E-Base Coat 042003862-0065A	Room 201 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	2% Cellulose HA: 13	98% Non-fibrous (Other)	None Detected
202-A 042003862-0066	Room 202 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
202-B-Skim Coat 042003862-0067	Room 202 - Wall B - Plaster	White Non-Fibrous Homogeneous	5% Fibrous (Other) HA: 14	95% Non-fibrous (Other)	None Detected
202-B-Base Coat 042003862-0067A	Room 202 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic HA: 14	95% Non-fibrous (Other)	None Detected
202-C-Skim Coat 042003862-0068	Room 202 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
202-C-Base Coat 042003862-0068A	Room 202 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
202-D-Skim Coat 042003862-0069	Room 202 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
202-D-Base Coat 042003862-0069A	Room 202 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
202-E-Skim Coat 042003862-0070	Room 202 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
202-E-Base Coat 042003862-0070A	Room 202 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 14	100% Non-fibrous (Other)	None Detected
299-A-Skim Coat 042003862-0071	Room 299 Girls Gym - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 15	5% Fibrous (Other) 95% Non-fibrous (Other)	None Detected
299-A-Base Coat 042003862-0071A	Room 299 Girls Gym - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-B-Skim Coat 042003862-0072	Room 299 Girls Gym - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-B-Base Coat 042003862-0072A	Room 299 Girls Gym - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 15	5% Cellulose 95% Non-fibrous (Other)	None Detected
299-C-Skim Coat 042003862-0073	Room 299 Girls Gym - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-C-Base Coat 042003862-0073A	Room 299 Girls Gym - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-D-Skim Coat 042003862-0074	Room 299 Girls Gym - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-D-Base Coat 042003862-0074A	Room 299 Girls Gym - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-E-Skim Coat 042003862-0075	Room 299 Girls Gym - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
299-E-Base Coat 042003862-0075A	Room 299 Girls Gym - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 15	100% Non-fibrous (Other)	None Detected
203-A-Skim Coat 042003862-0076	Room 203 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 16	100% Non-fibrous (Other)	None Detected
203-A-Base Coat 042003862-0076A	Room 203 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 16	5% Cellulose 95% Non-fibrous (Other)	None Detected
203-B-Skim Coat 042003862-0077	Room 203 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 16	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
203-B-Base Coat 042003862-0077A	Room 203 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			HA: 16		
203-C-Skim Coat 042003862-0078	Room 203 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 16		
203-C-Base Coat 042003862-0078A	Room 203 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			HA: 16		
203-D-Skim Coat 042003862-0079	Room 203 - Wall D - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 16		
203-D-Base Coat 042003862-0079A	Room 203 - Wall D - Plaster	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 16		
203-E-Skim Coat 042003862-0080	Room 203 - Ceiling - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 16		
203-E-Base Coat 042003862-0080A	Room 203 - Ceiling - Plaster	Gray Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
			HA: 16		
205-A-Skim Coat 042003862-0081	Room 205 - Wall A - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 17		
205-A-Base Coat 042003862-0081A	Room 205 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic	95% Non-fibrous (Other)	None Detected
			HA: 17		
205-B-Skim Coat 042003862-0082	Room 205 - Wall B - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 17		
205-B-Base Coat 042003862-0082A	Room 205 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			HA: 17		
205-C-Skim Coat 042003862-0083	Room 205 - Wall C - Plaster	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
			HA: 17		
205-C-Base Coat 042003862-0083A	Room 205 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	5% Synthetic	95% Non-fibrous (Other)	None Detected
			HA: 17		
205-D 042003862-0084	Room 205 - Wall D - Plaster	Gray Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
			HA: 17		

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
205-E-Skim Coat 042003862-0085	Room 205 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 17	100% Non-fibrous (Other)	None Detected
205-E-Base Coat 042003862-0085A	Room 205 - Ceiling - Plaster	Gray Fibrous Homogeneous	HA: 17	3% Cellulose 97% Non-fibrous (Other)	None Detected
207-A-Skim Coat 042003862-0086	Room 207 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-A-Base Coat 042003862-0086A	Room 207 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-B-Skim Coat 042003862-0087	Room 207 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-B-Base Coat 042003862-0087A	Room 207 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-C-Skim Coat 042003862-0088	Room 207 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-C-Base Coat 042003862-0088A	Room 207 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-D-Skim Coat 042003862-0089	Room 207 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-D-Base Coat 042003862-0089A	Room 207 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-E-Skim Coat 042003862-0090	Room 207 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 18	100% Non-fibrous (Other)	None Detected
207-E-Base Coat 042003862-0090A	Room 207 - Ceiling - Plaster	Gray Fibrous Homogeneous	HA: 18	3% Cellulose 97% Non-fibrous (Other)	None Detected
209-A-Skim Coat 042003862-0091	Room 209 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected
209-A-Base Coat 042003862-0091A	Room 209 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
209-B-Skim Coat 042003862-0092	Room 209 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected
209-B-Base Coat 042003862-0092A	Room 209 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 19 5% Cellulose	95% Non-fibrous (Other)	None Detected
209-C-Skim Coat 042003862-0093	Room 209 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected
209-C-Base Coat 042003862-0093A	Room 209 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 19 5% Synthetic	95% Non-fibrous (Other)	None Detected
209-D-Skim Coat 042003862-0094	Room 209 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected
209-D-Base Coat 042003862-0094A	Room 209 - Wall D - Plaster	Gray Fibrous Homogeneous	HA: 19 5% Synthetic	95% Non-fibrous (Other)	None Detected
209-E-Skim Coat 042003862-0095	Room 209 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 19	100% Non-fibrous (Other)	None Detected
209-E-Base Coat 042003862-0095A	Room 209 - Ceiling - Plaster	Gray Fibrous Homogeneous	HA: 19 5% Cellulose	95% Non-fibrous (Other)	None Detected
211-A-Skim Coat 042003862-0096	Room 211 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 20	100% Non-fibrous (Other)	None Detected
211-A-Base Coat 042003862-0096A	Room 211 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 20 2% Hair	98% Non-fibrous (Other)	None Detected
211-B-Skim Coat 042003862-0097	Room 211 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 20	100% Non-fibrous (Other)	None Detected
211-B-Base Coat 042003862-0097A	Room 211 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 20 100% Non-fibrous (Other)	100% Non-fibrous (Other)	None Detected
211-C-Skim Coat 042003862-0098	Room 211 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 20	100% Non-fibrous (Other)	None Detected
211-C-Base Coat 042003862-0098A	Room 211 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 20 3% Hair	97% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
211-D-Skim Coat 042003862-0099	Room 211 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 20	100% Non-fibrous (Other)	None Detected
211-D-Base Coat 042003862-0099A	Room 211 - Wall D - Plaster	Gray Fibrous Homogeneous	4% Cellulose HA: 20	96% Non-fibrous (Other)	None Detected
211-E-Skim Coat 042003862-0100	Room 211 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 20	100% Non-fibrous (Other)	None Detected
211-E-Base Coat 042003862-0100A	Room 211 - Ceiling - Plaster	Gray Fibrous Homogeneous	6% Cellulose HA: 20	94% Non-fibrous (Other)	None Detected
214-A-Skim Coat 042003862-0101	Room 214 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 21	100% Non-fibrous (Other)	None Detected
214-A-Base Coat 042003862-0101A	Room 214 - Wall A - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 21	95% Non-fibrous (Other)	None Detected
214-B-Skim Coat 042003862-0102	Room 214 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 21	100% Non-fibrous (Other)	None Detected
214-B-Base Coat 042003862-0102A	Room 214 - Wall B - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 21	95% Non-fibrous (Other)	None Detected
214-C-Skim Coat 042003862-0103	Room 214 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 21	100% Non-fibrous (Other)	None Detected
214-C-Base Coat 042003862-0103A	Room 214 - Wall C - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 21	95% Non-fibrous (Other)	None Detected
214-D-Skim Coat 042003862-0104	Room 214 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 21	100% Non-fibrous (Other)	None Detected
214-D-Base Coat 042003862-0104A	Room 214 - Wall D - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 21	95% Non-fibrous (Other)	None Detected
214-E-Skim Coat 042003862-0105	Room 214 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 21	100% Non-fibrous (Other)	None Detected
214-E-Base Coat 042003862-0105A	Room 214 - Ceiling - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 21	95% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
217-A-Skim Coat 042003862-0106	Room 217 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 22	100% Non-fibrous (Other)	None Detected
217-A-Base Coat 042003862-0106A	Room 217 - Wall A - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 22	97% Non-fibrous (Other)	None Detected
217-B 042003862-0107	Room 217 - Wall B - Plaster	Brown/White Fibrous Homogeneous	30% Cellulose HA: 22	70% Non-fibrous (Other)	None Detected
217-C-Skim Coat 042003862-0108	Room 217 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 22	100% Non-fibrous (Other)	None Detected
217-C-Base Coat 042003862-0108A	Room 217 - Wall C - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 22	97% Non-fibrous (Other)	None Detected
217-D-Skim Coat 042003862-0109	Room 217 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 22	100% Non-fibrous (Other)	None Detected
217-D-Base Coat 042003862-0109A	Room 217 - Wall D - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 22	97% Non-fibrous (Other)	None Detected
217-E-Skim Coat 042003862-0110	Room 217 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 22	100% Non-fibrous (Other)	None Detected
217-E-Base Coat 042003862-0110A	Room 217 - Ceiling - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 22	95% Non-fibrous (Other)	None Detected
219-A-Skim Coat 042003862-0111	Room 219 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected
219-A-Base Coat 042003862-0111A	Room 219 - Wall A - Plaster	Gray Fibrous Homogeneous	4% Cellulose HA: 23	96% Non-fibrous (Other)	None Detected
219-B-Skim Coat 042003862-0112	Room 219 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected
219-B-Base Coat 042003862-0112A	Room 219 - Wall B - Plaster	Gray Fibrous Homogeneous	4% Synthetic HA: 23	96% Non-fibrous (Other)	None Detected
219-C-Skim Coat 042003862-0113	Room 219 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
219-C-Base Coat 042003862-0113A	Room 219 - Wall C - Plaster	Gray Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected
219-D-Skim Coat 042003862-0114	Room 219 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected
219-D-Base Coat 042003862-0114A	Room 219 - Wall D - Plaster	Gray Fibrous Homogeneous	HA: 23	3% Cellulose 97% Non-fibrous (Other)	None Detected
219-E-Skim Coat 042003862-0115	Room 219 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 23	100% Non-fibrous (Other)	None Detected
219-E-Base Coat 042003862-0115A	Room 219 - Ceiling - Plaster	Gray Fibrous Homogeneous	HA: 23	3% Cellulose 97% Non-fibrous (Other)	None Detected
101-A-Skim Coat 042003862-0116	Room 101 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 24	100% Non-fibrous (Other)	None Detected
101-A-Base Coat 042003862-0116A	Room 101 - Wall A - Plaster	Gray Fibrous Homogeneous	HA: 24	100% Non-fibrous (Other)	None Detected
101-B-Plaster 042003862-0117	Room 101 - Wall B - Plaster	Brown/White/Orange Fibrous Heterogeneous	HA: 24	15% Cellulose 85% Non-fibrous (Other)	None Detected
Result includes a small amount of inseparable attached material					
101-B-Insulation 042003862-0117A	Room 101 - Wall B - Plaster	Brown Fibrous Homogeneous	HA: 24	90% Cellulose 10% Non-fibrous (Other)	None Detected
101-C-Plaster 042003862-0118	Room 101 - Wall C - Plaster	Brown/White/Blue Fibrous Heterogeneous	HA: 24	20% Cellulose 80% Non-fibrous (Other)	None Detected
Result includes a small amount of inseparable attached material					
101-C-Insulation 042003862-0118A	Room 101 - Wall C - Plaster	Brown Fibrous Homogeneous	HA: 24	90% Cellulose 10% Non-fibrous (Other)	None Detected
101-D-Skim Coat 042003862-0119	Room 101 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 24	100% Non-fibrous (Other)	None Detected
101-D-Base Coat 042003862-0119A	Room 101 - Wall D - Plaster	Tan Fibrous Homogeneous	HA: 24	3% Cellulose 97% Non-fibrous (Other)	None Detected
101-E 042003862-0120	Room 101 - Ceiling - Plaster	Brown/White Fibrous Homogeneous	HA: 24	20% Cellulose 80% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
102-A-Skim Coat 042003862-0121	Room 102 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-A-Base Coat 042003862-0121A	Room 102 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-B-Skim Coat 042003862-0122	Room 102 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-B-Base Coat 042003862-0122A	Room 102 - Wall B - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 25	97% Non-fibrous (Other)	None Detected
102-C-Skim Coat 042003862-0123	Room 102 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-C-Base Coat 042003862-0123A	Room 102 - Wall C - Plaster	Tan Fibrous Homogeneous	2% Cellulose HA: 25	98% Non-fibrous (Other)	None Detected
102-D-Skim Coat 042003862-0124	Room 102 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-D-Base Coat 042003862-0124A	Room 102 - Wall D - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 25	97% Non-fibrous (Other)	None Detected
102-E-Skim Coat 042003862-0125	Room 102 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 25	100% Non-fibrous (Other)	None Detected
102-E-Base Coat 042003862-0125A	Room 102 - Ceiling - Plaster	Gray Fibrous Homogeneous	3% Cellulose HA: 25	97% Non-fibrous (Other)	None Detected
103-A-Skim Coat 042003862-0126	Room 103 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected
103-A-Base Coat 042003862-0126A	Room 103 - Wall A - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 26	97% Non-fibrous (Other)	None Detected
103-B-Skim Coat 042003862-0127	Room 103 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected
103-B-Base Coat 042003862-0127A	Room 103 - Wall B - Plaster	Tan Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
103-C-Skim Coat 042003862-0128	Room 103 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected
103-C-Base Coat 042003862-0128A	Room 103 - Wall C - Plaster	Tan Fibrous Homogeneous	3% Cellulose HA: 26	97% Non-fibrous (Other)	None Detected
103-D-Skim Coat 042003862-0129	Room 103 - Wall D - Plaster	Brown/White Fibrous Homogeneous	10% Cellulose HA: 26	90% Non-fibrous (Other)	None Detected
103-D-Base Coat 042003862-0129A	Room 103 - Wall D - Plaster	Tan Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected
103-E-Skim Coat 042003862-0130	Room 103 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 26	100% Non-fibrous (Other)	None Detected
103-E-Base Coat 042003862-0130A	Room 103 - Ceiling - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 26	95% Non-fibrous (Other)	None Detected
105-A-Skim Coat 042003862-0131	Room 105 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-A-Base Coat 042003862-0131A	Room 105 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-B-Skim Coat 042003862-0132	Room 105 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-B-Base Coat 042003862-0132A	Room 105 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-C-Skim Coat 042003862-0133	Room 105 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-C-Base Coat 042003862-0133A	Room 105 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-D-Skim Coat 042003862-0134	Room 105 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-D-Base Coat 042003862-0134A	Room 105 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
105-E-Skim Coat 042003862-0135	Room 105 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 27	100% Non-fibrous (Other)	None Detected
105-E-Base Coat 042003862-0135A	Room 105 - Ceiling - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 27	95% Non-fibrous (Other)	None Detected
107-A-Skim Coat 042003862-0136	Room 107 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-A-Base Coat 042003862-0136A	Room 107 - Wall A - Plaster	Gray Fibrous Homogeneous	3% Cellulose HA: 28	97% Non-fibrous (Other)	None Detected
107-B-Skim Coat 042003862-0137	Room 107 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-B-Base Coat 042003862-0137A	Room 107 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-C-Skim Coat 042003862-0138	Room 107 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-C-Base Coat 042003862-0138A	Room 107 - Wall C - Plaster	Gray Fibrous Homogeneous	3% Cellulose HA: 28	97% Non-fibrous (Other)	None Detected
107-D-Skim Coat 042003862-0139	Room 107 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-D-Base Coat 042003862-0139A	Room 107 - Wall D - Plaster	Gray Fibrous Homogeneous	3% Cellulose HA: 28	97% Non-fibrous (Other)	None Detected
107-E-Skim Coat 042003862-0140	Room 107 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 28	100% Non-fibrous (Other)	None Detected
107-E-Base Coat 042003862-0140A	Room 107 - Ceiling - Plaster	Gray Fibrous Homogeneous	5% Cellulose HA: 28	95% Non-fibrous (Other)	None Detected
109-A-Skim Coat 042003862-0141	Room 109 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-A-Base Coat 042003862-0141A	Room 109 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
109-B-Skim Coat 042003862-0142	Room 109 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-B-Base Coat 042003862-0142A	Room 109 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-C-Skim Coat 042003862-0143	Room 109 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-C-Base Coat 042003862-0143A	Room 109 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-D-Skim Coat 042003862-0144	Room 109 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-D-Base Coat 042003862-0144A	Room 109 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-E-Skim Coat 042003862-0145	Room 109 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
109-E-Base Coat 042003862-0145A	Room 109 - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 29	100% Non-fibrous (Other)	None Detected
111-A-Skim Coat 042003862-0146	Room 111 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-A-Base Coat 042003862-0146A	Room 111 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-B-Skim Coat 042003862-0147	Room 111 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-B-Base Coat 042003862-0147A	Room 111 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-C-Skim Coat 042003862-0148	Room 111 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-C-Base Coat 042003862-0148A	Room 111 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
111-D-Skim Coat 042003862-0149	Room 111 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-D-Base Coat 042003862-0149A	Room 111 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-E-Skim Coat 042003862-0150	Room 111 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 30	100% Non-fibrous (Other)	None Detected
111-E-Base Coat 042003862-0150A	Room 111 - Ceiling - Plaster	Gray Fibrous Homogeneous	4% Cellulose HA: 30	96% Non-fibrous (Other)	None Detected
115-A-Skim Coat 042003862-0151	Room 115 - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-A-Base Coat 042003862-0151A	Room 115 - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-B-Skim Coat 042003862-0152	Room 115 - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-B-Base Coat 042003862-0152A	Room 115 - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-C-Skim Coat 042003862-0153	Room 115 - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-C-Base Coat 042003862-0153A	Room 115 - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-D-Skim Coat 042003862-0154	Room 115 - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-D-Base Coat 042003862-0154A	Room 115 - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-E-Skim Coat 042003862-0155	Room 115 - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 31	100% Non-fibrous (Other)	None Detected
115-E-Base Coat 042003862-0155A	Room 115 - Ceiling - Plaster	Gray Fibrous Homogeneous	6% Cellulose HA: 31	94% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com / cinnaslab@EMSL.com>

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos % Type
			% Fibrous	% Non-Fibrous	
COR3-A-Skim Coat 042003862-0156	Third Floor Hall - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-A-Base Coat 042003862-0156A	Third Floor Hall - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-B-Skim Coat 042003862-0157	Third Floor Hall - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-B-Base Coat 042003862-0157A	Third Floor Hall - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-C-Skim Coat 042003862-0158	Third Floor Hall - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-C-Base Coat 042003862-0158A	Third Floor Hall - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-D-Skim Coat 042003862-0159	Third Floor Hall - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-D-Base Coat 042003862-0159A	Third Floor Hall - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-E-Skim Coat 042003862-0160	Third Floor Hall - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR3-E-Base Coat 042003862-0160A	Third Floor Hall - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 32	100% Non-fibrous (Other)	None Detected
COR2-A-Skim Coat 042003862-0161	Second Floor Hall - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-A-Base Coat 042003862-0161A	Second Floor Hall - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-B-Skim Coat 042003862-0162	Second Floor Hall - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-B-Base Coat 042003862-0162A	Second Floor Hall - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53

**EMSL Analytical, Inc.**

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnaslab@EMSL.com**EMSL Order:** 042003862**Customer ID:** COCC45**Customer PO:****Project ID:****Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy**

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
COR2-C-Skim Coat 042003862-0163	Second Floor Hall - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-C-Base Coat 042003862-0163A	Second Floor Hall - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-D-Skim Coat 042003862-0164	Second Floor Hall - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-D-Base Coat 042003862-0164A	Second Floor Hall - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-E-Skim Coat 042003862-0165	Second Floor Hall - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR2-E-Base Coat 042003862-0165A	Second Floor Hall - Ceiling - Plaster	Gray Non-Fibrous Homogeneous	HA: 33	100% Non-fibrous (Other)	None Detected
COR1-A-Skim Coat 042003862-0166	First Floor Hall - Wall A - Plaster	White Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-A-Base Coat 042003862-0166A	First Floor Hall - Wall A - Plaster	Gray Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-B-Skim Coat 042003862-0167	First Floor Hall - Wall B - Plaster	White Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-B-Base Coat 042003862-0167A	First Floor Hall - Wall B - Plaster	Gray Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-C-Skim Coat 042003862-0168	First Floor Hall - Wall C - Plaster	White Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-C-Base Coat 042003862-0168A	First Floor Hall - Wall C - Plaster	Gray Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-D-Skim Coat 042003862-0169	First Floor Hall - Wall D - Plaster	White Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-D-Base Coat 042003862-0169A	First Floor Hall - Wall D - Plaster	Gray Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected

Initial report from: 02/20/2020 07:39:53



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042003862

Customer ID: COCC45

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
COR1-E-Skim Coat 042003862-0170	First Floor Hall - Ceiling - Plaster	White Non-Fibrous Homogeneous	HA: 34	100% Non-fibrous (Other)	None Detected
COR1-E-Base Coat 042003862-0170A	First Floor Hall - Ceiling - Plaster	Gray Fibrous Homogeneous	4% Cellulose HA: 34	96% Non-fibrous (Other)	None Detected

Analyst(s)

Andrew Burke (48)

Christina Maiorana (4)

Daniel Blake (33)

John Witcraft (46)

Kelly Thomas (48)

Marvalyn Sandling (48)

Nicholas Montoya-Orozco (53)

Nancy Stalter (26)

Paige Havener (30)

Samantha Rundstrom, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367, LA #04127

Initial report from: 02/20/2020 07:39:53