

Lead in Water Testing Results
South Washington County Schools
Grey Cloud Elementary School

On December 31st, 2020 Grey Cloud Elementary School's drinking water was tested for concentration of lead.

The following water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Hallway (outside 130)	SINK	3.8
Room 130	SINK	3.7
Room 130	FOUNTAIN	2.5
Room 131	SINK	2.4
Room 131	FOUNTAIN	1.8
Room 132	SINK	3.2
Room 132	FOUNTAIN	3.3
Hallway (SE)	FOUNTAIN	1.8
Room 102	SINK	2.3
Room 102	FOUNTAIN	1.8
Room 101	SINK	13.1
Room 101	FOUNTAIN	2.1
Room 101 (bath)	SINK	13.1
Room 005	SINK	5.6
Room 005	FOUNTAIN	1.6
Room 006	SINK	4.9

Hallway (NE)	FOUNTAIN	3.0
Room 115	SINK	2.3
Room 115	FOUNTAIN	5.9
Room 116	SINK	2.6
Room 117	SINK	3.0
Room 117	FOUNTAIN	3.4
Hallway (outside 117)	SINK	2.7
Hallway (outside 118)	SINK	2.5
Room 118	SINK	2.2
Room 122	FOUNTAIN	3.7
Room 123	SINK	3.0
Room 123	FOUNTAIN	3.3
Room 124	SINK	19.7
Room 124	FOUNTAIN	4.6
Hallway (outside 124)	SINK	3.0
Hallway (outside 123)	SINK	2.7
Room 126	SINK	9.8
Room 126	FOUNTAIN	5.0
Room 125	SINK	3.3
Room 119	SINK	4.3
Room 119	FOUNTAIN	3.0
Room 120	SINK	2.6
Room 120	FOUNTAIN	9.3
Room 121	SINK	2.2
Room 121	FOUNTAIN	2.9

Hallway (north, left)	FOUNTAIN	.89
Hallway (north, right)	FOUNTAIN	2.5
Room 200	SINK	8.5
Room 200	FOUNTAIN	6.0
Room 201	SINK	8.4
Room 201	FOUNTAIN	4.2
Room 201 (bath)	SINK	10.8
Room 201 (bath)	FOUNTAIN	3.3
Room 200 (bath)	SINK	7.8
Hallway (SW, right)	FOUNTAIN	2.1
Hallway (SW, left)	FOUNTAIN	2.4
Room 301	SINK	6.5
Room 301	FOUNTAIN	7.7
Room 302	SINK	3.6
Room 302	FOUNTAIN	1.9
Room 303	SINK	5.9
Room 303	FOUNTAIN	3.2
Room 304	SINK	5.1
Room 304	FOUNTAIN	3.0
Room 305	SINK	6.3
Room 305	FOUNTAIN	3.2
Room 306	SINK	5.2
Room 306	FOUNTAIN	2.7
Nurse's Office	SINK	.88
Office	SINK	.78

Staff Dining	SINK	2.9
Kitchen	SPRAYER	6.0
Hallway by Gym	BOTTLE FILLER	0
Gym A	FOUNTAIN	1.3
Gym B	FOUNTAIN	7.6
Gym C	FOUNTAIN	.70
Room 134	SINK	2.8
Room 134	FOUNTAIN	1.8
Room 133	SINK	2.9
Room 133	FOUNTAIN	4.8
Room 127	FOUNTAIN	6.4
Room 128	SINK	1.6
Room 128	FOUNTAIN	3.1
Room 129	SINK	2.2
Room 129	FOUNTAIN	1.1
Hallway (outside 129)	SINK	4.2
Hallway (south, left)	FOUNTAIN	1.7
Hallway (south, right)	FOUNTAIN	1.2
Room 138	SINK	2.9
Room 138	FOUNTAIN	4.7
Room 137	SINK	2.7
Room 137	FOUNTAIN	6.3
Room 136	SINK	3.4
Room 136	FOUNTAIN	2.4
Hallway (outside 136)	SINK	4.4

Room 135	SINK	2.3
Room 135	FOUNTAIN	1.5
Hallway (outside 135)	SINK	6.7

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources were replaced, and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion, and no further action was taken at this time.

LOCATION	SOURCE	INITIAL RESULTS (in ug/L)	RE-TEST RESULTS
Room 102 (bath)	SINK	22.1	15.8
Room 122	SINK	24.8	13.1
Room 127	SINK	30.1	1.2
Kitchen	SINK	28.3	7.9
Media Center WR	SINK	31.9	1.0