

# **Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update**

**for  
Tashua Elementary School**

**For Compliance with  
State of Connecticut Department of Public Health  
Asbestos-Containing Materials in Schools Regulation  
(Sections 19a - 333-1 through 19a - 333-13)  
and  
EPA Asbestos Hazard Emergency Response Act  
(Title 40 CFR, Part 763, Subpart E)**

**Trumbull Public Schools  
Trumbull, Connecticut**

June 2024



59 Elm Street -Suite 500  
New Haven, CT 06510

June 11, 2024

Mr. David P. Cote, PE.  
Director of Operations  
Trumbull Public Schools  
401 Stonehouse Road  
Trumbull, CT 06611

**RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update**  
**Re-Inspection Date: April 8, 2024**  
**Tashua Elementary School**  
**401 Stonehouse Road, Trumbull, CT.**  
Fuss & O'Neill Project No. 20201149.A30

Dear Mr. Cote:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Asbestos Management Plan (AMP) Update report prepared by Fuss & O'Neill, Inc. at the Tashua Elementary School located at 401 Stonehouse Road in Trumbull, Connecticut (the "Site"). The inspection was performed for the Trumbull Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the AMPs are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,



Eduardo Miguel Marques  
Senior Environmental Analyst

EMM/nw

Enclosure

## Table of Contents

### Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Tashua Elementary School

---

<b>1</b>	<b>Introduction.....</b>	<b>1</b>
1.1	Background.....	1
1.2	Local Education Agency (LEA) Responsibilities .....	1
1.3	Accreditation.....	2
<b>2</b>	<b>Building and Mechanical System Description.....</b>	<b>3</b>
<b>3</b>	<b>Three Year Re-Inspection .....</b>	<b>3</b>
3.1	Re-Inspection Procedures .....	3
<b>4</b>	<b>Re-Inspection Report .....</b>	<b>3</b>
4.1	Review of Existing Records .....	3
4.2	Re-Inspection Summary .....	3
4.3	Newly Identified or Re-sampled ACBM Materials .....	6
4.4	Physical Assessment of ACBM .....	7
<b>5</b>	<b>Management Plan Update .....</b>	<b>8</b>
5.1	Recommended Response Actions .....	8
5.2	Periodic Surveillance .....	9
5.3	Preventive Measures.....	9
5.4	Abatement (Removal) Cost Estimates .....	9
<b>6</b>	<b>EPA Accreditation Requirements .....</b>	<b>10</b>

## APPENDICES

APPENDIX A	EXISTING RECORDS CHECKLIST
APPENDIX B	RE-INSPECTION FORM 1A
APPENDIX C	RE-INSPECTION FORM 1B
APPENDIX D	RE-INSPECTION FORM 2
APPENDIX E	SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM
APPENDIX F	PREVENTIVE MEASURES
APPENDIX G	ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE LICENSES AND EPA ACCREDITATIONS

## **1 Introduction**

### **1.1 Background**

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988, that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public-school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

### **1.2 Local Education Agency (LEA) Responsibilities**

The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:

1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
2. The LEA must ensure that the asbestos management plans (AMPs) are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA AMPs for the school buildings.
4. The LEA must ensure proper accreditations for all persons who perform asbestos inspections, asbestos re-inspections, develop/update AMPs, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.

5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after AMP implementation, in all school buildings that it leases, owns, or otherwise uses that contain ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after an AMP is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

### **1.3 Accreditation**

- A. LEA: Trumbull Public Schools  
 Address: 401 Stonehouse Road  
 Trumbull, CT  
 Phone: (203) 452-4300
- B. Designated Person: Mr. David P. Cote, PE.  
 Address: 401 Stonehouse Road  
 Trumbull, CT  
 Phone: (203) 452-4300
- C. Asbestos Consultant:  
  
 Firm: Fuss & O'Neill, Inc.  
 Address: 59 Elm Street – Suite 500  
 New Haven, CT  
 Phone: (203) 374-3748  
 Fax: (860) 533-5143
- D. Asbestos Inspector:  
  
 Inspector: Sandra L. Guzman  
 CTDPH License #: 000335  
 Expiration Date: 08/31/2024

E. Asbestos Inspector/Management Planner:

Planner:	Eduardo Miguel Marques
CTDPH License #:	000201
Expiration:	02/28/2025

## 2 Building and Mechanical System Description

The original Tashua Elementary School is a one-story building and was reportedly constructed in 1965. The building contains approximately 52,000 square feet (SF) of total floor area. The building is heated by gas-fired hot water and rooftop heating, ventilation and air conditioning (HVAC) units.

## 3 Three Year Re-Inspection

### 3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On April 8, 2024, Fuss & O'Neill, Inc. (Fuss & O'Neill) representatives Ms. Sandra Guzman performed the re-inspection.

A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:

1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
3. Identification and assessment of any newly identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

## 4 Re-Inspection Report

### 4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where AMPs are stored.

Please see *Appendix A* for the checklist for existing records.

### 4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This

form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifying the last known conditions of ACBM in the building. It additionally provides the inspector a "quick glance" reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified (See *Appendix C*). It also lists the ACBM in areas newly acquired by the school for student use either permanently or temporarily.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding re-assessment of the ACBM (see *Appendix D*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in School Name at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.

**Table 1**  
**Asbestos-Containing Building Materials**

Material	Location	Reference	Asbestos Content
12"x12" Blue Floor Tile & associated Adhesive	Rooms 1, 3, 4, 5, 7, 8, 16, and 19 - 22	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Green Floor Tile & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room, and Music Rooms 1A (GA3)	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Gray with Multiple Colors Specks Floor Tile & associated Adhesive	Rooms 13, 14	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Gray with Tan Specks Floor Tile & associated Adhesive	Rooms 2, 4, 18, and Reading Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Green with Green Floor Tile & associated Adhesive	Room 1A	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Gray with Green Specks Floor Tile & associated Adhesive	Room 4, Psychologist Office, Social Worker Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12" x 12" Light Blue with Blue/White Specks and Black Specks Floor Tiles & associated Adhesive	Stage Mechanical Room, Library (Media Center), Computer Lab, Room 6; and Main Office, Elevator access and Staff Lounge	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
12"x12" Beige with Tan Floor Tile & associated Adhesive	Cafeteria, and Room 12,	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed

<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
9" x 9" Green/Gray Floor Tile & associated Mastic	Custodial Closet across from Room 20	Fuss & O'Neill October 2021	Assumed
Green Rubber Flooring & associated Adhesive	Stage Stairways	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Blue/Greenish Sheet Flooring & associated Adhesive	Room 11	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Tan Sheet Flooring & associated Adhesive	Nurse's Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Gray Sheet Flooring & associated Adhesive	Math Spec. Office, Staff Office, and Media Center Office	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Carpet Adhesive	Administration Offices, Rooms 1E, 1F and GA2	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Boys Bathrooms, Girls Bathrooms, Faculty Bathrooms	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
4" Blue/Dark Blue Cove Base Molding & associated Adhesive	Main Office, Elevator Access, Media Center, Computer Lab, Staff Lounge, Nurses, rooms 1, 1E, 1F, GA2, 3, 5, 6, 7, 8, 11, 16, and 19 – 22	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
4" Green Cove Base Molding & associated Adhesive	Rooms 9, 15, 17, TLC Room, Stage Side Access, Music Room 1A	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
4" Gray Cove Base Molding & associated Adhesive	Rooms 2, 4, 12, 13, 14, 18, Reading, Psychologist's Office, and Social Worker's Office	Gray 4" Cove Base Molding & associated Adhesive	Rooms 2, 12, 13, 14, 18, Reading, Psychologist's Office, and Social Worker's Office
4" Cream Cove Base Molding & associated Adhesive	Cafeteria, and 10	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Pipe Insulation & Pipe Fitting Insulation	Custodial Closets, General Supplies Room and Above Suspended Ceiling Tiles Throughout Building	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
2' x 2' Suspended Ceiling Tiles (Multiple types: slots with pinholes, pinholes)	Main Office, 1F, GA2, Music Room, TLC Room, Hallway to TLC, Boys Bathrooms, Girls Bathrooms, Faculty Bathrooms,	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed



Material	Location	Reference	Asbestos Content
	Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Music Room, Psychologist's Office, GA2, and 1F Offices, Reading Room, Computer Lab and Media Center		
2' x 4' Suspended Ceiling Tiles	Administration Offices, Classrooms 1 - 3, 5, 7 -9, 11 - 15, 17 - 21, Kitchen, Social Worker's Office, and Hallways	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Tectum Ceiling	Custodial Closets, Custodians Office, Storage Closets	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Adhesive associated with Chalkboard and Tackboard	Rooms 1 - 21	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
Gray Sink Undercoating	Rooms 1 – 22, Staff Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed
White Sink Undercoating	TLC Room	EnviroMed 2015 AHERA 3-Year Re-Inspection	Assumed

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Inspector/Management Planner

#### 4.3 Newly Identified or Re-sampled ACBM Materials

The following newly identified suspect ACBM have been recognized in the building:

- Beige, brown specks 12" x 12" floor tile & associated adhesive;
- Green sheet flooring & associated adhesive;
- Blue Sheet Flooring & associated adhesive;
- Mortar associated with 6" quarry tiles/grout/adhesive
- 4" black cove base molding and associated adhesive;
- 4" brown cove base molding and associated adhesive;
- 6" black cove base molding and associated adhesive;
- Concrete and glazed wall and associated mortar;
- Brick wall and associated mortar;
- Gypsum wall;
- 4" yellow, pink, beige, blue and white with gay specks ceramic wall tiles and associated adhesive;
- 1' x 1' Suspended Ceiling Tiles;
- Light Fixtures Wiring;

- Brown Interior Window Glazing Compound; and
- Red Terrazzo Flooring.

The above-listed materials may have been recently installed. If the materials have been recently installed, the Client may obtain a letter from an Architect for renovations conducted at the Site, a Safety Data Sheet (SDS) for the product or a letter from the material manufacturer stating asbestos was not used in the manufacturing of the product. Alternatively, the material may be sampled to determine potential asbestos content. If this information cannot be obtained, this material will be quantified and included in the AMP during the next triennial update.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the AMP as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

**Additional Information:**

- Asbestos-containing floor tile and associated mastics may exist below non-moveable objects such as cabinets, platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing compounds, roofing materials and materials behind exterior walls and panels should be collected and analyzed to determine asbestos content prior to performing activities that would disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

#### **4.4 Physical Assessment of ACBM**

During the inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

1. Damaged or significantly damaged TSI ACBM
2. Damaged friable surfacing ACBM
3. Significantly damaged friable surfacing ACBM

4. Damaged or significantly damaged friable miscellaneous ACBM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

## **5 Management Plan Update**

### **5.1 Recommended Response Actions**

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

1. Removal - Not Applicable
2. Repair - Not Applicable
3. Enclosure - Not Applicable
4. Encapsulation - Not Applicable
5. Operations and Maintenance (O & M) - All remaining ACBM and:
  - Repair one 12"x12" blue floor tile broken in Room 16.
  - Repair two linear feet of 4" blue/dark blue cove base peeling in Rooms 1, 8 and 21.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
  1. Restrict entry into the area either by physically isolating or by scheduling.
  2. Post asbestos warning signs to prevent entry by unauthorized persons.
  3. Deactivate or temporarily shut off or divert the air-handling system to the area.
  4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini enclosures/glove bags, etc. to inhibit fiber migration.
  5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.

- C. Minor Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
1. Saturate the debris using wet method.
  2. Place the debris in a sealed, leak-tight container and clean the area.
  3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
1. Restrict entry into the area and post asbestos warning signs.
  2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
  3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
  4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

## **5.2 Periodic Surveillance**

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix E* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

## **5.3 Preventive Measures**

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix F* for preventive measures designed for various types of ACBM that may exist in the school.

## **5.4 Abatement (Removal) Cost Estimates**

At the time of the April 10, 2024, re-inspection, no materials were observed to be damaged (other than O&M repairs); therefore, estimated abatement cost have not been provided.

## 6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector licenses for Sandra Guzman and Eduardo Miguel Marques are provided in *Appendix G*.

Report prepared by Environmental Analyst I, Sandra Guzman.

Reviewed by:



Eduardo Miguel Marques  
Senior Environmental Analyst



Kathleen C. Pane  
Associate | Department Manager

## **Appendix A**

---

### Existing Records Checklist

## Existing Records Checklist

Local Education Agency (LEA): Trumbull Public Schools  
6254 Main Street  
Trumbull, CT 06611

School Building: Tashua Elementary School,  
401 Stonehouse Road, Trumbull, CT 06611

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of a three-year Re-Inspection.

DOCUMENTATION		LOCATION	
		School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	No	No
2	Three Year Re-Inspection (First and All Subsequent Inspections)	No	Limited
3	Parents and Teachers Notifications (Annually Since Last Re-Inspection)	No	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	No	-
5	Designated Person Periodic Surveillance (Once Every Six Months)	No	Yes
6	Maintenance Staff Awareness Training Records	No	Yes
7	Outside Vendor Awareness Notification	No	Yes
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	No	NA
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	No	Yes

Comments: Items marked "No" indicate not present/available at the time of this inspection. LEA office found to contain only limited records of 3-year re-inspection, 6-month surveillance and response actions conducted from 2015 to present. "NA" indicates not applicable.

Inspector (LEA Office): Sandra Guzman

Date: April 8, 2024

Inspector (School): Sandra Guzman

Date: April 8, 2024

## **Appendix B**

---

### Re-Inspection Form 1A



## Re-Inspection Form 1 (A) – List of Identified ACBM

Page 1 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	12"x12" Blue Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 1, 3, 4, 5, 7, 8, 16, and 19 - 22	Repair one 12"x12" blue floor tile broken in Room 16. Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Green Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 9, 10, 15, 17, TLC Room, and Music Rooms 1A (GA3)	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Gray with Multiple Colors Specks Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 13, 14	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Gray with Tan Specks Floor Tile & associated Adhesive	Misc.	NF	5	Rooms 2, 4, 18, and Reading Room	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Green with Green Floor Tile & associated Adhesive	Misc.	NF	5	Room 1A	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Gray with Green Specks Floor Tile & associated Adhesive	Misc.	NF	5	Room 4, Psychologist Office, Social Worker Office	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

## Re-Inspection Form 1 (A) – List of Identified ACBM

Page 2 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	12" x 12" Light Blue with Blue/White Specks and Black Specks Floor Tiles and associated Adhesive	Misc.	NF	5	Stage Mechanical Room, Library (media center), Computer Lab, Room 6; and Main Office, Elevator access and Staff Lounge	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	12"x12" Beige with Tan Floor Tile & associated Adhesive	Misc.	NF	5	Cafeteria and Room 12	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	9" x 9" Green/Gray Floor Tile & associated Mastic	Misc.	NF	5	Custodial Closet across from Room 20	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Green Rubber Flooring & associated Adhesive	Misc.	NF	5	Stage Stairways	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Blue/Greenish Sheet Flooring & associated Adhesive	Misc.	NF	5	Room 11	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Tan Sheet Flooring & associated Adhesive	Misc.	NF	5	Nurse's Office	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

## Re-Inspection Form 1 (A) – List of Identified ACBM

Page 3 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	Gray Sheet Flooring & associated Adhesive	Misc.	NF	5	Math Spec. Office, Staff Office, and Media Center Office	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Carpet Adhesive	Misc.	NF	5	Administration Offices, Rooms 1E, 1F and GA2	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Misc.	NF	5	Boys' Bathrooms, Girls' Bathrooms, Faculty Bathrooms	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	4" Blue/Dark Blue Cove Base Molding & associated Adhesive	Misc.	NF	5	Main Office, Elevator Access, Media Center, Computer Lab, Staff Lounge, Nurses, rooms 1, 1E, 1F, GA2, 3, 5, 6, 7, 8, 11, 16 and 19 – 22.	2 LF of material is peeling in rooms 1, 8 and 21. Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	4" Green Cove Base Molding & associated Adhesive	Misc.	NF	5	Rooms 9, 15, 17, TLC Room, Stage Side Access, Music Room 1A.	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	4" Gray Cove Base Molding & associated Adhesive	Misc.	NF	5	Rooms 2, 4, 12, 13, 14, 18, Reading, Psychologist's Office, and Social Worker's Office	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

## Re-Inspection Form 1 (A) – List of Identified ACBM

Page 4 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	4" Cream Cove Base Molding & associated Adhesive	Misc.	NF	5	Cafeteria and Room 10	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Pipe Insulation & Pipe Fitting Insulation	TSI	F	5	Custodial Closets, General Supplies Room and Above Suspended Ceiling Tiles Throughout Building	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	2' x 2' Suspended Ceiling Tiles (Multiple types: slots with pinholes, pinholes)	Misc.	NF	5	Main Office, 1F, GA2, Music Room, TLC Room, Hallway to TLC, Boys Bathrooms, Girls Bathrooms, Faculty Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Music Room, Psychologist's Office, GA2, and 1F Offices, Reading Room, Computer Lab, and Media Center	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	2' x 4' Suspended Ceiling Tiles	Misc.	NF	5	Administration Offices, Classrooms 1 - 3, 5, 7 - 9, 11 - 15, 17 - 21, Kitchen, Social Worker's Office, and Hallways	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Tectum Ceiling	Misc.	NF	5	Custodial Closets, Custodians Office, Storage Closets	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

## Re-Inspection Form 1 (A) – List of Identified ACBM

Page 5 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	Adhesive associated with Chalkboard and Tackboard	Misc.	NF	5	Rooms 1 - 21	Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance
N/A	Assumed	Gray Sink Undercoating	Misc.	NF	5	Rooms 1 – 22, Staff Room	Not Regulated By AHERA; for Informational Purposes only. Material Must be Managed/Disposed of as ACBM. Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

Re-Inspection Form 1 (A) – List of Identified ACBM

Page 6 of 6

School: Tashua Elementary School  
Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Original Inspection: Unknown  
Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
N/A	Assumed	White Sink Undercoating	Misc.	NF	5	TLC Room	Not Regulated By AHERA; for Informational Purposes only. Material Must be Managed/Disposed of as ACBM. Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance

Information abstracted by: Sandra Guzman

Date: April 8, 2024

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories: 1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

## Appendix C

---

### Re-Inspection Form 1B

## Re-Inspection Form 1 (B) – List of Previously-Unidentified Suspect ACBM

Page 1 of 1

School: Tashua Elementary School

Date(s) of Original AHERA Inspection: Unknown

Address: 401 Stonehouse Road, Trumbull, CT

Date(s) of Re-Inspection: 2015, 2021, 2024

Homogeneous Material		Asbestos Content (%)	Material Category	Estimated Quantity (SF/LF)	Friability	Assessment Category (1-7)	Recorded Locations of Material for Each Assessment Category
Sample Number	Material Description						
NA	9" x 9" Green/Gray Floor Tile & associated Mastic	Assumed	Misc.	40 SF	NF	5	Custodial Closet across from Room 20

Inspected by: Sandra Guzman

Date: April 8, 2024

Material Category: TSI = Thermal System Insulation, S = Surfacing, M = Miscellaneous

LF = Linear Feet; SF = Square Feet

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories: 1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM



## Appendix D

---

### Re-Inspection Form 2

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 1 of 25

 School: Tashua Elementary School

 Date of Re-Inspection: April 8, 2024

 Homogeneous Material: 12"x12" Blue Floor Tile & associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1, 3, 4, 5, 7, 8, 16 and 19 - 22	NF	5,000 SF	5	ACBM with Potential for Damage	Repair one 12"x12" blue floor tile broken in Room 16. Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 2 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12"x12" Green Floor Tile & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 9, 10, 15, 17, TLC Room and Music Rooms 1A (GA3)	NF	2,200	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 3 of 25

 School: Tashua Elementary School

 Date of Re-Inspection: April 8, 2024

 Homogeneous Material: 12"x12" Gray with Multiple Colors Specks Floor Tile & associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 13, 14	NF	800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 4 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12"x12" Gray with Tan Specks Floor Tile & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 2, 4, 18 and Reading Room	NF	1,600 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 5 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12"x12" Green with Green Floor Tile & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 1A	NF	250 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 6 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12"x12" Gray with Green Specks Floor Tile & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 4, Psychologist Office, Social Worker Office	NF	1,200 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 7 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12" x 12" Light Blue with Blue/White Specks and Black Specks Floor Tiles and & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stage Mechanical Room, Library (media center), Computer Lab, Room 6; and Main Office, Elevator access and Staff Lounge	NF	1,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 8 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 12"x12" Beige with Tan Floor Tile & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria and Room 12	NF	2,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 9 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 9" x 9" Green/Gray Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Custodial Closet across from Room 20	NF	40 SF	5	ACBM with Potential for Damage	6 tiles are missing. Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 10 of 25

 School: Tashua Elementary School

 Date of Re-Inspection: April 8, 2024

 Homogeneous Material: Green Rubber Flooring & associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stage Stairways	NF	60 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 11 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Blue/Greenish Sheet Flooring & associated Adhesive Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room 11	NF	350 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 12 of 25

 School: Tashua Elementary School

 Date of Re-Inspection: April 8, 2024

 Homogeneous Material: Tan Sheet Flooring & associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Nurse's Office	NF	400 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 13 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Gray Sheet Flooring & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Math Spec. Office, Staff Office, and Media Center Office	NF	350 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 14 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Math Spec. Office, Staff Office, and Media Center Office

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Administration Offices, Rooms 1E, 1F and GA2	NF	1,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 15 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boys Bathrooms, Girls Bathrooms, Faculty Bathrooms	NF	800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 16 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 4" Blue/Dark Blue Cove Base Molding & associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Main Office, Elevator Access, Media Center, Computer Lab, Staff Lounge, Nurse's, Rooms 1, 1E, 1F, GA2, 3, 5, 6, 7, 8, 11, 16 and 19 – 22	ND	800 LF	5	ACBM with Potential for Damage	2 LF of material is peeling in rooms 1, 8 and 21 Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 17 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 4" Green Cove Base Molding & associated Adhesive Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 9, 15, 17, TLC Room, Stage Side Access, Music Room 1A	NF	800 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 18 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 4" Gray Cove Base Molding & associated Adhesive Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 2, 4, 12, 13, 14, 18, Reading, Psychologist's Office, and Social Worker's Office	NF	800 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 19 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 4" Cream Cove Base Molding & associated Adhesive Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria and 10	NF	200 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 20 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Pipe Insulation & Pipe Fitting Insulation

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Custodial Closets, General Supplies Room and Above Suspended Ceiling Tiles Throughout Building	F	Unquantified	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 21 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 2' x 2' Suspended Ceiling Tiles (Multiple types: slots with pinholes, pinholes)

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Main Office, 1F, GA2, Music Room, TLC Room, Hallway to TLC, Boy's Bathrooms, Girls Bathrooms, Faculty Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Music Room, Psychologist's Office, GA2, and 1F Offices, Reading Room, Computer Lab and Media Center	NF	3,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 22 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: 2' x 4' Suspended Ceiling Tiles

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Administration Offices, Classrooms 1 - 3, 5, 7 - 9, 11 - 15, 17 - 21, Kitchen, Social Worker's Office, and Hallways	NF	2,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? ( <u>No</u> )					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 23 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Tectum Ceiling

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Custodial Closets, Custodians Office, Storage Closets	NF	800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 24 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Adhesive associated with Chalkboard and Tackboard Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1 - 21	NF	100 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations



Page 25 of 25

School: Tashua Elementary School

Date of Re-Inspection: April 8, 2024

Homogeneous Material: Gray Sink Undercoating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 1 – 22, Staff Room	NF	23 EA	5	ACBM with Potential for Damage	Not Regulated By AHERA; for Informational Purposes only. Material Must be Managed/Disposed of as ACBM. Maintain under O & M Plan; Recommend sampling to determine asbestos content prior to disturbance.	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u>  Inspector Signature: <u></u>  Accreditation #/State: <u>000335</u>  Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u>  Management Planner Signature: <u></u>  Accreditation #/State: <u>000201</u>  Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						

## **Appendix E**

---

### Sample 6-Month Periodic Surveillance Form

### Sample 6- Month Periodic Surveillance Form

Local Education Agency (LEA): Trumbull Public Schools

Facility Address: Tashua Elementary School, 401 Stonehouse Road, Trumbull, CT

Date of Surveillance: \_\_\_\_\_

#### ACBM Damage Report

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
12"x12" Blue Floor Tile & associated Adhesive	Rooms 1, 3, 4, 5, 7, 8, 16, 19 - 22					
12"x12" Green Floor Tile & associated Adhesive	Rooms 9, 10, 15, 17, TLC Room, and Music Rooms 1A (GA3)					
12"x12" Gray with Multiple Colors Specks Floor Tile & associated Adhesive	Rooms 13, 14					
12"x12" Gray with Tan Specks Floor Tile & associated Adhesive	Rooms 2, 4, 18, and Reading Room					
12"x12" Green with Green Floor Tile & associated Adhesive	Room 1A					
12"x12" Gray with Green Specks Floor Tile & associated Adhesive	Room 4, Psychologist Office, Social Worker Office					
12" x 12" Light Blue with Blue/White Specks and Black Specks Floor Tiles and & associated Adhesive	Stage Mechanical Room, Library (media center), Computer Lab, Room 6; and Main Office, Elevator access and Staff Lounge					
12"x12" Beige with Tan Floor Tile & associated Adhesive	Cafeteria, and Room 12					
9" x 9" Green/Gray Floor Tile & associated Mastic	Custodial Closet across from Room 20					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Green Rubber Flooring & associated Adhesive	Stage Stairways					
Blue/Greenish Sheet Flooring & associated Adhesive	Room 11					
Tan Sheet Flooring & associated Adhesive	Nurse's Office					
Gray Sheet Flooring & associated Adhesive	Math Spec. Office, Staff Office, and Media Center Office					
Carpet Adhesive	Administration Offices, Rooms 1E, 1F and GA2					
Thinset & Grout associated with Ceramic Tile (multiple colors and sizes)	Boys' Bathrooms, Girls Bathrooms, Faculty Bathrooms					
4" Blue/Dark Blue Cove Base Molding & associated Adhesive	Main Office, Elevator Access, Media Center, Computer Lab, Staff Lounge, Nurses, rooms 1, 1E, 1F, GA2, 3, 5, 6, 7, 8, 11, 16, and 19 – 22					
4" Green Cove Base Molding & associated Adhesive	Rooms 9, 15, 17, TLC Room, Stage Side Access, Music Room 1A					
4" Gray Cove Base Molding & associated Adhesive	Rooms 2, 4, 12, 13, 14, 18, Reading, Psychologist's Office, and Social Worker's Office					
4" Cream Cove Base Molding & associated Adhesive	Cafeteria and Room 10					
Pipe Insulation & Pipe Fitting Insulation	Custodial Closets, General Supplies Room and Above Suspended Ceiling Tiles Throughout Building					
2' x 2' Suspended Ceiling Tiles (Multiple types: slots with pinholes, pinholes)	Main Office, 1F, GA2, Music Room, TLC Room, Hallway to TLC, Boys Bathrooms, Girls Bathrooms, Faculty					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	Bathrooms, Cafeteria, Hallways, Rooms 4, 6, 10, 16, 22, Music Room, Psychologist's Office, GA2, and 1F Offices, Reading Room, Computer Lab, and Media Center					
2' x 4' Suspended Ceiling Tiles	Administration Offices, Classrooms 1 - 3, 5, 7 -9, 11 - 15, 17 - 21, Kitchen, Social Worker's Office and Hallways					
Tectum Ceiling	Custodial Closets, Custodians Office, Storage Closets					
Adhesive associated with Chalkboard and Tackboard	Rooms 1 - 21					
Gray Sink Undercoating	Rooms 1 – 22, Staff Room					
White Sink Undercoating	TLC Room					

Conditions: D = Damaged; F = Fair; G = Good; IA = Inaccessible; N/A = Not Applicable; SD = Significant Damage; SF = Square Feet

Surveillance conducted by: \_\_\_\_\_  
 (print name) (signature)

I, the LEA's Designated Person, have read and understood the findings noted above: \_\_\_\_\_

Date: \_\_\_\_\_

## **Appendix F**

---

### Preventive Measures

## **Preventive Measures for Various Asbestos-Containing Building Materials**

### **A. Surfacing Materials**

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

#### **1. Sprayed-Applied Fireproofing**

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels, and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

#### **2. Ceiling and Wall Plasters**

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

### **B. Thermal System Insulation (TSI)**

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:



1. Boiler and Breeching Insulation

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in an intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

**C. Miscellaneous Materials**

“Miscellaneous Materials” are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.

- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

## **Appendix G**

---

Asbestos Inspector and Management Planner State Licenses and EPA Accreditations

1000418-00000422-00000001 of 0000001-C01-a1d00101-1284-00420

Dear SANDRA L GUZMAN,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health  
P.O. Box 340308  
M.S.#12MQA  
Hartford, CT 06134-0308

(860) 509-7603  
oplc.dph@ct.gov  
www.ct.gov/dph/license

Sincerely,



MANISHA JUTHANI, MD, COMMISSIONER  
DEPARTMENT OF PUBLIC HEALTH

**STATE OF CONNECTICUT**  
**DEPARTMENT OF PUBLIC HEALTH**

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED  
BY THIS DEPARTMENT AS A

**ASBESTOS CONSULTANT-INSP/MGMT PLANNER**

SANDRA L GUZMAN

CERTIFICATE NO.  
**000335**

CURRENT THROUGH  
**08/31/24**

VALIDATION NO.  
**03-055356**

  
SIGNATURE  
COMMISSIONER

**EMPLOYER'S COPY**

**STATE OF CONNECTICUT**  
**DEPARTMENT OF PUBLIC HEALTH**

NAME

**SANDRA L GUZMAN**

VALIDATION NO.  
**03-055356**

CERTIFICATE NO.  
**000335**

CURRENT THROUGH  
**08/31/24**

PROFESSION

**ASBESTOS CONSULTANT-INSP/MGMT PLANNER**

  
SIGNATURE  
COMMISSIONER

**INSTRUCTIONS:**

1. Detach and sign each of the cards on this form
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

**WALLET CARD**

**STATE OF CONNECTICUT**  
**DEPARTMENT OF PUBLIC HEALTH**

NAME

**SANDRA L GUZMAN**


VALIDATION NO.  
**03-055356**

CERTIFICATE NO.  
**000335**

CURRENT THROUGH  
**08/31/24**

PROFESSION

**ASBESTOS CONSULTANT-INSP/MGMT PLANNER**

  
SIGNATURE  
COMMISSIONER

1000218-0000222-0000001 of 0000001-C01-a1d00101-0564-00220

Dear EDUARDO M. MARQUES,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:



Department of Public Health  
P.O. Box 340308  
M.S.#12MQA  
Hartford, CT 06134-0308



(860) 509-7603  
oplcdph@ct.gov  
www.ct.gov/dph/license

Sincerely,





MANISHA JUTHANI, MD, COMMISSIONER  
DEPARTMENT OF PUBLIC HEALTH

STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH	
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT	
THE INDIVIDUAL NAMED BELOW IS CERTIFIED BY THIS DEPARTMENT AS A	
ASBESTOS CONSULTANT-INSP/MGMT PLANNER	
EDUARDO M. MARQUES	CERTIFICATE NO. 000201
	CURRENT THROUGH 02/28/25
	VALIDATION NO. 03-083603
 SIGNATURE	 COMMISSIONER

EMPLOYER'S COPY STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH		
NAME EDUARDO M. MARQUES		
VALIDATION NO. 03-083603	CERTIFICATE NO. 000201	CURRENT THROUGH 02/28/25
PROFESSION ASBESTOS CONSULTANT-INSP/MGMT PLANNER		
 SIGNATURE	 COMMISSIONER	

#### INSTRUCTIONS:

1. Detach and sign each of the cards on this form
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

WALLET CARD STATE OF CONNECTICUT DEPARTMENT OF PUBLIC HEALTH		
NAME EDUARDO M. MARQUES		
VALIDATION NO. 03-083603	CERTIFICATE NO. 000201	CURRENT THROUGH 02/28/25
PROFESSION ASBESTOS CONSULTANT-INSP/MGMT PLANNER		
 SIGNATURE	 COMMISSIONER	





## CERTIFICATE OF ACHIEVEMENT

*This certifies that*

**Eduardo Miguel Marques**

*has successfully completed the*  
**8 Hour Asbestos Site Inspector/Management Planner Refresher Training**  
**Asbestos Accreditation Under TSCA Title II**  
**40 CFR Part 763**

Course training provided  
via Live Webinar

Exam Score: 92%

*conducted by:*  
**ATLAS Technical Consultants, LLC**  
73 William Franks Drive  
West Springfield, MA 01089  
(413) 781-0070



A handwritten signature in dark ink, appearing to read "Thomas Dion".

Principal Instructor: Thomas Dion

May 23, 2024  
Date of Course

May 23, 2025  
Expiration Date

A handwritten signature in dark ink, appearing to read "Gregory J. Morsch".

Regional Training Director: Gregory Morsch

MPAR-3619  
Certificate Number

May 23, 2024  
Examination Date