



ENVIRONMENTAL ASSISTANCE GROUP

179 NIBLICK ROAD #401 PASO ROBLES CA 93446

PHONE/FAX 805-286-4921 E-MAIL comply@haztrainer.com

March 4, 2021

Mr. Bob Lombard,
Newport Mesa Unified School District
2990 Mesa Verde Drive,
Costa Mesa 92626

SUMMARY REPORT OF SAMPLING FLOOR MATERIALS FOR ASBESTOS

INTRODUCTION

On February 17, 2021 Environmental Assistance Group represented by Ed Kennedy, Certified Asbestos Consultant (CAC) collected samples of non-friable miscellaneous flooring materials from Newport Heights Elementary School 300 E. 15th Street Newport Beach, California 92660 in the Newport Mesa Unified School District. The sampling was requested for Rooms 1,2,3,4,5,6,8,9,10,11,12,13,14,15,16,17,18,19,20,21, Library, 24 and 25 because flooring replacement was expected to be scheduled for approximately 20,700 square feet of flooring.

METHOD

The sampling method included collecting representative samples of vinyl asbestos floor tile and mastic (mostly under carpet) as well as vinyl base and mastic. Most rooms had areas of 12" x 12" floor tile not under carpet, but since a majority of the tile under carpet was also present, it was considered in the homogeneous area. All samples were placed in leak tight containers and transported to a NVLAP and DHS certified laboratory, SGS Forensic Laboratories in California, for analysis by Polarized Light Microscopy (PLM). After analysis, the results were provided for inclusion in this report.

RESULTS

The analyses showed that the homogenous areas of 9"x9" vinyl asbestos floor tile (VAT) were trace to 3% Chrysotile asbestos, and the black mastic was 2% to 3% Chrysotile asbestos in all rooms inspected. Vinyl Base (VB) and mastic were None Detected (ND) for asbestos.

RECOMMENDATION

Disturbance of the flooring materials with asbestos content greater than one tenth of a percent including removal of the floor tile, black mastic on the concrete floors, must be accomplished by certified asbestos workers in accordance with a CAC prepared Project Design.

Eldwin "Ed" Kennedy, CAC 93-1249, CLP 4092

Attachments: Homogeneous Area/Sampling Reports, Forensic Analytical Bulk Asbestos Analysis Report and Chain of Custody

HOMOGENOUS AREA/SAMPLING FORM ASBESTOS

Page 1 of 4

Environmental Assistance Group
179 Niblick Rd. #401
Paso Robles, CA 93446
Office: 805-286-4921

CLIENT: NMUSD

DATE: 2-17-21

SITE: Newport Heights Elementary

PROJECT # NMNH221

SAMPLED: 2-17-21

CERT/CAC #: 93-1249

INSPECTOR: Eldwin "Ed" Kennedy

Signature: 

HA	SAMPLE #	HOMOGENOUS MATERIAL	CONDI-TION	LOCATION/SURFACE	BLDG/SUITE	RM/#	SAMPLE LOCATION	AMT
1	NMNH221-1	Brown 9x9 VFT	Good	Floor	A	1	12' off S. wall, 2' off E. wall	667 SF Tile 5%
2	NMNH221-2	Blue VB	Good	Wall	A	1	3' off W. wall at S. door threshold	221 LF ND
3	NMNH221-3	White 12x12 VFT	Good	Floor	A	1	2' off W. wall at S. door threshold	280 SF ND
1	NMNH221-4	Cream 9x9 VFT	Good	Floor	A	2	2.5' off W. wall, 2' off N. wall under carpet	667 SF Tile 5% ND
2	NMNH221-5	Blue VB	Good	Wall	A	2	4' off W. wall at N. door threshold	221 LF ND
3	NMNH221-6	Blue 12x12 VFT	Good	Floor	A	2	4' off W. wall at N. door threshold	280 SF Mastic Trace
1	NMNH221-7	Brown 9x9 FVT	Good	Floor	A	3	8.5' off N. wall, 12' off E. wall under carpet	667 SF Tile 5% ND
3	NMNH221-8	Blue VB	Good	Wall	A	3	3.5' off S. wall, 3.5' off W. wall	221 LF ND
2	NMNH221-9	White 12x12 VFT	Good	Floor	A	3	3.5' off S. wall, 3.5' off W. wall	280 SF ND
1	NMNH221-10	Black mastic	Good	Under carpet (no 9x9 VFT)	A	4	3.5' off N. wall, 18.5' off W. wall	667 SF Trace
2	NMNH221-11	Blue VB	Good	Wall	A	4	2.5' off W. wall, 15' off N. wall, near cabinets	221 LF ND
3	NMNH221-12	Blue 12x12 VFT	Good	Floor	A	4	2.5' off W. wall, 5' off N. wall	280 SF ND
1	NMNH221-13	Brown 9x9 VFT	Good	Floor	E	5	14.5' off N. wall 3" off E. wall	667 SF Tile 5%
2	NMNH221-14	Blue VB	Good	Wall	E	5	3' off W. wall, 3' off S. wall near S. door	221 LF ND
3	NMNH221-15	White 12x12 VFT	Good	Floor	E	5	3' off W. wall, 3' off S. wall	280 SF ND
3	NMNH221-16	Brown 9x9 VFT	Good	Floor	E	6	4' off N. wall, 12' off E. wall	667 SF Tile 5%
1	NMNH221-17	Blue VB	Good	Wall	E	6	10.5' off S. wall, 3' off W. wall	221 LF ND
2	NMNH221-18	Blue 12x12 VFT	Good	Floor	E	6	10.5' off S. wall, 3' off W. wall	280 SF ND
4	NMNH221-19	Brown 9x9 VFT	Good	Floor	B	8	8.5' off S. wall, 6" off E. wall under car[et	667 SF Tile 5%

HOMOGENOUS AREA/SAMPLING FORM ASBESTOS

Page 2 of 4

Environmental Assistance Group
179 Niblick Rd. #401
Paso Robles, CA 93446
Office: 805-286-4921

CLIENT: NMUSD

DATE: 2-17-21

SITE: Newport Heights Elementary

PROJECT # NMNH221

SAMPLED: 2-17-21

CERT/CAC #: 93-1249

INSPECTOR: Eldwin "Ed" Kennedy

Signature: 

HA	SAMPLE #	HOMOGENOUS MATERIAL	CONDI-TION	LOCATION/SURFACE	BLDG/SUITE	RM/#	SAMPLE LOCATION	AMT
5	NMNH221-20	Blue VB	Good	Wall	B	8	4' off W. wall at N. door threshold	221 LF ND
6	NMNH221-21	White 12x12 VFT	Good	Floor	B	8	4' off W. wall, at N. door threshold	280 SF ND
4	NMNH221-22	Brown 9x9 VFT	Good	Floor	B	9	10.5' off E. wall, 1' off S. wall under carpet	667 SF Tile 5%
5	NMNH221-23	Blue VB	Good	Wall	B	9	7.5' off W. wall at N. door threshold	221 LF ND
6	NMNH221-24	Blue 12x12 VFT	Good	Floor	B	9	7.5' off W. wall at N. threshold	280 SF
4	NMNH221-25	Brown 9x9 VFT	Good	Floor	B	10	7.5' off N. wall, 1.5' off E. wall under carpet	667 SF Tile 5%
5	NMNH221-26	Blue VB	Good	Wall	B	10	8' off W. wall at S. door	221 LF ND
6	NMNH221-27	White 12x12 VFT	Good	Floor	B	10	8' off W. wall at S. door threshold	280 SF ND
7	NMNH221-28	Brown 9x9 VFT	Good	Floor	D	11	2.5' off E. wall, 1' off S. wall under carpet	667 SF Tile 5%
8	NMNH221-29	Blue VB	Good	Wall	D	11	4' off S. wall, 3' off W. wall at floor	221 LF ND
9	NMNH221-30	Blue 12x12 VFT	Good	Floor	D	11	4' off S. wall, 3' off W. wall	280 SF ND
7	NMNH221-31	Brown 9x9 VFT	Good	Floor	D	12	12' off E. wall, 8' off N. wall under carpet	667 SF Tile 5%
8	NMNH221-32	Blue VB	Good	Wall	D	12	7.5' off W. wall at N. door threshold	221 LF ND
9	NMNH221-33	White 12x12 VFT	Good	Floor	D	12	7.5' off W. wall at N. door threshold	280 SF ND
7	NMNH221-34	Brown 9x9 VFT	Good	Floor	C	13	9.5' off W. wall, 1' off N. wall under carpet	667 SF Tile 5%
8	NMNH221-35	Blue VB	Good	Wall	C	13	3.5' off W. wall at N. door threshold	221 LF ND
9	NMNH221-36	White 12x12 VFT	Good	Floor	C	13	3.5' off W. wall at N. door	280 SF ND
7	NMNH221-37		Good	Floor	C	15	8.5' off N. wall' 1' off E. wall under carpet	667 SF Tile 5%

HOMOGENOUS AREA/SAMPLING FORM ASBESTOS

Page 3 of 4

Environmental Assistance Group
179 Niblick Rd. #401
Paso Robles, CA 93446
Office: 805-286-4921

CLIENT: NMUSD

DATE: 2-17-21

SITE: Newport Heights Elementary

PROJECT # NMNH221

SAMPLED: 2-17-21

CERT/CAC #: 93-1249

INSPECTOR: Eldwin "Ed" Kennedy Signature: *Eldwin E Kennedy*

HA	SAMPLE #	HOMOGENOUS MATERIAL	CONDI-TION	LOCATION/SURFACE	BLDG/SUITE	RM/#	SAMPLE LOCATION	AMT
8	NMNH221-38	Blue 4" VB	Good	Wall	C	15	4' off S. wall, 3' off W. wall at S. door	221 LF ND
9	NMNH221-39	Blue 12x12 VFT	Good	Floor	C	15	4' off S. wall, 3' off W. wall at S. door	280 SF ND
7	NMNH221-40	Cream 9x9 VFT	Good	Floor	C	14	11.5' off S. wall, 1' off E. wall under carpet	667 SF Tile 5%
8	NMNH221-41	Blue 4" VB	Good	Wall	C	14	3.5' off W. wall at S. door threshold	221 LF ND
9	NMNH221-42	Blue 12x12 VFT	Good	Floor	C	14	3.5' off W. wall off S. door threshold	280 SF ND
7	NMNH221-43	Brown 9x9 VFT	Good	Floor	C	16	1' off N. wall, 11' off W. wall under carpet	667 SF Tile 5%
8	NMNH221-44	Blue 4" VB	Good	Wall	C	16	4' off w. wall at N. door threshold	221 LF ND
9	NMNH221-45	White 12x12 VFT	Good	Floor	C	16	4' off W. wall at N. door threshold	280 SF ND
10	NMNH221-46	Cream 9x9 VFT	Good	Floor	I	21	12' off E. wall, 3.5' off N. wall under carpet	667 SF Tile 5% Mastic 3%
11	NMNH221-47	Blue 4" VB	Good	Wall	I	21	4' off W. wall at S. door	221 LF ND
12	NMNH221-48	Blue 12x12 VFT	Good	Floor	I	21	5.5' off W. wall at S. door threshold	280 SF ND
10	NMNH221-49	Cream 9x9 VFT	Good	Floor	I	Workroom/ Counselor	1' off N. wall, 1' off E. wall under	667 SF Tile 5%
10	NMNH221-50	Brown 9x9 VFT	Good	Floor	H	17	1.5' off E wall, 14' off N. wall under carpet	667 SF Tile 5%
11	NMNH221-51	Blue 4" VB	Good	Wall	H	17	12' off S. wall, 2.5' off W. wall	221 LF ND
12	NMNH221-52	Blue 12x12 VFT	Good	Floor	H	17	12' off S. wall, 2.5' off W. wall	280 SF ND
10	NMNH221-53	Brown 9x9 VFT	Good	Floor	H	18	20.5' off N. wall, 1.5' off E. wall under carpet	667 SF Tile 5%
11	NMNH221-54	Blue 4" VB	Good	Wall	H	18	7' off w. wall at S. door threshold	221 LF ND
12	NMNH221-55	White 12x12 VFT	Good	Floor	H	18	7' off w. wall at S. door threshold	280 SF ND

HOMOGENOUS AREA/SAMPLING FORM ASBESTOS

Page 4 of 4

Environmental Assistance Group
179 Niblick Rd. #401
Paso Robles, CA 93446
Office: 805-286-4921

CLIENT: NMUSD

DATE: 2-17-21

SITE: Newport Heights Elementary

PROJECT # NMNH221

SAMPLED: 2-17-21

CERT/CAC #: 93-1249

INSPECTOR: Eldwin "Ed" Kennedy

Signature: 

HA	SAMPLE #	HOMOGENOUS MATERIAL	CONDI-TION	LOCATION/SURFACE	BLDG/SUITE	RM/#	SAMPLE LOCATION	AMT
10	NMNH221-56	Brown 9x9 VFT	Good	Floor	H	19	4' off E. wall, 1' off S. wall under carpet	667 SF Tile 5%
11	NMNH221-57	Blue 4" VB	Good	Wall	H	19	7' off W. wall at N. door threshold	221 LF ND
12	NMNH221-58	Blue 12x12 VFT	Good	Floor	H	19	6' off W. wall at N. door	280 SF ND
10	NMNH221-59	Brown 9x9 VFT	Good	Floor	H	20	3.5' off N. wall, 18' off S. wall under carpet	667 SF Tile 5%
11	NMNH221-60	Blue 4" VB	Good	Wall	H	20	6.5' off w. wall at S. door threshold	221 LF ND
12	NMNH221-61	Blue 12x12 VFT	Good	Floor	H	20	7' off W. wall at S. door	280 SF ND
13	NMNH221-62	Cream 9x9 VFT	Good	Floor	J	Library	1' off N. wall, 3' off E. wall under carpet	1276 SF Tile 5%
14	NMNH221-63	Blue 4" VB	Good	Wall	J	Library	25.5' off E. wall, 6" off N. wall at threshold	221 LF ND
15	NMNH221-64	White 12x12 VFT	Good	Floor	J	Library	26.5' off E wall at N. door threshold	580 SF ND
13	NMNH221-65	Brown 9x9 VFT	Good	Floor	J	24	1.5' off E. wall, 6' off N. wall under carpet	667 SF Tile 5%
14	NMNH221-66	Blue 4" VB	Good	Wall	J	24	4' off W. wall at S. door threshold	221 LF ND
15	NMNH221-67	Blue 12x12 VFT	Good	Floor	J	24	5' off W. wall at S. door	280 SF ND
13	NMNH221-68	Cream 9x9 VFT	Good	Floor	J	25	4' off E. wall, 1' off S. wall under carpet	667 SF Tile 5%
14	NMNH221-69	Blue 4" VB	Good	Wall	J	25	4' off W. wall at N. door threshold	221 LF ND
15	NMNH221-70	White 12x12 VFT	Good	Floor	J	25	4' off W. wall at N. door threshold	280 SF ND



Bulk Asbestos Analysis

(EPA Method 40CFR, Part 763, Appendix E to Subpart E and EPA 600/R-93-116, Visual Area Estimation)
NVLAP Lab Code: 101459-1

Environmental Assistance Group
Ed Kennedy
179 Niblick Road #401

Paso Robles, CA 93446

Client ID: L1206
Report Number: B313955
Date Received: 02/18/21
Date Analyzed: 02/24/21
Date Printed: 02/25/21
First Reported: 02/25/21

Job ID/Site: NMNH221; Newport Heights ES, Classrooms

SGSFL Job ID: L1206
Total Samples Submitted: 72
Total Samples Analyzed: 53

Date(s) Collected: 01/17/2021, 02/17/2021

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 1	51416192						
Layer: Green Mastic with Carpet Debris			ND				
Layer: Brown Tile		Chrysotile	5 %				
Layer: Black Mastic with Debris			ND				
Total Composite Values of Fibrous Components:		Asbestos (5%)					
Cellulose (Trace)		Synthetic (Trace)					
NMNH221 2	51416193						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 3	51416194						
Layer: Light Grey Tile			ND				
Layer: Black/Tan Mastics			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 4	51416195						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 5	51416196						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 6	51416197						
Layer: Blue Tile			ND				
Layer: Black Mastics		Chrysotile	Trace				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (Trace)							
NMNH221 7	51416198						
Comment: Sample not analyzed due to prior positive result in series.							

Report Number: B313955

Client Name: Environmental Assistance Group

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 8	51416199						
Layer: Grey Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 9	51416200						
Layer: Beige Tile			ND				
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 10	51416201						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 11	51416202						
Layer: Blue Tile			ND				
Layer: Black Mastics		Chrysotile	Trace				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (Trace)							
NMNH221 12	51416203						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 13	51416204						
Layer: Green Mastic with Carpet Debris			ND				
Layer: Paint			ND				
Layer: Brown Tile		Chrysotile	5 %				
Layer: Black Mastic with Debris			ND				
Total Composite Values of Fibrous Components:		Asbestos (5%)					
Cellulose (Trace) Synthetic (Trace)							
NMNH221 14	51416205						
Layer: Grey Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 15	51416206						
Layer: Light Grey Tile			ND				
Layer: Black/Tan Mastics			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 16	51416207						
Comment: Sample not analyzed due to prior positive result in series.							

Report Number: B313955

Client Name: Environmental Assistance Group

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 17	51416208						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 18	51416209						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 19	51416210						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 20	51416211						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skincoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 21	51416212						
Layer: Off-White Tile			ND				
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 22	51416213						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 23	51416214						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skincoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 24	51416215						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 25	51416216						
Comment: Sample not analyzed due to prior positive result in series.							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 26	51416217						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 27	51416218						
Layer: Beige Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 28	51416219						
Layer: Green Mastic with Carpet Debris			ND				
Layer: Brown Tile		Chrysotile	5 %				
Layer: Black Mastic with Debris			ND				
Total Composite Values of Fibrous Components:		Asbestos (5%)					
Cellulose (Trace) Synthetic (Trace)							
NMNH221 29	51416220						
Layer: Grey Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 30	51416221						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 31	51416222						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 32	51416223						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 33	51416224						
Layer: Off-White Tile with Debris			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 34	51416225						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 35	51416226						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Layer: Paint			ND				
Layer: White Plaster			ND				
Layer: Beige Plaster			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 36	51416227						
Layer: Off-White Tile with Debris			ND				
Layer: Black Mastic			ND				
Layer: Beige Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 37	51416228						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 38	51416229						
Layer: Grey Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: White Skimcoat/Joint Compound			ND				
Layer: Drywall Backing			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (7 %)							
NMNH221 39	51416230						
Layer: Blue Tile with Debris			ND				
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 40	51416231						
Comment: Sample not analyzed due to prior positive result in series.							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 41	51416232						
Layer: Grey Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: White Drywall			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (7 %)							
NMNH221 42	51416233						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 43	51416234						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 44	51416235						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skincoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 45	51416236						
Layer: Beige Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Layer: White Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 46	51416237						
Layer: Green Mastic with Carpet Debris			ND				
Layer: Beige Tile		Chrysotile	5 %				
Layer: Black Mastic with Debris		Chrysotile	3 %				
Total Composite Values of Fibrous Components:		Asbestos (5%)					
Cellulose (Trace) Synthetic (Trace)							
NMNH221 47	51416238						
Layer: Blue Non-Fibrous Material			ND				
Layer: Off-White Mastic			ND				
Layer: Paint			ND				
Layer: White Skincoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Report Number: B313955

Client Name: Environmental Assistance Group

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 48	51416239						
Layer: Blue Tile			ND				
Layer: Black Mastics		Chrysotile	Trace				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (Trace)							
NMNH221 49	51416240						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 50	51416241						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 51	51416242						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 52	51416243						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 53	51416244						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 54	51416245						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 55	51416246						
Layer: Light Beige Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 56	51416247						
Comment: Sample not analyzed due to prior positive result in series.							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 57	51416248						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Brown Mastic		Anthophyllite	Trace				
Layer: Paint			ND				
Layer: Pink Plaster			ND				
Total Composite Values of Fibrous Components:		Asbestos (Trace)					
Cellulose (Trace)							
NMNH221 58	51416249						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 59	51416250	Comment: Sample not analyzed due to prior positive result in series.					
NMNH221 60	51416251						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 61	51416252						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 62	51416253						
Layer: Green Mastic with Carpet Debris			ND				
Layer: Beige Tile		Chrysotile	5 %				
Layer: Black Mastic with Debris		Chrysotile	3 %				
Total Composite Values of Fibrous Components:		Asbestos (5%)					
Cellulose (Trace) Synthetic (Trace)							
NMNH221 63	51416254						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 64	51416255						
Layer: Light Beige Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 65	51416256						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 66	51416257						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 67	51416258						
Layer: Blue Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 68	51416259						
Comment: Sample not analyzed due to prior positive result in series.							
NMNH221 69	51416260						
Layer: Blue Non-Fibrous Material			ND				
Layer: Beige Mastic			ND				
Layer: Paint			ND				
Layer: White Skimcoat/Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 70	51416261						
Layer: Light Beige Tile			ND				
Layer: Black Mastic			ND				
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
NMNH221 71	51416262						
Layer: Black Tar and Felt			ND				
Layer: White Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace) Synthetic (25 %)							

Client Name: Environmental Assistance Group

Report Number: B313955

Date Printed: 02/25/21

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
NMNH221 72	51416263						
Layer: 2 Grey Roof Shingles			ND				
Layer: Multi-Layer Black Tars			ND				
Layer: Multi-Layer Black Felts			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)	Fibrous Glass (40 %)						



Tiffani Ludd, Laboratory Supervisor, Carson Laboratory

Note: Limit of Quantification (LOQ) = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by SGS Forensic Laboratories (SGSFL) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by SGSFL to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by SGSFL. The client is solely responsible for the use and interpretation of test results and reports requested from SGSFL. SGSFL is not able to assess the degree of hazard resulting from materials analyzed. SGS Forensic Laboratories reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206	PO / Job#: NMNH221 Date: 2-17-21
Contact: Ed Kennedy		Phone: (661) 304-8981	Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / 5Day
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B / ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435	
Site Name: Newport Heights ES		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)	
Site Location: Classrooms		☐ IAQ Particle Identification (PLM LAB) / ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) / ☐ Special Project	
Comments: 1 of 8 Positive Stop each HA		☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only	

Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH221 1	1-17-21	HA 1	A P C				
2		2	A P C				
3		3	A P C				
4		1	A P C				
5		2	A P C				
6		3	A P C				
7		1	A P C				
8		2	A P C				
9		3	A P C				
10		1	A P C				

Sampled By: Ed Kennedy		Date/Time: 2-17-21		Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☐ Courier ☒ Drop Off ☐ Other:	
Relinquished By: Ed Kennedy		Relinquished By:		Relinquished By:	
Date / Time: 2-18-21 1500		Date / Time:		Date / Time:	
Received By: Chr. M...		Received By:		Received By:	
Date / Time: 2-18-21 3:15pm D/O		Date / Time:		Date / Time:	
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☒ No		Condition Acceptable? ☐ Yes ☐ No	

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206	PO / Job#: NMNH221	Date: 2-17-21
Contact: Ed Kennedy		Phone: (661) 304-8981	Turn Around Time: ☐ Same Day / ☐ 1Day / ☐ 2Day / ☐ 3Day / ☐ 4Day / ☒ 6Day	
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435		
Site Name: Newport Heights		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)		
Site Location: Classrooms		☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project		
Comments: 2 of 8 Positive Stop Each HA		☐ Metals Analysis Matrix: Method: ☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only		

Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH221	2-17-21	HA 2	☐ A ☐ P ☐ C				
12		3	☐ A ☐ P ☐ C				
13		4	☐ A ☐ P ☐ C				
14		5	☐ A ☐ P ☐ C				
15		6	☐ A ☐ P ☐ C				
16		4	☐ A ☐ P ☐ C				
17		5	☐ A ☐ P ☐ C				
18		6	☐ A ☐ P ☐ C				
19		4	☐ A ☐ P ☐ C				
20		5	☐ A ☐ P ☐ C				

Sampled By: Ed Kennedy	Date/Time: 2-17-21	Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☐ Courier ☒ Drop Off ☐ Other:
Relinquished By: Ed Kennedy	Relinquished By:	Relinquished By:
Date / Time: 2-17-21	Date / Time:	Date / Time:
Received By: CCU Mhu	Received By:	Received By:
Date / Time: 2-18-21 3:55pm D/O	Date / Time:	Date / Time:
Condition Acceptable? ☒ Yes ☐ No	Condition Acceptable? ☐ Yes ☐ No	Condition Acceptable? ☐ Yes ☐ No

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206		PO / Job#: NMNH221		Date: 2-17-21	
Contact: Ed Kennedy		Phone: (661) 304-8981		Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / 5Day			
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435					
Site Name: Newport Heights ES		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)					
Site Location: Classrooms		☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project					
Comments: 3 of 8 Positive stoeprech HA		☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only					
Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH221	2-17-21	HA 6	A P C				
22		4	A P C				
23		5	A P C				
24		6	A P C				
25		4	A P C				
26		5	A P C				
27		6	A P C				
28		7	A P C				
29		8	A P C				
30		9	A P C				
Sampled By: Ed Kennedy		Date/Time: 2-17-21		Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☒ Courier ☐ Drop Off ☐ Other:			
Relinquished By: Ed Kennedy		Relinquished By:		Relinquished By:			
Date / Time: 2-18-21		Date / Time:		Date / Time:			
Received By: CCN ML		Received By:		Received By:			
Date / Time: 2-18-21 3:15pm DYO		Date / Time:		Date / Time:			
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No			

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206		PO / Job#: NMNH 221		Date: 2-17-21	
Contact: Ed Kennedy		Phone: (661) 304-8981		Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / 5Day			
E-mail: comply@haztrainer.com				☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435			
Site Name: Newport Heights ES				☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)			
Site Location: Classrooms				☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project			
Comments: 4 of 8 Positive stop each HA				☐ Metals Analysis Matrix: Method: Analytes:		☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only	
Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH 221 31	2-17-21	HA #7	A P C				
32		8	A P C				
33		9	A P C				
34		7	A P C				
35		8	A P C				
36		9	A P C				
37		7	A P C				
38		8	A P C				
39		9	A P C				
40		7	A P C				
Sampled By: Ed Kennedy		Date/Time: 2-17-21		Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☐ Courier ☒ Drop Off ☐ Other:			
Relinquished By: Ed Kennedy		Relinquished By:		Relinquished By:			
Date / Time: 2-18-21		Date / Time:		Date / Time:			
Received By: CEC		Received By:		Received By:			
Date / Time: 2-18-21 3:50pm D/O		Date / Time:		Date / Time:			
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No			

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206	PO / Job#: NMNH 221	Date: 2-17-21			
Contact: Ed Kennedy		Phone: (661) 304-8981	Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / <u>5Day</u>				
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435					
Site Name: Newport Heights ES		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)					
Site Location: Classrooms		☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project					
Comments: 5 of 8 Positive Stop each HA		☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only					
Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH 221	12-17-21	HA 8	A P C				
42		9	A P C				
43		7	A P C				
44		8	A P C				
45		9	A P C				
46		10	A P C				
47		11	A P C				
48		12	A P C				
49		10	A P C				
50		10	A P C				
Sampled By: Ed Kennedy		Date/Time: 2-17-21	Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☒ Courier ☐ Drop Off ☐ Other:				
Relinquished By: Ed Kennedy		Relinquished By:	Relinquished By:				
Date / Time: 2-18-21		Date / Time:	Date / Time:				
Received By: CC, WH		Received By:	Received By:				
Date / Time: 2-10-21 3:15pm		Date / Time:	Date / Time:				
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No	Condition Acceptable? ☐ Yes ☐ No				

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206		PO / Job#: NMNH221		Date: 2-12-21	
Contact: Ed Kennedy		Phone: (661) 304-8981		Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / 6Day			
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count 400 / 1000 / ☐ CARB 435					
Site Name: Newport Heights ES		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)					
Site Location: CLASSROOMS		☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project					
Comments: 6 of 8 Positive Stop Each HA		☐ Metals Analysis Matrix: Method: ☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only					

Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NMNH221	5/12-12-21	HA 11	A P C				
52		12	A P C				
53		10	A P C				
54		11	A P C				
55		12	A P C				
56		10	A P C				
57		11	A P C				
58		12	A P C				
59		10	A P C				
60		11	A P C				

Sampled By: Ed Kennedy		Date/Time: 2-17-21		Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☐ Courier ☒ Drop Off ☐ Other:	
Relinquished By: Ed Kennedy		Relinquished By:		Relinquished By:	
Date / Time: 2-18-21		Date / Time:		Date / Time:	
Received By: CCL		Received By:		Received By:	
Date / Time: 2-18-21 3:15pm DVO		Date / Time:		Date / Time:	
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No	

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



FORENSIC
LABORATORIES

Analysis Request Form (COC)

Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446		Client No.: L-1206	PO / Job#: NH NH221	Date: 2-17-21			
Contact: Ed Kennedy		Phone: (661) 304-8981	Turn Around Time: ☐ Same Day / ☐ 1Day / ☐ 2Day / ☐ 3Day / ☐ 4Day / ☒ 5Day				
E-mail: comply@haztrainer.com		☐ PCM: ☐ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer ☒ PLM: ☒ Standard / ☐ Point Count ☐ 400 / ☐ 1000 / ☐ CARB 435					
Site Name: Newport Heights		☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)					
Site Location: Classrooms		☐ IAQ Particle Identification (PLM LAB) ☐ PLM Opaques/Soot ☐ Particle Identification (TEM LAB) ☐ Special Project					
Comments: 7 of 8 Positive Stop each HA		☐ Metals Analysis Matrix: Method: ☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only					
Sample ID	Date / Time	Sample Location / Description	FOR AIR SAMPLES ONLY				Sample Area / Air Volume
			Type	Time On/Off	Avg LPM	Total Time	
NH NH221 61	2-17-21	HA 12	☒ A ☐ P ☐ C				
62		13	☒ A ☐ P ☐ C				
63		14	☒ A ☐ P ☐ C				
64		15	☒ A ☐ P ☐ C				
65		13	☒ A ☐ P ☐ C				
66		14	☒ A ☐ P ☐ C				
67		15	☒ A ☐ P ☐ C				
68		13	☒ A ☐ P ☐ C				
69		14	☒ A ☐ P ☐ C				
70		15	☒ A ☐ P ☐ C				
Sampled By: Ed Kennedy		Date/Time: 2-17-21	Shipped Via: ☐ Fed Ex ☐ UPS ☐ US Mail ☐ Courier ☒ Drop off ☐ Other:				
Relinquished By: Ed Kennedy		Relinquished By:	Relinquished By:				
Date / Time: 2-18-21		Date / Time:	Date / Time:				
Received By: CEL		Received By:	Received By:				
Date / Time: 2-18-21 3:55pm DVO		Date / Time:	Date / Time:				
Condition Acceptable? ☒ Yes ☐ No		Condition Acceptable? ☐ Yes ☐ No	Condition Acceptable? ☐ Yes ☐ No				

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.
 San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274
 Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417
 Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040



Client Name & Address: Environmental Assistance Group 179 Niblick Road #401 Paso Robles Ca. 93446							
Client No.: L-1206							
PO / Job#: MNH221 Date: 2-17-21							
Turn Around Time: Same Day / 1Day / 2Day / 3Day / 4Day / 5Day							
☐ PCM: ☒ NIOSH 7400A / ☐ NIOSH 7400B ☐ Rotometer							
☒ PLM: ☒ Standard / ☐ Point Count 400 - 1000 / ☐ CARB 435							
Contact:	Ed Kennedy		Phone:	(661) 304-8981			
E-mail:	comply@haztrainer.com						
Site Name:			☐ TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 ☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Weight % ☐ TEM Microvac: ☐ Qual / ☐ D5755(str/area) / ☐ D5756(str/mass)				
Site Location:			☐ IAQ Particle Identification (PLM LAB) ☐ Particle Identification (TEM LAB) ☐ Metals Analysis Matrix: Method: Analytes: ☐ Silica in Air ☐ w/Gravimetry ☐ Quartz Only				
Comments: 8088 Positive Stop Each HA							
Sample ID	Date / Time	Sample Location / Description	Type	Time On/Off	Avg IPM	Total Time	Sample Area / Air Volume
MNH221712-17-21	HA 16	I 72 I 16	A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
			A P E				
Sampled By: Ed Kennedy EK	Date/Time: 2-17-21	Shipped Via: Fed Ex UPS US Mail Courier Drop Off Other:					
Relinquished By: Ed Kennedy EK	Date / Time: 2-18-21	Received By:	Date / Time:	Condition Acceptable? Yes No			
Received By: CLK MHL	Date / Time: 2-18-21 3:15pm D/O	Received By:	Date / Time:	Condition Acceptable? Yes No			

SGS Forensic Laboratories may subcontract client samples to other SGSFL locations to meet client requests.

San Francisco Office: 3777 Depot Road, Suite 409, Hayward, CA 94545-2761 • Phone: 510/887-8828 • 800/827-3274

Los Angeles Office: 20535 South Belshaw Ave., Carson, CA 90746 • Phone: 310/763-2374 • 888/813-9417

Las Vegas Office: 6765 S. Eastern Avenue, Suite 3, Las Vegas, NV 89119 • Phone: 702/784-0040