Hoyt Renovation

Site – 3.17 Acres Original Construction 1956 Area – 33, 900 SF 3 Story Building

DEFICIENCIES:

Parking Lot – Cracking and Pot holes exist Poor site grading, pitching toward building Roof and Gutters are original construction Windows are single pane, non insulated Ramps in lower level are not ADA Compliant Casework throughout do not meet ADA Requirements VCT Flooring is cracked throughout the building Settlement has occurred in East Classrooms Casework Non ADA Compliant and chipping Poor Ventilation Restrooms not ADA compliant

IMPROVEMENTS:

All Classrooms Refreshed New Flooring New Ceilings All Walls Repainted New Windows New Doors & Hardware New Secure Entry New Science Classroom New Culinary Classroom New Art Classroom All Restrooms Gutted and Refurbished New Elevator New All Gender Restroom On Each Floor Improved Technology Improved HVAC System New Lighting









