

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Auditorium	Mastic associated w/ floor tile	011A	4,360 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	9"x9" taupe floor tile under carpet	001A	4,360 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
Wood Shop Office (336)	9"x9" white w/ blue floor tile	001A	300 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	Mastic associated w/ floor tile	011A	300 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
Wood Shop	Transite panels	013S		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Wood Shop (332)	Mastic associated w/ floor tile	011A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	9"x9" taupe floor tile under carpet	001A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
Back Stage Storage	Mastic associated w/ floor tile	011A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	9"x9" taupe floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	HVAC vibration collar	003A		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Book Room next to custodial closet across from Rm 223	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Coaches Rm in girls locker Rm	Pipe Fitting Insulation	012A	7 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Could not locate	Could not locate
Technology Rm (former Curriculum Office)	Window Sill		7 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M
	9"x9" taupe floor tile	001A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	O&M	O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Custodial Office	12"x12" black w/ white floor tile	001A	550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Pipe Fitting Insulation	012A	16 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Department Chair Office	Mastic associated w/ floor tile	011A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Department Chair Office	Window Sill		16 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Dressing Room behind stage	Mastic associated w/ floor tile		160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Exterior windows & doors	Caulking	004A		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Nurse's Office (Next to 207)	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	No Access	No Access
	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage		
	9"x9" taupe floor tile under 12"x12" tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage		
Props Rm behind Stage	Mastic associated with 9"x9" floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile under 12"x12" tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Publications Office by Rm 309 (now 307)	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ pink floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	HVAC Vibrarion damper		4 Lineat Ft	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Radio Station Rm (New) (Room 138)	12"x12" white w/ blue floor tile		400 Ft ²	No Access	No Access	No Access	No Access
	Mastic associated w/ floor tile	011A	400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 103	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 104	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 105	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 106	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 108	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 107/109	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 111	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 113	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 114	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 115	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 116	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 118	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 120	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 122	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 12124	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 201A/B- Special Services (across from 212)	Mastic associated w/ 9"x9" floor tile	011A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 203	Lab Table tops		400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" floor tile		8600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 203 storage	Pipe Fitting Insulation		10 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Lab Table tops		120 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" white w/ red floor tile	011A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	660 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 204 & store room	Lab Table tops		215 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood		45 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	8600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ blue floor tile		860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	EVTs in store room		8 count	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 205	Lab Table tops		400Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood		45 Ft ²	Gone	Gone	Gone	Gone
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile (Under carpet)	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Ricks Room (former dark room)	Lab Table tops		60Ft ²	No Access	No Access	No Access	No Access
	Mastic associated w/ floor tile	011A	60 Ft ²	No Access	No Access	No Access	No Access
	9"x9" taupe floor tile	001A	60 Ft ²	No Access	No Access	No Access	No Access
Rm 205 Storage	Lab Table tops		60Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Pipe Fitting Insulation		10 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Curriculum Rm	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/ blue floor tile	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 206	9"x9" white w/ blue floor tile (Under Carpet?)		200 FT2	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" mastic associated w/ floor tile	011A	200 FT2	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Room 206 Storage	Pipe Fitting Insulation		4 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Radio Station Rm (Old) Near 209	Carper over 9"x9" white w/ blue floor tile ?		400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 208 Teachers Lounge	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 210	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 213	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" white w/red floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 218	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 220	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" floor tile (under carpet)	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 221 (Drama) (Carpet over suspect tile)	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Store Rm across from 221	Mastic associated w/ floor tile	011A	144Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9"taupe floor tile	001A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 222	Window Sill		9 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 223	Window Sill		20 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 224	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/green floor tile	001A	1550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 303	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 304/306	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1520 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	1520 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 305	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 307	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/red floor tile	001A	760 Ft ²	8 missing	8 missing	Replace/Continue O&M	Replace/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 308	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 309	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ coral floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 310	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 311	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 312	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 313 (Speech Therapy)	Mastic associated w/ floor tile	011A	250 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	250 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 314	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 315	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 316	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 317	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 321	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 323	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Damage Assessment	Previous Response	Current Response
Rm 325	Transite table tops		40 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	EVTS in corner above ceiling		20count	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	900 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	900 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 332 (Wood Storage)	Mastic associated w/ floor tile	011A	850Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/teal floor tile	001A	850 Ft ²	Broken & Damaged Tile/Debris Present	Broken & Damaged Tile/Debris Present	Clean up debris & Replace missing tile ASAP	Clean up debris & Replace missing tile ASAP
Rm 401, 402 & Prep room between 401, 402	Lab Table tops		800Ft ²	Gone	Gone	Gone	Gone
	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood	006A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Teachers Room	Mastic associated w/ floor tile	011A	600Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	12"x12" white w/ red floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Could not locate room	Could not locate room
Throughout Building	Hollow Metal fire doors		860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
				ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Auditorium	Mastic associated w/ floor tile	011A	4,360 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile under carpet	001A	4,360 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Wood Shop Office (336)	9"x9" white w/ blue floor tile	001A	300 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	300 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Wood Shop	Transite panels	013S		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Wood Shop (332)	Mastic associated w/ floor tile	011A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile under carpet	001A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Back Stage Storage	Mastic associated w/ floor tile	011A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	HVAC vibration collar	003A		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Book Room next to custodial closet across from Rm 223	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Coaches Rm in girls locker Rm	Pipe Fitting Insulation	012A	7 LF	ACM w/ Potential for Damage	Could not locate	Could not locate	Could not locate
Technology Rm (former Curriculum Office)	Window Sill		7 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Custodial Office	12"x12" black w/ white floor tile	001A	550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Pipe Fitting Insulation	012A	16 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Department Chair Office	Mastic associated w/ floor tile	011A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	1,817 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Department Chair Office	Window Sill		16 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Dressing Room behind stage	Mastic associated w/ floor tile		160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Exterior windows & doors	Caulking	004A		ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Nurse's Office (Next to 207)	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	No Access	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage		Monitor/Continue O&M
	9"x9" taupe floor tile under 12"x12" tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage		Monitor/Continue O&M
Props Rm behind Stage	Mastic associated with 9"x9" floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile under 12"x12" tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Publications Office by Rm 309 (now 307)	Mastic associated w/ floor tile	011A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ pink floor tile	001A	160 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	HVAC Vibrarion damper		4 Lineat Ft	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Radio Station Rm (New) (Room 138)	12"x12" white w/ blue floor tile		400 Ft ²	No Access	No Access	No Access	No Access
	Mastic associated w/ floor tile	011A	400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 103	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 104	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 105	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" beige w/ brown floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 106	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 108	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 107/109	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 111	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 113	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 114	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 115	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 116	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 118	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 120	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 122	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 12124	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 201A/B- Special Services (across from 212)	Mastic associated w/ 9"x9" floor tile	011A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 203	Lab Table tops		400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" floor tile		8600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 203 storage	Pipe Fitting Insulation		10 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Lab Table tops		120 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" white w/ red floor tile	011A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	660 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 204 & store room	Lab Table tops		215 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood		45 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	8600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ blue floor tile		860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	EVTs in store room		8 count	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 205	Lab Table tops		400Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood		45 Ft ²	Gone	Gone	Gone	Gone
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile (Under carpet)	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Ricks Room (former dark room)	Lab Table tops		60Ft ²	No Access	No Access	No Access	No Access
	Mastic associated w/ floor tile	011A	60 Ft ²	No Access	No Access	No Access	No Access
	9"x9" taupe floor tile	001A	60 Ft ²	No Access	No Access	No Access	No Access
Rm 205 Storage	Lab Table tops		60Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Pipe Fitting Insulation		10 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Curriculum Rm	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/ blue floor tile	001A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 206	9"x9" white w/ blue floor tile (Under Carpet?)		200 FT2	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" mastic associated w/ floor tile	011A	200 FT2	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Room 206 Storage	Pipe Fitting Insulation		4 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Radio Station Rm (Old) Near 209	Carper over 9"x9" white w/ blue floor tile ?		400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	400 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 208 Teachers Lounge	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
Rm 210	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 213	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" white w/red floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 218	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 220	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ 9"x9" tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" floor tile (under carpet)	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 221 (Drama) (Carpet over suspect tile)	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Store Rm across from 221	Mastic associated w/ floor tile	011A	144Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9"taupe floor tile	001A	144 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 222	Window Sill		9 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" taupe floor tile	001A	950 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 223	Window Sill		20 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 224	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/green floor tile	001A	1550 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 303	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 304/306	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	1520 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	1520 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 305	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 307	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/red floor tile	001A	760 Ft ²	8 missing	8 missing	Replace/Continue O&M	Replace/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 308	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 309	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ coral floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 310	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 311	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 312	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 313 (Speech Therapy)	Mastic associated w/ floor tile	011A	250 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	250 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 314	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 315	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 316	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 317	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ green floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 321	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 323	Window Sill		12 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/ red floor tile	001A	760 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M

AHERA 3 YEAR RE-INSPECTION

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Condition	Previous Response	Current Response
Rm 325	Transite table tops		40 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	EVTS in corner above ceiling		20count	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage	ACM w/ Potential for Damage
	Mastic associated w/ floor tile	011A	900 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/blue floor tile	001A	900 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Rm 332 (Wood Storage)	Mastic associated w/ floor tile	011A	850Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	9"x9" white w/teal floor tile	001A	850 Ft ²	Broken & Damaged Tile/Debris Present	Broken & Damaged Tile/Debris Present	Clean up debris & Replace missing tile ASAP	Clean up debris & Replace missing tile ASAP
Rm 401, 402 & Prep room between 401, 402	Lab Table tops		800Ft ²	Gone	Gone	Gone	Gone
	Window Sill		24 LF	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Transite Fume Hood	006A	60 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	Mastic associated w/ floor tile	011A	860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
Teachers Room	Mastic associated w/ floor tile	011A	600Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
	12"x12" white w/ red floor tile	001A	600 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Could not locate room	Could not locate room
Throughout Building	Hollow Metal fire doors		860 Ft ²	ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M
				ACM w/ Potential for Damage	ACM w/ Potential for Damage	Monitor/Continue O&M	Monitor/Continue O&M