



**RainCrow**

Environmental

***Triennial Asbestos  
Re-inspection  
Report***

**St. Clair County BOE  
410 Roy Drive  
Ashville, AL 35953**

**May 23<sup>rd</sup>, 2018**

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.**  
**Central Office**  
**410 Roy Drive**  
**Ashville, AL 35953**

**REINSPECTION DATE:** 5/23/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL051857655


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**


All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15												Date Of Reinspection – 5-23-18											
LEA Name - St. Clair Co. Board of Education												LEA # 058											
School Name – Administrative Buildings												School # 000											
Building Name – Central Office												Building # 01											
Address: 410 Roy Drive Ashville, Alabama 35953												Inspector's Name – Stan Eller											
												Signature - 											
												Alabama Accreditation No. – APL0518257655											
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Drywall ceiling – textured (lobby)- 252 ft²		Drywall ceiling – textured (offices)- 3046 ft²		Drywall ceil.-text ured (supply rm, kitch., comp server & personnel file rms)- 274 ft²		Drywall ceiling – textured (restrooms)- 288 ft²		Drywall (lobby)- 660 ft²		Drywall (offices)- 5040 ft²		Drywall (supply rm, kitch, comp. server & personnel file rms)- 1170 ft²		Drywall (restrooms)- 960 ft²		Glue-down comm. carpet/mastic (offices) brn & burgdy pattern - 3046 ft²		12" VFT (supply rm, kitch, comp. server & personnel file rms) bge w/brze flecks -274 ft²		
			No.																				
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																						
	Surfacing		X		X		X		X		X		X		X		X						
	Miscellaneous																		X		X		
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																						
	Non ACBM																						
	ACBM																						
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																							
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
	40 Hours/Week																						
Check All That Apply	Maintenance																						
	Custodial																						
	Faculty/Students																						
	Public																						
Assessment Category																							

**Alabama Asbestos Management Program  
AHRA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Administrative Buildings										School # 000									
Building Name – Central Office										Building # 01									
Address: 410 Roy Drive Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4"x 8" Ceramic floor tile/grout (lobby) brown -252 ft²	1" Ceramic floor tile/grout (restrooms) tan -288 ft²	2" Expansion joint (basement mechanical room) black - 25 Lf	Sink w/ spray-on material (kitchen) - 1	12" VFT (Basement)									
			No.	35-01	35-04	41-05	45-03	31-01								

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																
	Surfacing							X									
	Miscellaneous		X		X		X				X						
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X						
	Sampled/Tested																
	Non ACBM																
	ACBM																
	Nonfriable	X	X	X	X	X	X	X	X	X	X						
	Friable																
Assessment/Reassessment																	
Change in Condition? (Y/N)			N		N		N		N		N						
Rate 1 To 5 5 is Worst	Deterioration																
	Physical Damage																
	Water Damage																
	Activity/Vibration																
	Exposure																
Length of Exposure	Accessibility																
	1 Hour/Week																
	5 Hours/Week																
	10 Hours/Week																
	20 Hours/Week																
	40 Hours/Week																
Check All That Apply	Maintenance																
	Custodial																
	Faculty/Students																
	Public																
Assessment Category																	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Administrative Buildings										School # 000									
Building Name – Bus Shop										Building # 02									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (back office) tan w/ lt. green swirls - 180 ft <sup>2</sup>	1 - Sink w/ black spray-on material (back kitchen)	1 – “Modine” Gas Ceiling Heater / Linings (Shop)	1 – “Trane” Gas Ceiling Heater / Linings (Shop)	Sheetrock Ceiling (Old Office)												
			No.	31-01	45-02	56-03	56-04	14-01											

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI							X		X											
	Surfacing				X																
	Miscellaneous		X									X									
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X								
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X								
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		N		N		N		N										
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.**  
**Ashville High School**  
**Hwy. 231**  
**Ashville, AL 35953**

**REINSPECTION DATE: 5/23/18**

**INSPECTOR: Stan Eller**

**ACCREDITATION NO.: APL051857655**


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**


All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Ashville High School										School # 001												
Building Name – Main										Building # 01												
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 Vinyl coated fiberglass ceiling tile (CR-109, strg rm hallway, comp. lab) - 1610 ft²		2x2 white-worm ceiling tile (CR's 101-108, 110-113, home-ec, vo-ag, off, hall) - 12,252 ft²		2x4 white-worm ceiling tile (corridor) - 2708 ft²		2x2 white-worm ceiling tile (home-ec living room) - 552 ft²		2x2 white-worm ceiling tile (central corridor) - 1520 ft²		2x4 white-worm ceiling tile (guidance counselor off & g.c. front off) - 360 ft²		2x2 white-worm ceiling tile (coach's office) - 204 ft²		2x4 white-worm ceiling tile (girls' team-room) - 558 ft²		Corrugated transite awning (back of shop) - 15 ft²		Transite panels (S. corridor entrance) - 23 ft²	
			No.	07-04	10-01	10-05	10-09	10-13	10-14	10-18	10-24	11-10A	29-01A									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X			X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested						X															
	Non ACBM						X															
	ACBM																					
	Nonfriable		X	X	X	X	X		X	X	X	X	X	X	X	X	X	X	X	X		
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville High School										School # 001									
Building Name – Main										Building # 01									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Glue-down commercial carpet/mastic (coach's office) grey - 204 ft²		Glue-down commercial carpet/mastic (girls' team-room) dark green - 324 ft²		12" Vinyl floor tile (janitor storage & RR) beige w/ brn & grey swirls -256 ft²		12" VFT (guidance counselor off. & g.c. front off.) bge w/ brn & grey swirls -360 ft²		12" VFT (stage & hall, boys basket ball LR) gry w/ wht & blk swirls-1520 ft²		12" Vinyl floor tile (boys locker rm) beige w/ grey - 48 ft²		12" VFT (boys & girls LR) dark green w/white swirls -336 ft²		12" VFT (coach's off, laundry rm.) cream w/ grey & lavender streaks -119 ft²		12" VFT (coach's off & laundry rm accent pieces) grey w/dark grey - 63 ft²		12" Vinyl floor tile (girls team room ) white - 279 ft²	
			No.	30-18	30-24	31-08	31-14	31-16	31-17A	31-17B	31-20	31-20A	31-24									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X		X	X	X	X	X	X			X	X								
	Sampled/Tested									X				X				X		X	
	Non ACBM									X				X				X		X	
	ACBM																				
	Nonfriable	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category		Non-glue-down																			



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18					
LEA Name - St. Clair Co. Board of Education						LEA # 058					
School Name – Ashville High School						School # 001					
Building Name – Main						Building # 01					
Address: Hwy 231 Ashville, Alabama 35953						Inspector's Name – Stan Eller					
						Signature - 					
						Alabama Accreditation No. – APL0518257655					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl floor tile (girls team room ) green - 279 ft²		9" VFT (CR's 101-108, 110-113, home-ec & vo-ag) orange tan w/pink, grey, brn - 12,120 ft²		9" VFT (vo-ag office, hall) orange tan w/ pink, grey, brn swirls - 132 ft		9" VFT (lab strg, HVAC rm, teacher wrk rm) orange tan w/ pink, grey, brn - 672 ft²		9" VFT (CR-101 strg, teacher lng, home-ec strg) orange tan w/ pink, grey, brn - 704 ft²		9" VFT (guidance couns. off strg, concess strd) orange tan w/ pink, grey, brn - 256 ft²		9" VFT (CR-109, strg room hall, comp lab) orange tan w/ pink, grey, brn swirls - 1610 ft²		9" VFT (corridor) orange tan w/ pink, grey, brn swirls - 2708 ft²		9" VFT (home-ec living rm.) orange tan w/ pink, grey, brn swirls - 552 ft²		9" VFT (guidance counselor's off) orange tan w/ pink, grey, brn - 160 ft²	
			No.	31-24A	32-01	32-01	32-02	32-02	32-02	32-04	32-05	32-09	32-14									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X																			
	Sampled/Tested			X		X		X		X		X		X		X		X		X	
	Non ACBM																				
	ACBM			X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Nonfriable	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Friable																				


  

Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	

<b>Check All That Apply</b>	<b>Rate 1 To 5 5 is Worst</b>	Deterioration	<b>Removed</b>	<b>Classroom 110 Covered W/ New 12" VFT.</b>	<b>Covered W/ New 12" VFT.</b>																		
		Physical Damage																					
		Water Damage																					
		Activity/Vibration																					
		Exposure																					
	<b>Length of Exposure</b>	Accessibility																					
		1 Hour/Week																					
		5 Hours/Week																					
		10 Hours/Week																					
		20 Hours/Week																					
	40 Hours/Week																						
	Maintenance																						
	Custodial																						
	Faculty/Students																						
	Public																						
	Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville High School										School # 001									
Building Name – Main										Building # 01									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" Vinyl floor tile (coach's off ) orange tan w/ pink, grey, brn swirls - 204 ft²		9" Vinyl floor tile (off strg) orange tan w/ pink, grey, brn swirls - 25 ft²		1" Cer. floor tile/ grout (boys,shop, & guidn. cnslr rr) drk brn & tan-325 ft²		1" Cer. floor tile/ grout (girls,men,women, home-ec rr) drk grn - 324 ft²		1" Cer. floor tile/ grout (girls shower rm) grn w/ wht specks -292 ft²		6" Red quarry tile (central corridor) -1520 ft²		4" Vinyl cove base (home-ec) -210 Lf		3x2" Vinyl cove base (gym wall & floor) black -348 Lf		4" Vinyl cove base (girls locker room) black - 70 Lf		Lab table tops (classrooms 110 & 111) black -196 ft²	
			No.	32-18	32-21	35-07	35-07A	35-23	38-13	42-01	42-15	42-22	44-01									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM											X	X	X	X	X	X	X	X	X	
	Sampled/Tested	X		X		X		X		X											
	Non ACBM					X		X		X											
	ACBM	X	X	X	X																
	Nonfriable	X	X	X	X	X		X		X		X	X	X	X	X	X	X	X	X	
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					

Not Covered Under AHERA.

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville High School										School # 001									
Building Name – Main										Building # 01									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4 – Sinks w/ spray-on material (home-ec)	Fire brick (old boiler room) - 648 ft²	Canvas HVAC Expansion Joint (Custodial Mechanical Rm) - 16 lf														
		No.	45-01	54-12	55-12														

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing	X																		
	Miscellaneous			X		X														
	Assumed ACBM	X	X	X		X	X													
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable	X	X	X		X	X													
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)		N		N		N														
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville High School										School # 001									
Building Name – Band Hall										Building # 02									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (throughout band hall) - 2000 ft²	12" Vinyl floor tile (Gray) - 80 ft²	12" Vinyl floor tile (Gray) - 48 ft²	12" Vinyl floor tile (Gray) - 80 ft²	12" Vinyl floor tile (Gray) - 32 ft²	12" Vinyl floor tile (Gray) bge W/ gray marbled- 32 ft²								
			No.	10-01	31-01	31-02	31-03	31-04	31-05							

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																	
	Surfacing																	
	Miscellaneous	X		X		X		X		X		X						
	Assumed ACBM	X		X	X	X	X	X	X	X	X	X	X					
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable	X		X	X	X	X	X	X	X	X	X	X	X				
	Friable																	

Assessment/Reassessment																	
Change in Condition? (Y/N)		N		N		N		N		N		N					

<b>Rate 1 To 5 5 is Worst</b>	Deterioration	This Ceiling Tile is a Vinyl Coated Fiberglass.																
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	


  

<b>Length of Exposure</b>	Accessibility	Not Listed In The Original Management Plan.																
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
	40 Hours/Week																	

<b>Check All That Apply</b>	Maintenance	Not Listed In The Original Management Plan.																
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category																	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville High School										School # 001									
Building Name – Football Concession										Building # 04									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (Throughout Concessions) - 442 ft²																
			No.	10-01															

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X																			
	Assumed ACBM																				
	Sampled/Tested																				
	Non ACBM	X																			
	ACBM																				
	Nonfriable	X																			
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N																			
Rate 1 To 5 5 is Worst	Deterioration	Determined To Be "Armstrong" Non-ACBM.																			
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
	Assessment Category																				

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.**  
**Ashville Elementary School**  
**Hwy. 231**  
**Ashville, AL 35953**

**REINSPECTION DATE:** 5/23/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL051857655

**SIGNATURE:** 


**COMMENTS AND INSTRUCTIONS:**

Since the last inspection, the carpet has been replaced with new 12"vinyl floor tile in the lounge office / workroom (HA 30-11) at the *Main* building (01).

All changes are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18					
LEA Name - St. Clair Co. Board of Education						LEA # 058					
School Name – Ashville Elementary School						School # 005					
Building Name – Main						Building # 01					
Address: Hwy 231 Ashville, Alabama 35953						Inspector's Name – Stan Eller					
						Signature - 					
						Alabama Accreditation No. – APL0518257655					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (CR's 9,10,13,14)- 2880 ft <sup>2</sup>		2x2 white-worm ceiling tile (library)- 1408 ft <sup>2</sup>		2x4 w/w ceiling tile (computer rm, speech off, & nurse rm) - 1188 ft <sup>2</sup>		2x4 white-worm ceiling tile (southwest corridor) - 384 ft <sup>2</sup>		2x4 white-worm ceiling tile (CR's 4 - 8) - 3600 ft <sup>2</sup>		2x2 white-worm ceiling tile (southwest & north corridor) - 1464 ft <sup>2</sup>		2x2 white-worm ceiling tile (lounge office/ work room) - 690 ft <sup>2</sup>		2x2 white-worm ceiling tile (central corridor) - 893 ft <sup>2</sup>		2x2 white-worm ceiling tile (gym storage & teacher work room) - 432 ft <sup>2</sup>		2x2 white-worm ceiling tile (classroom - 20) - 576 ft <sup>2</sup>	
			No.	10-01	10-02	10-03	10-05	10-06	10-07	10-11	10-12	10-14	10-15									


  

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																						
	Surfacing																						
	Miscellaneous		X		X		X		X		X		X		X		X		X		X		
	Assumed ACBM		X	X	X		X		X		X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																						
	Non ACBM																						
	ACBM																						
	Nonfriable		X	X	X		X		X		X	X	X	X	X	X	X	X	X	X	X	X	X
	Friable																						
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week																						
	Maintenance																						
	Custodial																						
	Faculty/Students																						
	Public																						
Assessment Category																							

All Replaced W/ New 2x2 Ceiling Tile.	All Replaced W/ New 2x2 Ceiling Tile.	All Replaced W/ New 2x2 Ceiling Tile.
---------------------------------------	---------------------------------------	---------------------------------------


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Ashville Elementary School										School # 005												
Building Name – Main										Building # 01												
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Transite ceiling panel (north corridor entrance) - 9 ft²		Vinyl coated wood paneling (lounge office / work room) - 144 ft²		4"x7" Quarry tile wainscoting/grout (CR's 1-3 & 15-18) - 252 ft²		4"x7" Quarry wall tile /grout (storage hallway) - 120 ft²		Glue-down commercial carpet/mastic (library) lavender grev - 1408 ft²		Glue-down commercial carpet/mastic (storage) dark brown - 395 ft²		Glue-down commercial carpet / mastic (lng off / work rm) grev - 690 ft²		Glue-down carpet/mastic (work rm / gym strg) gry & drk brn- 432 ft²		Glue-down commercial carpet/mastic (CR – 20 & comp lab)grev-576 ft²		12" VFT (speech off, nurse & comp rm) tan w/grey & brn streaks - 1116 ft²	
			No.	11-07A	25-11	28-02	28-17	30-02	30-10	30-11	30-14	30-15	31-03									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		Y		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						



[illegible]

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ashville Elementary School										School # 005									
Building Name – Main										Building # 01									
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	6" Red quarry floor tile/grout (central corridor) -893 ft²		6" Red quarry floor tile/grout (CR -20, computer lab) -576 ft²		6" Red quarry floor tile/grout (storage hallway) -143 ft²		4" Vinyl cove base/mastic (CR's 9,10,13, 14) -312 Lf		14" Pipe (boiler room)		2x4 Vinyl Coated Fiberglass Ceiling Tile (CR's 1-3 & 15-18)-5040sf		12" Vinyl floor tile (cafe) It tan w/ gray & brown marbled - 4374 ft²		Fire-door (Janitor's Closet)					
			No.	38-12	38-15	38-17	42-01	53-20	07-02	31-21	40-01											

Inspection/Reinspection			Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	
			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now								

<b>Check one</b>	TSI																													
	Surfacing																													
	Miscellaneous		X		X		X		X		X		X		X		X		X											
	Assumed ACBM	X	X	X	X	X	X	X		X	X	X		X	X	X	X													
	Sampled/Tested																													
	Non ACBM													X																
	ACBM																													
	Nonfriable	X	X	X	X	X	X	X		X	X	X	X	X	X	X	X													
	Friable																													

Assessment/Reassessment																													
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N													

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																												
	Physical Damage																												
	Water Damage																												
	Activity/Vibration																												
	Exposure																												

<b>Length of Exposure</b>	Accessibility																											
	1 Hour/Week																											
	5 Hours/Week																											
	10 Hours/Week																											
	20 Hours/Week																											


  

<b>Check All That Apply</b>	Maintenance																											
	Custodial																											
	Faculty/Students																											
	Public																											


  

Assessment Category																													
---------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18														
LEA Name - St. Clair Co. Board of Education										LEA # 058														
School Name – Ashville Elementary School										School # 005														
Building Name – Trailer # 1 (1 <sup>st</sup> Grade Classroom)										Building # 10														
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller														
										Signature - 														
<b>Still Remains</b>										Alabama Accreditation No. – APL0518257655														
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Stippled Ceiling (Classroom) -546 ft <sup>2</sup>		Sheetrock Wall Panels (Classroom) -770 ft <sup>2</sup>		12" Vinyl floor tile (CR) lt. tan w/ brwn marbled flecks- 546 ft <sup>2</sup>																	
			No.	15-01	22-01	31-01																		
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now				
Check one	TSI																							
	Surfacing		X																					
	Miscellaneous				X		X																	
	Assumed ACBM		X	X	X	X	X	X																
	Sampled/Tested																							
	Non ACBM																							
	ACBM																							
	Nonfriable		X	X	X	X	X	X																
Friable																								
Assessment/Reassessment																								
Change in Condition? (Y/N)			N		N		N																	
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																	
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																	
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																	
	Maintenance																							
	Custodial																							
	Faculty/Students																							
Public		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																		
Assessment Category																								


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18												
LEA Name - St. Clair Co. Board of Education						LEA # 058												
School Name – Ashville Elementary School						School # 005												
Building Name – Trailer # 2 (Resource Rm./Special Ed.)						Building # 20												
Address: Hwy 231 Ashville, Alabama 35953						Inspector's Name – Stan Eller												
						Signature - 												
<b>Removed</b>						Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Stippled Ceiling (Classroom) - 546 ft²	Sheetrock Wall Panels (Classroom) - 770 ft²	12" Vinyl floor tile (Classroom) - 546 ft²													
		No.	15-01	22-01	31-01													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing		X															
	Miscellaneous				X	X												
	Assumed ACBM		X		X	X												
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable		X		X	X												
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N											
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan.													
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week																	
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category																	


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18										
LEA Name - St. Clair Co. Board of Education										LEA # 058										
School Name – Ashville Elementary School										School # 005										
Building Name – Trailer # 3 (Resource Rm./Special Ed.)										Building # 30										
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller										
										Signature - 										
										Alabama Accreditation No. – APL0518257655										
<b>Removed</b>																				
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Textured Sheetrock Ceiling (Classroom) – 546 ft <sup>2</sup>		Sheetrock Wall Panels (Classroom) - 770 ft <sup>2</sup>															
			No.	15-01	22-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing		X																	
	Miscellaneous				X															
	Assumed ACBM		X		X															
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X															
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N															
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	Maintenance																			
	Custodial																			
	Faculty/Students																			
Public																				
Assessment Category																				


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18												
LEA Name - St. Clair Co. Board of Education						LEA # 058												
School Name – Ashville Elementary School						School # 005												
Building Name – Trailer # 4 (2 <sup>nd</sup> Grade Classroom)						Building # 40												
Address: Hwy 231 Ashville, Alabama 35953						Inspector's Name – Stan Eller												
						Signature - 												
						Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Textured Sheetrock Ceiling (Classroom) - 504 ft <sup>2</sup>		Vinyl Coated Sheetrock Wall Panels (Classroom) - 756 ft <sup>2</sup>		12" Vinyl floor tile (Classroom) gray marbled - 504 ft <sup>2</sup>											
			No.	15-01	22-01	31-01												
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing		X															
	Miscellaneous				X		X											
	Assumed ACBM		X		X		X											
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable		X		X		X											
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N											
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week																	
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category			Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.											

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18																
LEA Name - St. Clair Co. Board of Education						LEA # 058																
School Name – Ashville Elementary School						School # 005																
Building Name – Trailer # 5 (2 <sup>nd</sup> Grade Classroom)						Building # 50																
Address: Hwy 231 Ashville, Alabama 35953						Inspector's Name – Stan Eller																
						Signature - 																
<b>Removed</b>						Alabama Accreditation No. – APL0518257655																
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Textured Sheetrock Ceiling (Classroom) - 504 ft <sup>2</sup>		Vinyl Coated Sheetrock Wall Panels (Classroom) - 756 ft <sup>2</sup>		12" Vinyl floor tile (Classroom) gray marbled - 504 ft <sup>2</sup>															
			No.	15-01	22-01	31-01																
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now				
Check one	TSI																					
	Surfacing		X																			
	Miscellaneous				X		X															
	Assumed ACBM		X		X		X															
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X															
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N															
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public			Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18													
LEA Name - St. Clair Co. Board of Education										LEA # 058													
School Name – Ashville Elementary School										School # 005													
Building Name – Trailer # 56 (Resource Room)										Building # 60													
Address: Hwy 231 Ashville, Alabama 35953										Inspector's Name – Stan Eller													
										Signature - 													
<b>Still Remains</b>										Alabama Accreditation No. – APL0518257655													
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Stippled Sheetrock Ceiling (Classroom) - 540 ft <sup>2</sup>		Sheetrock Wall Panels (Classroom) - 798 ft <sup>2</sup>		12" Vinyl floor tile (Classroom) lt. tan w/ bronze marbled - 540 ft <sup>2</sup>																
			No.	15-01	22-01	31-01																	
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now			
Check one	TSI																						
	Surfacing		X																				
	Miscellaneous				X		X																
	Assumed ACBM		X	X	X	X	X	X															
	Sampled/Tested																						
	Non ACBM																						
	ACBM																						
	Nonfriable		X	X	X	X	X	X															
Friable																							
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N																
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																
	Maintenance																						
	Custodial																						
	Faculty/Students																						
Public		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.																	
Assessment Category																							



Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.  
Ragland High School  
1060 Main St.  
Ragland, AL 35131**

**REINSPECTION DATE:** 5/23/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL051857655


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**

All changes are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	1500 ft² 2x4 vinyl coated fiberglass ceil. tile		151 ft² 2x4 vinyl coated fiberglass ceil. tile		16 ft² 2x4 vinyl coated fiberglass ceil. tile		750 ft² 2x4 white-worm ceiling tile		3963 ft² 2x4 white pin-point ceiling tile		2x2 white-worm ceiling tile(home ec) - 2304 ft²		264 ft² 2x4 white-worm ceiling tile		384 ft² 2x2 white-worm ceiling tile		714 ft² 2x2 white-worm ceiling tile		105 ft² 2x4 white-worm ceiling tile	
			No.																			
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X		X		X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X		X		X	X	X	X	X	X	X	X
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		Y		Y		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**


Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Ragland High School										School # 012												
Building Name – High School Building										Building # 01												
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	288 ft² 2x2 white-worm ceiling tile		2x2 white-worm ceiling tile (concess. stand) - 80 ft²		2x2 white-worm ceiling tile (gym corridor) - 1248 ft²		2x4 white-worm ceiling tile (corridor) - 525 ft²		2x2 white-worm ceiling tile (principals' & mechanical off) - 276 ft²		2x2 white-worm ceiling tile (receptionists office) - 56 ft²		2x2 white-worm ceiling tile (main office) - 256 ft²		2x2 white-worm ceiling tile (CR# 204) - 1728 ft²		2x2 white-worm ceiling tile (library) - 1736 ft²		2x2 white-worm ceiling tile (library storage) - 252 ft²	
			No.	10-10	10-11	10-12	10-18	10-21	10-24	10-25	10-01U	10-03U	10-04U									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15												Date Of Reinspection – 5-23-18											
LEA Name - St. Clair Co. Board of Education												LEA # 058											
School Name – Ragland High School												School # 012											
Building Name – High School Building												Building # 01											
Address: 1060 Main St. Ragland, Alabama 35131												Inspector's Name – Stan Eller											
												Signature - 											
												Alabama Accreditation No. – APL0518257655											
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (boys/girls restroom) - 216 ft²		2x2 white-worm ceiling tile (library corridor) - 242 ft²		2x2 white-worm ceiling tile (elevator room) - 330 ft²		2x2 white-worm ceiling tile (center corridor @ stairs) - 99 ft²		2x2 w/w ceiling tile (corr., stair corr., CR's 201,203, 205,206,208,210) - 6228 ft²		2x2 white-worm ceiling tile (lounge) - 272 ft²		2x2 white-worm ceiling tile (stairwell) - 96 ft²		Drywall (front corridor) - 184 ft²		Drywall (main office) - 48 ft²		Drywall (elevator room) - 80 ft²		
			No.	10-06U	10-07U	10-08U	10-09U	10-10U	10-14U	10-15U	22-20	22-25	22-08U										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																						
	Surfacing														X		X				X		
	Miscellaneous		X		X		X		X		X		X										
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	
	Sampled/Tested																						
	Non ACBM																						
	ACBM																						
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	
Friable																							
Assessment/Reassessment																							
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																						
	Physical Damage																						
	Water Damage																						
	Activity/Vibration																						
	Exposure																						
Length of Exposure	Accessibility																						
	1 Hour/Week																						
	5 Hours/Week																						
	10 Hours/Week																						
	20 Hours/Week																						
Check All That Apply	40 Hours/Week																						
	Maintenance																						
	Custodial																						
	Faculty/Students																						
Public																							
Assessment Category																							

Removed.

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl coated wood paneling (classrooms# 105, 107) - 880 ft²	Vinyl coated wood paneling (copy room# 104) - 432 ft²	Transite panels (front corridor)	Transite wall panels (receptionist office)	Glue-down commercial carpet/mastic (copy rm# 104) purple - 792 ft²	Glue-down comm carpet/mastic (stage strg & coaches off strg) purple - 330 ft²	Glue-down commercial carpet/mastic (corridor) purple - 140 ft²	Glue-down commercial carpet/mastic (mech., princ & secr off) purple - 444 ft²	Glue-down commercial carpet/mastic (library) purple - 1736 ft²	Glue-down commercial carpet/mastic (library storage) purple - 540 ft²
			No.	25-03	25-05	29-20	29-24	30-05	30-14	30-19	30-21	30-03U

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous	X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X		X		X	X	X	X	X		X	X	X	X
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X	X	X		X		X	X	X	X	X		X	X	X	X
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration					Removed.	Removed.					Removed.	Removed.			Removed In Summer Of 2010.	Removed In Summer Of 2010.		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility					Removed.	Removed.					Removed.	Removed.			Removed In Summer Of 2010.	Removed In Summer Of 2010.		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week					Removed.	Removed.					Removed.	Removed.			Removed In Summer Of 2010.	Removed In Summer Of 2010.		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Glue-down commercial carpet/mastic (lounge) purple - 272 ft²		12" Vinyl floor tile (home ec.) lt grn w/wht & grey flecks - 2304 ft²		12" Vinyl floor tile (CR's 103,105,107) cream w/brn swirls - 1500 ft²		12" Vinyl floor tile (NE cor.) purple w/lavender flecks - 264 ft²		12" Vinyl floor tile (CR's 101) cream w/grey flecks - 714 ft²		12" VFT(storage adj. CR's 101) cream w/mauve flecks - 105 ft²		12" Vinyl floor tile (concession stand) white w/red & grey flecks - 80 ft²		12" Vinyl floor tile (gym corridor) purple - 1248 ft²		12" Vinyl floor tile (stage) grey painted - 840 ft²		12" Vinyl floor tile (corridor) white w/red & grey flecks - 1050 ft²	
			No.	30-14U	31-01A	31-03	31-04	31-06	31-07	31-11	31-12	31-15	31-18									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Vinyl floor tile (main office) beige w/white & bronze streaks -256 ft²		12" Vinyl floor tile (lab storage) cream w/tan swirls -144 ft²		12" Vinyl floor tile (elevator rm) cream w/red & brown swirls -330ft²		12" Vinyl floor tile (center cor. @ stairs) cream w/lt brn streaks -99 ft²		12" Vinyl floor tile (stairs landing) black - 32 ft²		9" VFT (CR# 108,110) orange /tan w/red & grey swirls -1500 ft²		9" VFT (home ec) covered w/ 12" vinyl floor tile -2304 ft²		9" VFT (NE corridor) covered w/ 12" vinyl floor tile -264 ft²		9" VFT (copy room# 104) covered w/ 12" vinyl floor tile -792 ft²		9" Vinyl floor tile (office closet) orange /tan -16ft²	
			No.	31-25	31-02U	31-08U	31-09U	31-11U	32-01	32-01A	32-04	32-05	32-22									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																					
	Surfacing																					
	Miscellaneous	X		X		X		X		X		X		X		X		X		X		
	Assumed ACBM	X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)		N		Y		N		N		Y		Y		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (libr cor., CR# 202,204) cream w/ brown streaks -1970 ft²		9" VFT (cor., stair landing) orange /tan w/red & grey streaks		9" VFT (CR's 201, 203,205,206,208,210) orange /tan w/red & gry stkr -6188 ft²		9" Vinyl floor tile (lounge) orange /tan w/red & grey swirls -272 ft²		1" Ceramic floor tile/grout (boys rest room) grey -144 ft²		1" Ceramic floor tile/grout (girls rest room) green -144 ft²		1" Ceramic floor tile/grout (basement locker rms) grn -354 ft²		1" Ceramic floor tile/grout (office rest room) – 30 ft²		1" Ceramic floor tile/grout (boys/girls rest room) -216 ft²		1" Ceramic floor tile/grout (men/women lounge rest room) -50 ft²	
			No.	32-01U	32-10U	32-10U	32-14U	35-10	35-10A	35-16	35-23	35-06U	35-13U									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now					
Check one	TSI																									
	Surfacing																									
	Miscellaneous	X		X		X		X		X		X		X		X		X		X						
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X					
	Sampled/Tested																									
	Non ACBM																									
	ACBM																									
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X				
Friable																										
Assessment/Reassessment																										
Change in Condition? (Y/N)		N		Y		Y		Y		N		N		N		N		N		N						
Rate 1 To 5 5 is Worst	Deterioration	Hall Adjacent Library Replaced W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.																		
	Physical Damage																									
	Water Damage																									
	Activity/Vibration																									
	Exposure																									
Length of Exposure	Accessibility	Hall Adjacent Library Replaced W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.																		
	1 Hour/Week																									
	5 Hours/Week																									
	10 Hours/Week																									
	20 Hours/Week																									
Check All That Apply	40 Hours/Week	Hall Adjacent Library Replaced W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.																		
	Maintenance																									
	Custodial																									
	Faculty/Students																									
	Public	Hall Adjacent Library Replaced W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.		All Covered W/ New 12" VCT.																		
Assessment Category																										



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – High School Building										Building # 01									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	6" Red quarry floor tile/grout (front corridor) -416 ft²		6" Red quarry floor tile/grout (receptionist office) -56 ft²		4 – Fire-doors (gym corridor)		4" Vinyl cove base (elevator room) black - 10 Lf		4" Vinyl cove base (gym & gym corridor) black -559 Lf		4 – Sinks w/spray-on material (home ec)		1 – Sink w/spray-on material (mechanical office)		1 – Sink w/spray-on material (library storage)		Gaskets & firebricks (boiler room)		Vinyl room dividers (library storage) – 81 ft²	
			No.	38-20	38-24	40-12	42-08U	42-12	45-01A	45-21	45-05U	50-08	51-04U									


  

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now			
Check one	TSI																							
	Surfacing											X		X		X								
	Miscellaneous		X		X		X		X		X							X		X				
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X		X	X			
	Sampled/Tested																							
	Non ACBM																							
	ACBM																							
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X		X	X	X	X	X		X	X			
Friable																								
Assessment/Reassessment																								
Change in Condition? (Y/N)		N		N		N		N		N		Y		N		N		Y		N				
Rate 1 To 5 5 is Worst	Deterioration	Covered W/ Rubber.																						
	Physical Damage																							
	Water Damage																							
	Activity/Vibration																							
	Exposure																							
Length of Exposure	Accessibility		All New Sinks																					
	1 Hour/Week																							
	5 Hours/Week																							
	10 Hours/Week																							
	20 Hours/Week																							
Check All That Apply	40 Hours/Week			Removed																				
	Maintenance																							
	Custodial																							
	Faculty/Students																							
Public																								
Assessment Category																								

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18										
LEA Name - St. Clair Co. Board of Education						LEA # 058										
School Name – Ragland High School						School # 012										
Building Name – High School Building						Building # 01										
Address: 1060 Main St. Ragland, Alabama 35131						Inspector's Name – Stan Eller										
						Signature - 										
						Alabama Accreditation No. – APL0518257655										
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	“Reznor” Gas Ceiling Heater / Lining (Upstairs Hall)		2- “Modine” Gas Ceiling Heater / Lining (Gym Court Area)		9” Vinyl floor tile (stage)med. brown -840 ft <sup>2</sup>									
			No.	56-10	56-12	32-15										
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI		X		X											
	Surfacing															
	Miscellaneous						X									
	Assumed ACBM		X		X	X										
	Sampled/Tested						X									
	Non ACBM															
	ACBM						X	X								
	Nonfriable		X		X	X	X	X								
Friable																
Assessment/Reassessment																
Change in Condition? (Y/N)			N		N		N									
Rate 1 To 5 5 is Worst	Deterioration															
	Physical Damage															
	Water Damage															
	Activity/Vibration															
	Exposure															
Length of Exposure	Accessibility															
	1 Hour/Week															
	5 Hours/Week															
	10 Hours/Week															
	20 Hours/Week															
Check All That Apply	40 Hours/Week															
	Maintenance															
	Custodial															
	Faculty/Students															
	Public															
Assessment Category			Not Listed In The Original Management Plan. <b>Removed.</b>		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan. These Tiles Are Located Beneath Old 12” VFT.									

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15						Date Of Reinspection – 5-23-18					
LEA Name - St. Clair Co. Board of Education						LEA # 058					
School Name – Ragland High School						School # 012					
Building Name – Agri-Business						Building # 02					
Address: 1060 Main St. Ragland, Alabama 35131						Inspector's Name – Stan Eller					
						Signature - 					
						Alabama Accreditation No. – APL0518257655					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 vinyl coated sheetrock ceiling tile(wood shop) - 1500 ft <sup>2</sup>	2x4 white-worm ceiling tile (classroom) - 858 ft <sup>2</sup>	Tectum ceiling (classroom & welding shop) - 1978 ft <sup>2</sup>	12" Vinyl floor tile (classroom) beige w/grev streaks - 858 ft <sup>2</sup>	4" Vinyl cove base/mastic (base of welding shop lab table) - 34 Lf						
			No.	09-03	10-01	18-01	31-01	42-02					

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																
	Surfacing																
	Miscellaneous		X		X		X		X		X						
	Assumed ACBM	X	X	X				X		X							
	Sampled/Tested																
	Non ACBM					X				X							
	ACBM																
	Nonfriable	X	X	X		X		X		X	X						
	Friable																

Assessment/Reassessment																	
Change in Condition? (Y/N)			N		N		N		N		N						

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																
	Physical Damage																
	Water Damage																
	Activity/Vibration																
	Exposure																

<b>Length of Exposure</b>	Accessibility																
	1 Hour/Week																
	5 Hours/Week																
	10 Hours/Week																
	20 Hours/Week																

<b>Check All That Apply</b>	Maintenance																
	Custodial																
	Faculty/Students																
	Public																


Assessment Category																	
---------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

AL-AHERA Form 20 (May, 1991)

Page 1 of 1

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Band Hall / Weight Room										Building # 03									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 vinyl coated sheetrock ceiling tile(boys/girls RR) 280 ft <sup>2</sup>	2x4 white-worm ceiling tile (weight room) - 2000 ft <sup>2</sup>	2x4 white-worm ceiling tile (band-hall) - 1672 ft <sup>2</sup>	2x4 white-worm ceiling tile (band-hall office) - 140 ft <sup>2</sup>	2x4 white-worm ceiling tile (band storage) - 98 ft <sup>2</sup>	Glue-down comm carpet/mastic (weight rm) lt. brown - 2000 ft <sup>2</sup>	Glue-down comm carpet/mastic (band-hall) purple - 1368 ft <sup>2</sup>	Glue-down comm carpet/mastic (band-hall office) purple - 140 ft <sup>2</sup>	12" Vinyl floor tile (band-hall) white w/red flecks - 304 ft <sup>2</sup>	12" VFT (band storage) white w/red flecks - 98 ft <sup>2</sup>
			No.	09-04	10-01	10-03	10-05	10-06	30-01	30-03	30-05	31-03

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																				
	Surfacing									X	X	X	X								
	Miscellaneous	X		X	X	X		X	X	X	X	X	X	X	X	X	X	X	X		
	Assumed ACBM	X		X	X	X		X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																				
	Non ACBM					X															
	ACBM																				
	Nonfriable	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Friable																				
Assessment/Reassessment																					
Change in Condition? (Y/N)		Y		N		N		N		N		Y		Y		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category		<b>All Replaced.</b>						<b>Determined To Be USG Non-ACBM.</b>						<b>All Replaced W/ Rubber Floor.</b>				<b>All Replaced W/ New Carpet.</b>			

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Band Hall / Weight Room										Building # 03									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	6" Tan quarry floor tile/grout (boys/girls RR) lt. brwn -280 ft²	4 – Fire-doors (weight room & storage)	3 – Fire-doors (band hall)														
			No.	38-04	40-01	40-03													

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																		
	Surfacing																		
	Miscellaneous		X		X		X												
	Assumed ACBM	X	X	X	X	X	X												
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X	X	X	X												
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)			N		N		N												

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		


  

<b>Length of Exposure</b>	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
	40 Hours/Week																		

<b>Check All That Apply</b>	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Elementary Building										Building # 04									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 vinyl coated fiberglass ceil. tile(main office) 484 ft <sup>2</sup>		2x4 vinyl coated fiberglass ceil. tile(CR's 111,113) 768ft <sup>2</sup>		12" ceiling tile (classrooms 112,115-119,121-123) 6912 ft <sup>2</sup>		12" ceiling tile (faculty restrooms) 220 ft <sup>2</sup>		12" ceiling tile (offices) 664 ft <sup>2</sup>		12" ceiling tile (boys/girls restrooms) 1033 ft <sup>2</sup>		12" ceiling tile (N. corridor) 2706 ft <sup>2</sup>		2x2 vinyl coated sheetrock ceiling tile (boys/girls RR) 480 ft <sup>2</sup>		2x2 vinyl coated sheetrock ceiling tile (boys/girls RR) 1033 ft <sup>2</sup>		2x2 white-worm ceiling tile (CR's 112,115-119,121-123) 6912 ft <sup>2</sup>	
			No.	07-08	07-10	08-01	08-02	08-06	08-09	08-13	09-04	09-09	10-01									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X		X										X		X		X		X	
	Sampled/Tested					X		X		X		X		X							
	Non ACBM					X	X	X	X	X	X	X	X	X	X						
	ACBM																				
	Nonfriable	X		X		X	X	X	X	X	X	X	X	X	X			X		X	
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.												Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.		Replaced W/ New Ceiling Tile.	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Elementary Building										Building # 04									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (faculty restrooms) - 220 ft <sup>2</sup>	2x2 w/w ceiling tile (south & west corridor) - 578 ft <sup>2</sup>	2x2 w/w ceiling tile (offices & guidance counselor) - 664 ft <sup>2</sup>	2x2 white-worm ceiling tile (main offices) - 484 ft <sup>2</sup>	2x2 white-worm ceiling tile (classroom 110) - 768 ft <sup>2</sup>	2x2 white-worm ceiling tile (north corridor) - 2706 ft <sup>2</sup>	Vinyl coated wood paneling (main office) - 432 ft <sup>2</sup>	Vinyl coated wood paneling (CR's 111, 113) - 384 ft <sup>2</sup>	4" Ceramic wall tile/grout (boys/girls RR) grey - 1012 ft <sup>2</sup>	Glue-down comm. carpet/mastic (assistant principle off) purple-100ft <sup>2</sup>
			No.	10-02	10-03	10-06	10-08	10-11	10-13	25-08	25-10	28-09

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous	X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

Replaced W/ New Carpet

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Elementary Building										Building # 04									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Glue-down comm. carpet/mastic (main office) purple - 484 ft <sup>2</sup>		12" VFT (W&S corridor) cream w/blue & grey streaks - 578 ft <sup>2</sup>		12" Vinyl floor tile (other offices) cream w/grey streaks - 404 ft <sup>2</sup>		12" VFT (CR# 111,113) cream w/white & brown streaks - 768 ft <sup>2</sup>		12" VFT (CR# 110) avocado green w/white streaks - 444 ft <sup>2</sup>		12" VFT (Classroom # 110) cream w/green streaks - 60 ft <sup>2</sup>		12" VFT (N corridor) cream w/grey streaks - 2706 ft <sup>2</sup>		9" VFT (CR #s 112,115-119,121-123) black w/cream streaks - 6912 ft <sup>2</sup>		9" VFT (off & guidance counselors off) dark brn w/cream & red streaks - 664 ft <sup>2</sup>		9" Vinyl floor tile (main office) white - 484 ft <sup>2</sup>	
			No.	30-08	31-03	31-06	31-10	31-11	31-11A	31-13	32-01	32-06	32-08									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																					
	Surfacing																					
	Miscellaneous	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Assumed ACBM	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category		<div>Replaced W/ New Carpet.</div> <div>Covered Or Replaced W/ New 12" Vinyl Floor Tile.</div> <div>Covered W/ New 12" VCT.</div> <div>Covered W/ New Commercial Carpet.</div>																				



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-12-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ragland High School										School # 012									
Building Name – Elementary Building										Building # 04									
Address: 1060 Main St. Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (N corr) dark brn w/ cream & red streaks -2706 ft²		6" Red quarry floor tile/grout w/6" wainscot (faculty RR) -253 ft²		8" Tan quarry floor tile/grout w/8" wainscot (boys/girls RR) -546 ft²		6" Tan quarry floor tile/grout w/6" wainscot (boys / girls RR) -1100 ft²		2 – Fire-doors (north-west corridor)		2 – Fire-doors (south corridor)		4" Vinyl cove base/mastic (north-west corridor) lt.brwn -62 Lf		Sink w/spray-on material (classroom #'s 116, 117& 122) grey		2 - 6" Paper Light Fixture Heat Shields (Outside Porches)		Boiler Gaskets (basement boiler room)	
			No.	32-13	38-02	38-04	38-09	40-03	40-12	42-03	45-01	57-14	60									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				X
	Surfacing																				
	Miscellaneous		X		X		X		X		X		X		X		X		X		
	Assumed ACBM				X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested	X																			
	Non ACBM																				
	ACBM	X	X																		
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X				X	X
Friable																	X	X			
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		Y		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category		<div>Covered W/ New 12" Vinyl Floor Tile.</div> <div>Removed Remaining Room #116.</div> <div>One Heat Shield Removed During 2010 Renovations.</div> <div>Even Though Considered A Suspect ACBM, Not Covered Under AHERA.</div>																			

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.**  
**Springville Middle School**  
**6601 US Hwy 11**  
**Springville, AL 35146**

**REINSPECTION DATE:** 5/25/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**

All changes are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15												Date Of Reinspection – 5-25-18											
LEA Name - St. Clair Co. Board of Education												LEA # 058											
School Name – Springville Middle School												School # 013											
Building Name – Main Building												Building # 01											
Address: 6601 US Hwy 11 Springville, Alabama 35146												Inspector's Name – Stan Eller											
												Signature - 											
												Alabama Accreditation No. – APL0518257655											


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 vinyl coated sheetrock ceiling tile(restrooms) 27 ft <sup>2</sup>		2x2 vinyl coated sheetrock ceiling tile(boys/girls & faculty RR) 447 ft <sup>2</sup>		2x2 vinyl coated sheet-rock ceiling tile(main office RR) 30 ft <sup>2</sup>		2x2 vinyl coated sheet-rock ceiling tile(upstairs janitor closet) 10 ft <sup>2</sup>		2x2 vinyl coated sheetrock ceiling tile(upstairs boys /girls RR) 362 ft <sup>2</sup>		2x2 white-worm ceiling tile (auditorium) 4650 ft <sup>2</sup>		2x2 white-worm ceiling tile (work-room closet) 182 ft <sup>2</sup>		2x2 white-worm ceiling tile (work-room) - 1419 ft <sup>2</sup>		2x2 white-worm ceiling tile (work-room storage) - 143 ft <sup>2</sup>		2x2 white-pin-point ceiling tile (corridor) 608 ft <sup>2</sup>	
			No.	09-06	09-13	09-14	09-19	09-26	10-01	10-04	10-05	10-07	10-08									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
	Public																				
Assessment Category																					

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15						Date Of Reinspection – 5-25-18					
LEA Name - St. Clair Co. Board of Education						LEA # 058					
School Name – Springville Middle School						School # 013					
Building Name – Main Building						Building # 01					
Address: 6601 US Hwy 11 Springville, Alabama 35146						Inspector's Name – Stan Eller					
						Signature - 					
						Alabama Accreditation No. – APL0518257655					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (corridor)-3632 ft <sup>2</sup>		2x2 w/w ceiling tile (CR's 125, 126, 129, 150) - 2304 ft <sup>2</sup>		2x2 w/w ceiling tile (CR's 122, 140 & storage) - 1216 ft <sup>2</sup>		2x2 white-worm ceiling tile (stairs) - 296 ft <sup>2</sup>		2x2 white-worm ceiling tile (main office)-1506 ft <sup>2</sup>		2x2 w/w ceiling tile (upstairs classrooms 203, 213 216)-1800 ft <sup>2</sup>		2x2 w/w Ceiling Tile (upstairs CR's 218, 225 229, 230, 233)		2x2 w/w Ceiling Tile (compu. corr./work rm & HVAC)-3108 ft <sup>2</sup>		2x2 white-worm ceiling tile (library) - 1568 ft <sup>2</sup>		2x2 white-worm ceiling tile (corridor) - 2928 ft <sup>2</sup>	
			No.	10-09	10-10	10-11	10-12	10-14	10-16	10-17	10-17	10-18	10-21									


  

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable		X		X		X		X		X		X		X		X		X	
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N	

Rate 1 To 5 5 is Worst	Deterioration	“Armstrong” Ceiling Tile Is Non-ACBM.
	Physical Damage	
	Water Damage	
	Activity/Vibration	
	Exposure	
Length of Exposure	Accessibility	“Armstrong” Ceiling Tile Is Non-ACBM.
	1 Hour/Week	
	5 Hours/Week	
	10 Hours/Week	
	20 Hours/Week	
	40 Hours/Week	
Check All That Apply	Maintenance	“Armstrong” Ceiling Tile Is Non-ACBM.
	Custodial	
	Faculty/Students	
	Public	
	Assessment Category	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Main Building										Building # 01									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (storage room) - 90 ft <sup>2</sup>	2x2 w/w ceiling tile (lab storage, science lab, CR 235) - 1778 ft <sup>2</sup>	2x2 white-worm ceiling tile (corridor)-336 ft <sup>2</sup>	2x2 white-worm ceiling tile (book room storage)-77 ft <sup>2</sup>	Transite ceiling panels (above 2x2 lay-in @ science lab) - 864 ft <sup>2</sup>	Drywall (above stage )- 168 ft <sup>2</sup>	Drywall (@ stage storage )- 252 ft <sup>2</sup>	Drywall (work room storage )- 297 ft <sup>2</sup>	Drywall (work room restroom )- 195 ft <sup>2</sup>	Drywall (work room storage )- 117 ft <sup>2</sup>
			No.	10-22	10-23	10-24	10-25	11-23	22-02	22-03	22-04	22-06

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																		
	Surfacing																		
	Miscellaneous	X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X		X		X		X		X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X		X		X		X		X	X	X	X	X	X	X	X	X	X
	Friable																		


  

Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N	


  

<b>Rate 1 To 5 5 is Worst</b>	Deterioration	“Armstrong” Ceiling Tile Is Non-ACBM.	
	Physical Damage		
	Water Damage		
	Activity/Vibration		
	Exposure		
<b>Length of Exposure</b>	Accessibility	“Armstrong” Ceiling Tile Is Non-ACBM.	
	1 Hour/Week		
	5 Hours/Week		
	10 Hours/Week		
	20 Hours/Week		
<b>Check All That Apply</b>	40 Hours/Week	“Armstrong” Ceiling Tile Is Non-ACBM.	
	Maintenance		
	Custodial		
	Faculty/Students		
	Public		
Assessment Category			


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Main Building										Building # 01												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Drywall (classroom #'s 126,129,150)- 720 ft <sup>2</sup>		Drywall (classroom #'s 122,140)- 480 ft <sup>2</sup>		Drywall (main office) - 2720 ft <sup>2</sup>		Drywall (classroom #'s 218,225,229,230,233)- 3680 ft <sup>2</sup>		Drywall (library)- 560 ft <sup>2</sup>		Drywall (janitor closet)- 110 ft <sup>2</sup>		Drywall (science lab exterior wall )- 120 ft <sup>2</sup>		Vinyl coated ceiling & wall paneling (elevator) -328 ft <sup>2</sup>		6" Quarry tile wainscot (boys/girls restroom) - 132 ft <sup>2</sup>		Transite panels (classroom #'s 203,213,216) - 20 ft <sup>2</sup>	
			No.	22-10	22-11	22-14	22-17	22-18	22-19	22-23	24-15	28-26	29-16									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
	Assessment Category																					

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Main Building										Building # 01												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos.	Homogeneous Area	Description	Transite panels (CR #'s 218,225,229,230, 233) - 99 ft²		Transite panels (library) - 46 ft²		Glue-down comm. carpet/mastic (main office) purple - 438 ft²		Glue-down commercial carpet/mastic (library) purple - 1568 ft²		12" VFT (auditorium) dark beige w/grey swirls - 4650 ft²		12" VFT (work-room & work-room closet) lt green w/gry & wht swirls - 1601 ft²		12" VFT (work-room RR) lt green w/grey & white swirls - 27 ft²		12" VFT (work-room strg & RR) lt gm w/grey & white swirls - 233 ft²		12" VFT (corridor) lt green w/black skid flecks - 608 ft²		12" VFT (CR's 125, 126, 129) lt gm w/grey & white swirls - 2304 ft²	
			No.	29-17	29-18	30-14A	30-18	31-01	31-04	31-06	31-07	31-08	31-10									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous	X		X		X		X		X		X		X		X		X		X		
	Assumed ACBM	X	X	X	X	X		X		X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X	X	X	X	X		X		X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Main Building										Building # 01									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (main off, CR's 122,140,150 & strg)bge w/ wht & grey swirls -2732 ft²		12" VFT (stair landing) lt grn w/dark grn & white streaks -226 ft²		12" VFT (up & downstairs elevator) avocado green w/grey swirls -40 ft²		12" VFT (upstairs CR's 203, 213 216) bge w/white & grey swirls -1800 ft²		12" VFT (upstairs CR's 218,225,229,230,233)lt grn w/grn & wht swirls-3108 ft²		12" VFT (upstairs compu. corr./work rm.& HVAC) lt grn w/grn & wht swirls -270 ft²		12" VFT (corridor) green w/grey & white swirls -2928 ft²		12" Vinyl floor tile (storage room) bge w/ wht & grv swrl - 90 ft²		12" VFT (lab strg, science lab, CR's 235,237) bge w/ wht & gry swrl -1778 ft²		Terrazzo flooring (corridor) brn/blk /grey flecks -3632 ft²	
			No.	31-11	31-12	31-15	31-16	31-17	31-17	31-21	31-22	31-23	37-09									


Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																				
	Surfacing																				
	Miscellaneous	X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																				
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility																				
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week																				
	Maintenance																				
	Custodial																				
	Faculty/Students																				
Public																					
	Assessment Category																				



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Main Building										Building # 01												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Terrazzo flooring (B/G's & faculty RR & janitor closet) bm/blk /grey flecks -447 ft²		Terrazzo flooring (upstairs boys/ girls RR) bm/ blk /grey flecks -362 ft²		1 – Fire-door (stage area)		2 – Fire-doors (corridor)		4" Expansion joint (HVAC room) -10 Lf		4" Expansion joint (HVAC room) -10 Lf		4" Expansion joint (HVAC room)black -6 Lf		4" Expansion joint (HVAC room)black -6 Lf		4" Vinyl cove base (work room) lt brown - 158 Lf		4" Vinyl cove base (CR #'s 126,129,150) lt brown -384 Lf	
			No.	37-13	37-26	40-02	40-08	41-02	41-03	41-17	41-22	42-05	42-10									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Friable																					
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Main Building										Building # 01									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4" Vinyl cove base (CR #s 122,140 & storage) lt brown -224 Lf	4" Vinyl cove base (main office) lt brown - 4242 Lf	4" Vinyl cove base (CR #s 203,213,216) lt brown -294 Lf	4" Vinyl cove base (CR #s 218,225,229, 230, 233 & lib) lt brn -498 Lf	Sinks w/spray-on material (work room) black - 4	Vinyl stair treads – 360 ft <sup>2</sup>	5- 4" Expansion joint (HVAC room) white	9" VFT (Lab strg, science lab, CR's 235 & 237) drk brwn w/ orange streaks	Sinks w/spray-on material (Old Concess./Custodial room)	Sinks w/spray-on material (Library Work Room)
			No.	42-11	42-14	42-16	42-18	45-05	47-12	41-14	32-23	45-11


  

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing									X						X		X	
	Miscellaneous		X		X		X		X			X		X					
	Assumed ACBM	X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category				Determined To Be Yellow Mastic Non-ACBM.												Not Listed Originally. This Tile Is Underneath The 12" VFT – Could Be Through-out)		Not Listed In The Original Management Plan.	
																		Not Listed In The Original Management Plan.	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Band Hall										Building # 02												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (band room & offices) 2940 ft²		2x2 white-worm ceiling tile (restroom) 96 ft²		2x2 white-worm ceiling tile (band room storage) 520 ft²		Vinyl coated wood paneling (band room) - 848 ft²		Glue-down comm., carpet/mastic (band rm) dark blue w/ maroon & tan specks-2572 ft²		12" VFT (band room storage) beige w/brown & grey swirls -520 ft²		3 – Fire-doors (band room)							
			No.	10-01	10-02	10-03	25-01	30-01	31-03	40-01												
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X									
	Assumed ACBM		X		X		X		X	X	X		X	X	X							
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X	X	X		X	X	X							
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N									
Rate 1 To 5 5 is Worst	Deterioration		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.															
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.															
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.		"Armstrong" Ceiling Tile Is Non-ACBM.															
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category									Determined To Be Non-ACBM Yellow Mastic.		Covered W/ Glue-down Commer. Carpet.		Determined Not To Be Fire-doors.									

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Main Building (Basement)										Building # 03									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 vinyl coated sheetrock ceiling tile - 80 ft²	2x2 w/w ceiling tile (classrooms & storage) 1698 ft²	2x2 white-worm ceiling tile (basement storage) 232 ft²	12" VFT (classrooms & storage) beige w/brown streaks - 1698 ft²	12" Vinyl floor tile (restroom) beige w/brown streaks - 80 ft²								
			No.	09-04	10-01	10-02	31-01	31-04							

Inspection/Reinspection		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	

<b>Check one</b>	TSI																											
	Surfacing																											
	Miscellaneous		X		X		X		X		X		X															
	Assumed ACBM	X	X	X		X		X	X	X	X	X																
	Sampled/Tested																											
	Non ACBM																											
	ACBM																											
	Nonfriable	X	X	X		X		X	X	X	X	X																
	Friable																											

Assessment/Reassessment																												
Change in Condition? (Y/N)			N		N		N		N		N		N															

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																											
	Physical Damage																											
	Water Damage																											
	Activity/Vibration																											
	Exposure																											

<b>Length of Exposure</b>	Accessibility																											
	1 Hour/Week																											
	5 Hours/Week																											
	10 Hours/Week																											
	20 Hours/Week																											


  

<b>Check All That Apply</b>	40 Hours/Week																											
	Maintenance																											
	Custodial																											
	Faculty/Students																											
	Public																											


  

	Assessment Category																											
--	---------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Gym Building										Building # 04												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (lobby) - 560 ft²		2x2 white-worm ceiling tile (coach's office) - 160 ft²		2x2 white-worm ceiling tile (old locker room) - 304 ft²		2x2 white-worm ceiling tile (concession area) - 208 ft²		2x2 white-worm ceiling tile (lobby # 2) - 264 ft²		2x4 white-worm ceiling tile (boys/girls restroom) - 296 ft²		Transite wall panels (lobby entry doors) – 24 ft²		12" Vinyl floor tile (coach's office) lt grey w/ white swirls - 160 ft²		12" Vinyl floor tile (concession area) painted grey - 208 ft²		12" Vinyl floor tile (lobby # 2) lt grey w/ white & brown swirls - 264 ft²	
			No.	10-01	10-02	10-03	10-04	10-05	10-06	29-01	31-02	31-04	31-05									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X		X		X		X		X	
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.									
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.									
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.		Determined To Be "Armstrong" Non-ACBM.									
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category			Replaced W/New 12" VCT.		Replaced W/New 12" VCT.		Replaced W/New 12" VCT.		Replaced W/New 12" VCT.		Replaced W/New 12" VCT.		Replaced W/New 12" VCT.									

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Gym Building										Building # 04									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (boys locker room) ) lt grey w/ white swirls -638 ft²	8 – Fire-doors	5" Vinyl cove base (gym walls) black -356 Lf	White pipe insulation & Elbows (gym storage)- 38 Lf	2 – “Modine” Gas Ceiling Heater/ Linings								
		No.	31-09	40-01	42-07	48-08	56-07								

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI							X		X									
	Surfacing																		
	Miscellaneous		X		X		X												
	Assumed ACBM	X		X		X	X	X	X	X	X								
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X		X		X	X	X	X	X	X								
Friable																			


  

Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N		N		N		N									


  

<b>Check All That Apply</b>	<b>Rate 1 To 5 5 is Worst</b>	Deterioration	<b>Removed &amp; Replaced W/ Spray-on Floor.</b>	<b>Determined To Be Non-Fire-doors.</b>	<b>The Pipe Insulation Has Been Determined To Be Fiberglass But The Elbows Are Trowelled-on</b>	<b>Not Listed In The Original Management Plan.</b>													
		Physical Damage																	
		Water Damage																	
		Activity/Vibration																	
		Exposure																	
	<b>Length of Exposure</b>	Accessibility																	
		1 Hour/Week																	
		5 Hours/Week																	
		10 Hours/Week																	
		20 Hours/Week																	
<b>Public</b>	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
Assessment Category																			

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-19-11						Date Of Reinspection – 5-13-15												
LEA Name - St. Clair Co. Board of Education						LEA # 058												
School Name – Springville Middle School						School # 013												
Building Name – Special Education (Old 1940's Building)						Building # 05												
Address: 6601 US Hwy 11 Springville, Alabama 35146						Inspector's Name – Stan Eller												
						Signature - 												
						Alabama Accreditation No. – APL0514257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (through-out) - 1944 ft <sup>2</sup>	Vinyl coated wood paneling (through-out) - 1680 ft <sup>2</sup>	12" Vinyl floor tile (through-out) beige w/ grey - 1944 ft <sup>2</sup>													
			No.	10-01	25-01	31-01												
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing																	
	Miscellaneous		X		X		X											
	Assumed ACBM		X		X		X											
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable		X		X		X											
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			Y		Y		Y											
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
	40 Hours/Week																	
Check All That Apply	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
Assessment Category																		

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15						Date Of Reinspection – 5-25-18					
LEA Name - St. Clair Co. Board of Education						LEA # 058					
School Name – Springville Middle School						School # 013					
Building Name – Agri-Business Building						Building # 06					
Address: 6601 US Hwy 11 Springville, Alabama 35146						Inspector's Name – Stan Eller					
						Signature - 					
						Alabama Accreditation No. – APL0518257655					

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" ceiling tile (office) - 96 ft²	2x4 smooth white ceiling tile (classroom) - 620 ft²	2x4 white-worm ceiling tile (restroom) - 48 ft²	2x2 white-worm ceiling tile (restroom) - 24 ft²	12" VFT (CR & office) medium brown w/ red & white swirls - 716 ft²	12" VFT (corridor) medium brown w/ red & white swirls - 64 ft²	12" VFT (restroom) cream w/ gold & grey swirls - 72 ft²			
			No.	08-03	10-02	10-05	10-05A	31-02	31-04	31-05		

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now

<b>Check one</b>	TSI																	
	Surfacing																	
	Miscellaneous	X		X		X		X		X		X						
	Assumed ACBM	X	X	X		X	X	X	X	X	X	X	X	X				
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable	X	X	X		X	X	X	X	X	X	X	X	X				
	Friable																	

Assessment/Reassessment																		
Change in Condition? (Y/N)		N		N		N		N		N		N		N				

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	

<b>Length of Exposure</b>	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	

<b>Check All That Apply</b>	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category																	


		Replaced W/ New 2x2 Ceiling Tile															


--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Springville Middle School										School # 013												
Building Name – Pine Street Building										Building # 07												
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (library) - 880 ft²		2x4 white-worm ceiling tile (restroom) - 36 ft²		2x4 white-worm ceiling tile (electric room) - 91 ft²		2x4 w/w ceiling tile (computer storage @ 8 ft & lobby office)-2107 ft²		2x4 textured ceiling tile (computer storage @ 9 ft)-144 ft²		2x2 white-worm ceiling tile (stairs)-104 ft²		2x2 w/w ceiling tile (upstairs boys/girls restroom) - 440 ft²		2x2 w/w ceiling tile (CR's 7,8,10,12,13, 15-18) lt grey w/blk & wht streaks - 6048 ft²		2x2 white-worm ceiling tile (classrooms 9 & 14) - 1344 ft²		2x4 white pin-point (offices & office corridor) - 1248 ft²	
			No.	10-01	10-02	10-03	10-04	10-04A	10-07	10-08	10-11	10-12	10-13									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Pine Street Building										Building # 07									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (corridor) -1188 ft²		2x4 white-worm ceiling tile (classroom #'s 20-23) -3360 ft²		2x2 white-worm ceiling tile (boys/girls restroom) -320 ft²		8" Ceramic wall tile/grout (boys/girls restroom) -580 ft²		Transite panels (entrance @ front door) - 8 ft²		Transite panels (above windows @ classroom #'s 20-23) - ? ft²		12" VFT (comp. off. Strg, nurses off., corr.) lt brn w/crm & bronze swirls -1735 ft²		12" VFT (lobby office) lt brn w/cream & bronze swirls -372 ft²		12" VFT (upstairs CR's 9,11 &14) mauve w/white & bronze swirls -2016 ft²		12" VFT (upstairs offs & office corr.) med brwn w/red & wht swirls-1248 ft²	
			No.	10-14	10-15	10-16	28-16	29-05	29-15	31-04	31-04	31-12	31-13									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Pine Street Building										Building # 07									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (upstairs corridor) gold w/ red & white swirls -1188 ft²		12" VFT (upstairs CR's 20-23) med gm w/ drk gen & wht swirls -3360 ft²		9" VFT (upstairs CR's 7,8,10,12, 13, 15-18) lt grey w/blk & wht streaks -6048 ft²		9" VFT (corr.) lt grey w/blk & white streaks -1188 corr. ft²		1" & 2" Cer. floor tile/grout (girls RR) tan & dark brown -220 ft²		1" & 2" Ceramic floor tile/grout (boys RR) green & white -220 ft²		1" & 2" Ceramic floor tile/grout (boys / girls RR) lt tan -320 ft²		6" Red quarry floor tile/grout (library) -1050 ft²		6" Red quarry floor tile/grout (restroom) -36 ft²		6" Red quarry floor tile/grout (front corridor & stairs) -300 ft²	
			No.	31-14	31-15	32-11	32-14	35-08	35-09	35-16	38-01	38-02	38-05									

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																					
	Surfacing																					
	Miscellaneous	X		X		X		X		X		X		X		X		X		X		
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)		N		N		N		N		N		N		N		N		N		N		
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-25-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Springville Middle School										School # 013									
Building Name – Pine Street Building										Building # 07									
Address: 6601 US Hwy 11 Springville, Alabama 35146										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4" Vinyl cove base (offices & office corridor) tan w/ white-196 Lf																
				No.	42-13														

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous	X																		
	Assumed ACBM																			
	Sampled/Tested																			
	Non ACBM	X																		
	ACBM																			
	Nonfriable	X																		
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)		N																		
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
	40 Hours/Week																			
Check All That Apply	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
	Assessment Category																			

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.**  
**Ruben Yancey Alternative School**  
**466 - 10<sup>th</sup> St.**  
**Ashville, AL 35953**

**REINSPECTION DATE:** 5/23/18

**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL051857655


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**


All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15						Date Of Reinspection – 5-23-18						
LEA Name - St. Clair Co. Board of Education						LEA # 058						
School Name – Ruben Yancy Alternative School						School # 015						
Building Name – Main Building						Building # 01						
Address: 466 – 10 <sup>th</sup> Street Ashville, Alabama 35953						Inspector's Name – Stan Eller						
						Signature - 						
						Alabama Accreditation No. – APL0518257655						
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (office & corridor) - 2019 ft <sup>2</sup>	2x4 white-worm ceiling tile (closet) - 240 ft <sup>2</sup>	2x4 white-worm ceiling tile (storage) - 96 ft <sup>2</sup>	Transite wall panels (end of corridors)	Glue-down comm.. carpet /mastic (strg) wood plank pattern - 96 ft <sup>2</sup>	12" VFT (office & corr) lt grn w/wht&green swirls -2019 ft <sup>2</sup>	12" VFT (CR's 4,5&7) beige w/grey&green swirls -2160 ft <sup>2</sup>	12" VFT (closet) beige w/brown streaks -240 ft <sup>2</sup>	9" VFT (elec. rm @ end of stage) crm w/ mauve & blu strks -240 ft <sup>2</sup>	9" VFT (off. closets & CR's 1-3 & 6-8) cream w/ tan strks -3616 ft <sup>2</sup>
			No.	10-04	10-07	10-09	29-04	30-09	31-04	31-06	31-07	32-03
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI											
	Surfacing											
	Miscellaneous		X		X		X		X		X	
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X
	Sampled/Tested											
	Non ACBM											
	ACBM											
	Nonfriable		X	X	X	X	X	X	X	X	X	X
	Friable											
Assessment/Reassessment												
Change in Condition? (Y/N)			N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration											
	Physical Damage											
	Water Damage											
	Activity/Vibration											
	Exposure											
Length of Exposure	Accessibility											
	1 Hour/Week											
	5 Hours/Week											
	10 Hours/Week											
	20 Hours/Week											
Check All That Apply	40 Hours/Week											
	Maintenance											
	Custodial											
	Faculty/Students											
Public												
Assessment Category			<div>Not Armstrong or USG (Unidentified)</div> <div>Replaced W/New.</div> <div>Various Replacement Patches W/ 5 SF Exposed Mastic.</div> <div>Classrooms 7 &amp; 8 Covered W/ 12" VCT.</div>									

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ruben Yancy Alternative School										School # 015									
Building Name – Main Building										Building # 01									
Address: 466 – 10 <sup>th</sup> Street Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" Vinyl floor tile (storage) -96 ft <sup>2</sup>	1" & 2" Cer. floor tile/grout (boys RR) tan & brown -168 ft <sup>2</sup>	1" & 2" Ceramic floor tile/grout (girls RR) grn & dark grn -184 ft <sup>2</sup>	2" Expansion joint (elec. room @ end of stage) black - 7 Lf	Boiler brick (basement boiler room)	9" Vinyl floor tile (Under 12" VFT @ Office & Hall) -2019 ft <sup>2</sup>						
			No.	32-09	35-10	35-11	41-03	54-12	32-03					

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing																	
	Miscellaneous		X		X		X		X		X							
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X						
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable		X	X	X	X	X	X	X	X	X	X						
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)				N		N		N		N		N						
Rate 1 To 5 5 is Worst	Deterioration																	
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility																	
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week																	
	Maintenance																	
	Custodial																	
	Faculty/Students																	
	Public																	
	Assessment Category																	

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ruben Yancy Alternative School										School # 015									
Building Name – Book Room Building										Building # 02									
Address: 466 – 10 <sup>th</sup> Street Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x2 white-worm ceiling tile (high school book room) - 528 ft <sup>2</sup>	2x2 white-worm ceiling tile (elementary book room) - 960 ft <sup>2</sup>	12" Vinyl floor tile (elem. book room) 1t grn w/ grey swirls -960 ft <sup>2</sup>	"Modine" Gas Ceiling Heater / Lining													
			No.	10-01	10-03	31-03	51-01												

Inspection/Reinspection			Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	
Check one	TSI																													
	Surfacing																													
	Miscellaneous		X		X		X		X		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X	X	X	X																					
	Sampled/Tested																													
	Non ACBM																													
	ACBM																													
	Nonfriable	X	X	X	X	X	X	X	X																					
Friable																														
Assessment/Reassessment																														
Change in Condition? (Y/N)			N		N		N		N																					
Rate 1 To 5 5 is Worst	Deterioration									Not Listed In The Original Management Plan.																				
	Physical Damage																													
	Water Damage																													
	Activity/Vibration																													
	Exposure																													
Length of Exposure	Accessibility																													
	1 Hour/Week																													
	5 Hours/Week																													
	10 Hours/Week																													
	20 Hours/Week																													
Check All That Apply	40 Hours/Week																													
	Maintenance																													
	Custodial																													
	Faculty/Students																													
	Public																													
Assessment Category																														



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ruben Yancy Alternative School										School # 015									
Building Name – Day Program Building										Building # 03									
Address: 466 – 10 <sup>th</sup> Street Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 vinyl coated fiberglass ceil. tile(storage) 96 ft <sup>2</sup>		2x4 vinyl coated fiberglass ceil. tile(offices, lobby, CR's & conf rm) 2710 ft <sup>2</sup>		2x2 w/w ceiling tile (corr, counselor off., & counselor rms) 816 ft <sup>2</sup>		Drywall (counselor office)- 232 ft <sup>2</sup>		Drywall (offices & lobby)- 896 ft <sup>2</sup>		Vinyl coated wood paneling (offices & lobby)- 320 ft <sup>2</sup>		12" VFT (corr., counselor off.) beige w/grey marbled -256 ft <sup>2</sup>		12" VFT (off, lobby & conf. rm) beige w/grey marbled -2710 ft <sup>2</sup>		12" VFT (RR adjacent conf. room) white w/green swirls - 20 ft <sup>2</sup>		12" VFT (counselor rooms) beige w/grey marbled -560 ft <sup>2</sup>	
			No.	07-02	07-03	10-01	22-01	22-03	25-03	31-01	31-03	31-04	31-05									

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing								X		X											
	Miscellaneous		X		X		X						X		X		X		X		X	
	Assumed ACBM	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-13-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Ruben Yancy Alternative School										School # 015									
Building Name – Day Program Building										Building # 03									
Address: 466 – 10 <sup>th</sup> Street Ashville, Alabama 35953										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	9" VFT (Possibly Thru-out) dark brwn w/ yellow streaks - 2966 ft <sup>2</sup>																
				No.	32-04														

Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																			
	Surfacing																			
	Miscellaneous	X																		
	Assumed ACBM	X	X																	
	Sampled/Tested																			
	Non ACBM																			
	ACBM																			
	Nonfriable	X	X																	
Friable																				
Assessment/Reassessment																				
Change in Condition? (Y/N)		N																		
Rate 1 To 5 5 is Worst	Deterioration																			
	Physical Damage																			
	Water Damage																			
	Activity/Vibration																			
	Exposure																			
Length of Exposure	Accessibility																			
	1 Hour/Week																			
	5 Hours/Week																			
	10 Hours/Week																			
	20 Hours/Week																			
Check All That Apply	40 Hours/Week																			
	Maintenance																			
	Custodial																			
	Faculty/Students																			
	Public																			
Assessment Category																				

Stan Eller, Asbestos Inspector  
752 Myrick Rd., Deatsville, AL 36022

Cell Phone: 334-315-2892

**LEA: St. Clair Co. B.O.E.  
Coal City Head Start  
Route 1  
Ragland, AL 35131**

**REINSPECTION DATE:** 5/24/18  
**INSPECTOR:** Stan Eller

**ACCREDITATION NO.:** APL0518257655


**SIGNATURE:** 

**COMMENTS AND INSTRUCTIONS:**

All changes are noted on the inspection forms. All suspect and known ACBM was visually inspected and touched. All material was in good shape. The following items are noteworthy and should receive immediate attention:

- Two-hour training for custodial personnel should be accomplished as needed.
- Notification letter should be sent annually to all building occupants, including students.
- All renovation and remodeling should be done with full knowledge of the suspected ACBM being given to any contractor accomplishing work.
- All workers/contractors should be required to furnish letter of proof that no ACBM was used in remodeling or replacement of any material.
- This three-year inspection will serve as your six-month inspection.
- **Any demolition or remodeling that is done should be cleared with the asbestos inspector to determine if sampling should be done before work is accomplished.**


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Main Building										Building # 01									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" Perforated ceiling tile (boys/girls RR- above 2x4 C.T.) - 462 ft²		12" Perforated ceiling tile (stage storage) - 70 ft²		12" Perforated ceiling tile (principal's office- above 2x2 C.T.) - 154 ft²		12" Perforated ceiling tile (office storage)- 60 ft²		2x4 white-worm ceiling tile (classroom # 1) - 748 ft²		2x4 white-worm ceiling tile (CR # 2 & corridor) - 1942 ft²		2x4 white-worm ceiling tile (CR #'s 3&4, boys/girls RR) - 1958 ft²		2x4 white-worm ceiling tile (secretary office) - 56 ft²		2x4 white-worm ceiling tile (water heater closet) - 21 ft²		2x2 white-worm ceiling tile (office) - 154 ft²	
			No.	08-03	08-10	08-13	08-14	10-01	10-02	10-03	10-04	10-05	10-07									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now		
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X			
	Assumed ACBM		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X		
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N			
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
Check All That Apply	40 Hours/Week																					
	Maintenance																					
	Custodial																					
	Faculty/Students																					
Public																						
	Assessment Category																					

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Main Building										Building # 01									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


  

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	2x4 white-worm ceiling tile (cafe) - 1600 ft²	2x4 white-worm ceiling tile (stage) - 506 ft²	2x2 white-worm ceiling tile (principal's office) - 154 ft²	Transite/cellulose ceiling panel (corr. – 2 ft above 2x4 C.T.) - 1194 ft²	Transite/cellulose ceiling panel (stage – 2 ft above 2x4 C.T.) - 506 ft²	Drywall ceiling (lunchrm, serving area, wash-rm, kitchen) - 876 ft²	Drywall (classroom # 2 – above windows) - 96 ft²	Drywall (stage storage) - 264 ft²	4" Ceramic wall tile/grout (boys/girls RR) white w/ grn specks - 650 ft²	Glue-down comm. carpet/mastic (CR # 1) grey diamond pattern - 748 ft²
			No.	10-08	10-09	10-13	11-02	11-09	14-11	22-02	22-10	28-03


  

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing											X		X		X			
	Miscellaneous		X		X		X		X		X						X		X
	Assumed ACBM	X	X	X	X	X	X					X	X	X	X	X	X	X	X
	Sampled/Tested							X		X									
	Non ACBM																		
	ACBM							X	X	X	X								
	Nonfriable	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category																			

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

<b>Alabama Asbestos Management Program AHERA Reinspection Form</b>																						
Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18												
LEA Name - St. Clair Co. Board of Education										LEA # 058												
School Name – Coal City Head Start										School # 025												
Building Name – Main Building										Building # 01												
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller												
										Signature - 												
										Alabama Accreditation No. – APL0518257655												
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	12" VFT (secretary off.) beige w/brown & white streaks -56 ft <sup>2</sup>		12" VFT (water heater closet) beige w/bm & white streaks -21 ft <sup>2</sup>		12" VFT (janitor closet) beige w/brown & white streaks -20 ft <sup>2</sup>		12" VFT (office) beige w/brown & white streaks -154 ft <sup>2</sup>		12" VFT (Café & Corr.) beige w/brown & white streaks -2878 ft <sup>2</sup>		12" VFT (LR serving area, wash rm, kitch) bge w/bm & wht streaks -990 ft <sup>2</sup>		12" VFT (principal's office) bge w/bm & wht streaks -154 ft <sup>2</sup>		12" VFT (office storage) bge w/bm & wht streaks -60 ft <sup>2</sup>		Sheet rolled vinyl floor (Classrooms 2-4) tan - 2160 ft <sup>2</sup>		6" Red quarry floor tile/grout w/6" wainscot (boys/girls RR) -462 ft <sup>2</sup>	
			No.	31-04	31-05	31-06	31-07	31-08	31-11	31-13	31-14	36-02	38-03									
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																					
	Surfacing																					
	Miscellaneous		X		X		X		X		X		X		X		X		X		X	
	Assumed ACBM		X		X		X		X		X		X		X		X		X		X	
	Sampled/Tested																					
	Non ACBM																					
	ACBM																					
	Nonfriable		X		X		X		X		X		X		X		X		X		X	
Friable																						
Assessment/Reassessment																						
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N		N		N	
Rate 1 To 5 5 is Worst	Deterioration																					
	Physical Damage																					
	Water Damage																					
	Activity/Vibration																					
	Exposure																					
Length of Exposure	Accessibility																					
	1 Hour/Week																					
	5 Hours/Week																					
	10 Hours/Week																					
	20 Hours/Week																					
	40 Hours/Week																					
Check All That Apply	Maintenance																					
	Custodial																					
	Faculty/Students																					
	Public																					
Assessment Category																						

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Main Building										Building # 01									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	4" Vinyl cove base/mastic (corridor) - 326 Lf	4" Vinyl cove base/mastic (lunchroom serving area) - 50 Lf	2" Pipe insulation (boiler-room, wash-room, kitchen) - 102 Lf	9" VFT (Under 12" VFT @ Corridor, Café & Possibly Classrooms)	6" Light Fixture Heat Shield (Back Porch @ Kitchen)	Window Caulking (Corridor Windows)	Glue-dots (Bulletin Boards)						
			No.	42-02	42-11	48-12	32-08	50-01	49-01	60-01					

Inspection/Reinspection			Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	


  

<b>Check one</b>	TSI																													
	Surfacing																													
	Miscellaneous		X		X					X		X		X		X														
	Assumed ACBM	X	X	X	X					X	X	X	X	X	X	X	X													
	Sampled/Tested						X																							
	Non ACBM						X																							
	ACBM																													
	Nonfriable	X	X	X	X	X				X	X	X	X	X	X	X	X													
	Friable																													
Assessment/Reassessment																														
Change in Condition? (Y/N)			N		N		N		N		N		N		N		N													

<b>Rate 1 To 5 5 is Worst</b>	Deterioration																												
	Physical Damage																												
	Water Damage																												
	Activity/Vibration																												
	Exposure																												
<b>Length of Exposure</b>	Accessibility																												
	1 Hour/Week																												
	5 Hours/Week																												
	10 Hours/Week																												
	20 Hours/Week																												
<b>Check All That Apply</b>	40 Hours/Week																												
	Maintenance																												
	Custodial																												
	Faculty/Students																												
	Public																												
	Assessment Category																												

**Alabama Asbestos Management Program  
AHERA Reinspection Form**


Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Portable Storage # 1										Building # 02									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									


List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Popcorn Ceiling (Classroom) -585 ft <sup>2</sup>		Vinyl Coated Sheetrock Wall Panels (Classroom) -812 ft <sup>2</sup>		12" Vinyl floor tile (Classroom) lt. brown marbled- 585 ft <sup>2</sup>											
			No.	15-01	22-01	31-01												
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																	
	Surfacing		X															
	Miscellaneous				X		X											
	Assumed ACBM		X	X	X	X	X	X										
	Sampled/Tested																	
	Non ACBM																	
	ACBM																	
	Nonfriable		X	X	X	X	X	X										
Friable																		
Assessment/Reassessment																		
Change in Condition? (Y/N)			N		N		N											
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.											
	Physical Damage																	
	Water Damage																	
	Activity/Vibration																	
	Exposure																	
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.											
	1 Hour/Week																	
	5 Hours/Week																	
	10 Hours/Week																	
	20 Hours/Week																	
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.											
	Maintenance																	
	Custodial																	
	Faculty/Students																	
Public																		
Assessment Category																		



**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18											
LEA Name - St. Clair Co. Board of Education										LEA # 058											
School Name – Coal City Head Start										School # 025											
Building Name – Portable Storage # 2 (1993 Bldg.)										Building # 03											
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller											
										Signature - 											
										Alabama Accreditation No. – APL0518257655											
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Popcorn Ceiling (Classrooms & Hall) - 4785 ft <sup>2</sup>		Vinyl Coated Sheetrock Wall Panels (CR's & Hall) - 4424 ft <sup>2</sup>		Sheet Vinyl floor (Classrooms & Hall) 4785 ft <sup>2</sup>														
			No.	15-01	22-01	36-01															
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now			
Check one	TSI																				
	Surfacing		X																		
	Miscellaneous				X		X														
	Assumed ACBM		X	X	X	X	X	X													
	Sampled/Tested																				
	Non ACBM																				
	ACBM																				
	Nonfriable		X	X	X	X	X	X													
Friable																					
Assessment/Reassessment																					
Change in Condition? (Y/N)			N		N		N														
Rate 1 To 5 5 is Worst	Deterioration		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan. Covered W/ New 12" VFT.														
	Physical Damage																				
	Water Damage																				
	Activity/Vibration																				
	Exposure																				
Length of Exposure	Accessibility		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan. Covered W/ New 12" VFT.														
	1 Hour/Week																				
	5 Hours/Week																				
	10 Hours/Week																				
	20 Hours/Week																				
Check All That Apply	40 Hours/Week		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan. Covered W/ New 12" VFT.														
	Maintenance																				
	Custodial																				
	Faculty/Students																				
Public																					
Assessment Category																					

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-23-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Portable Storage # 3 (1994 Bldg.)										Building # 04									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Popcorn Ceiling (Classroom) - 1540 ft <sup>2</sup>	Vinyl Coated Sheetrock Wall Panels (Classrooms) - 1596 ft <sup>2</sup>	12" Vinyl floor tile (Classrooms) lt. gray marbled - 1540 ft <sup>2</sup>													
			No.	15-01	22-01	31-01												

Inspection/Reinspection			Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now		Prev.		Now	

<b>Check one</b>	TSI																													
	Surfacing		X																											
	Miscellaneous				X		X																							
	Assumed ACBM	X	X	X	X	X	X																							
	Sampled/Tested																													
	Non ACBM																													
	ACBM																													
	Nonfriable	X	X	X	X	X	X																							
	Friable																													

Assessment/Reassessment																														
Change in Condition? (Y/N)		N		N		N																								

<b>Rate 1 To 5 5 is Worst</b>	Deterioration	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan. <b>Covered W/ New Glue-down Carpet.</b>																										
	Physical Damage																													
	Water Damage																													
	Activity/Vibration																													
	Exposure																													


  

<b>Length of Exposure</b>	Accessibility	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan. <b>Covered W/ New Glue-down Carpet.</b>																										
	1 Hour/Week																													
	5 Hours/Week																													
	10 Hours/Week																													
	20 Hours/Week																													
	40 Hours/Week																													


  

<b>Check All That Apply</b>	Maintenance	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan.	Not Listed In The Original Management Plan. <b>Covered W/ New Glue-down Carpet.</b>																										
	Custodial																													
	Faculty/Students																													
	Public																													
	Assessment Category																													


**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Portable Storage # 4 (2005 Bldg.)										Building # 05									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Popcorn Ceiling (Classroom) - 3480 ft²		Vinyl Coated Sheetrock Wall Panels (Classrooms) - 3332 ft²		12" Vinyl floor tile (CR's) lt. gray & tan marbled - 3480 ft²												
			No.	15-01	22-01	31-01													
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																		
	Surfacing		X																
	Miscellaneous				X		X												
	Assumed ACBM		X	X	X	X	X	X											
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable		X	X	X	X	X	X											
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)			N		N		N												
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category			Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.												

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Portable # 5 (Future Classroom)										Building # 06									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
										Alabama Accreditation No. – APL0518257655									
<b>Removed</b>																			
List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Coated Sheetrock Ceiling (Classrooms) - 1320 ft <sup>2</sup>		Vinyl Coated Sheetrock Wall Panels (Classrooms) - 1988 ft <sup>2</sup>														
			No.	15-01	22-01														
Inspection/Reinspection			Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	
Check one	TSI																		
	Surfacing																		
	Miscellaneous		X		X														
	Assumed ACBM		X	X	X	X													
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable		X	X	X	X													
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)			N		N														
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category			Not Listed In The Original Management Plan.			Not Listed In The Original Management Plan.													

**Alabama Asbestos Management Program  
AHERA Reinspection Form**

Date of Previous Inspection – 5-15-15										Date Of Reinspection – 5-24-18									
LEA Name - St. Clair Co. Board of Education										LEA # 058									
School Name – Coal City Head Start										School # 025									
Building Name – Portable # 6 (Future Classroom)										Building # 07									
Address: Route 1 Ragland, Alabama 35131										Inspector's Name – Stan Eller									
										Signature - 									
<b>Removed</b>										Alabama Accreditation No. – APL0518257655									

List all homogeneous areas included in the previous inspection that contained asbestos or were assumed to contain asbestos.	Homogeneous Area	Description	Vinyl Coated Sheetrock Ceiling (Classrooms) - 1320 ft <sup>2</sup>	Vinyl Coated Sheetrock Wall Panels (Classrooms) - 1988 ft <sup>2</sup>													
			No.	15-01	22-01												

Inspection/Reinspection		Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now	Prev.	Now
Check one	TSI																		
	Surfacing																		
	Miscellaneous		X		X														
	Assumed ACBM	X	X	X	X														
	Sampled/Tested																		
	Non ACBM																		
	ACBM																		
	Nonfriable	X	X	X	X														
Friable																			
Assessment/Reassessment																			
Change in Condition? (Y/N)		N		N															
Rate 1 To 5 5 is Worst	Deterioration																		
	Physical Damage																		
	Water Damage																		
	Activity/Vibration																		
	Exposure																		
Length of Exposure	Accessibility																		
	1 Hour/Week																		
	5 Hours/Week																		
	10 Hours/Week																		
	20 Hours/Week																		
Check All That Apply	40 Hours/Week																		
	Maintenance																		
	Custodial																		
	Faculty/Students																		
	Public																		
Assessment Category		Not Listed In The Original Management Plan.		Not Listed In The Original Management Plan.															