

## Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

**PLEASE NOTE:** Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
1 CAD #:	H1C	Sprayed-On Structural Fireproofing Tan w/Vermiculite	THROUGHOUT BUILDING	3000 Sq Ft	Y	10 CH	5
Comments: ESTIMATED BEHIND SHEETROCK PERIMETER WALLS & CHASES. SOME RESIDUE VISIBLE ABOVE CEILING & AT PERIMETER CHASES.					Sample #: 101408ML-34		
14 CAD #:	X0G	Miscellaneous Material Cream Ceiling Tile Perimeter Grid Adhesive	THROUGHOUT BUILDING	200 Sq Ft	N	3 CH	5
Comments: ABOVE CEILING AT PREVIOUS CEILING TILE GRID LOCATIONS.					Sample #: 101408ML-32		
23 CAD #:	V0B	Sink Undercoating Pink	MAIN OFFICE WORK ROOM 1007	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 101408ML-22		
26 CAD #:	X1A	Miscellaneous Material 6" X 6" White Ceramic Wall Tile System	RESTROOMS 1101 & 1102	240 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
27 CAD #:	X1B	Miscellaneous Material 6" X 6" Quarry Tile System Gray with Red Specks	RESTROOMS 1101 & 1102	108 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
31 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1105	850 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: INCLUDES 12 SQ FT OF REPLACEMENT TILE AT EAST WALL. TILE SHOWING SIGNS OF WEAR THROUGHOUT.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
32 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1105	1 Sq Ft	N	5 CH	5
Comments:					Sample #:		
33 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1106	230 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: RECOMMEND SEALING WITH WAX AND INSTALLING CHAIR MATS.					Sample #:		
34 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1106	1 Sq Ft	N	5 CH	5
Comments:					Sample #:		
35 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	STORAGE 1107	230 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: MOST IS COVERED UP BY STORAGE ITEMS.					Sample #:		
36 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	STORAGE 1107	2 Sq Ft	N	5 CH	5
Comments:					Sample #:		
43 CAD #:	K3B	Miscellaneous Flooring Black Flooring Mastic (1973)	ENTRY TO ROOMS 1112 & 1113	35 Sq Ft	N	10 CH	5
Comments: RESIDUAL REMAINS UNDER CARPET.					Sample #:		
45 CAD #:	K3B	Miscellaneous Flooring Black Flooring Mastic (1973)	ROOM 1112	350 Sq Ft	N	10 CH	5
Comments: UNDER CARPET.					Sample #: 101408ML-17		
47 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1112	50 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: UNDER K3D.					Sample #: 101408ML-19		
48 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1112	3 Sq Ft	N	5 CH	5
Comments:					Sample #:		
51 CAD #:	K3B	Miscellaneous Flooring Black Flooring Mastic (1973)	ROOM 1113	350 Sq Ft	N	10 CH	5
Comments: UNDER CARPET.					Sample #:		
53 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1113	50 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: UNDER K3D.					Sample #:		
54 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1113	2 Sq Ft	N	5 CH	5
Comments:					Sample #:		
57 CAD #:	I3A	2' x 4' Ceiling Tile Unfinished Texture	GYMNASIUM 1201/1202	2500 Sq Ft	Y	ASSUMED	5
Comments: NEED LIFT TO SAMPLE. GLUED TO ROOF DECK & WALL.					Sample #:		
58 CAD #:	W3A	2' x 4' Ceiling Tile Adhesive Associated w/I3A	GYMNASIUM 1201/1202	625 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
60 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	GYMNASIUM 1201/1202	4200 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: CRACKED & CHIPPED AROUND PERIMETER. SOME EXPOSED MASTIC. SCRATCHES & DENTS THROUGHOUT. SEALED WITH WAX.					Sample #:		
61 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	GYMNASIUM 1201/1202	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
64 CAD #:	X0B	Miscellaneous Material AHU Seam Tar	NORTH GYMNASIUM MECHANICAL ROOM 1201B	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
65 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	NORTH GYMNASIUM MECHANICAL ROOM 1201B	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
67 CAD #:	X0B	Miscellaneous Material AHU Seam Tar	SOUTH GYMNASIUM MECHANICAL ROOM 1202B	10 Sq Ft	N	5 CH	5
Comments:					Sample #: 101408ML-13		
68 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	SOUTH GYMNASIUM MECHANICAL ROOM 1202B	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
71 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	CLASSROOM POD SOUTH OF GYMNASIUM - SOUTH ENTRY	2 Sq Ft	N	5 CH	5
Comments: AT VESTIBULE.					Sample #:		
72 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1401	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
73 CAD #:	V0B	Sink Undercoating Pink	CLASSROOM 1401	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
74 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1402	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
75 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1403	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
76 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1404	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
77 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1405	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
78 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1407	1 Sq Ft	N	5 CH	5
Comments: DOOR.					Sample #:		
79 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1407	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
80 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1408	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
84 CAD #:	K3B	Miscellaneous Flooring Black Flooring Mastic (1973)	CAFETERIA 1500	260 Sq Ft	N	10 CH	5
Comments: ASSUMED PERIMETER EDGE UNDER 12" TILE HAS RESIDUAL MASTIC. VERIFY IN ALL LOCATIONS PRIOR TO DISTURBANCE.					Sample #:		
86 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	HALLWAY 1300A	2 Sq Ft	N	5 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
87 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1301	2 Sq Ft	N	5 CH	5
Comments:				Sample #:			
88 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1301A	150 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: <u>SCRATCHES UNDERNEATH VENDING MACHINES.</u>				Sample #:			
89 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1301A	4 Sq Ft	N	5 CH	5
Comments:				Sample #: 101408ML-27			
90 CAD #:	V0C	Sink Undercoating Black	ROOM 1301A	4 Sq Ft	N	10 CH	5
Comments: <u>ONE (1) SINK.</u>				Sample #: 101408ML-24			
91 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1302	2 Sq Ft	N	5 CH	5
Comments:				Sample #:			
92 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1303	4 Sq Ft	N	5 CH	5
Comments:				Sample #:			
94 CAD #:	X0D	Miscellaneous Material Brass Colored Frame Chalkboard Adhesive	ROOM 1321	20 Sq Ft	N	ASSUMED	5
Comments:				Sample #:			
97 CAD #:	V0B	Sink Undercoating Pink	ROOM 1318	6 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) SINK.</u>				Sample #:			
99 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	CUSTODIAL CLOSET 1304	4 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: <u>TILE REMAINS UNDER HEATER.</u>				Sample #:			
103 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Tan Streaks	ROOM 1317	680 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: <u>UNDER CARPET.</u>				Sample #:			
104 CAD #:	X0D	Miscellaneous Material Brass Colored Frame Chalkboard Adhesive	ROOM 1317	20 Sq Ft	N	ASSUMED	5
Comments:				Sample #:			
105 CAD #:	V0B	Sink Undercoating Pink	ROOM 1317	6 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) SINK.</u>				Sample #:			
107 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	ROOM 1316	7 Sq Ft	N	5 CH	5
Comments: <u>INCLUDES WINDOW BETWEEN 1315/1316.</u>				Sample #:			
108 CAD #:	X0D	Miscellaneous Material Brass Colored Frame Chalkboard Adhesive	ROOM 1316	20 Sq Ft	N	ASSUMED	5
Comments:				Sample #:			
109 CAD #:	V0B	Sink Undercoating Pink	ROOM 1316	4 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) SINK.</u>				Sample #:			
111 CAD #:	X0D	Miscellaneous Material Brass Colored Frame Chalkboard Adhesive	ROOM 1315	20 Sq Ft	N	ASSUMED	5
Comments:				Sample #:			

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
113 CAD #:	V0B	Sink Undercoating Pink	ROOM 1315	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
116 CAD #:	X0E	Miscellaneous Material Black Ceiling Tile Perimeter Grid Mastic	ROOM 1311	20 Sq Ft	N	5 CH	5
Comments: ABOVE CEILING AT PREVIOUS CEILING TILE GRID LOCATION.					Sample #: 101408ML-31		
118 CAD #:	X0D	Miscellaneous Material Brass Colored Frame Chalkboard Adhesive	ROOM 1311	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
119 CAD #:	V0B	Sink Undercoating Pink	ROOM 1311	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
122 CAD #:	X0A	Miscellaneous Material Air Handler Seam Gasket	PENTHOUSE AIR HANDLER ROOM 2301	100 Sq Ft	N	5 CH	5
Comments: ACCESS THROUGH CUSTODIAL CLOSET 1308 NEAR RESTROOM 1309.					Sample #: 101408ML-01		
123 CAD #:	X0B	Miscellaneous Material AHU Seam Tar	PENTHOUSE AIR HANDLER ROOM 2301	25 Sq Ft	N	5 CH	5
Comments: ACCESS THROUGH CUSTODIAL CLOSET 1308 NEAR RESTROOM 1309.					Sample #: 101408ML-12		
124 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	HALLWAY 1600	8 Sq Ft	N	5 CH	5
Comments:					Sample #:		
127 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	SOUTHEAST CLASSROOM POD	10 Sq Ft	N	5 CH	5
Comments: NORTH & SOUTH ENTRYWAYS.					Sample #:		
128 CAD #:	X0C	Miscellaneous Material Wired Window Glaze	LAUNDRY ROOM 1601	2 Sq Ft	N	5 CH	5
Comments:					Sample #:		
129 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1610	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
130 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1609	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
131 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1608	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
132 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1607	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
133 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1605	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
134 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1604	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		
135 CAD #:	V0C	Sink Undercoating Black	CLASSROOM 1603	8 Sq Ft	N	10 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
136 CAD #:	VOC	Sink Undercoating Black	CLASSROOM 1602	8 Sq Ft	N	10 CH	5

Comments: ONE (1) DOUBLE SINK.

Sample #: