

## Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

**PLEASE NOTE:** Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
10 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive	THROUGHOUT BUILDING	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
18 CAD #:	D2A	Interior Boiler Insulation Boiler #1	BOILER ROOM 0116	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
20 CAD #:	D2B	Interior Boiler Insulation Boiler #2	BOILER ROOM 0116	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
21 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	BOILER ROOM 0116	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
23 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1961 Original Building	BASEMENT SOUTH ENTRANCE HALLWAY 0100B	5 Joints	N	30 CH, 20 AM	5
Comments: ESTIMATED. ABOVE PLASTER CEILING. INACCESSIBLE FOR REMOVAL.					Sample #: ACB-450BA-A17		
25 CAD #:	X1A	Miscellaneous Material 6" Red Quarry Tile	KITCHEN COOLER 0206	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
33 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	BASEMENT STAIRWELL/ENTRANCE 0299B	500 Sq Ft	N	ASSUMED	5
Comments: STAIRWELL 0299C, 0199D, STAGE STAIRS 1100A, 1199A.							Sample #:
37 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 0107	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.							Sample #:
43 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 0106	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.							Sample #:
45 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	BASEMENT STAIRWELL/ENTRANCE 0299C	500 Sq Ft	N	ASSUMED	5
Comments:							Sample #:
48 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 0105	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.							Sample #:
55 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 0104	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.							Sample #:
59 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1961 Original Building	CAFETERIA 0201	10 Joints	N	30 CH, 20 AM	5
Comments: ESTIMATED IN PERIMETER SOFFIT. INACCESSIBLE FOR REMOVAL.							Sample #:
61 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	DISCOVERY ROOM 0121	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.							Sample #:
64 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	STAIRWELL 0199D OFF STORAGE 0120	200 Sq Ft	N	ASSUMED	5
Comments:							Sample #:
68 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	CUSTODIAL OFFICE 0117	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. STORAGE 0117A.							Sample #:
75 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1110	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.							Sample #:
76 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1109	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.							Sample #:
78 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	STORAGE ROOM 1203 ACROSS HALLWAY FROM ROOM 1109	40 Sq Ft	N	80 CH	5
Comments: TWO (2) DOORS.							Sample #:
79 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1108	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.							Sample #:
80 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1107	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.							Sample #:
83 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1106	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.							Sample #:

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
84 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1105	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
86 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic White w/Black & Gray Smudges	GYMNASIUM 1201	4500 Sq Ft	N	3 CH (MASTIC)	5
Comments:					Sample #: 010509ML-18		
87 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	GYMNASIUM OFFICE 1205 ENTRY	24 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
88 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	GYMNASIUM OFFICE 1205 & ENTRY	40 Sq Ft	N	80 CH	5
Comments: TWO (2) DOORS. GYMNASIUM ENTRY DOOR WEARING AT BOTTOM, HINGE SIDE.					Sample #:		
89 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic White w/Black & Gray Smudges	GYMNASIUM OFFICE 1205	150 Sq Ft	N	3 CH (MASTIC)	5
Comments: INCLUDES OFFICE RESTROOM.					Sample #:		
91 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1961 Original Building	GYMNASIUM OFFICE RESTROOM 1205A	2 Joints	N	30 CH, 20 AM	5
Comments: ESTIMATED. ABOVE PLASTER CEILING. INACCESSIBLE FOR REMOVAL.					Sample #:		
94 CAD #:	S0A	Wood Floor Felt / Vapor Barrier Elevated (1961)	STAGE	720 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
95 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	STAGE	60 Sq Ft	N	ASSUMED	5
Comments: ON STAGE STAIRS.					Sample #:		
96 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	SERVER ROOM 1201C OFF OF STAGE	20 Sq Ft	N	80 CH	5
Comments: ONE (1) DOOR.					Sample #: 010509ML-43		
97 CAD #:	U0A	Light Pad Insulation Round Light Pads	SERVER ROOM 1201C OFF OF STAGE	2 Sq Ft	Y	35 CH	5
Comments: TWO (2) LIGHTS.					Sample #:		
98 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Tan w/Brown & Cream Streaks	SERVER ROOM 1201C OFF OF STAGE	120 Sq Ft	N	3 CH (MASTIC)	5
Comments:					Sample #: 010509ML-19		
99 CAD #:	U0A	Light Pad Insulation Round Light Pads	STAGE STORAGE/OFFICE 1201B	2 Sq Ft	Y	35 CH	5
Comments: TWO (2) LIGHTS.					Sample #:		
101 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	STAGE STORAGE/OFFICE 1201B	20 Sq Ft	N	80 CH	5
Comments: ONE (1) DOOR.					Sample #:		
102 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic White w/Black & Gray Smudges	STAGE ENTRANCE 1201A	100 Sq Ft	N	3 CH (MASTIC)	5
Comments:					Sample #:		
108 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1961 Original Building	ROOM 1006	1 Joints	N	30 CH, 20 AM	5
Comments: ABOVE CEILING. IN NORTH CENTRAL RISER CHASE. INACCESSIBLE FOR REMOVAL.					Sample #:		
110 CAD #:	U0A	Light Pad Insulation Round Light Pads	MAIN OFFICE STORAGE (OLD SAFE ROOM) 1009	1 Sq Ft	Y	35 CH	5
Comments: ONE (1) LIGHT.					Sample #: 010509ML-33		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
115 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Tan w/Brown & Cream Streaks	ART ROOM NORTHEAST STORAGE 1206A	60 Sq Ft	N	3 CH (MASTIC)	5
Comments: TWO (2) TILES MISSING.					Sample #:		
117 CAD #:	U0A	Light Pad Insulation Round Light Pads	ART ROOM SOUTHWEST STORAGE 1206B	1 Sq Ft	Y	35 CH	5
Comments: ONE (1) LIGHT. GLASS GLOBE MISSING W/EXPOSED LIGHT PAD.					Sample #:		
118 CAD #:	X1C	Miscellaneous Material 6" Beige Quarry Tile	MAIN ENTRY & STAIRWELL 1199A	700 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
119 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1961 Original Building	CUSTODIAL SLOP SINK ROOM 1205B	1 Joints	N	30 CH, 20 AM	5
Comments: ABOVE SLOP SINK. PARTIALLY IN WALL BETWEEN WALL & DUCTWORK.					Sample #:		
122 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1117	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
124 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1115	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
125 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1114	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
126 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1113	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
127 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1111	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
134 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2208	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
136 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2120	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
137 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2207	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
141 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2119	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
143 CAD #:	U0A	Light Pad Insulation Round Light Pads	SERVER ROOM 2118	1 Sq Ft	Y	35 CH	5
Comments: ONE (1) LIGHT.					Sample #:		
148 CAD #:	X0I	Miscellaneous Material Black Wall Drying Rack	ROOM 2117A	4 Sq Ft	N	18 CH	5
Comments:					Sample #: 081915BV-06		
152 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2116	30 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
158 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Gray Streaks	IMC 2114	1800 Sq Ft	N	5 CH (MASTIC)	5
Comments: UNDER CARPET.						Sample #: 010509ML-27	
159 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Gray Streaks	ROOM 2113	160 Sq Ft	N	5 CH (MASTIC)	5
Comments: UNDER CARPET.						Sample #:	
160 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Gray Streaks	ROOM 2112	160 Sq Ft	N	5 CH (MASTIC)	5
Comments: UNDER CARPET.						Sample #:	
161 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Gray Streaks	ROOM 2111	420 Sq Ft	N	5 CH (MASTIC)	5
Comments: UNDER CARPET.						Sample #:	
165 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2110	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
167 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	MECHANICAL ROOM 2203	20 Sq Ft	N	80 CH	5
Comments: ONE (1) DOOR. STARTING TO CRACK AT HINGES. MONITOR.						Sample #:	
168 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2109	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
169 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2108	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
170 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	MECHANICAL ROOM 2202	20 Sq Ft	N	80 CH	5
Comments: ONE (1) DOOR. LOWER CORNER IS WEARING.						Sample #:	
171 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2107	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
172 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2106	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
173 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2105	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
174 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2104	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
176 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2103	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
177 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2102	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.						Sample #:	
180 CAD #:	P0D	Fire Doors Wood - 1 Hr Rating (Weldwood)	MECHANICAL ROOM 2101	20 Sq Ft	N	80 CH	5
Comments: ONE (1) DOOR.						Sample #:	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
182 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 2121	60 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		