Frost Lake Elementary School Inspection Date: 8/10/2021

### 1505 Hoyt Avenue East, St. Paul, MN 55106

Chart C - All I	Materi		tains all events observe uped by homogeneous		or not they actually contained	
Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amoun
A3A		ed Pipe Joints on Pre-formed Insulation Original Building			Total Ar	mount - 7 Joints
	21	1964 ORIGINAL BUILDING HALLWAY (1200)	ASSUMED			2 Joints
	24	ROOM 1201	ASSUMED			5 Joints
A3C	Mudde 1973 A	ed Pipe Joints on Pre-formed Insulation ddition			Total Am	ount - 62 Joints
	111	REC CENTER HALLWAY 1500	NONE DETECTED			2 Joints
	118	REC CENTER WOMEN'S RESTROOM (1501) WEST PIPE CHASE	NONE DETECTED	052909-MV-5		8 Joints
	120	REC CENTER WOMEN'S RESTROOM (1501) SOUTH PIPE CHASE	NONE DETECTED			2 Joints
	122	CUSTODIAL OFFICE (1502)	NONE DETECTED			2 Joints
	144	COMPUTER LAB 1510	NONE DETECTED	061009-BF-4		9 Joints
	165	REC CENTER LOWER LEVEL STAIRWELL LANDING AREA (599)	NONE DETECTED	050509-MV-06	MV-06: ROOM 1504A (GYMNASIUM FAN ROOM) (SINCE REMOVED).	13 Joints
	167	ROOM 503 (STORAGE ROOM BY WARMING HOUSE)	NONE DETECTED			4 Joints
	169	ROOM 504 (WARMING HOUSE)	NONE DETECTED	052909-MV-4		16 Joints

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	182	ROOM 505 (BOYS' RESTROOM)	NONE DETECTED			3 Joints
	184	ROOM 506 (GIRLS' RESTROOM)	NONE DETECTED	061009-BF-6	BF-6: ROOM 501 (REC CENTER GARAGE) (SINCE REMOVED).	3 Joints
A4B	Mudde 1966 A	ed Pipe Joints on Fiberglass Insulation ddition			Total Amo	unt - 15 Joints
	86	ROOM 1223	8 CH			4 Joints
	97	1966 ADDITION WOMEN'S RESTROOM 1359	8 CH			2 Joints
	99	ROOM 1361 (MAINTENANCE OFFICE)	8 CH			2 Joints
	105	1966 ADDITION HALLWAY (1300)	8 CH	050509-MV-07, 08	MV-07: OUTSIDE ROOM 1321 W/CANVAS WRAP.	1 Joints
	106	ROOM 1319	8 CH			6 Joints
A4C	Mudde 1973 A	ed Pipe Joints on Fiberglass Insulation ddition			Total Amo	ount - 3 Joints
	112	REC CENTER HALLWAY 1500	NONE DETECTED			1 Joints
	123	CUSTODIAL OFFICE (1502)	NONE DETECTED	050509-MV-09		2 Joints
A4D	Mudde 1973 A	ed Pipe Joints on Fiberglass Insulation ddition			Total Amo	ount - 9 Joints
	132	ROOM 1504 (REC CENTER GYMNASIUM)	ASSUMED			9 Joints
ВЗА	Pre-Fo	ormed Pipe Insulation Original Building			Total Amo	unt - 55 Lin Ft
	20	1964 ORIGINAL BUILDING HALLWAY (1200)	5 CH, 60 AM	100P-1A; 206Z-4A, 7A	1A: BOILER ROOM (SINCE REMOVED). 4A,7A: TUNNELS.	20 Lin Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	23	ROOM 1201	5 CH, 60 AM			25 Lin Ft
	32	ROOM 1203A	5 CH, 60 AM			10 Lin Ft
взс	Pre-Fo	rmed Pipe Insulation ddition			Total Amou	nt - 278 Lin Ft
	110	REC CENTER HALLWAY 1500	NONE DETECTED			8 Lin Ft
	117	REC CENTER WOMEN'S RESTROOM (1501) WEST PIPE CHASE	NONE DETECTED	061009-BF-1		35 Lin Ft
	119	REC CENTER WOMEN'S RESTROOM (1501) SOUTH PIPE CHASE	NONE DETECTED			20 Lin Ft
	121	CUSTODIAL OFFICE (1502)	NONE DETECTED	050509-MV-11; 052909-MV-2		20 Lin Ft
	143	COMPUTER LAB 1510	NONE DETECTED	061009-BF-3		55 Lin Ft
	164	REC CENTER LOWER LEVEL STAIRWELL LANDING AREA (599)	NONE DETECTED	061009-BF-2		30 Lin Ft
	166	ROOM 503 (STORAGE ROOM BY WARMING HOUSE)	NONE DETECTED			40 Lin Ft
	168	ROOM 504 (WARMING HOUSE)	NONE DETECTED	052909-MV-3		25 Lin Ft
	181	ROOM 505 (BOYS' RESTROOM)	NONE DETECTED			10 Lin Ft
	183	ROOM 506 (GIRLS' RESTROOM)	NONE DETECTED	061009-BF-5	BF-5: ROOM 501 (REC CENTER GARAGE) (SINCE REMOVED).	10 Lin Ft
	185	REC CENTER LOWER LEVEL RESTROOM PIPE CHASE	NONE DETECTED			25 Lin Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
B3CC	Pre-Fo	ormed Pipe Insulation addition (ACM)			Total Amo	unt - 22 Lin Ft
	172	1973 ADDITION UNEXCAVATED AREA	5-15 CH, 10-20 AM	052909-MV-1; 061009- BF-7, 8, 9, 10, 11, 12, 13, 14, 15; 509P-6, 7, 8	MV-1: ROOM 1504A (GYMNASIUM FAN ROOM) (SINCE REMOVED).	22 Lin Ft
H1A	Spraye Fluffy,	ed-On Structural Fireproofing Gray Cellulose (2000)			Total Amount	- 20000 Sq Ft
	69	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	070920-BF-7, 8, 9, 10, 11, 12; 050509-MV-12	BF-7: ROOM 1302. BF-8: ROOM 1111. BF-9: ROOM 1115. BF-10: ROOM 1105. BF-11: HALL BY 147. BF-12: HALL BY DOOR 5. MV-12: CUSTODIAL ROOM.	20000 Sq Ft
I1A	1' x 1' . Fissur	Acoustical Ceiling Tile ed Spline (1964)			Total Amou	nt - 705 Sq Ft
	22	1964 ORIGINAL BUILDING HALLWAY (1200)	NONE DETECTED	206Z-2A		500 Sq Ft
	25	ROOM 1201	NONE DETECTED			135 Sq Ft
	31	ROOM 1203A	NONE DETECTED			70 Sq Ft
I1B	1' x 1' . Flat Gl	Acoustical Ceiling Tile acial Spline (1966)			Total Amoun	t - 4850 Sq Ft
	82	1966 ADDITION HALLWAY (1200)	NONE DETECTED	450Q-A1		600 Sq Ft
	84	ROOM 1221	NONE DETECTED			860 Sq Ft
	87	ROOM 1223	NONE DETECTED			860 Sq Ft
	100	ROOM 1361 (MAINTENANCE OFFICE)	NONE DETECTED			60 Sq Ft
	102	1966 ADDITION MAIN HALLWAY (1350)	NONE DETECTED	206Z-2A	2A: OUTSIDE ROOM 1351.	750 Sq Ft
		Fro	st Lake Elementary	School		Page 4 of 20

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	103	ROOM 1321	NONE DETECTED			860 Sq Ft
	107	ROOM 1319	NONE DETECTED			860 Sq Ft
IIC	1' x 1' / Fissure	Acoustical Ceiling Tile ed Spline (1973)			Total Amo	unt - 690 Sq Ft
	115	REC CENTER WOMEN'S RESTROOM (1501)	NONE DETECTED	509-P9	509-P9: 1973 LINK TO REC CENTER (SINCER REMOVED).	135 Sq Ft
	124	CUSTODIAL OFFICE (1502)	NONE DETECTED	464-2	464-2: SOUTH END OF ROOM.	400 Sq Ft
	127	REC CENTER HANDICAPPED RESTROOM	NONE DETECTED			55 Sq Ft
	139	ROOM 1506	NONE DETECTED			100 Sq Ft
12B	2' x 2' / Glacial	Acoustical Ceiling Tile I w/Revealed Edge (1994)			Total Amo	unt - 380 Sq Ft
	151	HALLWAY 1520	NONE DETECTED	050509-MV-13		380 Sq Ft
I2D	2' x 2' / Pockm	Acoustical Ceiling Tile narks with Pin Holes (2016)			Total Amou	nt - 4840 Sq Ft
	60	THROUGHOUT 1990 ADDITION	NEW			4000 Sq Ft
	76	ROOM 1217	NEW			840 Sq Ft
I3A	2' x 4' ( Rando	Ceiling Tile m Fissures w/Pin Holes			Total Amoun	t - 10960 Sq Ft
	27	ROOM 1203	NONE DETECTED			1000 Sq Ft
	33	ROOM 1205	NONE DETECTED			860 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	37	ROOM 1207	NONE DETECTED			860 Sq Ft
	41	ROOM 1209	NONE DETECTED			860 Sq Ft
	45	ROOM 1211	NONE DETECTED			860 Sq Ft
	50	ROOM 1213	NONE DETECTED			860 Sq Ft
	54	ROOM 1215	NONE DETECTED			860 Sq Ft
	113	REC CENTER HALLWAY 1500	NONE DETECTED			1400 Sq Ft
	145	COMPUTER LAB 1510	NONE DETECTED	474-1	474-1: MIDDLE OF ROOM.	530 Sq Ft
	150	ROOM 1510 & ENTRY	NONE DETECTED			220 Sq Ft
	154	REC CENTER RAMP OUTSIDE CAFETERIA	NONE DETECTED			250 Sq Ft
	157	ROOM 1523 (CAFETERIA)	NONE DETECTED	206Z-3A		2400 Sq Ft
I3B	2' x 4' ( Tectun	Ceiling Tile n			Total Amo	ount - 2450 Sq Ft
	133	ROOM 1504 (REC CENTER GYMNASIUM)	NSM			2450 Sq Ft
I3D	2' x 4' ( Vinyl-0	Ceiling Tile Coated Gypsum			Total An	nount - 830 Sq Ft
	161	KITCHEN, LOCKER AREA & STORAGE	NONE DETECTED	464-8	464-8: FOOD STORAGE.	830 Sq Ft
I3E	2' x 4' ( Dents 8	Ceiling Tile & Pin Holes (200X)			Total Amou	ınt - 16230 Sq Ft
	58	ROOM 1218	NONE DETECTED			230 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	70	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	050509-MV-14	MV-14: HALLWAY BY ROON 1406.	<sup>1</sup> 16000 Sq Ft
J2A	Transit 16" Du	te Piping/Ducting ct			Tota	l Amount - 26 Sq Ft
	137	ROOM 1504A (REC GYMNASIUM FAN ROOM)	ASSUMED			3 Sq Ft
	171	ROOM 504 (WARMING HOUSE)	ASSUMED			1 Sq Ft
	173	1973 ADDITION UNEXCAVATED AREA	ASSUMED			22 Sq Ft
J3A	Miscel Black V	laneous Cementitious Material Window Sills (1973)			Tota	l Amount - 12 Sq Ft
	141	ROOM 1506	NONE DETECTED			3 Sq Ft
	147	COMPUTER LAB 1510	NONE DETECTED	050509-MV-15		6 Sq Ft
	176	ROOM 507 (WARMING HOUSE STORAGE)	NONE DETECTED			3 Sq Ft
J3B		laneous Cementitious Material Nindow Sills (1994)			Tota	l Amount - 18 Sq Ft
	160	ROOM 1523 (CAFETERIA)	NONE DETECTED	050509-MV-16		18 Sq Ft
J3C	Miscel Black V	laneous Cementitious Material Nindow Sills (1990)			Tota	l Amount - 24 Sq Ft
	61	THROUGHOUT 1990 ADDITION	NONE DETECTED	050509-MV-17	MV-17: ROOM 1121.	24 Sq Ft
J3D		laneous Cementitious Material Vindow Sills (1966)			Tot	al Amount - 6 Sq Ft
	83	1966 ADDITION HALLWAY (1200)	NONE DETECTED	050509-MV-18	MV-18: EAST LINK.	6 Sq Ft
		Fro	st Lake Elementar	y School		Page 7 of 20

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount		
J3E		Miscellaneous Cementitious Material  Black Window Sills (1994)  Total Amount - 6 Sq Ft						
	77	ROOM 1217	NEW			6 Sq Ft		
K2B	12" x 1 Beige	2" Vinyl Floor Tile & Mastic w/Black Specks			Total Amoun	t - 4238 Sq Ft		
	114	REC CENTER HALLWAY 1500	NONE DETECTED			1400 Sq Ft		
	146	COMPUTER LAB 1510	NONE DETECTED			48 Sq Ft		
	152	HALLWAY 1520	NONE DETECTED	474-3	474-3: MAIN ENTRY.	410 Sq Ft		
	155	REC CENTER RAMP OUTSIDE CAFETERIA	NONE DETECTED			250 Sq Ft		
	158	ROOM 1523 (CAFETERIA)	NONE DETECTED	464-9	464-9: BY KITCHEN.	2130 Sq Ft		
K2C	12" x 1 Mauve	2" Vinyl Floor Tile & Mastic w/Black Specks			Total Amou	nt - 545 Sq Ft		
	153	HALLWAY 1520	NONE DETECTED			275 Sq Ft		
	159	ROOM 1523 (CAFETERIA)	NONE DETECTED	464-10	464-10: BY ENTRY DOORS.	270 Sq Ft		
K2D	12" x 1 Tan w	2" Vinyl Floor Tile & Mastic /Brown & Beige Streaks			Total Amou	nt - 960 Sq Ft		
	125	CUSTODIAL OFFICE (1502)	2 CH (TILE), 8 CH (MASTIC)			400 Sq Ft		
	134	ROOM 1504 (REC CENTER GYMNASIUM)	2 CH (TILE), 8 CH (MASTIC)	464-5	464-5: DOORWAY TO ROOM 1506.	560 Sq Ft		

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K2E	12" x 1 Green	2" Vinyl Floor Tile & Mastic w/White Streaks			Total Amoun	t - 2250 Sq Ft
	135	ROOM 1504 (REC CENTER GYMNASIUM)	3 CH (TILE), 8 CH (MASTIC)	464-7	464-7: MIDDLE OF ROOM.	2250 Sq Ft
K2F	12" x 1 Beige	2" Vinyl Floor Tile & Mastic w/Brown Streaks			Total Amoun	t - 1030 Sq Ft
	136	ROOM 1504 (REC CENTER GYMNASIUM)	3 CH (TILE), 8 CH (MASTIC)	464-6	464-6: MIDDLE OF ROOM.	930 Sq Ft
	140	ROOM 1506	3 CH (TILE), 8 CH (MASTIC)			100 Sq Ft
К2Н	12" x 1 Charco	2" Vinyl Floor Tile & Mastic oal w/Black & Orange Flecks			Total Amou	nt - 180 Sq Ft
	174	ROOM 507 (WARMING HOUSE STORAGE)	NONE DETECTED	2001-1504-T3; 464-10	T3: BY MIDDLE DOOR.	90 Sq Ft
	178	ROOM 508 (WARMING HOUSE STORAGE)	NONE DETECTED			90 Sq Ft
K2I	12" x 1 Gray w	2" Vinyl Floor Tile & Mastic //Multi-Colored Flecks			Total Amount	- 29500 Sq Ft
	1	THROUGHOUT BUILDING	NONE DETECTED	050509-MV-21	MV-21: 2000 HALLWAY AT MECHANICAL ROOM DOOR.	29500 Sq Ft
K2K	12" x 1 Beige	2" Vinyl Floor Tile & Mastic & Tan Stone Pattern			Total Amou	nt - 860 Sq Ft
	46	ROOM 1211	NONE DETECTED	050509-MV-23		860 Sq Ft
КЗВ	Miscel 1' x 2'	laneous Flooring Thick Black			Total Amou	nt - 850 Sq Ft
	170	ROOM 504 (WARMING HOUSE)	NONE DETECTED	050509-MV-25		850 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
LOA	Flexible Coarse	e Duct Connector White			Total Am	nount - 2 Sq Ft
	89	ROOM 1351	ASSUMED			2 Sq Ft
MOA	Plaster 1964 C	riginal Building			Total Amour	nt - 3000 Sq Ft
	15	THROUGHOUT 1964 ORIGINAL BUILDING	NONE DETECTED	050509-MV-01, 02, 03; 2001-01121-3B; 2001- 1501-FL-06	MV-01: ROOM 1203 (FIREBREAK). MV-02: ROOM 1209 (FIREBREAK). MV-03: ROOM 1311 (FIREBREAK). ; 3B: EAST RESTROOM HALLWAY.; FL-06: ROOM 1308	3000 Sq Ft
M0AA	Plaste Plaste	Sheets above Windows (1964)			Total Amou	ınt - 100 Sq Ft
	16	THROUGHOUT 1964 ORIGINAL BUILDING	NONE DETECTED	062221-BF-1	BF-1: OLD MAIN OFFICE.	100 Sq Ft
M0B	Plaster 1966 A	ddition			Total Amou	ınt - 490 Sq Ft
	90	1966 ADDITION MEN'S RESTROOM 1353	NONE DETECTED			85 Sq Ft
	92	1966 ADDITION BOYS' RESTROOM 1355	NONE DETECTED			160 Sq Ft
	94	1966 ADDITION GIRLS' RESTROOM 1357	NONE DETECTED	050509-MV-04	MV-04: AT VENT.	160 Sq Ft
	96	1966 ADDITION WOMEN'S RESTROOM 1359	NONE DETECTED			85 Sq Ft
MOC	Plaste 1973 A				Total Amou	ınt - 160 Sq Ft
	130	REC CENTER MEN'S RESTROOM (1505)	NONE DETECTED	050509-MV-05		160 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
M0D	Plaste 1990 A	r .ddition			Total Amou	nt - 630 Sq Ft
	67	1990 ADDITION RESTROOM & STORAGE AREAS	NONE DETECTED	2001-1501-FL-02	FL-02: ABOVE CEILING BOYS' RESTROOM.	630 Sq Ft
M0E	Plaste Exterio	r or Overhangs			Total Amou	nt - 200 Sq Ft
	6	THROUGHOUT BUILDING EXTERIOR	NONE DETECTED	063020-BF-12	BF-12: EXTERIOR BUILDING.	200 Sq Ft
NOC	Drywal 1973 A	ll/Joint Compound ddition			Total Amo	unt - 50 Sq Ft
	109	ROOM 1317	NONE DETECTED	509P4, 2001-1501-FL- 01	FL-01: STORAGE ROOM BY HALLWAY TO REC CENTER.	50 Sq Ft
N0D	Drywal 1990 A	ll/Joint Compound ddition			Total Amou	nt - 260 Sq Ft
	66	1990 ADDITION STORAGE ROOMS OUTSIDE ROOM 1002 (LOUNGE)	NONE DETECTED	463-13	463-13: ROOM 1302A.	100 Sq Ft
	68	1990 ADDITION SOUTH ENTRANCES	NONE DETECTED	2001-1501-FL-04	FL-04: ABOVE CEILING IN HALLWAY BY ROOM 1121.	160 Sq Ft
N0E	Drywal 1994 A	II/Joint Compound ddition			Total Amoun	t - 2480 Sq Ft
	78	ROOM 1219	NONE DETECTED			120 Sq Ft
	79	ROOM 1320 (IMC)	NONE DETECTED			1500 Sq Ft
	149	ROOM 1510 & ENTRY	NONE DETECTED	464-14	464-14: NORTH WALL.	300 Sq Ft
	156	ROOM 1523 (CAFETERIA)	NONE DETECTED			160 Sq Ft
	163	KITCHEN STORAGE ROOMS	NONE DETECTED	464-15	464-15: WEST ROOM.	400 Sq Ft
		Fro	st Lake Elementary	School		Page 11 of 20

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
NOF	Drywa 2021 li	ll/Joint Compound nstallation			Total Amou	nt - 500 Sq Ft
	4	THROUGHOUT BUILDING	NEW			500 Sq Ft
Q0B	Carpet Berber	t Adhesive Carpet (2000)			Total Amount	- 10000 Sq Ft
	71	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	050509-MV-27	MV-27: ROOM 1401.	10000 Sq Ft
R0A		oard/Mopboard Adhesive Baseboard			Total Amou	nt - 500 Sq Ft
	2	THROUGHOUT BUILDING	NONE DETECTED	050509-MV-28	MV-28: HALLWAY OUTSIDE MAIN OFFICE.	500 Sq Ft
ROB	Baseb Gray B	oard/Mopboard Adhesive Baseboard			Total Amou	nt - 500 Sq Ft
	3	THROUGHOUT BUILDING	NONE DETECTED	050509-MV-29	MV-29: ROOM 1213. BOTH TAN & BROWN ADHESIVES ANALYZED.	500 Sq Ft
ROC		oard/Mopboard Adhesive Baseboard (2000)			Total Amoun	t - 1000 Sq Ft
	72	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	050509-MV-30	ROOM 1415.	1000 Sq Ft
R0D	Baseb 6" Red	oard/Mopboard Adhesive Baseboard			Total Amo	unt - 20 Sq Ft
	175	ROOM 507 (WARMING HOUSE STORAGE)	NONE DETECTED			10 Sq Ft
	179	ROOM 508 (WARMING HOUSE STORAGE)	NONE DETECTED	050509-MV-31		10 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
V0B	Sink U Black (	ndercoating (200X)			Total Amo	ount - 60 Sq Ft
	28	ROOM 1203	NONE DETECTED	050509-MV-33		5 Sq Ft
	34	ROOM 1205	NONE DETECTED			5 Sq Ft
	38	ROOM 1207	NONE DETECTED			5 Sq Ft
	42	ROOM 1209	NONE DETECTED			5 Sq Ft
	47	ROOM 1211	NONE DETECTED			5 Sq Ft
	51	ROOM 1213	NONE DETECTED			5 Sq Ft
	55	ROOM 1215	NONE DETECTED			5 Sq Ft
	59	ROOM 1307	NONE DETECTED			5 Sq Ft
	85	ROOM 1221	NONE DETECTED			5 Sq Ft
	88	ROOM 1223	NONE DETECTED			5 Sq Ft
	104	ROOM 1321	NONE DETECTED			5 Sq Ft
	108	ROOM 1319	NONE DETECTED			5 Sq Ft
VOC	Sink U Rough	ndercoating , Gray (2000)			Total Amo	ount - 30 Sq Ft
	73	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	050509-MV-34	MV-34: ROOM 1402.	30 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount	
V0F	Sink U Gray (	ndercoating 2017)			Total A	mount - 4 Sq Ft	
	126	CUSTODIAL OFFICE (1502)	NEW			4 Sq Ft	
X0A		llaneous Material nterior Window Glaze			Total A	mount - 1 Sq Ft	
	177	ROOM 507 (WARMING HOUSE STORAGE)	45 CH	050509-MV-36		1 Sq Ft	
X0B	Misce Tan In	llaneous Material terior Window Glazing			Total A	mount - 6 Sq Ft	
	142	ROOM 1506	35 CH	050509-MV-37		2 Sq Ft	
	148	COMPUTER LAB 1510	35 CH	4 Sq Ft			
XOC	Miscel Slate (	laneous Material Chalkboard Adhesive (1964)			Total An	nount - 70 Sq Ft	
	29	ROOM 1203	2 CH	070920BF-5	BF-5: ROOM 1303 (SINCE REMOVED).	10 Sq Ft	
	35	ROOM 1205	2 CH			10 Sq Ft	
	39	ROOM 1207	2 CH			10 Sq Ft	
	43	ROOM 1209	2 CH			10 Sq Ft	
	48	ROOM 1211	2 CH			10 Sq Ft	
	52	ROOM 1213	2 CH			10 Sq Ft	
	56	ROOM 1215	2 CH			10 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
XOD		laneous Material oard Adhesive (1964)			Total Amo	unt - 70 Sq Ft
	30	ROOM 1203	3 CH	070920-BF-4	BF-4: ROOM 1303 (SINCE REMOVED).	10 Sq Ft
	36	ROOM 1205	3 CH			10 Sq Ft
	40	ROOM 1207	3 CH			10 Sq Ft
	44	ROOM 1209	3 CH			10 Sq Ft
	49	ROOM 1211	3 CH			10 Sq Ft
	53	ROOM 1213	3 CH			10 Sq Ft
	57	ROOM 1215	3 CH			10 Sq Ft
X0F	Miscel Chalkb	laneous Material oard Adhesive (1966)			Total Amou	nt - 100 Sq Ft
	80	THROUGHOUT 1966 ADDITION	ASSUMED			100 Sq Ft
X0G	Miscel Tackb	laneous Material pard Adhesive (1966)			Total Amoun	t - 1000 Sq Ft
	81	THROUGHOUT 1966 ADDITION	ASSUMED			1000 Sq Ft
ХОН	Miscel Black	laneous Material AHU Seam Material			Total Am	ount - 3 Sq Ft
	138	ROOM 1504A (REC GYMNASIUM FAN ROOM)	4 CH	052909-MV-6		3 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X0I		laneous Material Frame Chalkboard/Tackboard Adhesive			Total Amou	int - 100 Sq Ft
	62	THROUGHOUT 1990 ADDITION	NONE DETECTED	070920-BF-3; 062421- BF-1, 3	BF-3: ROOM 1103. 062421-BF-1: ROOM 1257 (SINCE REMOVED). 062421-BF-3: ROOM 1251 (SINCE REMOVED).	100 Sq Ft
X0J		laneous Material ooard/Tackboard Adhesive (2000)			Total Amou	nt - 100 Sq Ft
	74	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	070920-BF-2	BF-2: ROOM 1105.	100 Sq Ft
X0K		laneous Material loth Board Adhesive (2000)			Total Amou	nt - 100 Sq Ft
	75	THROUGHOUT 2000 ADDITIONS	NONE DETECTED	070920-BF-1	BF-1: ROOM 1105.	100 Sq Ft
XOL		laneous Material r/Exterior Window Caulk			Total Amou	nt - 100 Sq Ft
	18	THROUGHOUT 1964 ORIGINAL BUILDING	NONE DETECTED	063020-BF-6, 7	BF-6,7: ROOM 1303.	100 Sq Ft
X0M		laneous Material r Window Caulk			Total Amo	unt - 10 Sq Ft
	63	THROUGHOUT 1990 ADDITION	NONE DETECTED	063020-BF-9	BF-9: ROOM 1101.	10 Sq Ft
XON		laneous Material r Window Sill Caulk			Total Amo	unt - 10 Sq Ft
	64	THROUGHOUT 1990 ADDITION	NONE DETECTED	063020-BF-10	BF-10: ROOM 1101.	10 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount			
X00	Miscel Caulk a	laneous Material around Brick and below Windows			Total Amo	unt - 10 Sq Ft			
	65	THROUGHOUT EXTERIOR 1990 ADDITION	NONE DETECTED	063020-BF-11	BF-11: ROOM 1101.	10 Sq Ft			
XOP	Miscel Brick N	laneous Material Mortar			Total Amoun	t - 1000 Sq Ft			
	5	THROUGHOUT BUILDING EXTERIOR	NONE DETECTED	063020-BF-13	BF-13: EXTERIOR BUILDING	1000 Sq Ft			
XOQ	Miscel Louve	laneous Material Caulk			Total Amo	unt - 10 Sq Ft			
	7	THROUGHOUT BUILDING EXTERIOR	NONE DETECTED	THROUGHOUT BUILDING EXTERIOR	10 Sq Ft				
XOR		laneous Material or Door Caulk			Total Amo	unt - 10 Sq Ft			
	8	THROUGHOUT BUILDING EXTERIOR	NONE DETECTED	063020-BF-15	BF-16: DOOR 16.	OOR 16. 10 Sq Ft			
XOS		laneous Material sion Joint Caulk			Total Amo	unt - 20 Sq Ft			
	9	THROUGHOUT BUILDING EXTERIOR	NONE DETECTED	063020-BF-16	BF-16: EXTERIOR BUILDING.	20 Sq Ft			
ХОТ		laneous Material Gasket			Total Amou	nt - 100 Sq Ft			
	17	THROUGHOUT 1964 ORIGINAL BUILDING	50 CH	052121-BF-5	BF-5: BOILER ROOM.	100 Sq Ft			
X1A	Miscel Beige	laneous Material & Pink Terrazzo-Look Countertop			Total Amo	unt - 16 Sq Ft			
	180	ROOM 508 (WARMING HOUSE STORAGE)	NONE DETECTED	050509-MV-38	MV-38				

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1B		laneous Material Salmon Exterior Ceramic Tile System			Total Amou	nt - 420 Sq Ft
	19	THROUGHOUT 1964 ORIGINAL BUILDING EXTERIOR	<1 CH (GROUT), NONE DETECTED (TILE & CAULK)	063020-BF-8	BF-8: ROOM 1303.	420 Sq Ft
X1C		laneous Material Yellow/Blue Ceramic Wall Tile System			Total Amoun	t - 1460 Sq Ft
	26	RESTROOM 1201A	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)	052121-BF-1; 040721- BF-1	052121-BF-1: CUSTODIAL 1304 (SINCE REMOVED). 040721-BF- 1: GIRLS RESTROOM NEAR ROOM 1313 (SINCE REMOVED).	200 Sq Ft
	91	1966 ADDITION MEN'S RESTROOM 1353	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)			300 Sq Ft
	93	1966 ADDITION BOYS' RESTROOM 1355	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)			300 Sq Ft
	95	1966 ADDITION GIRLS' RESTROOM 1357	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)			300 Sq Ft
	98	1966 ADDITION WOMEN'S RESTROOM 1359	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)			300 Sq Ft
	101	ROOM 1361 (MAINTENANCE OFFICE)	<1 CH (SETTING BED), NONE DETECTED (TILE AND GROUT)			60 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1E	Misce 1" X 1' Syster	llaneous Material ' Multi Shaded Brown Ceramic Floor Tile n			Total Amou	nt - 380 Sq Ft
	116	REC CENTER WOMEN'S RESTROOM (1501)	ASSUMED			135 Sq Ft
	128	REC CENTER HANDICAPPED RESTROOM	ASSUMED			55 Sq Ft
	129	CUSTODIAL CLOSET OUTSIDE HANDICAPPED RESTROOM	ASSUMED			30 Sq Ft
	131	REC CENTER MEN'S RESTROOM (1505)	ASSUMED			160 Sq Ft
X1F		llaneous Material ' Red =Quarry Floor Tile System			Total Amou	nt - 830 Sq Ft
	162	KITCHEN, LOCKER AREA & STORAGE	ASSUMED			830 Sq Ft
Z0A		laneous Material Membrane			Total Amount	- 20000 Sq Ft
	10	THROUGHOUT BUILDING ROOF	NONE DETECTED	063020-BF-1	BF-1: THROUGHOUT BUILDING ROOF.	20000 Sq Ft
Z0B		llaneous Material Perimeter Flashing			Total Amoun	t - 1000 Sq Ft
	11	THROUGHOUT BUILDING ROOF	NONE DETECTED	063020-BF-2	BF-2: THROUGHOUT BUILDING ROOF.	1000 Sq Ft
ZOC		llaneous Material nous Roof Patch			Total Amo	unt - 50 Sq Ft
	12	THROUGHOUT BUILDING ROOF	NONE DETECTED	063020-BF-3	BF-3: THROUGHOUT BUILDING ROOF.	50 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
ZOD		laneous Material oof Flashing Caulk			Total Amo	unt - 10 Sq Ft
	13	THROUGHOUT BUILDING ROOF	NONE DETECTED	063020-BF-4	BF-4: THROUGHOUT BUILDING ROOF.	10 Sq Ft
Z0E		laneous Material of Overhang Caulk			Total Amo	unt - 10 Sq Ft
	14	THROUGHOUT BUILDING ROOF	NONE DETECTED	063020-BF-5	BF-5: THROUGHOUT BUILDING ROOF.	10 Sq Ft



### EMSL Analytical, Inc

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

EMSL Order: 352105837 Customer ID: IFEA50

Customer PO: Project ID:

Inst. For Environmental Assessment Jennifer Theis Phone: Fax:

Attention:

Fax: (763) 315-7920

Received Date: 06/24/2021 9:15 AM

Analysis Date: 06/24/2021

(763) 315-7900

Collected Date:

Project: 2001-202110251 - Frost Lake Elementary

Brooklyn Park, MN 55445

Suite 600

9201 West Broadway

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using **Polarized Light Microscopy**

			Non-Asbestos	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
062421-BF-1	Room 1257 -	Brown		100.0% Non-fibrous (Other)	None Detected
352105837-0001	Tackboard adhesive	Non-Fibrous			
		Homogeneous			
062421-BF-2	Room 1218 -	Brown		100.0% Non-fibrous (Other)	None Detected
352105837-0002	Chalkboard adhesive	Non-Fibrous			
		Homogeneous			
062421-BF-3	Room 1251 -	Brown		100,0% Non-fibrous (Other)	None Detected
352105837-0003	Tackboard adhesive	Non-Fibrous			
		Homogeneous			
062421-BF-4	Room 1220 -	Brown		100,0% Non-fibrous (Other)	None Detected
352105837-0004	Tackboard adhesive	Non-Fibrous			
		Homogeneous			
062421-BF-5	Room 1220 - Frame	Brown		100,0% Non-fibrous (Other)	None Detected
352105837-0005	adhesive	Non-Fibrous			
		Homogeneous			

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020). "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 06/24/2021 12:08:50



## EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

EMSL Order: 352105837 Customer ID: IFEA50

Customer PO: Project ID:

Inst. For Environmental Assessment Jennifer Theis Phone: Fax: (763) 315-7920 (763) 315-7900

Received Date: 06/24/2021 9:15 AM
Analysis Date: 06/24/2021

2001-202110251 - Frost Lake Elementary Brooklyn Park, MN 55445 Collected Date:

Project:

Suite 600

9201 West Broadway

EMSL Order ID above. Please use this reference number when calling about these samples. EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via

### Report Comments:

Sample Receipt Date: 06/24/2021 Sample Receipt Time: 9:15 AM

Analysis Completed Time: 11:22 AM

Analyst(s):

Analysis Completed Date:

06/24/2021

Thet Durain

Nicholas Asuncion PLM (5)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis, Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL, EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control endorsement by NVLAP, NIST or any agency of the federal government. Non-frieble organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is criteria and met method specifications unless otherwise noted. available on request. "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020

9201 West Broadway North, Suite 600 Brooklyn Park, MN 55445 (763) 315-7900 1-800-233-9513 352\05837

### CHAIN OF CUSTODY

						li .				-								
Client # Z		Project of	202110 ic Schools	251 S	В	uilding No		Frost	La	Ke I	Te	men	tar	4		ed Areas ratory U		
Address					- (	Contact Pe	rson				Co	ntact Pe	rson P	hone				
					Oth	er Informa	tion											
Verbal results to					Phone, Fa	x No. or E	-Mail				T.	AT (circl	e) 6h	hou	2d 3d 4d	Specify		
Verbal results rel	ayed to				Verbal r	esults rela	yed by					Date			Ti			
Analysis locat	ion: OO	n Site OLab	○Regional Off	fice OO	ther				Mat	rix ty	pe	An	alysi	s reg	uested	Filt	er t	ype
Sample #	Work Area or Phase #		Comme Locatio			i i	Sample type or (Interial code	Volume	Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE	% nm	.45 um
062421-8F-1 062421-8F-2 062421-8F-3 062421-8F-4 062421-8F-5	Room 1257 Room 1218 Room Room Room 1220	Chalkbo Tackbo Tackbo	and adhes novel adhes and adhes and adhes adhesive	sive.					00000000000000	000000000000000000000000000000000000000		00000000000000	000000000000000000000000000000000000000	000000000000000		00000000000000	0000000000000	00000000000000
The MN Departm	ent of Health	Alternative Indo	oor Air Standard for	this project	t is:			tch Number						ples A	cceptable?		0	O No
Sampled by Brendatise	har 6-2	Date Time 24-21 8100Am		cher 6	Date -24-21	Time 91/5A		0 -	4121		Time	moi				Date	I	Time
Received by		Date Time	Delivered by		Date	Time	Analysis by		D	ite	Time	Delin	vered by	y		Date	T	lime



Jennifer Theis

### EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

EMSL Order: 352105705 Customer ID: IFEA50

Customer PO: Project ID:

Phone: (763) 315-7900 Fax: (763) 315-7920

Received Date: 06/22/2021 11:45 AM Analysis Date: 06/22/2021

Collected Date: 06/22/2021

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

2001- 202110251- Frost Lake Elementary

Brooklyn Park, MN 55445

Suite 600

9201 West Broadway

Inst. For Environmental Assessment

			Non-Asbestos	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
062221-BF-1	Main office, Plaster	Gray/White		100.0% Non-fibrous (Other)	None Detected
352105705-0001	sheets above	Non-Fibrous			
	windows	Homogeneous			
062221-BF-2	Restroom 1214, Setting	Gray		100.0% Non-fibrous (Other)	None Detected
352105705-0002	bed	Non-Fibrous			
		Homogeneous			
062221-BF-3	Restroom 1216, Setting	Gray		100.0% Non-fibrous (Other)	None Detected
		Homogeneous		*	
062221-BF-4	Closet 1304, Setting	Gray		100.0% Non-fibrous (Other)	None Detected
352105705-0004	bed	Non-Fibrous			
		Homogeneous			

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction available on request. prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Report amended: 06/24/2021 10:39:25 Replaces initial report from: 06/22/2021 12:41:26 Reason Code: Client-Change to Location



Project:

2001- 202110251- Frost Lake Elementary

Brooklyn Park, MN 55445

Suite 600

## EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

EMSL Order: 352105705 Customer ID: IFEA50

Customer PO: Project ID:

9201 West Broadway Inst. For Environmental Assessment Jennifer Theis Received Date: Phone: Fax: 06/22/2021 11:45 AM (763) 315-7920 (763) 315-7900

Analysis Date: 06/22/2021 Collected Date: 06/22/2021

EMSL Order ID above. Please use this reference number when calling about these samples. EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via

Report Comments: Descriptions amended

Sample Receipt Date: 06/22/2021 Sample Receipt Time: 11:45 AM

Analysis Completed Date: 06/22/2021 Analysis Completed Time: 12:38 PM

Analyst(s):

Thet Durion

Nicholas Asuncion PLM (4)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis, interpretation and use of test results are the responsibility for the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. lincleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is

Page

0f

9201 West Broadway North, Suite 600 Brooklyn Park, MN 55445 (763) 315-7900 1-800-233-9513

### 05705

### CHAIN OF CUSTODY

Page of \_

	Client # 2001 Project # 202110251 Building Name Fross Client Saint Paul Public Schools Project Name  Address Contact Person								lake	E	len	nen:	tar	4	U.S. 200 (197)		Filter type  wm 8:  0 0 0 0  0							
Address	OLO II	1000	4170	ADITE OUT	حات	_					Cor	ntact Per	rson Pl	hone										
					Oti	her Inform	ation			_														
Verbal results to					Phone, I	ax No. or	E-Mail				TA	T (circle	e) 6 h <u>r</u>	1d 2	d 3d 4d	Specify	^							
Verbal results re	layed to		164		Verbal	results rel	ayed by			E.	-	ate		5 5		me								
Analysis loca	tion: O O	n Site (	OLab (	Regional Office	Other_				Mat	rix t	vpe	An	alvsis	s rea	uested	Filt	er t	vpe						
Sample #	Work Area or Phase #			Comments / Location			Sample type or Material code	Volume	Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE		-						
D62221-BF-2 D62221-BF-3 D62221-BF-4	Main Office Destroom 1214 Restrain 1214 Closet 1304	Set	ting ting thing	prets above brd bed bed	Windo	ows_			00000000000000	XXXX0000000000	0 0 0 0 0 0 0 0 0 0 0 0	000000000000000	× × × 00000000000000000000000000000000	0000000000000		00000000000000	00000000	00000000						
The MN Departm	nent of Healt	h Alterna	tive Indo	or Air Standard for this p	roject is:		The same	tch Number:	0	0	0	0	Samp	oples Ac	cceptable	O Yes	O	O No						
Sampled by  Brendaft  Received by	sherto-	Date 22-2 C	Time 7 Am Time	Chad Wayler Delivered by	Date  Date	Time 1145 a Time	Received by Analysis by	lake a	Da Da Da	u	Time 11: 45 Time		ed by ered by			Date		ime						



## EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

Attention:

Jennifer Theis

Project:

Suite 600

9201 West Broadway

Inst. For Environmental Assessment

2001-202110251- Frost Lake Elementary

Brooklyn Park, MN 55445

EMSL Order: 352104586 Customer ID: IFEA50

Customer PO:

Project ID:

Phone: (763) 315-7900 Fax: (763) 315-7920

Fax: (763) 315-7920 Received Date: 05/21/2021 8:45 AM

Analysis Date: 05/23/2021

Collected Date:

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using **Polarized Light Microscopy**

			Non-Asbestos	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
052121-BF-1-Ceram	Custodial 1304, Ceramic Wall tile &	White/Blue Non-Fibrous		100.0% Non-fibrous (Other)	None Detected
352104586-0001	grout	Homogeneous			
052121-BF-1-Grout 352104586-0001A	Custodial 1304, Ceramic Wall tile & grout	Gray Non-Fibrous Homogeneous		100.0% Nan-fibrous (Other)	None Detected
052121-BF-2 352104586-0002	Custodial 1304, Ceramic Wall setting bed	Gray Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	<1% Chrysotile
052121-BF-3-Ceram ic Tile 352104586-0003	Custodial 1304, Ceramic floor tile & grout	White/Blue Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
052121-BF-3-Grout 352104586-0003A	Custodial 1304, Ceramic floor tile & grout	Gray Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
052121-BF-4 352104586-0004	Custodial 1304, Ceramic floor setting bed	Gray Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
052121-BF-5 352104586-0005	Boiler Room, Flange gasket	Brown/Black Fibrous Homogeneous		50.0% Non-fibrous (Other)	50% Chrysotile

"interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, atc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020



Jennifer Theis

## EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

Tel/Fax: (763) 449-4922 / (763) 449-4924 http://www.EMSL.com / minneapolislab@emsl.com

> EMSL Order: 352104586 Customer ID: IFEA50

Customer ID: IFE Sustomer PO:

Customer PO: Project ID:

Phone: (763) 315-7900

Fax: (763) 315-7920 Received Date: 05/21/2021 8:45 AM

Analysis Date: 05/23/2021 Collected Date:

Project: 2001-202110251- Frost Lake Elementary

Brooklyn Park, MN 55445

Suite 600

9201 West Broadway

Inst. For Environmental Assessment

EMSL Order ID above. Please use this reference number when calling about these samples. The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the

### Report Comments:

Sample Receipt Date:

Analysis Completed Date:

05/23/2021

05/21/2021

Sample Receipt Time: 8:45 AM

Analysis Completed Time: 1:59 PM

Analyst(s):

Thet Surias

Nicholas Asuncion PLM (7)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager or other approved signatory

"Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is EMSL maintains liability limited to cost of analysis, Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020).

9201 West Broadway North, Suite 600 Brooklyn Park, MN 55445 (763) 315-7900 1-800-233-9513

**CHAIN OF CUSTODY** 

															_
Client # 2001 Project # 202   1025   Building Name Frost Lu									Tem	entan	<b>L</b>		led Areas ratory Us		
Address	- Miles			_	Contact Per	son				Contact Pe	rson Ph	none			
				Oth	er Informat	tion									
Verbal results to				Phone, Fa	x No. or E	-Mail				TAT (circl	le) 6 hr	1d 2d 3d 4d	Specify		
Verbal results relayed to				Verbal r	esults relay	yed by	BANT NO.			Date	BIFE	Ti	me	in	
Analysis location: (	On Site	OLab	O Regional Office O	Other			NI VEN	Matr	ix typ	e An	alvsis	requested	Filt	er typ	эe
Work or Sample # Phas	•		Comments / Location		1	Sample type or Interial code	Volume		Bulk	PCM	PLM	₩ H Other	MCE	8 mm	.45 um
052121-BF-2 052121-BF-2 052121-BF-3	Ceri	amic a	vall file tyrout vall setting bed bortile tyrout					0 0	<b>X</b> 0 0 <b>X</b> 0 0	0	8	o o	0 0	0 0	o
052121-BF-4 V	Cen	amic f	Your setting be	d				0	Ø 0	0	8	0	0	0 0	
052121-BF.5 Boile	om Fl	lange	gasket					0	& O	0	Ø	°	0	0 0	-
								0	0 0	0	0	°	0	0 0	
								0	0 0	0	0	· —	0		
								0	0 0	0	0	0	0	0 0	0
		9.						0	0 0	0	0	0	0	0 0	С
								0	0 0	0	0	0	0	0 0	О
							1	0	0 0	0	0	0	0		0
								0	0 0	0	0	° —	. 0	0 0	_
	_							0	0 0	0	0	°	0	0 0	
The MN Department of I	lealth Alten	native Indo	or Air Standard for this proje	ect is:		F/CC. Bat	ch Number:					oles Acceptable		ONo	
Sampled by	Date	Time	Delivered by	Date	Time	Received by		Date	Tu	me Ente	red by	no Acceptable	Date	Time	_
Brendatischer	5-21-21	7:30Am	Brendatisher	5-21-21	8:45am	alind	she Dis	5-21	21 84	5					
Received by	Date	Time	Delivered by	Date	Time	Analysis by		Date	Ti	ne Deli	vered by		Date	Time	e



Jennifer Theis

9201 West Broadway

Inst. For Environmental Assessment

Suite 600

Brooklyn Park, MN 55445

Project:

2001-202110251- Frost Lake Elementary School

### EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427 Tel/Fax: (763) 449-4922 / (763) 449-4924

http://www.EMSL.com / minneapolislab@emsl.com

EMSL Order: 352102854 Customer ID: IFEA50

Customer PO:
Project ID:

Phone: (763) 315-7900
Fax: (763) 315-7920
Received Date: 04/08/2021 12:30 PM

Analysis Date: 04/09/2021 - 04/12/2021

Collected Date:

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbestos	estos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
040721-BF-1-Ceram	Girls RR by 1313,	White		100.0% Non-fibrous (Other)	None Detected
ic Tile	Ceramic Wall tile, grout	Non-Fibrous			
352102854-0001	& bedding	Heterogeneous			
040721-BF-1-Grout	Girls RR by 1313,	Gray		100.0% Non-fibrous (Other)	None Detected
352102854-0001A	Ceramic Wall tile, grout	Non-Fibrous			
	& bedding	Heterogeneous			
040721-BF-1-Beddi	Girls RR by 1313,	Gray		100.0% Non-fibrous (Other)	<1% Chrysotile
ng	Ceramic Wall tile, grout	Non-Fibrous			
352102854-0001B	& bedding	Heterogeneous			
040721-BF-2 352102854-0002	Mezzanine by 1311, Tar AHU door gasket-	Black Non-Fibrous		100.0% Non-fibrous (Other)	None Detected
	AHU 2	Homogeneous			

"Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 criteria and method specifications unless otherwise noted. available on request. prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is



Jennifer Theis

Project:

2001-202110251- Frost Lake Elementary School

Brooklyn Park, MN 55445

9201 West Broadway

Suite 600

Inst. For Environmental Assessment

## EMSL Analytical, Inc

Tel/Fax: (763) 449-4922 / (763) 449-4924 3410 Winnetka Avenue North New Hope, MN 55427

http://www.EMSL.com / minneapolislab@emsl.com

**EMSL Order:** 352102854 IFEA50

**Customer PO:** Customer ID:

Project ID:

Phone: Fax: (763) 315-7920 (763) 315-7900

Received Date: Analysis Date: 04/09/2021 - 04/12/2021 04/08/2021 12:30 PM

Collected Date:

EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples. The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via

### Report Comments:

Sample Receipt Date: 04/08/2021 Sample Receipt Time: 12:30 PM

Analysis Completed Time: 9:55 AM

Analyst(s):

Analysis Completed Date:

04/12/2021

Lynn Scott PLM (4)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager or other approved signatory

"interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control availabte on request. criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020

1 Of

<del>---</del>

9201 West Broadway North, Suite 600 Brooklyn Park, MN 55445 (763) 315-7900 1-800-233-9513

Client #	2001 Faint Pa	Project	= 2021102 c schools	251 E	Building N	lame <u>FvO</u>	st Lak	e El	emanla	ny S	choo	Shade Labor	ed Areas atory U		
Address					Contact Pe	rson			Со	ntact Pe	rson Phon	e			
-				Oth	er Informa	ation									
Verbal results to	0			Phone, Fa	ax No. or E	-Mail			TA	AT (circl	e) 6 hr (1	d 2d 3d 4d S	pecify		
Verbal results re	elayed to			Verbal r	results rela	yed by			Γ	ate		Tim	ie		
Analysis loca	ition: OOr	n Site OLal	o Regional Office	e OOther_	3,215			Matr	ix type	An	alysis r	equested	Filt	er t	vpe
Sample #	Work Area or Phase #		Comments Location	s /		Sample type or Material code	Volume	Air	Bulk	PCM	PLM		MCE	.8 um	.45 um
040721-BF-1 040721-BF-Z	Gids RR by 1313 Mezzanna by 1311	Ceramic Tar Al	wall tile, ga HU door gasle	out + bedo et - AHUZ	ling			0 ,	000	0 0	<b>X</b> 0		0 0	0 0	0 0 0
								0	0 0	0 0	0 0		0 0 0	0 0	0 0 0
								0 0	0 0	0 0	0 0 0		0 0 0	0 0 0	0 0 0
		•						0 0	0 0	0 0 0	0 0 0		0 0 0	0 0 0	0 0 0
						6. 0.3		0	0 0	0 0	0 0		0 0 0	0 0 0	0 0 0
			door Air Standard for this				ch Number:					Acceptable?	O Yes	ON	No
Brendato	ther 4-1		7	Date	Time		le le Dax		1 12:30		ed by		Date	Ti	ime
Received by	D	Date Time	Delivered by	Date	Time	Analysis by		Date	Time	Deliv	ered by		Date	Ti	me

© IEA, Inc. 2010