

## Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

**PLEASE NOTE:** Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
5 CAD #:	X1B	Miscellaneous Material 6" Brown Quarry Tile	THROUGHOUT BUILDING	400 Sq Ft	N	ASSUMED	5
Comments: AT ENTRANCE 1160A. INCLUDES BASEBOARD THROUGHOUT.					Sample #:		
6 CAD #:	J3A	Miscellaneous Cementitious Material Black Window Sills	THROUGHOUT BUILDING	300 Sq Ft	N	5 CH	5
Comments:					Sample #: 102308MV-22		
8 CAD #:	X1D	Miscellaneous Material 1" X 1" Yellow Ceramic Floor Tile Systems	THROUGHOUT 1973 ORIGINAL BUILDING RESTROOMS	1200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
13 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	BOILER ROOM (1161)	20 Sq Ft	N	3 CH	5
Comments: AHU #1.					Sample #: 102308MV-1		
32 CAD #:	X1C	Miscellaneous Material 6" Red Quarry Tile	KITCHEN (1163)	740 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
39 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	KITCHEN RESTROOM (1209B)	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
58 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	MECHANICAL ROOM (TE-1)	10 Sq Ft	N	3 CH	5
Comments: AHU #4.					Sample #:		
60 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Eggers)	MECHANICAL ROOM (TE-1)	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
66 CAD #:	V0A	Sink Undercoating Black	ROOM 1207	5 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #: 2001-1501-EE1		
77 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	MEN'S GYMNASIUM RESTROOM	125 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
79 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	WOMEN'S GYMNASIUM RESTROOM	125 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
83 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 1203	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
92 CAD #:	V0A	Sink Undercoating Black	ROOM 1201	20 Sq Ft	N	3 CH	5
Comments: FOUR (4) SINKS.					Sample #:		
93 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 1201	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
132 CAD #:	V0A	Sink Undercoating Black	ROOM 1145	30 Sq Ft	N	3 CH	5
Comments: FOUR (4) SINKS.					Sample #:		
136 CAD #:	V0A	Sink Undercoating Black	ROOM 1146	5 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #:		
144 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	1ST FLOOR GIRLS' RESTROOM (1147)	350 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
146 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	1ST FLOOR BOYS' RESTROOM (1149)	350 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
174 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	LOWER LEVEL AREA 0100	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		
179 CAD #:	V0A	Sink Undercoating Black	ROOM 0102	5 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #:		
180 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 0102	5 Sq Ft	N	5 CH	5
Comments:					Sample #: 102308MV-11		
186 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 0101	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
190 CAD #:	V0A	Sink Undercoating Black	ROOM 0101 STORAGE	5 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #:		
191 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	ROOM 0101 RESTROOM	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
205 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	2ND FLOOR GIRLS' RESTROOM (2247)	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
208 CAD #:	P0B	Fire Doors Metal -1.5 Hour (Underwriter Laboratories)	CUSTODIAL ROOM 2299D	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
212 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	PENTHOUSE OFF OF ROOM 2299D	5 Sq Ft	N	3 CH	5
Comments: AHU'S #2 & #3.					Sample #:		
215 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	2ND FLOOR BOYS' RESTROOM	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		