

## Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

**PLEASE NOTE:** Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
10 CAD #:	X0J	Miscellaneous Material Exterior Black Dampproofing	THROUGHOUT BUILDING	5000 Sq Ft	N	12 CH	5
Comments: REMOVED FROM 2-STORY CLASSROOM WING. MAY ALSO BE BELOW GRADE.						Sample #: 021712-MA-1	
11 CAD #:	X11	Miscellaneous Material 6" X 6" Brown Quarry Floor Tile System	THROUGHOUT BUILDING STAIRWELLS	500 Sq Ft	N	ASSUMED	5
Comments:						Sample #:	
16 CAD #:	W1D	1' x 1' Ceiling Tile Adhesive Associated w/11B (Dark Brown Patch)	THROUGHOUT 1956 ORIGINAL BUILDING	30 Sq Ft	N	2 CH	5
Comments: VISIBLE ON SOME REPLACEMENT TILES.						Sample #: 071212MV-09, 10; 121609ML-27	
23 CAD #:	D2A	Interior Boiler Insulation Burner Refractory	BOILER ROOM	20 Sq Ft	N	ASSUMED	5
Comments: TWO (2) BOILERS.						Sample #:	
24 CAD #:	D2B	Interior Boiler Insulation Mineral Wool Access Panel Insulation	BOILER ROOM	20 Sq Ft	N	ASSUMED	5
Comments: TWO (2) BOILERS. THREE (3) ACCESS PANELS EACH.						Sample #:	
28 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	HALLWAY FROM MAIN OFFICE TO CAFETERIA	50 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. OPEN ENDS OUTSIDE GIRLS' RESTROOM FROM ORIGINAL CONSTRUCTION. SPLIT ABOVE GIRLS' RESTROOM. INACCESSIBLE FOR REPAIR.						Sample #:	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
31 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	HALLWAY FROM MAIN OFFICE TO CAFETERIA	350 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING AT EAST END.					Sample #:		
35 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	MAIN OFFICE 1002	240 Sq Ft	N	2 CH	5
Comments:					Sample #:		
36 CAD #:	B3A	Pre-Formed Pipe Insulation 1956 Original Building	ROOM 1006	10 Lin Ft	N	15 CH, 15 AM	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH.					Sample #: 2071-2A		
37 CAD #:	A3A	Mudded Pipe Joints on Pre-formed Insulation 1956 Original Building	ROOM 1006	2 Joints	N	30 CH	5
Comments: ABOVE CEILING.					Sample #: 207J-3A		
38 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1006	4 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. WHITE WRAP ANALYZED AS 3% CH. GRAY & BLACK LAYERS ANALYZED AT 60% CH. GOUGE IN LINE VISIBLE FROM HATCH. INACCESSIBLE FOR REPAIR.					Sample #: 112113MA-02		
39 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1006	1 Joints	Y	15-20 CH	5
Comments: UNCOVERED SINCE INSTALLATION. ABOVE CEILING.					Sample #: 112113MA-01		
42 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1005	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
45 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1004	45 Sq Ft	N	2 CH	5
Comments:					Sample #:		
47 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	COPY ROOM 1007	12 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. OPEN ENDS FROM ORIGINAL CONSTRUCTION. INACCESSIBLE FOR REPAIR. VISIBLE FROM CEILING HATCH.					Sample #:		
49 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	OFFICE 1008	12 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. OPEN ENDS FROM ORIGINAL CONSTRUCTION. INACCESSIBLE FOR REPAIR. VISIBLE FROM CEILING HATCH.					Sample #:		
51 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1008	25 Sq Ft	N	2 CH	5
Comments:					Sample #:		
54 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1003	35 Sq Ft	N	2 CH	5
Comments:					Sample #:		
57 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	TECHNOLOGY ROOM 1009	25 Sq Ft	N	2 CH	5
Comments:					Sample #:		
59 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1016	20 Sq Ft	N	2 CH	5
Comments:					Sample #:		
62 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1015	45 Sq Ft	N	2 CH	5
Comments:					Sample #:		
65 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	COUNSELOR'S WORK ROOM 1010	160 Sq Ft	N	2 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
66 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	NURSE 1011	60 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING & IN CHASE. VISIBLE FROM CEILING HATCH. WRAP COMING LOOSE. DAMAGE INACCESSIBLE FOR REPAIR.					Sample #:		
67 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	NURSE 1011	6 Joints	N	15-20 CH	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH.					Sample #:		
69 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	NURSE 1011	60 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILE IS MISSING.					Sample #: 071212MV-01		
72 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	NURSE'S OFFICE 1014	24 Lin Ft	N	3-60 CH	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH.					Sample #:		
74 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	NURSE'S OFFICE 1014	35 Sq Ft	N	2 CH	5
Comments:					Sample #:		
77 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	NURSE'S RESTROOM 1011A	6 Lin Ft	N	3-60 CH	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH IN ROOM 1011 (NURSE).					Sample #:		
78 CAD #:	X1B	Miscellaneous Material 2" X 2" Gray Ceramic Floor Tile System	NURSE'S RESTROOM 1011A	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
79 CAD #:	X1C	Miscellaneous Material 4" X 4" Gray Ceramic Wall Tile System	NURSE'S RESTROOM 1011A	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
81 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	COT ROOM 1013	30 Sq Ft	N	2 CH	5
Comments:					Sample #:		
84 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	OFFICE 1012	25 Sq Ft	N	2 CH	5
Comments:					Sample #:		
88 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	AUDITORIUM	200 Sq Ft	N	2 CH	5
Comments: NEAR ENTRANCE.					Sample #:		
91 CAD #:	T0A	Light Cord Insulation White	AUDITORIUM	25 Lin Ft	N	50 CH	5
Comments: SIX (6) LIGHTS.					Sample #:		
92 CAD #:	S0C	Wood Floor Felt / Vapor Barrier Elevated (1956)	AUDITORIUM STAGE	1500 Sq Ft	N	12 CH	5
Comments:					Sample #: 121609ML-8		
93 CAD #:	T0A	Light Cord Insulation White	AUDITORIUM STAGE	30 Lin Ft	N	50 CH	5
Comments: SEVEN (7) STORED ON RACK 20' UP.					Sample #: 121609ML-7		
95 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	AUDITORIUM LIGHT BOOTH 2102	50 Sq Ft	N	2 CH	5
Comments:					Sample #:		
97 CAD #:	U0A	Light Pad Insulation Round	HALLWAY SOUTHEAST OF AUDITORIUM OUTSIDE SPRINKLER SHUT-OFF ROOM	1 Sq Ft	N	70 CH	5
Comments: ONE (1) LIGHT.					Sample #: 121609ML-5		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
99 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	HALLWAY EAST OF AUDITORIUM	240 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILES ARE MISSING.					Sample #:		
100 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	GIRLS' LOCKER ROOM 1105	60 Lin Ft	Y	3-60 CH	1
Comments: ESTIMATED IN CHASES. OPEN ENDS FROM ORIGINAL CONSTRUCTION VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REPAIR.					Sample #:		
101 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	GIRLS' LOCKER ROOM 1105	10 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASES. INACCESSIBLE.					Sample #:		
102 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	GIRLS' LOCKER ROOM 1105	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
103 CAD #:	X1E	Miscellaneous Material 2" X 2" Light Yellow Ceramic Floor Tile System	GIRLS' LOCKER ROOM 1105	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
104 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	GIRLS' LOCKER ROOM OFFICE 1106	25 Lin Ft	Y	3-60 CH	1
Comments: ESTIMATED IN CHASES. OPEN ENDS FROM ORIGINAL CONSTRUCTION VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REPAIR.					Sample #:		
106 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	GIRLS' LOCKER ROOM OFFICE 1106 RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
111 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	BOYS' LOCKER ROOM OFFICE 1108	15 Lin Ft	Y	3-60 CH	1
Comments: ESTIMATED IN WALL CHASES. OPEN ENDS FROM ORIGINAL CONSTRUCTION VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REPAIR.					Sample #:		
113 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	BOYS' LOCKER ROOM OFFICE 1108 RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
114 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	BOYS' LOCKER ROOM 1109	20 Lin Ft	Y	3-60 CH	1
Comments: ESTIMATED IN WALL CHASES. OPEN ENDS FROM ORIGINAL CONSTRUCTION VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REPAIR.					Sample #:		
115 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	BOYS' LOCKER ROOM 1109	10 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASES. INACCESSIBLE.					Sample #:		
116 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	BOYS' LOCKER ROOM 1109	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
117 CAD #:	X1E	Miscellaneous Material 2" X 2" Light Yellow Ceramic Floor Tile System	BOYS' LOCKER ROOM 1109	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
119 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	HALLWAY WEST OF CAFETERIA	240 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE CEILING TILES ARE MISSING BY DOOR 4.					Sample #: 121609ML-12		
120 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1956)	EAST AUXILIARY GYMNASIUM 1110	1300 Sq Ft	N	3-8 CH	5
Comments:					Sample #: SN97-77892		
121 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1956)	WEST AUXILIARY GYMNASIUM 1104	1300 Sq Ft	N	3-8 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
122 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	KITCHEN 1111	20 Lin Ft	N	3-60 CH	5
Comments: ESTIMATE IN WALL CHASES FEEDING SINKS. INACCESSIBLE.					Sample #:		
123 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	KITCHEN 1111	8 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASES FEEDING SINKS. INACCESSIBLE.					Sample #:		
125 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	KITCHEN 1111	9 Sq Ft	N	2 CH	5
Comments: AT SOUTHWEST ENTRANCE.					Sample #:		
128 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	KITCHEN RESTROOM 1111B	15 Lin Ft	Y	3-60 CH	1
Comments: ACCESS THROUGH WALL HATCH. OPEN ENDS FROM ORIGINAL CONSTRUCTION. INACCESSIBLE FOR REPAIR.					Sample #:		
129 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	KITCHEN RESTROOM 1111B	5 Joints	Y	15-20 CH	1
Comments: ACCESS THROUGH WALL HATCH. THREE (3) DAMAGED FITTINGS INACCESSIBLE FOR REPAIR.					Sample #:		
130 CAD #:	U0A	Light Pad Insulation Round	KITCHEN RESTROOM 1111B	1 Sq Ft	Y	70 CH	5
Comments: ONE (1) LIGHT IN RESTROOM.					Sample #:		
134 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	KITCHEN SERVING AREA	100 Sq Ft	N	2 CH	5
Comments:					Sample #:		
137 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	CAFETERIA 1114	800 Sq Ft	N	2 CH	5
Comments:					Sample #:		
142 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	CAFETERIA STORAGE ROOMS 1115/1116	90 Sq Ft	N	2 CH	5
Comments:					Sample #:		
144 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	OFFICE 1201	40 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH. OPEN ENDS FROM ORIGINAL CONSTRUCTION. INACCESSIBLE FOR REPAIR.					Sample #:		
145 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	OFFICE 1201	5 Joints	N	15-20 CH	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH.					Sample #:		
147 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1201	70 Sq Ft	N	2 CH	5
Comments:					Sample #:		
150 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	OFFICE 1201 RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
152 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	UNISEX RESTROOM NEAR ROOM 1202	20 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. OPEN ENDS FROM ORIGINAL CONSTRUCTION. INACCESSIBLE FOR REPAIR. VISIBLE FROM ABOVE CEILING IN HALLWAY.					Sample #:		
153 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	UNISEX RESTROOM NEAR ROOM 1202	4 Joints	N	15-20 CH	5
Comments: ABOVE CEILING. VISIBLE FROM HALLWAY.					Sample #:		
154 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	UNISEX RESTROOM NEAR ROOM 1202	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
156 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1202	70 Sq Ft	N	2 CH	5
Comments:					Sample #:		
158 CAD #:	X1B	Miscellaneous Material 2" X 2" Gray Ceramic Floor Tile System	STAFF MEN'S RESTROOM 1203	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
159 CAD #:	X1F	Miscellaneous Material 4" X 4" Yellow Ceramic Wall Tile System	STAFF MEN'S RESTROOM 1203	450 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
160 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	STAFF WOMEN'S RESTROOM 1304	40 Lin Ft	N	3-60 CH	5
Comments: ABOVE CEILING. VISIBLE FROM HALLWAY.					Sample #:		
161 CAD #:	X1B	Miscellaneous Material 2" X 2" Gray Ceramic Floor Tile System	STAFF WOMEN'S RESTROOM 1304	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
162 CAD #:	X1G	Miscellaneous Material 4" X 4" Pink Ceramic Wall Tile System	STAFF WOMEN'S RESTROOM 1304	450 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
164 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	OFFICE 1205	60 Sq Ft	N	2 CH	5
Comments:					Sample #:		
167 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	HALLWAY FROM ROOMS 1205-1321	240 Lin Ft	Y	3-60 CH	1
Comments: ABOVE CEILING. ESTIMATED IN WALL CHASES FEEDING CLASSROOM SINKS. SOME VISIBLE FROM CEILING HATCHES IN HALLWAY. OPEN ENDS FROM ORIGINAL CONSTRUCTION OUTSIDE ROOM 1205. INACCESSIBLE FOR REPAIR.					Sample #:		
168 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	HALLWAY FROM ROOMS 1205-1321	50 Joints	N	15-20 CH	5
Comments: ABOVE CEILING OUTSIDE ROOM 1305 & ESTIMATED IN WALL CHASES FEEDING CLASSROOM SINKS. SOME VISIBLE FROM CEILING HATCHES IN HALLWAY.					Sample #:		
169 CAD #:	B3A	Pre-Formed Pipe Insulation 1956 Original Building	HALLWAY FROM ROOMS 1205-1321	20 Lin Ft	N	15 CH, 15 AM	5
Comments: ABOVE CEILING. SOME VISIBLE FROM CEILING HATCH OUTSIDE ROOM 1302.					Sample #:		
171 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	HALLWAY FROM ROOMS 1205-1321	1275 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILE IS MISSING OUTSIDE ROOM 1321.					Sample #: 071212MV-02		
172 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	MAINTENANCE ROOM 1206	16 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. SOME VISIBLE FROM HALLWAY.					Sample #:		
173 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	MAINTENANCE ROOM 1206	4 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. VISIBLE FROM HALLWAY.					Sample #:		
179 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STORAGE ROOM 1207	110 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILE IS MISSING.					Sample #: 325-7		
182 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STAIRWELL NEAR ROOM 1207	12 Sq Ft	N	2 CH	5
Comments:					Sample #:		
185 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ENTRANCE TO ROOM 1302	2 Lin Ft	N	3-60 CH	5
Comments: ABOVE CEILING. SOUTHWEST CORNER BY HATCH.					Sample #: 031909BF-01		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
187 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ENTRANCE TO ROOM 1302	30 Sq Ft	N	2 CH	5
Comments:					Sample #:		
189 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1302	40 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
190 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1302	6 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
195 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 1304A	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
202 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 1304B	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
204 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1306	90 Lin Ft	N	3-60 CH	5
Comments: THREE (3) LINES VISIBLE FROM HATCH. INACCESSIBLE.					Sample #:		
205 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1306	3 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #: 031909BF-02		
212 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1308	50 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
213 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1308	3 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
233 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1310	60 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
234 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1310	2 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
239 CAD #:	V0B	Sink Undercoating Black	ROOM 1310	6 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #:		
243 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1312	40 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
244 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1312	3 Joints	N	15-20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN CHASE. INACCESSIBLE.					Sample #:		
247 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 1312	200 Sq Ft	N	2 CH	5
Comments: ABOVE DROP CEILING. SAMPLE 071212MV-03 WAS ANALYZED AS "NONE DETECTED" IN THIS LOCATION.					Sample #: 071212MV-03		
252 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STAIRWELL NEAR ROOM 1312	7 Sq Ft	N	2 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
261 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 1312A	175 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING.					Sample #:		
263 CAD #:	V0B	Sink Undercoating Black	ROOM 1312A	6 Sq Ft	N	3 CH	5
Comments: ONE (1) SINK.					Sample #: 121609ML-28		
264 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 1314	30 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINKS IN ROOMS 1312 & 1312A. SOME VISIBLE FROM CEILING HATCH.					Sample #:		
265 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 1314	4 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINKS IN ROOMS 1312 & 1312A. INACCESSIBLE.					Sample #:		
288 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 1316	225 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING.					Sample #:		
292 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	STORAGE ROOM 1316B	2 Lin Ft	N	3-60 CH	5
Comments: ABOVE CEILING. IN WALL ABOVE DOOR. 1/2' VISIBLE FROM HATCH.					Sample #:		
295 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 1318	215 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING. SAMPLE 071212MV-04 ANALYZED AS "NONE DETECTED" IN THIS LOCATION.					Sample #: 071212MV-04		
297 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1956)	ROOM 1318	860 Sq Ft	N	3-8 CH	5
Comments: UNDER CARPET.					Sample #: 325-5		
299 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 1322	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
310 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 1324	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
312 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STAIRWELL OUTSIDE ROOM 1320	16 Sq Ft	N	2 CH	5
Comments:					Sample #:		
315 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 1320	110 Sq Ft	N	2 CH	5
Comments:					Sample #:		
316 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1956)	ROOM 1320	880 Sq Ft	N	3-8 CH	5
Comments: UNDER CARPET.					Sample #:		
320 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	HALLWAY FROM ROOMS 2301-2322	1275 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILES ARE MISSING.					Sample #: 071212MV-05		
322 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2322	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
323 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2322	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		



IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
330 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2321	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL FEEDING SINK. INACCESSIBLE.					Sample #:		
331 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2321	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL FEEDING SINK. INACCESSIBLE.					Sample #:		
337 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 2320B	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
338 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2319	25 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. ABOVE CEILING. INACCESSIBLE.					Sample #:		
339 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2319	4 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. ABOVE CEILING. INACCESSIBLE.					Sample #:		
345 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 2320A	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
346 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2320	25 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. ABOVE CEILING. INACCESSIBLE.					Sample #:		
347 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2320	4 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. ABOVE CEILING. INACCESSIBLE.					Sample #:		
353 CAD #:	V0B	Sink Undercoating Black	ROOM 2320	20 Sq Ft	N	3 CH	5
Comments: TWO (2) SINKS.					Sample #:		
354 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2318	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
355 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2318	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
362 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2317	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
363 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2317	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
372 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	STORAGE ROOM 2316	35 Sq Ft	N	2 CH	5
Comments:					Sample #:		
376 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2314	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
377 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2314	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
383 CAD #:	V0B	Sink Undercoating Black	ROOM 2314	20 Sq Ft	N	3 CH	5
Comments: TWO (2) SINKS.					Sample #:		
384 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2315	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
385 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2315	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
393 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	HALLWAY TO ROOMS 2310 & 2312	25 Sq Ft	N	2 CH	5
Comments:					Sample #:		
396 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	ROOM 2312	90 Sq Ft	N	2 CH	5
Comments: EXPOSED ADHESIVE WHERE TILES ARE MISSING.					Sample #: 071212MV-06		
402 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2313	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
403 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2313	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
411 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	STORAGE ROOM 2308A	65 Sq Ft	N	2 CH	5
Comments:					Sample #:		
414 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2311	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
415 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2311	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
425 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Gray w/White & Black Streaks	ROOM 2306C	120 Sq Ft	N	3-4 CH (TILE ONLY)	5
Comments: CHIPS IN TILE NEAR ENTRANCE. SLIGHT CRACKING PRESENT.					Sample #: 032014MV-01; 121609ML-3; 2001-1501-H2-04		
426 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2309	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
427 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2309	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE WHERE ORIGINAL SINK ONCE WAS. INACCESSIBLE.					Sample #:		
434 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2307	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
435 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2307	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
452 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2305	4 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
453 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2305	2 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. INACCESSIBLE.					Sample #:		
459 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 2302D	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
462 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 2304	200 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING AT NE CORNER.					Sample #:		
465 CAD #:	B2A	Millboard Pipe Insulation 1956 Original Building	ROOM 2303	25 Lin Ft	N	3-60 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK. ABOVE CEILING. INACCESSIBLE.					Sample #:		
466 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1956 Original Building	ROOM 2303	4 Joints	N	15-20 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING SINK & ABOVE CEILING. INACCESSIBLE.					Sample #:		
472 CAD #:	X1D	Miscellaneous Material 2" X 2" Blue Ceramic Floor Tile System	RESTROOM 2302C	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
479 CAD #:	X0K	Miscellaneous Material Cork Wall Adhesive	ROOM 2302	300 Sq Ft	N	5 CH	5
Comments: BEHIND PEGBOARD ON NORTH WALL.					Sample #: 073012-BF-2		