

## Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

**PLEASE NOTE:** Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
6 CAD #:	X0HH	Miscellaneous Material Exterior Grill Caulking	THROUGHOUT 1954 ADDITION	10 Sq Ft	N	8 CH	5
Comments:							Sample #: 072115BV-06
7 CAD #:	X0G	Miscellaneous Material Wired Window Glazing	THROUGHOUT 1954 ORIGINAL BUILDING CLASSROOMS	6 Sq Ft	N	6 CH	5
Comments:							Sample #: 072115BV-02
11 CAD #:	E1A	Stack Gasket 1954 Original Building	1954 ORIGINAL BUILDING BOILER ROOM 0201	2 Sq Ft	N	15 CH	5
Comments: ON UPPER ACCESS W/CAUTION SIGN AT CHIMNEY.							Sample #: 030209-RV-01
12 CAD #:	X0A	Miscellaneous Material Pipe & Valve Flange Gaskets	1954 ORIGINAL BUILDING BOILER ROOM 0201	25 Sq Ft	N	ASSUMED	5
Comments: APPROXIMATELY TWENTY-FIVE (25) GASKETS.							Sample #:
14 CAD #:	P0A	Fire Doors Metal - Underwriter's Laboratories	1954 ORIGINAL BUILDING BOILER ROOM 0201	22 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. TAG PAINTED.							Sample #:
17 CAD #:	J1D	Cementitious Panels Door Transom	1ST FLOOR HALLWAY OUTSIDE ELEVATOR	6 Sq Ft	N	ASSUMED	5
Comments: ABOVE DOUBLE DOORS.							Sample #:

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
20 CAD #:	J1A	Cementitious Panels Window Panels	CUSTODIAL OFFICE 1210	12 Sq Ft	N	ASSUMED	5
Comments: 2 PANELS					Sample #:		
25 CAD #:	J1A	Cementitious Panels Window Panels	CUSTODIAL OFFICE STORAGE 1211	12 Sq Ft	N	ASSUMED	5
Comments: 2 PANELS. BEHIND ALARM PANEL.					Sample #:		
26 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	CUSTODIAL RESTROOM 1211A	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
27 CAD #:	J1D	Cementitious Panels Door Transom	HALLWAY 1200 OUTSIDE CUSTODIAL OFFICE	6 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
34 CAD #:	J1A	Cementitious Panels Window Panels	ROOM 1209 (LOUNGE)	56 Sq Ft	N	ASSUMED	5
Comments: SEVEN (7) WINDOW PANELS. PAINTED WHITE.					Sample #:		
39 CAD #:	X1J	Miscellaneous Material 1" White, Brown & Beige Ceramic Floor Tile System	KITCHEN 1204	465 Sq Ft	N	ASSUMED	5
Comments: INCLUDES ROOMS 1204, 1205 & 1208.					Sample #:		
40 CAD #:	X1K	Miscellaneous Material 1" White, Brown & Tan Ceramic Floor Tile System	KITCHEN 1204	266 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
41 CAD #:	B3A	Pre-Formed Pipe Insulation (1954)	KITCHEN STORAGE 1207	1 Lin Ft	N	ASSUMED	5
Comments: AT SE CORNER FLOOR PENETRATION TO TUNNEL. ENCAPSULATED.					Sample #:		
45 CAD #:	J1A	Cementitious Panels Window Panels	KITCHEN STORAGE 1207	100 Sq Ft	N	ASSUMED	5
Comments: FIFTEEN (15) PANELS. PAINTED WHITE.					Sample #:		
48 CAD #:	A4D	Mudded Pipe Joints on Fiberglass Insulation	KITCHEN MECHANICAL ROOM 1206	12 Joints	N	50 CH	5
Comments: SMALLER LINES.					Sample #: 072115BV-01		
49 CAD #:	L0B	Flexible Duct Connector Coarse White Fabric	KITCHEN MECHANICAL ROOM 1206	5 Sq Ft	N	45 CH	5
Comments: ONE (1) JOINT.					Sample #: 524-JJT-16		
51 CAD #:	X1S	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System	KITCHEN RESTROOM 1205A	32 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
56 CAD #:	T0A	Light Cord Insulation White Fuzzy Cords	CAFETERIA (1203)	24 Lin Ft	N	ASSUMED	5
Comments: TWELVE (12) LIGHTS. IN RECESSED AREA.					Sample #:		
64 CAD #:	X1O	Miscellaneous Material Multi-Sized Blue & Pink Ceramic Floor Tile System	GIRLS' RESTROOM (1202B)	45 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
65 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	BOYS' RESTROOM (1202A)	72 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
85 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	ROOMS 1102-1106 & RESTROOMS	120 Lin Ft	N	20 CH	5
Comments: IN WALLS FOR SINKS & RESTROOM FIXTURES. VERIFIED OUTSIDE ROOM 1103 GOING UP TO 2ND FLOOR. INACCESSIBLE FOR REMOVAL.					Sample #: 450U-A-4, 5, 6;		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
91 CAD #:	X1M	Miscellaneous Material 2" Gray Ceramic Floor Tile System	ROOM 1112A (NURSE'S OFFICE RESTROOM)	36 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
92 CAD #:	X1N	Miscellaneous Material 4" White Ceramic Wall Tile System	ROOM 1112A (NURSE'S OFFICE RESTROOM)	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
93 CAD #:	P0B	Fire Doors Wood Composite - 30 Min Rating (Weyerhaeuser)	ROOM 1113	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
94 CAD #:	P0B	Fire Doors Wood Composite - 30 Min Rating (Weyerhaeuser)	ROOM 1115	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
101 CAD #:	P0B	Fire Doors Wood Composite - 30 Min Rating (Weyerhaeuser)	ROOM 1111	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
108 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	GIRLS' RESTROOM 1109	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
114 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	CUSTODIAL CLOSET 1108	3 Sq Ft	N	ASSUMED	5
Comments: SLOP SINK.					Sample #:		
120 CAD #:	X1O	Miscellaneous Material Multi-Sized Blue & Pink Ceramic Floor Tile System	BOYS' RESTROOM 1107	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
125 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	1954 ORIGINAL BUILDING NORTH HALLWAY 1600	200 Lin Ft	N	20 CH	5
Comments: ABOVE CEILING TILE/PLASTER SYSTEM. ACCESS THROUGH CEILING GRATES. INACCESSIBLE FOR REMOVAL.					Sample #:		
126 CAD #:	B3A	Pre-Formed Pipe Insulation (1954)	1954 ORIGINAL BUILDING NORTH HALLWAY 1600	8 Lin Ft	N	ASSUMED	5
Comments: UNDER WALL RADIATORS AT PENETRATIONS TO TUNNEL. ENCAPSULATED.					Sample #:		
137 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	ROOM 1602 & RESTROOM 1602A	50 Lin Ft	N	20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN WALL CHASE FOR RESTROOM. INACCESSIBLE FOR REMOVAL.					Sample #:		
138 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	RESTROOM 1602A	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
145 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	ROOM 1603 & RESTROOM 1603A	50 Lin Ft	N	20 CH	5
Comments: ESTIMATED ABOVE CEILING & IN WALL CHASE FOR RESTROOM. INACCESSIBLE FOR REMOVAL.					Sample #:		
146 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	RESTROOM 1603A	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
150 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	1954 ORIGINAL BUILDING 2ND FLOOR HALLWAY 2100	26 Lin Ft	N	20 CH	5
Comments: ABOVE CEILING. TWO (2) ROOF DRAINS. INACCESSIBLE FOR REMOVAL.					Sample #:		
151 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1954 Original Building	1954 ORIGINAL BUILDING 2ND FLOOR HALLWAY 2100	4 Joints	N	50 CH	5
Comments: ABOVE CEILING. TWO (2) ROOF DRAINS. INACCESSIBLE FOR REMOVAL.					Sample #: 207N-4A		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
156 CAD #:	B2A	Millboard Pipe Insulation 1954 Original Building	ROOMS 2101-2106 & RESTROOMS 2107 & 2109	50 Lin Ft	N	20 CH	5
Comments: INACCESSIBLE IN WALLS FOR SINKS AND RESTROOM FIXTURES. VISIBLE IN ROOM 2102 UNDER SINK.					Sample #:		
159 CAD #:	V0A	Sink Undercoating Lavender	ROOM 2101	10 Sq Ft	N	5 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #: 030209-RV-07		
173 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	GIRLS' RESTROOM 2109	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
176 CAD #:	X1I	Miscellaneous Material Multi-Sized Blue, Gray & Tan Ceramic Floor Tile System	CUSTODIAL CLOSET 2108	3 Sq Ft	N	ASSUMED	5
Comments: SLOP SINK.					Sample #:		
179 CAD #:	X1O	Miscellaneous Material Multi-Sized Blue & Pink Ceramic Floor Tile System	BOYS' RESTROOM 2107	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
185 CAD #:	X1Q	Miscellaneous Material 6" Red Quarry Tile	THROUGHOUT 1973 ADDITION	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
187 CAD #:	J2A	Transite Piping/Ducting 10"-30" Ducting (1974)	THROUGHOUT 1974 ADDITION	440 Sq Ft	N	ASSUMED	5
Comments: BELOW SLAB. VISIBLE FROM TUNNELS. CAN SEE IT WHERE DUCT WORK FUNNELS INTO THE WALL. SEE 1973 BLUEPRINT M2 FOR SPECIFIC LOCATIONS.					Sample #:		
192 CAD #:	X0H	Miscellaneous Material Tan Exterior Duct Caulking	1973 ADDITION TUNNELS	20 Sq Ft	N	10 CH	5
Comments:					Sample #: 072115BV-04		
193 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1306	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		
195 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1305	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
196 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1303	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
197 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1302	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
202 CAD #:	X1P	Miscellaneous Material 1" Beige Ceramic Wall Tile System	STORAGE 1311	170 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
211 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1403	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
216 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1406	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
217 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1409	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
218 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1410	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK. NO HARDWARE ATTACHED					Sample #:		
220 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1413	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
225 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1509	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		
226 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1506	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
229 CAD #:	V0D	Sink Undercoating Black (1974)	ROOM 1504	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 030209-RV-14		
230 CAD #:	V0E	Sink Undercoating White	ROOM 1504	10 Sq Ft	N	5 CH	5
Comments: TWO (2) SINKS.					Sample #: 030209-RV-15		