

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

| | | |
|-----------------------------------|--|--|
| EPA ASSESSMENT CATEGORIES: | 1 = Damaged or significantly damaged TSI ACM | 5 = ACBM with potential for damage |
| | 2 = Damaged friable surfacing ACM | 6 = ACBM with potential for significant damage |
| | 3 = Significantly damaged friable surfacing ACM | 7 = Remaining friable ACBM or friable suspect ACBM |
| | 4 = Damaged or significantly damaged friable miscellaneous ACM | |
| | | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|--|---------------|---|------------------|------------------------|-----------------------|---------------|---------------------|
| 11 CAD #: | P0A | Fire Doors Wood -1.5 Hr Rating (Warnock Hersey) | BOILER ROOM 1205 | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: ONE (1) DOOR. DOOR TO ROOM 1305. | | | | | Sample #: | | |
| 23 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1204 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARDS. | | | | | Sample #: | | |
| 28 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1203 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARDS. | | | | | Sample #: | | |
| 34 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1202 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARDS. | | | | | Sample #: 092712MV-29 | | |
| 40 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1201 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARDS. | | | | | Sample #: | | |
| 61 CAD #: | X0C | Miscellaneous Material Metal Frame Chalkboard Adhesive | ROOM 1103 | 10 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|---|---------------|---|-------------------------------|------------------------|-----------------------|---------------|---------------------|
| 70 CAD #: | X0H | Miscellaneous Material Red Fire Stop | LIBRARY ELECTRICAL ROOM 1104A | 3 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 71 CAD #: | P0C | Fire Doors Wood Jacket -1.5 Hr Rating (Intertek) | LIBRARY ELECTRICAL ROOM 1104A | 30 Sq Ft | N | ASSUMED | 5 |
| Comments: TWO (2) DOORS. | | | | | Sample #: | | |
| 73 CAD #: | P0C | Fire Doors Wood Jacket -1.5 Hr Rating (Intertek) | LIBRARY FAN ROOM 1104A | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: ONE (1) DOOR. | | | | | Sample #: | | |
| 74 CAD #: | X0H | Miscellaneous Material Red Fire Stop | LIBRARY FAN ROOM 1104A | 5 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 80 CAD #: | B1A | Air Cell Pipe Insulation | ROOM 1502 | 20 Lin Ft | N | ASSUMED | 5 |
| Comments: INACCESSIBLE. ONE (1) LINE IN WALL FEEDING CUH IN HALLWAY. | | | | | Sample #: | | |
| 81 CAD #: | B2A | Millboard Pipe Insulation | ROOM 1502 | 10 Lin Ft | N | 20 CH | 5 |
| Comments: INACCESSIBLE. ONE (1) LINE IN WALL FEEDING WATER FOUNTAIN IN HALLWAY. | | | | | Sample #: 032513JD-01 | | |
| 82 CAD #: | A2A | Mudded Pipe Joints on Millboard Insulation | ROOM 1502 | 2 Joints | N | 15 CH, 5 AM | 5 |
| Comments: ABOVE CEILING. | | | | | Sample #: 032513JD-02 | | |
| 85 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1502 | 10 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARD. | | | | | Sample #: | | |
| 88 CAD #: | B2A | Millboard Pipe Insulation | ROOM 1502B RESTROOM | 10 Lin Ft | N | 20 CH | 5 |
| Comments: INACCESSIBLE. IN SOUTH WALL (COLD WATER LINE). | | | | | Sample #: | | |
| 89 CAD #: | B1A | Air Cell Pipe Insulation | ROOM 1502B RESTROOM | 10 Lin Ft | N | ASSUMED | 5 |
| Comments: INACCESSIBLE. IN SOUTH WALL (HOT WATER LINE). | | | | | Sample #: | | |
| 91 CAD #: | X1F | Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System | ROOM 1502B RESTROOM | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 94 CAD #: | B1A | Air Cell Pipe Insulation | ROOM 1503 ENTRANCE | 20 Lin Ft | N | ASSUMED | 5 |
| Comments: INACCESSIBLE. TWO (2) LINES IN WALL FEEDING CUH. | | | | | Sample #: | | |
| 97 CAD #: | B2A | Millboard Pipe Insulation | ROOM 1504 | 25 Lin Ft | N | 20 CH | 5 |
| Comments: INACCESSIBLE. IN WALL BY ENTRANCE & UNDER CABINETS FEEDING SINK. | | | | | Sample #: | | |
| 98 CAD #: | B1A | Air Cell Pipe Insulation | ROOM 1504 | 25 Lin Ft | N | ASSUMED | 5 |
| Comments: INACCESSIBLE. IN WALL BY ENTRANCE & UNDER CABINETS FEEDING SINK. | | | | | Sample #: | | |
| 100 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 1504 | 10 Sq Ft | N | 2 CH | 5 |
| Comments: BEHIND WHITEBOARD. | | | | | Sample #: | | |
| 104 CAD #: | X1G | Miscellaneous Material Multi-Sized Blue Ceramic Floor Tile System | ROOM 1504 RESTROOM (1504B) | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|--------------------------|---------------|---|---------------------------------|------------------------|------------|---------------|---------------------|
| 118 CAD #: | X0G | Miscellaneous Material Metal Frame Corkboard Adhesive | ROOM 1304 | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 127 CAD #: | X0G | Miscellaneous Material Metal Frame Corkboard Adhesive | ROOM 1303 | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 132 CAD #: | P0E | Fire Doors Metal -45/90 Rating (Intertek) | LOADING DOCK 1407 | 40 Sq Ft | N | ASSUMED | 5 |
| Comments: TWO (2) DOORS. | | | | | Sample #: | | |
| 148 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2204 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 154 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2203 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 160 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2205 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 168 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2202 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 174 CAD #: | X1I | Miscellaneous Material Black/Brown Marble-Look Countertop | ROOM 2206 | 30 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 175 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2206 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 180 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2201 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 187 CAD #: | X0B | Miscellaneous Material Wood Frame Chalkboard Adhesive | ROOM 2207 | 40 Sq Ft | N | 2 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 189 CAD #: | X1I | Miscellaneous Material Black/Brown Marble-Look Countertop | ROOM 2207 | 30 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 196 CAD #: | X1F | Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System | STAFF RESTROOM 2102A | 25 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 199 CAD #: | X1G | Miscellaneous Material Multi-Sized Blue Ceramic Floor Tile System | 2ND FLOOR GIRLS' SOUTH RESTROOM | 200 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 202 CAD #: | X1J | Miscellaneous Material Multi-Sized Brown Ceramic Floor Tile System | 2ND FLOOR BOYS' SOUTH RESTROOM | 200 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 204 CAD #: | X1K | Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System | 2ND FLOOR BOYS' SOUTH RESTROOM | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |