

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

| | | |
|-----------------------------------|--|--|
| EPA ASSESSMENT CATEGORIES: | 1 = Damaged or significantly damaged TSI ACM | 5 = ACBM with potential for damage |
| | 2 = Damaged friable surfacing ACM | 6 = ACBM with potential for significant damage |
| | 3 = Significantly damaged friable surfacing ACM | 7 = Remaining friable ACBM or friable suspect ACBM |
| | 4 = Damaged or significantly damaged friable miscellaneous ACM | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|---|---------------|--|------------------------------|------------------------|----------------------|-----------------------------|---------------------|
| 7 CAD #: | J1A | Cementitious Panels Ceiling Panels | HALLWAY 1000 | 1200 Sq Ft | N | 60 CH | 5 |
| Comments: AIR PLENUM ABOVE PLASTER CEILING IN HALLWAY 1000 & ENTRY 1000A. INACCESSIBLE. SOME VISIBLE FROM CEILING HATCH IN KITCHEN. | | | | | Sample #: | | |
| 8 CAD #: | P0A | Fire Doors Metal - 1-1/2 Hr Rating (Underwriter's Laboratories) | BOILER ROOM 1107 | 20 Sq Ft | N | ASSUMED | 5 |
| Comments: ONE (1) DOOR. TAG PAINTED. | | | | | Sample #: | | |
| 9 CAD #: | J2A | Transite Piping/Ducting Round Transite Ductwork | TUNNEL & UNDER CONCRETE SLAB | 1000 Sq Ft | N | ASSUMED | 5 |
| Comments: VISIBLE IN TUNNEL. INACCESSIBLE. SOME VISIBLE FROM CEILING HATCH IN KITCHEN. | | | | | Sample #: | | |
| 10 CAD #: | K0B | 9" x 9" Vinyl Floor Tile & Mastic Tan w/White & Brown Streaks | STORAGE ROOM 1104 | 300 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: REPLACEMENT TILES AT ENTRANCE. | | | | | Sample #: 102110MV-9 | | |
| 11 CAD #: | X1B | Miscellaneous Material 6" X 6" Red Quarry Floor Tile System | KITCHEN 1103 | 150 Sq Ft | N | ASSUMED | 5 |
| Comments: | | | | | Sample #: | | |
| 13 CAD #: | V0A | Sink Undercoating Black | KITCHEN 1103 | 8 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) DOUBLE SINK. | | | | | Sample #: | | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|---|---------------|--|-----------------------------|------------------------|-------------------------|-----------------------------|---------------------|
| 14 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | THROUGHOUT MAIN OFFICE 1001 | 1500 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: INCLUDES ROOMS 1002-1006. WEARING UNDER RECEPTIONIST'S DESK & NURSE'S OFFICE & PRINCIPAL'S OFFICE. RECOMMEND CHAIR MATS. CHIPPED AT DOOR 1000B. | | | | | Sample #: | | |
| 16 CAD #: | X0B | Miscellaneous Material Chalkboard Adhesive | OFFICE 1002 | 10 Sq Ft | N | 5 CH | 5 |
| Comments: BEHIND NEW WHITEBOARD. | | | | | Sample #: 071311-BF-2 | | |
| 17 CAD #: | V0A | Sink Undercoating Black | OFFICE 1004 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 18 CAD #: | U0A | Light Pad Insulation White | OFFICE HALLWAY 1000B | 2 Sq Ft | N | 70 CH | 5 |
| Comments: TWO (2) ROUND LIGHTS. | | | | | Sample #: 2001-01356-1B | | |
| 21 CAD #: | V0A | Sink Undercoating Black | LOUNGE 1006 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: 102110MV-14 | | |
| 28 CAD #: | K0B | 9" x 9" Vinyl Floor Tile & Mastic Tan w/White & Brown Streaks | STORAGE ROOM 1102 | 120 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: CHIPPED W/PIECES MISSING AT ENTRANCE. | | | | | Sample #: 581-04 | | |
| 29 CAD #: | U0A | Light Pad Insulation White | STORAGE ROOM 1102 | 1 Sq Ft | N | 70 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 30 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | STORAGE ROOM 1201 | 75 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: TILE WEAR AT SECOND DOOR. | | | | | Sample #: | | |
| 31 CAD #: | U0A | Light Pad Insulation White | STORAGE ROOM 1201 | 1 Sq Ft | N | 70 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 33 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | STAGE OFFICE 1204A | 65 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: CHIPPED NEAR WEST DOOR. | | | | | Sample #: 102110MV-8 | | |
| 35 CAD #: | U0A | Light Pad Insulation White | RESTROOM 1201A | 1 Sq Ft | N | 70 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 36 CAD #: | U0A | Light Pad Insulation White | RESTROOM 1202 | 1 Sq Ft | N | 70 CH | 5 |
| Comments: | | | | | Sample #: | | |
| 39 CAD #: | J1A | Cementitious Panels Ceiling Panels | HALLWAY 1200 | 1200 Sq Ft | N | 60 CH | 5 |
| Comments: AIR PLENUM ABOVE PLASTER CEILING. ACCESS THROUGH CEILING HATCH. | | | | | Sample #: 581-02 | | |
| 40 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1203 | 1200 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: SLIGHT WEARING NEAR ENTRANCE. SEVERAL TILES LOOSE NEAR WEST WHITEBOARD. | | | | | Sample #: | | |
| 41 CAD #: | V0A | Sink Undercoating Black | ROOM 1203 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 42 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1204 | 1200 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: SLIGHT WEARING NEAR ENTRANCE. REPLACEMENT TILES BY EXTERIOR ENTRANCE. CHIPPED TILE IN NORTHEAST CORNER. SEVERAL TILES LOOSE NEAR WEST WHITEBOARD. | | | | | Sample #: | | |

| IEA Event No. | Material Type | Material Description/Id | Location | Estimated Amount Total | Friability | % of Asbestos | EPA Assess Category |
|---|---------------|--|---------------------|------------------------|------------------------|--------------------------------|---------------------|
| 43 CAD #: | V0A | Sink Undercoating Black | ROOM 1204 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 47 CAD #: | V0A | Sink Undercoating Black | ROOM 1205 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 48 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1206 | 1200 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: SLIGHT WEARING NEAR ENTRANCE. SEVERAL TILES COMING LOOSE NEAR EXTERIOR ENTRANCE. REPLACEMENT TILES AT EXTERIOR ENTRANCE. | | | | | Sample #: | | |
| 49 CAD #: | V0A | Sink Undercoating Black | ROOM 1206 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 52 CAD #: | J1A | Cementitious Panels Ceiling Panels | HALLWAY 1300 | 700 Sq Ft | N | 60 CH | 5 |
| Comments: AIR PLENUM ABOVE PLASTER CEILING. ACCESS THROUGH CEILING HATCH. | | | | | Sample #: | | |
| 54 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1302 | 1200 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: CRACKING, CHIPPING & WEARING AT ENTRANCE. REPLACEMENT TILES AT EXTERIOR ENTRANCE. | | | | | Sample #: 2001-01161-1 | | |
| 55 CAD #: | V0A | Sink Undercoating Black | ROOM 1302 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 58 CAD #: | V0A | Sink Undercoating Black | ROOM 1301 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 60 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1303 | 1200 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: PARTIALLY CARPETED. SLIGHT WEARING AT ENTRANCE. REPLACEMENT TILES AT EXTERIOR ENTRANCE. | | | | | Sample #: | | |
| 62 CAD #: | V0A | Sink Undercoating Black | ROOM 1303 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 64 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1303C STORAGE | 12 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: | | | | | Sample #: | | |
| 65 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1304 | 1500 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: PARTIALLY CARPETED. SLIGHT WEARING AT ENTRANCE. CRACKING DOWN MIDDLE OF ROOM & BY RESTROOMS. GOUGES ON NORTH END BY CABINETS. CRACKING AND CHIPPED PIECE SOUTH END BY DOOR. | | | | | Sample #: | | |
| 68 CAD #: | J1A | Cementitious Panels Ceiling Panels | ROOM 1304 | 500 Sq Ft | N | 60 CH | 5 |
| Comments: AIR PLENUM ABOVE I4A. | | | | | Sample #: | | |
| 69 CAD #: | V0A | Sink Undercoating Black | ROOM 1304 | 6 Sq Ft | N | 3 CH | 5 |
| Comments: ONE (1) SINK. | | | | | Sample #: | | |
| 70 CAD #: | U0A | Light Pad Insulation White | ROOM 1304 RESTROOMS | 2 Sq Ft | N | 70 CH | 5 |
| Comments: TWO (2) LIGHTS. | | | | | Sample #: | | |
| 72 CAD #: | K0A | 9" x 9" Vinyl Floor Tile & Mastic White w/Light Streaks | ROOM 1304C STORAGE | 40 Sq Ft | N | 5 CH (TILE), 10 CH (MASTIC) | 5 |
| Comments: | | | | | Sample #: | | |