

2023 - 2024 Ventilation Assessment



Contact Us:

BROOKLYN PARK OFFICE

9201 W. BROADWAY, #600 BROOKLYN PARK, MN 55445 763-315-7900

MANKATO OFFICE

610 N. RIVERFRONT DRIVE MANKATO, MN 56001 507-345-8818

ROCHESTER OFFICE

210 WOOD LAKE DRIVE SE ROCHESTER, MN 55904 507-281-6664

BRAINERD OFFICE

601 NW 5TH STREET SUITE #4 BRAINERD, MN 56401 218-454-0703

MARSHALL OFFICE

1420 EAST COLLEGE DRIVE MARSHALL, MN 56258 507-476-3599

VIRGINIA OFFICE

5525 EMERALD AVENUE MOUNTAIN IRON, MN 55768 218-410-9521

www.ieasafety.com

info@ieasafety.com

800-233-9513

Saint Paul Public Schools Battle Creek Middle School

Assessment Date: Friday, April 21, 2023

Project Description

IEA conducted a ventilation inspection in Battle Creek Middle School by IEA representative, Sashya Wandmaker, with the intent of gathering visual observations and overall ventilation information which will assist the District in making informed and proactive decisions to improve and maintain acceptable air quality in the building. This inspection is based upon the Environmental Protection Agency's (EPA's) Tools for Schools IAQ guidelines and the recommended Minnesota Department of Education (MDE) portion of a school district's IAQ management plan. Ventilation verification is also recommended by American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE).

Some observations gathered during the inspection may identify issues which may require additional testing, evaluation, further investigation, or maintenance on the ventilation systems.

The findings, conclusions and recommendations presented herein are believed to be accurate and representative of the building on the date and time of the inspection.

GENERAL COMMENTS

The analysis and opinions expressed in this report are based upon data obtained from Saint Paul Public Schools at the indicated locations. This report does not reflect variations in conditions that may occur across the site, property, or facility. Actual conditions may vary and may not become evident without further assessment.

The report is prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted indoor air quality practices. Other than as provided in the preceding sentence, no warranties are extended or made.

Building Information

General information regarding the building was collected by IEA during an interview with building maintenance staff. The information gathered during this process is a vital component, as it is helpful in determining how these items may play a role in possible IAQ related issues.

Below is a summary of the information gathered during the interview:

- Automation controls are managed internally.
- A Building Automation System is present. The automation control software program is Tridium and controls can be accessed remotely.
- Schedules:

Ventilation operation:

Day:	Occupied?	Start	End
		Time:	Time:
Monday- Friday	Yes	5:30 AM	9:00 PM
Monday- Friday	Yes	6:30 AM	5:00 PM

Typical occupancy:


Day:	Occupied?	Start Time:	End Time:
Monday- Friday	Yes		4:30 PM
Saturday	No		
Sunday	No		
Holiday	No		

- CO2 sensors are not associated with the ventilation system.
- VAVs are present. They are not fan powered.
- Building does not have variable frequency drives (VFD).
- The heating system is a hot water boiler.
- A cooling system is not present.
- Filters used are:

Filter Type	MERV Rating
Pleated	MERV 11

- Filters are changed quarterly.
- Energy Recovery Units are not present.
- Units do not contain system Enhancements.
- Personal air purifiers are supplied for individual rooms. They are Winix /Areomax2.0.
 - o Location: In classrooms with low circulation
- It is not known whether or not the building was commissioned during the original construction.

Air Handling Unit Designations & Service Zones:1st Floor



4 of 28 |

Air Handling Unit Designations & Service Zones: 2nd Floor



Assessment

Ventilation System

The following information was gathered by IEA on Friday, April 21, 2023 with support from the district building representative during the on-site interview. The type of heating, ventilating and air-conditioning (HVAC) system and its assessment is included for each unit below:

(IIVAC)	System and its a.	ssessifierit is iriciuueu i	or each and below.
Unit De	esignation:	AHU-01	
Locatio	n of Unit:	Boiler room 1502	
Areas S	erved:	Home Economics-See	Attached Map
System	Enhancements:	None	
Su	pply System	Outdoor Air	Cleanliness and Observations
Filter T	Energy Recovery Unit (ERU) - None ype - Mixed	Outdoor air intake is	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is inaccessible, and its condition is not known.
			The general condition of the differs good.

Water Cooling - None Energy Recovery Unit (ERU) - None Pre-filter: None Main filter: Pleated, MERV 11 Water unknown location. It is not known if there are nearby pollution sources. Outdoor air intake is in good condition. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals.	Unit Des	ignation:	AHU-02	
System Enhancements: Supply System Outdoor Air Cleanliness and Observations Outdoor air intake is Supply System Constant Volume Outdoor air intake is Heating - Hot Water Energy Recovery Unit (ERU) - None Filter Type - Mixed Pre-filter: None Main filter: Pleated, MERV 11 Cleanliness and Observations Outdoor air intake is Outdoor air intake is Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of some condition is not known. Outdoor air intake is It is not known if there are nearby pollution sources. Outdoor air intake is It is not known if there are nearby pollution sources. Outdoor air intake is It is not known if there are nearby pollution sources. Outdoor air intake is It is not known. Outdoor air intake is It is not known if there are nearby pollution sources. Outdoor air intake is It is not known. It is not known. Outdoor air intake is It is not known. Outdoor air intake is It is not known. Outdoor air intake is It is not known. It is not known. Outdoor air intake is It is not known. Outdoor air intake is It is not known. It is not known. Outdoor air intake is It is not known. Outdoor air intake is It is not	Location	of Unit:	Boiler room 1502	
Type Supply System Constant Volume Heating - Hot Water Energy Recovery Unit (ERU) - None Pre-filter: None Main filter: Pleated, MERV 11 Outdoor air intake is inaccessible Outdoor air intake is inaccessible Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filter are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pans are not applicable or not present. Drain pan condition is not known. Outdoor air intake is in good condition. Heating coils are inaccessible. Heat wheels are not present. Heating coils are inaccessible. Exterior ducting is visible. Exterior ducting insulation in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals.	Areas Se	rved:	Music-See Attached M	Лар
Outdoor air intake is Supply System Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed Main filter: Pleated, MERV 11 Outdoor air intake is located in an unknown if in good condition. Main filter: Pleated, MERV 11 Outdoor air intake is located in an unknown if in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. There are nearby Couldoor air intake is in good condition. Mixed air pre-filters are not present. Mixed air main filter are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. There are nearby Couldoor air intake is in good condition. Mixed air pre-filters are not present. Mixed air pre-filters are not present	System E	Enhancements:	None	
 Supply System Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed Pre-filter: None Main filter: Pleated, MERV 11 Return air filters are not present. Mixed air main filter are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. there are nearby condition is not known. Filter Type - Mixed Pre-filter: None Main filter: Pleated, MERV 11 Laterior ducting is visible. Exterior ducting insulation is not visible. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. 	Sup	ply System	Outdoor Air	Cleanliness and Observations
Outside damper is inaccessible, and its condition is not known. Return damper is inaccessible, and its condition is not known.	• ! • ! • ! • ! • ! Filter Ty	Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Pre-filter: None Main filter: Pleated, MERV	inaccessible Outdoor air intake is located in an unknown location. It is not known if there are nearby pollution sources. Outdoor air intake is	Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is inaccessible, and its condition is not

Unit Designation:	AHU-03	
Location of Unit:	1006 mechanical roc	om
Areas Served:	Administration-See A	Attached Map
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Water • Cooling - Dx	is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible and cooling coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is closed, and its condition is good. The general condition of the unit is good.

Unit Designation:	AHU-04	
Location of Unit:	1103B, access filters window into 1103B.	through a panel in room 1103. Panel is above viewing
Areas Served:	Shops-See Attached	Мар
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
• Supply System - Constant Volume • Heating - Hot Water • Cooling - None • Energy Recovery Unit (ERU) - None Filter Type - Mixed • Pre-filter: None • Main filter: Pleated, MERV 11	Outdoor air intake is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	

Unit D	Designation:	AHU-05	
Locati	ion of Unit:	Boiler room 1502 me	ezzanine
Areas	Served:	Auditorium-See Atta	ched Maps
Syster	m Enhancements:	None	
S	upply System	Outdoor Air	Cleanliness and Observations
Type		Outdoor air intake is	Outdoor air filters are not present.
•	Supply System -	accessible	
	Constant		Return air filters are not present.
	Volume	Outdoor air intake is	
•	•		Mixed air pre-filters are not present. Mixed air main filters
	Water	exterior wall.	are clean and not in need of replacement (scoring 1 out of
•	Cooling - None		5) and fit well. Mixed air main filters are installed correctly.
•		No nearby pollution	
	Recovery Unit	sources were found.	Drain pans are not applicable or not present. Drain pan
	(ERU) - None		condition is not known.
		Outdoor air intake is	
		in good condition.	Heating coils are inaccessible.
•	Pre-filter: None		Hard for the control of the control
•	Main filter:		Heat wheels are not present.
	Pleated, MERV		Catanian duration is visible. Catanian duration is substitution in the
	11		Exterior ducting is visible. Exterior ducting insulation is not
			present.
			Interior ducting is visible. Interior ducting insulation is in
			good condition. Interior ducting is clean.
			good condition. Interior ducting is clean.
			Air handling room is free of trash/chemicals.
			Outside damper is inaccessible, and its condition is not
			known.
			Return damper is open, and its condition is good.
			The general condition of the unit is good.

Unit D	esignation:	AHU-06	
Locati	on of Unit:	Boiler room 1502 me	ezzanine
Areas	Served:	Boiler Room-See Att	ached Maps
System Enhancements:		None	
S	upply System	Outdoor Air	Cleanliness and Observations
Type			Outdoor air filters are not present.
•	Supply System -	is accessible	
	Constant		Return air filters are not present.
	Volume	Outdoor air intake	
•		is located on an	Mixed air pre-filters are not present. Mixed air main filters
	Water	exterior wall.	are clean and not in need of replacement (scoring 1 out of
•	Cooling - None	Nia waa waxa a libaa a	5) and fit well. Mixed air main filters are installed
•		No nearby pollution sources were found.	incorrectly.
	Recovery Unit (ERU) - None	sources were round.	Drain pans are not applicable or not present. Drain pan
	(ENO) - NOITE	Outdoor air intake	condition is not known.
Filter '	Type - Mixed	is in good condition.	condition is not known.
•	Pre-filter: None	is in good condition.	Heating coils are inaccessible.
•	Main filter:		The same and made and
	Pleated		Heat wheels are not present.
			Exterior ducting is visible. Exterior ducting insulation is not present.
			Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean.
			Air handling room is free of trash/chemicals.
			Outside damper is open, and its condition is good.
			Return damper is open, and its condition is good.
			The general condition of the unit is good.

Unit I	Designation:	AHU-07	
Locat	ion of Unit:	2302A	
Areas	Served:	2nd Floor East Clas	srooms-See Attached Maps
Syste	m Enhancements:	None	
9	Supply System	Outdoor Air	Cleanliness and Observations
Туре		Outdoor air intake	Outdoor air filters are not present.
•	Supply System -	is accessible	
	Constant		Return air filters are not present.
	Volume	Outdoor air intake	
•	Heating - None	is located on the	Mixed air pre-filters are not present. Mixed air main filters
•	Cooling - None		are clean and not in need of replacement (scoring 2 out of 5)
•	Energy		and fit well. Mixed air main filters are installed incorrectly.
	Recovery Unit	No nearby	
	(ERU) - None	-	Drain pans are not applicable or not present. Drain pan
		were found.	condition is not known.
<u>Filter</u>	Type - Mixed		
•			Heat wheels are not present.
•	Main filter:	is in good	
	Pleated, MERV	condition.	Exterior ducting is visible. Exterior ducting insulation is not
	11		present.
			Interior ducting is visible. Interior ducting insulation is not
			Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean.
			present. Interior ducting is clean.
			Air handling room is free of trash/chemicals.
			Outside damper is inaccessible, and its condition is not known.
			Return damper is open, and its condition is good.
			The general condition of the unit is good.

Unit Designation:	AHU-08	
Location of Unit:	2302A	
Areas Served:	North Library-See A	Attached Maps
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - None Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed Pre-filter: None Main filter:	Outdoor air intake is accessible Outdoor air intake is located on the roof. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pans are not applicable or not present. Drain pan condition is not known. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present.
		Interior ducting is not visible. Interior ducting insulation is not present. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Designation:	AHU-09	
Location of Unit:	2102 mechanical roc	om
Areas Served:	2nd Floor Southeast	Classrooms-See Attached Maps
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None	is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pan plugged status is not known. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is closed, and its condition is good.

Unit Designation:		AHU-10		
Location of Unit:		2102, ceiling		
Areas Served:		South Library-See At	tached Maps	
Syster	m Enhancements:	None		
Si	upply System	Outdoor Air	Cleanliness and Observations	
<u>Type</u>			Outdoor air filters are not present.	
•	Supply System -	is accessible		
	Constant		Return air filters are not present.	
	Volume	Outdoor air intake		
•	•	is located on an	Mixed air pre-filters are not present. Mixed air main filters	
•	J	exterior wall.	are clean and not in need of replacement (scoring 1 out of	
•	Energy Recovery Unit	No poorby pollution	5) and fit well. Mixed air main filters are installed	
	(ERU) - None	No nearby pollution sources were found.	incorrectly.	
	(ENO) - NOITE	Sources were round.	Drain pans are not applicable or not present. Drain pan	
Filter '	Type - Mixed	Outdoor air intake	condition is not known.	
•		is in good condition.	condition is not known.	
•	Main filter:	8000 00	Heat wheels are not present.	
	Pleated, MERV			
	11		Exterior ducting is visible. Exterior ducting insulation is not present.	
			Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness.	
			Air handling room is free of trash/chemicals.	
			Outside damper is inaccessible, and its condition is not known.	
			Return damper is closed, and its condition is good.	
			The general condition of the unit is good.	

Unit Designation:	AHU-11		
Location of Unit:	Mechanical room 2102		
Areas Served:	1st Floor East Classrooms-See Attached Maps		
System Enhancements:	None		
Supply System	Outdoor Air	Cleanliness and Observations	
Type Supply System - Constant Volume Heating - None Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed Pre-filter: None	Outdoor air intake is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit poorly. Mixed air main filters are installed	

Unit Designation:	AHU-12			
Location of Unit:	Mechanical room 2102			
Areas Served:	Cafeteria-See Attached Maps			
System Enhancements:	None			
Supply System	Outdoor Air	Cleanliness and Observations		
 Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None 	is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed incorrectly. Drain pan plugged status is not known. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is inaccessible, and its condition is not known.		

Unit Designation:		AHU-13		
Location of Unit:		2302 mechanical Room		
Areas Served:		Gym-See Attached Maps		
System Enhancements:		None		
9	Supply System	Outdoor Air	Cleanliness and Observations	
Type		Outdoor air intake	Outdoor air filters are not present.	
•	Supply System -	is accessible		
	Constant		Return air filters are not present.	
	Volume	Outdoor air intake		
•	Heating - Hot	is located on the	Mixed air pre-filters are not present. Mixed air main filters	
	Water	roof.	are clean and not in need of replacement (scoring 2 out of 5)	
•	Cooling - None		and fit well. Mixed air main filters are installed correctly.	
•	Energy	No nearby		
	Recovery Unit	pollution sources	Drain pans are not applicable or not present. Drain pan	
	(ERU) - None	were found.	condition is not known.	
Filter	Type - Mixed	Outdoor air intake	Heating coils are inaccessible.	
•	Pre-filter: None	is in good		
•	Main filter:	condition.	Heat wheels are not present.	
	Pleated, MERV			
	11		Exterior ducting is visible. Exterior ducting insulation is not present.	
			Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness.	
			Air handling room is free of trash/chemicals.	
			Outside damper is inaccessible, and its condition is good.	
			Return damper is open, and its condition is good.	
			The general condition of the unit is good.	

Unit Designation:	AHU-14 (100% OA	A)		
Location of Unit:	2110 loading dock, ceiling			
Areas Served:	Kitchen-See Attac	hed Maps		
System	None	None		
Enhancements:				
Supply System	Outdoor Air	Cleanliness and Observations		
<u>Type</u>	Outdoor air	Outdoor air pre-filters are not present. Outdoor air main filters		
 Supply System 	intake is	are somewhat dirty and on the border of needing replacement		
- Constant	accessible	(scoring 3 out of 5) and fit well. Outdoor air main filters are		
Volume		installed correctly.		
 Heating - Hot 	Outdoor air			
Water		Return air filters are not present.		
Cooling - None	on the roof.			
• Energy		Drain pan plugged status is not known. Drain pan condition is		
Recovery Unit	No nearby	not known.		
(ERU) - None	pollution sources			
ETHALE AND A LABOR	were found.	Heating coils are inaccessible.		
Filter Type - Outdoor	0	Haak whaala aya gab gaaagt		
Pre-filter: None Nain filter:		Heat wheels are not present.		
Main filter: Name of MEDV	intake is in good	Futoriar dustina in visible. Futoriar dustina insulation is not		
Pleated, MERV 11	condition.	Exterior ducting is visible. Exterior ducting insulation is not present.		
11		present.		
		Interior ducting is visible. Interior ducting insulation is in good		
		condition. Interior ducting is clean.		
		condition. Interior ducting is clean.		
		Air handling room is free of trash/chemicals.		
		Outside damper is inaccessible, and its condition is not known.		
		Return damper is not present.		
		The general condition of the unit is good.		

Unit Designation:		AHU-15		
Location of Unit:		2302 mechanical room		
Areas Served:		Locker Rooms-See Attached Maps		
Systen	n Enhancements:	None		
Sı	upply System	Outdoor Air	Cleanliness and Observations	
Туре		Outdoor air intake	Outdoor air filters are not present.	
•	Supply System -	is accessible		
	Constant		Return air filters are not present.	
	Volume	Outdoor air intake		
•	•		Mixed air pre-filters are not present. Mixed air main filters	
•	•	roof.	are clean and not in need of replacement (scoring 1 out of 5)	
•	Energy		and fit well. Mixed air main filters are installed incorrectly.	
	Recovery Unit	No nearby		
	(ERU) - None	-	Drain pans are not applicable or not present. Drain pan	
		were found.	condition is not known.	
	Type - Mixed			
•			Heat wheels are not present.	
•	Main filter:	is in good		
	Pleated, MERV 11	condition.	Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition.	
	11		an unknown condition.	
			Interior ducting is not visible. Interior ducting insulation is in	
			an unknown condition. Interior ducting is of unknown	
			cleanliness.	
			orea. miness.	
			Air handling room is free of trash/chemicals.	
			, , , , , , , , , , , , , , , , , , ,	
			Outside damper is inaccessible, and its condition is good.	
			Return damper is open, and its condition is good.	
			The general condition of the unit is good.	

Unit Designation:	ERV-16			
_	Roof access from 2110			
Areas Served:	Science Rooms-Se	e Attached Maps		
System Enhancements:				
Supply System	Outdoor Air	Cleanliness and Observations		
Type Supply System - VAV Heating - Hot Water Cooling - Dx Energy Recovery Unit (ERU) - Wheel Filter Type - Outdoor Pre-filter: None Main filter: Pleated, MERV	Outdoor air intake is accessible Outdoor air intake is located on the unit. No nearby pollution sources were found.	Outdoor air pre-filters are not present. Outdoor air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Outdoor air main filters are installed incorrectly. Return air pre-filters are not present. Return air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Return air main filters are installed correctly. Mixed air filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Mixed air filters are installed incorrectly. Drain pans are not plugged. Drain pan condition is good. Heating coils are dirty and cooling coils are clean. Heat wheels are clean. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition.		
Filter Type - Mixed • Pre-filter: Pleated, MERV 11 • Main filter: Pleated, MERV 11		Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good.		

Recommendations

Dirty Coils were observed on unit ERV-16 during the ventilation inspection.

Recommendation: Impacted/dirty coils can result in poor ventilation air supply as well as be a source for mold and bacterial growth on the coils. Coils should be cleaned annually, or as needed, as identified in the operations and maintenance program.

Dirty or poorly fitting filters were observed in units AHU-02, AHU-03, AHU-04, AHU-06, AHU-07, AHU-08, AHU-09, AHU-10, AHU-11, AHU-12, AHU-15 and ERV-16 during the ventilation inspection.

Recommendation: The operations and maintenance program for filter changes should be reviewed and revised to ensure proper filter changes to optimize filtration capacity.

Appendix A

Photo Documentation



AHU-02
Mixed Main Filter Installation



AHU-04
Mixed Main Filter Installation



AHU-03
Mixed Main Filter Installation



AHU-06
Mixed Main Filter Installation



AHU-07
Mixed Main Filter Installation



AHU-09
Mixed Main Filter Installation



AHU-08
Mixed Main Filter Installation



AHU-10
Mixed Main Filter Installation



AHU-11 Mixed Main Filter Fit



AHU-12
Mixed Main Filter Installation




AHU-11
Mixed Main Filter Installation



AHU-14 (100% OA)
Outdoor Main Filter Cleanliness



AHU-15
Mixed Main Filter Installation




ERV-16
Outdoor Main Filter Installation



ERV-16
Outdoor Main Filter Cleanliness



ERV-16
Mixed Pre-Filter Installation



ERV-16 Heating Coils