


Midwest
Environmental
Consulting, L.L.C.



 Printed on Recycled Paper

**Parkway Elementary School
Saint Paul Public Schools**

Lead-Based Paint Inspection

Inspection Dates: 8/26/97, 8/27/97, 8/28/97, 8/29/97, 9/3/97

submitted to:

Saint Paul Public Schools

MEC Project # 62/0197AZ

38894 Llama Street NW * Dalbo, Minnesota 55017 * (612) 689-3612
fax (612) 689-5209

INTRODUCTION

At the request of Saint Paul Public Schools Environmental Safety Department, Midwest Environmental Consulting, L.L.C. (MEC), conducted a lead-based paint inspection at Parkway Elementary School, 1363 Bush Avenue, St. Paul, MN. The purpose of this inspection was to identify lead-based painted, varnished, or otherwise coated building components on the interior and exterior of the school building.

The inspection protocol incorporated applicable portions of the U.S. Department of Housing and Urban Development (HUD) *Guidelines for the Evaluation and Control of Lead-based Paint Hazards in Housing* (HUD Guidelines, June 1995) and OSHA 1926.62 requirements (Lead in Construction). The HUD guidelines are formulated to guide agencies in conducting random sampling of the interiors and exteriors of dwellings and common areas in public housing. The OSHA requirement is designed to minimize worker exposure when working with material containing lead.

Confirmatory testing was conducted when inconclusive XRF results were encountered. Inconclusive refers to XRF readings less than 0.2 mg/cm² (milligrams per square centimeter). Inconclusive results were confirmed with laboratory analysis of paint chip samples (Appendix B). This report contains a list of such results.

The United States Environmental Protection Agency defines "lead-based paint" as a paint or other surface coating that contains lead equal to or in excess of 1.0 milligrams per square centimeter when analyzed by XRF or more than 0.5% by weight (5000 parts per million) by laboratory analysis of a bulk sample.

Minnesota Department of Labor and Industry (MN OSHA) adopted the EPA lead levels for the purpose of enforcing OSHA 1926.62 federal regulations. Detection of lead in dried paint film by XRF is a dependable indicator of levels of lead and is accepted by MN OSHA.

For this Saint Paul Public Schools Lead Inspection, all building components were tested on site using a Niton XL® X-ray Fluorescence Spectrum Analyzer⁽¹⁾. Building components included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases. Only painted or glazed surfaces or surfaces which were varnished were tested. Suspended ceilings, structural steel, and corrugated decking were not included in the inspection. Neither anodized (e.g., window sashes) nor plastic (e.g., vinyl baseboard and vinyl mini-blinds) were included in the scope of this inspection.

⁽¹⁾ This is a portable hand held machine that can analyze building components instantly for lead concentrations.

Each building was divided into unique sites based on the year of construction or renovation. Portable classrooms, playgrounds, and other detached buildings were automatically designated as a unique site. Each site was inspected independently assuming differences in painting history and construction characteristics.

SITE DESCRIPTION AND BUILDING HISTORY

According to information provided to MEC by Saint Paul Public Schools, Parkway Elementary School was constructed in essentially three phases. The initial phase includes the 9,684 square-foot older section of the building and dates from 1925. The second phase is a 10,029 square foot addition dating from 1958. The third phase is a 51,626 square foot addition from 1974.

All room and area designations used in this report are depicted on sampling maps found in Appendix A.

XRF SAMPLE RESULTS TABLE

The results of all samples analyzed are listed in the table at the end of this section. The following is a description of the column headings:

Site	Each school is divided into sites based on their unique construction characteristics. Each site has a unique date of construction or major renovation.
Sample #	Each sample taken was given a unique number to identify the type and location of the sample. The sampling date is an integral part of the sample number.
Analysis	This defines the type of analysis which can be categorized into two types: 1) XRF: This is an on-site analysis using a hand held Niton XL® X-ray Fluorescence Spectrum Analyzer; 2) Bulk or Chip: This is a bulk sample where paint is removed from the substrate and sent to a laboratory for analysis;
Floor	This is the level of the building in which the area tested was found, example, 1 (first floor), 0 (basement), etc.
Area	This further defines the specific functional space inspected such as a classroom, exterior, playground, gym, kitchen, etc.

- Room #** This is typically the actual number on the room as identified at the building.
- Component** Building "components" included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases.
- Feature** Identifies more detailed information of the component.
- Condition** This describes condition of the surface, whether it is intact, cracked, peeling, or chalking.
- Substrate** This refers to the material the building component is made of (wood, concrete, drywall, metal, etc.).
- Result** This is the analysis results for lead. Less than 1.0 mg/cm² or less than 0.5% by weight is considered to be non-lead and these building components are below the action levels of EPA and HUD. (All results are in mg/cm² except where noted.)

The table of results is designed for quick information on lead concentrations of tested building components. Generally, all repetitions of a test combination within a given room or area, may be assumed to contain similar concentrations of lead to that of the tested sample. For instance, the lead concentration of a tested wooden window sash was found to be above the action level of 1.0 mg/cm² in a given classroom. The classroom has five windows, all of wood, the same color and appearing to be of the same era. It can be assumed that the remaining four wooden window sashes each contain lead above the action limit.

Other columns identify the component and the component feature tested, condition of the component, type of substrate and the result of the analytical test.

As an example, the following illustration shows that the wooden door jamb in Room 123, first floor in the 1923 building section was in good, solid condition, and had an XRF test result of 0.3 mg/cm², which is below the action level.

Illustration Only

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1923 Bldg.	52		XRF	1	Room	123	Door	Jamb	Solid	Wood	0.3

In a similar manner, the table shows that the plaster walls in room 23, on the second floor has peeling paint with more than 1.0 mg/cm² (shaded).

ILLUSTRATION ONLY

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1910 Bldg.	16		XRF	2	Room	23	Door	Jamb	Peeling	Wood	0.25
1910 Bldg.	17		XRF	2	Room	23	Wall	Wall	Peeling	Plaster	1.2
1910 Bldg.	18		XRF	2	Room	23		Ceiling	Peeling	Plaster	0.25
1910 Bldg.	19		XRF	2	Room	23	Wall	Baseboard	Peeling	Wood	0.002

APPLICABLE REGULATIONS

When building components test above 1.0 mg/cm² of lead by XRF or 0.5% lead by weight from laboratory analysis all employees and contractors who will be working with these components in a construction related activity must be notified. The requirements of OSHA 1926.62, Lead in Construction are enforceable. This regulation defines construction work as "work for construction, alteration and/or repair, including painting and decorating." This regulation further defines monitoring requirements to minimize employee exposure to lead during construction activities.

When work is performed on external painted building structures (i.e. flashing, fire escapes, playground equipment, handrails, etc.), regulations of the Minnesota Pollution Control Agency (MPCA) may also be applicable. For removal of lead based paint from steel structures, MN Rules 7025.0200 - 7025.0380 apply to steel materials on the exterior of a building, or on the property when levels exceed 0.5 mg/cm² based on the average of three XRF spectrum results of the sample tested, or 5,000 ppm by laboratory analysis. If it is other than a steel surface, then MPCA regulates the painted surfaces under MN Rules 7025.010 - 7025.0080, when surfaces are to be disturbed using abrasive blasting methods.

Please contact MEC directly if you have questions about any portion of this report or the lead-based paint inspection itself.

APPENDIX A

**XRF TESTING DATA
WITH
LOCATION MAPS**

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
1	Parkway Elementary School											
2												
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
4	1925 Bldg.	44	XRF	8/29/97	1	Classroom	102	Wall	Wall	Solid	Concrte	0.29
5	1925 Bldg.	45	XRF	8/29/97	1	Classroom	102	Chalkboard	Rail	Solid	Wood	0.02
6	1925 Bldg.	46	XRF	8/29/97	1	Classroom	102	Wall	Midle Wall	Solid	Concrte	0.04
7	1925 Bldg.	47	XRF	8/29/97	1	Classroom	102	Wall	Wall	Solid	Concrte	0.38
8	1925 Bldg.	48	XRF	8/29/97	1	Classroom	102	Wall	Wall	Solid	Concrte	0
9	1925 Bldg.	49	XRF	8/29/97	1	Classroom	102	Wall	Wall	Solid	Concrte	0.19
10	1925 Bldg.	50	XRF	8/29/97	1	Classroom	102		Radiator	Solid	Metal	0.06
11	1925 Bldg.	51	XRF	8/29/97	1	Classroom	102	Window	Stool	Solid	Metal	0.7
12	1925 Bldg.	52	XRF	8/29/97	1	Classroom	102	Door	Door	Solid	Wood	0
13	1925 Bldg.	53	XRF	8/29/97	1	Classroom	102	Door	Casing	Solid	Metal	0
14	1925 Bldg.	54	XRF	8/29/97	1	Classroom	102	Wall	Wall	Solid	Concrte	3.33
15	1925 Bldg.	55	XRF	8/29/97	1	Classroom	102	Wall	Baseboar	Solid	Wood	0.02
16	1925 Bldg.	39	XRF	8/29/97	1	Classroom	104	Wall	Midle Wall	Solid	Concrte	0.03
17	1925 Bldg.	40	XRF	8/29/97	1	Classroom	104	Wall	Wall	Solid	Concrte	0.18
18	1925 Bldg.	41	XRF	8/29/97	1	Classroom	104	Door	Door	Solid	Wood	0
19	1925 Bldg.	42	XRF	8/29/97	1	Classroom	104	Door	Casing	Solid	Metal	0.01
20	1925 Bldg.	43	XRF	8/29/97	1	Classroom	104		Radiator	Solid	Metal	0.02
21	1925 Bldg.	26	XRF	8/29/97	1	Classroom	105		Radiator	Solid	Metal	0.05
22	1925 Bldg.	27	XRF	8/29/97	1	Classroom	105	Window	Stool	Solid	Metal	0
23	1925 Bldg.	28	XRF	8/29/97	1	Classroom	105	Wall	Midle Wall	Solid	Concrte	0.25
24	1925 Bldg.	29	XRF	8/29/97	1	Classroom	105	Wall	Wall	Solid	Concrte	0.24
25	1925 Bldg.	30	XRF	8/29/97	1	Classroom	105	Window	Panel	Solid	Wood	0
26	1925 Bldg.	31	XRF	8/29/97	1	Classroom	105	Wall	Baseboar	Solid	Wood	3.34
27	1925 Bldg.	32	XRF	8/29/97	1	Classroom	105	Wall	Baseboar	Solid	Wood	0.03
28	1925 Bldg.	33	XRF	8/29/97	1	Classroom	105	Chalkboard	Rail	Solid	Wood	0.03
29	1925 Bldg.	34	XRF	8/29/97	1	Classroom	105	Wall	Midle Wall	Solid	Concrte	3.31
30	1925 Bldg.	35	XRF	8/29/97	1	Classroom	105	Door	Door	Solid	Wood	0.02
31	1925 Bldg.	36	XRF	8/29/97	1	Classroom	105	Door	Casing	Solid	Wood	0.02
32	1925 Bldg.	37	XRF	8/29/97	1	Classroom	105	Cabinet	Door	Solid	Wood	0.02
33	1925 Bldg.	38	XRF	8/29/97	1	Classroom	105	Wall	Wall	Solid	Concrte	0.25
34	1925 Bldg.	95	XRF	8/29/97	2	Classroom	202	Cabinet	Door	Solid	Wood	0.02
35	1925 Bldg.	96	XRF	8/29/97	2	Classroom	202	Chalkboard	Rail	Solid	Wood	0.03
36	1925 Bldg.	97	XRF	8/29/97	2	Classroom	202	Wall	Wall	Solid	Concrte	0.25
37	1925 Bldg.	98	XRF	8/29/97	2	Classroom	202	Door	Door	Solid	Wood	0
38	1925 Bldg.	99	XRF	8/29/97	2	Classroom	202	Door	Jamb	Solid	Metal	0
39	1925 Bldg.	100	XRF	8/29/97	2	Classroom	202	Wall	Midle Wall	Solid	Drywall	0.05
40	1925 Bldg.	101	XRF	8/29/97	2	Classroom	202	Wall	Wall	Solid	Concrte	5.09
41	1925 Bldg.	102	XRF	8/29/97	2	Classroom	202		Radiator	Solid	Metal	0.06
42	1925 Bldg.	103	XRF	8/29/97	2	Classroom	202	Window	Stool	Solid	Metal	0.89
43	1925 Bldg.	104	XRF	8/29/97	2	Classroom	202	Wall	Baseboar	Solid	Wood	0.02
44	1925 Bldg.	105	XRF	8/29/97	2	Classroom	202	Wall	Wall	Solid	Concrte	0.06
45	1925 Bldg.	74	XRF	8/29/97	2	Classroom	205		Radiator	Solid	Metal	0.05
46	1925 Bldg.	75	XRF	8/29/97	2	Classroom	205	Window	Stool	Solid	Metal	0.13
47	1925 Bldg.	76	XRF	8/29/97	2	Classroom	205	Wall	Wall	Solid	Concrte	0.19
48	1925 Bldg.	77	XRF	8/29/97	2	Classroom	205	Chalkboard	Rail	Solid	Wood	0.03
49	1925 Bldg.	78	XRF	8/29/97	2	Classroom	205	Window	Panel	Cracked	Wood	0.75
50	1925 Bldg.	79	XRF	8/29/97	2	Classroom	205	Wall	Wall	Solid	Concrte	5.09
51	1925 Bldg.	80	XRF	8/29/97	2	Classroom	205	Wall	Baseboar	Solid	Wood	0.03
52	1925 Bldg.	81	XRF	8/29/97	2	Classroom	205	Door	Door	Solid	Wood	0.04
53	1925 Bldg.	82	XRF	8/29/97	2	Classroom	205	Door	Casing	Solid	Wood	0.02
54	1925 Bldg.	83	XRF	8/29/97	2	Classroom	205	Wall	Midle Wall	Solid	Concrte	2.32
55	1925 Bldg.	84	XRF	8/29/97	2	Classroom	205	Cabinet	Door	Solid	Wood	0.02
56	1925 Bldg.	85	XRF	8/29/97	2	Classroom	205	Cabinet	Door	Solid	Wood	0.09
57	1925 Bldg.	141	XRF	8/29/97	3	Classroom	302	Cabinet	Door	Solid	Wood	0.02
58	1925 Bldg.	142	XRF	8/29/97	3	Classroom	302	Window	Panel	Solid	Wood	0.85
59	1925 Bldg.	143	XRF	8/29/97	3	Classroom	302	Wall	Midle Wall	Solid	Concrte	0
60	1925 Bldg.	144	XRF	8/29/97	3	Classroom	302	Door	Door	Solid	Wood	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
61	1925 Bldg.	145	XRF	8/29/97	3	Classroom	302	Door	Casing	Solid	Metal	0
62	1925 Bldg.	146	XRF	8/29/97	3	Classroom	302	Cabinet	Door	Solid	Wood	0
63	1925 Bldg.	147	XRF	8/29/97	3	Classroom	302		Radiator	Solid	Metal	0.05
64	1925 Bldg.	148	XRF	8/29/97	3	Classroom	302	Wall	Midle Wall	Solid	Concrte	0.22
65	1925 Bldg.	149	XRF	8/29/97	3	Classroom	302		Radiator	Solid	Metal	0.06
66	1925 Bldg.	150	XRF	8/29/97	3	Classroom	302		Locker	Solid	Metal	0.77
67	1925 Bldg.	138	XRF	8/29/97	3	Classroom	303	Door	Door	Solid	Wood	0
68	1925 Bldg.	139	XRF	8/29/97	3	Classroom	303	Door	Casing	Solid	Metal	0
69	1925 Bldg.	140	XRF	8/29/97	3	Classroom	303	Wall	Midle Wall	Solid	Drywall	0.04
70	1925 Bldg.	124	XRF	8/29/97	3	Classroom	305	Wall	Wall	Solid	Concrte	0.33
71	1925 Bldg.	125	XRF	8/29/97	3	Classroom	305	Wall	Wall	Solid	Concrte	0
72	1925 Bldg.	126	XRF	8/29/97	3	Classroom	305		Radiator	Solid	Metal	0.04
73	1925 Bldg.	127	XRF	8/29/97	3	Classroom	305	Window	Stool	Solid	Metal	0.11
74	1925 Bldg.	128	XRF	8/29/97	3	Classroom	305	Window	Panel	Solid	Wood	0
75	1925 Bldg.	129	XRF	8/29/97	3	Classroom	305	Wall	Wall	Solid	Concrte	3.38
76	1925 Bldg.	130	XRF	8/29/97	3	Classroom	305	Chalkboard	Rail	Solid	Wood	0.02
77	1925 Bldg.	131	XRF	8/29/97	3	Classroom	305	Wall	Midle Wall	Solid	Concrte	3.16
78	1925 Bldg.	132	XRF	8/29/97	3	Classroom	305	Door	Door	Solid	Wood	0.03
79	1925 Bldg.	133	XRF	8/29/97	3	Classroom	305	Door	Casing	Solid	Wood	0.02
80	1925 Bldg.	134	XRF	8/29/97	3	Classroom	305	Cabinet	Door	Solid	Wood	0.02
81	1925 Bldg.	135	XRF	8/29/97	3	Classroom	305	Wall	Wall	Solid	Concrte	0.48
82	1925 Bldg.	136	XRF	8/29/97	3	Classroom	305	Window	Panel	Solid	Wood	0.84
83	1925 Bldg.	137	XRF	8/29/97	3	Classroom	305	Wall	Baseboar	Solid	Wood	0.01
84	1925 Bldg.	56	XRF	8/29/97	1	Hall	1100	Door	Door	Solid	Wood	0.02
85	1925 Bldg.	57	XRF	8/29/97	1	Hall	1100	Door	Casing	Solid	Wood	0.03
86	1925 Bldg.	58	XRF	8/29/97	1	Hall	1100	Wall	Wall	Solid	Concrte	5.09
87	1925 Bldg.	59	XRF	8/29/97	1	Hall	1100	Wall	Chair rail	Solid	Wood	0
88	1925 Bldg.	60	XRF	8/29/97	1	Hall	1100	Wall	Wall	Solid	Concrte	0.3
89	1925 Bldg.	61	XRF	8/29/97	1	Hall	1100	Window	Casing	Solid	Wood	0.4
90	1925 Bldg.	62	XRF	8/29/97	1	Hall	1100	Door	Door	Cracked	Wood	0.34
91	1925 Bldg.	63	XRF	8/29/97	1	Hall	1100	Door	Jamb	Solid	Metal	5.09
92	1925 Bldg.	64	XRF	8/29/97	1	Hall	1100	Wall	Wall	Solid	Concrte	0.09
93	1925 Bldg.	65	XRF	8/29/97	1	Hall	1100	Wall	Midle Wall	Solid	Concrte	5.09
94	1925 Bldg.	66	XRF	8/29/97	1	Hall	1100	Door	Door	Solid	Metal	0.05
95	1925 Bldg.	67	XRF	8/29/97	1	Hall	1100	Door	Casing	Solid	Metal	5.09
96	1925 Bldg.	68	XRF	8/29/97	1	Hall	1100	Door	Door	Solid	Wood	0.02
97	1925 Bldg.	69	XRF	8/29/97	1	Hall	1100	Door	Jamb	Solid	Wood	0.01
98	1925 Bldg.	70	XRF	8/29/97	1	Hall	1100	Window	Casing	Solid	Wood	0
99	1925 Bldg.	71	XRF	8/29/97	1	Hall	1100	Door	Door	Solid	Wood	0
100	1925 Bldg.	72	XRF	8/29/97	1	Hall	1100	Door	Casing	Solid	Metal	0.08
101	1925 Bldg.	73	XRF	8/29/97	1	Hall	1100	Wall	Midle Wall	Solid	Drywall	0
102	1925 Bldg.	106	XRF	8/29/97	2	Hall	2100	Door	Door	Solid	Wood	0.03
103	1925 Bldg.	107	XRF	8/29/97	2	Hall	2100	Door	Casing	Solid	Wood	0.03
104	1925 Bldg.	108	XRF	8/29/97	2	Hall	2100	Wall	Wall	Solid	Concrte	0.18
105	1925 Bldg.	109	XRF	8/29/97	2	Hall	2100	Wall	Chair rail	Solid	Wood	0.02
106	1925 Bldg.	110	XRF	8/29/97	2	Hall	2100	Wall	Wall	Solid	Concrte	3.71
107	1925 Bldg.	111	XRF	8/29/97	2	Hall	2100	Window	Casing	Solid	Metal	0.39
108	1925 Bldg.	112	XRF	8/29/97	2	Hall	2100	Door	Door	Solid	Metal	0.41
109	1925 Bldg.	113	XRF	8/29/97	2	Hall	2100	Door	Jamb	Solid	Metal	4.21
110	1925 Bldg.	114	XRF	8/29/97	2	Hall	2100		Radiator	Peeling	Metal	0.06
111	1925 Bldg.	115	XRF	8/29/97	2	Hall	2100		Radiator	Solid	Wood	0
112	1925 Bldg.	116	XRF	8/29/97	2	Hall	2100	Window	Stool	Solid	Metal	1.78
113	1925 Bldg.	117	XRF	8/29/97	2	Hall	2100	Window	Panel	Solid	Wood	0
114	1925 Bldg.	118	XRF	8/29/97	2	Hall	2100	Door	Door	Solid	Wood	0
115	1925 Bldg.	119	XRF	8/29/97	2	Hall	2100	Door	Casing	Solid	Wood	0.05
116	1925 Bldg.	120	XRF	8/29/97	2	Hall	2100	Wall	Midle Wall	Solid	Drywall	0
117	1925 Bldg.	121	XRF	8/29/97	2	Hall	2100	Wall	Wall Rgstr	Solid	Metal	0
118	1925 Bldg.	122	XRF	8/29/97	2	Hall	2100	Door	Door	Solid	Wood	0
119	1925 Bldg.	123	XRF	8/29/97	2	Hall	2100	Door	Jamb	Solid	Metal	0.08

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
120	1925 Bldg.	151	XRF	8/29/97	3	Hall	3100	Door	Door	Solid	Wood	0.03
121	1925 Bldg.	152	XRF	8/29/97	3	Hall	3100	Door	Casing	Solid	Wood	0.03
122	1925 Bldg.	153	XRF	8/29/97	3	Hall	3100	Wall	Wall	Solid	Concrte	5.09
123	1925 Bldg.	154	XRF	8/29/97	3	Hall	3100	Wall	Chair rail	Solid	Wood	0
124	1925 Bldg.	155	XRF	8/29/97	3	Hall	3100	Window	Casing	Solid	Metal	0.29
125	1925 Bldg.	156	XRF	8/29/97	3	Hall	3100	Door	Door	Solid	Metal	0.42
126	1925 Bldg.	157	XRF	8/29/97	3	Hall	3100	Door	Casing	Solid	Metal	5.09
127	1925 Bldg.	158	XRF	8/29/97	3	Hall	3100		Radiator	Peeling	Metal	0.12
128	1925 Bldg.	159	XRF	8/29/97	3	Hall	3100	Window	Stool	Solid	Metal	0.81
129	1925 Bldg.	160	XRF	8/29/97	3	Hall	3100	Door	Door	Solid	Metal	0.12
130	1925 Bldg.	161	XRF	8/29/97	3	Hall	3100	Door	Casing	Solid	Metal	0.13
131	1925 Bldg.	162	XRF	8/29/97	3	Hall	3100	Door	Door	Solid	Metal	0
132	1925 Bldg.	163	XRF	8/29/97	3	Hall	3100	Door	Jamb	Solid	Metal	0.09
133	1925 Bldg.	164	XRF	8/29/97	3	Hall	3100	Door	Door	Solid	Wood	0
134	1925 Bldg.	165	XRF	8/29/97	3	Hall	3100	Window	Stool	Solid	Metal	0.11
135	1925 Bldg.	131	XRF	9/3/97	1	Outside	1	Door	Casing	Cracked	Wood	5.09
136	1925 Bldg.	132	XRF	9/3/97	1	Outside	1	Door	Door	Solid	Metal	0
137	1925 Bldg.	6	XRF	8/29/97	1	Room	0	Door	Door	Cracked	Wood	5.09
138	1925 Bldg.	86	XRF	8/29/97	2	Room	204	Wall	Wall	Solid	Concrte	0.25
139	1925 Bldg.	87	XRF	8/29/97	2	Room	204	Wall	Wall Rgstr	Solid	Metal	0.24
140	1925 Bldg.	88	XRF	8/29/97	2	Room	204		Locker	Solid	Metal	0.36
141	1925 Bldg.	89	XRF	8/29/97	2	Room	204	Wall	Wall	Solid	Concrte	3.97
142	1925 Bldg.	90	XRF	8/29/97	2	Room	204	Wall	Midle Wall	Solid	Drywall	0
143	1925 Bldg.	91	XRF	8/29/97	2	Room	204	Wall	Wall Rgstr	Solid	Metal	0
144	1925 Bldg.	92	XRF	8/29/97	2	Room	204	Door	Door	Solid	Wood	0
145	1925 Bldg.	93	XRF	8/29/97	2	Room	204	Door	Casing	Solid	Metal	0.01
146	1925 Bldg.	94	XRF	8/29/97	2	Room	204	Wall	Midle Wall	Solid	Drywall	0.01
147	1925 Bldg.	166	XRF	8/29/97	3	Room	400	Wall	Midle Wall	Solid	Concrte	5.09
148	1925 Bldg.	167	XRF	8/29/97	3	Room	400		Radiator	Solid	Metal	5.09
149	1925 Bldg.	168	XRF	8/29/97	3	Room	400	Door	Door	Solid	Wood	0.03
150	1925 Bldg.	169	XRF	8/29/97	3	Room	400	Door	Casing	Solid	Wood	0.02
151	1925 Bldg.	170	XRF	8/29/97	3	Room	400	Window	Casing	Solid	Wood	0.04
152	1925 Bldg.	171	XRF	8/29/97	3	Room	400	Bookcase	Shelf	Solid	Wood	0.09
153	1925 Bldg.	172	XRF	8/29/97	3	Room	400	Stairs	Hand rail	Solid	Metal	2.22
154	1925 Bldg.	173	XRF	8/29/97	3	Room	400	Wall	Midle Wall	Solid	Concrte	5.09
155	1925 Bldg.	174	XRF	8/29/97	3	Room	400	Ceiling		Solid	Concrte	5.09
156	1925 Bldg.	7	XRF	8/29/97	1	Room	1300	Door	Door	Solid	Metal	5.09
157	1925 Bldg.	8	XRF	8/29/97	1	Room	1300	Door	Jamb	Solid	Metal	3.92
158	1925 Bldg.	9	XRF	8/29/97	1	Room	1300	Door	Door	Solid	Metal	5.09
159	1925 Bldg.	10	XRF	8/29/97	1	Room	1300	Wall	Midle Wall	Solid	Concrte	0.01
160	1925 Bldg.	11	XRF	8/29/97	1	Room	1300	Door	Door	Solid	Metal	0.06
161	1925 Bldg.	12	XRF	8/29/97	1	Room	1300	Door	Jamb	Solid	Metal	5.09
162	1925 Bldg.	13	XRF	8/29/97	1	Room	1300	Wall	Wall	Solid	Concrte	0.03
163	1925 Bldg.	14	XRF	8/29/97	1	Room	1300	Stairs	Hand rail	Cracked	Metal	5.09
164	1925 Bldg.	15	XRF	8/29/97	1	Room	1300	Stairs	Tread	Solid	Concrte	0.01
165	1925 Bldg.	16	XRF	8/29/97	1	Room	1300	Wall	Wall	Solid	Concrte	0
166	1925 Bldg.	17	XRF	8/29/97	1	Room	1300	Wall	Wall	Solid	Concrte	0.01
167	1925 Bldg.	18	XRF	8/29/97	1	Room	1300	Wall	Wall	Solid	Concrte	0
168	1925 Bldg.	19	XRF	8/29/97	1	Room	1300	Door	Door	Cracked	Metal	0.1
169	1925 Bldg.	20	XRF	8/29/97	1	Room	1300	Door	Jamb	Solid	Metal	0.05
170	1925 Bldg.	21	XRF	8/29/97	1	Room	1300	Wall	Transom	Cracked	Wood	0.05
171	1925 Bldg.	22	XRF	8/29/97	1	Room	1300		Elec Pane	Cracked	Metal	0.01
172	1925 Bldg.	23	XRF	8/29/97	1	Room	1300	Door	Door	Solid	Metal	0.1
173	1925 Bldg.	24	XRF	8/29/97	1	Room	1300	Door	Door	Solid	Metal	5.09
174	1925 Bldg.	25	XRF	8/29/97	1	Room	1300		Locker	Cracked	Metal	0.25
175	1925 Bldg.	175	XRF	8/29/97	3	Stairwell	4	Door	Door	Solid	Wood	0.02
176	1925 Bldg.	176	XRF	8/29/97	3	Stairwell	4	Door	Casing	Solid	Wood	0.02
177	1925 Bldg.	177	XRF	8/29/97	3	Stairwell	4	Window	Casing	Solid	Wood	0.03
178	1925 Bldg.	178	XRF	8/29/97	3	Stairwell	4	Wall	Wall	Solid	Concrte	0.01

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
179	1925 Bldg.	179	XRF	8/29/97	3	Stairwell	4	Wall	Wall	Solid	Concrte	0.26
180	1925 Bldg.	180	XRF	8/29/97	3	Stairwell	4	Stairs	Wall	Solid	Concrte	4.43
181	1925 Bldg.	181	XRF	8/29/97	3	Stairwell	4	Stairs	Hand rail	Solid	Wood	0.01
182	1925 Bldg.	182	XRF	8/29/97	3	Stairwell	4	Wall	Chair rail	Solid	Wood	0.02
183	1925 Bldg.	183	XRF	8/29/97	3	Stairwell	4	Stairs	Rail cap	Solid	Concrte	0.48
184	1925 Bldg.	184	XRF	8/29/97	3	Stairwell	4	Door	Door	Solid	Metal	0.44
185	1925 Bldg.	185	XRF	8/29/97	3	Stairwell	4		Radiator	Solid	Metal	0.02
186	1925 Bldg.	186	XRF	8/29/97	3	Stairwell	4		Radiator	Solid	Wood	0
187	1925 Bldg.	187	XRF	8/29/97	3	Stairwell	4	Wall	Wall	Solid	Concrte	4.32
188	1925 Bldg.	188	XRF	8/29/97	3	Stairwell	4	Wall	Wall	Solid	Concrte	0.3
189	1925 Bldg.	189	XRF	8/29/97	3	Stairwell	4	Door	Door	Solid	Metal	0.03
190	1925 Bldg.	190	XRF	8/29/97	3	Stairwell	4	Door	Jamb	Cracked	Metal	0.06
191	1925 Bldg.	191	XRF	8/29/97	3	Stairwell	4		Radiator	Solid	Metal	0
192	1925 Bldg.	192	XRF	8/29/97	3	Stairwell	4		Radiator	Solid	Metal	0.01
193	1958 Bldg.	52	XRF	9/3/97	1	Classroom	131	Cabinet	Door	Solid	Wood	0
194	1958 Bldg.	53	XRF	9/3/97	1	Classroom	131	Wall	Wall	Solid	Drywall	0
195	1958 Bldg.	54	XRF	9/3/97	1	Classroom	131	Door	Door	Solid	Wood	0
196	1958 Bldg.	55	XRF	9/3/97	1	Classroom	131	Door	Casing	Solid	Metal	0.05
197	1958 Bldg.	56	XRF	9/3/97	1	Classroom	131	Wall	Midle Wall	Solid	Concrte	0.01
198	1958 Bldg.	57	XRF	9/3/97	1	Classroom	131	Door	Door	Solid	Wood	0
199	1958 Bldg.	58	XRF	9/3/97	1	Classroom	131		Radiator	Solid	Metal	0.06
200	1958 Bldg.	59	XRF	9/3/97	1	Classroom	131	Window	Panel	Solid	Wood	0.03
201	1958 Bldg.	27	XRF	9/3/97	1	Classroom	132	Wall	Wall	Solid	Plaster	0
202	1958 Bldg.	28	XRF	9/3/97	1	Classroom	132	Cabinet	Door	Solid	Wood	0
203	1958 Bldg.	29	XRF	9/3/97	1	Classroom	132	Door	Door	Solid	Wood	0
204	1958 Bldg.	30	XRF	9/3/97	1	Classroom	132	Door	Casing	Solid	Metal	0.03
205	1958 Bldg.	31	XRF	9/3/97	1	Classroom	132	Wall	Chair rail	Solid	Wood	0
206	1958 Bldg.	32	XRF	9/3/97	1	Classroom	132	Wall	Midle Wall	Solid	Concrte	0.06
207	1958 Bldg.	33	XRF	9/3/97	1	Classroom	132	Door	Door	Solid	Wood	0
208	1958 Bldg.	34	XRF	9/3/97	1	Classroom	132	Window	Panel	Solid	Wood	0
209	1958 Bldg.	35	XRF	9/3/97	1	Classroom	132	Window	Panel	Solid	Wood	0
210	1958 Bldg.	36	XRF	9/3/97	1	Classroom	132	Window	Panel	Solid	Wood	0
211	1958 Bldg.	37	XRF	9/3/97	1	Classroom	132	Wall	Midle Wall	Solid	Concrte	0.23
212	1958 Bldg.	38	XRF	9/3/97	1	Classroom	132	Wall	Midle Wall	Solid	Concrte	0
213	1958 Bldg.	39	XRF	9/3/97	1	Classroom	132	Bookcase	Shelf	Solid	Wood	0
214	1958 Bldg.	40	XRF	9/3/97	1	Classroom	132		Radiator	Solid	Metal	0.02
215	1958 Bldg.	41	XRF	9/3/97	1	Classroom	132	Wall	Wall	Solid	Plaster	0.08
216	1958 Bldg.	42	XRF	9/3/97	1	Classroom	132	Ceiling		Solid	Plaster	0.02
217	1958 Bldg.	43	XRF	9/3/97	1	Classroom	132	Ceiling		Solid	Plaster	0.11
218	1958 Bldg.	97	XRF	9/3/97	1	Hall	1200	Window	Panel	Solid	Wood	0
219	1958 Bldg.	98	XRF	9/3/97	1	Hall	1200	Window	Stool	Solid	Metal	0.07
220	1958 Bldg.	99	XRF	9/3/97	1	Hall	1200	Door	Door	Solid	Wood	0
221	1958 Bldg.	100	XRF	9/3/97	1	Hall	1200	Door	Casing	Solid	Metal	0.04
222	1958 Bldg.	101	XRF	9/3/97	1	Hall	1200		Elec Pane	Solid	Metal	0.01
223	1958 Bldg.	102	XRF	9/3/97	1	Hall	1200	Door	Door	Solid	Metal	0.03
224	1958 Bldg.	103	XRF	9/3/97	1	Hall	1200	Door	Casing	Solid	Metal	0.06
225	1958 Bldg.	104	XRF	9/3/97	1	Hall	1200	Window	Header	Solid	Plaster	0.14
226	1958 Bldg.	105	XRF	9/3/97	1	Hall	1200		Radiator	Solid	Metal	0
227	1958 Bldg.	106	XRF	9/3/97	1	Hall	1200	Door	Header	Solid	Wood	0.01
228	1958 Bldg.	107	XRF	9/3/97	1	Hall	1200	Door	Jamb	Solid	Metal	0.03
229	1958 Bldg.	108	XRF	9/3/97	1	Hall	1200	Door	Door	Solid	Metal	0.02
230	1958 Bldg.	109	XRF	9/3/97	1	Hall	1200	Wall	Wall	Solid	Plaster	0.18
231	1958 Bldg.	110	XRF	9/3/97	1	Hall	1200	Wall	Midle Wall	Solid	Concrte	0
232	1958 Bldg.	111	XRF	9/3/97	1	Hall	1200	Bench		Solid	Wood	0
233	1958 Bldg.	112	XRF	9/3/97	1	Hall	1200	Door	Door	Chalking	Metal	0.08
234	1958 Bldg.	60	XRF	9/3/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrte	0.03
235	1958 Bldg.	61	XRF	9/3/97	1	Kitchen	1	Door	Door	Solid	Wood	0
236	1958 Bldg.	62	XRF	9/3/97	1	Kitchen	1	Door	Casing	Solid	Metal	0.06
237	1958 Bldg.	63	XRF	9/3/97	1	Kitchen	1	Ceiling		Solid	Plaster	0.07

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
238	1958 Bldg.	77	XRF	9/3/97	1	Lunch Area	1	Wall	Midle Wall	Solid	Concrte	0.05
239	1958 Bldg.	78	XRF	9/3/97	1	Lunch Area	1	Cabinet	Door	Solid	Metal	0.73
240	1958 Bldg.	79	XRF	9/3/97	1	Lunch Area	1	Cabinet	Shelf	Solid	Metal	0.37
241	1958 Bldg.	80	XRF	9/3/97	1	Lunch Area	1	Stairs	Hand rail	Solid	Metal	0.07
242	1958 Bldg.	81	XRF	9/3/97	1	Lunch Area	1	Door	Door	Solid	Wood	0
243	1958 Bldg.	82	XRF	9/3/97	1	Lunch Area	1	Door	Casing	Solid	Metal	0.05
244	1958 Bldg.	83	XRF	9/3/97	1	Lunch Area	1	Wall	Wall	Solid	Concrte	0.07
245	1958 Bldg.	84	XRF	9/3/97	1	Lunch Area	1		Elec Pane	Solid	Metal	0.01
246	1958 Bldg.	85	XRF	9/3/97	1	Lunch Area	1	Wall	Baseboar	Solid	Wood	0
247	1958 Bldg.	113	XRF	9/3/97	1	Outside	1	Window	Panel	Chalking	Wood	0.04
248	1958 Bldg.	114	XRF	9/3/97	1	Outside	1	Door	Door	Solid	Metal	0.03
249	1958 Bldg.	115	XRF	9/3/97	1	Outside	1	Door	Casing	Solid	Metal	0.03
250	1958 Bldg.	116	XRF	9/3/97	1	Outside	1	Door	Column	Cracked	Metal	1.23
251	1958 Bldg.	117	XRF	9/3/97	1	Outside	1	Door	Door	Solid	Metal	0.02
252	1958 Bldg.	118	XRF	9/3/97	1	Outside	1	Door	Casing	Solid	Metal	0.03
253	1958 Bldg.	119	XRF	9/3/97	1	Outside	1	Window	Stool	Solid	Metal	0.03
254	1958 Bldg.	120	XRF	9/3/97	1	Outside	1	Window	Stool	Solid	Metal	0.04
255	1958 Bldg.	121	XRF	9/3/97	1	Outside	1	Grounds	Fence	Solid	Wood	0
256	1958 Bldg.	122	XRF	9/3/97	1	Outside	1	Door	Door	Solid	Metal	0.02
257	1958 Bldg.	123	XRF	9/3/97	1	Outside	1	Stairs	Hand rail	Cracked	Metal	0.01
258	1958 Bldg.	124	XRF	9/3/97	1	Outside	1	Door	Door	Solid	Metal	0
259	1958 Bldg.	125	XRF	9/3/97	1	Outside	1	Door	Casing	Solid	Metal	0.02
260	1958 Bldg.	126	XRF	9/3/97	1	Outside	1	Window	Panel	Cracked	Wood	0
261	1958 Bldg.	127	XRF	9/3/97	1	Outside	1	Window	Panel	Cracked	Wood	0
262	1958 Bldg.	128	XRF	9/3/97	1	Outside	1	Light Pole		Cracked	Metal	0.01
263	1958 Bldg.	129	XRF	9/3/97	1	Outside	1	Stairs	Hand rail	Cracked	Metal	0.02
264	1958 Bldg.	130	XRF	9/3/97	1	Outside	1	Grounds	Fence	Cracked	Metal	0
265	1958 Bldg.	135	XRF	9/3/97	1	Outside	1	Stairs	Stringer	Cracked	Metal	0.01
266	1958 Bldg.	6	XRF	9/3/97	1	Restroom	1310	Window	Panel	Solid	Wood	0
267	1958 Bldg.	7	XRF	9/3/97	1	Restroom	1310		Radiator	Solid	Metal	0.19
268	1958 Bldg.	8	XRF	9/3/97	1	Restroom	1310		Stall Door	Solid	Metal	0.09
269	1958 Bldg.	9	XRF	9/3/97	1	Restroom	1310	Door	Door	Solid	Metal	0.08
270	1958 Bldg.	10	XRF	9/3/97	1	Restroom	1310	Door	Casing	Solid	Metal	0.03
271	1958 Bldg.	11	XRF	9/3/97	1	Restroom	1310	Ceiling		Solid	Drywall	0.18
272	1958 Bldg.	16	XRF	9/3/97	1	Restroom	1330	Window	Panel	Solid	Wood	0
273	1958 Bldg.	17	XRF	9/3/97	1	Restroom	1330		Radiator	Solid	Metal	0.18
274	1958 Bldg.	18	XRF	9/3/97	1	Restroom	1330	Wall	Midle Wall	Solid	Drywall	0
275	1958 Bldg.	19	XRF	9/3/97	1	Restroom	1330		Stall Door	Solid	Metal	0.61
276	1958 Bldg.	20	XRF	9/3/97	1	Restroom	1330	Door	Door	Solid	Wood	0
277	1958 Bldg.	21	XRF	9/3/97	1	Restroom	1330	Door	Door	Solid	Metal	0.04
278	1958 Bldg.	22	XRF	9/3/97	1	Restroom	1330	Door	Casing	Solid	Metal	0.06
279	1958 Bldg.	23	XRF	9/3/97	1	Restroom	1330	Cabinet	Door	Solid	Wood	0
280	1958 Bldg.	24	XRF	9/3/97	1	Restroom	1330	Door	Door	Solid	Wood	0
281	1958 Bldg.	25	XRF	9/3/97	1	Restroom	1330	Wall	Midle Wall	Solid	Drywall	0.03
282	1958 Bldg.	26	XRF	9/3/97	1	Restroom	1330	Wall	Midle Wall	Solid	Drywall	0
283	1958 Bldg.	86	XRF	9/3/97	1	Room	100		Radiator	Solid	Metal	0.25
284	1958 Bldg.	87	XRF	9/3/97	1	Room	100	Window	Panel	Solid	Wood	0.06
285	1958 Bldg.	88	XRF	9/3/97	1	Room	100	Wall	Midle Wall	Solid	Concrte	0.09
286	1958 Bldg.	89	XRF	9/3/97	1	Room	100	Door	Door	Solid	Wood	0
287	1958 Bldg.	90	XRF	9/3/97	1	Room	100	Door	Casing	Solid	Metal	0.06
288	1958 Bldg.	91	XRF	9/3/97	1	Room	100	Wall	Wall	Solid	Concrte	0.14
289	1958 Bldg.	44	XRF	9/3/97	1	Room	113		Radiator	Solid	Metal	0.21
290	1958 Bldg.	45	XRF	9/3/97	1	Room	113	Window	Panel	Solid	Wood	0.08
291	1958 Bldg.	46	XRF	9/3/97	1	Room	113	Wall	Midle Wall	Solid	Concrte	0.12
292	1958 Bldg.	47	XRF	9/3/97	1	Room	113	Door	Door	Solid	Wood	0
293	1958 Bldg.	48	XRF	9/3/97	1	Room	113	Window	Stool	Solid	Metal	0.1
294	1958 Bldg.	49	XRF	9/3/97	1	Room	113	Window	Panel	Solid	Wood	0.01
295	1958 Bldg.	50	XRF	9/3/97	1	Room	113	Wall	Midle Wall	Solid	Plaster	0.19
296	1958 Bldg.	51	XRF	9/3/97	1	Room	113	Ceiling		Solid	Plaster	0.09

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
297	1958 Bldg.	12	XRF	9/3/97	1	Room	1320	Wall	Midle Wall	Solid	Concrte	0.35
298	1958 Bldg.	13	XRF	9/3/97	1	Room	1320	Wall	Midle Wall	Solid	Concrte	0.19
299	1958 Bldg.	14	XRF	9/3/97	1	Room	1320	Door	Door	Solid	Metal	0.03
300	1958 Bldg.	15	XRF	9/3/97	1	Room	1320	Door	Casing	Solid	Metal	0.04
301	1958 Bldg.	64	XRF	9/3/97	1	Room	1340	Wall	Wall	Solid	Concrte	0.09
302	1958 Bldg.	65	XRF	9/3/97	1	Room	1340	Door	Door	Solid	Wood	0
303	1958 Bldg.	66	XRF	9/3/97	1	Room	1340	Door	Casing	Solid	Metal	0.03
304	1958 Bldg.	67	XRF	9/3/97	1	Room	1340	Wall	Wall	Solid	Concrte	0.09
305	1958 Bldg.	68	XRF	9/3/97	1	Room	1340	Stairs	Hand rail	Solid	Metal	0.05
306	1958 Bldg.	69	XRF	9/3/97	1	Room	1340	Wall	Wall	Solid	Concrte	0
307	1958 Bldg.	70	XRF	9/3/97	1	Room	1340	Door	Door	Solid	Metal	0.02
308	1958 Bldg.	71	XRF	9/3/97	1	Room	1340	Door	Casing	Solid	Metal	0.04
309	1958 Bldg.	72	XRF	9/3/97	1	Room	1340	Window	Casing	Cracked	Metal	0.03
310	1958 Bldg.	73	XRF	9/3/97	1	Room	1340	Door	Door	Solid	Wood	0
311	1958 Bldg.	74	XRF	9/3/97	1	Room	1340	Door	Casing	Solid	Metal	0.06
312	1958 Bldg.	75	XRF	9/3/97	1	Room	1340	Cabinet	Door	Solid	Wood	0
313	1958 Bldg.	76	XRF	9/3/97	1	Room	1340	Wall	Wall	Solid	Plaster	0.04
314	1958 Bldg.	92	XRF	9/3/97	1	Room	1350	Wall	Midle Wall	Solid	Concrte	0.01
315	1958 Bldg.	93	XRF	9/3/97	1	Room	1350	Bookcase	Shelf	Solid	Wood	0.01
316	1958 Bldg.	94	XRF	9/3/97	1	Room	1350	Door	Door	Solid	Metal	0
317	1958 Bldg.	95	XRF	9/3/97	1	Room	1350	Door	Casing	Solid	Metal	0.09
318	1958 Bldg.	96	XRF	9/3/97	1	Room	1350	Wall	Midle Wall	Solid	Concrte	0.02
319	1974 Bldg.	1	XRF	8/29/97		Calibrate						0.37
320	1974 Bldg.	98	XRF	8/26/97	1	Classroom	109	Wall	Midle Wall	Solid	Drywall	0
321	1974 Bldg.	99	XRF	8/26/97	1	Classroom	109	Wall	Wall	Solid	Drywall	0.06
322	1974 Bldg.	100	XRF	8/26/97	1	Classroom	109	Door	Door	Solid	Wood	0
323	1974 Bldg.	101	XRF	8/26/97	1	Classroom	109	Door	Casing	Solid	Metal	0.11
324	1974 Bldg.	102	XRF	8/26/97	1	Classroom	109	Window	Stool	Solid	Metal	0.08
325	1974 Bldg.	103	XRF	8/26/97	1	Classroom	109	Wall	Midle Wall	Solid	Concrte	0
326	1974 Bldg.	104	XRF	8/26/97	1	Classroom	109	Wall	Midle Wall	Solid	Drywall	0.01
327	1974 Bldg.	105	XRF	8/26/97	1	Classroom	109		Radiator	Solid	Metal	0.05
328	1974 Bldg.	106	XRF	8/26/97	1	Classroom	109	Wall	Midle Wall	Solid	Concrte	0
329	1974 Bldg.	111	XRF	8/26/97	1	Classroom	110		Radiator	Solid	Metal	0.03
330	1974 Bldg.	112	XRF	8/26/97	1	Classroom	110	Wall	Midle Wall	Solid	Concrte	0
331	1974 Bldg.	113	XRF	8/26/97	1	Classroom	110	Cabinet	Door	Solid	Wood	0
332	1974 Bldg.	114	XRF	8/26/97	1	Classroom	110	Door	Door	Solid	Wood	0
333	1974 Bldg.	115	XRF	8/26/97	1	Classroom	110	Door	Casing	Solid	Metal	0
334	1974 Bldg.	116	XRF	8/26/97	1	Classroom	110	Wall	Midle Wall	Solid	Drywall	0.04
335	1974 Bldg.	117	XRF	8/26/97	1	Classroom	110	Wall	Midle Wall	Solid	Concrte	0
336	1974 Bldg.	118	XRF	8/26/97	1	Classroom	110	Wall	Wall	Solid	Drywall	0
337	1974 Bldg.	91	XRF	8/26/97	1	Classroom	111	Door	Door	Solid	Wood	0
338	1974 Bldg.	92	XRF	8/26/97	1	Classroom	111	Door	Casing	Solid	Metal	0
339	1974 Bldg.	93	XRF	8/26/97	1	Classroom	111	Wall	Midle Wall	Solid	Drywall	0
340	1974 Bldg.	94	XRF	8/26/97	1	Classroom	111		Radiator	Solid	Metal	0.04
341	1974 Bldg.	95	XRF	8/26/97	1	Classroom	111	Wall	Wall	Solid	Drywall	0
342	1974 Bldg.	96	XRF	8/26/97	1	Classroom	111	Cabinet	Door	Solid	Wood	0
343	1974 Bldg.	97	XRF	8/26/97	1	Classroom	111	Wall	Midle Wall	Solid	Concrte	0
344	1974 Bldg.	119	XRF	8/26/97	1	Classroom	112	Wall	Midle Wall	Solid	Drywall	0
345	1974 Bldg.	120	XRF	8/26/97	1	Classroom	112	Cabinet	Door	Solid	Wood	0
346	1974 Bldg.	121	XRF	8/26/97	1	Classroom	112		Radiator	Solid	Metal	0.01
347	1974 Bldg.	122	XRF	8/26/97	1	Classroom	112	Door	Door	Solid	Wood	0
348	1974 Bldg.	123	XRF	8/26/97	1	Classroom	112	Door	Casing	Solid	Metal	0
349	1974 Bldg.	124	XRF	8/26/97	1	Classroom	112	Wall	Midle Wall	Solid	Concrte	0.01
350	1974 Bldg.	125	XRF	8/26/97	1	Classroom	112	Wall	Midle Wall	Solid	Drywall	0.01
351	1974 Bldg.	65	XRF	8/26/97	1	Classroom	113	Wall	Wall	Solid	Drywall	0
352	1974 Bldg.	66	XRF	8/26/97	1	Classroom	113	Door	Door	Solid	Wood	0
353	1974 Bldg.	67	XRF	8/26/97	1	Classroom	113	Door	Casing	Solid	Metal	0
354	1974 Bldg.	68	XRF	8/26/97	1	Classroom	113	Window	Casing	Solid	Metal	0
355	1974 Bldg.	69	XRF	8/26/97	1	Classroom	113	Wall	Midle Wall	Solid	Concrte	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
356	1974 Bldg.	70	XRF	8/26/97	1	Classroom	113	Wall	Midle Wall	Solid	Drywall	0
357	1974 Bldg.	71	XRF	8/26/97	1	Classroom	113	Wall	Wall Rgstr	Solid	Metal	0
358	1974 Bldg.	72	XRF	8/26/97	1	Classroom	113	Cabinet	Door	Solid	Wood	0
359	1974 Bldg.	73	XRF	8/26/97	1	Classroom	113		Radiator	Solid	Metal	0.03
360	1974 Bldg.	74	XRF	8/26/97	1	Classroom	113	Wall	Midle Wall	Solid	Concrte	0
361	1974 Bldg.	25	XRF	8/26/97	1	Classroom	114		Radiator	Solid	Metal	0.02
362	1974 Bldg.	26	XRF	8/26/97	1	Classroom	114	Wall	Midle Wall	Solid	Concrte	0
363	1974 Bldg.	27	XRF	8/26/97	1	Classroom	114	Wall	Midle Wall	Solid	Drywall	0
364	1974 Bldg.	28	XRF	8/26/97	1	Classroom	114	Cabinet	Door	Solid	Wood	0
365	1974 Bldg.	29	XRF	8/26/97	1	Classroom	114	Wall	Wall Rgstr	Solid	Metal	0
366	1974 Bldg.	30	XRF	8/26/97	1	Classroom	114	Door	Door	Solid	Wood	0
367	1974 Bldg.	31	XRF	8/26/97	1	Classroom	114	Door	Casing	Solid	Metal	0
368	1974 Bldg.	32	XRF	8/26/97	1	Classroom	114	Window	Stool	Solid	Metal	0
369	1974 Bldg.	33	XRF	8/26/97	1	Classroom	114	Wall	Midle Wall	Solid	Concrte	0.02
370	1974 Bldg.	17	XRF	8/26/97	1	Classroom	115	Door	Door	Solid	Wood	0
371	1974 Bldg.	18	XRF	8/26/97	1	Classroom	115	Door	Casing	Solid	Metal	0
372	1974 Bldg.	19	XRF	8/26/97	1	Classroom	115	Wall	Midle Wall	Solid	Drywall	0.04
373	1974 Bldg.	20	XRF	8/26/97	1	Classroom	115	Window	Casing	Solid	Metal	0.01
374	1974 Bldg.	21	XRF	8/26/97	1	Classroom	115	Wall	Midle Wall	Solid	Drywall	0
375	1974 Bldg.	22	XRF	8/26/97	1	Classroom	115		Radiator	Solid	Metal	0.01
376	1974 Bldg.	23	XRF	8/26/97	1	Classroom	115	Wall	Midle Wall	Solid	Concrte	0.01
377	1974 Bldg.	24	XRF	8/26/97	1	Classroom	115	Bookcase	Shelf	Solid	Metal	0.05
378	1974 Bldg.	6	XRF	8/26/97	1	Classroom	116	Door	Door	Solid	Wood	0
379	1974 Bldg.	7	XRF	8/26/97	1	Classroom	116	Door	Jamb	Solid	Metal	0
380	1974 Bldg.	8	XRF	8/26/97	1	Classroom	116	Door	Casing	Solid	Metal	0
381	1974 Bldg.	9	XRF	8/26/97	1	Classroom	116	Window	Stool	Solid	Metal	0
382	1974 Bldg.	10	XRF	8/26/97	1	Classroom	116	Wall	Midle Wall	Solid	Concrte	0.05
383	1974 Bldg.	11	XRF	8/26/97	1	Classroom	116		Radiator	Solid	Metal	0.01
384	1974 Bldg.	12	XRF	8/26/97	1	Classroom	116	Wall	Midle Wall	Solid	Concrte	0
385	1974 Bldg.	13	XRF	8/26/97	1	Classroom	116	Wall	Wall	Solid	Drywall	0.05
386	1974 Bldg.	14	XRF	8/26/97	1	Classroom	116	Wall	Wall	Solid	Drywall	0
387	1974 Bldg.	15	XRF	8/26/97	1	Classroom	116	Wall	Midle Wall	Solid	Drywall	0
388	1974 Bldg.	16	XRF	8/26/97	1	Classroom	116	Wall	Wall	Solid	Drywall	0
389	1974 Bldg.	34	XRF	8/26/97	1	Classroom	118	Door	Door	Solid	Wood	0
390	1974 Bldg.	35	XRF	8/26/97	1	Classroom	118	Door	Casing	Solid	Metal	0
391	1974 Bldg.	36	XRF	8/26/97	1	Classroom	118	Wall	Midle Wall	Solid	Drywall	0.01
392	1974 Bldg.	37	XRF	8/26/97	1	Classroom	118	Wall	Midle Wall	Solid	Drywall	0
393	1974 Bldg.	38	XRF	8/26/97	1	Classroom	118	Cabinet	Door	Solid	Wood	0
394	1974 Bldg.	39	XRF	8/26/97	1	Classroom	118		Radiator	Solid	Metal	0
395	1974 Bldg.	40	XRF	8/26/97	1	Classroom	118	Wall	Midle Wall	Solid	Drywall	0
396	1974 Bldg.	41	XRF	8/26/97	1	Classroom	118	Wall	Midle Wall	Solid	Concrte	0.03
397	1974 Bldg.	42	XRF	8/26/97	1	Classroom	118	Wall	Upper Wal	Solid	Concrte	0.11
398	1974 Bldg.	43	XRF	8/26/97	1	Classroom	119	Wall	Midle Wall	Solid	Drywall	0
399	1974 Bldg.	44	XRF	8/26/97	1	Classroom	119	Wall	Midle Wall	Solid	Concrte	0
400	1974 Bldg.	45	XRF	8/26/97	1	Classroom	119	Wall	Wall	Solid	Drywall	0
401	1974 Bldg.	46	XRF	8/26/97	1	Classroom	119		Radiator	Solid	Metal	0.01
402	1974 Bldg.	47	XRF	8/26/97	1	Classroom	119	Cabinet	Door	Solid	Wood	0
403	1974 Bldg.	48	XRF	8/26/97	1	Classroom	119	Wall	Midle Wall	Solid	Drywall	0
404	1974 Bldg.	49	XRF	8/26/97	1	Classroom	119	Wall	Midle Wall	Solid	Drywall	0
405	1974 Bldg.	50	XRF	8/26/97	1	Classroom	119	Wall	Wall Rgstr	Solid	Metal	0
406	1974 Bldg.	51	XRF	8/26/97	1	Classroom	119	Door	Door	Solid	Wood	0
407	1974 Bldg.	52	XRF	8/26/97	1	Classroom	119	Door	Casing	Solid	Metal	0
408	1974 Bldg.	53	XRF	8/26/97	1	Classroom	119	Window	Casing	Solid	Metal	0
409	1974 Bldg.	54	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Drywall	0
410	1974 Bldg.	55	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Drywall	0
411	1974 Bldg.	56	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Concrte	0
412	1974 Bldg.	57	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Drywall	0
413	1974 Bldg.	58	XRF	8/26/97	1	Classroom	120	Cabinet	Door	Solid	Wood	0
414	1974 Bldg.	59	XRF	8/26/97	1	Classroom	120		Radiator	Solid	Metal	0.01

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
415	1974 Bldg.	60	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Concrte	0
416	1974 Bldg.	61	XRF	8/26/97	1	Classroom	120	Wall	Midle Wall	Solid	Concrte	0
417	1974 Bldg.	62	XRF	8/26/97	1	Classroom	120	Door	Door	Solid	Wood	0
418	1974 Bldg.	63	XRF	8/26/97	1	Classroom	120	Door	Casing	Solid	Metal	0
419	1974 Bldg.	64	XRF	8/26/97	1	Classroom	120	Window	Stool	Solid	Metal	0
420	1974 Bldg.	111	XRF	8/27/97	1	Classroom	136	Door	Casing	Solid	Metal	0
421	1974 Bldg.	112	XRF	8/27/97	1	Classroom	136	Wall	Midle Wall	Solid	Concrte	0
422	1974 Bldg.	113	XRF	8/27/97	1	Classroom	136	Wall	Midle Wall	Solid	Drywall	0
423	1974 Bldg.	114	XRF	8/27/97	1	Classroom	136	Cabinet	Door	Solid	Wood	0
424	1974 Bldg.	115	XRF	8/27/97	1	Classroom	136	Wall	Midle Wall	Solid	Drywall	0
425	1974 Bldg.	116	XRF	8/27/97	1	Classroom	136	Door	Door	Solid	Wood	0
426	1974 Bldg.	117	XRF	8/27/97	1	Classroom	136	Bookcase	Shelf	Solid	Wood	0
427	1974 Bldg.	155	XRF	8/26/97	1	Classroom	137	Door	Door	Solid	Wood	0
428	1974 Bldg.	156	XRF	8/26/97	1	Classroom	137	Door	Casing	Solid	Metal	0
429	1974 Bldg.	157	XRF	8/26/97	1	Classroom	137	Wall	Midle Wall	Solid	Drywall	0
430	1974 Bldg.	158	XRF	8/26/97	1	Classroom	137	Wall	Wall Rgstr	Solid	Metal	0.01
431	1974 Bldg.	159	XRF	8/26/97	1	Classroom	137	Wall	Midle Wall	Solid	Concrte	0
432	1974 Bldg.	160	XRF	8/26/97	1	Classroom	137	Wall	Wall	Solid	Drywall	0
433	1974 Bldg.	161	XRF	8/26/97	1	Classroom	137	Wall	Midle Wall	Solid	Concrte	0
434	1974 Bldg.	162	XRF	8/26/97	1	Classroom	137	Wall	Midle Wall	Solid	Drywall	0
435	1974 Bldg.	163	XRF	8/26/97	1	Classroom	137	Cabinet	Door	Solid	Wood	0
436	1974 Bldg.	79	XRF	8/28/97	2	Classroom	200	Wall	Midle Wall	Solid	Drywall	0.11
437	1974 Bldg.	80	XRF	8/28/97	2	Classroom	200	Wall	Column	Solid	Concrte	0
438	1974 Bldg.	81	XRF	8/28/97	2	Classroom	200		Radiator	Solid	Metal	0.01
439	1974 Bldg.	82	XRF	8/28/97	2	Classroom	200	Door	Door	Solid	Wood	0
440	1974 Bldg.	83	XRF	8/28/97	2	Classroom	200	Door	Jamb	Solid	Metal	0
441	1974 Bldg.	84	XRF	8/28/97	2	Classroom	200	Wall	Column	Solid	Concrte	0
442	1974 Bldg.	71	XRF	8/28/97	2	Classroom	202	Wall	Midle Wall	Solid	Drywall	0
443	1974 Bldg.	72	XRF	8/28/97	2	Classroom	202	Door	Door	Solid	Wood	0
444	1974 Bldg.	73	XRF	8/28/97	2	Classroom	202	Door	Jamb	Solid	Metal	0
445	1974 Bldg.	74	XRF	8/28/97	2	Classroom	202	Window	Stool	Solid	Metal	0.04
446	1974 Bldg.	75	XRF	8/28/97	2	Classroom	202	Wall	Midle Wall	Solid	Drywall	0
447	1974 Bldg.	76	XRF	8/28/97	2	Classroom	202	Wall	Wall Rgstr	Solid	Metal	0
448	1974 Bldg.	77	XRF	8/28/97	2	Classroom	202	Cabinet	Door	Solid	Wood	0
449	1974 Bldg.	78	XRF	8/28/97	2	Classroom	202		Radiator	Solid	Metal	0.01
450	1974 Bldg.	58	XRF	8/28/97	2	Classroom	203		Radiator	Solid	Metal	0.01
451	1974 Bldg.	59	XRF	8/28/97	2	Classroom	203	Wall	Column	Solid	Concrte	0
452	1974 Bldg.	60	XRF	8/28/97	2	Classroom	203	Wall	Midle Wall	Solid	Drywall	0
453	1974 Bldg.	61	XRF	8/28/97	2	Classroom	203	Cabinet	Door	Solid	Wood	0
454	1974 Bldg.	62	XRF	8/28/97	2	Classroom	203	Wall	Midle Wall	Solid	Drywall	0
455	1974 Bldg.	63	XRF	8/28/97	2	Classroom	203	Door	Door	Solid	Wood	0
456	1974 Bldg.	64	XRF	8/28/97	2	Classroom	203	Door	Jamb	Solid	Metal	0
457	1974 Bldg.	65	XRF	8/28/97	2	Classroom	203	Window	Stool	Solid	Wood	0.03
458	1974 Bldg.	66	XRF	8/28/97	2	Classroom	203	Wall	Column	Solid	Concrte	0
459	1974 Bldg.	67	XRF	8/28/97	2	Classroom	203	Wall	Column	Solid	Concrte	0
460	1974 Bldg.	68	XRF	8/28/97	2	Classroom	203	Wall	Column	Solid	Concrte	0
461	1974 Bldg.	69	XRF	8/28/97	2	Classroom	203	Wall	Wall	Solid	Drywall	0.07
462	1974 Bldg.	70	XRF	8/28/97	2	Classroom	203	Wall	Wall	Solid	Drywall	0.01
463	1974 Bldg.	46	XRF	8/28/97	2	Classroom	204	Door	Door	Solid	Wood	0
464	1974 Bldg.	47	XRF	8/28/97	2	Classroom	204	Door	Casing	Solid	Metal	0
465	1974 Bldg.	48	XRF	8/28/97	2	Classroom	204	Window	Stool	Solid	Metal	0
466	1974 Bldg.	49	XRF	8/28/97	2	Classroom	204	Wall	Midle Wall	Solid	Drywall	0.02
467	1974 Bldg.	50	XRF	8/28/97	2	Classroom	204		Radiator	Solid	Metal	0
468	1974 Bldg.	51	XRF	8/28/97	2	Classroom	204	Cabinet	Door	Solid	Wood	0
469	1974 Bldg.	52	XRF	8/28/97	2	Classroom	204		Radiator	Solid	Metal	0.01
470	1974 Bldg.	53	XRF	8/28/97	2	Classroom	204		Radiator	Solid	Metal	0.01
471	1974 Bldg.	54	XRF	8/28/97	2	Classroom	204	Wall	Column	Solid	Concrte	0.07
472	1974 Bldg.	55	XRF	8/28/97	2	Classroom	204	Wall	Column	Solid	Concrte	0
473	1974 Bldg.	56	XRF	8/28/97	2	Classroom	204	Wall	Midle Wall	Solid	Drywall	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
474	1974 Bldg.	57	XRF	8/28/97	2	Classroom	204	Wall	Column	Solid	Concrte	0
475	1974 Bldg.	37	XRF	8/28/97	2	Classroom	205	Wall	Wall	Solid	Drywall	0
476	1974 Bldg.	38	XRF	8/28/97	2	Classroom	205	Cabinet	Door	Solid	Wood	0
477	1974 Bldg.	39	XRF	8/28/97	2	Classroom	205	Wall	Column	Solid	Concrte	0.01
478	1974 Bldg.	40	XRF	8/28/97	2	Classroom	205	Door	Door	Solid	Wood	0
479	1974 Bldg.	41	XRF	8/28/97	2	Classroom	205	Door	Jamb	Solid	Metal	0
480	1974 Bldg.	42	XRF	8/28/97	2	Classroom	205	Wall	Wall	Solid	Drywall	0
481	1974 Bldg.	43	XRF	8/28/97	2	Classroom	205	Wall	Midle Wall	Solid	Drywall	0.01
482	1974 Bldg.	44	XRF	8/28/97	2	Classroom	205		Radiator	Solid	Metal	0.01
483	1974 Bldg.	45	XRF	8/28/97	2	Classroom	205	Wall	Midle Wall	Solid	Concrte	0
484	1974 Bldg.	6	XRF	8/28/97	2	Classroom	206	Wall	Midle Wall	Solid	Drywall	0
485	1974 Bldg.	7	XRF	8/28/97	2	Classroom	206	Chalkboard	Rail	Solid	Wood	0
486	1974 Bldg.	8	XRF	8/28/97	2	Classroom	206	Door	Door	Solid	Wood	0
487	1974 Bldg.	9	XRF	8/28/97	2	Classroom	206	Door	Jamb	Solid	Metal	0
488	1974 Bldg.	10	XRF	8/28/97	2	Classroom	206	Window	Stool	Solid	Metal	0
489	1974 Bldg.	11	XRF	8/28/97	2	Classroom	206	Wall	Column	Solid	Concrte	0
490	1974 Bldg.	12	XRF	8/28/97	2	Classroom	206	Wall	Midle Wall	Solid	Drywall	0
491	1974 Bldg.	13	XRF	8/28/97	2	Classroom	206	Cabinet	Door	Solid	Wood	0
492	1974 Bldg.	14	XRF	8/28/97	2	Classroom	206		Radiator	Solid	Metal	0
493	1974 Bldg.	15	XRF	8/28/97	2	Classroom	206		Radiator	Solid	Metal	0.02
494	1974 Bldg.	172	XRF	8/27/97	2	Classroom	207		Radiator	Solid	Metal	0.01
495	1974 Bldg.	173	XRF	8/27/97	2	Classroom	207	Cabinet	Door	Solid	Wood	0
496	1974 Bldg.	174	XRF	8/27/97	2	Classroom	207	Wall	Midle Wall	Solid	Drywall	0.02
497	1974 Bldg.	175	XRF	8/27/97	2	Classroom	207	Wall	Midle Wall	Solid	Drywall	0
498	1974 Bldg.	176	XRF	8/27/97	2	Classroom	207	Wall	Midle Wall	Solid	Drywall	0
499	1974 Bldg.	177	XRF	8/27/97	2	Classroom	207	Door	Door	Solid	Wood	0
500	1974 Bldg.	178	XRF	8/27/97	2	Classroom	207	Door	Casing	Solid	Metal	0.1
501	1974 Bldg.	179	XRF	8/27/97	2	Classroom	207	Door	Casing	Solid	Metal	0
502	1974 Bldg.	180	XRF	8/27/97	2	Classroom	207	Wall	Column	Solid	Concrte	0
503	1974 Bldg.	165	XRF	8/27/97	2	Classroom	208	Door	Door	Solid	Wood	0
504	1974 Bldg.	166	XRF	8/27/97	2	Classroom	208	Door	Casing	Solid	Metal	0
505	1974 Bldg.	167	XRF	8/27/97	2	Classroom	208	Wall	Midle Wall	Solid	Drywall	0.02
506	1974 Bldg.	168	XRF	8/27/97	2	Classroom	208	Wall	Midle Wall	Solid	Drywall	0.05
507	1974 Bldg.	169	XRF	8/27/97	2	Classroom	208	Cabinet	Door	Solid	Wood	0
508	1974 Bldg.	170	XRF	8/27/97	2	Classroom	208		Radiator	Solid	Metal	0
509	1974 Bldg.	171	XRF	8/27/97	2	Classroom	208	Wall	Column	Solid	Concrte	0.01
510	1974 Bldg.	156	XRF	8/27/97	2	Classroom	209	Window	Stool	Solid	Metal	0
511	1974 Bldg.	157	XRF	8/27/97	2	Classroom	209	Door	Door	Solid	Wood	0
512	1974 Bldg.	158	XRF	8/27/97	2	Classroom	209	Wall	Midle Wall	Solid	Drywall	0.03
513	1974 Bldg.	159	XRF	8/27/97	2	Classroom	209	Wall	Midle Wall	Solid	Plaster	0.06
514	1974 Bldg.	160	XRF	8/27/97	2	Classroom	209	Wall	Midle Wall	Solid	Drywall	0.04
515	1974 Bldg.	161	XRF	8/27/97	2	Classroom	209		Radiator	Solid	Metal	0.01
516	1974 Bldg.	162	XRF	8/27/97	2	Classroom	209	Cabinet	Door	Solid	Wood	0
517	1974 Bldg.	163	XRF	8/27/97	2	Classroom	209	Wall	Midle Wall	Solid	Drywall	0.04
518	1974 Bldg.	164	XRF	8/27/97	2	Classroom	209	Wall	Wall Rgstr	Solid	Metal	0
519	1974 Bldg.	144	XRF	8/28/97	2	Classroom	211	Wall	Midle Wall	Solid	Drywall	0
520	1974 Bldg.	145	XRF	8/28/97	2	Classroom	211	Wall	Wall Rgstr	Solid	Metal	0
521	1974 Bldg.	146	XRF	8/28/97	2	Classroom	211	Cabinet	Door	Solid	Wood	0
522	1974 Bldg.	147	XRF	8/28/97	2	Classroom	211	Wall	Midle Wall	Solid	Drywall	0
523	1974 Bldg.	148	XRF	8/28/97	2	Classroom	211		Radiator	Solid	Metal	0.03
524	1974 Bldg.	149	XRF	8/28/97	2	Classroom	211	Wall	Column	Solid	Concrte	0
525	1974 Bldg.	150	XRF	8/28/97	2	Classroom	211		Radiator	Solid	Metal	0.02
526	1974 Bldg.	151	XRF	8/28/97	2	Classroom	211	Door	Door	Solid	Wood	0
527	1974 Bldg.	152	XRF	8/28/97	2	Classroom	211	Door	Jamb	Solid	Metal	0
528	1974 Bldg.	153	XRF	8/28/97	2	Classroom	211	Window	Stool	Solid	Metal	0
529	1974 Bldg.	132	XRF	8/28/97	2	Classroom	212	Wall	Midle Wall	Solid	Drywall	0
530	1974 Bldg.	133	XRF	8/28/97	2	Classroom	212	Wall	Column	Solid	Concrte	0
531	1974 Bldg.	134	XRF	8/28/97	2	Classroom	212	Wall	Wall	Solid	Drywall	0
532	1974 Bldg.	135	XRF	8/28/97	2	Classroom	212	Wall	Wall	Solid	Drywall	0.04

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
533	1974 Bldg.	136	XRF	8/28/97	2	Classroom	212		Radiator	Solid	Metal	0.05
534	1974 Bldg.	137	XRF	8/28/97	2	Classroom	212	Wall	Column	Solid	Concrte	0
535	1974 Bldg.	138	XRF	8/28/97	2	Classroom	212	Wall	Midle Wall	Solid	Drywall	0
536	1974 Bldg.	139	XRF	8/28/97	2	Classroom	212	Cabinet	Door	Solid	Wood	0
537	1974 Bldg.	140	XRF	8/28/97	2	Classroom	212	Wall	Wall Rgstr	Solid	Metal	0
538	1974 Bldg.	141	XRF	8/28/97	2	Classroom	212	Door	Door	Solid	Wood	0
539	1974 Bldg.	142	XRF	8/28/97	2	Classroom	212	Door	Jamb	Solid	Metal	0
540	1974 Bldg.	143	XRF	8/28/97	2	Classroom	212	Window	Stool	Solid	Metal	0
541	1974 Bldg.	120	XRF	8/28/97	2	Classroom	213	Wall	Midle Wall	Solid	Drywall	0.12
542	1974 Bldg.	121	XRF	8/28/97	2	Classroom	213	Wall	Wall Rgstr	Solid	Metal	0
543	1974 Bldg.	122	XRF	8/28/97	2	Classroom	213	Wall	Midle Wall	Solid	Drywall	0
544	1974 Bldg.	123	XRF	8/28/97	2	Classroom	213	Wall	Wall	Solid	Drywall	0
545	1974 Bldg.	124	XRF	8/28/97	2	Classroom	213	Cabinet	Door	Solid	Wood	0
546	1974 Bldg.	125	XRF	8/28/97	2	Classroom	213		Radiator	Solid	Metal	0.01
547	1974 Bldg.	126	XRF	8/28/97	2	Classroom	213	Wall	Wall	Solid	Drywall	0
548	1974 Bldg.	127	XRF	8/28/97	2	Classroom	213	Wall	Column	Solid	Concrte	0.07
549	1974 Bldg.	128	XRF	8/28/97	2	Classroom	213	Door	Door	Solid	Wood	0
550	1974 Bldg.	129	XRF	8/28/97	2	Classroom	213	Door	Casing	Solid	Metal	0
551	1974 Bldg.	130	XRF	8/28/97	2	Classroom	213	Window	Stool	Solid	Metal	0.01
552	1974 Bldg.	131	XRF	8/28/97	2	Classroom	213	Wall	Column	Solid	Concrte	0
553	1974 Bldg.	110	XRF	8/28/97	2	Classroom	214	Wall	Midle Wall	Solid	Drywall	0
554	1974 Bldg.	111	XRF	8/28/97	2	Classroom	214	Wall	Wall	Solid	Drywall	0.01
555	1974 Bldg.	112	XRF	8/28/97	2	Classroom	214	Wall	Column	Solid	Concrte	0
556	1974 Bldg.	113	XRF	8/28/97	2	Classroom	214		Radiator	Solid	Metal	0
557	1974 Bldg.	114	XRF	8/28/97	2	Classroom	214	Wall	Column	Solid	Concrte	0.01
558	1974 Bldg.	115	XRF	8/28/97	2	Classroom	214	Cabinet	Door	Solid	Wood	0
559	1974 Bldg.	116	XRF	8/28/97	2	Classroom	214	Wall	Wall Rgstr	Solid	Metal	0.01
560	1974 Bldg.	117	XRF	8/28/97	2	Classroom	214	Door	Door	Solid	Wood	0
561	1974 Bldg.	118	XRF	8/28/97	2	Classroom	214	Door	Jamb	Solid	Metal	0
562	1974 Bldg.	119	XRF	8/28/97	2	Classroom	214	Window	Stool	Solid	Metal	0
563	1974 Bldg.	101	XRF	8/28/97	2	Classroom	215	Wall	Midle Wall	Solid	Drywall	0.04
564	1974 Bldg.	102	XRF	8/28/97	2	Classroom	215		Radiator	Solid	Metal	0
565	1974 Bldg.	103	XRF	8/28/97	2	Classroom	215		Radiator	Solid	Metal	0.02
566	1974 Bldg.	104	XRF	8/28/97	2	Classroom	215	Wall	Column	Solid	Concrte	0.05
567	1974 Bldg.	105	XRF	8/28/97	2	Classroom	215	Wall	Midle Wall	Solid	Drywall	0
568	1974 Bldg.	106	XRF	8/28/97	2	Classroom	215	Wall	Column	Solid	Concrte	0
569	1974 Bldg.	107	XRF	8/28/97	2	Classroom	215	Door	Door	Solid	Wood	0
570	1974 Bldg.	108	XRF	8/28/97	2	Classroom	215	Door	Jamb	Solid	Metal	0
571	1974 Bldg.	109	XRF	8/28/97	2	Classroom	215	Cabinet	Door	Solid	Wood	0
572	1974 Bldg.	92	XRF	8/28/97	2	Classroom	216	Wall	Midle Wall	Solid	Drywall	0.01
573	1974 Bldg.	93	XRF	8/28/97	2	Classroom	216	Wall	Wall	Solid	Drywall	0.01
574	1974 Bldg.	94	XRF	8/28/97	2	Classroom	216		Radiator	Solid	Metal	0.03
575	1974 Bldg.	95	XRF	8/28/97	2	Classroom	216	Wall	Column	Solid	Concrte	0
576	1974 Bldg.	96	XRF	8/28/97	2	Classroom	216	Cabinet	Door	Solid	Wood	0
577	1974 Bldg.	97	XRF	8/28/97	2	Classroom	216	Wall	Column	Solid	Concrte	0.02
578	1974 Bldg.	98	XRF	8/28/97	2	Classroom	216	Door	Door	Solid	Wood	0
579	1974 Bldg.	99	XRF	8/28/97	2	Classroom	216	Door	Jamb	Solid	Metal	0.04
580	1974 Bldg.	100	XRF	8/28/97	2	Classroom	216	Wall	Wall Rgstr	Solid	Metal	0
581	1974 Bldg.	139	XRF	8/26/97	1	Classroom	1040	Door	Door	Solid	Wood	0
582	1974 Bldg.	140	XRF	8/26/97	1	Classroom	1040	Door	Casing	Solid	Metal	0.08
583	1974 Bldg.	7	XRF	8/27/97	0	Gym	1	Wall	Wall	Solid	Concrte	0
584	1974 Bldg.	8	XRF	8/27/97	0	Gym	1	Wall	Wall	Solid	Concrte	0
585	1974 Bldg.	9	XRF	8/27/97	0	Gym	1	Wall	Wall	Solid	Concrte	0
586	1974 Bldg.	10	XRF	8/27/97	0	Gym	1	Wall	Wall	Solid	Concrte	0.01
587	1974 Bldg.	11	XRF	8/27/97	0	Gym	1	Wall	Wall	Solid	Concrte	0
588	1974 Bldg.	12	XRF	8/27/97	0	Gym	1	Door	Door	Solid	Metal	0
589	1974 Bldg.	13	XRF	8/27/97	0	Gym	1	Door	Casing	Solid	Metal	0.13
590	1974 Bldg.	14	XRF	8/27/97	0	Gym	1	Wall	Column	Solid	Concrte	0
591	1974 Bldg.	15	XRF	8/27/97	0	Gym	1	Door	Door	Solid	Wood	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
592	1974 Bldg.	16	XRF	8/27/97	0	Gym	1	Wall	Wall Rgstr	Solid	Metal	0.04
593	1974 Bldg.	17	XRF	8/27/97	0	Gym	1	Door	Door	Solid	Metal	0
594	1974 Bldg.	18	XRF	8/27/97	0	Gym	1	Door	Casing	Solid	Metal	0.05
595	1974 Bldg.	19	XRF	8/27/97	0	Gym	1	Wall	Backboar	Solid	Wood	0.01
596	1974 Bldg.	32	XRF	8/27/97	0	Gym	1081		Locker	Solid	Metal	0.44
597	1974 Bldg.	33	XRF	8/27/97	0	Gym	1081		Locker	Solid	Metal	0
598	1974 Bldg.	34	XRF	8/27/97	0	Gym	1081	Wall	Midle Wall	Solid	Concrte	0.05
599	1974 Bldg.	35	XRF	8/27/97	0	Gym	1081	Door	Door	Solid	Wood	0
600	1974 Bldg.	36	XRF	8/27/97	0	Gym	1081	Door	Casing	Solid	Metal	0.15
601	1974 Bldg.	37	XRF	8/27/97	0	Gym	1081	Ceiling		Solid	Drywall	0
602	1974 Bldg.	20	XRF	8/27/97	0	Gym	1082	Cabinet	Door	Solid	Wood	0.04
603	1974 Bldg.	21	XRF	8/27/97	0	Gym	1082	Cabinet	Door	Solid	Wood	0.06
604	1974 Bldg.	22	XRF	8/27/97	0	Gym	1082	Wall	Midle Wall	Solid	Concrte	0
605	1974 Bldg.	23	XRF	8/27/97	0	Gym	1082	Door	Door	Solid	Metal	0.02
606	1974 Bldg.	24	XRF	8/27/97	0	Gym	1082	Door	Door	Solid	Metal	0
607	1974 Bldg.	25	XRF	8/27/97	0	Gym	1082	Door	Door	Solid	Metal	0.03
608	1974 Bldg.	26	XRF	8/27/97	0	Gym	1082	Door	Casing	Solid	Metal	0.17
609	1974 Bldg.	27	XRF	8/27/97	0	Gym	1083	Wall	Midle Wall	Solid	Concrte	0.01
610	1974 Bldg.	28	XRF	8/27/97	0	Gym	1083	Door	Door	Solid	Metal	0
611	1974 Bldg.	29	XRF	8/27/97	0	Gym	1083	Door	Casing	Solid	Metal	0.04
612	1974 Bldg.	30	XRF	8/27/97	0	Gym	1083	Door	Casing	Solid	Metal	0.25
613	1974 Bldg.	31	XRF	8/27/97	0	Gym	1083	Wall	Column	Solid	Concrte	0.02
614	1974 Bldg.	38	XRF	8/27/97	0	Gym	1086	Wall	Midle Wall	Solid	Concrte	0.01
615	1974 Bldg.	39	XRF	8/27/97	0	Gym	1086	Door	Door	Solid	Wood	0
616	1974 Bldg.	40	XRF	8/27/97	0	Gym	1086	Door	Casing	Solid	Metal	0.08
617	1974 Bldg.	41	XRF	8/27/97	0	Gym	1086	Ceiling		Solid	Drywall	0
618	1974 Bldg.	123	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0
619	1974 Bldg.	124	XRF	8/27/97	1	Hall	1000	Window	Stool	Solid	Metal	0.02
620	1974 Bldg.	125	XRF	8/27/97	1	Hall	1000	Door	Door	Solid	Wood	0
621	1974 Bldg.	126	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0
622	1974 Bldg.	127	XRF	8/27/97	1	Hall	1000	Door	Door	Solid	Metal	0.12
623	1974 Bldg.	128	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0.02
624	1974 Bldg.	129	XRF	8/27/97	1	Hall	1000	Bench		Solid	Wood	0.69
625	1974 Bldg.	130	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0
626	1974 Bldg.	131	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0.02
627	1974 Bldg.	132	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0
628	1974 Bldg.	133	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0.01
629	1974 Bldg.	134	XRF	8/27/97	1	Hall	1000	Wall	Column	Solid	Concrte	0
630	1974 Bldg.	135	XRF	8/27/97	1	Hall	1000	Wall	Midle Wall	Solid	Concrte	0.01
631	1974 Bldg.	136	XRF	8/27/97	1	Hall	1000		Radiator	Solid	Metal	0.01
632	1974 Bldg.	137	XRF	8/27/97	1	Hall	1010	Door	Door	Solid	Wood	0
633	1974 Bldg.	138	XRF	8/27/97	1	Hall	1010	Door	Casing	Solid	Metal	0.05
634	1974 Bldg.	139	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0.02
635	1974 Bldg.	140	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0
636	1974 Bldg.	141	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0
637	1974 Bldg.	142	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0.01
638	1974 Bldg.	143	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0.04
639	1974 Bldg.	144	XRF	8/27/97	1	Hall	1010	Door	Door	Solid	Metal	0
640	1974 Bldg.	145	XRF	8/27/97	1	Hall	1010	Wall	Midle Wall	Solid	Concrte	0
641	1974 Bldg.	146	XRF	8/27/97	1	Hall	1010	Wall	Wall	Solid	Plaster	0
642	1974 Bldg.	147	XRF	8/27/97	1	Hall	1010	Wall	Midle Wall	Solid	Concrte	0.01
643	1974 Bldg.	148	XRF	8/27/97	1	Hall	1010	Door	Door	Solid	Metal	0
644	1974 Bldg.	149	XRF	8/27/97	1	Hall	1010		Radiator	Solid	Metal	0.01
645	1974 Bldg.	150	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0
646	1974 Bldg.	151	XRF	8/27/97	1	Hall	1010	Wall	Midle Wall	Solid	Concrte	0
647	1974 Bldg.	152	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0.01
648	1974 Bldg.	153	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0.03
649	1974 Bldg.	154	XRF	8/27/97	1	Hall	1010	Wall	Column	Solid	Concrte	0
650	1974 Bldg.	155	XRF	8/27/97	1	Hall	1010	Ceiling		Solid	Drywall	0.05

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
651	1974 Bldg.	183	XRF	8/28/97	2	Hall	2000	Door	Door	Solid	Metal	0.11
652	1974 Bldg.	184	XRF	8/28/97	2	Hall	2000	Door	Jamb	Solid	Metal	0.06
653	1974 Bldg.	185	XRF	8/28/97	2	Hall	2000	Wall	Column	Solid	Concrte	0
654	1974 Bldg.	186	XRF	8/28/97	2	Hall	2000	Door	Door	Solid	Wood	0
655	1974 Bldg.	187	XRF	8/28/97	2	Hall	2000	Door	Casing	Solid	Metal	0.01
656	1974 Bldg.	188	XRF	8/28/97	2	Hall	2000	Wall	Column	Solid	Concrte	0.05
657	1974 Bldg.	189	XRF	8/28/97	2	Hall	2000	Wall	Wall	Solid	Concrte	0
658	1974 Bldg.	190	XRF	8/28/97	2	Hall	2000	Stairs	Hand rail	Solid	Wood	0
659	1974 Bldg.	191	XRF	8/28/97	2	Hall	2000	Window	Stool	Solid	Metal	0
660	1974 Bldg.	192	XRF	8/28/97	2	Hall	2000	Window	Casing	Solid	Metal	0.02
661	1974 Bldg.	193	XRF	8/28/97	2	Hall	2000	Wall	Midle Wall	Solid	Concrte	0
662	1974 Bldg.	194	XRF	8/28/97	2	Hall	2000	Wall	Column	Solid	Concrte	0
663	1974 Bldg.	54	XRF	8/27/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrte	0
664	1974 Bldg.	55	XRF	8/27/97	1	Kitchen	1	Door	Door	Solid	Metal	0
665	1974 Bldg.	56	XRF	8/27/97	1	Kitchen	1	Door	Casing	Solid	Metal	0.18
666	1974 Bldg.	57	XRF	8/27/97	1	Kitchen	1	Door	Door	Solid	Metal	0.01
667	1974 Bldg.	58	XRF	8/27/97	1	Kitchen	1		Elec Pane	Solid	Metal	0.01
668	1974 Bldg.	59	XRF	8/27/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrte	0.01
669	1974 Bldg.	60	XRF	8/27/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrte	0.03
670	1974 Bldg.	61	XRF	8/27/97	1	Kitchen	1	Door	Door	Solid	Metal	0
671	1974 Bldg.	62	XRF	8/27/97	1	Kitchen	1	Door	Casing	Solid	Metal	0.15
672	1974 Bldg.	71	XRF	8/27/97	1	Kitchen	1092	Wall	Midle Wall	Solid	Concrte	0
673	1974 Bldg.	72	XRF	8/27/97	1	Kitchen	1092	Door	Door	Solid	Metal	0
674	1974 Bldg.	73	XRF	8/27/97	1	Kitchen	1092	Door	Casing	Solid	Metal	0.13
675	1974 Bldg.	86	XRF	8/27/97	1	Kitchen	1093	Door	Door	Solid	Metal	0
676	1974 Bldg.	87	XRF	8/27/97	1	Kitchen	1093	Door	Casing	Solid	Metal	0.03
677	1974 Bldg.	88	XRF	8/27/97	1	Kitchen	1093	Wall	Midle Wall	Solid	Concrte	0
678	1974 Bldg.	89	XRF	8/27/97	1	Kitchen	1093	Cabinet	Door	Solid	Metal	0.33
679	1974 Bldg.	90	XRF	8/27/97	1	Kitchen	1093	Floor		Solid	Concrte	0.11
680	1974 Bldg.	67	XRF	8/27/97	1	Kitchen	10912	Wall	Midle Wall	Solid	Concrte	0
681	1974 Bldg.	68	XRF	8/27/97	1	Kitchen	10912	Door	Door	Solid	Metal	0.01
682	1974 Bldg.	69	XRF	8/27/97	1	Kitchen	10912	Door	Casing	Solid	Metal	0.14
683	1974 Bldg.	70	XRF	8/27/97	1	Kitchen	10912	Floor		Cracked	Concrte	0
684	1974 Bldg.	118	XRF	8/27/97	1	Library	123	Wall	Midle Wall	Solid	Concrte	0
685	1974 Bldg.	119	XRF	8/27/97	1	Library	123	Wall	Midle Wall	Solid	Drywall	0.01
686	1974 Bldg.	120	XRF	8/27/97	1	Library	123		Radiator	Solid	Metal	0.01
687	1974 Bldg.	121	XRF	8/27/97	1	Library	123	Door	Door	Solid	Wood	0
688	1974 Bldg.	122	XRF	8/27/97	1	Library	123	Door	Casing	Solid	Metal	0.19
689	1974 Bldg.	126	XRF	8/26/97	1	Library	125	Wall	Midle Wall	Solid	Drywall	0
690	1974 Bldg.	127	XRF	8/26/97	1	Library	125	Door	Door	Solid	Wood	0
691	1974 Bldg.	128	XRF	8/26/97	1	Library	125	Door	Casing	Solid	Metal	0.1
692	1974 Bldg.	129	XRF	8/26/97	1	Library	125		Radiator	Solid	Metal	0
693	1974 Bldg.	130	XRF	8/26/97	1	Library	125	Wall	Midle Wall	Solid	Concrte	0
694	1974 Bldg.	131	XRF	8/26/97	1	Library	125	Wall	Column	Solid	Concrte	0
695	1974 Bldg.	132	XRF	8/26/97	1	Library	125	Stairs	Hand rail	Solid	Metal	0.03
696	1974 Bldg.	133	XRF	8/26/97	1	Library	125	Stairs	Wall	Solid	Concrte	0
697	1974 Bldg.	134	XRF	8/26/97	1	Library	125	Wall	Wall	Solid	Concrte	0
698	1974 Bldg.	135	XRF	8/26/97	1	Library	125	Window	Stool	Solid	Metal	0.02
699	1974 Bldg.	136	XRF	8/26/97	1	Lounge	1000	Cabinet	Door	Solid	Wood	0
700	1974 Bldg.	137	XRF	8/26/97	1	Lounge	1000	Door	Door	Solid	Wood	0
701	1974 Bldg.	138	XRF	8/26/97	1	Lounge	1000	Door	Casing	Solid	Metal	0.13
702	1974 Bldg.	91	XRF	8/27/97	1	Main	1	Door	Door	Solid	Wood	0
703	1974 Bldg.	92	XRF	8/27/97	1	Main	1	Door	Casing	Solid	Metal	0.12
704	1974 Bldg.	93	XRF	8/27/97	1	Main	1	Cabinet	Door	Solid	Wood	0
705	1974 Bldg.	94	XRF	8/27/97	1	Main	1		Radiator	Solid	Metal	0.01
706	1974 Bldg.	95	XRF	8/27/97	1	Main	1	Wall	Midle Wall	Solid	Drywall	0
707	1974 Bldg.	96	XRF	8/27/97	1	Main	1	Cabinet	Door	Solid	Wood	0
708	1974 Bldg.	97	XRF	8/27/97	1	Main	1	Window	Stool	Solid	Metal	0.06
709	1974 Bldg.	98	XRF	8/27/97	1	Main	1	Wall	Midle Wall	Solid	Concrte	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection


	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
710	1974 Bldg.	99	XRF	8/27/97	1	Main	1	Wall	Transom	Solid	Wood	0
711	1974 Bldg.	100	XRF	8/27/97	1	Main	1	Wall	Midle Wall	Solid	Drywall	0
712	1974 Bldg.	101	XRF	8/27/97	1	Main	2	Door	Door	Solid	Wood	0
713	1974 Bldg.	102	XRF	8/27/97	1	Main	2	Door	Casing	Solid	Metal	0.33
714	1974 Bldg.	103	XRF	8/27/97	1	Main	3	Wall	Midle Wall	Solid	Drywall	1.07
715	1974 Bldg.	104	XRF	8/27/97	1	Main	3		Radiator	Solid	Metal	0
716	1974 Bldg.	105	XRF	8/27/97	1	Main	3	Door	Door	Solid	Wood	0
717	1974 Bldg.	106	XRF	8/27/97	1	Main	3	Door	Casing	Solid	Metal	0.1
718	1974 Bldg.	107	XRF	8/27/97	1	Main	4		Radiator	Solid	Metal	0.04
719	1974 Bldg.	108	XRF	8/27/97	1	Main	4	Wall	Midle Wall	Solid	Drywall	1.24
720	1974 Bldg.	109	XRF	8/27/97	1	Main	4	Door	Door	Solid	Wood	0
721	1974 Bldg.	110	XRF	8/27/97	1	Main	4	Door	Casing	Solid	Metal	0.19
722	1974 Bldg.	84	XRF	8/26/97	1	Restroom	1020		Stall Door	Solid	Metal	0.41
723	1974 Bldg.	85	XRF	8/26/97	1	Restroom	1020	Wall	Midle Wall	Solid	Concrte	0
724	1974 Bldg.	86	XRF	8/26/97	1	Restroom	1020	Wall	Midle Wall	Solid	Concrte	0
725	1974 Bldg.	87	XRF	8/26/97	1	Restroom	1020	Door	Door	Solid	Wood	0
726	1974 Bldg.	88	XRF	8/26/97	1	Restroom	1020	Door	Casing	Solid	Metal	0.13
727	1974 Bldg.	89	XRF	8/26/97	1	Restroom	1020	Door	Bthrm Stil	Solid	Metal	0.36
728	1974 Bldg.	90	XRF	8/26/97	1	Restroom	1020	Ceiling		Solid	Drywall	0
729	1974 Bldg.	141	XRF	8/26/97	1	Restroom	1050	Door	Door	Solid	Wood	0
730	1974 Bldg.	142	XRF	8/26/97	1	Restroom	1050	Door	Casing	Solid	Metal	0.16
731	1974 Bldg.	143	XRF	8/26/97	1	Restroom	1050	Door	Bthrm Stil	Solid	Metal	0
732	1974 Bldg.	144	XRF	8/26/97	1	Restroom	1050	Ceiling		Solid	Drywall	0
733	1974 Bldg.	145	XRF	8/26/97	1	Restroom	1060	Ceiling		Solid	Drywall	0
734	1974 Bldg.	146	XRF	8/26/97	1	Restroom	1060	Door	Door	Solid	Wood	0
735	1974 Bldg.	147	XRF	8/26/97	1	Restroom	1060	Door	Casing	Solid	Metal	0.19
736	1974 Bldg.	148	XRF	8/26/97	1	Restroom	1060	Wall	Midle Wall	Solid	Drywall	0
737	1974 Bldg.	149	XRF	8/26/97	1	Restroom	1060		Stall Door	Solid	Metal	0.01
738	1974 Bldg.	179	XRF	8/26/97	1	Restroom	1080	Wall	Midle Wall	Solid	Concrte	0
739	1974 Bldg.	180	XRF	8/26/97	1	Restroom	1080	Door	Door	Solid	Wood	0
740	1974 Bldg.	181	XRF	8/26/97	1	Restroom	1080	Door	Casing	Solid	Metal	0.1
741	1974 Bldg.	182	XRF	8/26/97	1	Restroom	1080	Door	Bthrm Stil	Solid	Metal	0.41
742	1974 Bldg.	183	XRF	8/26/97	1	Restroom	1080	Ceiling		Solid	Drywall	0
743	1974 Bldg.	42	XRF	8/27/97	0	Restroom	1085	Wall	Midle Wall	Solid	Concrte	0
744	1974 Bldg.	43	XRF	8/27/97	0	Restroom	1085	Door	Door	Solid	Wood	0
745	1974 Bldg.	44	XRF	8/27/97	0	Restroom	1085	Door	Casing	Solid	Metal	0.12
746	1974 Bldg.	45	XRF	8/27/97	0	Restroom	1085	Door	Bthrm Stil	Solid	Metal	0.25
747	1974 Bldg.	46	XRF	8/27/97	0	Restroom	1085	Ceiling		Solid	Drywall	0.02
748	1974 Bldg.	26	XRF	8/28/97	2	Restroom	2030	Wall	Bthrm Stil	Solid	Metal	0.56
749	1974 Bldg.	27	XRF	8/28/97	2	Restroom	2030	Wall	Stall Door	Solid	Metal	0.58
750	1974 Bldg.	28	XRF	8/28/97	2	Restroom	2030		Radiator	Solid	Metal	0.01
751	1974 Bldg.	29	XRF	8/28/97	2	Restroom	2030	Wall	Midle Wall	Solid	Concrte	0
752	1974 Bldg.	30	XRF	8/28/97	2	Restroom	2030	Door	Door	Solid	Wood	0
753	1974 Bldg.	31	XRF	8/28/97	2	Restroom	2030	Door	Jamb	Solid	Metal	0.15
754	1974 Bldg.	32	XRF	8/28/97	2	Restroom	2030	Ceiling		Solid	Drywall	0
755	1974 Bldg.	33	XRF	8/28/97	2	Restroom	2040	Door	Door	Solid	Wood	0
756	1974 Bldg.	34	XRF	8/28/97	2	Restroom	2040	Door	Jamb	Solid	Metal	0
757	1974 Bldg.	35	XRF	8/28/97	2	Restroom	2040	Wall	Midle Wall	Solid	Drywall	0
758	1974 Bldg.	36	XRF	8/28/97	2	Restroom	2040	Ceiling		Solid	Drywall	0.01
759	1974 Bldg.	74	XRF	8/27/97	1	Room	124	Wall	Midle Wall	Solid	Plaster	0
760	1974 Bldg.	75	XRF	8/27/97	1	Room	124	Cabinet	Door	Solid	Wood	0
761	1974 Bldg.	76	XRF	8/27/97	1	Room	124	Wall	Wall	Solid	Concrte	0
762	1974 Bldg.	77	XRF	8/27/97	1	Room	124	Wall	Midle Wall	Solid	Concrte	0
763	1974 Bldg.	78	XRF	8/27/97	1	Room	124	Door	Door	Solid	Wood	0
764	1974 Bldg.	79	XRF	8/27/97	1	Room	124	Door	Casing	Solid	Metal	0.08
765	1974 Bldg.	80	XRF	8/27/97	1	Room	124		Radiator	Solid	Metal	0
766	1974 Bldg.	164	XRF	8/26/97	1	Room	135	Door	Door	Solid	Wood	0
767	1974 Bldg.	165	XRF	8/26/97	1	Room	135	Door	Casing	Solid	Metal	0.1
768	1974 Bldg.	166	XRF	8/26/97	1	Room	135	Window	Stool	Solid	Metal	0.05

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
769	1974 Bldg.	167	XRF	8/26/97	1	Room	135	Wall	Midle Wall	Solid	Drywall	0
770	1974 Bldg.	168	XRF	8/26/97	1	Room	135	Wall	Midle Wall	Solid	Drywall	0
771	1974 Bldg.	169	XRF	8/26/97	1	Room	135	Wall	Midle Wall	Solid	Concrte	0
772	1974 Bldg.	170	XRF	8/26/97	1	Room	135	Wall	Column	Solid	Concrte	0
773	1974 Bldg.	171	XRF	8/26/97	1	Room	135	Door	Jamb	Solid	Metal	0
774	1974 Bldg.	172	XRF	8/26/97	1	Room	135	Wall	Midle Wall	Solid	Concrte	0
775	1974 Bldg.	173	XRF	8/26/97	1	Room	135	Wall	Midle Wall	Solid	Drywall	0.01
776	1974 Bldg.	150	XRF	8/26/97	1	Room	143	Door	Door	Solid	Wood	0
777	1974 Bldg.	151	XRF	8/26/97	1	Room	143	Door	Casing	Solid	Metal	0.07
778	1974 Bldg.	152	XRF	8/26/97	1	Room	143	Cabinet	Door	Solid	Wood	0
779	1974 Bldg.	153	XRF	8/26/97	1	Room	143	Wall	Midle Wall	Solid	Drywall	0
780	1974 Bldg.	154	XRF	8/26/97	1	Room	143	Cabinet	Door	Solid	Wood	0
781	1974 Bldg.	81	XRF	8/27/97	1	Room	146		Radiator	Solid	Metal	0.04
782	1974 Bldg.	82	XRF	8/27/97	1	Room	146	Wall	Midle Wall	Solid	Concrte	0
783	1974 Bldg.	83	XRF	8/27/97	1	Room	146	Wall	Wall	Solid	Concrte	0.01
784	1974 Bldg.	84	XRF	8/27/97	1	Room	146	Door	Door	Solid	Wood	0
785	1974 Bldg.	85	XRF	8/27/97	1	Room	146	Door	Casing	Solid	Metal	0.2
786	1974 Bldg.	75	XRF	8/26/97	1	Room	1000	Wall	Transom	Solid	Wood	0.05
787	1974 Bldg.	76	XRF	8/26/97	1	Room	1000	Wall	Midle Wall	Solid	Drywall	0.03
788	1974 Bldg.	77	XRF	8/26/97	1	Room	1000	Door	Door	Solid	Wood	0
789	1974 Bldg.	78	XRF	8/26/97	1	Room	1000	Door	Casing	Solid	Metal	0.1
790	1974 Bldg.	79	XRF	8/26/97	1	Room	1000	Floor		Cracked	Concrte	0.02
791	1974 Bldg.	80	XRF	8/26/97	1	Room	1010	Wall	Midle Wall	Solid	Drywall	0.01
792	1974 Bldg.	81	XRF	8/26/97	1	Room	1010	Door	Door	Solid	Wood	0
793	1974 Bldg.	82	XRF	8/26/97	1	Room	1010	Door	Casing	Solid	Metal	0.01
794	1974 Bldg.	83	XRF	8/26/97	1	Room	1010	Ceiling		Solid	Drywall	0
795	1974 Bldg.	107	XRF	8/26/97	1	Room	1030	Wall	Midle Wall	Solid	Plaster	0
796	1974 Bldg.	108	XRF	8/26/97	1	Room	1030	Wall	Midle Wall	Solid	Concrte	0.01
797	1974 Bldg.	109	XRF	8/26/97	1	Room	1030	Door	Door	Solid	Wood	0
798	1974 Bldg.	110	XRF	8/26/97	1	Room	1030	Door	Jamb	Solid	Metal	0.08
799	1974 Bldg.	174	XRF	8/26/97	1	Room	1070	Door	Door	Solid	Wood	0
800	1974 Bldg.	175	XRF	8/26/97	1	Room	1070	Door	Casing	Solid	Metal	0.08
801	1974 Bldg.	176	XRF	8/26/97	1	Room	1070	Wall	Midle Wall	Solid	Concrte	0
802	1974 Bldg.	177	XRF	8/26/97	1	Room	1070	Stairs	Hand rail	Solid	Metal	0.03
803	1974 Bldg.	178	XRF	8/26/97	1	Room	1070	Floor		Cracked	Concrte	0.02
804	1974 Bldg.	63	XRF	8/27/97	1	Room	1090	Door	Door	Solid	Metal	0
805	1974 Bldg.	64	XRF	8/27/97	1	Room	1090	Door	Casing	Solid	Metal	0.14
806	1974 Bldg.	65	XRF	8/27/97	1	Room	1090	Wall	Midle Wall	Solid	Concrte	0
807	1974 Bldg.	66	XRF	8/27/97	1	Room	1090	Floor		Cracked	Concrte	0
808	1974 Bldg.	16	XRF	8/28/97	2	Room	2010	Wall	Wall	Solid	Drywall	0
809	1974 Bldg.	17	XRF	8/28/97	2	Room	2010	Wall	Transom	Solid	Wood	0
810	1974 Bldg.	18	XRF	8/28/97	2	Room	2010	Door	Door	Solid	Wood	0
811	1974 Bldg.	19	XRF	8/28/97	2	Room	2010	Door	Jamb	Solid	Metal	0.07
812	1974 Bldg.	20	XRF	8/28/97	2	Room	2010		Elec Pane	Solid	Metal	0.03
813	1974 Bldg.	21	XRF	8/28/97	2	Room	2010	Floor		Solid	Concrte	0
814	1974 Bldg.	22	XRF	8/28/97	2	Room	2020	Wall	Midle Wall	Solid	Drywall	0.06
815	1974 Bldg.	23	XRF	8/28/97	2	Room	2020	Door	Door	Solid	Wood	0
816	1974 Bldg.	24	XRF	8/28/97	2	Room	2020	Door	Jamb	Solid	Metal	0.02
817	1974 Bldg.	25	XRF	8/28/97	2	Room	2020	Ceiling		Solid	Drywall	0.02
818	1974 Bldg.	85	XRF	8/28/97	2	Room	2050		Elec Pane	Solid	Metal	0.06
819	1974 Bldg.	86	XRF	8/28/97	2	Room	2050	Door	Door	Solid	Wood	0
820	1974 Bldg.	87	XRF	8/28/97	2	Room	2050	Door	Jamb	Solid	Metal	0.18
821	1974 Bldg.	88	XRF	8/28/97	2	Room	2050	Floor		Cracked	Concrte	0.01
822	1974 Bldg.	89	XRF	8/28/97	2	Room	2060	Wall	Midle Wall	Cracked	Concrte	0
823	1974 Bldg.	90	XRF	8/28/97	2	Room	2060	Door	Door	Solid	Wood	0
824	1974 Bldg.	91	XRF	8/28/97	2	Room	2060	Door	Casing	Solid	Metal	0.02
825	1974 Bldg.	47	XRF	8/27/97	2	Room	2400	Wall	Midle Wall	Solid	Concrte	0
826	1974 Bldg.	48	XRF	8/27/97	2	Room	2400	Wall	Midle Wall	Solid	Concrte	0
827	1974 Bldg.	49	XRF	8/27/97	2	Room	2400	Wall	Transom	Solid	Wood	0

Saint Paul Public Schools
Parkway Elementary School
Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample #	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
828	1974 Bldg.	50	XRF	8/27/97	2	Room	2400	Floor		Solid	Concrte	0
829	1974 Bldg.	51	XRF	8/27/97	2	Room	2400	Stairs	Hand rail	Solid	Metal	0.03
830	1974 Bldg.	52	XRF	8/27/97	2	Room	2400	Door	Door	Solid	Metal	0
831	1974 Bldg.	53	XRF	8/27/97	2	Room	2400	Door	Casing	Solid	Metal	0.12
832	1974 Bldg.	154	XRF	8/28/97	2	Stairwell	1	Door	Door	Solid	Wood	0
833	1974 Bldg.	155	XRF	8/28/97	2	Stairwell	1	Window	Casing	Solid	Metal	0.02
834	1974 Bldg.	156	XRF	8/28/97	2	Stairwell	1	Window	Stool	Solid	Metal	0.04
835	1974 Bldg.	157	XRF	8/28/97	2	Stairwell	1	Wall	Midle Wall	Solid	Concrte	0
836	1974 Bldg.	158	XRF	8/28/97	2	Stairwell	1	Wall	Midle Wall	Solid	Concrte	0
837	1974 Bldg.	159	XRF	8/28/97	2	Stairwell	1	Wall	Wall	Solid	Concrte	0.02
838	1974 Bldg.	160	XRF	8/28/97	2	Stairwell	1	Stairs	Hand rail	Solid	Metal	0
839	1974 Bldg.	161	XRF	8/28/97	2	Stairwell	1	Window	Panel	Solid	Wood	0
840	1974 Bldg.	162	XRF	8/28/97	2	Stairwell	1		Radiator	Solid	Metal	0.01
841	1974 Bldg.	163	XRF	8/28/97	2	Stairwell	1	Wall	Wall	Solid	Concrte	0.01
842	1974 Bldg.	164	XRF	8/28/97	2	Stairwell	2	Wall	Midle Wall	Solid	Concrte	0
843	1974 Bldg.	165	XRF	8/28/97	2	Stairwell	2	Wall	Wall	Solid	Concrte	0.05
844	1974 Bldg.	166	XRF	8/28/97	2	Stairwell	2	Door	Door	Solid	Wood	0
845	1974 Bldg.	167	XRF	8/28/97	2	Stairwell	2	Window	Casing	Solid	Metal	0.03
846	1974 Bldg.	168	XRF	8/28/97	2	Stairwell	2	Wall	Wall	Solid	Concrte	0.01
847	1974 Bldg.	169	XRF	8/28/97	2	Stairwell	2	Wall	Midle Wall	Solid	Concrte	0
848	1974 Bldg.	170	XRF	8/28/97	2	Stairwell	2	Wall	Wall	Solid	Concrte	0.03
849	1974 Bldg.	171	XRF	8/28/97	2	Stairwell	2	Stairs	Hand rail	Solid	Metal	0.01
850	1974 Bldg.	172	XRF	8/28/97	2	Stairwell	2	Door	Casing	Solid	Metal	0.16
851	1974 Bldg.	173	XRF	8/28/97	2	Stairwell	2		Radiator	Solid	Metal	0.05
852	1974 Bldg.	174	XRF	8/28/97	2	Stairwell	3	Wall	Wall	Solid	Concrte	0
853	1974 Bldg.	175	XRF	8/28/97	2	Stairwell	3	Wall	Wall	Solid	Concrte	0
854	1974 Bldg.	176	XRF	8/28/97	2	Stairwell	3	Stairs	Hand rail	Solid	Metal	0.01
855	1974 Bldg.	177	XRF	8/28/97	2	Stairwell	3	Door	Door	Solid	Wood	0
856	1974 Bldg.	178	XRF	8/28/97	2	Stairwell	3	Window	Casing	Solid	Metal	0.04
857	1974 Bldg.	179	XRF	8/28/97	2	Stairwell	3	Door	Casing	Solid	Metal	0.15
858	1974 Bldg.	180	XRF	8/28/97	2	Stairwell	3	Wall	Wall	Solid	Concrte	0.01
859	1974 Bldg.	181	XRF	8/28/97	2	Stairwell	3	Wall	Wall	Solid	Concrte	0
860	1974 Bldg.	182	XRF	8/28/97	2	Stairwell	3		Radiator	Solid	Metal	0.03



exterior

THIRD FLOOR PLAN



INDEPENDENT SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102


PARKWAY ELEMENTARY
800 CLARENCE STREET
ST. PAUL, MN

CONSTRUCTED: 1925, 58, 74


4
5

9-3-97

B



8-29-97



93-97

FIRST FLOOR PLAN




MIDLEBENT SCHOOL DIST. #025
360 COLUMBIE STREET
ST. PAUL, MINN. 55107

PARKWAY ELEMENTARY
800 CLARENCE STREET
ST. PAUL, MN


CONSTRUCTED: 1925, 58, 74

2
5




2 5
 CONSTRUCTED 1925, 58, 74
 PARKWAY ELEMENTARY
 800 CLARENCE STREET
 ST. PAUL, MN
 INDEPENDENT SCHOOL DIST. # 625
 2514 WILKINSON AVE. ST. PAUL, MN 55107
 380 COLUMBIA STREET
 ST. PAUL, MN 55107

9-3-97
 8-29-97
 8-26-97
 8-27-97








INDEPENDENT SCHOOL DIST #625
360 COLBORNE STREET

PARKWAY ELEMENTARY
800 CLARENCE STREET

CONSTRUCTED 1925, 58, 74

3'

9-3-97




SECOND FLOOR PLAN

INDEPENDENT SCHOOL DIST #625
360 COLBORNE STREET
ST PAUL, MINNESOTA 55102

PARKWAY ELEMENTARY
800 CLARENCE STREET
ST. PAUL, MN

CONSTRUCTED 1925, 58, 76

3'
5




3 5


CONSTRUCTED 1925, 58, 74

PARKWAY ELEMENTARY
800 CLARENCE STREET
ST. PAUL, MN


INDEPENDENT SCHOOL DIST #625
360 COLBORNE STREET
ST. PAUL, MN

SECOND FLOOR PLAN






SECOND FLOOR PLAN



AUG-19-97 TUE 11:05 AM MIDWEST ENVIRO CONSULT14 612 757 5541

7
'
5
N



APPENDIX B

LABORATORY SAMPLE ANALYSIS DATA



301 West County Road E2 • St. Paul, MN 55112
(612) 633-0101 • FAX (612) 633-1402

LABORATORY ANALYSIS REPORT

DATE: December 17, 1997

PAGE: 1 Of 3

CLIENT: Midwest Environmental
38894 Llama St.
Dalbo, MN 55017

PROJECT NO: 120297-200888
COLLECTION DATE: 8/26/97-9/03/97
COLLECTED BY: Client
RECEIVED DATE: 12/02/97
PROJECT DESCP: 62/0197-AW

CONTACT: Richard Cox

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	25	1800	DATE
					12/09/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	34	11,000	DATE
					12/09/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	25	600	DATE
					12/09/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	37	2800	DATE
					12/09/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	32	58	DATE
					12/16/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	34	150	DATE
					12/16/97

ANALYSIS	UNITS	Sample No.:	MDL	RESULT	ANALYSIS
Lead (6010A)	mg/kg	Sample ID.:	56	7300	DATE
					12/16/97

ND means Not Detected or below reported MDL

MDL means Method Detection Limit

mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies



301 West County Road E2 • St. Paul, MN 55112
(612) 633-0101 • FAX (612) 633-1402

LABORATORY ANALYSIS REPORT

DATE: December 17, 1997

PAGE: 2 Of 3

CLIENT: Midwest Environmental
38894 Llama St.
Dalbo, MN 55017

PROJECT NO: 120297-200888
COLLECTION DATE: 8/26/97-9/03/97
COLLECTED BY: Client
RECEIVED DATE: 12/02/97
PROJECT DESCP: 62/0197-AW

CONTACT: Richard Cox

<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 18	<u>L978442-8</u> <u>PC-8</u> <u>RESULT</u> 57	<u>ANALYSIS</u> <u>DATE</u> 12/16/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 32	<u>L978442-9</u> <u>PC-9</u> <u>RESULT</u> 2900	<u>ANALYSIS</u> <u>DATE</u> 12/16/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 36	<u>L978442-10</u> <u>PC-10</u> <u>RESULT</u> 1900	<u>ANALYSIS</u> <u>DATE</u> 12/16/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 42	<u>L978442-11</u> <u>PC-11</u> <u>RESULT</u> 82	<u>ANALYSIS</u> <u>DATE</u> 12/16/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 28	<u>L978442-12</u> <u>PC-12</u> <u>RESULT</u> 960	<u>ANALYSIS</u> <u>DATE</u> 12/16/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> <u>Sample ID.:</u> <u>MDL</u> 40	<u>L978442-13</u> <u>PC-13</u> <u>RESULT</u> ND	<u>ANALYSIS</u> <u>DATE</u> 12/16/97

ND means Not Detected or below reported MDL

MDL means Method Detection Limit

mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies



301 West County Road E2 • St. Paul, MN 55112
(612) 633-0101 • FAX (612) 633-1402

LABORATORY ANALYSIS REPORT

DATE: December 17, 1997

PAGE: 3 Of 3


CLIENT: Midwest Environmental
38894 Llama St.
Dalbo, MN 55017

PROJECT NO: 120297-200888
COLLECTION DATE: 8/26/97-9/03/97
COLLECTED BY: Client
RECEIVED DATE: 12/02/97
PROJECT DESCP: 62/0197-AW

CONTACT: Richard Cox

This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.

Report Submitted By,


Thomas L. Halverson
Laboratory Manager

TLH:wmc
mec351-1

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies



Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address _____
Contact R Cox

CHAIN OF CUSTODY RECORD

Project Number 62-0197-AW

Client ST. PAUL FSD

Project PARKWAY Elem

Phone/Fax 689-3612

Sample ID	Sample Description	Collection Date/Time	Matrix (Vol./Area)	Analysis Requested
PC-1	Paint Chip-Rm 105 (# 29, 8-29-97, Side A)	9-3-97 7:45pm	1-2 inches ²	ppm / pb
PC-2	Path 1310 -Paint Chip (# 8, 9-3-97, Side B)	9-3-97 7:48pm	"	"
PC-3	Bath 1310 -Paint Chip (# 9, 9-3-97, Side C)	9-3-97 7:50pm	"	"
PC-4	Bg 1300 -Paint Chip (# 11, 9-3-97, D)	9-3-97 7:52pm	"	"
PC-5	Rm 113 -Paint Chip (# 45, 9-3-97, A)	9-3-97 7:55pm	"	"
PC-6	Hall 1200 -Paint Chip (# 104, 9-3-97, A)	9-3-97 7:58pm	"	"
PC-7	Rm 131 -Paint Chip (# 58, 9-3-97, C)	9-3-97 8:00pm	"	"
PC-8	Kit 1093 -Paint Chip (# 90, 8-27-97, O)	9-3-97 8:05am	"	"
PC-9	Gym 1082 -Paint Chip (# 20, 8-27-97, A)	9-3-97 8:10pm	"	"
PC-10	Rm 1000 -Paint Chip (# 78, 8-26-97, B)	9-3-97 8:15pm	"	"
PC-11	Rm 118 -Paint Chip (# 42, 8-26-97, D)	9-3-97 8:18pm	"	"
PC-12	Hall 2100 -Paint Chip (# 51, 8-29-97, B)	9-3-97 8:20pm	"	"
PC-13	Rm 213 -Paint Chip (# 127, 8-28-97, B)	9-3-97 8:25pm	"	"

Sampled By: SLOAN Date: 9/3/97 Time: 7:45pm

Delivered By: _____ Date: _____ Time: _____

Received By: _____ Date: _____ Time: _____

Delivered By: _____ Date: _____ Time: _____

Received By Lab: _____ Date: _____ Time: _____

Disposition of Samples _____

Notes:

APPENDIX C INSPECTOR

Bill Sloan
MDH Lead Inspector # 476