IEA, INC.

2023 - 2024 Ventilation Assessment



Contact Us:

 BROOKLYN PARK OFFICE

 9201 W. BROADWAY, #600

 BROOKLYN PARK, MN 55445

 763-315-7900

MANKATO OFFICE 610 N. RIVERFRONT DRIVE MANKATO, MN 56001 507-345-8818

ROCHESTER OFFICE 210 WOOD LAKE DRIVE SE ROCHESTER, MN 55904 507-281-6664

BRAINERD OFFICE 601 NW 5TH STREET SUITE #4 BRAINERD, MN 56401 218-454-0703

MARSHALL OFFICE 1420 EAST COLLEGE DRIVE MARSHALL, MN 56258 507-476-3599

VIRGINIA OFFICE 5525 EMERALD AVENUE MOUNTAIN IRON, MN 55768 218-410-9521

www.ieasafety.com

info@ieasafety.com

800-233-9513

Saint Paul Public Schools Open World Learning

Assessment Date: Thursday, April 6, 2023

Project Description

IEA conducted a ventilation inspection in Open World Learning by IEA representative, Jack Skluzacek, with the intent of gathering visual observations and overall ventilation information which will assist the District in making informed and proactive decisions to improve and maintain acceptable air quality in the building. This inspection is based upon the Environmental Protection Agency's (EPA's) Tools for Schools IAQ guidelines and the recommended Minnesota Department of Education (MDE) portion of a school district's IAQ management plan. Ventilation verification is also recommended by American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE).

Some observations gathered during the inspection may identify issues which may require additional testing, evaluation, further investigation, or maintenance on the ventilation systems.

The findings, conclusions and recommendations presented herein are believed to be accurate and representative of the building on the date and time of the inspection.

GENERAL COMMENTS

The analysis and opinions expressed in this report are based upon data obtained from Saint Paul Public Schools at the indicated locations. This report does not reflect variations in conditions that may occur across the site, property, or facility. Actual conditions may vary and may not become evident without further assessment.

The report is prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted indoor air quality practices. Other than as provided in the preceding sentence, no warranties are extended or made.

Building Information

General information regarding the building was collected by IEA during an interview with building maintenance staff. The information gathered during this process is a vital component, as it is helpful in determining how these items may play a role in possible IAQ related issues.

Below is a summary of the information gathered during the interview:

- Automation controls are managed internally.
- A Building Automation System is present. The automation control software program is Tridium and controls can not be accessed remotely.
- Schedules:

Ventilation operation:

Day:	Occupied?	Start Time:	End Time:
Monday- Friday	Yes	6:00 AM	4:00 PM
Saturday	No		
Sunday	No		
Holiday	No		

Typical occupancy:


Day:	Occupied?	Start	End
		Time:	Time:
Monday- Friday	Yes	7:00 AM	3:30 PM
Saturday	No		
Sunday	No		
Holiday	No		

- CO2 sensors are not associated with the ventilation system.
- VAVs are not present.
- It is not known whether or not the building has variable frequency drives (VFD).
- The heating system is a steam boiler.
- A cooling system is not present.
- Filters used are:

Filter Type	MERV Rating
Pleated	MERV 11
Pleated	MERV 13

- Filters are changed quarterly.
- Energy Recovery Units are present.
- Units do not contain system Enhancements.
 - Personal air purifiers are supplied for individual rooms. They are of unknown make or model.
 - $\circ \quad \text{Location: Nurse's office} \\$
- It is not known whether or not the building was commissioned during the original construction.


Air Handling Unit Designations & Service Zones: 1st Floor



Air Handling Unit Designations & Service Zones: 2nd Floor



Air Handling Unit Designations & Service Zones: 3rd Floor



Assessment

Ventilation System

The following information was gathered by IEA on Thursday, April 6, 2023 with support from the district building representative during the on-site interview. The type of heating, ventilating and air-conditioning (HVAC) system and its assessment is included for each unit below:

Location of Unit: Bike		HVU 2	
	Bike Shop 1114 above ceiling		
Areas Served: See a	e attached map		
System Enhancements: None	ne		
Supply System	Outdoor Air	Cleanliness and Observations	
TypeOuto• Supply System - Constant VolumeOuto• Heating - Steam • Cooling - NoneIocat unkr• Energy Recovery Unit (ERU) - NoneIt is not sour	ccessible tdoor air intake is ated in an known location. 5 not known if there nearby pollution irces. tdoor air intake is good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known.	

Unit Designation:	HVU 3	
Location of Unit:	Art room 1106	
Areas Served:	See attached map	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed	Outdoor air intake is inaccessible Outdoor air intake is located in an unknown location. It is not known if there are nearby pollution sources. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Mixed air main filters are installed

Unit D	esignation:	HVU 4	
Locatio	on of Unit:	Art room 1106 above ceiling	
Areas S	Served:	See attached map	
System	Enhancements:	None	
Su	pply System	Outdoor Air	Cleanliness and Observations
Type • • • •	Constant Volume Heating - Hot Water	Outdoor air intake is inaccessible Outdoor air intake is located on the unit. It is not known if there are nearby pollution sources. Condition of the outdoor air intake is not known.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is inaccessible, and its condition is not known.

Unit Designation:	HVU 8	
Location of Unit:	Gym Storage	
Areas Served:	See attached map.	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
 Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Return	Outdoor air intake is inaccessible Outdoor air intake is located in an unknown location. It is not known if there are nearby pollution sources. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air pre-filters are not present. Return air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Return air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is not present. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is not present. Return damper is inaccessible, and its condition is not known. The general condition of the unit is good.

Unit Designation:	HVU 9	
Location of Unit:	Gym Storage	
Areas Served:	See attached map	
System Enhancements:		
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Return		Outdoor air filters are not present. Return air pre-filters are not present. Return air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Return air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is not present. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is not present. Return damper is inaccessible, and its condition is good.

Unit Designation:	HVU 19	
Location of Unit:	Mechanical room 3208 A	
Areas Served:	See attached map	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
 Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit 	Outdoor air intake is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Mixed air main filters are installed correctly.
Pre-filter: None	were found. Outdoor air intake is in good condition.	Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in good condition. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Des	signation:	AHU 9	
Location	n of Unit:	Mechanical Room 3208A	
Areas Se	erved:	See attached map.	
System	Enhancements:	None	
Sup	ply System	Outdoor Air	Cleanliness and Observations
• • Filter Ty •	Supply System - Unknown Heating - Steam Cooling - None Energy Recovery Unit (ERU) - None pe - Mixed Pre-filter: None Main filter:	Outdoor air intake is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 4 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in poor condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good.

Unit Designation:	AHU 10	
Location of Unit:	Mechanical Room 2604	
Areas Served:	See attached map.	
	None	
Enhancements:		
Supply System	Outdoor Air	Cleanliness and Observations
 Supply System Constant Volume Heating - Steam Cooling - None Energy Recovery Unit (ERU) - None 	Outdoor air intake is inaccessible Outdoor air intake is located on the roof. It is not known if there are nearby pollution sources. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 4 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Designatio	n:	AHU 11 (RTU_11)	
Location of Unit	t:	Roof via stage access	
Areas Served:		Roof top on the stag See attached map	e
System Enhance	ements:	None	
Supply Syst	em	Outdoor Air	Cleanliness and Observations
Constar Volume • Heating Water	- Hot - None ry Unit Wheel xed er: None ter:	accessible Outdoor air intake is located on the roof. It is not known if there are nearby pollution sources. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheels are clean. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is visible. Interior ducting insulation is in good condition. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is not known. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit De	esignation:	AHU 12 (RTU_12)		
Location of Unit:		Roof via stage access		
Areas Served:		Roof top on the st	age	
		See attached map		
System	Enhancements:	None		
Suj	pply System	Outdoor Air	Cleanliness and Observations	
<u>Type</u> •	Supply System -	Outdoor air intake is	Outdoor air filters are not present.	
		accessible	Return air filters are not present.	
•	Water Cooling - None Energy	Outdoor air intake is located on the roof. No nearby	Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 4 out of 5) and fit well. Mixed air main filters are installed correctly.	
	(ERU) - None		Drain pan plugged status is not known. Drain pan condition is not known.	
	ype - Mixed			
•	Pre-filter: None Main filter:		Heating coils are inaccessible.	
•		intake is in good condition.	Heat wheels are not present.	
			Exterior ducting is visible. Exterior ducting insulation is not present.	
			Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness.	
			Air handling room is free of trash/chemicals.	
			Outside damper is inaccessible, and its condition is not known.	
			Return damper is inaccessible, and its condition is not known.	
			The general condition of the unit is good.	

Unit Designation:	AHU 13		
	Unlabeled Mechanical Room on mezzanine between floors 1 and 2 (Theater Area)		
Areas Served:	OWL Gym		
System Enhancements:	None		
Supply System	Outdoor Air Cleanliness and Observations		
 Supply System - Constant Volume Heating - Steam Cooling - Dx Energy Recovery Unit (ERU) - Fixed 	inaccessible Outdoor air intake is	Outdoor air pre-filters are not present. Outdoor air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Outdoor air main filters are installed correctly. Return air pre-filters are not present. Return air main filters are clean and not in need of replacement (scoring 2 out of 5) and fit well. Return air main filters are installed correctly. Drain pans are not plugged. Drain pan condition is good.	
	Outdoor air intake is in good condition.	 Heating coils are clean and cooling coils are clean. Heat wheels are inaccessible. Exterior ducting is visible. Exterior ducting insulation is in good condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good. 	

Unit Designation:	ERV 2			
Location of Unit:	2114 A			
Areas Served:	See attached map			
System Enhancements:	None			
Supply System	Outdoor Air	Cleanliness and Observations		
Supply System • Supply System - Constant Volume • Heating - Hot Water • Cooling - None • Energy Recovery Unit (ERU) - Fixed Plate Filter Type - Outdoor • • Pre-filter: Unknown, N/A • Main filter: Unknown, N/A • Pre-filter: Unknown, N/A • Pre-filter: Unknown, N/A • Main filter: Unknown, N/A • Main filter: Unknown, N/A	Outdoor air intake is inaccessible Outdoor air intake is located in an unknown	Cleaniness and ObservationsOutdoor air filters are of unknown cleanliness and fit well. Outdoor air filters are installed correctly.Return air filters are of unknown cleanliness and fit well. Return air filters are installed correctly.Drain pans are not applicable or not present. Drain pan condition is not known.Heating coils are inaccessible.Heat wheel cleanliness is not known.Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition.Interior ducting is visible. Interior ducting insulation is in good condition. Interior ducting is clean.Air handling room is free of trash/chemicals.Outside damper is unknown, and its condition is good.Return damper is unknown, and its condition is good.		

Unit D	esignation:	ERV 3			
Location of Unit:		Hallway above ceiling near 2114			
Areas Served:		See attached map			
System	n Enhancements:	None			
	Supply System	Outdoor Air	Cleanliness and Observations		
Туре		Outdoor air intake is	Outdoor air filters are of unknown cleanliness and		
•	Supply System - Constant Volume	inaccessible	fit well. Outdoor air filters are installed correctly.		
•	Heating - Hot Water	Outdoor air intake is	Return air filters are of unknown cleanliness and		
•	Cooling - None Energy Recovery	located in an unknown location.	fit well. Return air filters are installed correctly.		
	Unit (ERU) - Fixed		Mixed air filters are of unknown cleanliness and fit		
	Plate	It is not known if there are nearby pollution	well. Mixed air filters are installed correctly.		
Filter T	<u> ype - Outdoor</u>	sources.	Drain pans are not applicable or not present. Drain		
•	Pre-filter: Unknown,		pan condition is not known.		
	N/A	Outdoor air intake is in			
•	Main filter:	good condition.	Heating coils are inaccessible.		
	Unknown, N/A				
			Heat wheel cleanliness is not known.		
	<u>ype - Return</u>				
•	Pre-filter: Unknown,		Exterior ducting is not visible. Exterior ducting		
	N/A		insulation is in an unknown condition.		
•	Main filter:				
	Unknown, N/A		Interior ducting is not visible. Interior ducting		
F :14 a # 7	Supe Missed		insulation is in good condition. Interior ducting is of unknown cleanliness.		
	Type - Mixed Pre-filter: Unknown,		or unknown cleaniness.		
•	N/A		Air handling room is free of trash/chemicals.		
	Main filter:				
•	Unknown, N/A		Outside damper is inaccessible, and its condition is		
			not known.		
			Return damper is inaccessible, and its condition is good.		
			The general condition of the unit is good.		

Unit De	esignation:	ERV 1 (NEW)		
Location of Unit:		2114A		
Areas Served:		See attached map		
System Enhancements:		None		
Su	pply System	Outdoor Air	Cleanliness and Observations	
<u>Туре</u> • •	Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - Fixed Plate ype - Return Pre-filter:	Outdoor air intake is inaccessible	Outdoor air filters are not present. Return air pre-filters are inaccessible and fit well. Return air pre-filters are installed correctly. Return air main filters are of unknown cleanliness and fit well. Return air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are inaccessible. Heat wheel cleanliness is not known. Exterior ducting is not visible. Exterior ducting insulation is	
			in an unknown condition. Interior ducting is visible. Interior ducting insulation is in good condition. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is unknown, and its condition is good. Return damper is unknown, and its condition is good. The general condition of the unit is good.	

Location of Unit: Room 2116 above Ceiling Areas Served: See attached map. System None Enhancements: Control of the state of		ion: 2116 CEILING			
System None Enhancements:	cation of Unit:	nit: Room 2116 above Ce	Room 2116 above Ceiling		
Enhancements:	reas Served:	See attached map.	See attached map.		
	Supply System		Cleanliness and Observations		
Volume • Heating - None • Cooling - None • Energy Recovery Unit (ERU) - NoneOutdoor air intake is in good condition.are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Return air main filters are installed correctly.Filter Type - Return • Pre-filter: • Main filter: • Pleated, MERVIt is not known if there are nearby pollution sources.Drain pans are not applicable or not present. Drain pan condition is not known.• Pre-filter: • Pre-filter: • Pleated, MERVOutdoor air intake is in good condition.Heat wheels are not present.	 Supply System Constant Volume Heating - None Cooling - None Energy Recovery Unit (ERU) - None Iter Type - Return Pre-filter: None Main filter: Pleated, MERV 	y System inaccessible itant be Outdoor air intake is located in an located in an located in an located in an unknown location. y ery Unit It is not known if - None there are nearby pollution sources. <u>eturn</u> ter: Outdoor air intake is in good condition.	Return air pre-filters are not present. Return air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Return air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is not present. Return damper is open, and its condition is good.		

Unit D	esignation:	UNIVENT ROOM 210	8 #1	
Location of Unit:		Room 2108		
Areas Served:		Room 2108		
System Enhancements:		None		
Su	pply System	Outdoor Air	Cleanliness and Observations	
Type • • • •	Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None	accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good.	

Unit Des	signation:	UNIVENT ROOM 210	8 #2	
Location of Unit:		Room 2108		
Areas Served:		Room 2108		
System Enhancements:		None		
Sup	oply System	Outdoor Air	Cleanliness and Observations	
•	Heating - Hot Water Cooling - None Energy Recovery Unit		Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known.	
•		Outdoor air intake is in good condition.	 Heating coils are clean. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good. 	

Unit Designation:	UNIVENT ROOM 211	0	
Location of Unit:	Room 2110		
Areas Served:	Room 2110		
System Enhancements:	None		
Supply System	Outdoor Air	Cleanliness and Observations	
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None	accessible Outdoor air intake is	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are clean and not in need of replacement (scoring 1 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known.	
Filter Type - Mixed • Pre-filter: None • Main filter: Pleated, MERV 11	in good condition.	 Heating coils are clean. Heat wheels are not present. Exterior ducting is visible. Exterior ducting insulation is not present. Interior ducting is visible. Interior ducting insulation is not present. Interior ducting is clean. Air handling room is free of trash/chemicals. Outside damper is inaccessible, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good. 	


Recommendations

The accessible ductwork for unit AHU 9 was visibly dirty, damaged, or had evidence of moisture at the time of the site inspection.

Recommendation: IEA recommends further inspection into the overall condition of the interior ductwork and level of dirt/debris quantified. If deemed a concern, it is recommended that the interior ducting be cleaned by a professional contractor to improve the impact on the IAQ for the supply spaces.

Appendix A

Photo Documentation






HVU 8 Return Main Filter Cleanliness

HVU 9 Return Pre-Filter Cleanliness



HVU 9 Return Main Filter Cleanliness



HVU 9 Mixed Main Filter Cleanliness



HVU 19 Mixed Main Filter Cleanliness




AHU 10 Mixed Main Filter Cleanliness



AHU 9 Mixed Main Filter Cleanliness



AHU 11 (RTU_11) Mixed Main Filter Cleanliness



AHU 12 (RTU_12) Mixed Main Filter Cleanliness



2116 CEILING Return Pre-Filter Cleanliness



AHU 13 Outdoor Main Filter Cleanliness



2116 CEILING Return Main Filter Cleanliness