2023 - 2024 Ventilation Assessment



IEA, INC.

Contact Us:

 BROOKLYN PARK OFFICE

 9201 W. BROADWAY, #600

 BROOKLYN PARK, MN 55445

 763-315-7900

MANKATO OFFICE 610 N. RIVERFRONT DRIVE MANKATO, MN 56001 507-345-8818

ROCHESTER OFFICE 210 WOOD LAKE DRIVE SE ROCHESTER, MN 55904 507-281-6664

BRAINERD OFFICE 601 NW 5TH STREET SUITE #4 BRAINERD, MN 56401 218-454-0703

MARSHALL OFFICE 1420 EAST COLLEGE DRIVE MARSHALL, MN 56258 507-476-3599

VIRGINIA OFFICE 5525 EMERALD AVENUE MOUNTAIN IRON, MN 55768 218-410-9521

www.ieasafety.com

info@ieasafety.com

800-233-9513

Saint Paul Public Schools Nokomis Montessori North

Assessment Date: Thursday, April 6, 2023

Project Description

IEA conducted a ventilation inspection in Nokomis Montessori North by IEA representative, Sashya Wandmaker, with the intent of gathering visual observations and overall ventilation information which will assist the District in making informed and proactive decisions to improve and maintain acceptable air quality in the building. This inspection is based upon the Environmental Protection Agency's (EPA's) Tools for Schools IAQ guidelines and the recommended Minnesota Department of Education (MDE) portion of a school district's IAQ management plan. Ventilation verification is also recommended by American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE).

Some observations gathered during the inspection may identify issues which may require additional testing, evaluation, further investigation, or maintenance on the ventilation systems.

The findings, conclusions and recommendations presented herein are believed to be accurate and representative of the building on the date and time of the inspection.

GENERAL COMMENTS

The analysis and opinions expressed in this report are based upon data obtained from Saint Paul Public Schools at the indicated locations. This report does not reflect variations in conditions that may occur across the site, property, or facility. Actual conditions may vary and may not become evident without further assessment.

The report is prepared for the exclusive use of our client for specific application to the project discussed and has been prepared in accordance with generally accepted indoor air quality practices. Other than as provided in the preceding sentence, no warranties are extended or made.

Building Information

General information regarding the building was collected by IEA during an interview with building maintenance staff. The information gathered during this process is a vital component, as it is helpful in determining how these items may play a role in possible IAQ related issues.

Below is a summary of the information gathered during the interview:

- Automation controls are managed internally. •
- A Building Automation System is present. The automation control software program is Tridium and controls can not be accessed remotely.
- Schedules: •

Ventilation operation:

Day:	Occupied?	Start Time:	End Time:
Monday- Friday	Yes	6:00 AM	10:00 PM
Saturday	No		
Sunday	No		
Holiday	No		
Notes: Not sure of times			

Typical occupancy:

Day:	Occupied?	Start Time:	End Time:
Monday- Friday	Yes	9:00 AM	4:00 PM
Saturday	No		
Sunday	No		
Holiday	No		

Notes: Not sure of times

- CO2 sensors are not associated with the ventilation system.
- VAVs are present. It is not known whether or not they are fan powered.
- It is not known whether or not the building has variable frequency drives (VFD).
- The heating system is a hot water boiler.
- A cooling system is not present.
- Filters used are: •

Filter Type MERV Rating


Pleated MERV 11

- Filters are changed Twice a year.
- Energy Recovery Units are not present.
- Units do not contain system Enhancements.
 - Personal air purifiers are supplied for individual rooms. They are of unknown make or model.
 - Location: All classrooms
- It is not known whether or not the building was commissioned during the original construction.

Air Handling Unit Designations & Service Zones: 1st Floor



Air Handling Unit Designations & Service Zones: 2nd Floor



Assessment

Ventilation System

The following information was gathered by IEA on Thursday, April 6, 2023 with support from the district building representative during the on-site interview. The type of heating, ventilating and air-conditioning (HVAC) system and its assessment is included for each unit below:

		ed for each unit below:	
Unit Designation:	AHU_01 (100% OA)		
Location of Unit:	Mechanical room 2201		
Areas Served:	Room 1102 Kitchen	1	
	See attached map		
System	None		
Enhancements:			
Supply System	Outdoor Air	Cleanliness and Observations	
Туре	Outdoor air intake	Outdoor air pre-filters are not present. Outdoor air main	
Supply System	is accessible	filters are somewhat dirty and on the border of needing	
- Constant		replacement (scoring 3 out of 5) and fit well. Outdoor air	
Volume	Outdoor air intake	main filters are installed correctly.	
Heating - Hot	is located on an		
Water	exterior wall.	Return air filters are not present.	
Cooling - None			
	-	Drain pan plugged status is not known. Drain pan condition is	
		not known.	
(ERU) - None	were found.		
		Heating coils are inaccessible.	
Filter Type - Outdoor	Outdoor air intake		
Pre-filter:	is in good condition.	Heat wheels are not present.	
NoneMain filter:		Exterior ducting is visible. Exterior ducting inculation is not	
• Main Inter. Pleated, MERV		Exterior ducting is visible. Exterior ducting insulation is not present.	
11			
11		Interior ducting is visible. Interior ducting insulation is not	
		present. Interior ducting is clean.	
		Air handling room is free of trash/chemicals.	
		Outside damper is open, and its condition is good.	
		Return damper is not present.	
		The general condition of the unit is good.	

Unit Designation:	RTU_01	
Location of Unit:	Mechanical room roof access	
Areas Served:	See attached map	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None Filter Type - Mixed Pre-filter: None Main filter:	Outdoor air intake is accessible Outdoor air intake is located on the roof. No nearby pollution sources were found. Outdoor air intake is in good condition.	Cleanliness and Observations Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 3 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good.

Unit Designation: RTU_03			
Locatio	on of Unit:	Mechanical room Roof over Gym	
Areas S	erved:	Room 1111 Gym N	North
		See attached map	
System	Enhancements:	None	
Su	pply System	Outdoor Air	Cleanliness and Observations
Type • • • • •	Water Cooling - None Energy Recovery Unit (ERU) - None ype - Mixed Pre-filter: None Main filter:	accessible Outdoor air intake is located on the roof. No nearby pollution sources were found.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing replacement (scoring 4 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good.
			Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Designation:	UV-1406	
Location of Unit:	1406	
Areas Served:	1406	
System Enhancements:	ts: None	
Supply System	Outdoor Air	Cleanliness and Observations
 Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None 	accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is in good condition.	Outdoor air pre-filters are not present. Outdoor air main filters are not present. Return air filters are not present. Mixed air main filters are dirty and in need of replacement (scoring 5 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good.

Unit Designation:	UV-18	
Location of Unit:	1307	
Areas Served:	1307	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Supply System • Supply System - Constant Volume • Heating - Hot Water • Cooling - None • Energy Recovery Unit (ERU) - None Filter Type - Mixed • Pre-filter: None • Main filter: Pleated, MERV 11	Outdoor air intake is accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found. Outdoor air intake is	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are dirty and in need of replacement (scoring 5 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not applicable or not present. Drain pan condition is not known. Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Desi	ignation:	UV-15	
Location	of Unit:	1301, south wall	
Areas Se	rved:	1301	
System E	nhancements:	None	
Sup	oly System	Outdoor Air	Cleanliness and Observations
C V • F V • C • E R (1 Filter Typ • P • N • P	upply System - Constant /olume leating - Hot Vater Cooling - None Energy Recovery Unit ERU) - None	accessible Outdoor air intake is located on an exterior wall. No nearby pollution sources were found.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are dirty and in need of replacement (scoring 5 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not plugged. Drain pan condition is good. Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good.

Unit Designation:	UV-3	
Location of Unit:	1207	
Areas Served:	1207	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
Type Supply System - Constant Volume Heating - Hot Water Cooling - None Energy Recovery Unit (ERU) - None	Outdoor air intake is located on an exterior wall. No nearby pollution sources were found.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are dirty and in need of replacement (scoring 5 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not plugged. Drain pan condition is good.
Filter Type - Mixed Pre-filter: None Main filter: Pleated, MERV 11	Outdoor air intake is in good condition.	 Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Designation:	UV-1	
Location of Unit:	1203	
Areas Served:	1203	
System Enhancements:	None	
Supply System	Outdoor Air	Cleanliness and Observations
	Outdoor air intake is located on an exterior wall. No nearby pollution sources were found.	Outdoor air filters are not present. Return air filters are not present. Mixed air pre-filters are not present. Mixed air main filters are dirty and in need of replacement (scoring 5 out of 5) and fit well. Mixed air main filters are installed correctly. Drain pans are not plugged. Drain pan condition is good.
Filter Type - Mixed Pre-filter: None Main filter: Pleated, MERV 11	Outdoor air intake is in good condition.	 Heating coils are clean. Heat wheels are not present. Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition. Interior ducting is not visible. Interior ducting insulation is in an unknown condition. Interior ducting is of unknown cleanliness. Air handling room is free of trash/chemicals. Outside damper is open, and its condition is good. Return damper is open, and its condition is good. The general condition of the unit is good.

Unit Designation:	UV-6	
Location of Unit:	2203	
Areas Served:	2203	
System	None	
Enhancements:		
Supply System	Outdoor Air	Cleanliness and Observations
Туре		Outdoor air filters are not present.
	inaccessible	
- Constant		Return air filters are not present.
	Outdoor air intake is located on an	Mixed air pro filters are not present. Mixed air main filters
Ũ		Mixed air pre-filters are not present. Mixed air main filters are somewhat dirty and on the border of needing
Cooling - None		replacement (scoring 4 out of 5) and fit well. Mixed air main
_		filters are installed correctly.
	sources were found.	
(ERU) - None		Drain pans are not plugged. Drain pan condition is good.
	Outdoor air intake is	
	in good condition.	Heating coils are clean.
Pre-filter:		
None		Heat wheels are not present.
Main filter:		Exterior ducting is not visible. Exterior ducting insulation is
Pleated, MERV 11		Exterior ducting is not visible. Exterior ducting insulation is in an unknown condition.
		Interior ducting is not visible. Interior ducting insulation is in
		an unknown condition. Interior ducting is of unknown
		cleanliness.
		Air handling room is free of trash/chemicals.
		Outside damper is open, and its condition is good.
		Return damper is open, and its condition is good.
		The general condition of the unit is good.

Unit Designation:	UV-10	
Location of Unit:	2206	
Areas Served:	2206	
System	None	
Enhancements:		
Supply System	Outdoor Air	Cleanliness and Observations
Туре		Outdoor air filters are not present.
	inaccessible	
- Constant Volume	Outdoor air intake is	Return air filters are not present.
		Mixed air pre-filters are not present. Mixed air main filters
Water	exterior wall.	are somewhat dirty and on the border of needing
Cooling - None		replacement (scoring 4 out of 5) and fit well. Mixed air main
Energy	No nearby pollution	filters are installed correctly.
	sources were found.	,
(ERU) - None		Drain pans are not plugged. Drain pan condition is good.
	Outdoor air intake is	
Filter Type - Mixed	in good condition.	Heating coils are clean.
Pre-filter:		
NoneMain filter:		Heat wheels are not present.
Pleated, MERV		Exterior ducting is not visible. Exterior ducting insulation is
11		in an unknown condition.
		Interior ducting is not visible. Interior ducting insulation is in
		an unknown condition. Interior ducting is of unknown
		cleanliness.
		Air handling room is free of trash/chemicals.
		Outside damper is open, and its condition is good.
		Return damper is open, and its condition is good.
		The general condition of the unit is good.

Unit Designation:	UV-8	
Location of Unit:	2207	
Areas Served:	2207	
System	None	
Enhancements:		
Supply System	Outdoor Air	Cleanliness and Observations
<u>Type</u>		Outdoor air filters are not present.
Supply System Constant	inaccessible	Daturn air filtars are not present
Volume	Outdoor air intake is	Return air filters are not present.
		Mixed air pre-filters are not present. Mixed air main filters
_		are somewhat dirty and on the border of needing
Cooling - None		replacement (scoring 4 out of 5) and fit well. Mixed air main
		filters are installed correctly.
	sources were found.	
(ERU) - None		Drain pans are not plugged. Drain pan condition is good.
	Outdoor air intake is	
 Filter Type - Mixed Pre-filter: 	in good condition.	Heating coils are clean.
• Pre-Inter. None		Heat wheels are not present.
Main filter:		
Pleated, MERV		Exterior ducting is not visible. Exterior ducting insulation is
11		in an unknown condition.
		Interior ducting is not visible. Interior ducting insulation is in
		an unknown condition. Interior ducting is of unknown
		cleanliness.
		Air handling room is free of trash/chemicals.
		Outside damper is open, and its condition is good.
		Return damper is open, and its condition is good.
		The general condition of the unit is good.


Recommendations

Dirty or poorly fitting filters were observed in units UV-1, UV-1406, UV-15, UV-18 and UV-3 during the ventilation inspection.

Recommendation: The operations and maintenance program for filter changes should be reviewed and revised to ensure proper filter changes to optimize filtration capacity.

Appendix A


Photo Documentation



AHU_01 (100% OA) Outdoor Main Filter Cleanliness



RTU_02 Mixed Main Filter Cleanliness



RTU_01 Mixed Main Filter Cleanliness



RTU_03 Mixed Main Filter Cleanliness



UV-1406 Mixed Main Filter Cleanliness



UV-15 Mixed Main Filter Cleanliness



UV-18 Mixed Main Filter Cleanliness



UV-3 Mixed Main Filter Cleanliness



UV-1 Mixed Main Filter Cleanliness



UV-10 Mixed Main Filter Cleanliness



UV-6 Mixed Main Filter Cleanliness



UV-8 Mixed Main Filter Cleanliness