

PLAY

Location: SALISBURY E.S. PLAY GROUND #2 out BACK
Inspection Date: 7-25-23 Time: _____
Inspected by: MIKE / SHAKE Age Appropriate: K-6

Priority Rating Scale (1-4)

1. Permanent disability, loss of life or body part – correct immediately.
2. Serious injury resulting in temporary disability – correct as soon as possible.
3. Minor (Non-Disabling) Injury – correct when time permits.
4. Potential for injury Minimal – check to see if worsens.

SAFETY SURFACINGS

Compliant Hazard

- | | | |
|--|-------------------------------------|-------|
| 1. Transition from the path to surfacing is less than .5". | ☒ | _____ |
| 2. Surfacing material is adequate and proper depth. | ☒ | _____ |
| 3. Loose fill is at correct height at Transfer Platform. | ☒ | _____ |
| 4. Loose fill is at correct depth at Slide exits & Swings. | ☒ | _____ |
| 5. Surfacing material is free from weeds and trash. | ☒ | _____ |
| 6. No roots, rocks or objects are a tripping hazard. | ☒ | _____ |
| 7. Unitary surface retains adequate absorbing abilities. | ☒ | _____ |
| 8. _____ | _____ | _____ |

EQUIPMENT

- | | | |
|--|-------------------------------------|-------|
| 9. Warning/information sign and/or labels are in place. | ☒ | _____ |
| 10. Equipment and site furnishings are free of debris. | ☒ | _____ |
| 11. No footings are exposed, cracked or loose. | ☒ | _____ |
| 12. Clamps and rivets are in place and secure. | ☒ | _____ |
| 13. All barriers and guardrails are in place and secure. | ☒ | _____ |
| 14. Decks are level, secure and coated with no metal. | ☒ | _____ |
| 15. No rust, corrosion or peeling paint. | ☒ | _____ |
| 16. Plastic is smooth, no cracks or cuts. | ☒ | _____ |
| 17. Tree limbs are greater than 84" from equipment. | ☒ | _____ |
| 18. Border around playground is adequate and secure. | ☒ | _____ |
| 19. All hardware is in place and secure. | ☒ | _____ |
| 20. Upright and pipe caps are in place and secure. | ☒ | _____ |
| 21. No excessive wear, broken or missing parts. | ☒ | _____ |
| 22. _____ | _____ | _____ |

Required Repairs / Comments:

NOT AT THIS TIME 7-25-23

B. Sassan

Builders Specialty Service, Inc.
PO Box 433, 37 S. Wilson Avenue
Elizabethtown, PA 17022
Ph. 717-367-0322 Fax 717-367-8210

Location: SALISBURY E.S. PLAY GROUND #1 - FRONT OF BUILDING
Inspection Date: 7-25-23 Time: _____
Inspected by: MIKE/SHAKE Age Appropriate: K-6

Priority Rating Scale (1-4)

1. Permanent disability, loss of life or body part – correct immediately.
2. Serious injury resulting in temporary disability – correct as soon as possible.
3. Minor (Non-Disabling) Injury – correct when time permits.
4. Potential for injury Minimal – check to see if worsens.

SAFETY SURFACINGS

Compliant Hazard

- | | | |
|--|-------------------------------------|------------------------|
| 1. Transition from the path to surfacing is less than .5". | ☒ | <u>RUBBER SURFACE.</u> |
| 2. Surfacing material is adequate and proper depth. | ☒ | _____ |
| 3. Loose fill is at correct height at Transfer Platform. | ☒ | _____ |
| 4. Loose fill is at correct depth at Slide exits & Swings. | ☒ | _____ |
| 5. Surfacing material is free from weeds and trash. | _____ | _____ |
| 6. No roots, rocks or objects are a tripping hazard. | _____ | _____ |
| 7. Unitary surface retains adequate absorbing abilities. | _____ | _____ |
| 8. _____ | _____ | _____ |

EQUIPMENT

- | | | |
|--|-------------------------------------|------------------------|
| 9. Warning/information sign and/or labels are in place. | ☒ | _____ |
| 10. Equipment and site furnishings are free of debris. | ☒ | _____ |
| 11. No footings are exposed, cracked or loose. | ☒ | _____ |
| 12. Clamps and rivets are in place and secure. | ☒ | _____ |
| 13. All barriers and guardrails are in place and secure. | ☒ | _____ |
| 14. Decks are level, secure and coated with no metal. | ☒ | _____ |
| 15. No rust, corrosion or peeling paint. | ☒ | <u>RUST ON STEPS ✓</u> |
| 16. Plastic is smooth, no cracks or cuts. | ☒ | _____ |
| 17. Tree limbs are greater than 84" from equipment. | ☒ | _____ |
| 18. Border around playground is adequate and secure. | ☒ | _____ |
| 19. All hardware is in place and secure. | ☒ | _____ |
| 20. Upright and pipe caps are in place and secure. | ☒ | _____ |
| 21. No excessive wear, broken or missing parts. | ☒ | _____ |
| 22. _____ | _____ | _____ |

Required Repairs / Comments:

RUST ON STEPS COATING PEELING OFF SURFACE
CHECK TO MAKE SURE IT DON'T WORSEN.
FACING FRONT PARKING LOT

b. Sano

Builders Specialty Service, Inc.
PO Box 433, 37 S. Wilson Avenue
Elizabethtown, PA 17022
Ph. 717-367-0322 Fax 717-367-8210

Location: SALISBURY E.S. PLAYGROUND #3 FRONT LEFT SIDE
Inspection Date: 7-25-23 Time: _____ OF SCHOOL.
Inspected by: MIKE/SHAKE Age Appropriate: K-6

Priority Rating Scale (1-4)

1. Permanent disability, loss of life or body part – correct immediately.
2. Serious injury resulting in temporary disability – correct as soon as possible.
3. Minor (Non-Disabling) Injury – correct when time permits.
4. Potential for injury Minimal – check to see if worsens.

SAFETY SURFACINGS

- | | Compliant | Hazard |
|--|-------------------------------------|--------|
| 1. Transition from the path to surfacing is less than .5". | ☒ | _____ |
| 2. Surfacing material is adequate and proper depth. | ☒ | _____ |
| 3. Loose fill is at correct height at Transfer Platform. | ☒ | _____ |
| 4. Loose fill is at correct depth at Slide exits & Swings. | ☒ | _____ |
| 5. Surfacing material is free from weeds and trash. | ☒ | _____ |
| 6. No roots, rocks or objects are a tripping hazard. | ☒ | _____ |
| 7. Unitary surface retains adequate absorbing abilities. | ☒ | _____ |
| 8. _____ | _____ | _____ |

EQUIPMENT

- | | | |
|--|-------------------------------------|--------------------------|
| 9. Warning/information sign and/or labels are in place. | ☒ | _____ |
| 10. Equipment and site furnishings are free of debris. | ☒ | _____ |
| 11. No footings are exposed, cracked or loose. | ☒ | _____ |
| 12. Clamps and rivets are in place and secure. | ☒ | _____ |
| 13. All barriers and guardrails are in place and secure. | ☒ | _____ |
| 14. Decks are level, secure and coated with no metal. | ☒ | _____ |
| 15. No rust, corrosion or peeling paint. | ☒ | _____ |
| 16. Plastic is smooth, no cracks or cuts. | ☒ | <u>#2 Climbing Chair</u> |
| 17. Tree limbs are greater than 84" from equipment. | ☒ | _____ |
| 18. Border around playground is adequate and secure. | ☒ | _____ |
| 19. All hardware is in place and secure. | ☒ | _____ |
| 20. Upright and pipe caps are in place and secure. | ☒ | _____ |
| 21. No excessive wear, broken or missing parts. | ☒ | _____ |
| 22. <u>ON Climbing Chain.</u> | ☒ | <u>#2 Broken Chain</u> |

Required Repairs / Comments:

BROKEN Chain on Climbing Ladder. Need
Repaired AS SOON AS POSSIBLE.
OR REPLACE.

D. Sasser