







- Fine Arts Classroom and Performance Space Improvements
- Collaboration Rooms
- Exterior Upgrades
- Interior Upgrades
- Mechanical, Electrical, and Plumbing Systems Upgrades
- Landscaping Improvements
- Kitchen Renovation
- New Marquee

#### Safety and Security

- Access Control
- Cameras
- Bollards
- Fire Sprinkler System Upgrades



- Secure and Climate Controlled Server Space
- Cabling
- Wireless Upgrades
- Phone System Upgrades

cfbbond.com

BLALACK MIDDLE SCHOOL



- Fine Arts Classroom and Performance Space
   Improvements
  - O Band, Orchestra, Choir, Theater, and Percussion Hall Renovations
- Collaboration Rooms
  - Practice Rooms in Fine Arts
- Exterior Upgrades
  - Roof Replacement and Repair
- Interior Upgrades
  - Makerspace /Engineering Room
     Renovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing Systems
   Upgrades
  - O New LED Site Lighting and Controls
  - New Rooftop Units and Controls
  - Water Bottle Fillers
- Landscape Improvements
  - Exterior Concrete Replacement
  - Exterior Benches
- Kitchen Renovation
  - New Kitchen Equipment
- O New Marquee Coming Soon

## PROMISES MADE PROMISES



- Access Control
  - Intercom
  - Card Readers
  - Security Alarm
- Cameras
- Bollards
- Fire Sprinkler System Upgrades



#### **Technology**


- Secure Climate Controlled ServerSpace
- **Cabling**
- Wireless Upgrades
- Phone System Upgrades






## Improvements Fine Arts Classroom and Performance Space

- Fine Arts Classroom and Performance Space Improvements
  - O Band, Orchestra, Choir, Theater, and Percussion Hall Renovations
- Collaboration Rooms
  - O Practice Rooms in Fine Arts
- Exterior Upgrades
  - Roof Replacement and Repair
- Interior Upgrades
  - Makerspace /Engineering RoomRenovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing SystemsUpgrades
  - O New LED Site Lighting and Controls
  - New Rooftop Units and Controls
  - Water Bottle Fillers
- Landscape Improvements
  - Exterior Concrete Replacement
  - Exterior Benches
- Kitchen Renovation
  - New Kitchen Equipment
- New Marquee Coming Soon











- **Improvements** 
  - Band, Orchestra, Choir, Theater, and **Percussion Hall Renovations**
- **Collaboration Rooms** 
  - **Practice Rooms in Fine Arts**
- **Exterior Upgrades** 
  - **Roof Replacement and Repair**
- **Interior Upgrades** 
  - **Makerspace / Engineering Room** Renovation
  - **Structural Joist Reinforcement**
- Mechanical, Electrical, and Plumbing Systems **Upgrades** 
  - **New LED Site Lighting and Controls**
  - **New Rooftop Units and Controls**
  - **Water Bottle Fillers**
- **Landscape Improvements** 0
  - **Exterior Concrete Replacement**
  - **Exterior Benches**
- **Kitchen Renovation** 0
  - **New Kitchen Equipment**











- O Fine Arts Classroom and Performance Space Improvements
  - Band, Orchestra, Choir, Theater, and
     Percussion Hall Renovations
- Collaboration Rooms
  - Practice Rooms in Fine Arts
- Exterior Upgrades
  - Roof Replacement and Repair
- Interior Upgrades
  - Makerspace /Engineering RoomRenovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing Systems Upgrades
  - O New LED Site Lighting and Controls
  - O New Rooftop Units and Controls
  - Water Bottle Fillers
- Landscape Improvements
  - Exterior Concrete Replacement
  - Exterior Benches
- Kitchen Renovation
  - New Kitchen Equipment










- Fine Arts Classroom and Performance Space **Improvements** 
  - Band, Orchestra, Choir, Theater, and **Percussion Hall Renovations**
- **Collaboration Rooms** 
  - **Practice Rooms in Fine Arts**
- **Exterior Upgrades** 
  - **Roof Replacement and Repair**
- **Interior Upgrades** 0
  - **Makerspace / Engineering Room** Renovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing Systems **Upgrades** 
  - **New LED Site Lighting and Controls**
  - **New Rooftop Units and Controls**
  - **Water Bottle Fillers**
- **Landscape Improvements** 
  - **Exterior Concrete Replacement**
  - **Exterior Benches**
- **Kitchen Renovation** 
  - **New Kitchen Equipment**

# PROMISES MADE











- **Improvements** 
  - Band, Orchestra, Choir, Theater, and **Percussion Hall Renovations**
- **Collaboration Rooms** 
  - **Practice Rooms in Fine Arts**
- **Exterior Upgrades** 
  - **Roof Replacement and Repair**
- **Interior Upgrades** 
  - **Makerspace / Engineering Room** Renovation
  - **Structural Joist Reinforcement**
- Mechanical, Electrical, and Plumbing Systems **Upgrades** 
  - **New LED Site Lighting and Controls**
  - **New Rooftop Units and Controls** 0
  - **Water Bottle Fillers**
- **Landscape Improvements** 
  - **Exterior Concrete Replacement**
  - **Exterior Benches**
- **Kitchen Renovation** 
  - **New Kitchen Equipment**









- **Fine Arts Classroom and Performance Space Improvements** 
  - Band, Orchestra, Choir, Theater, and **Percussion Hall Renovations**
- **Collaboration Rooms** 
  - **Practice Rooms in Fine Arts**
- **Exterior Upgrades** 
  - **Roof Replacement and Repair**
- **Interior Upgrades** 
  - **Makerspace / Engineering Room** Renovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing Systems **Upgrades** 
  - **New LED Site Lighting and Controls**
  - **New Rooftop Units and Controls** 0
  - **Water Bottle Fillers**
- **Landscape Improvements** 0
  - **Exterior Concrete Replacement**
- Kitchen Renovation 0
  - **New Kitchen Equipment**
- New Marquee Coming Soon











- **Fine Arts Classroom and Performance Space Improvements** 
  - Band, Orchestra, Choir, Theater, and **Percussion Hall Renovations**
- **Collaboration Rooms** 
  - **Practice Rooms in Fine Arts**
- **Exterior Upgrades** 
  - **Roof Replacement and Repair**
- **Interior Upgrades** 
  - **Makerspace / Engineering Room** Renovation
  - Structural Joist Reinforcement
- Mechanical, Electrical, and Plumbing Systems **Upgrades** 
  - **New LED Site Lighting and Controls**
  - **New Rooftop Units and Controls**
  - **Water Bottle Fillers**
- **Landscape Improvements** 
  - **Exterior Concrete Replacement**
- **Kitchen Renovation** 
  - **New Kitchen Equipment**
- **New Marquee Coming Soon**

# ROMISES MADE





## Safety and Security

- Access Control
  - o Intercom 2023
  - Card Readers- 2023
  - Security Alarm
- Cameras
- Bollards
- Fire Sprinkler System Upgrades


















### Technology

- Secure Climate ControlledServer Space
- Cabling
- Wireless Upgrades
- Phone System Upgrades















#### CFAC RECOMMENDATIONS



PROMISES MADE PROMISES

#### ALL CFBISD SCHOOLS \$189.7m



Bring all CFBISD facilities to a minimum assessment score of 85\*

Mechanical, electrical and plumbing (MEP)
Collaboration
Roofs, Exteriors and Finishes etc.



` Building Element	Type/Material	<b>Prior Condition</b>	Current	Prior Description	2022 Reno Comments
On-Site Utilities & Drainage					
Site Drainage / Erosion Control		Good	Good	Positive slope away from building, no visible signs of erosion or ponding water.	
Site Lighting - Parking Lots		Good	Good	Toolard disposaling from ballang, no violate digite of disolate of portaing water.	
, , , , , , , , , , , , , , , , , , ,					
Exterior Concrete Pads & Pavement- Around building, mechanical yards		Good	Good		
Fire Hydrants / Utility Vaults / Misc.		Fair	Fair		Not in Scope
Grease Trap		Fair	Fair		Not in Scope
Site Parking & Drives	_				
Pavement - Roads / Drives / Parking Areas		Good	Good	Clean and clear of cracks, heaving, potholes. Joint Sealer is properly in place.	
Fire Lanes		Good	Good	Fire lane paint striping in good condition.Clean and clear of cracks, heaving, potholes. Joint Sealer is properly in place.	
Striping - Parking lot and fire lane		Poor	Good	Incomplete, missing or severely deteriorated/aged. No handicapped parking spaces provided.	Restiped Parking Lot
Curbs		Good	Good	Free of cracks, damage and almost new in appearance.	
Curbs				Free of cracks, damage and almost new in appearance.	
Site Lighting					
Site Lighting		Fair	Good	Very few fixtures have minor damage or are not working. Lighting is adequate for security.	Upgraded all Site Lighting to LED
	_				
Site Security					
Security Cameras	Megapixels	11	388		Upgraded camera resolution and doubled camera count
Chain Link Fencing / Gates		Fair	Fair	Little to no damage to material, poles & gates. Some signs of age.	Not in Scope
Misc. Stuctures					
Metarial		N/A	N/A		
Site Walls - Retaining / Screen		IN/A	IN/A		
		Fair	Fair	Moderate to Minor signs of damage to dumpster walls, may need a refresh of finish paint if	
Dumpster Service Area				applicable and additional bollards. Gates function as required.	
Material:		Fair	Good		
Bollards Ste	eel		0000	Minor to moderate signs of age and deterioration but still visible.	Added New Concrete Bollards
Site Signage - Directional / Handicapped		Good	Good		
Misc. Site work / Site Structures		N/A	N/A		
Circulation		·			
Sidewalks		Fair	Good	Sinking at curb by front entrance, front plaza has lots of cracking	Repoured sinking curb by front entrance
OldGWalk3				Onlining at only by north entiance, more plaza has lots of chacking	repoured similing out by front critication
Stairs		N/A	N/A		
		Good	Good	Clean and clear of cracks or heaving. Joint Sealer is properly in place. Slope is compliant.	
Ramps				Handrails (if present) are compliant & finish is in good condition.	
ADA Compliance / Accessibility					
Compliant Sidewalks/Curbs		Good	Good		
Compliant Ramps & Handrails		Good	Good		

Site

Scored Categories	18	18
Good	10	14
Fair Poor	7	4
	1	0
N/A	3	3

Previous Aggregate Score:	83
Reno Aggregate Score:	93



					OPDAILS
Building Element	Type/Material	Prior Condition	Current	Prior Description	2022 Reno Comments
Building Structure/Foundation	•				
Foundation	Type: Slab on Grade	Fair	Fair	Minor cracks visible, no signs of heaving.	Not in Scope
Substructure - Slab - on - Grade	77 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -				
Basement / Below Grade Exterior Walls		Fair	Fair		Not in Scope
Miscellanous		N/A	N/A	<del>-</del>	
Superstructure					
Fireproofing		N/A	N/A		
Pre-Engineered Metal building		N/A	N/A		
Building Exterior Shell					
Roofing					
General Roof Condition (Visual		Cale	Cood	Roof is nearing the end of it's expected useful life. Some leaks are reported with areas of	
Inspection)		Fair	Good	ponding. Some sealants and flashings are in need of repair or replacement.	Replaced roofing in areas reaching the end
Roof Warranty Status				Valid	
Roofing Manufacturer /					
Warranty Issuer				additions- Johns Manville, new- Flex Membrane Int. Inc.	
Years Remaining in					
Warranty Period				new- 12 years	
Skylights		Fair	Fair	·	
Roof Curbs / Openings / Misc.		Fair	Good		Reaplced roof curbs as part of RTU replacement
Exterior Walls					
Exterior Wall Material	Material: Brick	Good	Good	Veneer is free of cracks, signs of settling, rotation or damage.	
Building Caulking/Sealant		Fair	Fair	May show minor signs of aging, minor fading or stains.	
Exterior Painting		N/A	N/A		
Windows/Glazed Walls					
Windows					
	Glazing				
	Type: Single Pane		Fair		Not in Scope
	Frame Type: Aluminum			Minor scratches or signs of wear.	Not in Scope
Exterior Doors Systems	Aluminum			Minor scratches or signs or wear.	Not in Scope
Exterior Doors Systems Exterior Doors					
					1
	Frame Type: Hollow Metal	Fair	Fair	Minor scratches or signs of wear, may need a refresh of finish, door hardware is compliant	Not in Scope
	Panel Type: Hollow Metal	all	all	willor scratches or signs of wear, may need a refresh of littlesh, door hardware is compliant	Not in Scope
Exterior Overhead Doors	Type: Hollow Metal	N/A	N/A	and functioning property.	Not in Scope
Card Access Reader	туре.	Fair	Good		Replaced all Existing Card Readers
Door Bell		Tall	Good	<u> </u>	Replaced all Existing Gard Neaders
Peep Hole				<u> </u>	+
Canopies					
Cartopies			4	No visible damage, proper weather coverage, finishes are almost new in appearance. No	T
Canopy	Type: Attached to Building	Good	Good	signs of settling or movement.	
Loading Area	Type. y muonos to banang			Stylls of settling of movement.	
Locality / 1100				No visible damage, no signs of settling or movement. Dock bumpers present and almost	T
Raised Loading Dock		Good	Good	new in appearance.	
Independent Loading Area		N/A	N/A	нем ін арреатинос.	
Misc. Exterior					
		Good	Good	1.91. fullion organia	
Exterior Soffit - Material	Material: Plaster			Almost new in appearance, no visible fading or stains.	+
Exterior Louvers / Sunscreens		N/A	N/A		
	Coared Categories	40	42		
	Scored Categories	13	13		
			7	_	
	Good	4	1		

Exterior

Calegories	13	13
Good	4	7
Fair	9	6
Poor	0	0
N/A	7	7

Previous Aggregate Score: 77
Reno Aggregate Score: 85



Dellation Classes to	Town of Manda visal	Dulan Oan ditian	0	Dates December 2	0000 Dama Oammanta
Building Element	Type/Material	Prior Condition	Current	Prior Description	2022 Reno Comments
Interior Finishes					
Interior Ceiling Finishes				Almost you in appearance no signs of acquire demage looks or	
Acquetical Callings 2v2 Tiles	Scrubbable Finish Yes	Good	Good	Almost new in appearance, no signs of sagging, damage, leaks, or stains.	
Acoustical Cailings - 2x2 Tiles	Scrubbable Finish Yes Scrubbable Finish	N/A	N/A	stains.	+
Acoustical Ceilings - 2x4 Tiles Plaster Ceilings	Scrubbadie Finish [	N/A N/A	N/A N/A	+	+
Plaster Ceilings				Almost new in appearance, no signs of sagging, damage, leaks, or	+
Painted Gypsum Ceiling		Good	Good	stains.	
Metal Ceilings		N/A	N/A	Stallis.	+
Exposed / Painted Ceilings		N/A	N/A	_	+
Exposed / Lamied Comings				Minor signs of aging with minimal apparent stains, leaks, sagging or	
Soffit / Bulkhead Walls		Fair	Fair	damage.	Not In Scope
Special/Misc.		N/A	N/A		100 111 000 00
Interior Floor Finishes		14/	- Corre		
TROTOL LIBOTO				Almost new in appearance, no signs of damage or stains, properly	
Resilient Flooring - VCT		Good	Good	sealed and finished.	
rooment rooming 10.				Almost new in appearance, no signs of damage or stains, properly	
Quarry Tile		Good	Good	sealed and finished.	
Quality 1110				Almost new in appearance, no signs of damage or stains, properly	
Ceramic Tile		Good	Good	sealed and finished.	
Out and				Almost new in appearance, no signs of damage or stains, properly	
Terrazzo		Good	Good	sealed and finished.	
Poured Resinous Epoxy		N/A	N/A	bouled and innorted.	
Finish Concrete - (sealed)		N/A	N/A	+	
(3.7.7)		,.		Almost new in appearance, no signs of damage or stains, properly	
Carpet (Classrooms, Library, and Administration)		Good	Good	sealed and finished.	
Carpet (Fine Arts Wing)		Fair	Good		
Natural Stone		N/A	N/A	<del>1</del>	
Wo				Almost new in appearance, no signs of damage or stains, properly	
od		Good	Good	sealed and finished.	
Special/Misc.		N/A	N/A		
Interior Wall Finishes					
Painted Gypsum Board - Full Height		Good	Good	Almost new in appearance, no signs of damage, stains or cracking.	
Painted CMU - Full Height		Good	Good	Almost new in appearance, no signs of damage, stains or cracking.	
Painted Gypsum Board + Tile Wainscot		Good	Good	Almost new in appearance, no signs of damage, stains or cracking.	
Full Height Tile		Good	Good	Almost new in appearance, no signs of damage, stains or cracking.	
PLAM		N/A	N/A		
FRP		N/A	N/A		
Wood Panels		N/A	N/A		
Interior Wall Base & Trim					
Rubber Base (Classrooms, Library, and Administration)		Good	Good	Almost new in appearance, no signs of damage and properly installed.	
Rubber Base (Fine Arts Wing)		Fair	Good		Replaced in Areas of Renovation
Quarry Tile		Good	Good	Almost new in appearance, no signs of damage and properly installed.	. T
Ceramic Tile		N/A	N/A		
Terrazzo		Good	Good	Almost new in appearance, no signs of damage and properly installed.	
Poured Resinous Epoxy		N/A	N/A		
Wood Base		N/A	N/A		
The second secon					-

Interior

	_				
Misc. Interior					
Interior Door Systems					
Frame Type:	Hollow Metal	Good	Good	No visible damage, proper weatherproofing/threshold apparent, door hardware compliant	
Panel Type:		3000	Good	and functioning properly.	
		Fair	Fair	Minor scratches or signs of wear, may need a refresh of finish, door hardware is compliant	
Interior Overhead Door/Grille	Type:			and functioning properly, motor works as required (if applicable).	Not In Scope
Specialty Doors	Type:	N/A	N/A		
Millwork Cabinets		Good	Good		
Corner Guards	Type: Stainless Steel	Good	Good	Almost new in appearance.	
Interior Signage		Good	Good		
Digital Clocks		N/A	Good		New Digital Clocks Installed
Operable Partitions		N/A	N/A		
Marker & Tack Boards		Good	Good	No cracking or warping of the board surface.	Replaced in All Areas of Renovation
Projection Screens		N/A	N/A		
A/V Equipment		Good	Good		Upgraded in Areas of Renovation
Lockers	Required Number of Lockers:				
LOCKCIO		Good Good			
	Provided Number of Lockers:				
Railings		Good	Good		
Elevator Cab Finishes		N/A	N/A		
Wireless Access		Fair	Good		Wired Building for new Wireless Access Points
		Good	Good		
Toilet Partitions	Material Type: Plastic	Good	Good		
Toilet Accessories	, , , , , , , , , , , , , , , , , , ,	Good	Good	Almost new condition, proper installation.	
Interior Window Blinds/Shades	Type of Blinds: Metal				
	Type of Shades:	Good	Good		
	Operation: Manual			No visible damage, motor properly functions (if applicable).	
- 10 1 1				3,,,,,,,, .	
Food Service Area	_				b
Equipment Condition		Fair	Good		Replaced Kitchen Equipment and Freezer/Cooler Units
Digital Menu Boards		N/A	N/A		
Restrooms open to Kitchen?		No No	No		
Drinking Fountains in Cafeteria?		No	No		
A 11.111					
Accessibility					
Restrooms		Good	Good	Compliant	
Drinking Fountains		Good	Good	Compliant	
Ramps		Good	Good	Compliant	
0.		Good	Good		
Signage				Compliant	
Doors		Good	Good	Compliant	
Millwork		Fair	Fair	Few compliance items	Not in Scope

Inter	rior
IIII	101

Scored Categories		41
Good	31	36
Fair	7	3
Poor	0	0
N/A	21	20

Previous Aggregate Score:	89
Reno Aggregate Score:	93



BLALACK MIDDLE SCHOOL		AGE: 31 Years 171,150 sf		
ITEM	DESCRIPTION	DESCRIPTION		
OPERATIONAL, SYSTEM & CODE DEFICIENCIES	Assessed Scope	Performed Scope	Prior Grade	Current
HVAC	Task: Replace 1998 York packaged units.	Replaced as part of renovation		
EMCS	Task: Replace CSI controls system. Cost included in 1998 York unit replacement.	Replaced as part of renovation	60	98
PLUMBING	Task: Replace and repipe grease trap.	Not in Scope		-
	Task: Provide new EWCs With bottle fillers in select locations.	Replaced as part of renovation	86	95
	Task: Replace two 2008 Lochinvar electric water heaters.	Not in Scope		
ELECTRICAL SYSTEM	Task:		86	86
INTERIOR LIGHTING	Task: Provide tunable lighting for special education classrooms.	Not in Scope	93	93
EXTERIOR LIGHTING	Task: Replace all existing exterior wall packs with LED fixtures.	Replaced as part of renovation		
	Task: Renovate all exterior parking lot lighting to LED.	Replaced as part of renovation	80	95
FIRE ALARM SYSTEMS	<b>Task:</b> Replace the FCI fire alarm system that was installed in 2006.	n Replaced as part of renovation	70	95
FIRE PROTECTION SYSTEM	Task:		93	93
OTHER	Task: Provide digital marque. Provide power and connectivity.	Will be replaced as part of this renovation	NA NA	NA
		TOTAL	S 78	94



#### Blalack MS Technology and Security Status

System	Possible Score	Corgan Score (2018)	TNCG Score (2022)	Notes
Cabling				
Infrastructure	10	8	9	Small improvements to renovation areas and all new wireless access point cabling
Local Area Network	15	13	13	No upgrade (that True North is aware of)
				Wireless could use a refresh in the next few years but in good condition right now. New cabling
Wireless LAN	15	13	13	in place to support refresh.
Unified Comm				
(Phone) System	10	10	10	Upgraded prior to renovation project
Video Management				
System	10	5	10	Complete upgrade to Genetec
Public Address	10	5	10	Complete upgrade to Informacast
Premise Access				
Control (and				
Intrusion)	10	6	10	Complete upgrade to Genetec
Intercom System	5	3	5	Added new intercom stations with renovation
Special Space AV	5	4	4	District item. AV upgrade as part of technology package
Instruction Space				
Presentation	10	8	9	New Interactive Displays in renovation areas matching district standard
Total Score	100	75	93	

Technology



Bring all CFBISD facilities to a minimum assessment score of 85\*
Mechanical, electrical and plumbing (MEP)
Collaboration
Roofs, Exteriors and Finishes etc.

Blalack MS Assessment

Site: 83

Exterior: 77

Interior: 89

MEP: 78

Technology: 75

Score: 80

PROMISES MADE PROMISES



After Bond Improvements

Site: 93

Exterior: 85

Interior: 93

MEP: 94

Technology: 93

Score: 92

#### ALL CFBISD SCHOOLS \$189.7m



Bring all CFBISD facilities to a minimum assessment score of 85\*

Mechanical, electrical and plumbing (MEP)
Collaboration
Roofs, Exteriors and Finishes etc.

# THANKYOU #cfbpr@ud