

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
C. I. Waggoner Elementary School
1050 East Carver Road, Tempe
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC

Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\C.I. Waggoner\Cvr Ltr.doc8/19/15

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-CMU-13	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious	Exterior	%/ASSUMED Assumed	NF/F NF	G/D/SD G	2,000	LF/SF/EA SF	01/03/19
M-MRT-14	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	200	SF	01/03/19
M-CON-15	M	Concrete (Columns), Gray, Cementitious	Exterior	Assumed	NF	G	100	SF	01/03/19
S-STU-16	M	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	350	SF	01/03/19
M-SLT-17	M	Sealant (Windows), Black, Pliable	Exterior	Assumed	NF	G	4	SF	01/03/19
M-CON-18	M	Concrete (Foundation), Gray, Cementitious	Entry	Assumed	NF	G	1,500	SF	01/03/19
			Entry Closet						
			Bedroom 1						
			Restroom						
			Storage						
			Dining Room						
			Kitchen						
			Living Room						
			Master Bedroom						
			Master Bath						
M-SLT-19	M	Sealant (Duct), Gray, Pliable	Roof	Assumed	NF	G	5	SF	01/03/19
M-BUR-20	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	1,200	SF	01/03/19
M-MAS-21	M	Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint	Roof	Assumed	NF	G	10	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-SLT-22	M/S/T M	Sealant (Flashings), Gray, Pliable	Roof	%/ASSUMED Assumed	NF/F NF	G/D/SD G	20	LF/SF/EA SF	01/03/19
M-CON-23	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	200	SF	01/03/19

***The following materials were not found: S-SAT-01, M-GWB-02, S-JTC-03 and M-SLT-12.**

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Apt-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-FDI-16	M/S/T M	Fire Door Insulation, Metal/Wood Cladding	Reception	%/ASSUMED Assumed	NF/F NF	G/D/SD G	2,562	LF/SF/EA SF	01/03/19
			Receiving						
			Room 04A						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Electrical 6						
			Treatment						
			Assistant Principal						
			Principal						
			Reading						
			Patio						
			Lounge						
			Electrical 1						
			Women's Restroom 1						
			Men's Restroom 1						
			Library						
			AV						
			Server						
			Computer 21						
			Classroom 22						
			Classroom 26						
			Classroom 27						
			Classroom 28						
			Classroom 29						
			Classroom 30						
			Classroom 33						
			Classroom 34						
			Classroom 35						
			Classroom 39B						
			Classroom 39C						
			Classroom 40						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 41						
			Psychology						
			Speech						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Electrical 2						
			Classroom 36						
			Classroom 37						
			Classroom 38						
			Room 39A						
			Classroom 42						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Electrical 3						
			Electrical 5						
			Janitor						
			Art Room 23						
			Vestibule 3						
			Multi-Purpose Room						
			Kitchen						
			P.E. Storage						
			Electrical 4						
			Table Storage						
			North Wing						
			South Wing						
			Music 1						
			Maintenance						
			Music 2						
			Music Storage						
			Classroom 01						
			Classroom 02						
			Classroom 03						
			Classroom 04						
			Classroom 05						
			Classroom 06						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 07						
			Classroom 08						
			Classroom 09						
			Classroom 10						
			Classroom 11						
			Classroom 12						
			Classroom 13						
			Classroom 14						
			Classroom 15						
			Classroom 16						
			Classroom 17						
			Classroom 18						
			Classroom 19						
			Classroom 20						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Vestibule 1						
			Vestibule 2						
			Exterior						
M-GWT-20	M	Glazed Wall Tile, 4"x4", Tan, Smooth	Room 39C Restroom	Assumed	NF	G	250	SF	01/03/19
M-GRT-21	M	Grout, Gray, Cementitious	Room 39C Restroom	Assumed	NF	G	25	SF	01/03/19
M-CMT-22	M	Ceramic Mosaic Tile, 2"x2", Tan, Smooth	Room 39C Restroom	Assumed	NF	G	30	SF	01/03/19
M-GRT-23	M	Grout, Gray, Cementitious	Room 39C Restroom	Assumed	NF	G	3	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS.	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-31	M	Glazed Wall Tile (Pillars), Various, Blue, Smooth, Mosaic Pattern	Reading	Assumed	NF	G	400	SF	01/03/19
			Library						
M-GRT-32	M	Grout, Gray, Cementitious	Reading	Assumed	NF	G	40	SF	01/03/19
			Library						
M-CON-33	M	Concrete (Pillars), Gray, Cementitious	Reading	Assumed	NF	G	500	SF	01/03/19
			Library						
			A/V						
M-GWT-37	M	Glazed Wall Tile, 2"X2", Light Blue, Smooth	Girl's Restroom 3	Assumed	NF	G	4,000	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-38	M	Glazed Wall Tile (Pattern), 2"X2", Dark Blue, Smooth	Girl's Restroom 3	Assumed	NF	G	600	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-39	M	Glazed Wall Tile, 2"X2", Tan, Smooth	Girl's Restroom 3	Assumed	NF	G	600	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/IT		Boy's Restroom 1	%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-40	M	Grout, Gray, Cementitious	Girl's Restroom 3	Assumed	NF	G	460	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-41	M	Ceramic Mosaic Tile (Pattern), 2"X2", Light Blue, Smooth	Girl's Restroom 3	Assumed	NF	G	200	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-42	M	Ceramic Mosaic Tile (Pattern), 2"X2", Dark Blue, Smooth	Girl's Restroom 3	Assumed	NF	G	200	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-43	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Girl's Restroom 3	Assumed	NF	G	2,000	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-44	M	Grout, Gray, Cementitious	Girl's Restroom 3	Assumed	NF	G	240	SF	01/03/19
			Boy's Restroom 3						
			Women's Restroom 1						
			Men's Restroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMU-46	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	1,500	SF	01/03/19
M-GWT-48	M	Glazed Wall Tile, 8"X8", Light Blue, Smooth, Blue and White Spots	Exterior	Assumed	NF	G	400	SF	01/03/19
M-GWT-49	M	Glazed Wall Tile, 8"X8", Blue, Smooth	Exterior	Assumed	NF	G	400	SF	01/03/19
M-GWT-50	M	Glazed Wall Tile, 8"X8", Tan, Smooth, Blue and White Spots	Exterior	Assumed	NF	G	400	SF	01/03/19
M-CON-57	M	Concrete, Gray, Cementitious	Roof	Assumed	NF	G	3,000	SF	01/03/19
M-PES-59	M	Pipe End Sealant, White, Pliable	Electrical 2 Electrical 3	Assumed	NF	G	10	SF	01/03/19
M-ADH-60	M	Adhesive (FRP), Brown, Brittle	Electrical 6 Electrical 2	Assumed	NF	G	30	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T		Electrical 3	%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-62	M	Vinyl Composition Tile (Strip), 2"X24", Black, Smooth	Multi-Purpose Room	Assumed	NF	G	5	SF	01/03/19
M-VCT-63	M	Vinyl Composition Tile (Strip), 2"X24", Red, Smooth	Multi-Purpose Room	Assumed	NF	G	5	SF	01/03/19
M-VCT-64	M	Vinyl Composition Tile (Strip), 2"X24", Green, Smooth	Multi-Purpose Room	Assumed	NF	G	5	SF	01/03/19
M-VCT-65	M	Vinyl Composition Tile (Strip), 2"X24", Yellow, Smooth	Multi-Purpose Room	Assumed	NF	G	5	SF	01/03/19
M-VCT-66	M	Vinyl Composition Tile (Strip), 2"X24", Blue, Smooth	Multi-Purpose Room	Assumed	NF	G	5	SF	01/03/19
M-VCT-68	M	Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth	Multi-Purpose Room	Assumed	NF	G	20	SF	01/03/19
M-CMU-69	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Electrical 4	Assumed	NF	G	800	SF	01/03/19
			Roof						
M-MRT-70	M	Mortar, Gray, Cementitious	Electrical 4	Assumed	NF	G	80	SF	01/03/19
			Roof						
M-VST-78	M	Vinyl Stair Tread, 12"X60", Brown, Vinyl-Like, Circle Pattern	South Wing	Assumed	NF	G	30	SF	01/03/19
M-MAS-79	M	Mastic, Yellow, Tacky	South Wing	Assumed	NF	G	30	SF	01/03/19
M-GWT-82	M	Glazed Wall Tile (Pattern), Various Sizes, White, Smooth	Reading	Assumed	NF	G	150	SF	01/03/19
M-GWT-83	M	Glazed Wall Tile (Pattern), Various Sizes, White, Smooth	Reading	Assumed	NF	G	10	SF	01/03/19
M-GRT-84	M	Grout, Gray, Cementitious	Reading	Assumed	NF	G	16	SF	01/03/19

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-GWT-85	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
	M	Glazed Wall Tile, 2"X2", Tan, Textured	Reading	Assumed	NF	G	2	SF	01/03/19
M-GWT-86	M	Glazed Wall Tile, 3"X3", Tan, Textured	Reading	Assumed	NF	G	10	SF	01/03/19
M-GRT-87	M	Grout, Gray, Cementitious	Reading	Assumed	NF	G	1	SF	01/03/19
M-BUR-92	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	60,000	SF	01/03/19
M-MAS-93	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Roof	Assumed	NF	G	2,000	SF	01/03/19
M-SLT-94	M	Sealant (Flashings), White, Tar- Like	Roof	Assumed	NF	G	20	SF	01/03/19
M-SLT-95	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	20	SF	01/03/19
M-SLT-96	M	Sealant (Flashings), Black, Pliable	Roof	Assumed	NF	G	20	SF	01/03/19
M-SLT-97	M	Sealant (Duct), Gray, Pliable	Roof	Assumed	NF	G	10	SF	01/03/19

G:\2018 Projects\10 EN\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Main-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-CMU-01	M/S/IT M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Mechanical Yard	%/ASSUMED Assumed	NF/F NF	G/D/SD G	3,500	LF/SF/EA SF	01/03/19
			Electrical Room						
			Mechanical Room						
			Exterior						
M-CMU-02	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Mechanical Yard	Assumed	NF	G	1,200	SF	01/03/19
			Electrical Room						
			Mechanical Room						
			Exterior						
M-MRT-03	M	Mortar, Gray, Cementitious	Mechanical Yard	Assumed	NF	G	550	SF	01/03/19
			Electrical Room						
			Mechanical Room						
			Exterior						
M-CON-04	M	Concrete (Foundation), Gray, Cementitious	Mechanical Yard	Assumed	NF	G	5,000	SF	01/03/19
			Electrical Room						
			Mechanical Room						
			Control Room						
M-FDI-05	M	Fire Door Insulation, Metal/Wood Cladding	Electrical Room	Assumed	NF	G	126	SF	01/03/19
			Exterior						
M-SLT-06	M	Sealant (Doors, Windows), White, Pliable	Control Room	Assumed	NF	G	6	SF	01/03/19
			Exterior						
M-CMU-07	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth	Mechanical Yard	Assumed	NF	G	100	SF	01/03/19

3-Year Reinspection
C.I. Waggoner Elementary School, KSD
Mechanical Building
FM Project 18-259

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T		Exterior	%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BRK-08	M	Brick, 4"X16", Red, Cementitious	Mechanical Yard	Assumed	NF	G	500	SF	01/03/19
			Exterior						
M-PES-12	M	Pipe End Sealant, Gray, Pliable	Mechanical Room	Assumed	NF	G	50	SF	01/03/19
M-BUR-13	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	3,000	SF	01/03/19
M-MAS-14	M	Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint	Roof	Assumed	NF	G	25	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Mech-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS.	MTL QUAN	UNITS	DATE LAST INSPECTED
S-SAT-01	M/S/T S	Spray-Applied Texture, White, Chalky	Custodian	%/ASSUMED Assumed	NF/F NF	G G	2,500	LF/SF/EA SF	01/03/19
			Girl's Restroom						
			Boy's Restroom						
M-GWB-02	M	Gypsum Wallboard, White, Chalky	Custodian	Assumed	NF	G	2,500	SF	01/03/19
			Girl's Restroom						
			Boy's Restroom						
S-JTC-03	S	Joint Compound, White, Chalky	Custodian	Assumed	NF	G	250	SF	01/03/19
			Girl's Restroom						
			Boy's Restroom						
M-GWT-04	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Girl's Restroom	Assumed	NF	G	1,500	SF	01/03/19
			Boy's Restroom						
M-GWT-05	M	Glazed Wall Tile (Pattern), 4"X4", Light Blue, Smooth	Girl's Restroom	Assumed	NF	G	200	SF	01/03/19
			Boy's Restroom						
M-GWT-06	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Girl's Restroom	Assumed	NF	G	200	SF	01/03/19
			Boy's Restroom						
M-GRT-07	M	Grout, Gray, Cementitious	Girl's Restroom	Assumed	NF	G	190	SF	01/03/19
			Boy's Restroom						
M-CMT-08	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Girl's Restroom	Assumed	NF	G	900	SF	01/03/19
			Boy's Restroom						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS.	MTL QUAN	UNITS	DATE LAST INSPECTED
M-CMT-09	M	Ceramic Mosaic Tile (Pattern), 2"X2", Light Blue, Smooth	Girl's Restroom	%/ASSUMED Assumed	NF/F NF	G/D/SD G	50	LF/SF/EA SF	01/03/19
			Boy's Restroom						
M-CMT-10	M	Ceramic Mosaic Tile (Pattern), 2"X2", Blue, Smooth	Girl's Restroom	Assumed	NF	G	50	SF	01/03/19
			Boy's Restroom						
M-GRT-11	M	Grout, Gray, Cementitious	Girl's Restroom	Assumed	NF	G	100	SF	01/03/19
			Boy's Restroom						
M-SLT-12	M	Sealant (Doors, Millwork, Fixtures), White, Pliable	Custodian	Assumed	NF	G	17	SF	01/03/19
			Girl's Restroom						
			Boy's Restroom						
M-FDI-13	M	Fire Door Insulation, Metal/Wood Cladding	Custodian	Assumed	NF	G	63	SF	01/03/19
			Girl's Restroom						
			Boy's Restroom						
			Exterior						
S-TOT-14	S	Troweled-On Texture, White, Chalky	Custodian	Assumed	NF	G	100	SF	01/03/19
M-GWB-15	M	Gypsum Wallboard, White, Chalky	Custodian	Assumed	NF	G	100	SF	01/03/19
S-JTC-16	S	Joint Compound, White, Chalky	Custodian	Assumed	NF	G	10	SF	01/03/19
M-WAB-17	M	Wallbase (Coved), 4", Blue, Vinyl- Like	Custodian	Assumed	NF	G	15	SF	01/03/19
M-ADH-18	M	Adhesive, Cream, Pliable	Custodian	Assumed	NF	G	15	SF	01/03/19
M-VCT-19	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Multi-Colored	Custodian	Assumed	NF	G	100	SF	01/03/19
M-MAS-20	M	Mastic, Yellow, Tacky	Custodian	Assumed	NF	G	100	SF	01/03/19

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-21	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious	Exterior	Assumed	NF	G	1,600	SF	01/03/19
M-MRT-22	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	160	SF	01/03/19
M-CON-23	M	Concrete (Gutters), Gray, Cementitious	Exterior	Assumed	NF	G	4	SF	01/03/19
M-CON-24	M	Concrete (Foundation), Gray, Cementitious	Custodian	Assumed	NF	G	1,100	SF	01/03/19
			Girl's Restroom						
			Chase						
			Boy's Restroom						
M-CON-25	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	650	SF	01/03/19
M-BUR-26	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	1,100	SF	01/03/19
M-MAS-27	M	Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint	Roof	Assumed	NF	G	10	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\RR-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-SAT-01, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: MATERIAL MISSING

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes
Explain: UPDATE MANAGEMENT PLAN

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson

Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment

AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-02, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: MATERIAL MISSING

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____

Degree of Activity Near the Material: High _____ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain: UPDATE MANAGEMENT PLAN

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGELO

Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-03, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find [initials]

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: MATERIAL MISSING

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: UPDATE MANAGEMENT PLAN

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: ALL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-12, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find [check]

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: MATERIAL MISSING

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: UPDATE MANAGEMENT PLAN

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anick
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CMU-13, Concrete Masonry Unit, 4"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Ali Abdel
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69223 Signature of Inspector: [Signature]
*Material Reinspected: M-MRT-14, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Phil Angol
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CON-15, Concrete (Columns), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PLU ANKER
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-STU-16, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 64023 Signature of Inspector: [Signature]
*Material Reinspected: M-SLT-17, Sealant (Windows), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ansel
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CON-18, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-SLT-19, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: DAU Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-20, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Don Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-21, Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-SLT-22, Sealant (Flashings), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Apt\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Apartment
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CON-23, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-FDI-16, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGLER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-20, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: ALL ANGELO
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: PS

*Material Reinspected: M-GRT-21, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CMT-22, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ansbacher

Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-23, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:
Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ancker
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-31, Glazed Wall Tile (Pillars), Various, Blue, Smooth, Mosaic Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GRT-32, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CON-33, Concrete (Pillars), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-37, Glazed Wall Tile, 2"X2", Light Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angor
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-38, Glazed Wall Tile (Pattern), 2"X2", Dark Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-39, Glazed Wall Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-40, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anzor

Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-41, Ceramic Mosaic Tile (Pattern), 2"X2", Light Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: G9023 Signature of Inspector: [Signature]
*Material Reinspected: M-CMT-42, Ceramic Mosaic Tile (Pattern), 2"X2", Dark Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-43, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Amber

Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-44, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-46, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-48, Glazed Wall Tile, 8"X8", Light Blue, Smooth, Blue and White Spots

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium 2 Low 3
Degree of Activity Near the Material: High 1 Medium 2 Low 3
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-49, Glazed Wall Tile, 8"X8", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Blue Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-50, Glazed Wall Tile, 8"X8", Tan, Smooth, Blue and White Spots

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-57, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:


Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\57.doc



Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHRA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-PES-59, Pipe End Sealant, White, Pliable



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-ADH-60, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find 2.

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-VCT-62, Vinyl Composition Tile (Strip), 2"X24", Black, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\62.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69923 Signature of Inspector: [Signature]

*Material Reinspected: M-VCT-63, Vinyl Composition Tile (Strip), 2"X24", Red, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\63.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-VCT-64, Vinyl Composition Tile (Strip), 2"X24", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\64.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-VCT-65, Vinyl Composition Tile (Strip), 2"X24", Yellow, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:
Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\65.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-VCT-66, Vinyl Composition Tile (Strip), 2"X24", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\66.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-VCT-68, Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\68.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CMU-69, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\69.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Phil Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-MRT-70, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No

Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\70.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-VST-78, Vinyl Stair Tread, 12"X60", Brown, Vinyl-Like, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:
Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-MAS-79, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:
Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 6923 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-82, Glazed Wall Tile (Pattern), Various Sizes, White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\82.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Ambler
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-83, Glazed Wall Tile (Pattern), Various Sizes, White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GRT-84, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\84.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-85, Glazed Wall Tile, 2"X2", Tan, Textured

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\85.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-86, Glazed Wall Tile, 3"X3", Tan, Textured

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\86.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GRT-87, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\87.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAU ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-92, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low ✓
Degree of Activity Near the Material: High Medium Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\92.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anstett
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-93, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-94, Sealant (Flashings), White, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\94.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-95, Sealant (Flashings), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\95.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Main

AHERA certification number: 6A023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-96, Sealant (Flashings), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\96.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Main
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-SLT-97, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Main\97.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 6923 Signature of Inspector: [Signature]
*Material Reinspected: M-CMU-01, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.9 Person performing reinspection: Paul Angelo
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-02, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. 3

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 49023 Signature of Inspector: PS
*Material Reinspected: M-MRT-03, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-04, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.15 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-FDI-05, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69923 Signature of Inspector: [Signature]
*Material Reinspected: M-SLT-06, Sealant (Doors, Windows), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-BRK-08, Brick, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. (Misc)

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-PES-12, Pipe End Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low 1
Degree of Activity Near the Material: High _____ Medium _____ Low 1
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-13, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:
1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: C.I. Waggoner Elementary School Building Name/Number: Mechanical

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-14, Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\Mech\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-SAT-01, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-02, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-JTC-03, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 2

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-04, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-05, Glazed Wall Tile (Pattern), 4"X4", Light Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-GWT-06, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-07, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-08, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\IRR\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-09, Ceramic Mosaic Tile (Pattern), 2"X2", Light Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-10, Ceramic Mosaic Tile (Pattern), 2"X2", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-11, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-12, Sealant (Doors, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-FDI-13, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-14, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find 2.

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Low Medium _____ Low _____
Degree of Activity Near the Material: High Low Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-15, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-16, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-WAB-17, Wallbase (Coved), 4", Blue, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-18, Adhesive, Cream, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-VCT-19, Vinyl Composition Tile, 12"X12", Tan, Smooth, Multi-Colored

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:
Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-20, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: G9023 Signature of Inspector: [Signature]
*Material Reinspected: M-CMU-21, Concrete Masonry Unit, 4"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-22, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-23, Concrete (Gutters), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGOR
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: G9023 Signature of Inspector: PA

*Material Reinspected: M-CON-24, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:
Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? — Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? — Yes / No
Explain: —

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\24.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69223 Signature of Inspector: DS

*Material Reinspected: M-CON-25, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\25.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-BUR-26, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\26.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: C.I. Waggoner Elementary School Building Name/Number: Restroom
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-27, Mastic (Penetrations and Flashings), Black, Brittle, Silver Paint

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\C.I. Waggoner\Forms\RR\27.doc