



LEARN MORE AT  
energystar.gov

# ENERGY STAR® Progress & Goals Report

# 89

ENERGY STAR®  
Score<sup>1</sup>

## Miller Ed Center East, 215 SE 6th

**Primary Property Type:** K-12 School  
**Gross Floor Area (ft²):** 13,923  
**Built:** 1958

**For Year Ending:** February 28, 2018  
**Date Generated:** May 30, 2018

**Property Address:**  
Miller Ed Center East, 215 SE 6th  
215 SE 6th Ave  
Hillsboro, Oregon 97123

**Property ID:** 2562163

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

### Performance Comparison

	Progress			Performance Goals		
	Baseline (Ending Date 11/30/2009)	(Ending Date 2/28/2018)	% Change	Property's Target	National Median	ENERGY STAR Score of 75
ENERGY STAR Score	97	89	8	75	50	75

#### Energy

Site EUI (kBtu/ft²)	25.4	38.3	50.9	47.5	60.8	47.5
Source EUI (kBtu/ft²)	62.1	86.9	39.8	107.9	137.9	107.9
Energy Cost (\$)	10,310.06	12,662.16	22.81	15,717.87	20,099.05	15,717.87
Energy Cost Intensity (\$/ft²)	0.62	0.91	22.81	1.13	1.44	1.13

#### Greenhouse Gas Emissions

Total GHG Emissions (Metric Tons CO2e)	41.6	49.6	19.23	61.5	78.7	61.5
Total GHG Emissions Intensity (kgCO2e/ft²)	2.5	3.6	19.23	4.4	5.7	4.4

#### Water

All Water Use (kgal)	N/A	N/A	N/A	*	*	*
Indoor Water Use (kgal)	N/A	N/A	N/A	*	*	*
Indoor Water Use Intensity (gal/ft²)	N/A	N/A	N/A	*	*	*
Total Water Cost (\$)	N/A	N/A	N/A	*	*	*

\*Setting and managing water targets is not yet available in Portfolio Manager.