

FIVE-YEAR CAPITAL FACILITIES PLAN

						ITEM NUMBER LEGEND		SYSTEM TYPE		SYSTEM RATING		COST TYPE		Clark Patterson Lee		ARCHITECTURE ENGINEERING PLANNING	
District Name:			Onteora CSD					HS - Health & Safety	E - Excellent	NY State Building Aid	Construction	Y*	Must be part of larger Building project				
Facility Name:			Bennett Elem. School					ST - Structure	S - Satisfactory	Y	MSR	Y					
								EE - Energy Efficiency	U - Unsatisfactory								
								AP - Asset Preservation	NF - Non-Functioning								
SED Number:									CF - Critical Failure								



(A1)



(A2)



(A3) TYPICAL



(A4)



(A5) TYPICAL



(A6)



(A7)



(A8)



CPL | Architecture Engineering Planning
CPLteam.com

ONTEORA CSD - 5 YEAR PLAN - BENNETT ELEMENTARY SCHOOL

PHOTOS





C1



C2




C3



C4



C5



C6



C7



C8



C9



C10



C11



C12

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Information

Page Last Modified: 02/28/2022

Building Information**1. Name of school district**

Onteora CSD

2. SED District 8-Digit BEDS Code

62120106

3. Building Name:

Bennett Elementary School

4. SED 4-Digit Facility Code:

0002

5. Survey Inspection Date:

07/27/2021

6. Building 911 Address:

4166 Route 28

7. City:

Boiceville

8. Zip Code:

12412

9. Certificate of Occupancy Status:

- ☒ A - Annual
☐ T - Temporary
☐ N - None

10. Certificate of Occupancy Expiration Date:

02/01/2023

10a. Is this a manufactured building? (Relocatable, modular, portable)

- ☐ Yes
☒ No

11. Have there been renovations or construction in the building during the past 12 months?

- ☐ Yes
☒ No

12. Was major construction/renovation work since 2015 conducted when school was in session?

- ☐ Yes
☒ No

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)

5,740,162.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Information

Page Last Modified: 02/28/2022

14. Overall building rating (to be answered after the building inspection is complete)

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Failing

15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?

- ☐ Yes
☒ No

16. A/E Firm Name:

CPL

17. A/E Firm Address:

50 Front Street, Suite 202, Newburgh, NY 12550

18. A/E Firm Phone Number:

8455676700

19. E-mail:

ccolby@cplteam.com

20. A/E Name:

Christopher Colby

21. A/E License #:

033581

Building Age, Gross Square Footage and Maintenance Staff**22. Building Age**

	Year
Original Construction	1960
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

23. Square feet of construction

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Information

Page Last Modified: 02/28/2022

	Sq Feet
Original construction	33,654.00
Addition #1	13,785.00
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

24. Gross square ft. of Building as currently configured:

47,439

25. Number of Floors:

1

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	0
Part-time custodians:	3
Totals:	3

Building Ownership and Occupancy Status**27. Building Ownership (check one):**

- ☒ Owned and used by district
☐ Owned by District and leased to non-district entity
☐ Owned by District, part used by district, part leased to non-district entity
☐ Owned by non-district entity and leased to district

28. For which of the following purposes is the building currently used? (check all that apply)

- ☒ Used for student instructional purposes
☐ Used for district administration
☐ Used for other district purposes
☒ Used by other organization(s)

Building Users**29. How many students were registered to receive instruction in this building as of October 1, 2019? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)**

257

30. Of these registered students, how many receive most of their instruction in:

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Information

Page Last Modified: 02/28/2022

	Quantity
Permanent instructional spaces (i.e., regular classrooms)	257
Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	(No Response)
Non-instructional spaces used as instructional spaces	(No Response)

31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2019? (check all that apply)

- ☐ Cafeteria
- ☐ Gymnasium
- ☐ Administrative Spaces
- ☐ Library
- ☐ Lobby
- ☐ Stairwell
- ☐ Storage space
- ☐ Other (please describe)
- ☒ None

32. Grades Housed

- | | |
|---|-------------------------------------|
| ☐ Pre-K | ☐ 7th |
| ☐ Kindergarten | ☐ 8th |
| ☐ 1st | ☐ 9th |
| ☐ 2nd | ☐ 10th |
| ☐ 3rd | ☐ 11th |
| ☒ 4th | ☐ 12th |
| ☒ 5th | ☐ N/A (none) |
| ☒ 6th | |

33. For how many instructional days during the 2018-19 school year (July 1 through June 30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

34. Is the building used for instructional purposes in the summer?

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSProgram Spaces

Page Last Modified: 02/16/2022

Program Spaces**35. Number of instructional classrooms:**

22

36. Gross square footage of all instructional classrooms (combined):

17,600.00

37. Other spaces provided:

- | | | |
|---|--|--|
| ☐ a. N/A (none) | ☒ j. Health Office | ☐ s. Resource Rooms |
| ☒ b. Administration | ☐ k. Home & Careers | ☐ t. Science Labs |
| ☒ c. Art | ☒ l. Kitchen | ☒ u. Special Education |
| ☐ d. Audio Visual | ☐ m. Large Group Instruction | ☐ v. Swimming Pool |
| ☐ e. Auditorium | ☒ n. Library | ☐ w. Teacher Resource |
| ☒ f. Cafeteria | ☐ o. Multipurpose Rooms | ☐ x. Technology/Shop |
| ☒ g. Computer Room | ☒ p. Music | ☐ y. Other (please describe) |
| ☐ h. Guidance | ☐ q. Pre-K | |
| ☒ i. Gymnasium | ☐ r. Remedial Rooms | |

37a. Describe other spaces

No Response

Space Adequacy**38. Rating of space adequacy:**

- ☒ Good
- ☐ Fair
- ☐ Poor

38a. Enter comments:

No Response

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Site Utilities

Page Last Modified: 02/24/2022

SITE UTILITIES**39. Water (H)**

- ☒ Yes
☐ No

39a. Type of Service:

- ☐ Municipal or Utility provided
☒ Well
☐ Other

39b. Types of water service piping

- ☒ Iron
☐ Galvanized
☐ Copper
☐ Lead
☐ PVC
☐ Other
☐ N/A (None)

39c. Overall condition of water service piping

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

39d. Year of Last Major Reconstruction/Replacement:

1960

39e. Expected Remaining Useful Life (Years):

5

39f. Cost to Reconstruct/Replace \$:

(No Response)

39g. Comments:

Well system shared with HS/MS

40. Site Sanitary (H)

- ☒ Yes
☐ No

40a. Type of Service:

- ☒ Municipal or utility sewer
☐ Site septic
☐ Other

40b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Site Utilities

Page Last Modified: 02/24/2022

40c. Year of Last Major Reconstruction/Replacement:

2011

40d. Expected Remaining Useful Life (Years):

25

40e. Cost to reconstruct/Replace \$:

(No Response)

40f. Comments:

No Response

41. Site Gas☐ Yes☒ No**42. Site Fuel Oil**☒ Yes☐ No**42a. Number of Above-Ground Tanks:**

0

42a.1 Capacity of Above-Ground Tanks (gallons):

0

42b. Number of Below-Ground Tanks:

1

42b.1 Capacity of Below-Ground Tanks (gallons):

10,000

42c. Condition:☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure☐ N/A**42d. Year of Last Major Reconstruction/Replacement:**

1987

42e. Expected Remaining Useful Life (Years):

0

42f. Cost to Reconstruct/Replace \$:

250,000.00

42g. Comments:

Installation of new tank in Design Process/Review process

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Site Utilities

Page Last Modified: 02/24/2022

43. Site Electrical, Including Exterior Distribution☒ Yes☐ No**43a. Service Provider:**☒ Municipal or utility provided☐ Self-Generated☐ Other☐ N/A**43b. Type of Service:**☐ Above Ground☒ Below Ground☐ N/A**43c. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**43d. Year of Last Major Reconstruction/Replacement:**

2003

43e. Expected Remaining Useful Life (Years):

5

43f. Cost to Reconstruct/Replace \$:

100,000.00

43g. Comments:

Replace transformer, CT cabinet and meter

SITE FEATURES**44. Closed Drainage Pipe Stormwater Management System****44a. Does this facility have a closed pipe system?**☒ Yes☐ No**44b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**44c. Year of Last Major Reconstruction/Replacement:**

2016

44d. Expected Remaining Useful Life (Years):

20

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSSite Utilities

Page Last Modified: 02/24/2022

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

Concrete liner installed in 2016

45. Open Drainage Pipe Stormwater Management System**45a. Does this facility have an open stormwater system (ditch)?**☐ Yes☒ No**46. Catch Basins/Drop Inlets/Manholes****46a. Does this facility have catch basins/drop inlets/manholes?**☒ Yes☐ No**46b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**46c. Year of Last Major Reconstruction/Replacement:**

1960

46d. Expected Remaining Useful Life (Years):

10

46e. Cost to Reconstruct/Replace \$:

(No Response)

46f. Comments:

(No Response)

47. Culverts**47a. Does this facility have culverts?**☒ Yes☐ No**47b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**47c. Year of Last Major Reconstruction/Replacement:**

2019

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Site Utilities

Page Last Modified: 02/24/2022

47d. Expected Remaining Useful Life (Years):

10

47e. Cost to Reconstruct/Replace \$:

(No Response)

47f. Comments:

Entrance to CMP needs to be cleaned

48. Outfalls**48a. Does this facility have outfalls?**☒ Yes☐ No**48b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**48c. Year of Last Major Reconstruction/Replacement:**

1960

48d. Expected Remaining Useful Life (Years):

5

48e. Cost to Reconstruct/Replace \$:

(No Response)

48f. Comments:

(No Response)

49. Infiltration Basins/Chambers**49a. Does this facility have infiltration basins/chambers?**☐ Yes☒ No**50. Retention Basins****50a. Does this facility have retention basins?**☐ Yes☒ No**51. Wetponds****51a. Does this facility have wetponds?**☐ Yes☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSSite Utilities

Page Last Modified: 02/24/2022

52. Manufactured Stormwater Proprietary Units**52a. Does this facility have proprietary units?**

- ☐ Yes
- ☒ No

53. Point of Outfall Discharge: (check all that apply)

- ☐ Municipal storm sewer system
- ☐ Combined sewer system
- ☒ Surface Water
- ☐ On-site recharge
- ☐ Other (describe)
- ☐ Not Applicable

54. Outfall Reconnaissance Inventory**Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?**

- ☒ Yes
- ☐ No
- ☐ Not Applicable

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSOther Site Features

Page Last Modified: 02/24/2022

SITE FEATURES**55. Pavement (Roadways and Parking Lots)**

- ☒ Yes
☐ No

55a. Type: (check all that apply)

- ☐ Concrete
☒ Asphalt
☐ Gravel
☐ Other

55b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

55c. Year of Last Major Reconstruction/Replacement:

2003

55d. Expected Remaining Useful Life (Years):

3

55e. Cost to Reconstruct/Replace \$:

575,800.00

55f. Comments:

Full depth asphalt replacement of upper teacher lot, mill and pave upper ADA parking area, and mill and pave front asphalt area

56. Sidewalks

- ☒ Yes
☐ No

56a. Type: (check all that apply)

- ☒ Asphalt
☒ Concrete
☐ Gravel
☐ Paver
☐ Other

56b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

56c. Year of Last Major Reconstruction/Replacement:

2003

56d. Expected Remaining Useful Life (Years):

5

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSOther Site Features

Page Last Modified: 02/24/2022

56e. Cost to Reconstruct/Replace \$:

274,750.00

56f. Comments:

Remove asphalt sidewalk and replace with concrete; Remove and replace all existing concrete curbing; Remove and replace existing stairs concrete stairs

57. Playgrounds and Playground Equipment☒ Yes☐ No**57a. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

57b. Year of Last Major Reconstruction/Replacement:

2015

57c. Expected Remaining Useful Life (Years):

10

57d. Cost to Reconstruct/Replace \$:

200,000.00

57e. Comments:

Remove asphalt play area and grade area to be level, reinstall asphalt surface

58. Athletic Fields and Play Fields☒ Yes☐ No**58a. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

58b. Year of Last Major Reconstruction/Replacement:

2003

58c. Expected Remaining Useful Life (Years):

5

58d. Cost to Reconstruct/Replace \$:

1,000.00

58e. Comments:

Install new chain linked fence gate on north side of asphalt play area

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSOther Site Features

Page Last Modified: 02/24/2022

58f. Does the facility have synthetic turf field(s)

- ☐ Yes
☒ No

58f.1 If Yes, how many synthetic turf fields?

(No Response)

58f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):

(No Response)

58f.3 Type of synthetic turf field infill:

(No Response)

59. Exterior Bleachers / Stadiums

- ☐ Yes
☒ No

60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)

- ☒ Yes
☐ No

60a. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

60b. Year of Last Major Reconstruction/Replacement:

1960

60c. Expected Remaining Useful Life (Years):

5

60d. Cost to Reconstruct/Replace \$:

3,000.00

60e. Comments:

Remove and install new flag pole

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Structure

Page Last Modified: 02/24/2022

Building Structure**61. Foundation (S)****61a. Type (check all that apply):**

- ☒ Reinforced Concrete
- ☐ Masonry on Concrete Footing
- ☐ Other (specify)

61a1. If "Other" please specify

(No Response)

61b. Evidence of structural concerns (check all that apply):

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

61c. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

61d. Year of Last Major Reconstruction/Replacement:

2003

61e. Expected Remaining Useful Life (Years):

20

61f. Cost to Reconstruct/Replace \$:

(No Response)

61g. Comments:

(No Response)

62. Piers (S)

- ☐ Yes
- ☒ No

62f. Cost to Reconstruct/Replace \$:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Structure

Page Last Modified: 02/24/2022

63. Columns (S)**Type (check all that apply):**

- ☐ Concrete
- ☒ Masonry
- ☐ Steel
- ☐ Stone
- ☐ Wood
- ☐ Other (specify)
- ☐ N/A (None)

63.1. If "Other" please specify

(No Response)

63a. Evidence of structural concerns (check all that apply)

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

63b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

63c. Year of Last Major Reconstruction/Replacement

(No Response)

63d. Expected Remaining Useful Life (Years):

(No Response)

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

(No Response)

64. Footings (S)**Type (check all that apply):**

- ☒ Concrete
- ☐ Other (specify)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Structure

Page Last Modified: 02/24/2022

64a. Evidence of structural concerns (check all that apply)

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other (specify)
- ☒ None

64.a1. If "Other" please specify

(No Response)

64b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

64c. Year of Last Major Reconstruction/Replacement

1960

64d. Expected Remaining Useful Life (Years):

20

64e. Cost to Reconstruct/Replace \$:

(No Response)

64f. Comments:

(No Response)

65. Structural Floors (S)**65a. Type (check all that apply):**

- ☐ Concrete Deck on Wood Structure
- ☐ Concrete/Metal Deck/Metal Joists
- ☐ Cast in Place Concrete Structural System
- ☐ Precast Concrete Structural System
- ☒ Reinforced Concrete Slab on Grade
- ☐ Wood Deck on Wood Trusses
- ☐ Wood Deck on Wood Joists
- ☐ Other (specify)

65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Unsupported Ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously Damaged/Missing Components
- ☒ Other Problems
- ☐ None

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Structure

Page Last Modified: 02/24/2022

65b.1 Describe Other Problems:

Edge of slab has degrade at window wall base.

65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- ☒ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☐ None

65d. Overall Condition of Structural Floors:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

65e. Year of Last Major Reconstruction/Replacement:

2003

65f. Expected Remaining Useful Life (Years):

20

65g. Cost to Reconstruct/Replace \$:

(No Response)

65h. Comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Envelope

Page Last Modified: 02/16/2022

BUILDING ENVELOPE**66. Exterior Walls/Columns (S)****66a. Material (check all that apply):**

- ☐ Aluminum/Glass Curtain Wall
- ☐ Brick
- ☐ Concrete
- ☐ Composite Insulated Panels
- ☒ Masonry
- ☐ Steel
- ☐ Wood
- ☐ Other (specify)

66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

66b.1 Describe Other Problems:

(No Response)

66c. Evidence of Concerns with Exterior Cladding (check all that apply):

- ☒ Cracks/Gaps
- ☐ Inadequate Flashing
- ☐ Efflorescence
- ☐ Moisture Penetration
- ☒ Rot/Decay/Corrosion
- ☐ Other Problems
- ☐ None

66c.1 Describe Other Problems:

(No Response)

66d. Overall Condition of Exterior Walls/Columns:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

66e. Year of Last Major Reconstruction/Replacement:

2003

66f. Expected Remaining Useful Life (Years):

3

66g. Cost to Reconstruct/Replace \$:

69,000.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Envelope

Page Last Modified: 02/16/2022

66h. Comments:

Decay at lintels, repoint and reflash, prime and paint lintels.

67. Chimneys (S)

- ☒ Yes
☐ No

67a. Material (check all that apply):

- ☒ Masonry
☐ Concrete
☐ Metal
☐ Wood
☐ Other

67a.1 Specify other:

(No Response)

67b. Overall Condition of Chimneys:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical failure

67c. Year of Last Major Reconstruction/Replacement:

1960

67d. Expected Remaining Useful Life (Years):

5

67e. Cost to Reconstruct/Replace \$:

4,600.00

67f. Comments:

Repoint chimney and reset cap

68. Parapets (S)

- ☐ Yes
☒ No

69. Exterior Doors**69a. Overall Condition of Exterior Door Units:**

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

69b. Do any exterior doors have magnetic locking devices?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Envelope

Page Last Modified: 02/16/2022

69c. Safety/Security features are adequate?

- ☒ Yes
☐ No

69d. Year of Last Major Reconstruction/Replacement:

2003

69e. Expected Remaining Useful Life (Years):

2

69f. Cost to Reconstruct/Replace \$:

51,750.00

69g. Comments:

Replace select exterior doors

70. Exterior Steps, Stairs, Ramps (S)

- ☒ Yes
☐ No

70a. Construction Type (Check all that apply)

- ☒ Concrete
☐ Paver
☐ Steel
☐ Wood
☐ Other (specify)

70b. If "other", specify here

(No Response)

70c. Overall Condition of Exterior Steps, Stairs and Ramps

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

70d. Year of Last Major Reconstruction/Replacement:

1960

70e. Expected Remaining Useful Life (Years):

1

70f. Cost to Reconstruct/Replace \$:

123,000.00

70g. Comments:

Replace aging concrete stairs/railing

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Envelope

Page Last Modified: 02/16/2022

71. Fire Escapes (S)**71a. Does This Facility Have One or More Fire Escapes?**

- ☐ Yes
☒ No

72. Windows

- ☒ Yes
☐ No

72a. Window Material: (check all that apply)

- ☒ Aluminum
☐ Steel
☐ Vinyl
☐ Solid Wood
☐ Wood w/ External Cladding System
☐ Other

72a1. If "Other" please specify

(No Response)

72b. Overall Condition of Windows:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

72c. All Rescue Windows are Operable:

- ☒ Yes
☐ No
☐ N/A

72d. Year of Last Major Reconstruction/Replacement:

1960

72e. Expected Remaining Useful Life (Years):

1

72f. Cost to Reconstruct/Replace \$:

448,500.00

72g. Comments:

Replace original windows/block system (check for asbestos) not included in price.

73. Roof and Skylights (S)

- ☒ Yes
☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Envelope

Page Last Modified: 02/16/2022

73a. Type of roof construction (check all that apply):

- ☐ Concrete on metal deck on metal trusses/joists
- ☐ Concrete (poured or plank) on concrete beams
- ☐ Gypsum (poured or plank) on metal trusses/joists
- ☒ Metal deck on metal trusses/joists
- ☐ Wood deck on wood trusses/joists
- ☐ Wood deck on metal trusses/joists
- ☐ Tectum on metal trusses/joists
- ☒ Other (describe below)

73a.1 Other roof construction type:

(No Response)

73b. Type of roofing material (check all that apply):

- ☒ Single-ply membrane
- ☐ Built-up
- ☐ Asphalt shingle
- ☐ Pre-formed metal
- ☐ IRMA
- ☐ Slate
- ☐ Fluid applied seamless surfacing
- ☐ Other (describe below)

73b.1 Other roofing material:

(No Response)

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- ☐ Structural cracks
- ☐ Unsupported ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously damaged/missing components
- ☐ Other concerns (describe)
- ☒ None

73c.1 Describe other concerns:

(No Response)

73d. Evidence of structural concerns with roof deck (check all that apply):

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

73e. Does this facility have skylights?

- ☐ Yes
- ☒ No

73f. Skylight material (check all that apply):

- ☐ Plastic
- ☐ Glass
- ☐ Other
- ☒ N/A

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Envelope

Page Last Modified: 02/16/2022

73g. Overall condition of skylights:

- ☐ Excellent
- ☐ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- ☐ Failures/Splits/Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Inadequate flashing/curbs/pitch pockets
- ☐ Inadequate or poorly functioning roof drains
- ☒ Evidence of water penetration/active leaks
- ☐ Other (specify)
- ☐ None

73h.1 Specify other concerns:

(No Response)

73i. Overall Condition of Roof and Skylights:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

73j. Year of Last Major Reconstruction/Replacement:

2003

73k. Expected Remaining Useful Life (Years):

2

73l. Cost to Reconstruct/Replace \$:

278,918.00

73m. Comments:

Restore 2003 roof system.

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Interiors

Page Last Modified: 02/16/2022

BUILDING INTERIOR**74. Interior Bearing Walls and Fire Walls (S)**

- ☒ Yes
☐ No

74a. Overall condition of interior bearing walls and fire walls:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical Failure

74b. Year of Last Major Reconstruction/Replacement:

1960

74c. Expected Remaining Useful Life (Years):

10

74d. Cost to Reconstruct/Replace \$:

(No Response)

74e. Comments:

(No Response)

75. Other Interior Walls

- ☒ Yes
☐ No

75a. Overall condition of other interior walls:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

1960

75c. Expected Remaining Useful Life (Years):

10

75d. Cost to Reconstruct/Replace \$:

(No Response)

75e. Comments:

(No Response)

76. Carpet

- ☒ Yes
☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Interiors

Page Last Modified: 02/16/2022

76a. Where located (check all that apply):

- ☒ Classrooms
- ☐ Corridors
- ☐ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Other Areas

76b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

76c. Year of Last Major Reconstruction/Replacement:

2003

76d. Expected Remaining Useful Life (Years):

5

76e. Cost to Reconstruct/Replace \$:

(No Response)

76f. Comments:

(No Response)

77. Resilient Tiles or Sheet Flooring

- ☒ Yes
- ☐ No

77a. Where located (check all that apply):

- ☒ Classrooms
- ☒ Corridors
- ☒ Offices
- ☒ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Other Areas

77b. Overall condition of resilient tiles or sheet flooring:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

1960

77d. Expected Remaining Useful Life (Years):

1

77e. Cost to Reconstruct/Replace \$:

207,000.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Interiors

Page Last Modified: 02/16/2022

77f. Comments:

Abate poor condition VAT in classrooms

78. Hard Flooring (concrete; ceramic tile; stone; etc)

- ☒ Yes
☐ No

78a. Where located (check all that apply):

- ☐ Classrooms
☐ Corridors
☐ Offices
☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
☒ Kitchen
☒ Locker Rooms/Toilet Rooms
☐ Other Areas

78b. Overall condition of hard flooring:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

78c. Year of Last Major Reconstruction/Replacement:

1960

78d. Expected Remaining Useful Life (Years):

5

78e. Cost to Reconstruct/Replace \$:

(No Response)

78f. Comments:

Replace tile with ADA renovations

79. Wood Flooring

- ☐ Yes
☒ No

80. Ceilings (H)

- ☒ Yes
☐ No

80a. Overall condition of ceilings:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

80b. Year of Last Major Reconstruction/Replacement:

1960

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Interiors

Page Last Modified: 02/16/2022

80c. Expected Remaining Useful Life (Years):

1

80d. Cost to Reconstruct/Replace \$:

247,800.00

80e. Comments:

Replace spline and damaged 2x4 ceilings

81. Lockers

☐ Yes

☒ No

81d. Cost to Reconstruct/Replace \$:

(No Response)

82. Interior Doors

☒ Yes

☐ No

82a. Overall condition of interior door units:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

82b. Overall condition of interior door hardware:

☐ Excellent

☐ Satisfactory

☒ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

2003

82d. Expected Remaining Useful Life (Years):

3

82e. Cost to Reconstruct/Replace \$:

94,400.00

82f. Comments:

Replace older 1960's doors, approximately 40

83. Interior Stairs (H)

☒ Yes

☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSBuilding Interiors

Page Last Modified: 02/16/2022

83a. Overall condition of interior stairs:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

83b. Stair material

- ☒ Concrete
- ☐ Steel
- ☐ Wood
- ☐ Other

83c. Year of Last Major Reconstruction/Replacement:

2003

83d. Expected Remaining Useful Life (Years):

10

83e. Cost to Reconstruct/Replace \$:

(No Response)

83f. Comments:

(No Response)

84. Elevator, Lift, and Escalators (H)

- ☒ Yes
- ☐ No

84a. Overall condition of elevators, lifts, escalators:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

84b. Year of Last Major Reconstruction/Replacement:

2003

84c. Expected Remaining Useful Life (Years):

10

84d. Cost to Reconstruct/Replace \$

(No Response)

84e. Comments:

(No Response)

85. Swimming Pool and Swimming Pool Systems (H)

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Building Interiors

Page Last Modified: 02/16/2022

86. Interior Bleachers

☐ Yes

☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

HVAC Systems

Page Last Modified: 02/16/2022

HVAC Systems**87. Heat Generating Systems (H)**

- ☒ Yes
☐ No

87a. Heat generation source (check all that apply):

- ☐ Biomass
☒ Boiler / Hot Water
☐ Boiler / Steam
☐ Cogeneration Plant
☐ Electric
☐ Furnace / Forced Air
☐ Geothermal
☐ Heat Pump
☐ Unit Ventilation
☐ Other (describe below)

87a.1 Other heat generation source:

(No Response)

87b. Overall condition of heat generating systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2002

87d. Expected Remaining Useful Life (Years):

10

87e. Cost to Reconstruct/Replace \$:

(No Response)

87f. Comments:

(No Response)

88. Ventilation System (exhaust fans, etc) (H)

- ☒ Yes
☐ No

88a. Type of ventilation system (check all that apply)

- | | |
|--|---|
| ☐ Natural ventilation | ☐ Heat pump |
| ☐ Central system | ☐ Split system/ variable refrigerant |
| ☐ Energy recovery ventilator | ☒ Powered relief air system |
| ☒ Rooftop units | ☐ Gravity/barometric relief |
| ☒ Unitary (UVs, FC/BC, PTAC) | ☐ Other (specify) |
| ☐ Forced air furnace | |

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

HVAC Systems

Page Last Modified: 02/16/2022

88b. If "Other" please specify here

(No Response)

88c. Overall condition of ventilation systems

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical Failure

88d. Year of last major reconstruction/replacement

2002

88e. Expected remaining useful life (years):

10

88f. Cost to reconstruct/replace \$:

(No Response)

88g. Comments

Gym units are currently being replaced.

89. Mechanical Cooling / Air-Conditioning Systems

- ☐ Yes
- ☒ No

90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc. (H)

- ☒ Yes
- ☐ No

90a. Overall condition of piped heating and cooling distribution systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2002

90c. Expected Remaining Useful Life (Years):

10

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

HVAC Systems

Page Last Modified: 02/16/2022

91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

- ☒ Yes
☐ No

91a. Overall condition of ducted heating and cooling distribution systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2002

91c. Expected Remaining Useful Life (Years):

15

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

- ☒ Yes
☐ No

92a. Type of control system

- ☐ Pneumatic
☒ Electric
☐ Digital Direct Control (DDC)
☐ Web based DDC

92b. Overall condition of control systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

92c. Year of Last Major Reconstruction/Replacement:

2016

92d. Expected Remaining Useful Life (Years):

20

92e. Cost to Reconstruct/Replace \$:

(No Response)

92f. Comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSPlumbing Systems

Page Last Modified: 02/16/2022

PLUMBING**93. Water Supply System (H)**

- ☒ Yes
☐ No

93a. Types of pipes (check all that apply):

- ☐ Asbestos/transite
☒ Copper
☐ Galvanized
☐ Iron
☐ Lead
☐ PVC/CPVC/PEX/Plastic
☐ Other (specify)

93b. If "Other" please specify here

(No Response)

93c. Overall condition of water supply system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

93d. Year of Last Major Reconstruction/Replacement:

1960

93e. Expected Remaining Useful Life (Years):

5

93f. Cost to Reconstruct/Replace \$:

(No Response)

93g. Comments:

(No Response)

94. Sanitary System (H)

- ☒ Yes
☐ No

94a. Types of pipes (check all that apply):

- ☒ Iron
☐ Galvanized
☐ Copper
☐ Glass/ceramic
☐ PVC/CPVC/ABS/poly propylene/plastic
☐ Lead
☐ Other (specify)

94a1. If "Other" please specify

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSPlumbing Systems

Page Last Modified: 02/16/2022

94b. Types of special sanitary systems (Check all that apply)

- ☐ Acid waste and vent
- ☐ Grease interceptor
- ☐ Oil separator
- ☐ Pumping station
- ☐ Sediment trap
- ☐ Septic tank
- ☐ Waste water treatment plant

94c. Overall condition of sanitary system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

2011

94e. Expected Remaining Useful Life (Years):

25

94f. Cost to Reconstruct/Replace \$:

(No Response)

94g. Comments:

(No Response)

95. Storm Water Drainage System (H)

- ☒ Yes
- ☐ No

95a. Types of pipes (check all that apply)

- ☒ Iron
- ☐ Galvanized
- ☐ Copper
- ☐ Lead
- ☐ Plastic
- ☐ Other

95a1. If "Other" please specify

(No Response)

95b. Overall condition of storm water drainage system

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

95c. Year of Last Major Reconstruction/Replacement

1960

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Plumbing Systems

Page Last Modified: 02/16/2022

95d. Expected Remaining Useful Life (Years)

1

95e. Cost to Reconstruct/Replace \$:

(No Response)

95f. Comments:

(No Response)

96. Hot Water Heaters (H)

☒ Yes

☐ No

96a. Type of fuel (check all that apply):

- ☐ Oil
- ☐ Natural Gas
- ☐ Electricity
- ☐ Propane
- ☒ Other (specify)

96b. If "Other" please specify

Heat exchanger to boiler

96c. Overall condition of hot water heaters:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

96d. Year of Last Major Reconstruction/Replacement:

1985

96e. Expected Remaining Useful Life (Years):

5

96f. Cost to Reconstruct/Replace \$:

(No Response)

96g. Comments:

Heat exchanger to boiler

97. Plumbing Fixtures (H)

☒ Yes

☐ No

97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSPlumbing Systems

Page Last Modified: 02/16/2022

97b. Year of Last Major Reconstruction/Replacement:

2002

97c. Expected Remaining Useful Life (Years):

5

97d. Cost to Reconstruct/Replace \$:

75,000.00

97e. Comments:

Update to ADA

98. Water Outlets/Taps for Drinking/Cooking Purposes (H)☒ Yes☐ No**98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep, ice machines, etc).**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

98b. Year of last major reconstruction/replacement:

1960

98c. Expected remaining useful life (years):

5

98d. Cost to reconstruct/replace \$:

(No Response)

98e. Comments

Well shared with High School

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Fire Suppression Systems

Page Last Modified: 02/16/2022

Fire Suppression Systems

99. Fire Suppression System (H)

- ☐ Yes
- ☒ No

100. Kitchen Hoods (H)

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSElectrical Systems

Page Last Modified: 02/24/2022

ELECTRICAL SYSTEMS**101. Electrical Power Distribution System (H)**

- ☒ Yes
☐ No

101a. Electrical supply meets current needs:

- ☒ Yes
☐ No

101b. Condition of electrical power distribution system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

101c. Year of last major reconstruction/replacement?

2003

101d. Expected remaining useful life (years):

5

101e. Cost to reconstruct/replace:

250,000.00

101f. Comments:

Replace all original Federal Pacific panels

102. Lighting Fixtures (H)

- ☒ Yes
☐ No

102a. Condition of lighting figures:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

102b. Year of last major reconstruction/replacement:

2014

102c. Expected remaining useful life (years):

15

102d. Cost to reconstruct/replace:

(No Response)

102e. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSElectrical Systems

Page Last Modified: 02/24/2022

103. Emergency/ Exit Lighting Systems (H):☒ Yes☐ No**103a. Overall condition of emergency/exit lighting systems:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical failure**103b. Year of last major reconstruction/replacement:**

2010

103c. Expected remaining useful life (years):

10

103d. Cost to reconstruct/replace:

40000

103e. Comments

Replace original EM units

104. Emergency or standby power system (H)☐ Yes☒ No**105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)**☒ Yes☐ No**105a. Overall condition of fire alarm system:**☐ Excellent☐ Satisfactory☒ Unsatisfactory☐ Non-functioning☐ Critical failure**105b. Year of last major reconstruction/replacement:**

1998

105c. Expected remaining useful life (years):

0

105d. Cost to reconstruct/replace:

335,000

105e. Comments

System is beyond useful life and does not meet current code

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Electrical Systems

Page Last Modified: 02/24/2022

106. Carbon Monoxide Alarm System (H)

- ☒ Yes
☐ No

106a. Type of alarm system:

- ☒ 10-year battery stand alone alarm
☐ hardwired/interconnected detection and alarm
☐ gas detection (eg NG/CO)
☐ Other (specify)

106b. If "Other" please specify

(No Response)

106c. Overall condition of carbon monoxide alarm system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

106d. Year of last major reconstruction/replacement:

2015

106e. Expected remaining useful life (years):

0

106f. Cost to reconstruct/replace:

10,000.00

106g. Comments

Replace stand alone system with hardwired to fire alarm

107. Communication Systems (H)

- ☒ Yes
☐ No

107a. Type of communication system (check all that apply)

- ☒ Public Address
☐ Phones (VOIP)
☐ Phones (Cellular)
☒ Phones (other)
☐ Mass Notification
☐ Emergency voice communication fire alarm system
☐ Lockdown notification system
☐ Other (eg. radio) (describe below)

107b. If "Other" please describe

(No Response)

107c. Communication systems are adequate:

- ☒ Yes
☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSElectrical Systems

Page Last Modified: 02/24/2022

107d. Condition of communication system:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure

107e. Year of last major reconstruction/replacement:

1995

107f. Expected remaining useful life:

0

107g. Cost to replace/reconstruct:

500,000.00

107h. Comments

Replace entire PA system and phone system

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSStudent Transportation Facilities

Page Last Modified: 02/16/2022

Student Transportation Facilities**108. Is this building a transportation facility**

- ☐ Yes
☒ No

109. Does this facility have a fuel dispensing system?

- ☐ Yes
☒ No

110. Does this facility have vehicle lifts

- ☐ Yes
☒ No

111. Does this facility have a bus wash system?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSAccessibility

Page Last Modified: 02/16/2022

ACCESSIBILITY**112. Exterior Accessible Route to Building (H)**

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- ☐ Yes
☒ No

112a. Features provided for exterior accessible route (check all that apply)

- ☐ Curb ramps
☐ Exterior ramps
☐ Handicap parking

112b. Cost of improvements needed to provide exterior accessible route to building \$:

(No Response)

112c. Comment

(No Response)

113. Is there an exterior accessible route to recreational facilities?

- ☐ Yes
☒ No

113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:

(No Response)

113b. Comments

(No Response)

114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that apply)

- ☐ Playground and play equipment
☐ Playfield(s)
☐ Athletic Field(s)
☐ Exterior Bleachers
☐ Bathroom Facilities
☐ Concession Stand

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

(No Response)

114b. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSAccessibility

Page Last Modified: 02/16/2022

115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

- ☐ Yes
☒ No

115a. Cost of improvements needed to provide interior accessible route(s) as specified above \$:

45000

115b. Comments

Restrooms do not meet code, main entry is not ADA compliant; door hardware (1960's) is not compliant

116. Does this facility have interior spaces that meet accessibility standards (check all that apply)

- ☒ Classrooms
☐ Labs (science, art, technology, etc)
☐ Shops
☒ Main Office
☒ Health Office
☒ Gymnasium
☒ Cafeteria
☒ Auditorium
☒ Stage
☒ Restrooms on each floor

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

116b. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Environment/Comfort/Health

Page Last Modified: 02/16/2022

ENVIRONMENT/COMFORT/HEALTH**117. General Appearance****117a. Overall Rating:**

- ☐ Good
- ☒ Fair
- ☐ Poor

117b. Comments:

(No Response)

118. Cleanliness (H)**118a. Overall Rating:**

- ☒ Good
- ☐ Fair
- ☐ Poor

118b. Comments:

(No Response)

119. Are there walk off mats; grills in the entryway?

- ☒ Yes
- ☐ No

119a. If yes: at least 6 feet long?

- ☒ Yes
- ☐ No

120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)

- ☐ Yes
- ☒ No

121. Lighting Quality (H):**121a. Types of lighting in general purpose classrooms (check all that apply):**

- ☒ Daylight (natural)
- ☐ Not full spectrum
- ☐ Full spectrum
- ☒ LED
- ☐ Fluorescent
- ☐ Other (describe)

121b. Are there blinds in the classroom to prevent glare?

- ☒ Yes
- ☐ No

121c. Overall Rating:

- ☒ Good
- ☐ Fair
- ☐ Poor

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Environment/Comfort/Health

Page Last Modified: 02/16/2022

121d. Comments:

(No Response)

122. Evidence of Vermin (H)

122a. Is there evidence of active infestations of...(check all that apply)?

- ☐ Rodents
- ☐ Wood-boring or Wood-eating Insects
- ☐ Cockroaches
- ☐ Other Vermin
- ☒ None

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSIndoor Air Quality

Page Last Modified: 02/16/2022

Indoor Air Quality**123. Mold (H)****123a. Is there visible mold or moldy odors?**

- ☐ Yes
☒ No

123b. Are any surfaces constructed of any of the following materials?

- ☒ Paper-faced or gypsum products
☒ Cellulose products (typically ceiling tiles)

123c. Is there evidence of water intrusion?

- ☐ Yes
☒ No

123d. Estimated cost of necessary improvements \$:

(No Response)

123e. Comments:

(No Response)

124. Humidity/Moisture (H)**124a. Overall rating of humidity/moisture condition in building:**

- ☒ Good
☐ Fair
☐ Poor

124b. Are any of the following found in/or around classroom areas (check all that apply)?

- ☐ Active leaks in roof
☐ Active leaks in plumbing
☐ Moisture condensation
☐ Visible stains or water damage
☒ None

124c. Are any of the following found in/or around other areas (check all that apply)?

- ☐ Active leaks in roof
☐ Active leaks in plumbing
☐ Moisture condensation
☐ Visible stains or water damage
☒ None

125. Ventilation: fresh air intake locations, air filters, etc. (H)**125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?**

- ☒ Yes
☐ No

125b. Is there accumulated dirt, dust or debris around fresh air intakes?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCSIndoor Air Quality

Page Last Modified: 02/16/2022

125c. Are fresh air intakes free of blockage?

- ☒ Yes
☐ No

125d. Is accumulated dirt, dust or debris in ductwork?

- ☒ Yes
☐ No

125e. Are dampers functioning as designed?

- ☒ Yes
☐ No

125f. Condition of air filters:

- ☐ Good
☒ Fair
☐ Poor

125g. Outside air is adequate for occupant load:

- ☐ Yes
☒ No

125h. Rating of ventilation/indoor air quality:

- ☐ Good
☒ Fair
☐ Poor

125i. Comments:

(No Response)

126. Indoor Air Quality (IAQ) Plan (H)**126a. Does the school district use EPA's Tools for Schools program?**

- ☐ Yes
☒ No

126b. If No, is some other IAQ management plan used?

- ☐ Yes
☒ No

126c. Has the District assigned IAQ responsibilities to a designated individual?

- ☒ Yes
☐ No

126c.1 If Yes, what is their job title?

Director of Facilities

127. Does the school practice Integrated Pest Management (IPM)? (H)

- ☒ Yes
☐ No

127a. Is vegetation kept one foot away from the building?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Indoor Air Quality

Page Last Modified: 02/16/2022

127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?

- ☒ Yes
☐ No

127c. Is there a certified pesticide applicator on staff?

- ☐ Yes
☒ No

127d. Are pesticides used in the building?

- ☐ Yes
☒ No

127d.1 If Yes, how are they typically applied?

- ☐ Spot treatment
☐ Area wide treatments

127e. Are pesticides used on the grounds?

- ☐ Yes
☒ No

127e.1 If Yes, was an emergency exemption granted by the Board of Education?

- ☐ Yes
☐ No

**128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?
(H)**

- ☐ Yes
☒ No

128a. Has the facility been tested for the presence of radon?

- ☒ Yes
☐ No

128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- ☐ Yes
☒ No

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

- ☐ Yes, active mitigation system installed
☐ Yes, passive mitigation system made active
☐ Yes, ventilation controls (HVAC) adjusted
☐ Yes, other (describe)
☐ No action taken

128c.1 Describe other actions taken to mitigate elevated radon levels:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bennett ES-BCS

Emergency Shelter

Page Last Modified: 02/16/2022

Emergency Shelter

129. Does this building serve as an emergency shelter?

☐ Yes

☒ No