

FIVE-YEAR CAPITAL FACILITIES PLAN

[illegible]

District Name:		Onteora CSD		<div>ITEM NUMBER LEGEND</div> <div>BLDG BCS# ITEM BCS YR.</div> <div>BG - 067 - 01 - 21 [00 is no BCS #]</div>		<div>SYSTEM TYPE</div> <div>HS - Health & Safety</div> <div>ST - Structure</div> <div>EE - Energy Efficiency</div> <div>AP - Asset Preservation</div>		<div>SYSTEM RATING</div> <div>E - Excellent</div> <div>S - Satisfactory</div> <div>U - Unsatisfactory</div> <div>NF - Non-Functioning</div> <div>CF - Critical Failure</div>		<div>COST TYPE</div> <div>NEW - New Construction</div> <div>ADD - Addition</div> <div>ALT - Alterations</div> <div>MSR - Major System Replacement</div> <div>REP - Repair</div> <div>ENG - Energy</div> <div>MNT - Maintenance</div> <div>Y* - Must be part of larger building project</div>		<div><div><div></div><div></div></div><div>Clark Patterson Lee</div><div>ARCHITECTURE ENGINEERING PLANNING</div></div>			
Facility Name:		Bus Garage													
SED Number:		62-12-01-06-5-004													
Item #	Priority 1-5	System Type	System Rating	Description	Corrective Actions & Comments	Plan / Photo Key	Cost Type	NY State Building Aid Y N	Construction	10% Escalation	20% Incidentals	10% Contingency	PROBABLE BUDGET ALLOCATION		
PRIORITY 4															
BG-067-01-21	4	ST	S	Chimney	Repoint chimney and reset cap.		REP	Y*		\$ 8,000	\$ 800	\$ 1,600	\$ 800	\$ 11,200	
BG-082-02-21	4	HS	S	Doors	Replace doors @ end of useful life (10 leafs)		MSR	Y		\$ 30,000	\$ 3,000	\$ 6,000	\$ 3,000	\$ 42,000	
BG-042-01-21	4	HS	S	Fuel station	Remove and install new fuel station with new tanks, pumps, canopy, and slabs	C3	REP	Y		\$ 472,900	\$ 47,290	\$ 94,580	\$ 47,290	\$ 662,060	
PRIORITY 4 TOTAL										\$ 510,900	\$ 51,090	\$ 102,180	\$ 51,090	\$ 715,260	
PRIORITY 5															
BG-076-01-21	5	AP	U	Carpet	Replace carpet @ end of useful life		REP	Y*		\$ 5,000	\$ 500	\$ 1,000	\$ 500	\$ 7,000	
BG-065-01-21	5	AP	S	Concrete Floor	Concrete floor needs scraping and painting @ select areas		MSR	Y*		\$ 13,000	\$ 1,300	\$ 2,600	\$ 1,300	\$ 18,200	
BG-055-01-21	5	AP	S	Concrete slab	Remove concrete slab in dumpster area and replace with asphalt drive	C1	ALT	Y*		\$ 17,000	\$ 1,700	\$ 3,400	\$ 1,700	\$ 23,800	
BG-042-01-21	5	AP	S	Fence	Remove and install new fence line as needed	C4	REP	Y*		\$ 4,000	\$ 400	\$ 800	\$ 400	\$ 5,600	
PRIORITY 5 TOTAL										\$ 39,000	\$ 3,900	\$ 7,800	\$ 3,900	\$ 54,600	
DISTRICT MAINTENANCE															
DISTRICT MAINTENANCE TOTAL										\$ -	\$ -	\$ -	\$ -	\$ -	
ENERGY PERFORMANCE CONTRACT															
ENERGY PERFORMANCE CONTRACT TOTAL										\$ -	\$ -	\$ -	\$ -	\$ -	
BUILDING TOTAL										\$ 1,997,625	\$ 199,763	\$ 399,525	\$ 199,763	\$ 2,796,675	



(A1) TYPICAL



(A2)



(A3)



(A4) TYPICAL



(A5)



(A6) TYPICAL



(A7) TYPICAL




(A8)







C1



C2



C3



C4

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Information

Page Last Modified: 02/28/2022

Building Information**1. Name of school district**

Onteora CSD

2. SED District 8-Digit BEDS Code

62120106

3. Building Name:

Bus Garage

4. SED 4-Digit Facility Code:

5004

5. Survey Inspection Date:

08/10/2021

6. Building 911 Address:

4166 Route 28

7. City:

Boiceville

8. Zip Code:

12412

9. Certificate of Occupancy Status:

- ☒ A - Annual
☐ T - Temporary
☐ N - None

10. Certificate of Occupancy Expiration Date:

02/01/2023

10a. Is this a manufactured building? (Relocatable, modular, portable)

- ☐ Yes
☒ No

11. Have there been renovations or construction in the building during the past 12 months?

- ☐ Yes
☒ No

12. Was major construction/renovation work since 2015 conducted when school was in session?

- ☐ Yes
☒ No

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)

2,796,675.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Information

Page Last Modified: 02/28/2022

14. Overall building rating (to be answered after the building inspection is complete)

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Failing

15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?

- ☐ Yes
- ☒ No

16. A/E Firm Name:

CPL

17. A/E Firm Address:

50 Front Street, Suite 202, Newburgh, NY 12550

18. A/E Firm Phone Number:

8455676700

19. E-mail:

ccolby@cplteam.com

20. A/E Name:

Christopher Colby

21. A/E License #:

033581

Building Age, Gross Square Footage and Maintenance Staff**22. Building Age**

	Year
Original Construction	1952
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

23. Square feet of construction

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Information

Page Last Modified: 02/28/2022

	Sq Feet
Original construction	5,400.00
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

24. Gross square ft. of Building as currently configured:

5,400

25. Number of Floors:

1

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	0
Part-time custodians:	0
Totals:	0

Building Ownership and Occupancy Status**27. Building Ownership (check one):**

- ☒ Owned and used by district
☐ Owned by District and leased to non-district entity
☐ Owned by District, part used by district, part leased to non-district entity
☐ Owned by non-district entity and leased to district

28. For which of the following purposes is the building currently used? (check all that apply)

- ☐ Used for student instructional purposes
☐ Used for district administration
☒ Used for other district purposes
☐ Used by other organization(s)

28a. Describe use for other district purposes:

Garage/Transportation

Building Users

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Information

Page Last Modified: 02/28/2022

29. How many students were registered to receive instruction in this building as of October 1, 2019? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

0

30. Of these registered students, how many receive most of their instruction in:

	Quantity
Permanent instructional spaces (i.e., regular classrooms)	0
Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
Non-instructional spaces used as instructional spaces	0

31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2019? (check all that apply)

- ☐ Cafeteria
- ☐ Gymnasium
- ☐ Administrative Spaces
- ☐ Library
- ☐ Lobby
- ☐ Stairwell
- ☐ Storage space
- ☐ Other (please describe)
- ☒ None

32. Grades Housed

- | | |
|---------------------------------------|--|
| ☐ Pre-K | ☐ 7th |
| ☐ Kindergarten | ☐ 8th |
| ☐ 1st | ☐ 9th |
| ☐ 2nd | ☐ 10th |
| ☐ 3rd | ☐ 11th |
| ☐ 4th | ☐ 12th |
| ☐ 5th | ☒ N/A (none) |
| ☐ 6th | |

33. For how many instructional days during the 2018-19 school year (July 1 through June 30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

34. Is the building used for instructional purposes in the summer?

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSProgram Spaces

Page Last Modified: 02/17/2022

Program Spaces**35. Number of instructional classrooms:**

0

36. Gross square footage of all instructional classrooms (combined):

0.00

37. Other spaces provided:

- | | | |
|---|---|---|
| ☒ a. N/A (none) | ☐ j. Health Office | ☐ s. Resource Rooms |
| ☐ b. Administration | ☐ k. Home & Careers | ☐ t. Science Labs |
| ☐ c. Art | ☐ l. Kitchen | ☐ u. Special Education |
| ☐ d. Audio Visual | ☐ m. Large Group Instruction | ☐ v. Swimming Pool |
| ☐ e. Auditorium | ☐ n. Library | ☐ w. Teacher Resource |
| ☐ f. Cafeteria | ☐ o. Multipurpose Rooms | ☐ x. Technology/Shop |
| ☐ g. Computer Room | ☐ p. Music | ☐ y. Other (please describe) |
| ☐ h. Guidance | ☐ q. Pre-K | |
| ☐ i. Gymnasium | ☐ r. Remedial Rooms | |

37a. Describe other spaces

(No Response)

Space Adequacy**38. Rating of space adequacy:**

- ☐ Good
☒ Fair
☐ Poor

38a. Enter comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Site Utilities

Page Last Modified: 02/17/2022

SITE UTILITIES**39. Water (H)**

- ☒ Yes
☐ No

39a. Type of Service:

- ☐ Municipal or Utility provided
☒ Well
☐ Other

39b. Types of water service piping

- ☐ Iron
☐ Galvanized
☒ Copper
☐ Lead
☐ PVC
☐ Other
☐ N/A (None)

39c. Overall condition of water service piping

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

39d. Year of Last Major Reconstruction/Replacement:

1952

39e. Expected Remaining Useful Life (Years):

1

39f. Cost to Reconstruct/Replace \$:

3,000.00

39g. Comments:

Install new water service line with accompanied appurtenances; to be done during full depth asphalt removal

40. Site Sanitary (H)

- ☒ Yes
☐ No

40a. Type of Service:

- ☒ Municipal or utility sewer
☐ Site septic
☐ Other

40b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Site Utilities

Page Last Modified: 02/17/2022

40c. Year of Last Major Reconstruction/Replacement:

2010

40d. Expected Remaining Useful Life (Years):

20

40e. Cost to reconstruct/Replace \$:

(No Response)

40f. Comments:

(No Response)

41. Site Gas☐ Yes☒ No**42. Site Fuel Oil**☒ Yes☐ No**42a. Number of Above-Ground Tanks:**

2

42a.1 Capacity of Above-Ground Tanks (gallons):

7,000

42b. Number of Below-Ground Tanks:

1

42b.1 Capacity of Below-Ground Tanks (gallons):

5,000

42c. Condition:☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure☐ N/A**42d. Year of Last Major Reconstruction/Replacement:**

1987

42e. Expected Remaining Useful Life (Years):

5

42f. Cost to Reconstruct/Replace \$:

476,900.00

42g. Comments:

Install new tanks, fence, concrete landing, overhead canopy, and pumping station

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Site Utilities

Page Last Modified: 02/17/2022

43. Site Electrical, Including Exterior Distribution

- ☒ Yes
☐ No

43a. Service Provider:

- ☒ Municipal or utility provided
☐ Self-Generated
☐ Other
☐ N/A

43b. Type of Service:

- ☐ Above Ground
☒ Below Ground
☐ N/A

43c. Condition:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

43d. Year of Last Major Reconstruction/Replacement:

1952

43e. Expected Remaining Useful Life (Years):

0

43f. Cost to Reconstruct/Replace \$:

30,000.00

43g. Comments:

Past useful life. Replace incoming service, transformer, CT cabinet and meter.

SITE FEATURES**44. Closed Drainage Pipe Stormwater Management System****44a. Does this facility have a closed pipe system?**

- ☒ Yes
☐ No

44b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

1952

44d. Expected Remaining Useful Life (Years):

2

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSSite Utilities

Page Last Modified: 02/17/2022

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

Same system as HS/MS

45. Open Drainage Pipe Stormwater Management System**45a. Does this facility have an open stormwater system (ditch)?**☐ Yes☒ No**46. Catch Basins/Drop Inlets/Manholes****46a. Does this facility have catch basins/drop inlets/manholes?**☒ Yes☐ No**46b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**46c. Year of Last Major Reconstruction/Replacement:**

1952

46d. Expected Remaining Useful Life (Years):

3

46e. Cost to Reconstruct/Replace \$:

48,000.00

46f. Comments:

Remove and install catch basins as needed; investigate connecting drainage lines

47. Culverts**47a. Does this facility have culverts?**☐ Yes☒ No**48. Outfalls****48a. Does this facility have outfalls?**☐ Yes☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSSite Utilities

Page Last Modified: 02/17/2022

49. Infiltration Basins/Chambers**49a. Does this facility have infiltration basins/chambers?**

- ☐ Yes
- ☒ No

50. Retention Basins**50a. Does this facility have retention basins?**

- ☐ Yes
- ☒ No

51. Wetponds**51a. Does this facility have wetponds?**

- ☐ Yes
- ☒ No

52. Manufactured Stormwater Proprietary Units**52a. Does this facility have proprietary units?**

- ☐ Yes
- ☒ No

53. Point of Outfall Discharge: (check all that apply)

- ☐ Municipal storm sewer system
- ☐ Combined sewer system
- ☐ Surface Water
- ☐ On-site recharge
- ☐ Other (describe)
- ☒ Not Applicable

54. Outfall Reconnaissance Inventory**Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?**

- ☒ Yes
- ☐ No
- ☐ Not Applicable

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSOther Site Features

Page Last Modified: 02/17/2022

SITE FEATURES**55. Pavement (Roadways and Parking Lots)**

- ☒ Yes
☐ No

55a. Type: (check all that apply)

- ☒ Concrete
☒ Asphalt
☐ Gravel
☐ Other

55b. Condition:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

55c. Year of Last Major Reconstruction/Replacement:

1990

55d. Expected Remaining Useful Life (Years):

1

55e. Cost to Reconstruct/Replace \$:

630,150.00

55f. Comments:

Full depth asphalt removal and heavy duty asphalt installation in whole bus garage area; Remove concrete slab and replace with asphalt

56. Sidewalks

- ☒ Yes
☐ No

56a. Type: (check all that apply)

- ☐ Asphalt
☒ Concrete
☐ Gravel
☐ Paver
☐ Other

56b. Condition:

- ☐ Excellent
☐ Satisfactory
☐ Unsatisfactory
☒ Non-Functioning
☐ Critical Failure

56c. Year of Last Major Reconstruction/Replacement:

1990

56d. Expected Remaining Useful Life (Years):

4

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSOther Site Features

Page Last Modified: 02/17/2022

56e. Cost to Reconstruct/Replace \$:

(No Response)

56f. Comments:

(No Response)

57. Playgrounds and Playground Equipment☐ Yes☒ No**58. Athletic Fields and Play Fields**☐ Yes☒ No**59. Exterior Bleachers / Stadiums**☐ Yes☒ No**60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)**☐ Yes☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Structure

Page Last Modified: 02/24/2022

Building Structure**61. Foundation (S)****61a. Type (check all that apply):**

- ☒ Reinforced Concrete
- ☐ Masonry on Concrete Footing
- ☐ Other (specify)

61a1. If "Other" please specify

(No Response)

61b. Evidence of structural concerns (check all that apply):

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

61c. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

61d. Year of Last Major Reconstruction/Replacement:

1952

61e. Expected Remaining Useful Life (Years):

5

61f. Cost to Reconstruct/Replace \$:

(No Response)

61g. Comments:

(No Response)

62. Piers (S)

- ☐ Yes
- ☒ No

62f. Cost to Reconstruct/Replace \$:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Structure

Page Last Modified: 02/24/2022

63. Columns (S)**Type (check all that apply):**

- ☐ Concrete
- ☒ Masonry
- ☐ Steel
- ☐ Stone
- ☐ Wood
- ☐ Other (specify)
- ☐ N/A (None)

63.1. If "Other" please specify

(No Response)

63a. Evidence of structural concerns (check all that apply)

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

63b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

63c. Year of Last Major Reconstruction/Replacement

1952

63d. Expected Remaining Useful Life (Years):

5

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

(No Response)

64. Footings (S)**Type (check all that apply):**

- ☒ Concrete
- ☐ Other (specify)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Structure

Page Last Modified: 02/24/2022

64a. Evidence of structural concerns (check all that apply)

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other (specify)
- ☒ None

64.a1. If "Other" please specify

(No Response)

64b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

64c. Year of Last Major Reconstruction/Replacement

1952

64d. Expected Remaining Useful Life (Years):

10

64e. Cost to Reconstruct/Replace \$:

(No Response)

64f. Comments:

(No Response)

65. Structural Floors (S)**65a. Type (check all that apply):**

- ☐ Concrete Deck on Wood Structure
- ☐ Concrete/Metal Deck/Metal Joists
- ☐ Cast in Place Concrete Structural System
- ☐ Precast Concrete Structural System
- ☒ Reinforced Concrete Slab on Grade
- ☐ Wood Deck on Wood Trusses
- ☐ Wood Deck on Wood Joists
- ☐ Other (specify)

65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Unsupported Ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously Damaged/Missing Components
- ☐ Other Problems
- ☒ None

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Structure

Page Last Modified: 02/24/2022

65b.1 Describe Other Problems:

(No Response)

65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

65d. Overall Condition of Structural Floors:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

65e. Year of Last Major Reconstruction/Replacement:

1952

65f. Expected Remaining Useful Life (Years):

5

65g. Cost to Reconstruct/Replace \$:

(No Response)

65h. Comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Envelope

Page Last Modified: 02/17/2022

BUILDING ENVELOPE**66. Exterior Walls/Columns (S)****66a. Material (check all that apply):**

- ☐ Aluminum/Glass Curtain Wall
- ☐ Brick
- ☐ Concrete
- ☐ Composite Insulated Panels
- ☒ Masonry
- ☐ Steel
- ☐ Wood
- ☐ Other (specify)

66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

66b.1 Describe Other Problems:

(No Response)

66c. Evidence of Concerns with Exterior Cladding (check all that apply):

- ☒ Cracks/Gaps
- ☐ Inadequate Flashing
- ☐ Efflorescence
- ☐ Moisture Penetration
- ☒ Rot/Decay/Corrosion
- ☐ Other Problems
- ☐ None

66c.1 Describe Other Problems:

(No Response)

66d. Overall Condition of Exterior Walls/Columns:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

66e. Year of Last Major Reconstruction/Replacement:

1952

66f. Expected Remaining Useful Life (Years):

5

66g. Cost to Reconstruct/Replace \$:

90,000.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Envelope

Page Last Modified: 02/17/2022

66h. Comments:

Building requires re-pointing of brick. Block retaining wall entrance needs to be re-set.

67. Chimneys (S)

- ☒ Yes
☐ No

67a. Material (check all that apply):

- ☒ Masonry
☐ Concrete
☐ Metal
☐ Wood
☐ Other

67a.1 Specify other:

(No Response)

67b. Overall Condition of Chimneys:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical failure

67c. Year of Last Major Reconstruction/Replacement:

1952

67.d Expected Remaining Useful Life (Years):

0

67e. Cost to Reconstruct/Replace \$:

8,000.00

67f. Comments:

Re-point chimney, re-set cap.

68. Parapets (S)

- ☐ Yes
☒ No

69. Exterior Doors**69a. Overall Condition of Exterior Door Units:**

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

69b. Do any exterior doors have magnetic locking devices?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Envelope

Page Last Modified: 02/17/2022

69c. Safety/Security features are adequate?

- ☒ Yes
☐ No

69d. Year of Last Major Reconstruction/Replacement:

1952

69e. Expected Remaining Useful Life (Years):

0

69f. Cost to Reconstruct/Replace \$:

5,000.00

69g. Comments:

Replace passage doors

70. Exterior Steps, Stairs, Ramps (S)

- ☐ Yes
☒ No

71. Fire Escapes (S)**71a. Does This Facility Have One or More Fire Escapes?**

- ☐ Yes
☒ No

72. Windows

- ☒ Yes
☐ No

72a. Window Material: (check all that apply)

- ☒ Aluminum
☒ Steel
☐ Vinyl
☐ Solid Wood
☐ Wood w/ External Cladding System
☐ Other

72a1. If "Other" please specify

(No Response)

72b. Overall Condition of Windows:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Envelope

Page Last Modified: 02/17/2022

72c. All Rescue Windows are Operable:

- ☐ Yes
- ☐ No
- ☒ N/A

72d. Year of Last Major Reconstruction/Replacement:

1952

72e. Expected Remaining Useful Life (Years):

0

72f. Cost to Reconstruct/Replace \$:

115,000.00

72g. Comments:

replace original building windows

73. Roof and Skylights (S)

- ☒ Yes
- ☐ No

73a. Type of roof construction (check all that apply):

- ☐ Concrete on metal deck on metal trusses/joists
- ☐ Concrete (poured or plank) on concrete beams
- ☐ Gypsum (poured or plank) on metal trusses/joists
- ☒ Metal deck on metal trusses/joists
- ☐ Wood deck on wood trusses/joists
- ☐ Wood deck on metal trusses/joists
- ☐ Tectum on metal trusses/joists
- ☒ Other (describe below)

73a.1 Other roof construction type:

(No Response)

73b. Type of roofing material (check all that apply):

- ☒ Single-ply membrane
- ☐ Built-up
- ☐ Asphalt shingle
- ☒ Pre-formed metal
- ☐ IRMA
- ☐ Slate
- ☐ Fluid applied seamless surfacing
- ☐ Other (describe below)

73b.1 Other roofing material:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Envelope

Page Last Modified: 02/17/2022

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- ☐ Structural cracks
- ☐ Unsupported ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously damaged/missing components
- ☐ Other concerns (describe)
- ☒ None

73c.1 Describe other concerns:

(No Response)

73d. Evidence of structural concerns with roof deck (check all that apply):

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

73e. Does this facility have skylights?

- ☐ Yes
- ☒ No

73f. Skylight material (check all that apply):

- ☐ Plastic
- ☐ Glass
- ☐ Other
- ☒ N/A

73g. Overall condition of skylights:

- ☐ Excellent
- ☐ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- ☒ Failures/Splits/Cracks
- ☒ Rot/Decay/Corrosion
- ☒ Inadequate flashing/curbs/pitch pockets
- ☒ Inadequate or poorly functioning roof drains
- ☒ Evidence of water penetration/active leaks
- ☐ Other (specify)
- ☐ None

73h.1 Specify other concerns:

(No Response)

73i. Overall Condition of Roof and Skylights:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Envelope

Page Last Modified: 02/17/2022

73j. Year of Last Major Reconstruction/Replacement:

1990

73k. Expected Remaining Useful Life (Years):

0

73l. Cost to Reconstruct/Replace \$:

170,000.00

73m. Comments:

Replace existing EPDM roof. Re-coat metal roof, repair damaged gutters.

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Interiors

Page Last Modified: 02/17/2022

BUILDING INTERIOR**74. Interior Bearing Walls and Fire Walls (S)**

- ☒ Yes
☐ No

74a. Overall condition of interior bearing walls and fire walls:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical Failure

74b. Year of Last Major Reconstruction/Replacement:

1952

74c. Expected Remaining Useful Life (Years):

5

74d. Cost to Reconstruct/Replace \$:

(No Response)

74e. Comments:

(No Response)

75. Other Interior Walls

- ☒ Yes
☐ No

75a. Overall condition of other interior walls:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

1952

75c. Expected Remaining Useful Life (Years):

5

75d. Cost to Reconstruct/Replace \$:

(No Response)

75e. Comments:

(No Response)

76. Carpet

- ☒ Yes
☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Interiors

Page Last Modified: 02/17/2022

76a. Where located (check all that apply):

- ☐ Classrooms
- ☒ Corridors
- ☒ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Other Areas

76b. Condition:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

76c. Year of Last Major Reconstruction/Replacement:

1980

76d. Expected Remaining Useful Life (Years):

0

76e. Cost to Reconstruct/Replace \$:

5,000.00

76f. Comments:

Beyond useful life

77. Resilient Tiles or Sheet Flooring

- ☒ Yes
- ☐ No

77a. Where located (check all that apply):

- ☐ Classrooms
- ☒ Corridors
- ☒ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Other Areas

77b. Overall condition of resilient tiles or sheet flooring:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

1952

77d. Expected Remaining Useful Life (Years):

0

77e. Cost to Reconstruct/Replace \$:

18,000.00

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Interiors

Page Last Modified: 02/17/2022

77f. Comments:

Replace VAT flooring

78. Hard Flooring (concrete; ceramic tile; stone; etc)

- ☒ Yes
☐ No

78a. Where located (check all that apply):

- ☐ Classrooms
☐ Corridors
☐ Offices
☒ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
☐ Kitchen
☐ Locker Rooms/Toilet Rooms
☐ Other Areas

78b. Overall condition of hard flooring:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

78c. Year of Last Major Reconstruction/Replacement:

1952

78d. Expected Remaining Useful Life (Years):

0

78e. Cost to Reconstruct/Replace \$:

(No Response)

78f. Comments:

Concrete floor needs scraping and painting in select areas at end of 2015 term.

79. Wood Flooring

- ☐ Yes
☒ No

80. Ceilings (H)

- ☒ Yes
☐ No

80a. Overall condition of ceilings:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

80b. Year of Last Major Reconstruction/Replacement:

1952

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Building Interiors

Page Last Modified: 02/17/2022

80c. Expected Remaining Useful Life (Years):

0

80d. Cost to Reconstruct/Replace \$:

15,000.00

80e. Comments:

Replace ceiling in office area (ACT) - past useful life.

81. Lockers

☐ Yes

☒ No

81d. Cost to Reconstruct/Replace \$:

(No Response)

82. Interior Doors

☒ Yes

☐ No

82a. Overall condition of interior door units:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

82b. Overall condition of interior door hardware:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

1952

82d. Expected Remaining Useful Life (Years):

2

82e. Cost to Reconstruct/Replace \$:

30,000.00

82f. Comments:

Doors have reached end of useful life. Provide panic hardware to exit doors.

83. Interior Stairs (H)

☒ Yes

☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSBuilding Interiors

Page Last Modified: 02/17/2022

83a. Overall condition of interior stairs:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

83b. Stair material

- ☒ Concrete
- ☐ Steel
- ☐ Wood
- ☐ Other

83c. Year of Last Major Reconstruction/Replacement:

1952

83d. Expected Remaining Useful Life (Years):

0

83e. Cost to Reconstruct/Replace \$:

(No Response)

83f. Comments:

(No Response)

84. Elevator, Lift, and Escalators (H)

- ☐ Yes
- ☒ No

85. Swimming Pool and Swimming Pool Systems (H)

- ☐ Yes
- ☒ No

86. Interior Bleachers

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

HVAC Systems

Page Last Modified: 02/24/2022

HVAC Systems

87. Heat Generating Systems (H)

- ☒ Yes
☐ No

87a. Heat generation source (check all that apply):

- ☐ Biomass
☒ Boiler / Hot Water
☐ Boiler / Steam
☐ Cogeneration Plant
☐ Electric
☐ Furnace / Forced Air
☐ Geothermal
☐ Heat Pump
☐ Unit Ventilation
☐ Other (describe below)

87a.1 Other heat generation source:

(No Response)

87b. Overall condition of heat generating systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2012

87d. Expected Remaining Useful Life (Years):

10

87e. Cost to Reconstruct/Replace \$:

(No Response)

87f. Comments:

(No Response)

88. Ventilation System (exhaust fans, etc) (H)

- ☒ Yes
☐ No

88a. Type of ventilation system (check all that apply)

- | | |
|--|---|
| ☐ Natural ventilation | ☐ Heat pump |
| ☐ Central system | ☐ Split system/ variable refrigerant |
| ☐ Energy recovery ventilator | ☒ Powered relief air system |
| ☐ Rooftop units | ☐ Gravity/barometric relief |
| ☒ Unitary (UVs, FC/BC, PTAC) | ☐ Other (specify) |
| ☐ Forced air furnace | |

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

HVAC Systems

Page Last Modified: 02/24/2022

88b. If "Other" please specify here

(No Response)

88c. Overall condition of ventilation systems

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical Failure

88d. Year of last major reconstruction/replacement

2012

88e. Expected remaining useful life (years):

0

88f. Cost to reconstruct/replace \$:

(No Response)

88g. Comments

(No Response)

89. Mechanical Cooling / Air-Conditioning Systems

- ☐ Yes
- ☒ No

90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc. (H)

- ☒ Yes
- ☐ No

90a. Overall condition of piped heating and cooling distribution systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2012

90c. Expected Remaining Useful Life (Years):

0

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSHVAC Systems

Page Last Modified: 02/24/2022

91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

- ☒ Yes
☐ No

91a. Overall condition of ducted heating and cooling distribution systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

1978

91c. Expected Remaining Useful Life (Years):

0

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSPlumbing Systems

Page Last Modified: 02/17/2022

PLUMBING**93. Water Supply System (H)**

- ☒ Yes
☐ No

93a. Types of pipes (check all that apply):

- ☐ Asbestos/transite
☒ Copper
☐ Galvanized
☐ Iron
☐ Lead
☐ PVC/CPVC/PEX/Plastic
☐ Other (specify)

93b. If "Other" please specify here

(No Response)

93c. Overall condition of water supply system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

93d. Year of Last Major Reconstruction/Replacement:

1978

93e. Expected Remaining Useful Life (Years):

0

93f. Cost to Reconstruct/Replace \$:

(No Response)

93g. Comments:

(No Response)

94. Sanitary System (H)

- ☒ Yes
☐ No

94a. Types of pipes (check all that apply):

- ☒ Iron
☐ Galvanized
☐ Copper
☐ Glass/ceramic
☐ PVC/CPVC/ABS/poly propylene/plastic
☐ Lead
☐ Other (specify)

94a1. If "Other" please specify

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSPlumbing Systems

Page Last Modified: 02/17/2022

94b. Types of special sanitary systems (Check all that apply)

- ☐ Acid waste and vent
- ☐ Grease interceptor
- ☐ Oil separator
- ☐ Pumping station
- ☐ Sediment trap
- ☐ Septic tank
- ☐ Waste water treatment plant

94c. Overall condition of sanitary system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

2010

94e. Expected Remaining Useful Life (Years):

20

94f. Cost to Reconstruct/Replace \$:

(No Response)

94g. Comments:

(No Response)

95. Storm Water Drainage System (H)

- ☒ Yes
- ☐ No

95a. Types of pipes (check all that apply)

- ☒ Iron
- ☐ Galvanized
- ☐ Copper
- ☐ Lead
- ☐ Plastic
- ☐ Other

95a1. If "Other" please specify

(No Response)

95b. Overall condition of storm water drainage system

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

95c. Year of Last Major Reconstruction/Replacement

1978

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Plumbing Systems

Page Last Modified: 02/17/2022

95d. Expected Remaining Useful Life (Years)

0

95e. Cost to Reconstruct/Replace \$:

(No Response)

95f. Comments:

(No Response)

96. Hot Water Heaters (H)☒ Yes☐ No**96a. Type of fuel (check all that apply):**

- ☒ Oil
- ☐ Natural Gas
- ☐ Electricity
- ☐ Propane
- ☐ Other (specify)

96b. If "Other" please specify

(No Response)

96c. Overall condition of hot water heaters:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

96d. Year of Last Major Reconstruction/Replacement:

1998

96e. Expected Remaining Useful Life (Years):

0

96f. Cost to Reconstruct/Replace \$:

(No Response)

96g. Comments:

(No Response)

97. Plumbing Fixtures (H)☒ Yes☐ No**97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Plumbing Systems

Page Last Modified: 02/17/2022

97b. Year of Last Major Reconstruction/Replacement:

1978

97c. Expected Remaining Useful Life (Years):

0

97d. Cost to Reconstruct/Replace \$:

(No Response)

97e. Comments:

(No Response)

98. Water Outlets/Taps for Drinking/Cooking Purposes (H)

☐ Yes

☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Fire Suppression Systems

Page Last Modified: 02/17/2022

Fire Suppression Systems

99. Fire Suppression System (H)

☐ Yes

☒ No

100. Kitchen Hoods (H)

☐ Yes

☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Electrical Systems

Page Last Modified: 02/17/2022

ELECTRICAL SYSTEMS**101. Electrical Power Distribution System (H)**

- ☒ Yes
☐ No

101a. Electrical supply meets current needs:

- ☒ Yes
☐ No

101b. Condition of electrical power distribution system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

101c. Year of last major reconstruction/replacement?

2010

101d. Expected remaining useful life (years):

5

101e. Cost to reconstruct/replace:

75,000.00

101f. Comments:

Replace all panels

102. Lighting Fixtures (H)

- ☒ Yes
☐ No

102a. Condition of lighting figures:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

102b. Year of last major reconstruction/replacement:

2014

102c. Expected remaining useful life (years):

15

102d. Cost to reconstruct/replace:

(No Response)

102e. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSElectrical Systems

Page Last Modified: 02/17/2022

103. Emergency/ Exit Lighting Systems (H):

- ☒ Yes
☐ No

103a. Overall condition of emergency/exit lighting systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

103b. Year of last major reconstruction/replacement:

2014

103c. Expected remaining useful life (years):

15

103d. Cost to reconstruct/replace:

10,000

103e. Comments

Provide additional emergency/exit light as necessary

104. Emergency or standby power system (H)

- ☐ Yes
☒ No

105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)

- ☒ Yes
☐ No

105a. Overall condition of fire alarm system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

105b. Year of last major reconstruction/replacement:

2011

105c. Expected remaining useful life (years):

5

105d. Cost to reconstruct/replace:

35,000

105e. Comments

Replace to bring up to code

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSElectrical Systems

Page Last Modified: 02/17/2022

106. Carbon Monoxide Alarm System (H)

- ☒ Yes
☐ No

106a. Type of alarm system:

- ☒ 10-year battery stand alone alarm
☐ hardwired/interconnected detection and alarm
☐ gas detection (eg NG/CO)
☐ Other (specify)

106b. If "Other" please specify

(No Response)

106c. Overall condition of carbon monoxide alarm system:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure

106d. Year of last major reconstruction/replacement:

2014

106e. Expected remaining useful life (years):

0

106f. Cost to reconstruct/replace:

2,500.00

106g. Comments

Provide hardwired device to fire alarm system

107. Communication Systems (H)

- ☒ Yes
☐ No

107a. Type of communication system (check all that apply)

- ☒ Public Address
☐ Phones (VOIP)
☐ Phones (Cellular)
☒ Phones (other)
☐ Mass Notification
☐ Emergency voice communication fire alarm system
☐ Lockdown notification system
☐ Other (eg. radio) (describe below)

107b. If "Other" please describe

(No Response)

107c. Communication systems are adequate:

- ☒ Yes
☐ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSElectrical Systems

Page Last Modified: 02/17/2022

107d. Condition of communication system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure

107e. Year of last major reconstruction/replacement:

2011

107f. Expected remaining useful life:

10

107g. Cost to replace/reconstruct:

(No Response)

107h. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSStudent Transportation Facilities

Page Last Modified: 02/24/2022

Student Transportation Facilities**108. Is this building a transportation facility**

- ☒ Yes
☐ No

108a. Type of transportation facility

- ☒ Bus/vehicle maintenance facility
☒ Bus storage facility

109. Does this facility have a fuel dispensing system?

- ☒ Yes
☐ No

109a. Overall condition of fuel dispensing system

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure
☐ N/A

109b. Year of last major reconstruction/replacement

1987

109c. Expected remaining useful life (years):

5

109d. Cost to reconstruct/replace:

(No Response)

109e. Comments

(No Response)

110. Does this facility have vehicle lifts

- ☒ Yes
☐ No

110a. Overall condition of vehicle lifts

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-functioning
☐ Critical failure
☐ N/A

110b. Year of last major reconstruction/replacement

1952

110c. Expected remaining useful life (years):

5

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Student Transportation Facilities

Page Last Modified: 02/24/2022

110d. Cost to reconstruct/replace:

(No Response)

110e. Comments

(No Response)

111. Does this facility have a bus wash system?

☐ Yes

☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSAccessibility

Page Last Modified: 02/17/2022

ACCESSIBILITY**112. Exterior Accessible Route to Building (H)**

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- ☐ Yes
☒ No

112a. Features provided for exterior accessible route (check all that apply)

- ☐ Curb ramps
☐ Exterior ramps
☒ Handicap parking

112b. Cost of improvements needed to provide exterior accessible route to building \$:

(No Response)

112c. Comment

(No Response)

113. Is there an exterior accessible route to recreational facilities?

- ☐ Yes
☒ No

113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:

(No Response)

113b. Comments

(No Response)

114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that apply)

- ☐ Playground and play equipment
☐ Playfield(s)
☐ Athletic Field(s)
☐ Exterior Bleachers
☐ Bathroom Facilities
☐ Concession Stand

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

(No Response)

114b. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSAccessibility

Page Last Modified: 02/17/2022

115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

- ☐ Yes
☒ No

115a. Cost of improvements needed to provide interior accessible route(s) as specified above \$:

57,500

115b. Comments

No ADA bathrooms, office area at "stepped" up level, no clear exterior/interior path.

116. Does this facility have interior spaces that meet accessibility standards (check all that apply)

- ☐ Classrooms
☐ Labs (science, art, technology, etc)
☐ Shops
☐ Main Office
☐ Health Office
☐ Gymnasium
☐ Cafeteria
☐ Auditorium
☐ Stage
☒ Restrooms on each floor

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

116b. Comments

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSEnvironment/Comfort/Health

Page Last Modified: 02/17/2022

ENVIRONMENT/COMFORT/HEALTH**117. General Appearance****117a. Overall Rating:**

- ☐ Good
- ☒ Fair
- ☐ Poor

117b. Comments:

(No Response)

118. Cleanliness (H)**118a. Overall Rating:**

- ☐ Good
- ☒ Fair
- ☐ Poor

118b. Comments:

(No Response)

119. Are there walk off mats; grills in the entryway?

- ☒ Yes
- ☐ No

119a. If yes: at least 6 feet long?

- ☒ Yes
- ☐ No

120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)

- ☐ Yes
- ☒ No

121. Lighting Quality (H):**121a. Types of lighting in general purpose classrooms (check all that apply):**

- ☒ Daylight (natural)
- ☐ Not full spectrum
- ☐ Full spectrum
- ☒ LED
- ☐ Flourescent
- ☐ Other (describe)

121b. Are there blinds in the classroom to prevent glare?

- ☐ Yes
- ☒ No

121c. Overall Rating:

- ☒ Good
- ☐ Fair
- ☐ Poor

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSEnvironment/Comfort/Health

Page Last Modified: 02/17/2022

121d. Comments:

(No Response)

122. Evidence of Vermin (H)**122a. Is there evidence of active infestations of...(check all that apply)?**

- ☐ Rodents
- ☐ Wood-boring or Wood-eating Insects
- ☐ Cockroaches
- ☐ Other Vermin
- ☒ None

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Indoor Air Quality

Page Last Modified: 02/24/2022

Indoor Air Quality

123. Mold (H)

123a. Is there visible mold or moldy odors?

- ☒ Yes
☐ No

123a.1. If yes, where? (check all that apply)

- | | |
|---|--|
| ☐ Classrooms | ☐ Locker rooms |
| ☐ Hallways | ☐ Labs |
| ☐ Ventilation system | ☐ Workshops |
| ☐ Toilet rooms | ☐ Offices |
| ☐ Cafeteria | ☐ Storage |
| ☐ Kitchen | ☐ Crawl space |
| ☐ Auditorium | ☐ Attic |
| ☐ Gymnasium | ☐ Other places (describe) |

123a.2 Describe other:

(No Response)

123b. Are any surfaces constructed of any of the following materials?

- ☒ Paper-faced or gypsum products
☒ Cellulose products (typically ceiling tiles)

123c. Is there evidence of water intrusion?

- ☐ Yes
☒ No

123d. Estimated cost of necessary improvements \$:

(No Response)

123e. Comments:

(No Response)

124. Humidity/Moisture (H)

124a. Overall rating of humidity/moisture condition in building:

- ☐ Good
☒ Fair
☐ Poor

124b. Are any of the following found in/or around classroom areas (check all that apply)?

- ☐ Active leaks in roof
☐ Active leaks in plumbing
☐ Moisture condensation
☐ Visible stains or water damage
☒ None

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSIndoor Air Quality

Page Last Modified: 02/24/2022

124c. Are any of the following found in/or around other areas (check all that apply)?

- ☒ Active leaks in roof
- ☐ Active leaks in plumbing
- ☐ Moisture condensation
- ☐ Visible stains or water damage
- ☐ None

125. Ventilation: fresh air intake locations, air filters, etc. (H)**125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?**

- ☐ Yes
- ☒ No

125b. Is there accumulated dirt, dust or debris around fresh air intakes?

- ☐ Yes
- ☒ No

125c. Are fresh air intakes free of blockage?

- ☒ Yes
- ☐ No

125d. Is accumulated dirt, dust or debris in ductwork?

- ☐ Yes
- ☒ No

125e. Are dampers functioning as designed?

- ☒ Yes
- ☐ No

125f. Condition of air filters:

- ☐ Good
- ☒ Fair
- ☐ Poor

125g. Outside air is adequate for occupant load:

- ☐ Yes
- ☒ No

125h. Rating of ventilation/indoor air quality:

- ☐ Good
- ☒ Fair
- ☐ Poor

125i. Comments:

(No Response)

126. Indoor Air Quality (IAQ) Plan (H)**126a. Does the school district use EPA's Tools for Schools program?**

- ☐ Yes
- ☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Indoor Air Quality

Page Last Modified: 02/24/2022

126b. If No, is some other IAQ management plan used?

- ☒ Yes
☐ No

126c. Has the District assigned IAQ responsibilities to a designated individual?

- ☒ Yes
☐ No

126c.1 If Yes, what is their job title?

(No Response)

127. Does the school practice Integrated Pest Management (IPM)? (H)

- ☒ Yes
☐ No

127a. Is vegetation kept one foot away from the building?

- ☐ Yes
☒ No

127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?

- ☒ Yes
☐ No

127c. Is there a certified pesticide applicator on staff?

- ☐ Yes
☒ No

127d. Are pesticides used in the building?

- ☐ Yes
☒ No

127d.1 If Yes, how are they typically applied?

- ☐ Spot treatment
☐ Area wide treatments

127e. Are pesticides used on the grounds?

- ☐ Yes
☒ No

127e.1 If Yes, was an emergency exemption granted by the Board of Education?

- ☐ Yes
☐ No

128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)? (H)

- ☐ Yes
☒ No

128a. Has the facility been tested for the presence of radon?

- ☒ Yes
☐ No

128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- ☐ Yes
☒ No

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCSIndoor Air Quality

Page Last Modified: 02/24/2022

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

- ☐ Yes, active mitigation system installed
- ☐ Yes, passive mitigation system made active
- ☐ Yes, ventilation controls (HVAC) adjusted
- ☐ Yes, other (describe)
- ☐ No action taken

128c.1 Describe other actions taken to mitigate elevated radon levels:

(No Response)

2021 BUILDING CONDITION SURVEY - 2021 Building Condition Survey - Bus Garage-BCS

Emergency Shelter

Page Last Modified: 02/17/2022

Emergency Shelter

129. Does this building serve as an emergency shelter?

☐ Yes

☒ No