

AHERA THREE YEAR RE-INSPECTION LOG



LEA NAME:		Brownsville ISD					
SCHOOL BUILDING NAME:		Garden Park Elementary School					
ADDRESS:		855 Military Highway					
DATE:		05-01-2023					
HA No.	Material Type / Description	Material Location	Condition	Friability	Category	Classification	Results
001	12" x 12" Floor Tile with mastic White and Blue specks	Main Office and Amendment area	Good	Non-Friable	5	Miscellaneous	Presumed ACM
002	12" x 12" Floor Tile with mastic White and Brown specks	Library	Good	Non-Friable	5	Miscellaneous	Presumed ACM
003	12" x 12" Floor Tile with mastic Blue w/White speck	Cafeteria	Good	Non-Friable	5	Miscellaneous	Presumed ACM
004	12" x 12" Floor Tile with mastic Grey & White specks	Rm: 212-232	Good	Non-Friable	5	Miscellaneous	Presumed ACM
005	12" x 12" Floor Tile with mastic Grey & White specks	Rm: 210-201	Good	Non-Friable	5	Miscellaneous	Presumed ACM
006	Floor with mastic White Vinyl Floor	Pre-k to 1st grade	Good	Non-Friable	5	Miscellaneous	Presumed ACM
007	12" x 12" Floor Tile with mastic Brown and White Tile	Pre-k to 1st grade Hallway	Good	Non-Friable	5	Miscellaneous	Presumed ACM
008	12" x 12" Floor Tile with mastic Grey W/White Specks	Special Ed Building Rm: 303,304,305	Good	Non-Friable	5	Miscellaneous	Presumed ACM
201	12" x 12"	Throughout School	Good	Friable	5	Miscellaneous	Presumed ACM

AHERA THREE YEAR RE-INSPECTION LOG



	Ceiling Tile and Mastic Large Holes – Peg Board						
202	4'x 6' Ceiling Tile White & Brown Fiber Board	Rm: 303,304,305	Good	Friable	5	Miscellaneous	Presumed ACM
300	HVAC Mastic White	Throughout School	Good	Non-Friable	5	Miscellaneous	Presumed ACM
400	Sheet Rock and Joint Compound	Throughout School	Good	Non-Friable	5	Surfacing	Presumed ACM
401	Cinder Block White	Rm: 303,304,305. Rm201-210, Cafeteria	Good	Non-Friable	5	Miscellaneous	Non-Asbestos

Category:	1 Damaged/significantly damaged thermal insulation, 2 Damaged friable surfacing 3 Significantly damaged friable surfacing 4 Damaged/Significantly damaged friable miscellaneous 5 Potential for damage 6 Potential for significant damage 7 Remaining ACBM
Inspector Name	Eloy Palacios
Signature:	
Date:	5.31.23
Accreditation:	Asbestos Consultant 105727
PREVENTATIVE MEASURES (to keep undamaged from becoming damaged)	
Do not subject material to cutting, drilling, grinding, abrading, or burning. Prevent further damage by protecting from impact or vibration. Minimize entry to area by personnel.	
RESPONSE ACTIONS:	
Follow response action section of the management plan for maintenance activities. Follow response action section of the management plan for renovation and remodeling activities. Follow response action section of the management plan for emergency response procedures.	