

AHERA THREE YEAR RE-INSPECTION LOG



LEA NAME:		Brownsville ISD					
SCHOOL BUILDING NAME:		Aiken Elementary School					
ADDRESS:		6290 Southmost Blvd.					
DATE:		05-01-2023					
HA No.	Material Type / Description	Material Location	Condition	Friability	Category	Classification	Results
001	12" x 12" Floor Tile with mastic Beige / Grey specks	Main Office	Good	Non-Friable	5	Miscellaneous	Presumed ACM
002	12" x 12" Floor Tile with mastic Beige / White	Reception Area and Hallway	Good	Non-Friable	5	Miscellaneous	Presumed ACM
003	12" x 12" Floor Tile with mastic White / Grey specks	Admin. Offices	Good	Non-Friable	5	Miscellaneous	Presumed ACM
004	12" x 12" Floor Tile with mastic Off White / Blue specks	Throughout Classrooms 1st and 2nd Floors, Teacher Lounge, Music room	Good	Non-Friable	5	Miscellaneous	Presumed ACM
005	12" x 12" Floor Tile with mastic Beige	Library	Good	Non-Friable	5	Miscellaneous	Presumed ACM
006	12" x 12" Floor Tile with mastic Beige / Multi Color	Cafeteria	Good	Non-Friable	5	Miscellaneous	Presumed ACM
007	12" x 12" Floor Tile with mastic Beige / Green specks	Portables A1, A2, A3 and A4	Good	Non-Friable	5	Miscellaneous	Presumed ACM
101	2' x 2' Ceiling Tile Small Fissure, Small Hole	Throughout Halls, Classrooms and Portables	Good	Friable	5	Miscellaneous	Presumed ACM
201	Chalkboard Mastic Black or Green	Throughout Classrooms 1st and 2nd Floors	Good	Non-Friable	5	Miscellaneous	Presumed ACM
202	Stainless Steel Sink Undercoating/White	Throughout Classrooms 1st and 2nd Floors	Good	Non-Friable	5	Miscellaneous	Presumed ACM
204	Stage Curtains Stage Curtains / Blue	Cafeteria	Good	Non-Friable	5	Miscellaneous	Presumed ACM
205	Cove Base Brown	Throughout Classrooms	Good	Non-Friable	5	Miscellaneous	Presumed ACM
301	Pipe Insulation	Throughout School above drop Ceiling	Good	Friable	5	TSI	Presumed ACM
302	HVAC Mastic Grey Mastic	Throughout AC Duct	Good	Non-Friable	5	TSI	Presumed ACM
303	Tank Insulation Black Foam Insulation	*No Location noted, will check in Boiler Rooms and Pipe Chase	Good	Non-Friable	5	TSI	Presumed ACM

AHERA THREE YEAR RE-INSPECTION LOG



401	Sheet Rock and Joint Compound	Throughout School and Portables	Good	Friable	5	Surfacing	Presumed ACM
402	Cinder Block White	Throughout School	Good	Non-Friable	5	Surfacing	Non-Asbestos

Category:	1 Damaged/significantly damaged thermal insulation, 2 Damaged friable surfacing 3 Significantly damaged friable surfacing 4 Damaged/Significantly damaged friable miscellaneous 5 Potential for damage 6 Potential for significant damage 7 Remaining ACBM
Inspector Name	Eloy Palacios
Signature:	
Date:	5.31.23
Accreditation:	Asbestos Consultant 105727
PREVENTATIVE MEASURES (to keep undamaged from becoming damaged)	
Do not subject material to cutting, drilling, grinding, abrading, or burning. Prevent further damage by protecting from impact or vibration. Minimize entry to area by personnel.	
RESPONSE ACTIONS:	
Follow response action section of the management plan for maintenance activities. Follow response action section of the management plan for renovation and remodeling activities. Follow response action section of the management plan for emergency response procedures.	