Lompoc Unified School District

MASTER PLAN 2023-2028






Table of Contents

- Table of Contents
- Introduction
- Executive Summary
- Master Plan Approach
- District Facility Goals
- Adopted Board of Education Goals
- Acknowledgments
- Common Site Design Items
- List of Current Projects
- District Schools and Addresses
- Elementary School Sites
 - Buena Vista Elementary School
 - Clarence Ruth Elementary School
 - Crestview Elementary School
 - Fillmore Elementary School
 - Hapgood Elementary School
 - La Canada Elementary School
 - La Honda Elementary School
 - Los Berros Elementary School
 - Miguelito Elementary School
- Middle School Sites
 - Lompoc Valley Middle School
 - Vandenberg Middle School
- High School Sites
 - Cabrillo High School
 - Lompoc High School
 - o Maple High School



LOMPOC UNIFIED SCHOOL DISTRICT **FIVE YEAR MASTER PLAN**

2023-2028

- Other Schools
 - Lompoc Adult School (Previously El Camino Middle School)
 - o Forinash Community Day School
 - o Mission Valley
 - Martha Negas Orthopedic Center
- **Education Center Complex**
- Campus Data Sheets and Maps
- **Principal Meeting Minutes**
- Cost Estimates

EXHIBITS

- A. Agenda for Site Principal Interviews
- B. Portable Inventory
- C. Tremco Roofing Report Summary
 D. P.E.I. Paving Report Summary

Introduction

A Facilities Master Plan uses District data to provide a comprehensive study of facility needs. The Facilities Master Plan creates a document to be used for continuous planning of educational facilities that will meet the changing needs of the community. Information regarding the existing buildings, sites and enrollment is recorded and evaluated.

The Master Plan will assist the District with planning decisions about the future classroom modernizations, new facilities and maintenance projects.

The purpose of the plan is to define a method to provide school facilities that accommodate current and future educational programs. This plan is a "guide" for assessing the need for facility improvements and investments needed to implement the improvements.

The Facilities Master Plan is to be a living document that can be updated periodically as enrollment projections are updated and educational goals are changed. The planning process prioritizes facility needs and provides a roadmap for providing the educational needs.

Lompoc Unified School District Facts

- The Lompoc Unified School District offers an outstanding educational program for its 9,800 students. Quality leadership, teaching and support staff are just some of the reasons. The District serves K-12 students living in the City of Lompoc, Vandenberg Village, Mesa Oaks, Mission Hills, Vandenberg Air Force Base, and rural areas adjacent to these. The District offers a wide range of programs for students with special needs. These are opportunity classes at the middle and high school levels. There are specialists at all levels who provide support for bilingual children, migrant children, gifted, and handicapped children. The District has created an atmosphere of cooperation and collaboration at all levels. Win-win negotiations and problem solving have become institutionalized.
- Community: Lompoc is located 150 miles northwest of Los Angeles in Santa Barbara County. Its population is approximately 40,000 and the area is noted for its mild, smogfree climate. The average maximum temperature is 73 degrees, and the average winter high temperature is 63 degrees. Lompoc is the support city for Vandenberg Air Force Base, the aerospace center of the West Coast. Lompoc is also known as the flower seed capital of the world, as it produces more than half of the world's supply of flower seeds. Learn more about the Lompoc Community by visiting the Lompoc Valley Chamber Commerce website.

Executive Summary

BACKGROUND

Lompoc Unified School District began educating students around 1874. Historical documents state that Mrs. Whitlock opened the first school and taught seven children. The name and location of the school are uncertain.

The first Public School:

Public schooling was first recorded in the Lompoc District through a document stating that 20 citizens pledged \$60 for building repairs needed to start a new school. The first school was opened by Rev. J.W. Webb on May 3, 1875, and was located at the northeast corner of H Street and Walnut Avenue.

Current times:

The January 10 Board Meeting Enrollment Report lists a total K-12 of 9,033.

That is based on the Fourth School Month (November 7 to December 2, 2022) and lists the following:

- Elementary 4,682
- Middle 1,377
- High Schools (including Independent Study) 2,839
- Forinash CDS, Adult Transition Program, Mission Valley, Non-Public School, and private 135

PURPOSE

The Lompoc Unified School encompasses the city of Lompoc, Vandenberg Village, V.A.F.B., Mesa Oaks and Mission Hills.

The last bond passed by the community was "Measure N" on November 5, 2002. The local bond program provided approximately \$38 million, while a related State Proposition 47 bond issue also passed which provided additional funding in the amount of approximately an additional \$30 million. It has been more than 35 years since the community had passed a local bond to upgrade the aging campuses. These funds were used to modernize and correct code deficiencies for all of the Districts campuses. The majority of the school was built in the 1960s.



LOMPOC UNIFIED SCHOOL DISTRICT FIVE YEAR MASTER PLAN

2023-2028

This Five-Year Master Plan focuses on the following information:

- A. Incorporate improvements for campus safety, educational spaces for innovative learning, and sustainability.
- B. Identify the facility needs in the District that did not get addressed in the previous modernization effort.
- C. The Master Plan addresses a plan to improve the maintenance of District facilities in order to protect the community's investment in their schools.
- D. Maximize funding options.
- E. Create community partnerships.

METHODOLOGY

Kruger Bensen Ziemer Architects worked closely with District staff in development of this Five-Year Master Plan. The first step included site visits of each campus in order to prepare up to date and accurate campus site plans. These site plans will be used for tracking past D.S.A. application numbers, the size of each building, the number and age of the existing relocatable classrooms, as well as utility locations and emergency shut-offs. Included in the Master Plan are the recorded meeting minutes with each site.

MODERNIZATIONS - "CAPITAL IMPROVEMENTS"

The Five-Year Master Plan will identify the required funding goals for each of the campuses desired improvements. Potential improvements reviewed include:

A. All Schools – Common items that were brought up.

- 1. Safety
 - a. Establish a single point of entry.
 - b. More security cameras.
 - c. Parking lot security lighting.
 - d. Improve intercom.
- 2. Upgrades
 - a. Room finishes.
 - b. Furniture.
 - c. I.T. systems.
 - d. Electrical systems.
 - e. Add air conditioning.

B. Elementary Schools - Specific items

- 1. Upgraded doors, and windows.
- 2. Improve parking lots and bus drop off areas.
- 3. Upgrade administration space.
- 4. Provide space for T/K.
- 5. Improve site drainage issues.
- 6. Add a digital marquee sign.



LOMPOC UNIFIED SCHOOL DISTRICT FIVE YEAR MASTER PLAN

2023-2028

C. Middle Schools

- 1. Upgraded doors and windows.
- 2. Outdoor eating areas to serve the entire student population.
- 3. Add a digital marquee sign.
- 4. Modernize locker rooms.
- 5. Provide permanent storage buildings.

D. High Schools

- 1. Renovate swimming pools.
- 2. Modernize locker rooms.
- 3. Replace classroom storefront panels.
- 4. Improve site drainage issues.
- 5. Exterior painting.
- 6. Upgrade room finishes, doors and windows.

E. Central Facilities

- 1. These facilities include the District Offices, and the Corporate Yard located at 1301 North "A" Street.
- 2. Possible interior space planning redesign.
- 3. New general meeting room.

Master Plan Approach & Process

A "complete" approach to problem-solving that focuses the client at the center. This requires participation and interaction with the design team members.



Points to Consider:

- California Department of Education recommends a Master Plan every 3-5 years to apply for State Funding.
- The Master Plan must consider the local community members.
- Decisions are based on collected data.

Master Plan Process

- Site Visits
- Updating the Campus Site Plans
- Updating the "Campus Data Sheets"
- Interviewing the Principals
- Review of Past Improvements and Items Omitted from Past Measures

District Facility Goals

A. District Strategic Vision

"Meet the changing educational needs of the students, teachers, parents, staff, community and administrators."

The Master Plan is to address how the facilities support the students' education. Having flexible educational facilities are essential for providing future educational needs. Supporting student engagement is essential.

B. Master Planning Committee

The committee is to provide a road map to assist the District administration and facilities staff.

C. District Priorities

- 1. Health and Life Safety
- 2. Building Shell Integrity
- 3. Classroom Interior Upgrades
- 4. Educational Spaces for Innovation in Learning
- 5. Flexible Classroom Configurations
- 6. Permanent Buildings Replace Existing Portables
- 7. Energy Efficiency
- 8. Community Partnerships and Community Use
- 9. Sustainability Incorporated in the Facilities Plan and Educational Curriculum
- 10. Maximize Funding Options
- 11. Comply with State Requirements
- 12. Reduce Future Maintenance Requirements

Adopted Board of Education Goals

- 1. Academic Achievement and Instruction: Maximize academic achievement of all students and provide instructional programs and educational opportunities that enable our students to meet or exceed the adopted district standards.
- **2. Communication:** Promote positive, effective communication among our community, District, students, staff and stakeholders.
- **3. Professional Learning:** Develop capacity of all staff to meet the academic needs of all our students through ongoing professional development and collaboration.
- **4. Culture/Safety:** Provide a safe and respectful learning environment where each student, parent/guardian, and staff member is valued.
- **5. Commitment to Excellence:** Commit to excellence in education and awareness of Board responsibilities.
 - a. Participate in annual professional learning
 - b. Maintain ongoing review and development of pertinent policies.
 - c. Monitor student and system performance.
- **6.** School Facility Responsibilities: Updating and improving district-wide infrastructure.



Master Plan 2023-2028 **Acknowledgements**

School Board Officers / Members

William "Franky" Caldeira, Board President

Tom Blanco, Board Vice President

Janet Blevins, Clerk

Sarah Anne Read, Board Member

Jerri Thiel, Board Member

Clara A. Finneran, District Superintendent

Paul Bommersbach, Assistant Superintendent, Human Resources

Brian Jaramillo, Assistant Superintendent, Educational Services

Doug Sorum, Assistant Superintendent, Business Services

Sam J. Blanton, Operation and Maintenance Manager

Scott Bauldry, Supervisor, Maintenance and Operations

Common Site Design Items

Safety

- Site signage for visitors to check into the administration building first.
- Classroom locks that can be easily used for "lock down" from the inside.
- Interior doors between classrooms easily locked from either side.
- o Window treatments for visual "lock down" for security reasons.
- o "Emergency" button in each classroom.
- Site fencing and gates that can control site access points.
- Window repair.
- Video security cameras
- Asbestos removal.
- Working intercoms.
- Vision lights in doors or view ports.

Facilities

- o Interior finish upgrades: paint, carpet tile, replace rusty wall panels.
- o Remove asbestos tile where occurs.
- Drinking water fountains with bottle fillers.
- Site drainage.
- Expand kitchens to allow on site food preparation.
- Accessible administrative office furniture.
- The majority of the campuses requested lunch shelters.
- o At play structures replace fall zone "chips" with a rubberized system.
- Replace 60-year-old windows with energy efficient, modern windows.

List of Current Projects

List of Current Projects

- 1. CHS Track and Field
 - a. Artificial Turf
 - b. Rubberized Track
 - c. Scoreboard
 - d. P.A. System
- 2. CHS Baseball Lighting
- 3. All Sites Marquee signs
- 4. All Sites (except LVMS) shade structures
- 5. Los Berros Gates and ADA Signage
- 6. Hapgood Switchgear Replacement
- 7. Manzanita Public Charter School PSMI Modernization & Expansion
- 8. Crestview PSMI Modernization & Expansion
- 9. Miguelito Portable Classrooms
- 10. LVMS Portable Classrooms

District Schools and Addresses

Lompoc Unified School District

1301 North A Street

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-3300 Fax: (805) 735-8452

Superintendent: Trevor McDonald

Enrollment: 9,800

Buena Vista Elementary School, PK-6

100 Aldebaran Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2020; Fax: (805) 742-2021

Principal: Madalyn Anderson; E-mail: anderson.madalyn@lompocschools.org

Cabrillo High School, 9-12

4350 Constellation Road

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2900; Fax: (805) 733-4156

Principal: Mark Swanitz; E-Mail: swanitz.mark@lompocschools.org

Clarence Ruth Elementary School, K-6

501 North W Street

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2500; Fax: (805) 742-2504

Principal: Victor Velazquez; E-Mail: velazquez.victor@lompocschools.org

Crestview Elementary School, K-6

VAFB – Utah Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2050; Fax: (805) 742-2083

Principal: Christine Nagel; E-Mail: nagel.christine@lompocschools.org



Fillmore Elementary School, K-6

1211 East Pine Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2100; Fax: (805) 742-2135

Principal: Tina Wall; E-Mail: wall.tina@lompocschools.org

Hapgood Elementary School, K-6

324 South A Street

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2200; Fax: (805) 742-3309

Principal: Carmen Chavez; chavez.carmen@lompocschools.org

La Canada Elementary School, K-6

620 West North Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2250; Fax: (805) 742-2217

Principal: Lisa Wilson; E-Mail: wilson.lisa@lompocschools.org

La Honda Elementary School, K-6, Year-Round School

1213 North A Street

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2300; Fax: (805) 742-2307

Principal: Lesley Davis; E-Mail: davis.lesley@lompocschools.org

Lompoc Adult School

320 North J Street, Lompoc, CA 93436-5925

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-3100; Fax: (805) 742-3085

Principal: Elaine Webber; E-Mail: webber.elaine@lompocschools.org



LOMPOC UNIFIED SCHOOL DISTRICT FIVE YEAR MASTER PLAN

2023-2028

Lompoc High School, 9-12

515 West College Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-3000; Fax: (805) 742-3004

Principal: Celeste Pico; E-Mail: pico.celeste@lompocschools.org

Lompoc Valley Middle School, 7-8

234 South N Street

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2600; Fax: (805) 737-9480

Principal: Lisa Moore; E-Mail: moore.lisa@lompocschools.org

Los Berros Elementary School, K-6

3745 Via Lato

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2350; Fax: (805) 742-2352

Principal: Megan Evans; E-Mail: evans.megan@lompocschools.org

Manzanita Public Charter School, PK-6

991 Mountain View Blvd., Vandenberg Air Force Base, 93437

P.O. Box 2951, Lompoc, CA 93438

(805) 734-5600; Fax: (805) 734-3572

Principal: Suzanne Nicastro; E-Mail: suzanne.nicastro@manzanitacharterschool.com

Maple High School, 9-12

4010 Jupiter Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-3150; Fax: (805) 742-3163

Principal: Laurel Ciervo; E-Mail: ciervo.laurel@lompocschools.org



Miguelito Elementary School, K-6

1600 West Olive Ave.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2440; Fax: (805) 742-2450

Principal: Becky Sausker; E-Mail: sausker.becky@lompocschools.org

Vandenberg Middle School, 7-8

VAFB-Mountain View Blvd.

P.O. Box 8000, Lompoc, CA 93438-8000

(805) 742-2700; Fax: (805) 742-2759

Principal: Joel Jory; E-Mail: jory.joel@lompocschools.org

Bob Forinash Community Day School-Mission Valley

320 N. J Street

Lompoc, CA 93436


(805) 742-2940; Fax: (805) 742-3163

Principal: Eric Trigueiro; E-Mail: triguero.eric@lompocschools.org



BUENA VISTA ELEMENTARY SCHOOL

100 Aldebaran Ave, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101




BUENA VISTA ELEMENTARY SCHOOL

100 Aldebaran Ave, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. THREE NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO

ADJACENT ROOMS INTO A LIBRARY MEDIA





EXISTING PORTABLE CLASSROOM



CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Buena Vista Elementary School

100 Aldebaran

Lompoc, CA 93438-8000

Original Year Built: 1963

DSA History:

A03-23045 Construction: 18 Standard Classrooms and 2 Kindergarten, Administration,

and Cafetorium: Buildings: A, B, C, and D

A03-53932 Construction of pre-school relocatable classroom and alterations to building

A03-23045 for toilet accessibility. OLA # 25/20022

A03-69919 Construction of 1 relocatable classroom PC-307

A03-102759 Construction of 1 relocatable classroom building

A03-104640 Construction of: 1 30'x32' relocatable classroom (Previous DSA #04-101333).

Alterations to: toilets in classroom Building B (previous DSA #23045)

A03-107702 Alterations to classroom buildings and Administration building.

Entire campus fire alarm upgrade

A03-109121 Relocation of 3 relocatable classrooms from OPSC (Previous DSA #04-

.04244).

Relocation of 2 relocatable classroom buildings (Previous DSA #04-104923). Relocation of 1 relocatable restroom building (Previous DSA #04-104931).

A03-111853 Relocation of 3 relocatable classroom buildings (2) 24x40 and (1) 30x32.

A03-115588 5 Relocatable classroom and 1 relocatable toilet building.

A03-121724 Photovoltaic structure

A03-122368 Shade structure

Grade Span: K-6

Classroom Breakdown:

County SH Pre-School YMCA Preschool Kindergarten First Grade Second Grade Third Grade Fourth Grade Fifth Grade Sixth Grade Library Computer Lab

Teaching Stations on Campus:

- 17 Permanent Classrooms
- 12 Relocatable Classrooms, some used by County Ed or Community groups.
- z26 Total Classrooms on Site

Suggested Parking:

- Teaching Stations x 1.5 = 39 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 37 Standard Parking Stalls
 - 1 Loading/Unloading Zone
- 41 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from resurface to complete replacement), sidewalk repairs, and irrigation upgrades/ replacement. Electrical switchgear replacement and removal of adjacent service sink. Switchgear replaced, but not the panels.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs and multi-purpose room HVAC replacement. Consider entry/ administration "facelift".
- C. Access: assistive listening system (purchased/ held at D.O.)
- D. Portables: (9) on site as of 7/15/2009. Possible storage/ sink upgrades to all. (vs. 18 regular classrooms- doesn't count #9 and #12 at back MPR).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.
- D. Kitchen alterations.

Buena Vista- 6/27/2022- Agnes Asiedu-Kumi/Luisa Parkinson

Parking has been a problem. In size, many parents & visitors have to park in the neighborhood to walk over during drop off, pickups, & much worse when we have any event on site. Configuration of the front makes it impossible accommodate school buses. They have to park on the street & that obstructs parents dropping off or picking up. The busses cannot turn on the next immediate street.

Office space is very small to accommodate staff. We currently have staff (community liaison) in the storage room that also has supplies and no window etc. The main office is small. If possible it has to be opened up. Staff work room in main office is also used as staff lounge and other work room is used to house the new dean. Not adequate at all. Staff wanted to appeal to union for a lounge but I agreed to assign a classroom for lounge if we have room next year.

BV has enrollment of 481 on June 14th. Projection for next year is 500-550. Total staff are about 52.

Storm drainage is not adequate. We have areas that flood when it rains and we have areas that do not drain off when the sprinklers come on (front of the main office behind the Principal's office window).

BV primary facility wish is to increase office space to accommodate visitors, have drinking fountains outside like the one in the cafeteria for students, have a lounge for staff, and have the rest of the grounds fitted to take away the gopher holes. What was done to a portion of the ground should be done to all so there will be less accidents and students can run freely during breaks, PE etc.

No cameras on the site. Probably need 20 and a server.

Exterior digital marquee in design, include costs

Add outdoor filtered bottle-fill stations probably three. BV has one indoor Elkay located in MPR.

12 portable classrooms, one portable restroom, and all accompanying ramps beyond useful life; replace with permanent buildings, including modular concept. Note that one portable on this campus (YMCA) is not owned by LUSD.

Single point of entry needs defined.

Windows and window coverings at all buildings in poor condition and need addressing.

Classrooms- Ceilings and walls are the worst classroom conditions. All permanent classroom floors have rubber backed carpet overlaying the ACT. Classrooms need more convenience receptacles to support modern technology.

MPR ACT has been abated and replaced with new VCT.

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old- need 21st Century furniture for teachers and students. Some classes have new Lakeshore furniture.

Food service area has been upgraded.

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Include IT items as determined in meeting with Ian Trejo

Look at infrastructure gas and water from main to building. Gas leak smell between office and library.

HVAC- air conditioning should be listed. Admin and Kindergarten furnaces replaced with Prop 39

Need additional five Title V compliant classrooms for projected increases due to UTK.

A section of fencing at the front exposure from office to east side of Kindergarten yard has been replaced with galvanized, but no ADA gates. The remaining perimeter fence is in poor condition and needs to be modernized with iron fencing.

Gopher wire needed- only a small (30K feet) has been done, need more.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical upgrade for AC, additional classrooms, Gym, and Info Center

Roofing-working with Tremco for roofing plan.

Exterior painting-include costs

93.9 kW ground mount installed in back field 2021. Include array on new map. CHS as well.

Upgrade playground equipment and containment walls. Include rubberized surface playground, include backstops in the field. Need additional play equipment for lower grade Kindergarten. Site has to alternate classes for current equipment.

Asphalt playground equipment, tetherball poles, basketball poles and backstops need addressing

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some wooden storage and sea trains that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation hits all necessary spots on the site. Agnes notes that areas don't get watered. Solar panels out is really dry; it needs to be repaired per Sam.

Stage needs new lighting, draperies, stereo and audio throughout the MPR.

Behind solar needs new fencing; Scott suggests hardscape in this area

Walking path doesn't get irrigation

Back driveway as a student drop off? Pave a walking path from opening to campus.

School needs roof gutters

No parking lot lighting

Ball wall structure addition

Expand asphalt at Kindergarten playground area

Food service area was done but is inadequate for the campus. Can't find room for a dishwasher. If office expand, expand Kitchen as well.

New staff parking lot needs to be larger to help with parking issues.

Include new parking lot on new maps.

Office restroom need to be upsized


Floors tripping hazard. PK issue at entrance. Was carpeted, then cut away. This is an in house issue.

Structure inside restrooms needs updating



CLARENCE RUTH ELEMENTARY SCHOOL

501 North W St, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101



CLARENCE RUTH ELEMENTARY SCHOOL

501 North W St, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. THREE NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO ADJACENT

ROOMS INTO A LIBRARY MEDIA CENTER



EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Clarence Ruth Elementary School

501 North W Street Lompoc, CA 93438-8000

Original Year Built: 1960

DSA History:	
A03-19412	Construction: 3 classroom buildings, Kindergarten, Administration.
A03-19413	Construction : Cafetorium
A03-52500	Various: Clarence Ruth, Fillmore, Hapgood, La Canada, La Honda – Construction of 18 Steelgard relocatable classrooms.
A03-56104	Various : Clarence Ruth, La Canada, Fillmore - Construction of 10 relocatable classroom buildings and 2 toilet rooms.
A03-58364	Alterations to relocatable pre-school building (A# 57293).
A03-59240	Alterations to relocatable office building (A# 32317).
A03-61762	Various : Clarence Ruth and Hapgood – Alterations to existing toilet facilities.
A03-67091	Various: Clarence Ruth and La Honda – Construction of 3 relocatable classroom buildings.
A03-67855	Various : Clarence Ruth, La Canada, La Honda – Construction of 7 relocatable classroom buildings.
A03-100964	Various : Clarence Ruth, La Canada, La Honda – Construction of 6 relocatable classroom buildings.
A03-104639	Construction of 1 30'x32' relocatable classroom (Previous A# 04-101333).
A03-107714	Alterations to classroom buildings A,B, and C. Alterations to Kindergarten, Administration, and Cafetorium buildings. Entire campus fire alarm upgrade.
A03-107216	Construction of 1 relocatable classroom PC 04-104816.
A03-108593	Construction of 3 relocatable classrooms PC 02-104923. Construction of 1 relocatable restroom building PC 02-104931. Alterations to 3 relocatable classroom buildings (Relocation #04-104244).

A03-122524 Shade structure

A03-116351 Kitchen alterations

Grade Span: K-6

Classroom Breakdown:

YMCA Child Care Kindergarten First Grade Second Grade Third Grade Fourth Grade Fifth Grade Sixth Grade Library

Computer Lab

Teaching Stations on Campus:

19 Permanent Classrooms

19 Relocatable Classrooms, some used by County Ed or Community groups

38 Total Classrooms on Site

Suggested Parking:

38 Teaching Stations x 1.5 = 57 Spaces

1 Van Accessible

1 Typical Accessible

55 Standard Parking Stalls

1 Loading/ Unloading Zone

37 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from sealcoat to full remove/ replace), sidewalk repairs, and irrigation upgrades/ replacement. Infrastructure not replaced in modernization like phase 2 and 3 sites (water, sewer and gas).
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs. Consider entry/ administration "facelift".
- C. Access: assistive listening system (purchased/ held at D.O.)
- D. Portables: (16) on site as of 7/15/2009, plus (1) restroom building; not including YMCA or Dorothy Jackson Center. Possible storage/ sink upgrades to all portable classrooms. (vs. 20 regular classrooms.

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Clarence Ruth- 6/16/2022- Susan Reilly

No cameras on the site. Working with Juan at Solutionz for eight cameras which will go in this year.

Parking is not adequate. Traffic bottle necks before and after school. Teachers have to park on the street. Dangerous out front. Traffic a big issue. A lot of fields to use for increased parking.

Office space is not adequate. Tiny, only one person or visitor in there. Hallway too narrow. Like a submarine. Principal's office being used for extra room for confidential meetings. Principal now resides in small room off of the MPR. Wi-Fi in office is bad.

Ruth has enrollment of 458 on June 14th. Projection for next year is on target and same. Total staff are about 45 to 50.

Ruth primary facility wish is electrical system upgraded. Sewage from MPR out has an odor. Also smell it in the Principal's office. Portable room 24 has a breaker box outside, it trips the breaker when sun hits it. Trips power to one room. Kindergarten teachers have no playground. All playgrounds need addressing. Primary playground containment walls needs addressing. Blacktop cracking down the middle.

Exterior marquee in design, include costs

Add outdoor filtered bottle-fill stations probably three. Ruth has one indoor Elkay located in MPR.

20 portable classrooms, one portable restroom, and all accompanying ramps beyond useful life; replace with permanent buildings, including modular concept. Note that one portable on this campus (P38) is not owned by LUSD.

Single point of entry needs defined.

Windows and window coverings at all buildings in poor condition and need addressing.

Classrooms- Ceilings and walls are the worst classroom conditions. All permanent classroom floors have rubber backed carpet overlaying the ACT. Classrooms need more convenience receptacles to support modern technology.

MPR ACT has been abated and replaced with new LVT.

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old- need 21st Century furniture for teachers and students. Some classes have new Lakeshore furniture.

Food service area has been partially upgraded. There are no ovens or hood.

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Include IT items as determined in meeting with Ian Trejo

Look at infrastructure gas and water from main to building. Not all done, regularly repairing. Meter and the natural gas main line from meter then running between portables and then parallel to the front classroom building, then a 90 degree turn to the west at south side of Admin then to the back of the MPR has been replaced.

HVAC- air conditioning should be listed. Admin furnace replaced with condensate unit using Prop 39. Not sure on dates for air handlers, probably during modernization. Wall unit in principal's office which is room 21; pilot goes out and makes a boom sound.

Need additional four Title V compliant classrooms for projected increases due to UTK. Two modular TK classrooms w accompanying restrooms are being constructed here in 2023 and will land in the front near the existing K rooms.

A small section of fencing at the front exposure has been modernized with black iron, but no ADA gates. The remaining perimeter fence is in poor condition and needs to be modernized.

Gopher wire needed- only a small (30K feet) has been done, need more.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical upgrade for AC, additional classrooms, Gym, and Info Center

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include rubberized surface playground, include backstops in the field.

Asphalt playground equipment, tetherball poles, basketball poles and backstops need addressing

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some wooden storage and sea trains that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation is in good shape. Where the YMCA and DJC is in bad shape and needs addressed- north east corner.

DG area/hardscape needs redone west of portables.

Gate in the fence for YMCA, but no path to the building. Area of concern.

No gutters on campus anywhere.

Stage lighting in bad shape.

B building puddling by ball room, drainage issues. Near upper grade playground. At southeast corner of B building.

South wall of library


Carpeting in portables.

Next: La Canada 2:15pm June 16, 2022



CRESTVIEW ELEMENTARY SCHOOL

Utah Ave, Vandenberg AFB, CA 93437






KRUGER BENSEN ZIEMER ARCHITECTS

30 West Arrellaga Street, Santa Barbara, CA 93101



CRESTVIEW ELEMENTARY SCHOOL

Utah Ave, Vandenberg AFB, CA 93437





CONVENTIONAL STRUCTURE

CAMPUS DATA SHEET

Crestview Elementary School

1 Utah Avenue, Vandenberg AFB Lompoc, CA 93437

Original Year Built: 1959

DSA History:

A03-18285 Construction of 5 classroom buildings, Kindergarten, Administration, and

Cafetorium buildings.

A03-19414 Construction: 3 classrooms (1 classroom building) addition.

A03-21588 Construction of a 3-classroom building.

A03-27752 Construction of 5 classrooms and teacher work room buildings (detached).

A03-100630 Alterations to 3 classroom buildings (A# 18285) for toilet room accessibility.

A03-108031 Campus-wide modernization.

A03-109019 Relocation of 5 relocatable classroom buildings from stockpile 04-104244.

A03-111789 Relocation of 10 relocatable classroom buildings.

Relocation of 1 relocatable restroom building.

A03-114983 Kitchen Renovation

Grade Span: K-6

Classroom Breakdown:

Kindergarten First Grade Second Grade Third Grade Fourth Grade Fifth Grade Sixth Grade Library

Computer Lab

Teaching Stations on Campus:

- 28 Permanent Classrooms
- 12 Relocatable Classrooms
- 40 Total Classrooms on Site

Suggested Parking:

- 40 Teaching Stations x 1.5 = 60 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 58 Standard Parking Stalls
 - 1 Loading/ Unloading Zone
- 33 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from resurface to complete replacement), possible increase to asphalt play area due to portable added to site, sidewalk repairs, and irrigation upgrades/ replacement. Electrical switchgear and panelboard replacement for permanent buildings.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs. Consider entry/ administration "facelift".
- C. Access: sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (12) on site as of 7/15/2009, plus (1) restroom building. Possible storage/ sink upgrades to all portable classrooms. (vs. 27 regular classrooms- including four in "H" building).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Crestview- 5/26/2022- Christine Nagel

Exterior marquee in design, include costs

VSFB- flag illumination- current method inadequate

Add outdoor filtered bottle-fill stations probably three. Crestview has one Elkay located in MPR.

Crestview's primary wish list items are windows, doors, fencing

12 portable classrooms, one portable restroom and accompanying ramps beyond useful life; replace with permanent buildings, including modular. Restroom lift station inadequate frequently causes issues.

Wooden storage sheds need addressed

Crestview currently has enrollment of 395 on May 10, with projection for next year maybe twenty less. Losing one class a year. Total staff are roughly 50.

Single point of entry needs defined.

Windows and window coverings at all buildings, some of the worst in the District need addressing

Classrooms- Ceilings, floors, and walls are the worst classroom conditions. All classroom floors have rubber backed carpet overlaying the ACT except library and rooms in H building have old carpet that needs addressing. Sam will send list.

Classrooms need more convenience receptacles to support modern technology.

MPR ACT has been abated and replaced with new VCT

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old-need 21st Century furniture. Some classrooms, about 4 classes have new Lakeshore furniture student and teacher.

Office space is adequate.

Food service area has been upgraded

Backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. Not all done, regularly repairing. Crestview sewage main from front of campus out to the street connection frequently needs addressing

HVAC- air conditioning should be listed. Classroom furnaces replaced with Prop 39, some new closets. Admin office furnace replaced. MPR air handler has not been replaced.

Need additional five Title V compliant classrooms for projected increases due to UTK.

Electrical upgrades for AC and additional classrooms

No cameras on the site.

No fencing or gates have been modernized

Wi-Fi- outskirts. Separate meeting with Ian scheduled for June 2nd. Talk about voice over IP.

Gopher wire needed- only a small (30K feet) has been or will soon be done.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music

Include 21st century Information Center (library)

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include rubberized surface playground. Only have two playgrounds, and additional would be good.

Asphalt playground equipment ball-wall, tetherball poles, basketball poles and backstops need addressing

Irrigation needs addressing. A large portion of fields is not irrigated.

MPR tables, benches, and receivers need replacing

Shade structure over outdoor lunch tables, include costs

Drainage around MPR and Admin needs addressing

H building has folding walls that need addressing

Turning H building into a Gym is an idea, currently they don't need the classrooms.

Sam has someone coming to address ramp issues in the interim

Many C trains. Permanent storage should be included

Do we need to expand the trashcan enclosures/ why are the cans not being pushed back in? They may need new gates, Scott will get some information and photos of this area

Parking and drop off could be expanded, Todd look at potential areas.


Jogging track at back field

Next: VMS 2:00 today



FILLMORE ELEMENTARY SCHOOL

1211 E Pine Ave, Lompoc, CA 93436







FILLMORE ELEMENTARY SCHOOL

1211 E Pine Ave, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. THREE NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO ADJACENT

ROOMS INTO A LIBRARY MEDIA CENTER



LEGEND SITE AREA: 12.19 ACRES

EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Fillmore Elementary School

1211 East Pine Avenue Lompoc, CA 93438-8000

Original Year Built: 1959

DSA	History:	
-----	----------	--

DSA HISTORY.	
A03-18862	North East Elementary School – Construction of 18 classrooms, 2 Kindergarten rooms, Café, Administration building.
A03-20442	North East Elementary School – Construction of 3 incinerators (cancelled 4-25-62)
A03-28944	Reconstruction of Administration building E (fire damage).
A03-29860	Construction of Special Education (EMR/TMR) building.
A03-52500	Various: Fillmore, Hapgood, La Canada, La Honda, Clarence Ruth – Construction of 18 Steelgard relocatable classrooms.
A03-55902	Various: Fillmore, Lompoc Valley Middle School – Alterations to classroom buildings.
A03-56104	Various: Fillmore, La Cananda, Clarence Ruth – Construction of 10 relocatable classroom buildings and 2 toilet rooms.
A03-68283	Various: Fillmore, Hapgood, Miguelito - Construction of 6 relocatable classroom buildings.
A03-69566	Construction of 1 71'x40' Headstart building.
A03-102628	Construction of 2 relocatable classroom buildings. Alterations to classroom building (toilet upgrade).
A03-104116	Construction of 1 relocatable classroom building.
A03-107713	Alteration to classroom buildings A, B, and C. Alterations to Multi-purpose, Kindergarten, Administration, and Cafetorium buildings. Entire campus fire alarm upgrade.
A03-108592	Construction of 3 relocatable classroom buildings PC 02-104923. Construction of relocatable restroom building PC 02-104931. Alteration of 3 relocatable restroom buildings (Relocation #04-104244).
A03-116352	Kitchen alterations

A03-122369 Shade structure

Grade Span: K-6

Classroom Breakdown:

Kindergarten
First Grade
Second Grade
Third Grade
Fourth Grade
Fifth Grade
Sixth Grade
Library
Computer Lab

Teaching Stations on Campus:

25 Permanent Classrooms

12 Relocatable Classrooms

37 Total Classrooms on Site

Suggested Parking:

37 Teaching Stations x 1.5 = 56 Spaces

1 Van Accessible

1 Typical Accessible

54 Standard Parking Stalls

1 Loading/ Unloading Zone

33 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (mostly sealcoat), sidewalk repairs, and irrigation upgrades/ replacement. Infrastructure not replaced in Modernization like phase 2 and 3 sites (water, sewer, gas).
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs and Building E HVAC replacement. Consider entry/ administration "facelift".
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)

D. Portables: (11) on site as of 7/15/2009, plus (1) restroom building; not including Head Start. Possible storage/ sink upgrades to all portable classrooms. (vs. 25 regular classrooms- including five in "E" building).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Fillmore-6/17/2022- Tina Wall

No cameras on the site. This is a huge issue for the site. Fillmore needs about 16 and a server-approx. \$48K piggy back. No alarms on the campus.

Parking is not adequate. Staff park along road and at park, and around the block, kids crossing street. There is a lot of real estate along Pine being used for fields, this could be repurposed into a better parking, pick up/drop-off area.

Office space is not adequate for current needs. Account clerk works out of supply room. Dean coming in this year, no space for her.

Fillmore enrollment of 547 on June 14th. Projection for next year is hopefully higher; perhaps 100 more over next two years with addition of TKs. Total staff are about 65.

Fillmore primary facility wishes are as follows: more maintenance and upkeep. Several leaking roofs. Windows don't seal, some shattered recently due to age. Rotting walls on some portables from moisture rot. Ramps on portables are decaying. All but P10 and P1 have old carpet in them. Office still has ACT through most of it, and old carpet with duct tape in those areas that are carpeted-should be overlaid with rubber back. Storage is an issue; sea train leaks badly. Tried to repair it, but it still leaks and furniture is stored there. New music/drama position coming, site doesn't know where to put the person. Furniture is old, dilapidated, mismatched. Intercom can't be heard outside classrooms. Fencing around school is in bad shape with holes cut out in places. Gate areas are difficult to open and close. Office is fully exposed outside of fence and should be secured behind fence. Playground wood chips splintering kids, should change to rubberized system. Need to update playground equipment on the primary side playground. The upper grade equipment is adequate, but the primary is only a slide and six swings which are in bad shape. Need more outlets in the rooms. Space for

nurse/counseling in office is inadequate for the number of kids who are in there at one time (6-7). Counselor has no office, uses classrooms. MPR food line for service takes up a good portion of MPR so site can't seat the number of kids they need to seat for lunch. Site has outdoor tables/seating, but it's not covered. In the MPR the stage is used for storage because lack of storage on the site. Cabinets along back sides of rooms, some missing doors, doors can't close all the way. In some cases, need locking cabinets. Communication and signage is inadequate, people steal the letters and reconfigure our messages. Blacktop cracks on playground, needs resurfaced. Need to be more community-minded with pickle ball courts, soccer and baseball fields. Fields in general are in poor shape, need more gopher wire. Coned off area in field from leak still there, along with a bee hive-Scott/Sam can check.

Exterior digital marquee is in design, include costs

Add outdoor filtered bottle-fill stations probably three. Fillmore has one indoor Elkay located in MPR.

11 portable classrooms, 1 portable restroom and accompanying ramps beyond useful life; replace with permanent buildings, including modular concept. Note that two portables on this campus (P11 and Head Start) are not owned by LUSD. P11 will become LUSD property in the upcoming months. Site already uses this room during the daytime for multiple purposes.

Single point of entry needs defined at front entrance/office. One way in, through and out another office building door.

Windows and window coverings at all buildings in poor condition and need addressing.

Classrooms- Ceilings, cabinete and walls are the worst classroom conditions. All classroom floors have rubber backed carpet overlaying the ACT. Classrooms need more convenience receptacles to support modern technology.

MPR ACT has been abated and replaced with VCT.

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old- need 21st Century furniture for teachers and students. Some classes have new Lakeshore furniture.

Food service area has been upgraded.

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building.

Include IT items as determined in meeting with Ian Trejo

HVAC- air conditioning should be listed. Admin furnace, the units at Kindergarten rooms K1 and K2, and all of the E building classroom units replaced with condensate units with Prop 39. Not sure on dates for air handlers, probably during modernization.

Need additional five Title V compliant classrooms for projected increases due to UTK. Two modular TK classrooms w accompanying restrooms are being constructed here in 2023 and will land to the south of K1/K2.

No modernized fencing or ADA gates.

Gopher wire needed- only a small (30K feet) has been done, need more.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical upgrade for AC, additional classrooms, Gym, and Info Center

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include ADA accessible rubberized surfacing.

Asphalt playground equipment ball-wall, tetherball poles, basketball poles & backstops need addressing, as do baseball backstops in fields.

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some wooden storage and sea trains in poor condition that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation is in bad shape per Tina. Back field areas don't get covered at southwest corner, as well as at the north east section by head start.

Need a flashing beacon and pop-out at crosswalk; can work with City. Same on 6th street; needs a cross walk. Safe routes to school, federal program may be of help. City used the grant money for some schools.


Drainage issues near admin office is flood zone on north side of building. Another area is between where portables start and first building of permanent rooms. Also by MPR and C building near the shade structure. Opposite side of MPR also floods by A6

Next: Cabrillo 2:00 pm June 17, 2022



HAPGOOD ELEMENTARY SCHOOL

324 S A St, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101



HAPGOOD ELEMENTARY SCHOOL

324 S A St, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. TWO NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO ADJACENT

ROOMS INTO A LIBRARY MEDIA CENTER



LEGEND

EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE

SITE AREA: 13.14 ACRES





CAMPUS DATA SHEET

Hapgood Elementary School

324 South A Street Lompoc, CA 93438-8000

Original Year Built: 1961

DSA History:

•	
A03-10195	Construction of Administration and 5 classroom buildings.
A03-12410	Construction of new classrooms.
A03-15041	Construction of 12 new classrooms.
A03-15470	Construction of 4 classroom buildings.
A03-20282	Construction of Cafetorium and alterations to Kindergarten.
A03-38300	Alterations to classroom and Adminstration buildings.
A03-52500	Various: Hapgood, Fillmore, La Canada, La Honda, Clarence Ruth – Construction of 18 Steelgard relocatable classroom buildings.
A03-61762	Various: Hapgood, Clarence Ruth – Alterations to existing toilet facilities.
A03-68283	Various: Hapgood, Fillmore, Miguelito – Construction of 6 relocatable classroom buildings.
A03-69453	Construction of relocatable office building.
A03-108032	Campus-wide modernization.
A03-109020	Relocation of 4 relocatable classroom buildings from stockpile 04-104244.
A03-114984	Kitchen Renovation.
A03-122539	Shade structure
A03-122441	Electrical switchgear

Grade Span: K-6

Classroom Breakdown:

Kindergarten
First Grade
Second Grade
Third Grade
Fourth Grade
Fifth Grade
Sixth Grade
Library
Computer Lab

Teaching Stations on Campus:

- 31 Permanent Classrooms
- 4 Relocatable Classrooms
- 35 Total Classrooms on Site

Suggested Parking:

- 35 Teaching Stations x 1.5 = 53 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 51 Standard Parking Stalls
 - 1 Loading/Unloading Zone
- 48 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from sealcoat to complete remove/ replace), sidewalk repairs, and irrigation upgrades/ replacement- especially at Western turf area.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs. Consider entry/ administration "facelift".
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (3) on site as of 7/15/2009; not including Healthy Start. Possible storage/ sink upgrades to all portable classrooms. (vs. 37 regular classrooms).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Hapgood- 6/17/2022- Carmen Chavez

Carmen- shares Google doc (view here)

https://docs.google.com/document/d/1-

pX6FOusUMDFLrt8KwFyGEuV5o-

RxabhbP3DBWXAALs/edit?usp=sharing

Doc includes: Parking solutions, solar concept at parking lot, more ADA parking spaces, primary student restrooms need more toilets at TK/1st side of campus, only two staff toilets for 81 staff persons. Restrooms a big concern for site. Could add at blacktop by Kinder wing. Outdoor amphitheater concept. Additional gate by room 21. Playground rubberized surfacing and improve equipment. Sensor/activity paths for students to make pavement more fun. Install door at gate south of MPR/staff lounge. Community parent room addition. New tables and benches. Upgrade flooring to LVT like Ruth, upgrade stage appearance (water damage). Chair storage below stage problematic. Window covering replacements rooms 1-15. Window improvements. Signage for building room numbers. Paint poles for overhangs. More bottle fill stations by room 16.

Parking is not adequate; need more. Have 700 students. Traffic a challenge in the morning. Look at field space at northwest corner of campus. May be an opportunity to upgrade additional parking. Need more ADA parking.

Office space is not adequate. Needs re-arranging or expansion of office.

Hapgood enrollment of 696 on June 14th. Projection for next year is a little higher; over 700/710. Total staff are 82.

Hapgood primary facility wish is additional staff restrooms. Only two for eighty people. Need more space for every person on campus. Art sharing with librarian and PE teacher. Need a dedicated room for parent center.

Cameras are going in this year, probably sixteen and a server is adequate for this site.

Exterior marquee in design, include costs

Add outdoor filtered bottle-fill stations probably two more. Hapgood has one indoor Elkay located in MPR and 2 outdoor stations; one at primary by Kindergarten, and one by library (room 1), need another by room 10 or 13.

4 portable classrooms and accompanying ramps beyond useful life; replace with permanent buildings, including modular concept.

Single point of entry needs defined.

Windows and window coverings have been addressed at approximately half of the site. Windows at the five wings of rooms on Olive, Admin office have not been addressed.

Classrooms- Ceilings and walls, and cabinets are the worst classroom conditions. All classroom floors have rubber backed carpet overlaying the ACT. Classrooms need more convenience receptacles to support modern technology.

MPR ACT is original.

Fire alarms and intercom PA needs addressed. Site uses voice over IP.

Sidewalk trip hazards at expansion joints-staff member tripped this year.

Furniture is old- need 21st Century furniture for teachers and students. Some classes have new Lakeshore furniture.

Food service area has been upgraded.

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building.

Include costs of switch gear replacement. Scheduled for DSA submittal August 4, 2022.

HVAC- air conditioning should be listed. Unclear on status of classroom units. "A" street exposure classroom furnaces replaced about ten years ago. Look at modernization drawings. Stuart says Olive furnaces done at Modernization.

Need additional seven Title V compliant classrooms for projected increases due to UTK. Two modular TK classrooms w accompanying restrooms are being constructed here in 2023 and will land north of rooms 40/41 near the existing K rooms. Parent drop-off west of kindergarten/TK planned.

No modernized fencing or gates.

Include IT items as determined in meeting with Ian Trejo

Gopher wire needed- a small (30K feet) has been done or will soon be done. A small 26K foot oval area inside of a cement running track has been completed in the fields east of rooms 28, 33, 39.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical power plant upgrade for AC, additional classrooms, Gym, and Info Center

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include ADA accessible rubberized surfacing.

Asphalt playground equipment ball-wall, tetherball poles, basketball poles & backstops need addressing, baseball backstops/soccer goals in field need addressing

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some wooden storage and sea trains that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation is okay. There is issues between Olive wing classrooms. Go to hard scape.


Drainage is okay, but portable class doorways in bad shape.

Next: June 23rd @ 1pm-Site TBD



LA CAÑADA ELEMENTARY SCHOOL

621 W North Ave, Lompoc, CA 93436








LA CAÑADA ELEMENTARY SCHOOL

621 W North Ave, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. THREE NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO ADJACENT

ROOMS INTO A LIBRARY MEDIA CENTER



LEGEND

SITE AREA: 14.74 ACRES

EXISTING PORTABLE CLASSROOM



CONVENTIONAL STRUCTURE





KRUGER BENSEN ZIEMER ARCHITECTS

30 West Arrellaga Street, Santa Barbara, CA 93101

CAMPUS DATA SHEET

La Canada Elementary School

620 West North Avenue Lompoc, CA 93438-8000

Original Year Built: 1962

DSA History:	
A03-22593	Construction of classroom buildings A, B, C and D.
A03-30168	Construction of 1 classroom building with administrative space and toilet facilities.
A03-52500	Various: La Canada, Fillmore, Hapgood, La Honda, Clarence Ruth – Construction of 18 Steelgard relocatable classroom buildings.
A03-56104	Various: La Canada, Fillmore, Clarence Ruth – Construction of 10 relocatable classroom buildings and 2 toilet rooms.
A03-67855	Various: La Canada, Clarence Ruth, La Honda – Construction of 7 relocatable classroom buildings.
A03-100964	Various: La Canada, Clarence Ruth, La Honda – Construction of 6 relocatable classrooms.
A03-102627	Construction of relocatable classroom building. Restroom upgrade
A03-107712	Alteration to 4 classroom buildings B, C, D, and E. Alteration to Multi-purpose building. Entire campus fire alarm upgrade.
A03-108597	Construction of 2 relocatable classroom buildings PC 02-104923. Construction of relocatable restroom building PC 02-104931. Alteration to classroom buildings (Relocation #04-104244).
A03-114564	Parking lot expansion
A03-115735	HVAC replacement
A03-122525	Shade structure
A03-121358	Portable relocation (IEEEP)

Grade Span: K-6

Classroom Breakdown:

Kindergarten
First Grade
Second Grade
Third Grade
Fourth Grade
Fifth Grade
Sixth Grade
Library
Computer Lab

Teaching Stations on Campus:

- 24 Permanent Classrooms
- 15 Relocatable Classrooms
- 39 Total Classrooms on Site

Suggested Parking:

- 39 Teaching Stations x 1.5 = 59 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 57 Standard Parking Stalls
 - 1 Loading/Unloading Zone
- 48 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from sealcoat to complete remove/ replace), possible increase to asphalt play area due to portables added to site, sidewalk repairs, and irrigation upgrades/ replacement. Infrastructure not replaced in modernization like phase 2 and 3 sites (water, sewer and gas).
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs and Building E HVAC replacement. Consider entry/ administration "facelift". Consider adding restrooms for (7) portables at NE quadrant (behind Building E).
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (14) on site as of 7/15/2009; not including YMCA. Possible storage/ sink upgrades to all portable classrooms. (vs. 17 regular classrooms- including five in "E" building).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.
- D. Kitchen upgrade.

La Canada-6/16/2022- Lisa Wilson

La Canada primary facility wish is parking for safety reasons. Review parking lot proposal sent by Lisa. It includes a concept with another parking lot in the field (staff) and a turnaround for parent drop off coming in from North avenue at the eastern side of the E building. Currently, parents park along curb. Traffic moving on the outside of the two lanes and parents on the other side of street allowing kids to cross the street. All parking spaces filled by staff. Parents have two lanes, one a drive through lane, the other for pick up. They park in pick up lane, leave vehicle, it's a mess out front. Traffic moves at fast pace.

No cameras on the site. Eight or nine will be installed this year. Break ins becoming common this year.

Office space is inadequate. Three people in small area. When parents in the office it is a line going out the front door. Try to keep main gate closed throughout the day, difficult though, staff can't see people walking through the gate. Controlled access buzzer at front gate would be nice.

La Canada has enrollment of 592 on June 14th. Projection for next year may be fifty kids higher. Total staff at LC 45-50.

Exterior marquee in design, include costs.

Add outdoor filtered bottle-fill stations probably two. LC has one indoor Elkay located in MPR, and two outdoor units.

14 portable classrooms, 1 portable restroom and all accompanying ramps beyond useful life; replace with permanent buildings, including modular concept. Note that one portable on this campus (30) is not owned by LUSD.

Single point of entry needs defined.

Windows and window coverings at all buildings in poor condition and need addressing. Screens missing from many rooms.

Classrooms- Ceilings and walls are the worst classroom conditions. All permanent classroom floors have rubber backed carpet overlaying the ACT. Classrooms need more convenience receptacles to support modern technology.

MPR is original ACT.

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old- need 21st Century furniture for teachers and students. Some classes have new Lakeshore furniture.

Food service area has been upgraded

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building.

Include IT items as determined in meeting with Ian Trejo

HVAC- air conditioning should be listed. Admin furnace and units at Kindergarten rooms 1 & 8 replaced with condensate units using Prop 39. Not sure on dates for air handlers, probably during modernization. Rooftop unit supplying heat/ventilation to E building replaced around 2013-2015. Rooftop server room AC recently replaced.

Need additional six Title V compliant classrooms for projected increases due to UTK. Two modular TK classrooms w accompanying restrooms are being constructed here in 2023 and will land near the existing K rooms.

A small section of fencing at the front exposure has been modernized with black iron, but no ADA gates. The remaining perimeter fence is in poor condition and needs to be modernized.

Gopher wire needed- A small 30K foot area was done in 2017, another small 30K feet area is or will be done soon, need more.

Review LUSD's asphalt plan for needs.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical upgrade for AC, additional classrooms, Gym, and Info Center

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include rubberized surface playground.

Asphalt playground equipment ball-wall, tetherball poles, basketball poles and backstops need addressing

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some wooden storage and sea trains that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation is okay. No issues that Scott knows of.

Drainage issues

Overhangs should be looked at; sagging in some spots. Portables have gutters, not permanent building.

Carpeting in portables in bad shape.


Size of cafeteria is not adequate. Can we take the first two rooms to enlarge the cafeteria?

Next: Fillmore 1:00 pm June 17, 2022



LA HONDA ELEMENTARY SCHOOL

1213 N A St, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101



LA HONDA ELEMENTARY SCHOOL

1213 N A St, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS 1. ROOF RESTORATION 2. CLASSROOM MODERNIZATIONS 3. TWO NEW KINDERGARTEN CLASSROOMS 4. CONVERSION OF LIBRARY AND TWO ADJACENT ROOMS INTO A LIBRARY MEDIA CENTER

LEGEND

SITE AREA: 10.73 ACRES



EXISTING PORTABLE CLASSROOM



CONVENTIONAL STRUCTURE





"A" STREET

CAMPUS DATA SHEET

La Honda Elementary School

1213 North A Street Lompoc, CA 93438-8000

Original Year Built: 1963

DSA History:

A03-23176 Construction of classroom buildings A, C, D, E and F.

A03-49830 Construction of 2 relocatable classroom buildings.

A03-52500 Various: La Honda, Fillmore, Hapgood, La Canada, Clarence Ruth –

Construction of 18 Steelgard relocatable classroom buildings.

A03-62215 Construction of 1 relocatable classroom building.

A03-63681 Construction of 1 relocatable classroom building.

A03-67091 Various: La Honda, Clarence Ruth – Construction of 3 relocatable classroom

buildings PC 307.

A03-67855 Various: La Honda, Clarence ruth, La Canada – Construction of 7 relocatable

classroom buildings.

A03-100964 Various: La Honda, Clarence Ruth, La Canada – Construction of 6 relocatable

classroom buildings. (2 at La Honda)

A03-104068 Construction of relocatable classroom building.

A03-105428 Construction of relocatable classroom building.

A03-106117 Construction of shade structure PC 02-103546.

A03-108033 Entire campus fire alarm upgrade.

A03-108834 Construction of relocatable office building (36x40) PC 02-104926.

A03-122545 Shade structure

Grade Span: K-6

Classroom Breakdown:

Kindergarten First Grade Second Grade
Third Grade
Fourth Grade
Fifth Grade
Sixth Grade
Library
Computer Lab

Teaching Stations on Campus:

- 19 Permanent Classrooms
- 21 Relocatable Classrooms
- 40 Total Classrooms on Site

Suggested Parking:

- 40 Teaching Stations x 1.5 = 60 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 58 Standard Parking Stalls
 - 1 Loading/Unloading Zone
- 40 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from sealcoat to complete remove/ replace), possible increase to asphalt play area due to portables added to site, sidewalk repairs, and irrigation upgrades/ replacement. Existing octagonal buildings/ configuration do not lend themselves to easy expansion- consider complete demolition and starting from scratch.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs and multi-purpose room HVAC replacement. Consider entry/ administration "facelift". Consider adding restrooms for (13) portables at North end of site. Replace electrical switchboard and panelboards.
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (13) on site as of 7/15/2009; not including District units. Possible storage/ sink upgrades to all portable classrooms. (vs. 20 regular classrooms).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.
- D. HVAC upgrades to closet furnaces.

Master Plan Principal Meeting Minutes

La Honda-5/13/2022-Lesley Davis

Exterior marquee in design, include costs

Enclose trash receptacles-include costs

Add outdoor filtered bottle-fill stations 2/3 more. La Honda has one Elkay located in hallway outside of the MPR.

Permanent canopy structure over exterior dining area

12 La Honda portables, one portable restroom, and 7 District portables on La Honda campus beyond useful life; replace with permanent buildings, including modular. Have demolished two portables from this site in the last ten years

La Honda currently has enrollment of 494 with projection for next year roughly the same. Total staff are roughly 55.

Single point of entry needs defined. This is a major concern to the site. Gate left open frequently is dangerous.

Classrooms- Ceilings, and walls are the worst classroom conditions. Classroom carpet flooring is in pretty good shape. All permanent classrooms have ACT overlaid with a rubber-backed carpet.

Termite infestation at portable number 28, soft floor. Sam will look at.

MPR ACT has been abated and replaced with new VCT, around 2013.

Wooden storage near cafeteria needs addressing.

Windows and coverings need addressing

Fire alarms and intercom are old, parts hard to get, many rooms with no intercom (panel full). Can't call from office to class or vice versa.

Holes in portable ramps. Sam will look at.

Furniture is old-need 21st Century furniture.

Office space is inadequate for current staffing; stuffed. Workroom is being used as a Dean's office.

Food service area is inadequate, need cook from scratch like at many other sites. Space extremely limited. Cafeteria is small and doesn't fit all the students.

No outdoor restrooms, not accessible from the playing fields and not visible from Supervisors watching the recess/lunch.

Backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. Not all done, constantly repairing. Replaced gas line from main to portables in 2020

HVAC- air conditioning should be listed. Classroom forced air furnaces replaced in the three (classroom) pods with ABM project. Stuart or Sam could get list/confirm. Admin office and MPR/Cafeteria have not been replaced.

Electrical upgrades for AC and additional classrooms

Some cameras are installed at La Honda, maybe 8 or 10; expand.

Fencing. Part of the front exposure is complete, expand to entire perimeter, ADA for gates.

Wi-Fi- outskirts. Separate meeting with Ian scheduled for June 2nd. Talk about voice over IP.

Gopher wire needed in many places although one small area (30K feet) has been done.

Contact Joe R- Pavement Engineering to get LUSD's asphalt plan. Front parking lot replaced in 2014. About ¾ of upper grade playground asphalt replaced around 2019

Drop off and pick up is crazy because only one lane coming in. Traffic gets backed up. Can't get out of parking lot because kids in cross walk.

Need additional four Title V compliant classrooms for projected increases due to UTK.

Include gymnasium for PE, Civic Use, and theatrical/music

Include 21st century Information Center (library)

Roofing- contact Tremco for roofing plan. Some portable roofs replaced in 2013.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include rubberized surface playground. One rubberized surface has been installed at the small play structure to the east of Kindergarten room #3.

Ball-wall, tetherball poles, basketball poles on upper grade side. Relocate wall-ball. Poles are rusty, could be improved. Concrete retaining wall on play structure.

Irrigation is down right now. No irrigation in the front. Issues with valves at the volunteer garden. Sam or Scott will look into the valve issue.

La Honda's number one need is creating a safe campus with more space including restrooms that can be supervised. Repairing the PA system so that teachers and students can hear it outside on playgrounds.

Asphalt on primary playground floods during heavy rain. Parking lot out front does the same.

Outdoor trash cans are in bad shape. Remove, repair replace.

Inner campus gates need addressed

Soccer goals need addressed

MPR tables are in bad shape

Lunch area shade structure area is now DG, should be concrete or asphalt.

Roof gutters rotting away, need addressed

Message boards rotting away


Stump removal.

Next: Maple at 2:15 today



LOS BERROS ELEMENTARY SCHOOL

3745 Via Lato, Lompoc, CA 93436







LOS BERROS ELEMENTARY SCHOOL

3745 Via Lato, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. TWO NEW KINDERGARTEN CLASSROOMS
- 4. CONVERSION OF LIBRARY AND TWO ADJACENT

ROOMS INTO A LIBRARY MEDIA CENTER





EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Los Berros Elementary School

3745 Via Lato

Lompoc, CA 93438-8000

Original Year Built: 1963

DSA History:	
A03-22583	Construction of 18 classrooms and 2 Kindergartens, Administration and Cafeteria.
A03-27133	Construction of 6 classrooms and Library, building E.
A03-56103	Various: Los Berros, Lompoc Valley Middle School, Vandenberg Middle School – Construction of 10 relocatable classroom buildings (2 at Los Berros).
A03-64616	Various: Los Berros, Los Padres – Alterations to classroom buildings (toilet accessibility).
A03-104068	Construction of relocatable classroom building.
A03-105428	Construction of relocatable classroom building.
A03-106117	Construction of shade structure PC 02-103546.
A03-107711	Alteration to classrooms and Multi-purpose building, Administration building, 5 classroom buildings. Entire campus fire alarm upgrade.
A03-108033	Entire campus fire alarm upgrade.
A03-108834	Construction of relocatable office building (36x40) PC 02-104926.
A03-109112	Relocation of 2 relocatable classroom buildings (stockpile 04-104244).
A03-116947	Relocate 3 portable classrooms-new ramps
A03-122527	Shade structure
A03-121893	Building E New Windows

Grade Span: K-6

Classroom Breakdown:

Kindergarten
First Grade
Second Grade
Third Grade
Fourth Grade
Fifth Grade
Sixth Grade
Library
Computer Lab

Teaching Stations on Campus:

25 Permanent Classrooms

5 Relocatable Classrooms

27 Total Classrooms on Site

Suggested Parking:

27 Teaching Stations x 1.5 = 60 Spaces

1 Van Accessible

1 Typical Accessible

58 Standard Parking Stalls

1 Loading/Unloading Zone

49 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (from complete replacement to full reconstruction), sidewalk repairs, and irrigation upgrades/ replacement. Electrical switchgear replacement and removal of adjacent service sink. Electrical conduit infrastructure but no panel upgrades.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs. Consider entry/ administration "facelift". MPR and Office HVAC.
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (2) on site as of 7/15/2009. Possible storage/ sink upgrades to both. (vs. 26 regular classrooms).
- E. ADA sitework is required at Buildings C and D.

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Los Berros- 6/03/2022- Megan Evans

Exterior marquee in design, include costs

Add outdoor filtered bottle-fill stations probably three. Los Berros has one indoor Elkay located in MPR.

5 portable classrooms and accompanying ramps beyond useful life; replace with permanent buildings, including modular concept.

Single point of entry needs defined. This is the site's primary wish.

Windows and window coverings at all buildings in poor condition and need addressing. Back building housing rooms 21 through 26 will receive windows this year.

Classrooms- Ceilings and walls are the worst classroom conditions. Most if not all classroom floors have rubber backed carpet overlaying the ACT.

Classrooms need more convenience receptacles to support modern technology.

MPR ACT has been abated and replaced with new VCT

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old- need 21st Century furniture for teachers and students. About 4 classes have new Lakeshore furniture.

Food service area has been upgraded

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. Not all done, regularly repairing.

HVAC- air conditioning should be listed. Kindergarten classroom furnaces and Admin furnace replaced with Prop 39. Not sure on dates for air handlers, probably during modernization.

Need additional four Title V compliant classrooms for projected increases due to UTK.

No cameras on the site. Small system should be installed this year, approximately eight cameras and server; will need expansion.

A small section of fencing at the front exposure has been modernized with black iron, but no ADA gates. The remaining perimeter fence is in poor condition and needs to be modernized.

Gopher wire needed- only a small (30K feet) has been done, need more.

Review LUSD's asphalt plan for needs. Intermediate playground needs work.

Include gymnasium for PE, Civic Use, and theatrical/music. Include 21st century Information Center (library)

Electrical upgrade for AC, additional classrooms, Gym, and Info Center

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Upgrade playground equipment and containment walls. Include rubberized surface playground.

Asphalt playground equipment ball-wall, tetherball poles, basketball poles and backstops need addressing

MPR tables, benches, and receivers need addressing

Shade structure, include costs

Storage should be addressed. Some sea trains in back and wooden storage in front of site; permanent storage should be included.

Include costs of trashcan enclosures that are in design

Parking does not provide sufficient number of spaces for staff, however there is street parking surrounding the school. Parents picking up students must park on side streets.

Office space is adequate as far as square footage, but the current layout is not functional to meet the needs of our staff. Entry points are undesirable in terms of safety. Work spaces for six others is needed.

Los Berros had enrollment of 423 on May 10, with projection for next year of 450. Total staff are 67

Los Berros primary facility wish is security (single point of access). Adjust the access for all visitors on campus to ensure thy must go through the office.

Irrigation is in good shape.

Overhangs have bad structural rot that needs addressed. Some held up by 4x4 post.


Owl box addition.

Next: No further meetings are scheduled at this point. Next week is graduation.



MIGUELITO ELEMENTARY SCHOOL

324 S A St, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101



MIGUELITO ELEMENTARY SCHOOL

324 S A St, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS
- 3. THREE NEW KINDERGARTEN CLASSROOMS
- 4. NEW MPR/ CAFETERIA FACILITY
- 5. CONVERSION OF OLD CAFETERIA INTO A LIBRARY CENTER AND NEW MPR



LEGEND

SITE AREA: 9.26 ACRES

EXISTING PORTABLE CLASSROOM



CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Miguelito Elementary School

1600 West Olive Avenue Lompoc, CA 93438-8000

Original Year Built: 1969

DSA History:

A03-29861 Construction of 2 buildings, one with Administration, Library, 12 class areas, 2

offices, toilet rooms, and one with 2 class areas, 2 Kindergartens, and a music

room.

A03-49829 Construction of 2 relocatable classroom buildings.

A03-56894 Construction of a Multi-purpose building.

A03-63129 Construction of 4 relocatable classroom buildings and 1 relocatable toilet

facility.

A03-65052 Construction of relocatable classroom building.

A03-67092 Construction of 2 relocatable classroom buildings PC 307.

A03-68283 Various : Miguelito, Hapgood, Fillmore – construction of 6 relocatable

classroom buildings.

A03-108034 Alteration to entire campus (Modernization).

A03-115594 Relocation of two portable classrooms

A03-122370 Shade structure

Grade Span: K-6

Classroom Breakdown:

Kindergarten First Grade Second Grade Third Grade Fourth Grade Fifth Grade Sixth Grade Library

Computer Lab

Teaching Stations on Campus:

- 13 Permanent Classrooms
- 13 Relocatable Classrooms
- 26 Total Classrooms on Site

Suggested Parking:

- Teaching Stations x 1.5 = 39 Spaces
 - 1 Van Accessible
 - 1 Typical Accessible
 - 37 Standard Parking Stalls
 - 1 Loading/ Unloading Zone
- 80 Actual existing parking spaces

List of Measure "N" Work that was eliminated from the Site:

- A. Site: parking lot lighting, asphalt parking and playground rehabilitation (mostly sealcoat), sidewalk repairs, and irrigation upgrades/ replacement. Needs electrical panels completed, infrastructure only.
- B. Buildings: windows/ shades, lighting/ controls, classroom interior finishes (carpet/ flooring, ceilings, tackable wall surfacing), casework replacements or refinishing, marker boards, "smart" or interactive white boards, projection systems, EMS, administration/ office upgrades, computer lab furniture with wire management system, painting/ concealing exposed exterior conduit runs. Consider entry/ administration "facelift". Replace wood shingle mansard roof with standing seam metal panels. Consider replacing moveable walls with permanent wall construction to divide classrooms, etc.
- C. Access: classroom sinks, assistive listening system (purchased/ held at D.O.)
- D. Portables: (13) on site as of 7/15/2009; plus (1) restroom building. Possible storage/ sink upgrades to all portable classrooms. (vs. 13 regular classrooms).

Notes:

- A. All toilets and urinals replaced between 10/20 and 02/21.
- B. All exterior lighting was replaced between 10/20 and 02/21.
- C. Irrigation controllers were replaced between 10/20 and 02/21.

Master Plan Principal Meeting Minutes

Miguelito-5/12/2022 Becky Sausker

Add outdoor filtered bottle-fill stations 2/3 elementary, 4/5 middle, 6/7 high schools. Miguelito has one Elkay in the MPR.

Add a cafeteria building and reclaim four classrooms, or add permanent structure canopy over outdoor dining area

Some portables have no sewage line using French drain for sinks. Portables are sinking, compaction issues, and beyond useful life. Replace portables with permanent buildings, including modular.

Miguelito currently has enrollment of 610 projected higher next year.

Single point of entry is pretty well defined at Miguelito.

Classrooms- Flooring, ceilings, and walls are three worst classroom conditions.

Fire alarms and intercom are old, parts hard to get, many rooms with no intercom (panel full). Nonfunctioning PA system.

Furniture is old-need 21st Century furniture.

Office space is inadequate; principal has no office. Some of this would be mitigated if we had more classrooms. Speech and counseling have no class so using office. We have 27 classroom teachers plus three more specialties. Total of 50 staff members. MPR and staff lounge are being used for storage. On rainy days this is a problem because part of MPR is blocked with storage.

Permanent walls in classrooms replacing according walls.

Food service area is inadequate include with cafeteria

Backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

Look at infrastructure gas and water from main to building. Not all done, constantly repairing.

HVAC- air conditioning should be listed.

Electrical upgrades for AC and more classrooms

No cameras at Miguelito

Storage sheds need upgraded to more permanent structured

Fencing. Front exposure complete, expand to entire perimeter, ADA for gates. Low 4' height fence near Kindergarten is big concern. Pathway next to Kindergarten and fence is broken there. People entering campus through this area.

Wi-Fi- outskirts. Separate meeting with Ian for IT needs. Talk about voice over IP.

Gopher wire needed in many places although one small area (30K feet) has been done.

Contact Joe R- Pavement Engineering to get LUSD's asphalt plan. Would be nice to get the drainage ditch at concrete swale behind the classrooms and on the playground blacktop.

Drop off and pick up are challenging. There is only one street accessing Miguelito. Possible create larger parking lot by taking some of playground. Not enough parking spaces for parents. If extending parking lot into playground, playground asphalt could be extended into grass to make up the difference. This would allow more cars to clear the roadway.

HOA not amenable to back entrance.

How many UTK classrooms will we need? Doug will email Joe.


Miguelito number one need is more space.

Upgrade playground and containment wall. Include rubberized surface playground. Ball wall reconstructed or moved if making more parking. Tetherball poles need replaced.



LOMPOC VALLEY MIDDLE SCHOOL

234 South N Street, Lompoc, CA 93438







LOMPOC VALLEY MIDDLE SCHOOL

234 South N Street, Lompoc, CA 93438

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS



EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE







30 West Arrellaga Street, Santa Barbara, CA 93101

CAMPUS DATA SHEET

Lompoc Valley Middle School

234 South N Street Lompoc, CA 93438-8000

Original Year Built: 1964

DSA History:

A03-42477	Lompoc Middle – Additions to existing Gymnasium.
A03-12891	Lompoc Junior High – Alterations.
A03-19992	New Lompoc High School – Construction of Library, Science, English, Social Studies, Math, Administration, Business, Oral Communications, Language, Arts and Crafts, Shops, Agriculture and Home Economics, Gym, Paint Shop, Photography and Music.
A03-21589	Lompoc Junior High – Alterations and additions to Gymnasium, remodel of girls and boys locker rooms.
A03-22581	Lompoc Junior High – Alterations to agriculture building, gymnasium and industrial arts building.
A03-22831	Lompoc Junior High – Construction of Administration and classroom building.
A03-29789	Lompoc Junior High – Construction of 2 art classrooms and 2 music classrooms.
A03-55902	Various: Lompoc Valley Middle School, Fillmore Elementary School – Alterations to classroom buildings.
A03-56103	Various: Lompoc Valley Middle School, Los Berros, Vandenberg Middle School – Construction of 10 relocatable classroom buildings.
A03-106497	Construction of 1 30'x32' relocatable classroom building PC 02-101617 with related site work and utility connections.
A03-106497	Construction of relocatable classroom building (PC 02-101617).
A03-107692	Construction of shade structure (PC 03-106747).
A03-107860	Construction of elevator building, site work alteration to entire campus (Modernization), 2 story classroom building H (A03-22831) stairs attached to building H.
A03-108598	Construction of relocatable toilet building (PC 02-104931); alteration to 5 classroom buildings (relocation stockpile 04-101749).
A03-110684	Relocation of 30'x32' modular classroom building (relocation 03-104435, PC 04-101333).
A03-118576	Building G Kitchen Renovation (new kitchen/serving line)

Grade Span: 7-8

Note: Toilets, urinals, exterior lighting, irrigation controllers

LVMS- 6/24/2022- Lisa Moore

Parking is adequate on most occasions

Office Space is inadequate and a mess. Ingress and egress issues, fencing and security issues with people coming on campus all the time. Secure entrance at front office. It's just one big open space and is organized with a front counter unused, second long counter where three sit. Antiquated design. Attendance at front, we like that. Design is difficult with admin facing the patio area. Front parking lot is a little small and could be larger, plenty of real estate.

LVMS enrollment on June 14th was 830. Projection for next year is 825. Total staff are about 85.

LVMS primary facility wish is as follows: To have an indoor eating area that would serve the entire student population would be a dream. Our master schedule is dictated by the inadequacy of our dining area. This area would double for all student assemblies and parent involvement events. The acoustics in the gym make any gathering a challenge.

Include costs of a cafeteria building. Gym not appropriate for dining on inclement weather days.

Drainage issues at the building on the corner of Cypress and N where water seeps into classrooms below the walls. Also drainage issues in front of rooms 30-32 sandbags used to keep water off walkways, patio area, grass area by elevator.

Music room is outdated, too small, difficult for students to navigate because of the tiered levels, acoustics are terrible, and there isn't enough room for instrument storage.

Very few cameras on site, probably need about 25-30 with a server. Started some this year, maybe 15 or more.

Exterior digital marquee is in design, include costs

Add outdoor filtered bottle-fill stations probably two. LVMS has two indoor Elkay units located in the Gym.

4 portable classrooms and accompanying ramps beyond useful life; replace with permanent buildings, including modular concept. Note that there is discussion of moving one portable (64) to the south of 61 so that it sits on asphalt. Remove security trailer from campus map.

Single point of entry needs defined at front entrance/office. One way in, through and out another office building door.

Windows and window coverings at all buildings in poor condition and need addressing.

Classrooms- Ceilings, cabinets, floors, and walls are the worst classroom conditions. Classroom floors are original ACT and in bad shape. A few rooms, like computer labs and part of Maker Space (former wood shop) have carpet in poor condition. Classrooms need more convenience receptacles to support modern technology.

Gym floor resurfaced around 2013. Termites in building.

Fire alarms and intercom PA needs addressed

Sidewalk trip hazards at joints

Furniture is old-need 21st Century furniture for teachers and students.

Food service area has been upgraded. Please include this on the campus maps you are developing. Food service area not adequate for this size student population.

Need backup power for food, fire alarm, exit lights, Administration building.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. Many water main repairs at this site in the last ten years.

Include IT items as determined in meeting with Ian Trejo

HVAC- air conditioning should be listed. Classroom and Admin furnaces replaced during modernization.

No modernized fencing or ADA gates.

Gopher wire needed

Review LUSD's asphalt plan for needs.

Electrical upgrade for AC.

Electrical was updated with modernization. Look at switch gear.

Roofing- working with Tremco for roofing plan. Building at Cypress and N with saw tooth roof leaks badly.

Exterior painting- include costs. This campus currently has dimensional painting with two different base colors, another for trim, another for fascia- about 10% higher cost.

Upgrade track surfacing to rubberized, and internal grass area with gopher wire and sod.

Asphalt playground equipment basketball poles & backstops need addressing, as do softball/baseball backstops in fields.

Patio asphalt in bad shape. Replace with concrete.

Gym tables, benches, and receivers need addressing

Gym bleachers are mechanized and work, but they are old and have no handrails or ADA seating. Gym floors were resurfaced in 13 or 14. Overhead basketball backstop lift system needs addressed.

Locker rooms need modernization.

Permanent storage should be addressed

Include costs of trashcan enclosures that are in design

Home Economics building is used for special ed. One room is kitchen and needs to be addressed.

Irrigation is adequate.

Security lighting in back parking lot. No light poles in parking lots.

Greenhouse broken and outdated should be upgraded

Gopher wire at ball fields

Outdoor exercise area for PE

Outside of home economics kitchen tree removal, concrete redone. M&O trees

Tennis court surfacing

Upstairs drainage

Gutters throughout campus

Look at gas infrastructure lines, future issues on horizon

Next (final): Buena Vista 6/27/22 @9am



VANDENBERG MIDDLE SCHOOL

1145 Mountain View Blvd, Vandenberg AFB, CA 93437








VANDENBERG MIDDLE SCHOOL

1145 Mountain View Blvd, Vandenberg AFB, CA 93437

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM/LAB MODERNIZATIONS



LEGEND

SITE AREA: 24.27 ACRES

(E)

EXISTING PORTABLE CLASSROOM



CONVENTIONAL STRUCTURE





CAMPUS DATA SHEET

Vandenberg Middle School

1145 Mountain View Blvd. Lompoc, CA 93437

Original Year Built: 1963

DSA History:

A03-21887 Vandenberg Junior High – Construction of Administration building, 2 classrooms,

Homemaking, Science, Shop and Kitchen.

A03-23627 Vandenberg Junior High – Construction of buildings D, J, L, and D.

A03-26953 Vandenberg Junior High – Construction of building E – Multi-purpose building.

A03-24734 Vandenberg Junior High – Construction of building K.

A03-32021 Vandenberg Junior High – Alterations to Multi-purpose and Kitchen buildings.

A03-42444 Various: Vandenberg Middle School, Lompoc Senior High School – Alterations to

Cafeteria building and Multi-purpose building E Kitchen.

A03-56 103 Various: Vandenberg Middle School, Los Berros, Lompoc Valley Middle School -

Construction of 10 relocatable classroom buildings. (5 at VMS)

A03-56716 Alterations to emergency classroom (A52098) and building (A03-21887) for toilet

remodel.

A03-104435 Construction of 1 relocatable classroom building (CSR).

A03-106496 Construction of 1 30'x32' relocatable classroom building PC 04-101333 with

related site work and utility connections.

A03-107660 Alteration to Library/ Administration building (A03-21887 HVAC system).

A03-107861 Alteration to entire campus (Modernization).

A03-122648 Shade Structure

Grade Span: 7-8

Vandenberg Middle School Modernization:

- A. Relocated portable restroom building grading, AC pad, plumbing and electrical hook-ups and drinking fountain with safety rails-building was sent to different site.
- B. Coaches' offices, restrooms/ locker remodel and stair lifts-converted to storage (rough-plumbed for future restrooms).
- C. Building "L" boiler removed and replaced with larger system.
- D. Site lighting.
- E. Electrical (wire mold).
- F. I.T.
- G. 8 portable classrooms

Note: Toilets, urinals, exterior lighting, HVAC upgrades to locker building (ABM)

VMS- 5/26/2022- Joel Jory

Exterior marquee in design, include costs

Enclose trash receptacles-include costs

VMS number one need is security cameras- none currently. Installing some next year. Doug and Joel speak after this meeting.

VSFB- flag illumination- none at VMS

Wooden storage shed at patio needs addressed-permanent storage structure. Also at side of campus is wood sheds.

Add outdoor filtered bottle-fill stations, probably five, VMS has one in MPR. Kids love it, but security issue having the MPR open throughout the day unsupervised.

8 portable classrooms are all beyond useful life; replace with permanent buildings, include possibility of modular buildings. Five ramps are concrete.

Campus has no Gymnasium- add costs similar to PSMI design of Manzanita, but perhaps larger. West of tennis courts.

VMS currently has enrollment of 584 on May 10th with projection for next year about the same. Was 850 five years ago before bussing rules changed. Site is underutilized. Total staff including outside agency roughly 60 to 70.

Single point of entry needs defined. Currently there are three student entry points, two in front, one on the south side.

Windows and coverings at all buildings and classrooms in horrible shape need addressing

Sidewalk trip hazards at joints

Classrooms- Ceilings, floors, and walls are the worst classroom conditions. Most walls are block. Classroom flooring in bad shape, almost exclusively ACT. At least three portables with horrible carpeting; address through replacement of portables with

permanent. Any other room with carpet needs replaced. Two permanent structures with bad carpet.

Classrooms need more convenience receptacles to support modern technology. Daisy chain issue at VMS. A few buildings where light switches are in weird places. Occupancy sensor would address. Or, emergency lighting to provide some so you can see switches.

MPR ACT has been abated and replaced with new Omnisport rubber flooring court around 2015. Overhead basketball backstop lift system needs addressed.

Stage area/music room needs addressing.

MPR tables, benches, receivers

Fire alarms and intercom PA system are old, parts hard to get.

Furniture is old-need 21st Century furniture student and teacher.

Office space furniture replaced through Tri County Office. Replacing more of it. Furniture is good. Front door leaks water. If campus expands, not enough office space. Library is huge. Using F1 room off library for meeting space, could be used as expansion space.

Food service area is adequate.

Backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

All interior and exterior lighting has been replaced with LED. Parking areas in front are lit w/ LED, but not enough. Side entrance has no light other than a directional flood mounted on portable classroom. Back (north) parking has no light.

Look at infrastructure gas and water from main to building.

Irrigation needs addressed

Track in the field needs to be addressed-rubberize. Asphalt track in bad condition.

Sewage main out front needs addressed.

Tennis courts need surfacing; look at nets and poles. Also used for pickle-ball and floor hockey.

Asphalt playground equipment basketball poles and backstops

HVAC- air conditioning should be listed. Classroom and Admin furnaces replaced during Measure N modernization. MPR furnace replaced with Prop39 or ABM. PE furnaces replaced.

Electrical upgrades for AC and gymnasium

Switch gear

No modernized fencing or ADA gates.

Wi-Fi- outskirts. Separate meeting with Ian scheduled for June 2^{nd} . Talk about voice over IP.

No gopher wire/turf upgrades. Include a section of field. Also, inner campus area south of H and J buildings is an entrance and needs addressed with wire, sod and a landscaping beautification element.

Joel would like the trapezoid area between buildings H and J concrete with tables.

Review asphalt plan for needs. Much has been addressed, although more in need. Boys PE area in bad shape. Drop off area at south end of campus; not District property, how can surfacing be addressed? VSFB filled worst holes this year.

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Additional shade structure over outdoor lunch patio area

Drainage addressed in 2013 but still not great at PE area or patio near grass area floods badly.

Sand volleyball court would be a good addition

PE lockers in bad shape.

Partitions in restrooms need replaced with some kind of anti-graffiti surface?

Soccer field, backstops at field need addressing

Outdoor fitness station


Locker rooms need work, showers are old

Next: ITS June 2, 2:30, Los Berros June 3, 3:00



CABRILLO HIGH SCHOOL

4350 Constellation Rd, Lompoc, CA 93436





30 West Arrellaga Street, Santa Barbara, CA 93101



CABRILLO HIGH SCHOOL

4350 Constellation Rd, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM/LAB MODERNIZATIONS/REPAIR
- 3. CONVERSION OF COMPUTER LAB INTO DIGITAL ARTS \

PATHWAY ROOM





KRUGER BENSEN ZIEMER ARCHITECTS

30 West Arrellaga Street, Santa Barbara, CA 93101

CAMPUS DATA SHEET

Cabrillo High School

4350 Constellation Blvd. Lompoc, CA 93438-8000

Original Year Built: 1965

DSA History:	DSA	History:
--------------	------------	----------

DSA History:	
A03-25042	Construction of buildings A1, A2, B, C, D, E, F, G, H, K, L, M, N and O.
A03-26061	Construction of Medart gymnasium seats.
A03-28093	Construction of permanent outdoor bleachers.
A03-28312	Construction of buildings J, P, Q, R and additions to building H. Construction of building S (Cafeteria building).
A03-28960	Construction of swimming pool complex (equipment and change building).
A03-31482	Construction of outdoor products exterior bleachers (void 16-1-73 per Section 27 Title 21).
A03-35141	Various: Cabrillo Senior High School and Lompoc High School – Construction of portable bleachers.
A03-35614	Construction of bleachers.
A03-35719	Various: Cabrillo Senior High and Lompoc High School – Construction of athletic fields facilities.
A03-39194	Alterations to building S, Multi-purpose.
A03-63037	Additions to classroom building (accessible toilets).
A03-101745	Alterations and additions to the science building.
A03-108029	Alteration to entire campus (Modernization).
A03-112223	Relocation of 2 relocatable classroom buildings (stockpile 04-104244).
A03-113482	Construction of 1 score board.
A03-117266	Alterations & Relocation of 1-Relocatable Classroom
A03-121231	Construction of 11-Solar Panel Structures

Cabrillo High School Page **1** of **2**

A03-122163 Construction of 8-Sports Light Poles

Grade Span: 9-12

Note: Toilets, urinals, exterior lighting, irrigation controllers

General Note. All relocatable classrooms District wide were retrofitted with occupancy sensors that shut off the HVAC units (ABM Contract)

ABM Contract

Lompoc High School

- Replace Locker Room Boiler, Cafeteria Heaters, 8 classrooms units.

La Honda Elementary School

Replace 2 Pool Boilers

Vandenberg Middle School

- Replace Locker Rooms, Weight Room, and MPR Heaters

District Office

- Replace 6 Heaters, 2 Air Conditioners for Boardroom & Superintendent's Office

The total number of units installed District wide: 31 heating units, 3 boilers, 2 AC units.

Cabrillo High School Page 2 of 2

CHS-6/17/2022- Mark Swanitz

CHS primary facility wish is a camera system. There are only a few existing cameras at the aquarium. 30 cameras with a server is a ballpark for the site which would include parking lots and football field area.

Parking is adequate and meets the site's needs.

Office space is adequate, and meets current needs. But some inequity exists with the in-house upgrades done to one side of the office. Site would wish to build out the counseling side with the same type of built in furniture, mainly in the open area match the custom cabinetry.

CHS enrollment of 986 plus 54 IS on June 14th. Projection for next year about the same. Total staff are about 90.

Handball area is used at lunch time and for PE classes.

Parking structure solar array was constructed 2021. Site would like under side of solar array painted school colors.

Varsity baseball lighting addition will be constructed 2022 around fall.

Tennis courts resurfaced 21/22.

This site already has a digital marquee located in the front of the IA building.

Pool heaters replaced in 2021. Pool is old and needs renovation to a 25-yard, 6 or 8 lane water polo and swimming competition, new deck, modernized locker rooms. Conceptually, is there enough realestate to include a shallow pool for teaching kids to swim, and an all deep 25-yard pool for water polo, swimming, and diving competition including CIF. Real estate exists to the west out to the half-moon access road, and to the north towards the handball courts. LUSD has a state of the art shared track and field at LHS, it makes sense

that we have a state of the art shared aquatics center at CHS. If we needed to remove some handball courts, we could.

Gym bleachers work, but they are old and have no handrails, or ADA seating. Gym floors were resurfaced in 13 or 14. Foyer flooring was upgraded to ceramic around 13 or 14. Some tiles now broken.

Weight room (IA2) flooring and equipment recently upgraded including removal of wall separating back storage area and outside hard surface area with artificial turf going towards the student parking. Fitness center attached to weight room needs to be updated.

Include costs of artificial turf football field and rubberized track upgrade. Plans are in design phase now, and some funding has been set aside. Per Todd, tentative Schedule for CHS Football Field is for bid docs to be ready by the end of September. We're not planning to submit to DSA now that the project has shifted to only replacing the natural grass football field with artificial turf and the new replacement concrete curb (track inside curb/field edge). Rubberized track surface has been deleted per prior discussions, in favor of the artificial turf. Todd, Doug, and Mark to discuss soon. Disagreement with Gary's direction of not including track. Site needs more power at the football field for graduations and other events.

Classrooms- storefront panels are one of the worst conditions on this campus. Many of these rooms flood as water enters the wall below the windows. Some rooms you can see light. Window coverings are also in poor condition. Flooring, ceilings and walls are also in poor condition. Very few floors have been overlaid with rubber back carpet. Carpet isn't a preferred flooring surface at high school level. What opportunities exist for an overlay of hard surfacing without causing ADA issues at doorways? If none, should we include the costs of abatement then new hard surface install? Classrooms need more convenience receptacles to support modern technology.

Fire alarms and intercom are old, parts hard to get

Furniture is old-need 21st Century furniture for staff and students.

Add outdoor filtered bottle-fill stations probably seven or eight. CHS has one indoor Elkay located in Cafeteria and one in aquarium.

3 portable classrooms beyond useful life; replace with permanent buildings, including modular concept. Note that two portables on this campus (P7/P8) have been upgraded to an athletic training area. One room floor structure increased for the weight of hot tubs; both rooms contain large windows on adjacent wall so that one staff person can see into both rooms from either room.

Single point of entry needs defined.

Sidewalk trip hazards at joints

Include IT items as determined in meeting with Ian Trejo

Food service area is adequate although there are issues with the sliding wall at times.

Need backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building.

HVAC- air conditioning should be listed. Most air handlers replaced during modernization. Some other units were done during ABM project. I don't have the final list; Stuart can get that information

No modernized fencing or ADA gates at this site.

Auto Shop building had an alignment rack removed and never replaced. Most equipment in good working order. Look at portable racks.

Little theater has major flooding issues. Otherwise, theater needs new seating. Look at drainage.

Gopher wire- Varsity baseball, softball, and soccer (practice football) area are done.

Review LUSD's asphalt plan for needs.

Power plant electrical upgrade for AC. Some upgrades already happening for CHS lighting project; Todd has those specs.

Roofing- contact Tremco for roofing plan.

Exterior painting-include costs

Asphalt playground equipment basketball poles & backstops, volleyball poles and nets need addressing

Shade structure, include costs

Storage should be addressed. Many wooden storage and sea trains that should be addressed with permanent storage

Include costs of trashcan enclosures that are in design

Irrigation is inadequate.

Many drainage issues at this site.

Pick up and drop off works okay. People use visitor lot. Many kids getting dropped off now.

Some gym and cafeteria roof top furnaces not replaced yet

Locker rooms- girls in better than boys, most lockers no longer work. Benches need refurbishment.

Need a PA system for baseball area, pool, and football area. Announcements would be nice.


Sign out front falling down. Lash was supposed to give a quote. Stuart please check.

Next: Hapgood 3:00 pm June 17, 2022



LOMPOC HIGH SCHOOL

515 W College Ave, Lompoc, CA 93436





KRUGER BENSEN ZIEMER ARCHITECTS

30 West Arrellaga Street, Santa Barbara, CA 93101




LOMPOC HIGH SCHOOL

515 W College Ave, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM/LAB MODERNIZATIONS/REPAIR
- 3. CONVERSION OF COMPUTER LAB INTO DIGITAL ARTS
- **PATHWAY ROOM**
- 4. CONVERSION OF LIBRARY INTO 21ST CENTURY


LIBRARY MEDIA CENTER



LEGEND

EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE







CAMPUS DATA SHEET

Lompoc High School

515 West College Avenue Lompoc, CA 93438-8000

Original Year Built: 1962

DSA History:

A03-98 Electrical Shop building.

A03-2602 Gym and Shop.

A03-3457 Girls' shower and locker building.

A03-5243 Bleachers.

A03-8373 Auditorium building.

A03-8568 Agricultural shop.

A03-13289 Alterations to High School building.

A03-14354 Construction of Homemaking building (cancelled 7-26-57).

A03-14620 Alterations to Auditorium.

A03-14972 Reconstruction of transformer vault and switchboard.

A03-15081 Construction of Homemaking building.

A03-15738 Construction of Gymnasium.

A03-17876 Construction of gymnasium seats.

A03-17967 Construction of 1 classroom building (science, industrial arts, library,

classrooms).

A03-18394 Reconstruction of High School Auditorium Music Room.

A03-22555 Construction of Grandstand.

A03-22585 Construction of toilet facilities and Concessions Stand U.

A03-22596 Construction of buildings O, P, Q, R and S.

Alterations to buildings N-J.

A03-22777 Construction of floodlight poles.

A03-23047	Construction of Wayne Gym stands. Reconstruction of Medart gym seats (Appl. 17876) to be moved from existing high school to the new Lompoc High School.
A03-23630	Construction of 2 swimming pools and equipment building.
A03-25606	Construction of baseball backstop.
A03-26437	Construction of 1 20'x40' green house and 1 20'x40' lath house.
A03-33069	Additions to existing filter room.
A03-33536	Reconstruction of light tower work platforms.
A03-35141	Various: Lompoc and Cabrillo Senior High School – Construction of portable bleachers.
A03-35719	Various: Lompoc and Cabrillo Senior High School – Construction of athletic field facilities.
A03-41596	Construction of Auto Shop building.
A03-42444	Various: Lompoc Senior High and Vandenberg Middle School – alterations to Lompoc Senior High School Cafeteria building. 5 Kitchen. Vandenberg Middle School – Multi-purpose building. E-Kitchen.
A03-55379	Alterations to 1 OLA relocatable classroom (stockpile A53739) OLA no. 22/10421-00-29.
A03-62311	Alterations to science lab and classroom (A03-19992) for fire damage repair.
A03-63355	Reconstruction of classroom building (fire damage).
A03-102689	Construction of 3 relocatable classroom buildings (CSR).
A03-104069	Construction of 2 relocatable classroom buildings.
A03-105706	Construction of weight room.
A03-108030	Alteration to entire campus (Modernization).
A03-108632	Construction of relocatable classroom building (PC 02-104923). Construction of relocatable toilet building (PC 02-104931). 9 metal ramps (PC 04-104775) Alteration to 9 classroom buildings (relocation stockpile 04-101749).
A03-115079	Scoreboard

A03-116514	Construction of 2 relocatable classrooms
A03-119184	Electrical Switchgear Replacement
A03-119613	Track & Field Improvements
A03-119743	Baseball Scoreboard
A03-120472	Construction of 1 relocatable classroom
A03-122559	Shade Structures

Grade Span: 9-12

Note: Toilets, urinals, exterior lighting, irrigation controllers, water heater for locker room

HVAC upgrade to Cafeteria building

Master Plan Principal Meeting Minutes

LHS 6/05/2022

LHS currently has 1,653. Beginning of year 1,740. Next year 1,740 is projected.

Number one need-utilizing space better, don't have a lot of it. We're maxed out.

Wide open campus, need to focus on a single point of entry.

Gyms, weight rooms, and pools? Pool is old and needs renovation, deck too. Gym bleachers work, but they are old and have no handrails, or ADA. Floors resurfaced in 13 or 14. Football field bleachers have not been upgraded.

Classrooms- storefront panels, flooring, ceilings are three worst classroom conditions. Fire alarms and intercom are old, parts hard to get, many rooms with no intercom (panel full). Furniture is oldneed 21st Century furniture.

Need more office spaces. Not enough.

Food service is good and has been updated. Ceilings and floors need to be looked at.

Backup power for food, fire alarm, exit lights, small area in Admin.

Restroom in library not ADA.

All toilets and urinals have been replaced (ABM project).

Look at infrastructure gas and water from main to building. Not all done, constantly repairing.

Auto shop building in bad shape, roof leaks

More space for little theater- expand the building to northwest. Needs new seating.

HVAC- air conditioning should be listed. Would need electrical upgrades.

Solar array should be listed for five large cost centers.

Expand camera systems- different \$ at each site; work with Sam

Fencing. Expand to entire perimeter, ADA for gates.

Wi-Fi- outskirts. Separate meeting with Ian for IT needs. Talk about voice over IP.

AG area needs to be looked at.

Portables beyond useful life.

PA in stadium is aged and needs to be addressed.

Gopher wire needed in many places although some has been done like Varsity baseball and a small area to the north of that.

Contact Joe R- Pavement Engineering to get LUSD's asphalt plan.


CTE upgrades- auto shop

Handball area is in bad shape with storage containers stuffed in them.



MAPLE HIGH SCHOOL

4010 Jupiter Ave, Lompoc, CA 93436





KRUGER BENSEN ZIEMER ARCHITECTS

30 West Arrellaga Street, Santa Barbara, CA 93101




MAPLE HIGH SCHOOL

4010 Jupiter Ave, Lompoc, CA 93436

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS





30 West Arrellaga Street, Santa Barbara, CA 93101

CAMPUS DATA SHEET

Maple High School (Previously La Mesa Elementary School) 4010 Jupiter Avenue Lompoc, CA 93436

Original Year Built: 1962

DSA History:

A03-19648 La Mesa Elementary School – Construction of 12 classrooms, Cafetorium,

Administration and Kindergarten buildings.

A03-108028 (VAFB Site on Caron St) Campus-wide modernization (not constructed)

A03-122403 Shade Structure

Grade Span: 9-12

Maple High School Modernization:

- A. Partially open for continuation school in (8) portables; remainder of site is non-school use. HVAC in two kindergarten rooms was replaced, along with minimal path-of-travel upgrades to those spaces. Most modernization scope not completed: restroom upgrades, HVAC replacements, site infrastructure (gas, water, electric and sewer) including main switchboard and new campuswide fire alarm.
- B. No D.S.A. modernization drawings done- school was closed with no future plans at that time.
- C. Fire Alarm and HVAC upgrade in Multipurpose building (AE Group)

Maple High School Page 1 of 1

Master Plan Principal Meeting Minutes

Maple-5/13/2022-Laurel Ciervo

Exterior marquee in design, include costs.

Enclose trash receptacles-include costs

Add outdoor filtered bottle-fill stations 2/3 at Maple. Has one at the Cafeteria.

3 portables are beyond their useful life; replace with permanent buildings, including modular.

Windows and coverings in horrible condition. Many inoperable. Lead at glazing.

Maple currently has enrollment of 127 (with independent study included). Projection for next year is 150. Total staff are 20.

Single point of entry needs defined

Classrooms- Flooring, ceilings, and walls are three worst classroom conditions. A few classrooms have the ACT overlaid with rubber-backed carpet, Sam or Scott could get a list. The remaining classes are ACT only.

MPR ACT floor has been abated and replaced with new VCT around 2015.

Fire alarms and intercom are old, parts hard to get, many rooms with no intercom (panel full). Look at intercom. PA is new; goes through phones voice over IP. Standalone fire system at K building.

Furniture is old-need 21st Century furniture.

Office space is inadequate, could be bigger. No spot for counselor or outreach consultant. Registrar in a cubby.

Food service area unchanged since original design. Consider adding cook from scratch kitchen like other campus

Backup power for food, fire alarm, exit lights, small area in Admin.

All toilets and urinals have been replaced (ABM project).

All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. Not all done, constantly repairing. Small section of gas line below the grass to the north of the Admin building replaced 2013.

HVAC- air conditioning should be listed. Furnaces in rooms 1-12 and Admin office replaced with condensate units with Prop 39 funding around 2019 or 2020. Cafeteria and old K building not done. There is no gas line to the old K building; needs addressed so furnaces can be installed.

Electrical upgrades for AC

No cameras at Maple. LUSD is working on a small project 8 or 10 cameras. Probably okay for this campus. Doug will check.

Fencing. Small area by the old Kindergarten building complete, expand to entire perimeter, ADA for gates. Entire front exposure (minus the old K building) at Maple is exposed with no fence protection.

Wi-Fi- outskirts. Separate meeting with Ian scheduled for June 2nd. Talk about voice over IP.

Gopher wire needed; none at this point.

Exterior painting-include costs

Small parking area at west end of campus on Jupiter Avenue replaced around 2018. Doug sent the 2018 Asphalt Plan that Joe Ririe put together.

Roofing- contact Tremco for roofing plan. Maple overhang at south side of MPR/Admin building has structural issues. 14 squares of roofing over rooms 7-9 replaced 2016 along with 180' of wood planking and fascia at a few other classrooms (8, 9, and 10 area). Roof mastic is original so still contains asbestos.

Include gymnasium for PE, Civic Use, and theatrical/music Include 21st century Information Center (library)

Basketball poles need addressed. Volleyball court may need addressed. Lots of holes in grass area behind cafeteria.

Irrigation may need addressed


Maple's number one need is mold, windows rotting, window coverings don't close, fencing, need more protection.

Next: El Camino, Cabrillo, and Fillmore on May 20th.



LASCC - FORINASH CDS

320 N J St, Lompoc, CA 93436 PREVIOUSLY EL CAMINO MIDDLE SCHOOL





30 West Arrellaga Street, Santa Barbara, CA 93101




LASCC - FORINASH CDS

320 N J St, Lompoc, CA 93436 PREVIOUSLY EL CAMINO MIDDLE SCHOOL

PROPOSED CAMPUS IMPROVEMENTS

- 1. ROOF RESTORATION
- 2. CLASSROOM MODERNIZATIONS



LEGEND

EXISTING PORTABLE CLASSROOM

CONVENTIONAL STRUCTURE

SITE AREA: 8.03 ACRES





CAMPUS DATA SHEET

LASCC – Forinash CDS

320 North J Street Lompoc, CA 93438-8000

Original Year Built: 1969

DSA History:

A03-3910	Lompoc Union Elementary - Temporary additions.
A03-1236	Lompoc Elementary – Auditorium and 2 classrooms.
A03-3664	Lompoc Union – Cafeteria.
A03-5321	Lompoc Union – Kindergarten.
A03-13537	Lompoc Elementary School – Alterations to main classroom building.
A03-21521	El Camino Elementary School – Reconstruction of 3 classrooms (fire damage).
A03-30192	El Camino School – Construction of 2 classroom buildings A and B, and Administration building C.
A03-32062	El Camino elementary – rehabilitation and alterations to Auditorium, Cafeteria, classroom buildings A and B and Kindergarten building.
A03-42569	El Camino Elementary – Reconstruction of fire damage at existing Administration building C.
A03-102871	Construction of 40'x32' science classroom, relocation of 2 30'x32' classrooms.
A03-104014	Construction of 4 30'x32' relocatable classrooms (Previous DSA A# 04-101333).
A03-107862	Alteration to entire campus (Modernization).

Grade Span: N/A

Lompoc Adult School Modernization:

- A. New FAU's and associated framed closets- existing to remain except for one or two cases where fireboxes were cracked.
- B. New building gas piping for new FAU's.
- C. Conversion of existing relocatable science classroom to offices, toilet lights etc....

LASCC – Forinash CDS Page 1 of 1

LASCC/Forinash CDS- 6/24/2022- Elaine Webber/Eric Trigueiro

Campus now includes LASCC, Forinash CDS, and Mission Valley TK-8.

Parking- with the closure of campus due to security concerns, the north J street parking is very limited.

Office Space is sufficient and adequately configured

Drainage issues on north and east side of preschool building containing rooms 13 and 14. Water seeps into rooms below walls. Windows leak as well.

CDC enrollment on June 14th was 30. LASCC enrollment is 1,200 for next year. Total staff are about 21.

LASCC/CDC primary facility wish is as follows: Parking lot paint directional signage for safety in J St. parking lot as well as in Laurel St. parking lot. Intercom system needed for safety. Functional kitchen for K-12 student meals. Adult school has new phones on order. Remediate ancient windows that do not open. MPR and Cafeteria roof leak repair.

There are or will be seven cameras and server on the site. The site needs about 15-20 cameras total.

Exterior digital marquee is in design, include costs

Add outdoor filtered bottle-fill stations probably four. The site has only one indoor Elkay located in the Admin building. Started construction on another located near Cafeteria restrooms. Also contemplating one in room 2

2 portable classrooms and accompanying ramps beyond useful life; replace with permanent buildings, including modular concept.

Single point of entry undefined. May be hurdles with the configuration of this campus having parking lots on both sides of the campus.

Windows and window coverings at all buildings in poor condition and need addressing.

Classrooms- Ceilings, cabinets, and walls are the worst classroom conditions. Classroom floors are primarily ACT overlaid with rubber backed carpet. Classrooms need more convenience receptacles to support modern technology.

Fire alarm and intercom PA inadequate and needs addressed Sidewalk trip hazards at joints

Furniture is old-need 21st Century furniture for teachers and students.

No existing food service kitchen on this site.

Need backup power for food, fire alarm, exit lights, Administration building.

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

Look at infrastructure gas and water from main to building. There are drainage issues with the line running north and south below rooms 17-20 and out to Chestnut Avenue

Include IT items as determined in meeting with Ian Trejo

HVAC- air conditioning should be listed for classrooms. All classroom furnaces were replaced with Prop 39. Cafeteria, Admin, and MPR have not been addressed but may have been during modernization.

Switch gear

Small section (113') of modernized iron fencing around the CDS building, no ADA gates. Remainder of perimeter is galvanized fencing in poor condition.

Gopher wire needed in fields

Review LUSD's asphalt plan for needs.

Electrical upgrade for AC/switch gear

Roofing- working with Tremco for roofing plan. Building containing the Cafeteria, MPR, and rooms 21/22 is a Spanish tile roof that leaks badly and need replaced. Roof over rooms 17-20 replaced around 2013.

Exterior painting-include costs.

Asphalt playground equipment basketball poles & backstops need addressing.

MPR contains original ACT flooring, Cafeteria polished concrete.

Irrigation in good shape

Contain entire CDS so we can use parking? Many gang members in CDS. If the back parking lot is open and accessible, they can be targets for drive by shooter. Parking is an issue when we can't use back parking lot.

There are no planned shade structures for the site

Storage needs to be addressed

Trash can enclosures include costs

New exterior signage for building labels

Parking lot directional arrows

Ceiling tiles damaged should be replaced

Wallboard in most CDS rooms, need two more rooms done.

No security alarms

No fax line inside the CDS

Ed Center Complex- 6/30/2022- Sam, Scott, Doug

Parking is adequate in most areas. Around textbook room is questionable

Parking lot drainage addressed with recent asphalt work. Drainage issues still exist on south and north sides of Board room, maybe near textbook room- permanent sand bags.

13 cameras and server currently on sight, probably need about 15 more

Exterior digital marquee is needed

Need an architectural element design/beautification of front of the Ed Center. Make it more clearly defined, and less institutional

The Board room needs to be modernized

Exterior painting being completed this year.

ADA path of travel and restroom issues (two sets @ Ed Center, 3@ Central Services, Warehouse, Textbook)

Add 1 additional indoor chilled/filtered bottle-fill stations at Ed Center at front restroom hi/low station. Add 1 indoor chilled/filtered bottle- fill at Central Kitchen. Add 1 indoor chilled/filtered at Central Services.

Interior walls, flooring, drop ceiling, windows & coverings need addressing. Many windows do not lock or are secured shut with fasteners. Drop ceiling tiles are broken, missing, and stained at many places. Much of the hard surface walls have not been painted and really should have tackable surfaces overlaid. Flooring is a mix of VCT and carpeting. The entire complex should be carpeted except for areas around restrooms, fountains, lounge areas, mechanical shop areas, and front receptions (all with ceramic, LVT, or something more professional looking than 60-year-old VCT).

Poor sound efficiency in confidential offices (Superintendent, Assist Sups, Deputy Sup).

Fire alarms are not modernized, no heat/smokes in offices, no intercom PA system at Ed Center, no outdoor PA system to address entire complex

Furnishings are old-need modern furniture for staff

Backup power exists for Central Kitchen food, the IT server room, and a portion of the Board room. The Central Services admin area should have backup power as well (highly utilized during emergencies).

Need a drop ceiling installed in the server room

All toilets and urinals have been replaced (ABM project). All interior and exterior lighting has been replaced with LED

HVAC at Ed Center was replaced with ABM project. Unsure on units at Central Services, maintenance areas, transportation garage, warehouse, textbook

Look at infrastructure gas and water from main to building. Water main has been repaired in many places stretching from east edge of central services over to the north side of Ed Center. A portion of this line was replaced during the ABM project since we were doing the asphalt above it. Sam can point the replaced section out; any remaining should be replaced.

Look at sewage line at Ed Center; there may be a problem.

Perimeter fencing is being replaced this year.

Asphalt recently replaced at areas A, B, C, G, I, J, and H. Areas D, E, and F have not been addressed.

Roofing- work with Tremco for roofing needs. Many of the metal roofs at Maintenance areas leak.

Permanent storage should be addressed

IT- 6/02/2022- Ian Trejo

Todd shares screen with IT agenda.

Agenda for Master Plan IT Discussion:

All items below may need Elementary/Middle/High differentiation

- Network Cabling
- Other infrastructure: MDF/IDF
- Classroom standards (# wall & ceiling drops, projection/flatscreens, WAP's)
- Other WAP's (interior and exterior)
- IP phones
- Intercom
- PA
- Fire Alarm/EVACS
- Clock/Bell (combined with FA/IC/PA >> Rauland Telecenter U?)
- Computer Labs (?)
- Chromebook/iPad carts?
- Access Control?
- Other tech/IT?

Are District Office improvements part of the master plan?

Many items have been done, but some still are needed

Network cabling plus fiber replacement

Classrooms in good shape for the most part. Stan has them in pretty good shape.

Wireless access points, overhaul is in process with COVID and E-rate funds, maybe 2.5 million in last few years. Right now 675 access points that are paid for. We'll be almost one to one in each classroom. December access switches will arrive. This time next year, entire network is completely replaced and will last eight to ten years.

Phones- we found financing from Sysco. 80% of phones are good for next ten years. 20% need replaced in next two or three years, maybe in the \$80K range

Intercoms- we have written for grants but didn't get them. Voice over IP solution with indoor outdoor PA systems.

Computer labs have mostly been removed since we went one to one. LHS still has one and needs some money put into it.

Chromebooks and IPads, we have a good rotation going. Doing second retirement of 5,800 this year. We have sufficient in stock to replace. Next big retirement 2026, then 2029. IPads in good shape for about five more years.

Carts or centralized charging is mostly good.

Credentials to open locks or doors. Access control system makes sense.

Need about \$50K for outdoor antennas.

Spending all the E-rate so four years before next.

Ballpark idea for exterior coverage is \$50K for all secondary, \$100K for every site.

District Office improvements should be included on Master Plan

AC upgrade for server room is good. Should include a drop ceiling. Track is in place.

Server room AC across district needs upgraded, especially at Maple, need a server room. Ian will check with Stan about others.

Next: Los Berros June 3, 3pm.

AT THIDE IN STUDION TO	LOMPOC UNIFIED SCHOOL DISTRICT	
CANTED SCHOOLDES	<u></u>	
	5-YEAR MASTER PLAN 2023-2028	
Elementary		
1	BUENA VISTA ELEMENTARY SCHOOL	\$21,441,200
2	CLARENCE RUTH ELEMENTARY SCHOOL	\$24,527,100
3	CRESTVIEW ELEMENTARY SCHOOL	\$20,025,400
4	FILLMORE ELEMENTARY SCHOOL	\$19,563,000
5	HAPGOOD ELEMENTARY SCHOOL	\$18,469,200
6	LA CANADA ELEMENTARY SCHOOL	\$23,376,600
7	LA HONDA STEAM ACADEMY	\$18,487,400
8	LOS BERROS VAPA ACADEMY	\$14,139,300
9	MIGUELITO ELEMENTARY SCHOOL	\$22,104,400
Middle School		
10	LOMPOC VALLEY MIDDLE SCHOOL	\$31,350,000
11	VANDENBERG MIDDLE SCHOOL	\$24,834,400
High School		
12	CABRILLO HIGH SCHOOL	\$37,908,300
13	LOMPOC HIGH SCHOOL	\$36,890,500
14	MAPLE CONTINUATION	\$13,873,900
Adult Education		
15	LASCC, Dr.FORINASH CDS, MISSION VALLEY	\$9,722,000
16	EDUCATION CENTER	\$1,401,000
	TOTAL ALL SITES	\$338,113,700
	30% SOFT COSTS	\$101,434,110
	TOTAL PROJECT COSTS	\$439,547,810

LOMPOC UNIFIED SCHOOL DISTRICT		
DUENA VISTA ELEMENTA DV SCHOOL		NOTES NOTES
BUENA VISTA ELEMENTARY SCHOOL		
	2022 Needs Assessment	6.22 STUDENT ENROLLMENT 481, STAFF ± 52
A HEALTH & SAFETY	Assessment	
1 TRIP HAZARDS / SIDEWALKS / ADA PATH	\$25,000	\$33,000
2 SECURITY CAMERAS - 20 CAMERAS	\$100,000	\$132,000 Includes server
3 LEAD ABATEMENT	\$25,000	\$33,000
4 INTERCOM SYSTEM	\$35,000	\$46,200
5 SITE PERIMETER SECURITY FENCING/ADA GATES	\$700,000	\$924,000 2,800 LF
6 ALARM SYSTEM 7 FIRE ALARM - NEW CAMPUS WIDE	\$50,000 \$250,000	\$66,000 Security \$330,000 Based on JMPE recent school bids
8 BACK-UP POWER GENERATORS	\$68,000	\$89,760 40 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
9 PARKING LOT LIGHTING	\$50,000	\$66,000
10 NEW TRASH ENCLOSURES	\$65,000	\$85,800
B BUILDING IMPROVEMENT - GENERAL 1 ROOFING	\$0	\$0 Based on Tremco Report 07.22
a.REPAIRS	\$10,600	\$13,992
b.GUTTERS/DOWNSPOUTS/FASCIA	\$20,000	\$26,400
c.REPLACE	\$1,300,000	\$1,716,000 2025
2 PAINTING		
a. INTERIOR	\$60,000	\$79,200 @ \$4000/classroom x 15
b. EXTERIOR	\$75,000	\$99,000 \$1.716.000 01.33 Comparative HECD Estimate
3 HVAC - NEW AC COOLING 4 ELECTRICAL IMPROVEMENTS (NON-LIGHTING)	\$1,300,000 \$50,000	\$1,716,000 01.22 Comparative HESD Estimate \$66,000 Infrastructure to support technology
5 FLOOR FINISH REPLACEMENT - LUXURY VINYL TILE	\$130,000	\$171,600 at unimproved areas of the site
6 DOORS & HARDWARE	\$400,000	\$528,000 Based on HESD 2022
7 CEILING RESTORATION OR REPLACEMENT	\$50,000	\$66,000
8 WINDOW REPLACEMENT AND WINDOW COVERINGS	\$450,000	\$594,000 HESD VV BID 10/22
9 NEW CLASSROOM FURNITURE (21st Century) 10 INTERIOR LIGHTING	\$300,000	\$396,000 \$15,000 per classroom x 27-7=20
10 INTERIOR LIGHTING	50	\$0 Interior lighting was replaced with LED between 9/2017 and 9/2019.
C BUILDING IMPROVEMENT - SPECIFIC BUILDINGS		
1 LIBRARY FIXTURE UPGRADE	\$12,000	\$15,840
2 RESTROOM UPGRADES/SIGNAGE	\$15,000	\$19,800
3 CONVERT LIBRARIES TO MEDIA CENTERS	\$80,000	\$105,600
4 MPR TABLES	\$15,000	\$19,800
D ADDITIONAL IMPROVEMENTS		
1 FOOD SERVICE	N/A	N/A Completed
2 IMPROVE ADMIN OFFICE (SPACE PLAN)	\$35,000	\$46,200
3 PARKING LOT/IMPROVEMENTS/EXPANSION	\$250,000	\$330,000
F TECHNOLOGY IN PROVINCENT		
E TECHNOLOGY IMPROVEMENT 1 IT REQUIREMENTS	\$200,000	\$264,000
1 II REQUIREMENTS	7200,000	7207,000
F SITE IMPROVEMENT		
1 IRRIGATION	\$12,000	\$15,840 Currenty in good shape
2 GRADING/DRAINAGE IMPROVEMENTS	\$40,000	\$52,800
3 LANDSCAPING 4 PLAYOPOLIND CONTAINMENT	\$20,000	\$26,400 \$19,800
4 PLAYGROUND CONTAINMENT 5 PLAYGROUND RUBBERIZED FALL MEDIA	\$15,000 \$350,000	\$19,800 \$462,000 Includes ADA access
6 PLAYGROUND - KINDER UPGRADES	\$45,000	\$59,400
7 KINDERGARTEN CLASSROOM IMPROVEMENTS	\$30,000	\$39,600
8 PAVING RESTORATION OR REPLACEMENT	\$622,600	\$821,832 Based on PEI report,2018 escalated to 2023
9 TURF IMPROVEMENT / REPAIR	\$40,000	\$52,800
10 CAMPUS SITE SIGNAGE 11 NEW MARQUEE SIGNS	\$20,000 \$50,000	\$26,400 \$66,000 07.22 DPHS Bid
11 NEW MARQUEE SIGNS 12 SHADE STRUCTURE	\$200,000	\$66,000 07.22 DPHS BIG \$264,000
13 NEW BASKETBALL STANDARDS	\$15,000	\$19,800
14 OUTDOOR BOTTLE FILLER (3)	\$6,000	\$7,920
15 STORAGE BUILDINGS	\$20,000	\$26,400
16 SWITCHGEAR REPLACEMENT	\$45,000	\$59,400 CUSD 7.22 CHS
17 ILLUMINATE SITE FLAG	\$15,000	\$19,800
G REPLACEMENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT	BUILDINGS	
1 12 CLASSROOM BUILDINGS	\$7,200,000	\$9,504,000 \$600/SF @ 1000 SF
2 NEW RESTROOM BUILDING	\$800,000	\$1,056,000 \$800/SF @ 1000SF
3 5 NEW KINDERGARTEN CLASSROOMS - TITLE V "UTK"	\$5,775,000	\$7,623,000 \$700/ SF @ 1600SF
TOTAL	\$21,441,200	\$28,302,384
	321,441,200	λτο ¹ 20τ ¹ 20τ ¹

	WRIDE IN STUDE	LONDOC UNIFIED COLOOL DISTRICT NEEDS ASSESSMENT	2022 2029 M	ACTED DI ANI	1
	4	LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT	2023-2028 M	ASTER PLAN	NOTES
		CLARENCE RUTH ELEMENTARY SCHOOL			NOTES
	Sansan	CLARENCE ROTH ELEWENTARY SCHOOL	2022 Needs		
			Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 458, STAFF ± 50
Α	HEALTH 8	& SAFETY			
		TRIP HAZARDS / SIDEWALKS / ADA PATH	\$25,000	\$33,000	
	2	SECURITY CAMERAS - 10 CAMERAS	\$50,000		Includes Server
	3	LEAD ABATEMENT	\$25,000	\$33,000	
	4	INTERCOM SYSTEM	\$35,000	\$46,200	
		SITE PERIMETER SECURITY FENCING/ADA GATES	\$625,000		Partial fencing complete (front of school) , 2500 LF remaining
	6 7	ALARM SYSTEM FIRE ALARM -NEW CAMPUS WIDE	\$50,000 \$250,000		Security Based on JMPE recent school bids
	8	BACK-UP POWER GENERATORS	\$68,000		40 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
	9	PARKING LOT LIGHTING	\$50,000	\$66,000	
	10	NEW TRASH ENCLOSURES	\$65,000	\$85,800	
В		G IMPROVEMENT - GENERAL			
	1	ROOFING	\$0		Based on Tremco Report 07.22
		a. REPAIRS b. GUTTERS/DOWNSPOUTS/FASCIA	\$6,000 \$20,000	\$7,920 \$26,400	
		c. REPLACE	\$1,284,000	\$1,694,880	
	2	PAINTING	, , , , , , , , ,	. , ,	
		a. INTERIOR	\$72,000		@ \$4000/classroom x 18
		b. EXTERIOR	\$75,000		01.22 Comparative HESD Estimate
	3	HVAC - NEW AC COOLING	\$1,300,000	\$1,716,000	
-	5	ELECTRICAL IMPROVEMENTS (NON-LIGHTING) FLOOR FINISH REPLACEMENT- LUXURY VINYL TILE	\$50,000 \$130,000	\$66,000 \$171,600	Infrastructure to support technology
	6	DOORS & HARDWARE	\$350,000		Based on HESD 2022
	7	CEILING RESTORATION OR REPLACEMENT	\$50,000	\$66,000	
	8	WINDOW REPLACEMENT AND WINDOW COVERINGS	\$450,000	\$594,000	HESD VV BID 10/22
		NEW CLASSROOM FURNITURE (21st Century)	\$375,000		\$15,000 per classroom x 34-9=25
	10	INTERIOR LIGHTING	\$0	\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
-	DI III DING	G IMPROVEMENT - SPECIFIC BUILDINGS			
С		LIBRARY FIXTURE UPGRADE	\$4,600	\$6,072	
	2	RESTROOM UPGRADES/ SIGNAGE	\$15,000	\$19,800	
	3	CONVERT LIBRARIES TO MEDIA CENTERS	\$80,000	\$105,600	
		MPR TABLES	\$15,000	\$19,800	
	5	UPGRADE STAGE LIGHTING	\$40,000	\$52,800	
D	ADDITION	NAL IMPROVEMENTS			
U	1	FOOD SERVICE			
	2	IMPROVE ADMIN OFFICE (SPACE PLAN)	\$50,000	\$66,000	
	3	PARKING LOT/IMPROVEMENTS/EXPANSION	\$15,000	\$19,800	
E		OGY IMPROVEMENT			
	1	IT REQUIREMENTS	\$200,000	\$264,000	
F	SITE IMPE	ROVEMENT			
<u>'</u>	1	IRRIGATION	\$15,000	\$19.800	Currently in good shape. Figure minor repairs.
	2	GRADING/ DRAINAGE IMPROVEMENTS	\$40,000	\$52,800	
		LANDSCAPING	\$20,000	\$26,400	
		PLAYGROUND CONTAINMENT	\$15,000	\$19,800	
		PLAYGROUND RUBBERIZED FALL MEDIA PLAYGROUND - KINDER UPGRADES	\$350,000 \$65,000	\$462,000 \$85,800	Includes ADA access
	6 7	KINDERGARTEN CLASSROOM IMPROVEMENTS	\$65,000	\$85,800	
		PAVING RESTORATION OR REPLACEMENT	\$511,500		Based on PEI report, 2018 escalated to 2023
		TURF IMPROVEMENTS/REPAIR	\$30,000	\$39,600	
		CAMPUS SITE SIGNAGE	\$20,000	\$26,400	
		NEW MARQUEE SIGNS	\$25,000		07.22 DPHS Bid
		SHADE STRUCTURE	\$200,000	\$264,000	
		NEW BASKETBALL STANDARDS OUTDOOR BOTTLE FILLERS (3)	\$20,000 \$6,000	\$26,400 \$7,920	
		STORAGE BUILDINGS	\$20,000	\$26,400	
		SWITCHGEAR REPLACEMENT	\$40,000		CUSD 7.22 CHS
	17	ILLUMINATE SITE FLAG	\$15,000	\$19,800	
G		MENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT BUILDINGS	442.000.000	64F 040 CC	2 COO CT @ 1000 CT
		16 CLASSROOM BUILDINGS 1 RESTROOM BUILDING	\$12,000,000 \$800,000		\$600/SF @ 1000 SF \$800/SF @ 1000SF
		4 NEW KINDERGARTEN CLASSROOMS - TITLE V "UTK"	\$4,480,000) \$700/ SF @ 1600SF
	-	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Ţ 1, 133,000	+ = /3 = 3 / 3 0 0	
		TOTAL	\$24,527,100	\$32,375,772	

September 18 September 19 Septe	LOMPOC UNIFIED SCHOOL DISTRI	CT NEEDS	ASSESSMENT	2023-2028 M	IASTER PLAN		
					NOTES		
W. Lines St. Boat	CRESTVIEW ELEMENTA	ARY SCH	IOOL				
				2022 Needs	2026 Escalation 6.22 STUDENT ENROLLMENT 395. STAFF ± 50		
				Assessment	2026 Escalation 6.22 STUDENT ENROLLMENT 395, STAFF ± 50		
A HEALTH &							
1	TRIP HAZARDS / SIDEWALKS / ADA PATH			\$25,000	\$33,000		
2	SECURITY CAMERAS - 10 CAMERAS			\$50,000	\$66,000 Includes server		
3 4	INTERCOM SYSTEM			\$25,000 \$35,000	\$33,000 \$46,200		
5	SITE PERIMETER SECURITY FENCING/ADA GA	TES		\$675,000	\$891,000 2,700 LF		
6	ALARM SYSTEM	123		\$50,000			
7	FIRE ALARM - NEW CAMPUS WIDE			\$250,000	\$330,000 Based on JMPE recent school bids		
8	BACK-UP POWER GENERATORS			\$68,000	\$89,760 40 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.		
9	PARKING LOT LIGHTING			\$50,000	\$66,000		
10	NEW TRASH ENCLOSURES			\$65,000	\$85,800		
	IMPROVEMENT - GENERAL						
1	ROOFING	-		\$0			
	a.REPAIRS b.GUTTERS/DOWNSPOUTS/FASCIA	-		\$10,000 \$20,000	\$13,200 \$26,400		
	c.REPLACE			\$20,000			
2	PAINTING			50			
	a. INTERIOR			\$100,000	\$132,000 @ \$4000/classroom x25		
	b. EXTERIOR			\$75,000			
3	HVAC - NEW AC COOLING			\$1,300,000	\$1,716,000 01.22 Comparative HESD Estimate		
4	ELECTRICAL IMPROVEMENTS (NON-LIGHTING			\$50,000	\$66,000 Infrastructure to support technology		
5	FLOOR FINISH REPLACEMENT - LUXURY VINY	L TILE		\$130,000	\$171,600		
6	DOORS & HARDWARE			\$350,000	\$462,000 Based on HESD 2022		
7	CEILING RESTORATION OR REPLACEMENT	FRINCE		\$50,000	\$66,000		
8	WINDOW REPLACEMENT AND WINDOW COV NEW CLASSROOM FURNITURE (21st Century)			\$450,000	\$594,000 HESD VV BID 10/22 \$633,600 \$15,000 per classroom x 37-5=32		
9	INTERIOR LIGHTING			\$480,000 \$0			
10	INTERIOR EIGHTING			50	To litterior lighting was replaced with the detween 5/2017 and 5/2015.		
C BUILDING	IMPROVEMENT - SPECIFIC BUILDINGS AS APPI	ICABLE					
1	LIBRARY FIXTURE UPGRADE			\$4,600	\$6,072		
2	RESTROOM UPGRADE/SIGNAGE			\$15,000			
3	CONVERT LIBRARIES TO MEDIA CENTERS			\$80,000	\$105,600		
4	MPR TABLES			\$15,000	\$19,800		
	AL IMPROVEMENTS			11/4			
1 2	FOOD SERVICE IMPROVE ADMIN OFFICE (SPACE PLAN)			N/A \$50,000	N/A Upgrade has already been completed \$66,000		
3	PARKING LOT/IMPROVEMENTS/EXPANSION			\$150,000	\$198,000 \$198,000		
	TARRENTS EST, INTERVENTS, EXTANSION			\$150,000	4230,000		
E TECHNOLO	OGY IMPROVEMENT						
	IT REQUIREMENTS			\$200,000	\$264,000		
F SITE IMPR							
1	IRRIGATION UPGRADE			\$200,000	\$264,000 Large portion of the fields are not irrigated		
2	GRADING/DRAINAGE IMPROVEMENTS	-		\$40,000	\$52,800		
3	LANDSCAPING RIANGEOUND CONTAINMENT	-		\$20,000	\$26,400 Includes ADA access		
4	PLAYGROUND BURBERIZED FALL MEDIA	-		\$15,000	\$19,800		
5	PLAYGROUND RUBBERIZED FALL MEDIA PLAYGROUND KINDER UPGRADES	1		\$350,000 \$65,000			
7	KINDERGARTEN CLASSROOM IMPROVEMENT	rs		\$85,000			
8	PAVING RESTORATION OR REPLACEMENT			\$476,800			
9	TURF IMPROVEMENTS/REPAIR			\$60,000			
10	CAMPUS SITE SIGNAGE			\$20,000			
11	NEW MARQUEE SIGNS			\$25,000			
12	SHADE STRUCTURE			\$200,000			
13	NEW BASKETBALL STANDARDS			\$20,000			
14	OUTDOOR BOTTLE FILLERS (3)			\$6,000			
15	STORAGE BUILDINGS	-		\$20,000			
16	SWITCHGEAR REPLACEMENT			\$40,000			
17	ILLUMINATE SITE FLAG			\$15,000	\$15,000 \$19,800		
G REPLACEM		الحديد/ محد	RMANENT RIJII DINGS				
G REPLACEN	12 CLASSROOM BUILDINGS	NOS W/ PEI	VINIWEIN I DOILDINGS	\$7,200,000	\$9,504,000 \$600/SF @ 1000 SF		
2	1 RESTROOM BUILDING	 		\$800,000			
3	5 NEW KINDERGARTEN CLASSROOMS - TITLE	V "UTK		\$5,600,000			
	THE STATE OF			\$5,555,666			
			TOTAL	\$20,025,400	\$26,433,528		

	SANTON IN STEDNING	LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT	2023-2028 M	IASTER PLAN
	4	FILLANDE FLEATAITA DV SCU SCU		NOTES
	Allino Scient	FILLMORE ELEMENTARY SCHOOL	2022 Needs	
			Assessment	2026 Escalation 6.22 STUDENT ENROLLMENT 547, STAFF ± 65
Α	HEALTH &			
		TRIP HAZARDS / SIDEWALKS/ ADA PATH SECURITY CAMERAS - 16 CAMERAS	\$25,000 \$80,000	\$33,000 \$105,600 Includes server
		LEAD ABATEMENT	\$70,000	\$92,400
		INTERCOM SYSTEM	\$35,000	\$46,200
		SITE PERIMETER SECURITY FENCING/ADA GATES ALARM SYSTEM	\$825,000 \$50,000	\$1,089,000 3,300 LF \$66,000 Security
		FIRE ALARM - NEW CAMPUS WIDE	\$250,000	\$330,000 Based on JMPE recent school bids
	8	BACK-UP POWER GENERATORS	\$68,000	\$89,760 40 KW generator and a 100 amp transfer switch plus circuit rerouting.Based on JMPE 7.29.22 email.
		PARKING LOT LIGHTING NEW TRASH ENCLOSURES	\$50,000 \$65,000	\$66,000 \$85,800
	10	NEW TRASH ENCLOSURES	\$05,000	\$65,800
В		IMPROVEMENT - GENERAL		
	1	ROOFING a.REPAIRS	\$0 \$6,000	\$0 Based on TREMCO report 07.22 \$7,920
		b.GUTTERS/DOWNSPOUTS/FASCIA	\$20,000	\$26,400
		c.REPLACE	\$0	\$0
	2	PAINTING	¢0c 000	\$126.720 @ \$4000/classroom v24
		a. INTERIOR b. EXTERIOR	\$96,000 \$100,000	\$126,720 @ \$4000/classroom x24 \$132,000
		HVAC - NEW AC COOLING	\$1,300,000	\$1,716,000 01.22 comparative HESD estimate
		ELECTRICAL IMPROVEMENTS (NON-LIGHTING)	\$50,000	\$66,000 Infrastructure to support technology
		FLOOR FINISH REPLACEMENT - LUXURY VINYL TILE DOORS & HARDWARE	\$130,000 \$350,000	\$171,600 \$462,000 Based on HESD 2022
		CEILING RESTORATION OR REPLACEMENT	\$50,000	\$66,000
		WINDOW REPLACEMENT AND WINDOW COVERINGS	\$450,000	\$594,000 HESD VV BID 10/22
		NEW CLASSROOM FURNITURE (21st Century) INTERIOR LIGHTING	\$390,000	\$514,800 \$15,000/Classroom x 35-9=26 \$0 Interior lighting was replaced with LED between 9/2017 and 9/2019.
	10	INTERIOR EIGHTING	70	The first lighting was replaced with LED between 3/2017 and 3/2013.
С		IMPROVEMENT - SPECIFIC BUILDINGS AS APPLICABLE		
		LIBRARY FIXTURE UPGRADE RESTROOM UPGRADES/ SIGNAGE	\$120,000 \$15,000	\$158,400 \$19,800
		CONVERT LIBRARIES TO MEDIA CENTERS	\$80,000	\$105,600
	4	MPR TABLES	\$35,000	\$46,200
D	ADDITION	IAL IMPROVEMENTS		
_		FOOD SERVICE	\$0	\$0
		IMPROVE ADMIN OFFICE (SPACE PLAN)	\$50,000	\$66,000
	3	PARKING LOT IMPROVEMENTS/EXPANSION	\$25,000	\$33,000
E	TECHNOLO	OGY IMPROVEMENT		
	1	IT REQUIREMENTS	\$200,000	\$264,000
F	SITE IMPR	OVEMENT		
		IRRIGATION UPGRADE	\$25,000	\$33,000
		GRADING/DRAINAGE IMPROVEMENTS LANDSCAPING	\$40,000 \$20,000	\$52,800 \$26,400
		PLAYGROUND CONTAINMENT	\$10,000	\$13,200 Remove wood retaining walls
	5	PLAYGROUND RUBBERIZED FALL MEDIA	\$40,000	\$52,800 Includes ADA access
		PLAYGROUND KINDER UPGRADES KINDERGARTEN CLASSROOM IMPROVEMENTS	\$50,000 \$20,000	\$66,000 \$26,400
	-	PAVING RESTORATION OR REPLACEMENT	\$20,000	\$26,400 \$1,078,440 Based on PEI report,2018 escalated to 2023
	9	TURF IMPROVEMENTS/REPAIR	\$175,000	\$231,000
		CAMPUS SITE SIGNAGE NEW MARQUIES SIGNS	\$20,000	\$26,400 \$22,000,07,22,DBHS Bid
		NEW MARQUEE SIGNS SHADE STRUCTURE	\$25,000 \$200,000	\$33,000 07.22 DPHS Bid \$264,000 Assumes
	13	NEW BASKETBALL STANDARDS	\$25,000	\$33,000
		OUTDOOR BOTTLE FILLERS (3)	\$6,000	\$7,920 \$56,000
		STORAGE BUILDINGS SWITCHGEAR REPLACEMENT	\$50,000 \$40,000	\$66,000 \$52,800 CUSD 7.22 CHS
	17	ILLUMINATE SITE FLAG	\$15,000	\$19,800
G	REPLACEM	MENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT BUILDINGS		
	+	11 CLASSROOM BUILDINGS	\$6,600,000	\$8,712,000 \$600/SF @1,000 SF
		NEW RESTROOM BUILDING	\$800,000	\$1,056,000 \$800/SF @ 1000SF
	3	5 NEW KINDERGARTEN CLASSROOMS - TITLE V "UTK"	\$5,600,000	\$7,392,000 \$700/SF @ 1600 SF
		TOTAL	\$19,563,000	\$25,823,160
	1		. ,,	•

	ORIDE IN STUDEN	LONDOC UNIFIED COUGOU DISTRICT NEEDS ACCE	CCMENT 2022 2020 M	ACTED DI ANI	
		LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSE	SSMENT 2023-2028 M/	ASTEK PLAN	NOTES
	THE PROPERTY OF SCHOOLS	HAPGOOD ELEMENTARY SCHOOL			NUTES
	303.0	TIAF GOOD ELLIVIENTARY SCHOOL	2022 Needs		
			Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 700, STAFF ± 82
Α	HEALTH &	SAFETY	7.65655776776		
		TRIP HAZARDS / SIDEWALKS/ADA PATH	\$25,000	\$33,000	
	2	SECURITY CAMERAS - 10 CAMERAS	\$50,000	\$66,000	Includes Server
		LEAD ABATEMENT	\$25,000	\$33,000	
		INTERCOM SYSTEM	\$35,000	\$46,200	
		SITE PERIMETER SECURITY FENCING/ADA GATES	\$900,000	\$1,188,000	
		ALARM SYSTEM FIRE ALARM - NEW CAMPUS WIDE	\$50,000 \$250,000	\$66,000	Based on JMPE recent school bids
		BACK-UP POWER GENERATORS	\$68,000		40 KW generator and a 100 amp transfer switch plus circuit rerouting.Based on JMPE 7.29.22 email.
		PARKING LOT LIGHTING	\$50,000	\$66,000	
	11	NEW TRASH ENCLOSURES	\$65,000	\$85,800	
В		IMPROVEMENT - GENERAL			
	1	ROOFING	\$0	·	Based on Tremco Report 07.22
		a.REPAIRS b.GUTTERS/DOWNSPOUTS/FASCIA	\$15,600 \$20,000	\$20,592 \$26,400	
		c.REPLACE	\$20,000		Cafeteria 2024
	2	PAINTING	7-2/000	,,-20	
		a. INTERIOR	\$124,000		@ \$4000/classroom x 31
		b. EXTERIOR	\$75,000	\$99,000	
		HVAC - NEW AC COOLING	\$1,300,000		01.22 Comparative HESD Estimate
		ELECTRICAL IMPROVEMENTS (NON-LIGHTING)	\$50,000		Infrastructure to support technology
		FLOOR FINISH REPLACEMENT - LUXURY VINYL TILE DOORS & HARDWARE	\$130,000 \$350,000	\$171,600 \$462,000	Based on HESD 2022
		CEILING RESTORATION OR REPLACEMENT	\$15,000	\$19,800	
		WINDOW REPLACEMENT AND WINDOW COVERINGS	\$450,000		HESD VV BID 10/22
	9	NEW CLASSROOM FURNITURE (21st Century)	\$390,000	\$514,800	\$15,000 per classroom x 35-9=26
	10	INTERIOR LIGHTING	\$0	\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
С	BUILDING 1	IMPROVEMENT - SPECIFIC BUILDINGS AS APPLICABLE LIBRARY FIXTURE UPGRADE	¢4.000	¢c 072	
	_	RESTROOM UPGRADES/SIGNAGE	\$4,600 \$15,000	\$6,072 \$19,800	
		CONVERT LIBRARIES TO MEDIA CENTERS	\$80,000	\$105,600	
		MPR TABLES	\$15,000	\$19,800	
D		AL IMPROVEMENTS			
		FOOD SERVICE	\$0	·	Upgrade has already been completed
		IMPROVE ADMIN OFFICE (SPACE PLAN) PARKING LOT/IMPROVEMENTS/EXPANSION	\$50,000 \$250,000	\$66,000	Expand to the northwest
	3	TARRING EGYTINI ROVENIENTS/EAT ANSIGN	\$230,000	7330,000	Expand to the northwest
E	TECHNOLO	OGY IMPROVEMENT			
	1	IT REQUIREMENTS	\$200,000	\$264,000	
F	SITE IMPRO		A4F 000	640.000	Currently in good shape. Figure miner veneirs
-		IRRIGATION UPGRADE GRADING/DRAINAGE IMPROVEMENTS	\$15,000 \$40,000	\$19,800 \$52,800	Currently in good shape - Figure minor repairs
		LANDSCAPING	\$20,000	\$26,400	
		PLAYGROUND CONTAINMENT	\$15,000	\$19,800	
		PLAYGROUND RUBBERIZED FALL MEDIA	\$350,000	\$462,000	Includes ADA access
		PLAYGROUND - KINDER UPGRADES	\$40,000	\$52,800	
	7	KINDERGARTEN CLASSROOM IMPROVEMENTS	\$30,000	\$39,600	
		PAVING RESTORATION OR REPLACEMENT	\$580,000 \$250,000	\$765,600 \$330,000	Based on PEI report,2018 escalated to 2023
		TURF IMPROVEMENTS/REPAIR CAMPUS SITE SIGNAGE	\$250,000	\$330,000	
		NEW MARQUEE SIGNS	\$25,000		07.22 DPHS Bid
		SHADE STRUCTURE	\$200,000	\$264,000	
	13	NEW BASKETBALL STANDARDS	\$20,000	\$26,400	
		OUTDOOR BOTTLE FILLERS (3)	\$6,000	\$7,920	
		STORAGE BUILDINGS	\$20,000	\$26,400	
		SWITCHGEAR REPLACEMENT ILLUMINATE SITE FLAG	\$40,000 \$15,000	\$52,800 \$19,800	Verify CUSD 7.22 CHS
	1/	ILLOWING LAND	\$15,000	\$13,800	
G	REPLACEN		NENT BUILDINGS		
		4 CLASSROOM BUILDINGS	\$3,000,000	\$3,960,000	\$600/SF @ 1000 SF
		NEW RESTROOM BUILDING	\$800,000		\$800/SF @ 1000SF
	3	7 NEW KINDERGARTEN CLASSROOMS- TITLE V "UTK"	\$7,840,000	\$10,348,800	\$700/ SF @ 1600SF
			TAL	624.270.211	
			TAL \$18,469,200	\$24,379,344	

LOMPOCIU	NIFIED SCHOOL DISTRICT NEEDS ASS	ESSMENT 2023-2028 M.	ASTER DI ANI	
LA CAN	NIFIED SCHOOL DISTRICT NEEDS ASS	ESSIVIEIN1 2025-2026 IVI	ASTER PLAIN	NOTES
LA CANA	ADA ELEMENTARY SCHOO	DL DL		NOTES
		2022 Needs		
		Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 592, STAFF ± 50
A HEALTH & SAFETY				
1 TRIP HAZARDS / SIDEWA		\$25,000	\$33,000	
2 SECURITY CAMERAS - 6 C	CAMERAS	\$30,000		Includes Server
3 LEAD ABATEMENT		\$25,000	\$33,000	
4 INTERCOM SYSTEM		\$35,000	\$46,200	
5 SITE PERIMETER SECURIT 6 ALARM SYSTEM	Y FENCING/ADA GATES	\$650,000 \$50,000	\$858,000	Partial fencing completed, 2,600 LF remaining
7 FIRE ALARM -NEW CAME	PLIS WIDE	\$250,000	<u> </u>	Based on JMPE recent school bids
8 BACK-UP POWER GENER		\$68,000		40 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
9 PARKING LOT LIGHTING		\$50,000	\$66,000	
10 NEW TRASH ENCLOSURE	S	\$65,000	\$85,800	
B BUILDING IMPROVEMENT - GENERA	L .	60	Ć0	December Transport 07 22
1 ROOFING a.REPAIRS		\$0 \$8,000	\$0 \$10,560	Based on Tremco Report 07.22
b.GUTTERS/DOWNSPOU	TS/FASCIA	\$20,000	\$26,400	
c.REPLACE	,	\$1,240,000		Office (2026)
		\$227,000		Bldg 34-39 (2026) Replace
2 PAINTING				
a. INTERIOR		\$92,000		@ \$4000/classroom x 23
b. EXTERIOR		\$75,000	\$99,000	
3 HVAC - NEW AC COOLING		\$1,300,000		01.22 Comparative HESD Estimate
4 ELECTRICAL IMPROVEME 5 FLOOR FINISH REPLACEM	:NTS (NON-LIGHTING) 1ENT - LUXURY VINYL TILE	\$50,000 \$130,000	\$66,000 \$171,600	Infrastructure to support technology
6 DOORS & HARDWARE	TEINT - LOXONT VIINTE TILL	\$350,000		Based on HESD 2022
7 CEILING RESTORATION O	OR REPLACEMENT	\$15,000	\$19,800	
8 WINDOW REPLACEMENT	AND WINDOW COVERINGS	\$450,000		HESD VV BID 10/22
9 NEW CLASSROOM FURN	ITURE(21st Century)	\$420,000		\$15,000 per classroom x 37-9=28
10 INTERIOR LIGHTING		\$0	\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
C BUILDING IMPROVEMENT - SPECIFIC 1 LIBRARY FIXTURE UPGRA		\$4,600	\$6,072	
2 RESTROOM UPGRADES/S		\$15,000	\$19,800	
3 CONVERT LIBRARIES TO I		\$80,000	\$105,600	
4 MPR TABLES		\$15,000	\$19,800	
D ADDITIONAL IMPROVEMENTS				
1 FOOD SERVICE		\$0		Upgrade has been completed
2 IMPROVE ADMIN OFFICE		\$50,000	\$66,000	
3 PARKING LOT/IMPROVEN	VIENTS/EXPANSION	\$20,000	\$26,400	
E TECHNOLOGY IMPROVEMENT				
1 IT REQUIREMENTS		\$200,000	\$264,000	
F SITE IMPROVEMENT				
1 IRRIGATION UPGRADE		\$15,000		Currently in good shape, figure minor repairs
2 GRADING/DRAINAGE IM	PKUVEMENIS	\$40,000 \$20,000	\$52,800 \$26,400	
3 LANDSCAPING 4 PLAYGROUND CONTAINS	MENT	\$20,000	\$26,400	
5 PLAYGROUND RUBBERIZ		\$15,000		Includes ADA access
6 PLAYGROUND - KINDER U		\$20,000	\$26,400	
7 KINDERGARTEN CLASSRO		\$30,000	\$39,600	
8 PAVING RESTORATION O		\$411,000		Based on PEI report,2018 escalated to 2023
9 TURF IMPROVEMENTS/R	EPAIR	\$200,000		30000 SF completed
10 CAMPUS SITE SIGNAGE		\$20,000	\$26,400	
11 NEW MARQUEE SIGNS 12 SHADE STRUCTURE		\$25,000 \$200,000	\$33,000 \$264,000	07.22 DPHS Bid
12 SHADE STRUCTURE 13 NEW BASKETBALL STAND	DARDS	\$200,000	\$264,000	
14 OUTDOOR BOTTLE FILLER		\$6,000	\$7,920	
15 STORAGE BUILDINGS		\$20,000	\$26,400	
16 SWITCHGEAR REPLACEM	ENT	\$40,000	\$52,800	Verify CUSD 7.22 CHS
17 ILLUMINATE SITE FLAG		\$15,000	\$19,800	
6 95914571775	D DODTADIE 5:::: 5::::5::: /	TENT PUM PINGS		
G REPLACEMENT OF 20-PLUS YEAR OL			611 000 000	\$600/SE @ 1000 SE
1 14 CLASSROOM BUILDIN 2 1 RESTROOM BUILDING		\$8,400,000 \$800,000		\$600/SF @ 1000 SF \$800/SF @ 1000SF
	CLASSROOMS - TITLE V "UTK"	\$6,720,000		\$700/ SF @ 1600SF
5 OTELL KINDERGARTER	The state of the s	75,725,000	+0,0,0,100	
	тс	TAL \$23,376,600	\$30,857,112	
	-			

	S PRODE IN STUDIOS	LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT	2023-2028 N	1ASTER PLAN	
		LA HONDA STEAMA CADENAY			NOTES
	Charry Sowell	LA HONDA STEAM ACADEMY	2022 Noods		
			2022 Needs Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 494, STAFF ± 55
Α	HEALTH &	& SAFETY			
		TRIP HAZARDS / SIDEWALKS/ADA PATH	\$25,000	<u> </u>	
		SECURITY CAMERAS -6 CAMERAS LEAD ABATEMENT	\$30,000 \$25,000		ncludes server
		INTERCOM SYSTEM	\$35,000		
		SITE PERIMETER SECURITY FENCING/ADA GATES	\$675,000		artial fencing complete (front of school), 2,700 LF remaining
		ALARM SYSTEM FIRE ALARM - NEW CAMPUS WIDE	\$50,000 \$250,000		ecurity ased on JMPE recent school bids
		BACK-UP POWER GENERATORS	\$68,000		0 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
		PARKING LOT LIGHTING	\$50,000	\$66,000	
	10	NEW TRASH ENCLOSURES	\$65,000	\$85,800	
В	BUILDING I	G IMPROVEMENT - GENERAL			
		ROOFING	\$0		ased on TREMCO report 07.22
		a.REPAIRS b.GUTTERS/DOWNSPOUTS/FASCIA	\$22,800 \$20,000		team Academy repairs and PODS A,B,C (18,200 + 4,600)
		c.REPLACE	\$20,000		
	2	PAINTING	, ,	, -	
		a. INTERIOR b. EXTERIOR	\$72,000 \$75,000		② \$4000/classroom x 18
		D. EXTERIOR HVAC - NEW A/C COOLING	\$1,300,000		1.22 comparative HESD estimate
	4	ELECTRICAL IMPROVEMENTS (NON-LIGHTING)	\$50,000	\$66,000 In	nfrastructure to support technology
		FLOOR FINISH REPLACEMENT - LUXURY VINYL TILE	\$130,000		L UFCD 2022
		DOORS & HARDWARE CEILING RESTORATION OR REPLACEMENT	\$350,000 \$50,000	<u> </u>	ased on HESD 2022
		WINDOW REPLACEMENT AND WINDOW COVERINGS	\$450,000		ESD VV BID 10/22
		NEW CLASSROOM FURNITURE (21st Century)	\$405,000		15,000 per classroom x35-8=27
	10	INTERIOR LIGHTING	\$0	\$0 In	nterior lighting was replaced with LED between 9/2017 and 9/2019.
С	BUILDING I	S IMPROVEMENT - SPECIFIC BUILDINGS AS APPLICABLE			
		LIBRARY FIXTURE UPGRADE	\$4,600		
		RESTROOM UPGRADES/SIGNAGE CONVERT LIBRARIES TO MEDIA CENTERS	\$15,000 \$80,000		
		MPR TABLES	\$15,000	<u> </u>	
_					
D		NAL IMPROVEMENTS FOOD SERVICE	\$0	\$0.11	pgrade has already been completed
		IMPROVE ADMIN OFFICE (SPACE PLAN)	\$50,000		pg. add not an eddy according to the
	3	PARKING LOT/IMPROVEMENTS/EXPANSION	\$25,000	\$33,000	
F	TECHNOLO	OGY IMPROVEMENT			
		IT REQUIREMENTS	\$200,000	\$264,000	
	0.TT 100				
F		ROVEMENT RIGHTION UPGRADE	\$35,000	\$46 200 N	eeds extensive repair
		GRADING/DRAINAGE IMPROVMENTS	\$40,000	\$52,800	
		LANDSCAPING	\$20,000		
		PLAYGROUND CONTAINMENT PLAYGROUND RUBBERIZED FALL MEDIA	\$15,000 \$350,000		ncludes ADA access
		PLAYGROUND - KINDER UPGRADES	\$25,000	\$33,000	
			\$30,000	\$39,600	
		PAVING RESTORATION OR REPLACEMENT TURF IMPROVEMENTS/REPAIR	\$359,000 \$200,000		ased on PEI report,2018 escalated to 2023 0,000 SF completed
		CAMPUS SITE SIGNAGE	\$20,000		ojooo or completed
	11	NEW MARQUEE SIGNS	\$25,000	\$33,000 0	7.22 DPHS Bid
		SHADE STRUCTURE NEW BASKETBALL STANDARDS	\$200,000 \$20,000		
		OUTDOOR BOTTLE FILLERS (3)	\$6,000		
	15	STORAGE BUILDINGS	\$20,000	\$26,400	
		SWITCHGEAR REPLACEMENT ILLUMINATE SITE FLAG	\$40,000 \$15,000		
	1/	ILLOWINALL SILL FLAG	\$15,000	\$13,800	
G		MENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT BUILDINGS			
		17 CLASSROOM BUILDINGS	\$7,200,000		600/SF @ 1000 SF
		NEW RESTROOM BUILDING 4 NEW KINDERGARTEN CLASSROOMS- TITLE V "UTK"	\$800,000 \$4,480,000		800/SF @ 1000SF 700/ SF @ 1600SF
		TOTAL	\$18,487,400		· · ·

LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT 2023-2028 MASTER PLAN		STER PLAN	
LOS BERROS VAPA ACADEMY			NOTES
200 SERRIOS VIII TATA	2022 Needs	2026 Escalation	6.22 STUDENT ENROLLMENT 423, STAFF ± 67
A HEALTH & SAFETY	Assessment	2020 Escalation	0.22 STODENT ENNOCCIVIENT 423, STAIT ± 07
A HEALTH & SAFETY	\$25,000	\$33,000	
2 SECURITY CAMERAS -10 CAMERAS	\$50,000	\$66,000 Ir	ncludes Server
3 LEAD ABATEMENT	\$25,000	\$33,000	
4 INTERCOM SYSTEM 5 SITE PERIMETER SECURITY FENCING/ADA GA	\$35,000 TES \$700,000	\$46,200 \$924,000 P	artial fencing complete (front of school), 2,800 LF
6 ALARM SYSTEM	\$50,000	\$66,000 S	
7 FIRE ALARM - NEW CAMPUS WIDE	\$250,000	, ,	ased on JMPE recent school bids
8 BACK-UP POWER GENERATORS 9 PARKING LOT LIGHTING	\$68,000 \$50,000	\$89,760 4 \$66,000	0 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
10 NEW TRASH ENCLOSURES	\$65,000	\$85,800	
B BUILDING IMPROVEMENT - GENERAL			
1 ROOFING a.REPAIRS	\$0 \$12,500		ased on Tremco Report 07.22
b.GUTTERS/DOWNSPOUTS/FASCIA	\$12,500	\$16,500 N \$26,400	Aain Building
c.REPLACE	\$15,200	\$20,064	
2 PAINTING		4	
a. INTERIOR b. EXTERIOR	\$100,000 \$75,000	\$132,000 (\$99,000	② \$4000/classroom x 25
3 HVAC - NEW AC COOLING	\$1,300,000		1.22 Comparative HESD Estimate
4 ELECTRICAL IMPROVEMENTS (NON-LIGHTING	\$50,000	\$66,000 Ir	nfrastructure to support technology
5 FLOOR FINISH REPLACEMENT - LUXURY VINY 6 DOORS & HARDWARE	_TILE \$130,000 \$350,000	\$171,600 \$462,000 B	ased on HESD 2022
7 CEILING RESTORATION OR REPLACEMENT	\$50,000	\$462,000 B	00C0 OH TIEDD 2022
8 WINDOW REPLACEMENT AND WINDOW COV	YERINGS \$450,000	\$594,000 H	ESD VV BID 10/22
9 NEW CLASSROOM FURNITURE (21st Century)			15,000 per classroom x 25-6=19
10 INTERIOR LIGHTING	\$0	\$0 li	nterior lighting was replaced with LED between 9/2017 and 9/2019.
C BUILDING IMPROVEMENT - SPECIFIC BUILDINGS AS APPL	ICABLE		
1 LIBRARY FIXTURE UPGRADE	\$4,600	\$6,072	
2 RESTROOM UPGRADES/SIGNAGE 3 CONVERT LIBRARIES TO MEDIA CENTERS	\$15,000 \$80,000	\$19,800 \$105,600	
4 MPR TABLES	\$15,000	\$19,800	
D ADDITIONAL IMPROVEMENTS			
1 FOOD SERVICE 2 IMPROVE ADMIN OFFICE (SPACE PLAN)	\$0		pgrade has already been completed
3 PARKING LOT/IMPROVEMENTS/EXPANSION	\$50,000 \$20,000	\$66,000 \$26,400	
	720,000	,20,.00	
E TECHNOLOGY IMPROVEMENT			
1 IT REQUIREMENTS	\$200,000	\$264,000	
F SITE IMPROVEMENT			
1 IRRIGATION UPGRADE	\$15,000		urrently in good shape figure minor repairs
2 GRADING/DRAINAGE IMPROVEMENTS 3 LANDSCAPING	\$40,000 \$20,000	\$52,800 \$26,400	
4 PLAYGROUND CONTAINMENT	\$20,000	\$19,800	
5 PLAYGROUND RUBBERIZED FALL MEDIA	\$350,000	\$462,000 lr	ncludes ADA access
6 PLAYGROUND KINDER UPGRADES	\$25,000	\$33,000	
7 KINDERGARTEN CLASSROOM IMPROVEMENT 8 PAVING RESTORATION OR REPLACEMENT	\$30,000 \$228,000	\$39,600 \$300,960 B	ased on PEI report, 2018 escalated to 2023
9 TURF IMPROVEMENTS/REPAIR	\$250,000	\$330,000	3004 31.1 - 1.1 - 1.5 po. 1,3 = 0 = 0 = 0 = 0 = 0 = 0 = 0 = 0 = 0 =
10 CAMPUS SITE SIGNAGE	\$20,000	\$26,400	
11 NEW MARQUEE SIGNS 12 SHADE STRUCTURE	\$25,000 \$200,000	\$33,000 0 \$264,000	7.22 DPHS Bid
13 NEW BASKETBALL STANDARDS	\$200,000	\$26,400	
14 OUTDOOR BOTTLE FILLERS (3)	\$6,000	\$7,920	
15 STORAGE BUILDINGS	\$20,000	\$26,400	
16 SWITCHGEAR REPLACEMENT 17 ILLUMINATE SITE FLAG	\$40,000 \$15,000	\$52,800 V \$19,800	erify CUSD 7.22 CHS
17 ILLOWING TEACH	\$15,000	000,61¢	
G REPLACEMENT OF 20-PLUS YEAR OLD PORTABLE BUILDIN		40.000	
1 5 CLASSROOM BUILDINGS 2 NEW RESTROOM BUILDING	\$3,000,000 \$800,000		600/SF @ 1000 SF 800/SF @ 1000SF
3 4 NEW KINDERGARTEN CLASSROOMS - TITLE			700/ SF @ 1600SF
	TOTAL \$14,139,300	\$18,663,876	

ONE IN STURE		2023-2028 MASTER PLAN	
	LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT 202		NOTEC
	MIGUELITO ELEMENTARY SCHOOL		NOTES
Jan Saw	IVIIGUELITO ELEIVIENTARY SCHOOL	2022 Noodo	
		2022 Needs Assessment 2026 Escalation	6.22 STUDENT ENROLLMENT 610, STAFF ± 55
A HEALTH &	SAFETY	713C33ITCTC	
	TRIP HAZARDS / SIDEWALKS/ ADA PATH	\$25,000 \$33,0	
	SECURITY CAMERAS - 15 CAMERAS	\$75,000 \$99,0	00 Includes server
	LEAD ABATEMENT		50
	INTERCOM SYSTEM	\$35,000 \$46,2	
	SITE PERIMETER SECURITY FENCING/ADA GATES		00 Partial fencing complete (front of school), 2,400 LF remaining
	ALARM SYSTEM FIRE ALARM - NEW CAMPUS WIDE		00 Security 00 Based on JMPE recent school bids
	BACK-UP POWER GENERATORS		40 KW generator and a 100 amp transfer switch plus circuit rerouting. Based on JMPE 7.29.22 email.
	PARKING LOT LIGHTING	\$50,000 \$66,0	
10	NEW TRASH ENCLOSURES	\$65,000 \$85,8	
	IMPROVEMENT - GENERAL	40	
1	ROOFING a.REPAIRS	\$0 \$4,800 \$6,3	50 Based on Tremco Report 07.22
	b.GUTTERS/DOWNSPOUTS/FASCIA	\$20,000 \$26,4	
	c.REPLACE		50
2	PAINTING		
	a. INTERIOR		40 @\$4000/classroom x 13
_	b. EXTERIOR	\$75,000 \$99,0	
	HVAC - NEW AC COOLING ELECTRICAL IMPROVEMENTS (NON LIGHTING)		00 01.22 Comparative HESD Estimate
	ELECTRICAL IMPROVEMENTS (NON-LIGHTING) FLOOR FINISH REPLACEMENT - LUXURY VINYL TILE	\$50,000 \$66,0 \$130,000 \$171,6	00 Infrastructure to support technology
	DOORS & HARDWARE		00 Based on HESD 2022
	CEILING RESTORATION OR REPLACEMENT	\$50,000 \$66,0	
8	WINDOW REPLACEMENT AND WINDOW COVERINGS		00 HESD VV BID 10/22
	NEW CLASSROOM FURNITURE (21st Century)		00 \$15,000 per classroom x 27-6=21
10	INTERIOR LIGHTING	\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
C DIJUDING	IMPROVEMENT - SPECIFIC BUILDINGS AS APPLICABLE		
	LIBRARY FIXTURE UPGRADE	\$4,600 \$6,0	77
	RESTROOM UPGRADES/SIGNAGE	\$15,000 \$19,8	
	CONVERT LIBRARIES TO MEDIA CENTERS	\$80,000 \$105,6	
4	MPR TABLES	\$15,000 \$19,8	
5	INSTALL WALLS @ MPR	\$35,000 \$46,2	
D ADDITION	AL MADOUESAESAES		
	AL IMPROVEMENTS FOOD SERVICE	\$0	50
	IMPROVE ADMIN OFFICE (SPACE PLAN)	\$50,000 \$66,0	
	PARKING LOT/IMPROVEMENTS/EXPANSION	\$40,000 \$52,8	
	OGY IMPROVEMENT		
1	IT REQUIREMENTS	\$200,000 \$264,0	
F SITE IMPRO	OVEMENT		
	IRRIGATION UPGRADE	\$20,000 \$26,4	00 Needs additional coverage
	GRADING/DRAINAGE IMPROVEMENTS	\$40,000 \$52,8	
	LANDSCAPING	\$20,000 \$26,4	
	PLAYGROUND CONTAINMENT	\$15,000 \$19,8	
	PLAYGROUND RUBBERIZED FALL MEDIA 11,000 sq ft		00 Includes ADA access
	PLAYGROUND - KINDER UPGRADES VINDERCADTEN CLASSPOONA INARROVEMENTS	\$25,000 \$33,0	
	KINDERGARTEN CLASSROOM IMPROVEMENTS PAVING RESTORATION OR REPLACEMENT	\$30,000 \$39,6 \$764,000 \$1,008,4	00 80 Based on PEI report, 2018 escalated to 2023
	TURF IMPROVEMENTS/REPAIR	\$120,000 \$1,008,4	·
	CAMPUS SITE SIGNAGE	\$20,000 \$26,4	
	NEW MARQUEE SIGNS		00 07.22 DPHS Bid
	SHADE STRUCTURE	\$200,000 \$264,0	
	NEW BASKETBALL STANDARDS	\$20,000 \$26,4	
	OUTDOOR BOTTLE FILLER (3)	\$6,000 \$7,9	
	STORAGE BUILDINGS SWITCHGEAR REPLACEMENT	\$20,000 \$26,4 \$40,000 \$52,8	00 Verify CUSD 7.22 CHS
	ILLUMINATE SITE FLAG	\$15,000 \$19,8	
1,		Ç15,000 Ş15,0	
G REPLACEM	IENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT BUILDINGS		
	14 CLASSROOM BUILDINGS		00 \$600/SF @ 1000 SF
	NEW RESTROOM BUILDING		00 \$800/SF @ 1000SF
3	6 NEW KINDERGARTEN CLASSROOMS	\$6,720,000 \$8,870,4	00 \$700/ SF @ 1600SF
	TOTAL	\$22,104,400 \$29,177,8	
		722,104,40U 323,1/7,8	···

	LOMPOC UNIFIED SCHOOL DISTR	CT NEEDS ASSESSMENT 2023-2028 N	1ASTER PLAN	
				NOTES
The same of the sa	LOMPOC VALLEY MIDE	LE SCHOOL		
		2022 Needs	2026 Escalation	6.22 STUDENT ENROLLMENT 830, STAFF ± 85
		Assessment	2020 Escalation	0.22 STODENT ENNOCHMENT 630, STALL ± 65
A HEALTH & SAFETY	TARRE (SIREWALKS	440.000	ģ52.000	
	ZARDS / SIDEWALKS Y CAMERAS -15 NEW CAMERAS	\$40,000 \$75,000		Includes server
	ATEMENT	\$75,000		
	DM SYSTEM	\$50,000		
	IMETER SECURITY FENCING	\$975,000		
6 ALARM S		\$75,000		
	ARM - NEW CAMPUS WIDE	\$350,000		Based on JMPE recent school bids
	P POWER GENERATORS	\$80,000		160 amp ATS and a 50 KW generator
9 PARKING		\$20,000		
10 NEW TRA	ASH ENCLOSURES	\$65,000	\$85,800	
B BUILDING IMPROVE	MENT CENEDAL			
1 ROOFING		\$0	\$n	Based on Tremco Report 07.22, Gym not reviewed
a.REPAIR		\$15,800		
	ERS/DOWNSPOUTS/FASCIA	\$0		
c.REPLAC		\$203,000		Administration Bldg
2 PAINTING				Note: This campus has " Dimensional" Painting - 10% higher cost
a. INTERI		\$164,000		@ \$4000/classroom x 41
b. EXTER		\$85,000		
	NEW AC COOLING	\$1,800,000		01.22 Comparative HESD Estimate and added A/C cooling loads
	CAL IMPROVEMENTS (NON-LIGHTING			Infrastructure to support technology
	REPLACEMENT & HARDWARE	\$250,000		Based on HESD 2022
	RESTORATION OR REPLACEMENT	\$500,000 \$15,000		
	W REPLACEMENT AND WINDOW CO			
	ASSROOM FURNITURE	\$615,000		\$15,000/Classroom x 41
	R LIGHTING	\$0		Interior lighting was replaced with LED between 9/2017 and 9/2019.
			· · · · · · · · · · · · · · · · · · ·	
	MENT - SPECIFIC BUILDINGS AS APP		·	
	FIXTURE UPGRADE	\$9,200		
	SIUM MODERNIZATION	\$8,000,000	\$10,560,000	Similar to CHS Gym Modernization
	ERNIZE LOCKER ROOMS			
	S UPGRADED CE BLEACHERS			
	ET ELECTRIC LIFT STATIONS			
	RFACE GYM FLOORS			
	PA SYSTEM, SCORE			
	OM UPGRADES/SIGNAGE	\$10,000	\$13,200	
4 MODERN	NIZE & EXPAND (E) MUSIC BLDG	\$5,000,000		
5 MPR TAB	BLES	\$25,000	\$33,000	
D ADDITIONAL IMPROV	OVEMENTS			
1 FOOD SEI		N/A		
	E ADMIN OFFICE (SPACE PLAN)	\$50,000 \$20,000		
	G LOT/IMPROVEMENTS/EXPANSION FETERIA BUILDING WITH INDOOR DI			Parking is adaquate - figure repairs and reseal
	ROOM EXPANSION	\$5,500,000		
	C INSTRUMENT STORAGE	\$250,000	4330,000	
 	C LIBRARY			
c. MUSIC				
E TECHNOLOGY IMPRO				
1 IT REQUII	IREMENTS	\$400,000	\$528,000	
E CITE IN ARE 2017	_			
F SITE IMPROVEMENT 1 IRRIGATION		Ć40.000	ć22.7C0	Currently in good change, repairs hydget
	G/GRADING IMPROVEMENTS	\$18,000 \$40,000		Currently in good shape - repairs budget
3 LANDSCA		\$40,000		
	RESTORATION OR REPLACEMENT	\$20,000		Based on PEI report, 2018 escalated to 2023
	IPROVEMENTS/REPAIR	\$450,000		
 	S SITE SIGNAGE	\$25,000		
	ARQUEE SIGNS	\$25,000	\$33,000	07.22 DPHS Bid
8 SHADE ST		\$40,000		
	SKETBALL STANDARDS	\$35,000		
	OR BOTTLE FILLER (2)	\$10,000		
11 STORAGE		\$20,000		To replace existing
	GEAR REPLACEMENT DE TRACK SURFACE	\$50,000		Verify CUSD 7.22 CHS
15 UPGKADI	L INACK SURFACE	\$250,000	\$330,000	
G SITE SPECIFIC				
1 ALL WEA	ATHER TRACK	\$250,000	\$330,000	
	PATIO ASPHALT WITH CONCRETE	\$300,000		
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	0-PLUS YEAR OLD PORTABLE BUILDI			
1 4 CLASSR	ROOM BUILDINGS	\$3,120,000	\$4,118,400	\$650/SF @ 1200 SF
		TOTAL \$31,350,000	\$41,382,000	

and is still				
	LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT	T 2023-2028 MA	STER PLAN	NOTES
The Country State Line	VANDENBERG MIDDLE SCHOOL			NOTES
		2022 Needs	2026 Escalation	6.22 STUDENT ENROLLMENT 584, STAFF ± 65
A LIFALTIL & CAFETY		Assessment	2020 Escalation	0.22 STODENT ENNOLUMENT 384, STAIT ± 03
A HEALTH & SAFETY 1 TRIP HA	ZARDS / SIDEWALKS	\$73,600	\$97,152	
	TY CAMERAS - 15 CAMERAS	\$75,000		Includes Server
	BATEMENT	\$40,250	\$53,130	
	DM SYSTEM RIMETER SECURITY FENCING/ADA GATES	\$50,000 \$1,200,000	\$66,000 \$1,584,000	4 800 LE
6 ALARM		\$51,750	\$68,310	
	ARM MODIFICATIONS - NEW CAMPUS WIDE	\$350,000	\$462,000	Based on GUSD / CUSD 2017/ 2018 campus fire alarm modifications. Convert "stand alones" and carbon monoxide sensors.
	P POWER GENERATORS	\$80,000		160 amp ATS and a 50 KW generator
	G LOT LIGHTING ASH ENCLOSURES	\$20,000 \$65,000	\$26,400 \$85,800	
		13933	, , , , , ,	
B BUILDING IMPROVE		40	\$0	
1 ROOFIN		\$0 \$9,400	\$0 \$12,408	Based on Tremco Report 07.22
	ERS/DOWNSPOUTS/FASCIA	\$20,000	\$26,400	
c.REPLA		\$0	\$0	
2 PAINTIN a. INTER		\$176,000	ຽວວາ ວາດ	@ \$4000/classroom x 44
b. EXTER		\$176,000	\$232,320	דד א ווועטונעטווער שיט איז
3 HVAC - N	NEW AC COOLING	\$1,800,000	\$2,376,000	01.22 Comparative HESD Estimate and added A/C cooling loads
	CAL IMPROVEMENTS (NON-LIGHTING)	\$34,500		Infrastructure to support technology
	REPLACEMENT & HARDWARE	\$250,000 \$500,000	\$330,000 \$660,000	Based on HESD 2022
	RESTORATION OR REPLACEMENT	\$50,000	\$66,000	
	W REPLACEMENT AND WINDOW COVERINGS	\$20,000	\$26,400	
9 NEW CL	ASSROOM FURNITURE	\$660,000 \$0		\$15,000/Classroom x 50 Interior lighting was replaced with LED between 9/2017 and 9/2019.
TO INVIENCE	A CONTINO	30	Ç	micron ignating was replaced with the between 3/2017 and 3/2013.
	EMENT - SPECIFIC BUILDINGS AS APPLICABLE			
	/ FIXTURE UPGRADE	\$50,000	\$66,000	Pacad as civilar CUS Cum Madarnization
	ODERNIZATION ERNIZE LOCKER ROOMS	\$8,000,000	\$10,560,000	Based on similar CHS Gym Modernization
	TS UPGRADED			
	ACE BLEACHERS			
	ET ELECTRIC LIFT STATIONS RFACE GYM FLOORS			
	PA SYSTEM, SCORE			
	OM UPGRADES/SIGNAGE	\$10,000	\$13,200	
4 MPR TAI	BLES	\$25,000	\$33,000	
D ADDITIONAL IMPRO	DVEMENTS			
1 FOOD SE	ERVICE	N/A	N/A	
	/E ADMIN OFFICE (SPACE PLAN)	\$50,000	\$66,000	
	G LOT/IMPROVEMENTS/EXPANSION ROOM EXPANSION	\$250,000 \$1,500,000	\$330,000 \$1,980,000	
	DE TRACK SURFACING (RUBBERIZED)	\$500,000	, ,,,,,,,,	
6 FLAG ILL	LUMINATION	\$15,000		
E TECHNOLOGY IMPR	ROVEMENT			
1 IT REQU		\$368,000	\$485,760	
	_			
F SITE IMPROVEMENT 1 IRRIGAT		\$18,000		Exterior parking lot pole lights were replaced with LED lighting in 2016. Currently in good shape - figure repairs
2 GRADIN		\$40,000	\$52,800	own county on Book shakes in Desire Lebrains
3 LANDSC	APING	\$40,000	\$52,800	
	RESTORATION OR REPLACEMENT MPROVEMENTS / REPAIR	\$407,900 \$1,000,000	\$538,428 \$1,320,000	Based on PEI report, 2018 escalated to 2023
	S SITE SIGNAGE	\$1,000,000	\$1,320,000	
7 NEW MA	ARQUEE SIGNS	\$25,000	\$33,000	07.22 DPHS Bid
	STRUCTURE STANDARDS	\$40,000	\$52,800 \$46,300	
	SKETBALL STANDARDS OR BOTTLE FILLER (5)	\$35,000 \$25,000	\$46,200 \$33,000	
	SE BUILDINGS	\$20,000		To replace existing
12 SWITCH	GEAR REPLACEMENT	\$50,000	\$66,000	Verify CUSD 7.22 CHS - JMPE
G SITE SPECIFIC				
	OLLEYBALL COURT	\$500,000	\$660,000	
H REPLACEMENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT BUILDINGS 1 8 CLASSROOM BUILDINGS \$ \$6,240,000 \$8,236,800 \$650/SF @ 1200 SF				
1 8 CLASSI	NOON BUILDINGS	\$6,240,000	90,235,8UU	J0.70/31 € 1500.31
	TOTAL	\$24,834,400	\$32,781,408	

	TOPE IN STREET	LOMPOC	UNIFIED SC	HOOL DISTRICT NEEDS ASSESSMENT 2023-20	28 MASTER PLAN	
	<u> </u>	CARDI		H SCHOOL		NOTES
	San	CABNI	LLO HIG	2022 Needs		
				Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 986, STAFF ± 90
	LTH & SAFE					
		HAZARDS / SIDE		\$25		
		JRITY CAMERAS - D ABATEMENT	30 CAMERA	\$ \$150 \$50		10 Includes server
		RCOM SYSTEM		\$75		
		PERIMETER SECU	IRITY FENCII			00 6,000 LF includes fencing in student parking lot
		RM SYSTEM : ALARM - NEW CA	VADLIC WID	\$95 E \$400		
		K-UP POWER GEN		\$100		10 200 amp ATS and an 80 KW generator
		V TRASH ENCLOSU		\$65		
		OVEMENT - GENI OFING	RAL		\$0 \$	io Based on Tremco Report 07.22
		PAIRS		\$26		, , , , , , , , , , , , , , , , , , ,
		JTTERS/DOWNSP	OUTS/FASCI		\$0 \$	
		PLACE		\$1,883	,000 \$2,485,56	50 2023
		NTING ITERIOR		\$292	.000 \$385 44	10 \$4,000/ classroom x 73
		KTERIOR		\$750		
		C - NEW AC COOL		\$3,000	,000 \$3,960,00	
		CTRICAL IMPROVE		N-LIGHTING) \$125 \$750		
		OR REPLACEMEN ORS & HARDWARE		\$750		00 Based on HESD 2022
	7 CEIL	ING RESTORATIO	N OR REPLA	CEMENT \$500	.000 \$660,00	00
				NDOW COVERINGS \$250		
		CLASSROOM FU		\$1,500 OMS (includes doors) \$2,500		00 \$20,000/classroom x 75
		RIOR LIGHTING	@ CLASSIC	(NICidaes 40013) \$22,300		10 Interior lighting was replaced with LED between 9/2017 and 9/2019.
				IGS AS APPLICABLE	000 605.00	
		ARY FIXTURE UPO	KADE	\$65	.000 \$85,80	
		OORS		\$65	.000 \$85,80	
		OYS LOCKER		\$225		
		irls Locker Da bleacher up	CBADEC	\$225		00 Includes Handrails
		ATER BUILDING U		\$35	,000 \$46,20	includes Handralis
		EW SEATING		\$200	.000 \$264,00	
		NISHES/LIGHTING		\$100		
,	4 RES	TROOM UPGRADE	S/SIGNAGE	\$50	.000 \$66,00	
		MPROVEMENT				
	1 IT RI	EQUIREMENTS		\$250	.000 \$330,00	
E SITE	IMPROVEN	/ENT				Exterior parking lot pole lights were replaced with LED lighting in 2016.
	1 IRRI	GATION UPGRAD	E	\$50		00
		DING		\$50		
		DSCAPING ING RESTORATION	N OR REPLA	\$200 CEMENT \$1,942		10 18 Based on PEI report, 2018 escalated to 2023
		F IMPROVEMENT		\$100		100 100000 SF previously completed
	6 CAN	1PUS SITE SIGNAC		\$30	.000 \$39,60	
		DE STRUCTURE V BASKETBALL STA	MDABDS	\$200 \$15		
		DOOR BOTTLE FIL		\$15		70 8,000/STATION
	10 STO	RAGE BUILDINGS		\$25	.000 \$33,00	
		TCHGEAR REPLAC		\$65		
1	12 PER	MITER FENCE/ GA	IES	\$250	.000 \$330,00	
F						
		WEATHER TRACK		\$400		
		DIUM - NEW CON				00 Artifical turf, lights, scoreboard, track and field, P.A.
		EBALL & SOFTBAL		ESTORATION \$150 PRATION OR REPLACEMENT \$7,000		100 Includes PA System, Varisty lighting was installed in 2020 100 Aquatics Center
		NT UNDERSIDE OF				10 School colors preferred
		O SHOP ALIGNME				
6 255	A C E A 4 E 1 : =	OE 30 BLUG VE : -	OLD DOCT	DIE BUILDINGS/ DEBMANIENT BUILDINGS		
		OF 20-PLUS YEAR ASSROOM BUILD		BLE BUILDINGS w/ PERMANENT BUILDINGS \$2,160	,000 \$2,851,20	5700/SF @ 1,400 SF
				TOTAL \$37,908	.300 \$50,038,95	56 56
				TOTAL \$37,908	\$50,038,95	56

PRINTE IN STUDIO	LOMPOC UNIFIE	SCHOOL DIST	RICT NEEDS ASSESSMENT 2023-2028	MASTER PLAN	
	LOMPOC H	GH SCHO			NOTES
The State of the S	LOIVII OC II	dir scrio	2022 Needs		
			Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 1,740, STAFF ± 90
A HEALTH & SAFETY	ADDS / SIDENIAL KS		425.00	422.000	
	ARDS / SIDEWALKS CAMERAS - 30 CAI	ΛFRAS	\$25,000 \$150,000		Includes Server
3 LEAD ABA		TETO IS	\$50,000		
	M SYSTEM		\$75,000		
5 SITE PERI 6 ALARM S	METER SECURITY F	ENCING	\$1,425,000 \$75,000		Partial fencing complete, Prior bid for full project was \$350,000, 5,700 LF remaining inloudes enclosing student parking lot
	RM - NEW CAMPUS	WIDE	\$400,000		
	POWER GENERATO		\$100,000		200 amp ATS and an 80 KW generator
9 NEW TRA	ASH ENCLOSURES		\$65,000	\$85,800	
B BUILDING IMPROVE	MENT - GENERAL				
1 ROOFING			\$(\$0	Based on Tremco Report 07.22
a.REPAIR	S		\$23,000	\$30,360	
	RS/DOWNSPOUTS/	ASCIA	\$(· ·	
c.REPLAC 2 PAINTING			\$(\$0	
a. INTER			\$268,000	\$353,760	\$4,000/classroom x 67
b. EXTER			\$750,000		
	EW AC COOLING AL IMPROVEMENT	(NON LICUT	\$2,500,000 NG) \$125,000	_	01.22 Comparative HESD Estimate and added A/C cooling loads
	EPLACEMENT	(NON-LIGHTI	\$125,000		
	HARDWARE		\$900,000		Based on HESD 2022
	RESTORATION OR R		\$1,000,000		
	/ REPLACEMENT AN SSROOM FURNITU		OVERINGS \$500,000 \$1,480,000		\$20,000/ Classroom x 74
	ONTS PANELS @ CL				
12 INTERIOR	LIGHTING		\$(\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
C BUILDING IMPROVE	MENT COECIEIC DI	II DINCE AC AC	DUCARIE		
1 LIBRARY		ILDINGS AS AF	PLICABLE		
	RE UPGRADE - LIGH	S AND FINISH	\$1,500,000		
	ESTROOMS - NEEDE	D	\$80,000		
	IUM FLOORS OM UPGRADES/SIGN	AGE	\$65,000		
	IUM IMPROVEMEN		\$500,000		
	CAL/MUSIC BUILDIN				Little theater expansion
6 AUTO SH	OP IMPROVEMENT	S (CTE)	\$500,000	\$660,000	
D TECHNOLOGY IMPRO	OVEMENT				
1 IT REQUI	REMENTS		\$250,000	\$330,000	
E CITE IN ADD OVER ASNIT					
E SITE IMPROVEMENT 1 IRRIGATION	ON UPGRADE		\$50,000		Exterior parking lot pole lights were replaced with LED lighting in 2016.
2 GRADING			\$50,000		
3 LANDSCA			\$200,000		
	RESTORATION OR R PROVEMENTS /REP.		\$2,290,500		Based on PEI report, 2018 escalated to 2023 Baseball field is completed
	SITE SIGNAGE	****	\$30,000		
7 SHADE ST	TRUCTURE		\$200,000	\$264,000	
	KETBALL STANDAR		\$15,000		
	R BOTTLE FILLER(8)		\$64,000		\$8,000/STATION
	HANDBALL AREA		\$15,000		
F SITE SPECIFIC 1 STADIUM	LIGHTING RESTOR	ATION OF BED	ACEMENT \$850,000	\$1,122,000	
	L & SOFTBALL FACI				
3 SWIMMI	NG POOL FACILITY I	ESTORATION	DR REPLACEMENT \$5,000,000	\$6,600,000	
	BLEACHERS AND A				
	/LOCKER ROOM RE	TUKATION	\$350,000 \$75,000		
	AG AREA		\$125,000		
	O-PLUS YEAR OLD P OOM BUILDINGS	ORTABLE BUILI	INGS w/ PERMANENT BUILDINGS \$4,320,000) ¢E 702 400	\$700/SF @1,400 SF
1 7 CLASSR	CON BOILDINGS		\$4,320,000	\$5,702,400), non-trailing in thou or
			TOTAL \$36,890,500	\$48,695,460	

LOMPOC UNIFIED SCHOOL DISTRICT NEEDS ASSESSMEN	T 2023-2028 MASTER PLAN	
		NOTES
MAPLE HIGH SCHOOL		
	2022 Needs 2026 Escalation	6.22 STUDENT ENROLLMENT 150, STAFF ± 20
	Assessment	0.22 STODENT LINKOLLIVILINI 130, STAFF 1 20
A HEALTH & SAFETY	¢25 000 ¢22 000	
1 TRIP HAZARDS / SIDEWALKS 2 SECURITY CAMERAS - 10 CAMERAS	\$25,000 \$33,000 \$50,000 \$66,000 Inc	ludes server
3 LEAD ABATEMENT	\$50,000 \$66,000	idues sei vei
4 INTERCOM SYSTEM	\$35,000 \$46,200	
5 SITE PERIMETER SECURITY FENCING		00 LF includes enclosing one parking lot for students
6 ALARM SYSTEM	\$75,000 \$99,000	
7 FIRE ALARM - NEW CAMPUS WIDE	\$400,000 \$528,000	
8 BACK-UP POWER GENERATORS 9 NEW TRASH ENCLOSURES	\$100,000 \$132,000 20 \$65,000 \$85,800	O amp ATS and an 80 KW generator
9 NEW TRASITENCEOSORES	\$65,600	
B BUILDING IMPROVEMENT - GENERAL		
1 ROOFING		sed on Tremco Report 07.22
a.REPAIRS	\$7,100 \$9,372	
b.GUTTERS/DOWNSPOUTS/FASCIA	\$20,000 \$26,400	
c.REPLACE 2 PAINTING	\$0 \$0	
a. INTERIOR	\$48,000 \$63,360 @	\$4000/classroom x 12
b. EXTERIOR	\$750,000 \$990,000	r services es
3 HVAC - NEW AC COOLING	\$2,500,000 \$3,300,000 01	22 Comparative HESD Estimate and added A/C cooling loads
4 ELECTRICAL IMPROVEMENTS (NON-LIGHTING)	\$125,000 \$165,000	
5 FLOOR REPLACEMENT		ssrooms in poor shape
6 DOORS & HARDWARE		sed on HESD 2022
7 CEILING RESTORATION OR REPLACEMENT 8 WINDOW REPLACEMENT AND WINDOW COVERINGS	\$500,000 \$660,000 Cla \$250,000 \$330,000	ssrooms in poor shape
9 NEW FURNITURE		0,000/ Classroom x 17
10 WALL REPAIR - INTERIOR		ssrooms are in poor shape
11 ADD ADA RESTROOMS	\$100,000 \$132,000	
12 INTERIOR LIGHTING	\$0 \$0 Int	erior lighting was replaced with LED between 9/2017 and 9/2019.
C BUILDING IMPROVEMENT - SPECIFIC BUILDINGS AS APPLICABLE	Ć1 200 000	
1 FOOD SERVICE IMPROVEMENTS 2 ADMIN OFFICE IMPROVEMENTS	\$1,200,000 \$1,584,000 \$750,000 \$990,000	
3 RESTROOM UPGRADES/SIGNAGE	\$20,000 \$26,400	
	7-37.13	
D TECHNOLOGY IMPROVEMENT		
1 IT REQUIREMENTS	\$250,000 \$330,000	
E CITE IN ADDOMES AFAIT		
E SITE IMPROVEMENT	\$50,000 \$66,000	
2 GRADING	\$50,000 \$66,000	
3 LANDSCAPING	\$200,000 \$264,000	
4 PAVING RESTORATION OR REPLACEMENT	\$89,800 \$118,536 Ba	sed on PEI report, 2018 escalated to 2023
5 TURF IMPROVEMENTS / REPAIR	\$50,000 \$66,000	
6 CAMPUS SITE SIGNAGE	\$30,000 \$39,600	
7 SHADE STRUCTURE 8 NEW BASKETBALL STANDARDS	\$100,000 \$132,000 \$15,000 \$19,800	
8 NEW BASKETBALL STANDARDS 9 OUTDOOR BOTTLE FILLER(3)		000/STATION, 2-3 stated in mm
10 STORAGE BUILDINGS	\$25,000 \$33,000	
11 SWITCHGEAR REPLACEMENT	\$65,000 \$85,800	
12 NEW CAMPUS MARQUEE	\$40,000 \$52,800	
F SITE SPECIFIC	\$22,000 \$22,000	
1 ADA PATH OF TRAVEL 2 IMPROVE VOLLEYBALL COURT	\$23,000 \$30,360 \$12,000 \$15,840	
3 MPR/ADMIN BLDG SOUTH SIDE REPAIR	\$12,000 \$15,840 \$15,840	
		
G REPLACEMENT OF 20-PLUS YEAR OLD PORTABLE BUILDINGS W/ PERMANENT B	UILDINGS	
1 3 CLASSROOM BUILDINGS	\$2,940,000 \$3,880,800 \$7	00/SF @1,400 SF
	442.072.000	
TOTAL	\$13,873,900 \$18,313,548	

	SHIPTON IN STUDIES	access —	LOMPOC UNIFIED SCH	OOL DISTRI	CT NEEDS ASSESSMENT		2023-2028 M	ASTER PLAN	NOTEC
									NOTES
	LANGED SCHOOL ST	3 '	LASCC, DR.FORINASH	CDS, MISSIC	ON VALLEY				
							2022 Needs Assessment	2026 Escalation	6.22 STUDENT ENROLLMENT 1,200 (LASCC) 30 (CDS), STAFF ± 21
Α	HEALTH &								
			RDS / SIDEWALKS				\$25,000	\$33,000	
			CAMERAS(20)				\$100,000		Includes server
	3	LEAD ABAT					\$50,000	\$66,000	
	4	INTERCOM					\$35,000	\$46,200	
			TETER SECURITY FENCIN	NG .			\$600,000	\$792,000	
		ALARM SYS					\$75,000	\$99,000	
			M - NEW CaMPUS WIDE				\$400,000	\$528,000	
	8		OWER GENERATORS				\$100,000		200 amp ATS and an 80 KW generator
	9	NEW TRAS	H ENCLOSURES				\$65,000	\$85,800	@\$3/SF
В	BUILDING I	 MPROVEM	ENT - GENERAL						
		ROOFING	_				\$0	\$0	Based on Tremco Report 07.22
		a.REPAIRS					\$4,500	\$5,940	
			S/DOWNSPOUTS/FASCI	Α			\$20,000	\$26,400	
		c.REPLACE	·				\$800,000		MPR TDB (2023)
	2	PAINTING					7555,556	71,030,000	····· \ /
		a. INTERIO	R				\$48,000	\$63.360	@ \$4000/classsroom x 17
		b. EXTERIO					\$750,000	\$990,000	
	3		W AC COOLING				\$2,500,000		01.22 Comparative HESD Estimate and added A/C cooling loads
			L IMPROVEMENTS (NO	N-HGHTING	3)		\$125,000	\$165,000	
	7		PLACEMENT (NO	IN-LIGITIINC	')			\$990,000	
	,						\$750,000		Based on HESD 2022
			HARDWARE ESTORATION OR REPLACE	CENAENIT			\$900,000		
					VEDINICS.		\$500,000	\$660,000	
			REPLACEMENT AND WI	NDOW COV	ERINGS		\$250,000	\$330,000	
		NEW FURN					\$380,000		\$20,000/ Classroom x 19
	13	INTERIOR I	LIGHTING				\$0	\$0	Interior lighting was replaced with LED between 9/2017 and 9/2019.
_	DI III DINIC I		ENT. CDECIFIC DUILDIN	ICC AC ADDI	ICADI F				
С			ENT - SPECIFIC BUILDIN	IGS AS APPL	ICABLE			ćo	
		a. FIXTURE	POSE/CAFÉ				Ć 40.000	\$0	
							\$40,000	\$52,800	
		b. ADA RES					\$50,000	\$66,000	
		c. FLOORS					\$30,000	\$39,600	
С	TECHNOLO	 GY IMPRO\	VEMENT						
	1	IT REQUIRE	EMENTS				\$250,000	\$330,000	
D	SITE IMPRO	1							Exterior parking lot pole lights were replaced with LED lighting in 2016.
	1		N UPGRADE				\$15,000	\$19,800	
		GRADING					\$25,000	\$33,000	
		LANDSCAP					\$30,000	\$39,600	
	4		STORATION OR REPLAC	CEMENT			\$8,000		Based on PEI report, 2018 escalated to 2023
	5		ROVEMENTS / REPAIR				\$20,000	\$26,400	
	6		ITE SIGNAGE				\$30,000	\$39,600	
	7	NEW BASK	ETBALL STANDARDS				\$15,000	\$19,800	
	8	OUTDOOR	BOTTLE FILLER(4)				\$32,000		\$8,000/STATION, stated in mm
	9	STORAGE E	BUILDINGS				\$25,000	\$33,000	
	10	SWITCHGE	AR REPLACEMENT				\$65,000	\$85,800	
E	SITE SPECIF	FIC							
	1	ADA PATH	OF TRAVEL				\$92,000	\$121,440	
F	REPLACEM	ENT OF 30-	PLUS YEAR OLD PORTA	BLE BUILDIN	IGS w/ PERMANENT BU	ILDINGS			
		1	OM BUILDINGS				\$517,500	\$683.100	\$700/SF @1,400 SF
I.	. –	500					+==,,550	+ 555,200	· · · · · · · · · · · · · · · · · · ·

	LOMPOC (UNIFIED SCHOOL DISTRICT NEEDS ASSESSMENT	2023-2028 MASTER PLA			
	FDUCATIO	DN CENTER		NOTES		
THE SCHOOL	LDOCATIO	NCENTEN	2022 Needs	2026		
			Assessment	Escalation		
Building I	 mprove	ments	7.555551116116	Esculation		
). Lobby					
	1	ve Reception Area for security	\$40,000	\$52,800 Currently the receptionist has their back to the public		-
	-	Electronic Entrance button	\$12,000	\$15,840 Controlled at the reception desk to allow entrance		_
		e ADA Counter Height	\$4,000	\$5,280		_
		orroof Foundation	\$40,000	\$52,800 On the west side - currently has issues		_
	-	de Electrical Systems	\$120,000	\$158,400		_
		de HVAC Systems	\$80,000	\$105,600		
		e Data and Server Rooms	\$200,000	\$264,000		
Н.	Interio	r Lighting Upgrades	\$150,000	\$198,000		
2 M.	and O. F	Facilities				
	New Ro					
	1	Central Services Building	\$120,000	\$158,400 May 13, 2022 quote from Channel Islands Roofing		
	2	Maintenance Building	\$130,000	\$171,600 May 13, 2022 quote from Channel Islands Roofing		
	3	Warehouse Building	\$70,000	\$92,400 May 13, 2022 quote from Channel Islands Roofing		
В.	Upgrad	de Electrical Systems	\$150,000	\$198,000		
C.	Upgrad	de HVAC Systems	\$85,000	\$112,200		_
D.	Upgrac	de Plumbing	\$60,000	\$79,200		_
E.	Interio	r Lighting Upgrades	\$140,000	\$184,800 All interior lighting was replaced with LED between 9/2017 & 9/2019		
		TOTAL	\$1,401,000	\$1,849,320		
						_
						_

Agenda for Site Principals Interviews

A. WHAT IS YOUR NUMBER ONE SITE NEED?

B. CAMPUS SITE ITEMS

- 1. SECURITY/ SINGLE POINT OF ENTRY
- 2. SIGNAGE/ WAY FINDING
- 3. VISITOR PROCEDURES
- 4. FENCING
- 5. PARKING: DROP-OFF/ PICKUP
- 6. PLAYGROUNDS, PLAY EQUIPMENT, PLAY FIELDS
- 7. INTERCOM SYSTEMS

C. CLASSROOMS

- 1. PHYSICAL CONDITIONS
 - a. Flooring
 - b. Ceilings
 - c. Windows
 - d. Painting
 - e. Cabinets
 - f. Furniture
 - g. Alarming
- 2. TEACHING SUPPORT
 - a. Flexibility to Support Hybrid Teaching
 - b. Fixed items
 - c. I.T. Systems
 - d. Phone Systems
- 3. SPACE FOR NURSES/ COUNSELING

D. NUMBER OF CLASSROOMS ON SITE AND POTENTIAL INCREASES DUE TO UPCOMING UTK ENROLLMENTS

E. MULTIPURPOSE ROOMS

- 1. HOW ARE THEY USED
- 2. FOOD PREP and DELIVERY
- 3. BUILT-IN DINING TABLES/ BENCHES
- 4. KITCHEN AREA

F. HIGH SCHOOLS

- GYMS, WEIGHT ROOMS
- 2. POOLS
- 3. TRACK AND FIELD
- 4. SCORE BOARDS, P.A. SYSTEMS

G. COMMUNITY USE

Site	Room	Use	W/D	Size	R/R	Serial	Make	Year	DSA#
Mig	20	Class	Wet	30x32	N	Scheduled for demolish 22/23		1985	A49830, A49830, A49830
Mig	21	Class	Wet	30x32	N	Scheduled for demolish 22/23		1985	A49830, A49830, A49830
La Honda	24	Class	Dry	30X32	N		Steelguard	1989	A49830, A49830, A49830
La Honda	25	Class	Dry		N		Steelguard	1989	A49830, A49830, A49830
La Honda	26	Class	Dry	30x32	N		Steelguard	1989	A63681, A63681, A63681,
LHS	AG3	Class	Dry	24x40	N	2BAC666,2BAC667	Modular Structures	1990	
La Canada	11	Class	Dry	30x32	N		Steelguard	1990	66283
La Canada	12	Class	Dry	30x32	N		Steelguard	1990	
La Canada	13	Class	Dry	30x32	N		Steelguard	1990	
La Canada	14	Class	Dry	30x32	N	8985,8986,8987	Steelguard	1990	52500
La Canada	15	Class	Dry	30x32	N	8988,8989,8990	Steelguard	1990	52500
La Canada	16	Class	Dry	30x32	N	8666,8667,8668	Steelguard	1990	52500
La Canada	17	Class	Dry	30x32	N	8669,8670,8671	Steelguard	1990	52500
La Canada	18	Class	Dry	30x32	N	8672,8673,8674	Steelguard	1990	52500
Fillmore	P1	Class	Dry	30x32	N	8660, 8661, 8662	Steelguard	1992	A52500, A52500, A52500
Fillmore	P2	Class	Dry	30x32	N	8659, 8658, 8657	Steelguard	1992	A52500, A52500, A52500
Fillmore	Р3	Class	Dry	30x32	N	8970, 8971, 8972	Steelguard	1992	A52500, A52500, A52500
Fillmore	P4	Class	Dry	30x32	N	8965, 8966, 8967	Steelguard	1992	A52500, A52500, A52500
Fillmore	P5	Class	Dry	30x32	N	12004, 12005, 12006	Steelguard	1992	A56104, A56104, A56104
Fillmore	P6	Class	Dry	30x32	N	11998, 11999, 12000	Steelguard	1992	A56104, A56104, A56104
Fillmore	P7	Class	Dry	30x32	N	12001, 12002, 12003	Steelguard	1992	A56104, A56104, A56104
Hapgood	P1	Class	Dry	30x32	N	8958, 8959, 8960	Modtech	1992	A52500, A52500, A52500
Ruth	22	Class	Dry	30x32	N		Steelguard	1992	A03-52500, A03-52500, A03-52500
Ruth	23	Class	Dry	30x32	N		Steelguard	1992	A03-52500, A03-52500, A03-52500
Ruth	24	Class	Dry	30x32	N		Steelguard	1992	A03-52500, A03-52500, A03-52500
Ruth	25	Class	Dry	30x32	N		Steelguard	1992	A03-52500, A03-52500, A03-52500
Ruth	26	Class	Dry	30x32	N		Steelguard	1992	A03-52500, A03-52500, A03-52500
Ruth	27	Class	Dry	30x32	N			1992	A03-56104, A03-56104, A03-56104
Ruth	28	Class	Dry	30x32	N			1992	A03-56104, A03-56104, A03-56104
Ruth	29	Class	Dry	30x32	N			1992	A03-56104, A03-56104, A03-56104
Ruth	30	Class	Dry	30x32	N			1992	A03-56104, A03-56104, A03-56104
Mig	22	Class	Dry	30x32	N		Steelguard	1993	A59911, A59911, A59911
Mig	23	Class	Dry	30x32	N		Steelguard	1993	A59911, A59911, A59911
La Honda	21	Class	Dry	30x32	N	15439, 15438, 15437	Modtech	1994	A62215, A62215, A62215
La Honda	27	Class	Dry	30X32	N	95-R196-005A, 95-R196-005B, 95-R196-005C	American Modular	1995	A63681, A63681, A63681
Mig	24	Class	Wet	30x32	N	95R196-001A, 95R196-001B, 95R196-001C	American Modular	1995	A63129, A63129, A63129
Mig	25	Class	Wet	30x32	N	95-R196-002A, 95-R196-002B, 95-R196-002C	American Modular	1995	A63129, A63129, A63129
Mig	26	Class	Wet	30x32	N	95-R196-003A, 95-R196-003B, 95-R196-003C	American Modular	1995	A63129, A63129, A63129
Mig	27	Class	Wet	30x32	N	95-R196-004A, 95-R196-004B, 95-R196-004C	American Modular	1995	A63129, A63129, A63129

Mig	RR	RR	Wet		Υ			1995	A63129, A63129
Crestview	RR	RR	Wet		Υ			1995	
Mig	28	Class	Dry	30x32	N	96-R254-001A, 96-R254-001B, 96-R254-001C	American Modular	1996	A65052, A65052, A65052
Ruth	43	SELPA	Wet	24x40	Υ	96-R288-001A	American Modular	1996	95240
Ruth	42	SELPA	Wet		Υ			1996	66283
La Honda	28	Class	Dry	30X32	N	97-R288-002A, 97-R288-002B, 97-R288-002C	American Modular	1997	A60791, A60791, A60791
La Honda	29	Class	Dry	30x32	N	97R288-006A, 97-R288-006B, 97-R288-006C	American Modular	1997	A67855, A67855, A67855
La Honda	30	Class	Dry	30X32	N			1997	
Fillmore	None	CAC	Wet	30x32	Υ			1997	
Fillmore	None	CAC	Wet	30x32	Υ			1997	
Hapgood	P4	Class	Wet	24x40	Υ	97-R288-020A, 97-R288-020B	American Modular	1997	A69453, A69453
Mig	29	Class	Dry	30x32	N	97-R288-008A, 97-R288-008B, 97-R288-008C	American Modular	1997	A68283, A68283, A68283
Mig	30	Class	Dry	30x32	N	97-R288-007A, 97-R288-007B, 97-R288-007C	American Modular	1997	A68283, A68283, A68283
Mig	31	Class	Dry	30x32	N	97-R288-003A, 97-R288-003B, 97-R288-003C	American Modular	1997	A67091, A67091, A67091
Mig	32	Class	Dry	30x32	N	97R288-001A, 97R288-001B, 97R288-001C	American Modular	1997	A67091, A67091, A67091
La Honda	32	Class	Dry	30X32	N	98-R359-001A, 98-R359-001B, 98-R359-001C	American Modular	1998	A100964, A100964, A100964
La Honda	33	Class	Dry	30X32	N	98-R359-002A, 98-R359-002B, 98-R359-002C	American Modular	1998	A100964, A100964, A100964
Buena	NA	YMCA	Dry	30x32	Υ	98-R288-021A, 98-R288-021B	American Modular	1998	A69919, A69919
Fillmore	P8	Class	Dry	30x32	N	97-R288-009A, 97-R288-009B, 97-R288-009C	American Modular	1999	A68283, A68283, A68283
Fillmore	P9	Class	Dry	30x32	N	97R288-010A, 97R288-010B, 97R288-010C	American Modular	1999	A68283, A68283, A68283
Fillmore	P10	Class	Dry	30x32	N	99-335-217-001A, 99-335-217-001B, 99-335-217-001C	Pacesetter	1999	A102628, A102628, A102628
Fillmore	P11	B&G	Dry	30x32	N	99-335-217-002A, 99-335-217-002B, 99-335-217-002C	Pacesetter	1999	A104116, A104116, A104116
Hapgood	P2	Class	Dry	30x32	N	97-R288-011A, 97-R288-011B, 97-R288-011C	American Modular	1999	A68283, A68283, A68283
Hapgood	Р3	Class	Dry	30x32	N	97-R288-012A, 97-R288-012B, 97-R288-012C	American Modular	1999	A68283, A68283, A68283
Ruth	31	Class	Dry	30x32	N	97-R288-004A, 97-R288-004B, 97-R288-004C	American Modular	1999	A03-67091, A03-67091, A03-67091
Ruth	32	Class	Dry	30x32	N	97-R288-005A, 97-R288-005B, 97-R288-005C	American Modular	1999	A03-67091, A03-67091, A03-67091
Ruth	33	Class	Wet	24x40	Υ	92-115-016A, 92-115-016B	American Modular	1999	A58364,A58364
Ruth	34	Class	Dry	30x32	N	97R288-016A, 97R288-016B, 97R288-016C	American Modular	1999	A03-67855, A03-67855, A03-67855
Ruth	35	Class	Dry	30x32	N	97-R288-017A, 97-R288-017B, 97-R288-017C	American Modular	1999	A03-67855, A03-67855, A03-67855
Ruth	36	Class	Dry	30x32	N	98-R359-001A, 98-R359-001B, 98-R359-001C	American Modular	1999	A03-100964, A03-100964, A03-100964
Ruth	37	Class	Dry	30x32	N	98-R359-005A, 98-R359-005B, 98-R359-005C	American Modular	1999	A03-100964, A03-100964, A03-100964
LHS	R1	Class	Dry	30x32	N	99-335-217-004A, 99-335-217-004B, 99-335-217-004C	Pacesetter	1999	03-102-689
LHS	R2	Class	Dry	30x32	N	99-335-217-003A, 99-335-217-003B, 99-335-217-003C	Pacesetter	1999	03-102-689
LHS	R3	Class	Dry	30x32	N	99-335-217-005A, 99-335-217-005B, 99-335-217-005C	Pacesetter	1999	03-102-689
El Camino	P1							1999	
El Camino	P2							1999	
La Canada	30	YMCA	Dry	30x32	N	97-R288-019A, 97-R288-019B, 97-R288-019C	American Modular	1999	A52500, A52500, A52500
La Canada	31	Class	Dry	30x32	N	97-R288-013A, 97-R288-013B, 97-R288-013C	American Modular	1999	A56104, A56104, A56104
La Canada	32	Class	Dry	30x32	N	97-R288-014A, 97-R288-014B, 97-R288-014C	American Modular	1999	A56104, A56104, A56104
La Canada	33	Class	Dry	30x32	N	97-R288-015A, 97-R288-015B, 97-R288-015C	American Modular	1999	A56104, A56104, A56104

La Canada	40	Class	Dry	30x32	N	98-R359-003A, 98-R359-003B, 98-R359-003C	American Modular	1999	03-100964
La Canada	41	Class	Dry	30x32	N	98-R359-004A, 98-R359-004B, 98-R359-004C	American Modular	1999	03-100964
Ed Cen	P8	0.0.00	Dry		N			2000	
La Honda	31	Class	Dry	30x32	N	2007065, 2007065, 2007065	Modular Structure	2000	A67855, A67855, A67855
LVMS	61	Class	Dry	30x32	N	11926,11927,11928	Steelguard	2000	Tag no longer visible
LVMS	64	Class	Dry	30x32	N	11989, 11990, 11991	Steelguard	2000	Tag no longer visible
Mig	33	Class	Dry	30x32	N			2000	-
Mig	34	Class	Dry	30x32	N			2000	
LHS	R4	Class	Dry	30x32	N	2AA7428, 2AA7429, 2AA7430	Modular Structures	2000	
LHS	R5	Class	Dry	30x32	N	2AA7056, 2AA7057, 2AA7058	Modular Structures	2000	
LHS	R6	Class	Dry	30x32	N	2AA7073, 2AA7074, 2AA7075,	Modular Structures	2000	
LHS	SP1	SMed	Dry		N	Moved from MV 7/16		2000	
LHS	SP2	SMed	Dry		N	Moved from MV 7/16		2000	
La Canada	42	Class	Dry	30x32	N	2AA7070, 2AA7069, 2AA7068	American Modular	2000	
Buena	P5	Class	Dry	24x40	N			2000	
Buena	P7	Class	Dry	24x40	N			2000	
Buena	P8	Class	Dry	24x40	N			2000	
Buena	P10	Class	Dry	24x40	N			2000	
Buena	P11	Class	Dry	24x40	N			2000	
VMS	T1	Class	Dry		N	Tag no longer visible		2000	
VMS	T2	Class	Dry		N	Tag no longer visible		2000	
VMS	T3	Class	Dry		N	Tag no longer visible		2000	
VMS	T4	Class	Dry		N	Tag no longer visible		2000	
VMS	T5	Class	Dry		N	Tag no longer visible		2000	
VMS	T6	Class	Dry		N	Tag no longer visible		2000	
VMS	B8	Class	Dry		N	Tag no longer visible		2000	
VMS	B9	Class	Dry		N	Tag no longer visible		2000	
Crestview	S1	Class	Wet		N			2000	
Crestview	S2	Class	Wet		N			2000	
Crestview	S3	Class	Wet		N			2000	
Crestview	J1	Class	Dry		N			2000	
Crestview	J2	Class	Dry		N			2000	
Crestview	J3	Class	Dry		N			2000	
LVMS	63	Class	Dry	30x32	N	2AJ8305,2AJ8306,2AJ8307	Modular Structure	2001	
Buena	P1	Class	Wet	24x40	Υ			2001	A53932,A53932
Buena	P2	Class	Wet	24x40	N			2001	A54178, A54178
Buena	Р3	Class	Dry	24x40	N	51311,51312	Modtech	2001	A105638, A105638
Crestview	R1	Class	Wet		N			2001	
Crestview	R2	Class	Wet		N			2001	
Crestview	R3	Class	Wet		N			2001	

Crestview	R4	Class	Wet		N			2001	
Crestview	R5	Class	Wet		N			2001	
Crestview	R6	Class	Wet		N			2001	
LVMS	62	Class	Dry	30x32	N	02-767-001A, 02-767-001B, 02-767-001C	American Modular	2002	03-106497
La Canada	-	Class	Wet		Υ	Moved from Ed Center (P1) in 2021		2002	
Los Berros	27	Class	Dry	30x32	N	Tag no longer visible	Steelguard	2002	A56103, A56103, A56103
Los Berros	28	Class	Dry	30x32	N	Tag no longer visible	Steelguard	2002	A56103, A56103
Los Berros	30	Class	Dry	30x32	N	Moved from Ed Cen in 2016		2002	, ,
Los Berros	31	Class	Dry	30x32	N	Moved from Ed Cen in 2016		2002	
Buena	P4	Class	Dry	24x40	N			2002	
Buena	P6	Class	Dry	24x40	N			2002	
CHS	P9	Selpa	Wet		Υ	Moved from Ed Center in 2016		2002	
CHS	P7	SMed	Wet		N	56426, 56427	Modtech	2002	03-108507
CHS	P8	SMed	Wet		N	56416, 56417	Modtech	2002	03-108507
Ruth	41	YMCA	Wet	36x40	Υ	38977,38978,38979	American Modular	2003	
Buena	P9	Class	Dry	24x40	N			2003	
LM/Maple	Р3	Class	Dry	30x32	N			2003	
Ed Cen	P17		Dry	30x32	N	05-108-013A, 05-108-013B, 05-108-013C	American Modular	2005	03-108-592
Ed Cen	P18		Dry	30x32	N	05-108-012A, 05-108-012B, 05-108-012C	American Modular	2005	03-108-592
Ed Cen	P19		Dry	30x32	N	05-108-014A, 05-108-014B, 05-108-014C	American Modular	2005	03-108-592
Ed Cen	P20		Dry	30x32	N	05-108-007A, 05-108-007B, 05-108-007C	American Modular	2005	03-108-593
Ed Cen	P21		Dry	30x32	N	05-108-008A, 05-108-008B, 05-108-008C	American Modular	2005	03-108-593
Ed Cen	P22		Dry	30x32	N	05-108-009A, 05-108-009B, 05-108-009C	American Modular	2005	03-108-593
Ed Cen	P23		Dry	30x32	N	05-108-006A, 05-108-006B, 05-108-006C	American Modular	2005	03-108-632
Ed Cen	RR	RR	Wet		Υ			2005	
Ed Cen	RR	Class	Wet		Υ			2005	
Fillmore	RR	RR	Wet		Υ	05-108-004A	American Modular	2005	03-108592
Ruth	RR	RR	Wet		Υ	05-108-005A	American Modular	2005	03108598
La Canada	RR	RR	Wet		Υ	05-108-003A	American Modular	2005	03-108597
Los Berros	29	Class	Dry	30x32	N	Moved from Ed Cen in 2016		2005	
LM/Maple	P1	Class	Dry	30x32	N	05-108-011A, 05-108-011B, 05-108-011C	American Modular	2005	03-108597
LM/Maple	P2	Lab	Dry	30x32	N	05-108-010A, 05-108-010B, 05-108-010C	American Modular	2005	03-108597
Buena	RR	RR	Wet		Υ			2009	

School Name	<u>Area</u>	Work Description	Last M&R	Area (sf)	<u>2019</u>	<u>2020</u>	<u>2021</u>	<u>2022</u>	2023	Subtotals
Buena Vista	Α	Remove & Replace	2016	60,000				\$360,000.00		\$360,000.00
Buena Vista	В	Surface Preparation & Overlay		6,158	\$20,895.00					\$20,895.00
Buena Vista	С	Digout, Crack Fill & Seal Coat		5,040				\$2,764.00		\$2,764.00
Buena Vista	D	Remove & Replace	2016	17,234				\$103,404.00		\$103,404.00
Buena Vista	E	Remove & Replace	2016	13,212				\$79,272.00		\$79,272.00
Buena Vista Elementary	Total			101,644						\$566,335.00
Cabrillo	Α	Remove & Replace	2016	10,292				\$61,752.00		\$61,752.00
Cabrillo	В	Remove & Replace	2016	42,600				\$255,600.00		\$255,600.00
Cabrillo	С	Remove & Replace	2018	34,500					\$207,000.00	\$207,000.00
Cabrillo	D	Remove & Replace	2018	5,300					\$31,800.00	\$31,800.00
Cabrillo	E	Remove & Replace	2018	6,656					\$39,936.00	\$39,936.00
Cabrillo	F	Remove & Replace	2018	65,000					\$390,000.00	\$390,000.00
Cabrillo	G	Remove & Replace	2015	130,037			\$780,222.00			\$780,222.00
Cabrillo High Total				294,385						\$1,766,310.00
Clarence Ruth	А	Crack Fill and Seal Coat	2016	14,650				\$8,057.50		\$8,057.50
Clarence Ruth	В	Remove & Replace		4,326	\$26,630.00					\$26,630.00
Clarence Ruth	С	Crack Fill and Seal Coat	2016	4,845				\$2,664.75		\$2,664.75
Clarence Ruth	D	Remove & Replace	2018	31,184					\$187,104.00	\$187,104.00
Clarence Ruth	Е	Remove & Replace	2018	37,780					\$226,680.00	\$226,680.00
Clarence Ruth	F	Remove & Replace	2018	2,040					\$12,240.00	\$12,240.00
Clarence Ruth Elementa	ry Total			94,825						\$463,376.25
Crestview	А	Remove & Replace	2018	15,482					\$92,892.00	\$92,892.00
Crestview	В	Remove & Replace	2018	33,204					\$199,224.00	\$199,224.00
Crestview	С	Crack Fill and Seal Coat	2018	76,243					\$41,933.65	\$41,933.65
Crestview	D1	Remove & Replace	2018	8,606					\$51,636.00	\$51,636.00
Crestview	D2	Remove & Replace	2018	7,971					\$47,826.00	\$47,826.00
Crestview Elementary To	otal			141,506						\$433,511.65
District Office	Α	Remove & Replace		8,100	\$43,000.00					\$43,000.00
District Office	В	Remove & Replace		6,984	\$41,904.00					\$41,904.00
District Office	С	Remove & Replace		31,980	\$162,900.00					\$162,900.00
District Office	D	Double Application Emulsion Seal Coat		54,718	\$19,179.50					\$19,179.50
District Office	Е	Double Application Emulsion Seal Coat		8,600	\$4,300.00					\$4,300.00
District Office	F	Double Application Emulsion Seal Coat		8,004	\$4,201.60					\$4,201.60
District Office	G	Remove & Replace		48,132	\$243,660.00					\$243,660.00
District Office	Н	Digout, Crack Fill & Seal Coat		20,450	\$11,635.00					\$11,635.00
District Office	I	Remove & Replace		42,224	\$214,120.00					\$214,120.00
District Office	J	Remove & Replace		50,679	\$257,395.00					\$257,395.00
District Office	K	Double Application Emulsion Seal Coat		5,109	\$2,554.50					\$2,554.50
District Office Total				284,980						\$1,004,849.60



School Name	<u>Area</u>	Work Description	Last M&R	Area (sf)	<u>2019</u>	<u>2020</u>	<u>2021</u>	2022	2023	Subtotals
El Camino	А	Crack Fill and Seal Coat		13,200	\$6,780.00					\$6,780.00
El Camino	В	Remove & Replace	2018	38,735					\$232,410.00	\$232,410.00
El Camino	С	Remove & Replace	2018	24,729					\$148,374.00	\$148,374.00
El Camino	D	Crack Fill and Seal Coat		2,986	\$1,493.00					\$1,493.00
El Camino Middle Total				79,650						\$389,057.00
Fillmore	А	Double Application Emulsion Seal Coat		16,225	\$10,990.00					\$10,990.00
Fillmore	В	Double Application Emulsion Seal Coat		3,960	\$3,980.00					\$3,980.00
Fillmore	С	Remove & Replace	2018	50,462					\$302,772.00	\$302,772.00
Fillmore	D	Remove & Replace	2015	6,010			\$36,060.00			\$36,060.00
Fillmore	E	Remove & Replace	2015	49,300			\$295,800.00			\$295,800.00
Fillmore	F	Remove & Replace	2015	4,080			\$24,480.00			\$24,480.00
Fillmore	G	Remove & Replace	2018	6,326					\$37,956.00	\$37,956.00
Fillmore	Н	Remove & Replace	2018	5,126					\$30,756.00	\$30,756.00
Fillmore Elementary Tot	tal			141,489						\$742,794.00
Hapgood	А	Remove & Replace	2018	13,530					\$81,180.00	\$81,180.00
Hapgood	В	Remove & Replace	2018	10,162					\$60,972.00	\$60,972.00
Hapgood	С	Crack Fill and Seal Coat	2016	25,616				\$14,088.80		\$14,088.80
Hapgood	D	Crack Fill and Seal Coat	2016	21,250				\$11,687.50		\$11,687.50
Hapgood	Е	Remove & Replace	2016	12,431				\$74,586.00		\$74,586.00
Hapgood	F	Remove & Replace		49,730	\$250,150.00					\$250,150.00
Hapgood	G	Digout, Crack Fill and Seal Coat		4,360	\$3,180.00					\$3,180.00
Hapgood	I	Crack Fill and Seal Coat		56,975				\$31,336.25		\$31,336.25
Hapgood Elementary To	otal			194,054						\$527,180.55
La Canada	Α	Remove & Replace		16,510					\$99,060.00	\$99,060.00
La Canada	В	Remove & Replace		20,300					\$121,800.00	\$121,800.00
La Canada	С	Remove & Replace		17,462					\$104,772.00	\$104,772.00
La Canada	D	Crack Fill and Seal Coat		2,490					\$1,369.50	\$1,369.50
La Canada	Е	Remove & Replace		7,960	\$41,800.00					\$41,800.00
La Canada	F	Double Application Emulsion Seal Coat		7,268	\$4,907.20					\$4,907.20
La Canada Elementary	Γotal			71,990						\$373,708.70
La Honda	А	Remove & Replace	2016	16,048				\$96,288.00		\$96,288.00
La Honda	B1	Remove & Replace		5,775	\$31,375.00					\$31,375.00
La Honda	B2	Remove & Replace		948	\$4,740.00					\$4,740.00
La Honda	C1	Crack Fill and Seal Coat	2016	23,085				\$12,696.75		\$12,696.75
La Honda	C2	Remove & Replace	2016	8,550				\$51,300.00		\$51,300.00
La Honda	D	Remove & Replace	2016	21,750				\$130,500.00		\$130,500.00
La Honda Elementary To	otal			76,156						\$326,899.75





School Name	<u>Area</u>	Work Description	Last M&R	Area (sf)	<u>2019</u>	<u>2020</u>	<u>2021</u>	<u>2022</u>	<u>2023</u>	<u>Subtotals</u>
La Mesa	А	Remove & Replace	2016	12,950				\$77,700.00		\$77,700.00
La Mesa	В	Seal Coat		1,250	\$1,625.00					\$1,625.00
La Mesa	C1	Digout, Surface Prep & Overlay		9,465	\$35,895.00					\$35,895.00
La Mesa	C2	Crack Fill & Seal Coat		21,105	\$9,886.75					\$9,886.75
La Mesa	D	Double Application Emulsion Seal Coat		2,737	\$1,868.50					\$1,868.50
La Mesa	Е	Crack Fill & Seal Coat	2016	4,410				\$2,425.50		\$2,425.50
La Mesa Elementary To	otal			51,917						\$129,400.75
Lompoc	А	Digout, Crack Fill & Seal Coat		47,588		\$17,897.00				\$17,897.00
Lompoc	В	Remove & Replace	2015	119,719			\$718,314.00			\$718,314.00
Lompoc	С	Remove & Replace	2015	38,868			\$233,208.00			\$233,208.00
Lompoc	D	Remove & Replace	2015	35,700			\$214,200.00			\$214,200.00
Lompoc	E&F	Remove & Replace	2015	35,700			\$214,200.00			\$214,200.00
Lompoc	G	Remove & Replace	2015	8,230			\$49,380.00			\$49,380.00
Lompoc	Н	Remove & Replace		136,000	\$635,000.00					\$635,000.00
Lompoc High Total		·		421,805				•		\$2,082,199.00
Lompoc Valley	А	Remove & Replace	2016	33,050				\$198,300.00		\$198,300.00
Lompoc Valley	В	Remove & Replace	2015	88,843			\$533,058.00			\$533,058.00
Lompoc Valley	C1	Double Application Emulsion Seal Coat		6,692	\$3,846.00					\$3,846.00
Lompoc Valley	C2	Digout, Crack Fill & Seal Coat	2016	14,336				\$7,884.80		\$7,884.80
Lompoc Valley	D	Double Application Emulsion Seal Coat		19,950	\$10,982.50					\$10,982.50
Lompoc Valley	Е	Remove & Replace		3,198	\$17,990.00					\$17,990.00
Lompoc Valley	F	Remove & Replace	2016	5,210				\$31,260.00		\$31,260.00
Lompoc Valley	G	Remove & Replace	2016	5,586				\$33,516.00		\$33,516.00
Lompoc Valley Middle	Total	·		176,865				·		\$836,837.30
Los Berros	А	Crack Fill and Seal Coat	2018	14,520					\$7,986.00	\$7,986.00
Los Berros	В	Remove & Replace		8,746	\$45,230.00					\$45,230.00
Los Berros	С	Remove & Replace		27,871		\$145,855.00				\$145,855.00
Los Berros	D	Seal Coat		11,756		\$5,614.60				\$5,614.60
Los Berros	Е	Seal Coat		2,997		\$2,498.50				\$2,498.50
Los Berros Elementary	Total			65,890						\$207,184.10
Manzanita	А	Type I Slurry Seal		15,040	\$15,788.00					\$15,788.00
Manzanita	В	Remove & Replace	2016	25,092				\$150,552.00		\$150,552.00
Manzanita	С	Remove & Replace	2016	22,460				\$134,760.00		\$134,760.00
Manzanita	D	Remove & Replace	2016	7,744				\$46,464.00		\$46,464.00
Manzanita	Е	Digouts & Overlay		5,444	\$17,610.00					\$17,610.00
Manzanita	F	Slurry Seal/ Crack Fill/ Dig out		17,007	\$18,507.00					\$18,507.00
Manzanita	G	Remove & Replace		2,532	\$15,192.00					\$15,192.00
Manzanita Elementary	Total			95,319						\$398,873.00





Maple	School Name	<u>Area</u>	Work Description	Last M&R	Area (sf)	<u>2019</u>	<u>2020</u>	<u>2021</u>	<u>2022</u>	<u>2023</u>	<u>Subtotals</u>
Maple C Slurry Seal and Crack Fill 6,746 \$8,794.11 \$8,794.11 Maple D Double Application Emulsion Seal Coat 28,800 \$14,520.00 \$14,520 Maple High Total 87,304 \$14,520.00 \$244,350.00 \$244,350.00 \$244,350.00 \$244,350.00 \$244,350.00 \$244,350.00 \$244,350.00 \$244,350.00 \$158,310.00 \$158,310.00 \$158,310.00 \$158,310.00 \$158,310.00 \$172,800.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00 \$181,870.00	Maple	А	Slurry Seal and Crack Fill		22,158	\$25,402.00					\$25,402.00
Maple D Double Application Emulsion Seal Coat 28,800 \$14,520.00 \$14,520.00 \$14,520.00 Maple High Total 87,304 \$81,666 Miguelito A Remove & Replace 2016 40,725 \$244,350.00 \$224,350.00 Miguelito B Remove & Replace 2015 26,885 \$158,310.00 \$158,310.00 Miguelito C Remove & Replace 2015 28,800 \$172,800.00 \$172,800.00 \$158,310.00 Miguelito D Remove & Replace 2015 13,645 \$81,870.00 \$81,870.0	Maple	В	Slurry Seal and Crack Fill		29,600	\$32,950.00					\$32,950.00
Maple High Total	Maple	С	Slurry Seal and Crack Fill		6,746	\$8,794.11					\$8,794.11
Miguelito	Maple	D	Double Application Emulsion Seal Coat		28,800	\$14,520.00					\$14,520.00
Miguelito B Remove & Replace 2015 26,385 \$158,310.00 \$158,310 Miguelito C Remove & Replace 2015 28,800 \$172,800.00 \$172,800.00 Miguelito D Remove & Replace 2015 13,645 \$81,870.00 \$81,870 Miguelito E Remove & Replace 2015 6,195 \$37,170.00 \$37,170.00 Miguelito Elementary Total 115,750 \$694,500 Mission Valley A Seal Coat 16,804 \$6,721.60 \$6,721 Mission Valley Elementary Total 16,804 \$6,721.60 \$5,940 Vandenberg A Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232 Vandenberg B Crack Fill and Seal Coat 2018 26,316 \$14,473.80 \$14,473.80 \$14,473.80 Vandenberg D Crack Fill and Seal Coat 2018 26,068 \$1,938.20 \$1,938.20 Vandenberg F Remove & Replace 2018 29,241 \$1,500 \$175,446.00 \$175,446.00 \$175,446.00 Vandenberg G Crack Fill and Seal Coat 2018 5,942 \$3,268.10 \$3,268.10 Vandenberg G Crack Fill and Seal Coat 2018 5,942 \$3,268.10 \$3,268.10 Vandenberg G Crack Fill and Seal Coat 2018 5,942 \$3,268.10 \$3,268.10 Vandenberg G Crack Fill and Seal Coat 2018 5,942 \$3,268.10 \$3,268.10 Vandenberg H Remove & Replace 29,230 \$151,150.00 \$151,150.00 Vandenberg H Remove & Replace 29,230 \$151,150.00 \$151,150.00 Vandenberg Middle Total 138,816 \$370,785 Mission Valley Santon V	Maple High Total				87,304						\$81,666.11
Miguelito C Remove & Replace 2015 28,800 \$172,800.00 \$172,800.00 Miguelito D Remove & Replace 2015 13,645 \$81,870.00 \$81,870.00 Miguelito E Remove & Replace 2015 6,195 \$37,170.00 \$37,170.00 Miguelito Elementary Total 115,750 \$694,500 Mission Valley A Seal Coat 16,804 \$6,721.60 \$6,721	Miguelito	А	Remove & Replace	2016	40,725				\$244,350.00		\$244,350.00
Miguelito D Remove & Replace 2015 13,645 \$81,870.00 \$81,870.00 \$81,870.00 \$37,170.00 \$37,	Miguelito	В	Remove & Replace	2015	26,385			\$158,310.00			\$158,310.00
Miguelito E Remove & Replace 2015 6,195 \$37,170.00 \$37,170.00 Miguelito Elementary Total 115,750 \$694,500 Mission Valley A Seal Coat 16,804 \$6,721.60 \$6,721 Mission Valley Elementary Total 16,804 \$6,721.60 \$5,940.00 \$5,940.00 Vandenberg A Crack Fill and Seal Coat 2016 10,800 \$5,940.00 \$5,940.00 Vandenberg B Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232.25 Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$14,473.80 \$1	Miguelito	С	Remove & Replace	2015	28,800			\$172,800.00			\$172,800.00
Miguelito Elementary Total 115,750 \$694,500 Mission Valley A Seal Coat 16,804 \$6,721.60 \$6,721 Mission Valley Elementary Total 16,804 \$6,721.60 \$6,721 Vandenberg A Crack Fill and Seal Coat 2016 10,800 \$5,940.00 \$5,940.00 Vandenberg B Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232.25 Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$14,473.80 \$14,473.	Miguelito	D	Remove & Replace	2015	13,645			\$81,870.00			\$81,870.00
Mission Valley A Seal Coat 16,804 \$6,721.60 Mission Valley Elementary Total 16,804 \$6,721.60 Vandenberg A Crack Fill and Seal Coat 2016 10,800 \$5,940.00 \$5,940.00 Vandenberg B Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232.25 Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$11,473.80 \$14,473.80 \$1	Miguelito	E	Remove & Replace	2015	6,195			\$37,170.00			\$37,170.00
Mission Valley Elementary Total 16,804 \$6,721 Vandenberg A Crack Fill and Seal Coat 2016 10,800 \$5,940.00 \$5,940.00 \$5,940.00 \$5,940.00 \$4,232.25 \$14,473.80 \$14,473.80 \$14,473.80 \$14,473.80 \$14,473.80 \$14,473.80 \$14,473.80 \$14,237.40 \$14,237.40 \$14,237.40 \$14,237.40 \$14,23	Miguelito Elementary 7	otal			115,750						\$694,500.00
Vandenberg A Crack Fill and Seal Coat 2016 10,800 \$5,940.00 \$5,940.00 \$5,940 Vandenberg B Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232.25 Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$14,473.80	Mission Valley	А	Seal Coat		16,804	\$6,721.60					\$6,721.60
Vandenberg B Crack Fill and Seal Coat 2016 7,695 \$4,232.25 \$4,232.25 \$4,232 Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$14,473.80 \$14,4	Mission Valley Elemen	tary Total			16,804						\$6,721.60
Vandenberg C Crack Fill and Seal Coat 2018 26,316 \$14,473.80 </td <td>Vandenberg</td> <td>А</td> <td>Crack Fill and Seal Coat</td> <td>2016</td> <td>10,800</td> <td></td> <td></td> <td></td> <td>\$5,940.00</td> <td></td> <td>\$5,940.00</td>	Vandenberg	А	Crack Fill and Seal Coat	2016	10,800				\$5,940.00		\$5,940.00
Vandenberg D Crack Fill and Seal Coat 2018 26,068 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$14,337.40 \$1,938.20 \$1,938.20 \$1,938.20 \$1,938.20 \$1,938.20 \$1,938.20 \$1,938.20 \$175,446.00 <t< td=""><td>Vandenberg</td><td>В</td><td>Crack Fill and Seal Coat</td><td>2016</td><td>7,695</td><td></td><td></td><td></td><td>\$4,232.25</td><td></td><td>\$4,232.25</td></t<>	Vandenberg	В	Crack Fill and Seal Coat	2016	7,695				\$4,232.25		\$4,232.25
Vandenberg E Crack Fill and Seal Coat 2018 3,524 \$1,938.20 \$1,938.20 \$1,938 Vandenberg F Remove & Replace 2018 29,241 \$175,446.00<	Vandenberg	С	Crack Fill and Seal Coat	2018	26,316					\$14,473.80	\$14,473.80
Vandenberg F Remove & Replace 2018 29,241 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$175,446.00 \$3,268 \$3,268.10 \$3,268 \$3,268.10 \$3,268 \$151,150.00 \$151,150.00 \$151,150.00 \$151,150.00 \$370,785 \$370,785	Vandenberg	D	Crack Fill and Seal Coat	2018	26,068					\$14,337.40	\$14,337.40
Vandenberg G Crack Fill and Seal Coat 2018 5,942 \$3,268.10 \$3,268.10 \$3,268.10 \$3,268.10 \$151,150.00 \$151,150.00 \$151,150.00 \$370,785 Vandenberg Middle Total 138,816 \$370,785 \$370,785 \$370,785	Vandenberg	E	Crack Fill and Seal Coat	2018	3,524					\$1,938.20	\$1,938.20
Vandenberg H Remove & Replace 29,230 \$151,150.00 \$151,150 Vandenberg Middle Total 138,816 \$370,785	Vandenberg	F	Remove & Replace	2018	29,241					\$175,446.00	\$175,446.00
Vandenberg Middle Total 138,816 \$370,785	Vandenberg	G	Crack Fill and Seal Coat	2018	5,942					\$3,268.10	\$3,268.10
	Vandenberg	Н	Remove & Replace		29,230	\$151,150.00					\$151,150.00
Total 5 Year Plan \$2 480 728 26 \$171 865 10 \$3 549 072 00 \$2 233 382 10 \$2 967 142 65 \$11 402 190	Vandenberg Middle To	tal			138,816						\$370,785.75
	Total 5 Year Plan					\$2,480,728,26	\$171.865.10	\$3.549.072.00	\$2,233,382,10	\$2,967,142,65	\$11,402,190.11





















































		, s	and a state	,
Julius Comments of the Comment	Reput Type	Regaritudes Res	are laterate that	_
District Office Repairs	Built Up Roof	\$4,200	Immediate Repairs	
El Camino Adult School Repairs	Name and Address of the Landson Co.	\$4,500	Immediate Repairs	
Buena Vista ES Repairs	Name of the second	\$10,600	Immediate Repairs	-
Cabrillo HS Repairs	THE RESIDENCE OF THE PARTY OF T	\$26,400	Immediate Repairs	
Clarence Ruth ES Repairs		\$6,000	Immediate Repairs	
Crestview ES Repairs	E 2005 W TO T	100 000 000 000	Immediate Repairs	Unable to
Fillmore ES Repairs	THE RESERVE TO SERVE THE PROPERTY OF THE PERSON NAMED IN COLUMN TO SERVE THE PERSON NAMED IN COLUMN TO	\$6,000	Immediate Repairs	
Hapgood ES Repairs		\$15,600	Immediate Repairs	
La Canada ES Repairs		\$8,000	Immediate Repairs	_
La Honda STEAM Academy Repairs		\$18,200	Immediate Repairs	1000
Lompoc HS Repairs		\$23,600	Immediate Repairs	
Lompoc Valley MS Repairs		\$15,800	Immediate Repairs	
Los Berros ES Repairs		\$15,200	Immediate Repairs	
Maple HS Repairs	The same of the same	\$7,100	Immediate Repairs	
Miguelito ES Repairs		\$4,800	Immediate Repairs	
		\$9,400	Immediate Repairs	_

10tai \$166,000

Cabrillo HS - Main Office	Cap Sheet	\$277,000	Sagadon - S 22 Suspensor A Whole Spread
Cabrillo H5 - A	Cap Sheet	\$170,000	Regards - R 30 Removals & Wilco Grove
Cabrillo HS - AG	Cap Sheet	\$278,000	Pagaine - E. St. Barmont: & White Grove
Cabrillo HS - CB B	Cap Sheet	\$263,000	Republic - A SP Name on & White Group
Cabrillo HS - FL	Cap Sheet	\$164,000	Assessed - P. St. Commerce & White Security
Cabrillo HS - IA	Cap Sheet	\$332,000	Regular - R SD Sarrastin & White Grand
Cabrillo HS - MU	Cap Sheet	\$101,000	Magazine in 2th Sammarine & White Ground
Cabrillo HS - P	Cap Sheet	\$244,000	Regards - R 10 Recovery & White Street
Cabrillo HS - Student Store	Cap Sheet	\$54,000	Regular - R 39 Successio & White Grand
El Camino - Adult School - MPR	Tile	TBD	Anglain Curther Immerigation Assets
Clarence Ruth ES - Portable 34	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Clarence Ruth ES - Portable 35	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Clarence Ruth ES - Portable 39	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Hapgood ES - Portable 2	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Hapgood ES - Portable 3	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
La Honda STEAM - Portable 21	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
La Honda STEAM - Portable 27	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 25	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 26	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 27	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 29	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 30	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Miguelito ES - Portable 32	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Vandenberg MS - Portable B8	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee
Vandenberg MS - Portable B9	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Kee

\$2,147,000

Clarence Ruth ES - Building A	Cap Sheet	\$308,000	Repairs - A 30 Secretor & When State
Clarence Ruth ES - Building B	Cap Sheet	\$308,000	Apparel - S NO Supported & White Street
Clarence Ruth ES - Building C	Cap Sheet	\$308,000	Regular of 10 Serverses & White Gray
Clarence Ruth ES - Building F	Cap Sheet	\$360,000	Regalite of 16 hormonic & White Gree
Hapgood ES - Cafeteria	Cap Sheet	\$91,000	Regulate A 20 Numbers & White Gree
ompoc Valley MS - Administration Building	Cap Sheet	\$203,000	Regulate - A 10 Surmarrie & Wigns Saw
Buena Vista ES - P2	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
Buena Vista ES - P3	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
Clarence Ruth ES - Portable 28	Cap Sheet (Metal Deck)	\$17,600	Replace with 45 Mil Ke
Fillmore ES - Portable 8	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
Fillmore ES - Portable 9	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
Fillmore ES - Portable 10	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
Fillmore ES - Portable 11	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
La Canada ES - Portable 30	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
La Canada ES - Portable 31	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke
La Canada ES - Portable 32	Metal (Wood Deck)	\$17,600	Replace with 45 Mil Ke

Lompoc USD	Buena Vista ES									
	Roof Type	Tremco Warranty #	Rating 1-10 (1Fell, 10 Good)	Appril. Sq. Ft.	2022 Repair Budgets	Restors / Replace	Deficiencies	Notes	Good Condition Res	Repair / Replace
Building 1 - 20 / Cafeteria / Office	Cap Sheet			36,200	\$ 2,800	Restore	Granule foss, rust on perimeter metal, previous repairs done by others, open pipe penetrations, debris	Trees overhanging onto roof		
	Metal (Wood Deck)		s	1,100	99		Previous Repairs done by others, deteriorated sealant around fasteners			
	Metal		s	1,100	909		Deteriorated sealant around fasteners	8		
	Metal (Wood Deck)			1,100	009 \$	Replace	Deteriorated sealant around fasteners, rust on perimeter, previous repairs done by others			
	Metal (Metal Deck)		0.000	1,100		Replace	Deteriorated sealant around fasteners, rust on perimeter, previous repairs done by others			
	Metal		,	100			Deteriorated sealant around fasteners			
	Metal					Replace	Deteriorated sealant around fasteners, rust on perimeter, previous repairs done by others			
	Metal		,	1,160	909		Detenorated sealant around fasteners			
8	Metai		m		9 8	Replace	Deteriorated sealant around fasteners, rust on perimeter, previous repairs done by others			
	Metal				909	Replace	Deteriorated sealant around fasteners, rust on perimeter, previous repairs done by others			
	Metal		4	7,100	\$ 600		Deteriorated sealant around Jasteners, repairs done by others, debris			
	Metal		•	1,100	909 \$		Deteriorated sealant around fasteners, repairs done by athers, debris			
	Metal		4	1,100			Deteriorated sealant around fasteners, repairs done by others, debris			
	Metal		4		2.0		Deterlorated sealant around pipes, repairs done by others, debais	Trees overhanging onto roof		
					\$ 10.600					
	100 P. C.									

Lompoc USD	Clarence Ruth ES		0.0							
Building/section	$\overline{}$	Tremco Warranty #	Rating 1-10 (1Fail, 10 Good)	Appril. Sq Ft	2022 Repair Budgets	Restore / Replace	Deficiencies	Notes	Good Condition or PM needed	Restoration Rep
Building A	Cap Sheet			9,800	\$ 1200	Replace	Granule loss, previous repairs done by others, rusted vents			
Building B	C4p Sheet			8,800	\$ 1,200	Replace	Granule loss, previous repairs done by others, rusted			
Bullding C	Cap Sheet		1	8,800	\$ 1,200	Replace	Granule loss, previous repairs done by others, rusted vents			
Bullding D	Bulk Up Rood - Gravel 153062 (5 Yr / 2012)	153062 (5 Yr / 2012)	ů	4,650	- 3		Debris, deteriorated sealant around pipes			
Building F	Cap Sheet			15	\$ 1,200	Replace	Granule loss, previous repairs done by others, rusted vents, splits in membrane			
Portables 22 - 26	36	110017 (10 Yr / 2005)	9			Restore	Sulpred to subs			
Portable 27		110017 (10 Yr / 2005)	9	1,100		Restore	Sylve of ponding			
Portable 28	Cap Sheet (Metal Deck)		-	1,106		Replace	Majer repairs done in pass, granule loss			
Portable 29	Sentie No Metal Deck 110037 (10 vr / 2005)	110017 [10 Yr / 2005]	9	1100		Restore	Supposed to subsection			
Portable 30	Cas Sheet Meta Deck 110017 II D Yr / 2005	10017110 11/2005	4	971		Restore	Debris in gettees, minor granule loss	Restore before failure		
Fortable 31	Metal (Metal Deck)		•	811			Coating on metal portable starting to fail			
Portable 32	Metal (Metal Deck)		10	1,100			Coating on metal portable starting to fail			
Portable 33	Single Ptv (Wood Deck)	110017 (30 Yr / 2005)	in	1100		Restore	Aged membrane			
Portable 34	Metal (Wood Deck)		-	1,100		Replace	Previous repairs done by others, major rust on panels			
Portable 35	Metal (Wood Deck)		-	1,100			Previous repairs done by others, major rust on panels			
Portable 36	Metal (Metal Dech)		٠,	1.100			Previous repairs done by others, coating on roof			
Portable 37	Metal (Metal Deck)			1,100			Previous repairs done by others, coating on roof			
Portable 38 / YMCA	Single Piv (Metal Deck)		S	1,100		Restore	Debris in gutters		<i>y</i>	
Portable 39	Metal (Wood Deck)			7,100			Rust on panels, deteriorated sealant around fasteners			

			_		_	_				_		_		_			_	_
Aged membrane, signs of ponding	Previous repairs done by others around penetrations, deteriorated sealant around pipes and fasteners		:															
Restore																		
		\$ 6,000																
3,300	059	_																П
*	Р																	
Single Ply	Metal																	
Portable 40 - 42	Portable Restroom																	

Lompoc USD	Fillmore ES								
Building/section	Roaf Type	Tremco Warranty #	Rating 1-10 (1Fall, 10 Good)	Appril. Sq.	2022 Repair Budgets	Restore / Replace	Deficiencies	Notes	Good Condition Rest
Office / Kitchen	Cap Sheet			5,800	\$ 1,200	Replace	Minor granule loss, previous repairs done by others, deteriorated sealant around pipes		
MPR	Cip Sheet	89553 (10 Yr / 2001)		3,300	\$ 1,200		Did Not Walk		
Building A	Cup Sheet		in	9,000	1,200	Replace	Ridging, minor granule loss, deteriorated sealant around pipes, previous exams done by others		,
Building B	Cap Sheet			9,000	\$ 1.200	Replace	Minor granule loss, previous repairs done by others, deteriorated sealant around pipes, open lap on perimeter		
Building C	Cap Sheet			000'6	\$ 1200	Replace	Minor granule loss, previous repairs done by others, deteriorated sealant around pipes, open lap on perimeter		
Walk Ways	Cap Sheet		100	5,400		Replace	Major Fanuke loss, membrane failed		
Portables 1 - 7	Single Ply (Metal Deck) 89554 (10 Yr / 2001)	89554 (10 %r / 2001)	S.	8,200		Restore	Age membrane, signs of ponding		
Portable 8	Metal (Wood Deck)	100	1	1,150		Replace	Rust on panels, previous repairs done by others		
Portable 9	Metal (Wood Deck)		4	1,150		Replace	Rust on panels, previous repairs done by others		
Portable 10	Metal (Wood Deck)		1	1,150		Replace	Rust on panels, previous repairs done by others		
Portable 11	Metal (Wood Deck)		1	1,150		Replace	Rust on panek, previous repairs done by others		
Restrucem Portable	New N		s	980			Deteriorated sealant around lasteners, previous repairs done by others		
					9 6,000				





Good Condition Repair / Or PM needed Restoration Rep Notes Bisters, minor granule loss, previous repairs done in past by others, epen pitch pockets, fastener back out Previous repairs done in past by others, deteriorated sealant around fasteners Previous repairs done in past by others, deteriorated sealant around fasteners Blisters, minor granule loss, residental flashing, primous repairs done in part by others Previous repairs done in past by others, rust on permeter Restors / Replace Restore Restore 8,000 Tremco Warranty # (1504, 10 Good) Ft Budgets 35,400 \$ 5,000 6,500 \$ 3,000 4,400 3,300 1,100 Metal (Wood Deck) Metal (Metal Deck) La Canada ES Roof Type Cap Sheet Cap Sheet Metal ilding 1 - 29 / MPR / Office uilding/section Lompoc USD Building 34 - 39 P 30 - 33 P 40 - 42



Lomboc USD	La Honda STEAM Academy									
Britiding (section	Bood Ture	Rathg 3:10 Tremo Marantu # (1fell 10 Good)	Rating 1-10 (1Fail. 10 Good)	Appra. Sq.	2022 Repair Budgets	Restore / Replace	Deficiencies	Nester	Good Candition or PM needed	Restoration Rep
	Bud' in Road Count	Mary Lynni cannot		9010	98		Onen size penetrations, debris			
	Buch the Roof - Council	104451 10 Vr (7004)		970	-		Doen one penetrations, debris, rusted out ducts	Recoat ducts		
) PR	Built Up Roof - Gravel	104462 (10 Yr / 2004)		8,400			Open sine penetrations, debris, debris getters	38		
Rettroom Portable	Metal			690	000 5		Previous repairs done by others, deteriorated sealant around fasteners			
Portable 17	Metal (Metal Deck)		5	1,150	9 800		Previous repairs done by others, deteriorated sealant around fasteners		-	
Portable 18	Metal (Metal Deck)			1,150	\$ 800	Beplace	Previous repairs done by others, deteriorated sealant around fasteners, rust account on perimeter			
Portable 19	Metal (Metal Deck)		\$	1,150	\$ 800	11.59%	Previous repairs done by others, deteriorated sealant around fasteners	88. 88		
Portable 20	Mess (Mess Deck)		5	1,150	\$ 800		Previous repairs done by others, deteriorated sealant around fasteners.			
Portable 21	Metal (Metal Deck)		*	1,150	\$ 800		Previous repairs done by others, deteriorated sealant around fasteners			
Portable 22	Metal (Metal Deck)			1,150		Replace	Previous repairs done by others, deteriorated sealant around fasteners, rust in field			
Portable 23	Metal (Metal Deck)		\$	1,150	800		Previous repairs done by others, detenorated sealant around fasteners			
Portable 24	Metal (Metal Deck)			1,150	\$ 800	Replace	Previous repairs done by others, deteriorated sealant around fasteners, russ occuring on permeter			
Portable 21	Metal (Wood Dech) (Aluminum Coaling)			1,150	800	Replace 2023	Previous repairs done by others, deteriorated sealant around fasteners, rust in field and perimeter			
Portable 24	Agg-adhus	148371 10 Yr / 2012)	7	1,150		Restore	Signs of ponding, debris in patters			
Portuble 25	Ag about	148371 10 Yr / 2012)	7	1,150		Restore	Sem of ponding, debris in putters			
Portugle 24	Add agency	148371 10 Yr / 2012	,	1,150		Restore	Sens of ponding, debris in putters			
Portable 27	Metal (Wood Bect) (Aluminum Coating)			1,150	900	Regisce 2023	Previous repairs done by others, deteriorated sealant around fasteners, russ in field and pervineter			
Portable 28	Metal (Wood Deck)			1,150	\$ 800	Replace	Previous repairs done by others, deteriorated sealant around fasteners, russ occuring on perimeter			
Portable 29	Metal (Nood Deck)			1,150	800	Replace	Previous repairs done by others, detenorated sealant around fasteners, rust executing on perimeter		 1	
Portsile 30	Metal (Wood Deck)		9	1,150	\$ 800	Replace	Previous repairs done by others, deteriorated sealant around fasteners, rust actuming on perimeter			

					П	1	T	T	Γ	Γ				T	Ī							
Previous repairs done by others, deteriorated sealant around fasteners, nust occuring on perimeter	Previous repairs done by others, deteriorated sealant around fasteners, rust occuring on perimeter	Previous repairs done by others, deteriorated sealant around fasteners, rust occuring on perimeter		F 87 10																		
Replace	Replace	Replace																				
\$ 800	\$ 800	\$ 800	\$ 18,200				1	Ť					1	1	Ť	Ť	T	Ī	Γ			
1,150		1,150					1	T	T				T									
Metal (Wood Deck)	Metal (Wood Deck)	Metal (Wood Deck)																				
Portable 31	Portable 32	Portable 33																				



Good Condition Repair / or PM needed Restoration Notes Deternorated sealant around fasteners, rust on panels, rusted gulters Deteriorated sealant around fasteners, rust on panels, rusted parters Granule loss, previous repairs throughout done by others, open perimeter laps, nail pops, cracking in membrane, residential flashings, open pipe perefrations. Dirty membrane, recommend restoring Deteriorated sealant around fasteners Restore / Replace Replace Restore Replace Replace Apprx. Sq. 2022 Repair Ft. Budgets \$ 12,499 1,000 900 15,199 \$ 1,000 45,300 1,100 1,100 2,450 1,100 Tremco Warranty # (1folf, 10 Good) Single Ply (Hypalon) 947645 (10 Yr / 2002) Los Berros ES Roof Type Cap Sheet Metal Metal Metal **Sullding/section** Lompoc USD Portable 27 & 28 Wain Building Portable 29 Partable 30 Portable 31



Lompoc USD	Miguelito ES						11				
Bullding/section	Roof Type	Tremco Warranty #	Rating 1-10 (IFoil, IO Good)	Appril. Sq. Ft	2022 Repair Budgets	Restore / Replace	Deficiencies	Notes	Good Condition or PM needed	Repair / Restoration	Repla
MAPR	Built Up Roof - Grave	Built Up Roof - Gravel 137053 (10 Yr / 2010)		5,100	\$ 800		Open pipe penetrations				
Walk Ways	Built Up Roof - Gravel	Built Up Roof - Gravel 137053 (10 Yr / 2010)		9,700	\$ 800	9					
Office / Library	Buit Ur Roo! - Gravel	Bult U# Roo! - Gravel 137053 (10 %r / 2010)		3,000	\$ 600		Open penetrations in metal panel wall				
Building 1 - 5	Built Up Roof - Gravel 137053 (10 Yr / 2010)	137053 [10 Yr / 2010)		9000	\$ 800		Open pipe penetrations				
Building 6 - 10	Suit Up Reef - Grave	137053 (10 Yr / 2010).		6,000	\$ 800		Open pipe penetrations, rusted vents				
Building 15 - 39	Built Up Rool Gravel 137053 (10 Yr / 2010)	137053 (10 Yr / 2010)		6,200	\$ 800		Open pipe penetrations, rusted vents				
8-ilding 20	Shingles			1,500		Replace	Open pipe penetrations, missing shingles, aged shingles, aged				
Building 23	Shingles		*	1,100		Replace	Open pipe penetrations, missing shingles, aged shingles, aged				
Portsble 22	Single Pty (Metal Decit)		ş	1,100		Restore	Debris in gutters, signs of ponsing				
Portable 23	Single Phy (Metal Deck)		9	1,180		Restore	Debets in gutteres, signs of ponding				
Portable 24	Metal (Wood Deck)		4	1,100			Debris in gutters, deteriorated sealant around fasteners, previous repairs done by others with mastic	Metal coated with Aluminum coating			
Portable 25	Metal (Wood Deck)			1,100		Replace	Debris in gutters, rust on perimeter, previous repairs done by others with mastic, deteriorated sealant around fasteners	Metal coated with Aluminum coaling			
Portable 25	Metal (Wood Deck)			1,100		Replace	Debris in gutters, rust on perimeter, previous repairs done by others with massil, deteriorated sealant around lasteners	Metal coated with Aluminum coaling			
Portable 27	Metal (Wood Deck)			1,100		Replace	Debris in gutters, rust on perimeter, previous repairs done by others with mastic, deteriorated sealant around fasteners	Metal coated with Abuninum coating			
Portable 28	Metal (Wood Deck)		₹	1,100			Debris in gutters, deteriorated sealant around lasteners, previous repairs done by others with mastic.	Metal coated with Aluminum coating			
Portable 29	Metal (Wood Deck)			1,300		Replace	Debris in gutters, major rust on perimeter, previous repairs done by others with mastir, deteriorated sealant around fasteners	Metal coated with Aluminum coating			
Portable 30	Metal (Wood Deck)		0.040,000	1,100		Replace	Debris in gutters, rust on perimeter, previous repairs done by others with massic, deteriorated sealant around fasteners	Metal coated with Aluminum coating			
Portable 31	Metal (Wood Deck)	20		1,100			Debris in gutters, deteriorated sealant around fasteners, previous repairs done by others with mastic.	Metal coated with Aluminum coating			
Portable 32	Metal (Wood Deck)			1,100		Replace	Debris in gutters, major rust on perimeter, previous repairs done by others with mastic, deteriorated sealant around fasteners	Metal coated with Aluminum coating			

				<u> </u>	<u> </u>	Ţ	T	_						7	7				
			İ																:
Major rust on gutters, previous repairs done by others with mastic, deteriorated sealant around fasteners	Previous repairs done by others with mastic, deterlorated sealant around fasteners						:												
		\$ 4,800																	
1,100	1,100												_						
	,																		
																:			
Metal (Metal Deck)	Metal (Metal Deck)																		
Portable 33	Portable 34																		







Lompoc USD	Lompoc Valley MS			1	2		A CO CANADA MANAGEMENT OF THE COLUMN	6	
Building/section	Roof Type	Tremco Warranty #	Rating 1-10 (1fell, 10 Good)	Apprit. Sq Ft	2022 Repair Budgets	Restore / Replace	Deficiencies Notes	90 6	Good Condit or PM need
Administration Suilding	Cap Sheet		25	000'9	\$ 2,200	Replace	Minor granu ess, previous repairs done by others, open pipe penetrations, rusted vents, open laps on perimeter	_	
Building 1 - 20	Built Up Roof - Gravel	29553 10 Yr / 1998)	5	14,900	\$ 1,200		Deteriorated sealant around pipes		
Building 21 - 22	Shingles		ø		\$ 1,700		Deteriorated sealant around pages		
Beilding 23 / Ubrary	Built Up Roof Grave	20105 (10 Yr / 1993)	5	4,350	\$ 1,200		Debris on roof acrund drain, residential flashing.		
Building 24 - 29	Built Up Roof - Gravel	20102 (10 Yr / 1993)	3	13,600	\$ 1,600		Debris in putters, deteriorated sealant around pipes		
Outlding 30 - 35	Built Up Roof - Gravel	83439 10 Yr / 2000	9	4,800	\$ 1,200		Did not walk		
Bullding 36 - 41	Built Up Roof - Gravel	83439 (10 Yr / 2000)	9	5,300	\$ 1,200	_	Debris throughout, deteriorated sealant around pipes, access to roof is out of OSNA. Compliance (Guard Ralling needed)		
Building 42 - 46	Cap Sheet		4	6,200	\$ 1,200	Restore	Debris throughout, aged membrane		
Building S7 / Girls Locker Room	Built Up Roof - Gravel		9				Deterlorated sealant around pipes		
Building 48 - 50	Built Up Roof - Grave	17727 (10 Yr / 1992)	,	4,300	5 1,200		Debnis throughout, repairs done in past by others, deteriorated sealant around pipes.		
Buildi = 51 - 52 / Art	Bulk Up Roof - Gravel	Z0203 (30 Vr / 1993)	8	2,500	\$ 1,200		Deteriorated sealant around pipes		
Building St - 63 / Band & Choir	Built Up Roof - Gravel	19338 (10 W / 2993)	ş	3,800	\$ 1,200		Deteriorated sealant around pipes f debris on roof		
w.is	Single Ply (TPA)						Did not walk		
Civic Auditerium	Tile						Aged file / reported leaks		
Pertable 61	Single Ply (Metal Deat)		10	1,100			Signs of pending		
Pertable 62	Single Ply (Metal Gecit)		9	1,100			Signs of ponding		
Portable 63	Metal (Metal Deck)		*	1,100			Rust throughout, rusted partier		
Portable 64	Single Ply (Metal Deck)		9	1,100			Signs of possible		
					\$ 15,800				
5244					W. 25.00				

dition Repair / Replace

Good Condition Repair / or PM needed Restoration Trees should be cut back Open pipe penetrations, missing gravel, rusted vents, residental flashings Deteriorated sealant fasteners, rusted gutters, rust on perimeter, previous repairs done by others Deteriorated sealant fasteners, rusted gutters, rust on perimeter, previous repairs done by others Open pipe penetrations, missing gravel, rusted vents Open pipe penetrations, missing gravel, rusted vents Open pipe penetrations, missing gravel, previous repairs done by others Rust throughout, previous repairs done by others, debris Rust on panels, debris in putters, previous repairs Open pipe penetrations, debris in putters Debris in gutters, signs of ponding Debris in gutters, signs of ponding Debris in gutters, signs of ponding Debris in putters, signs of ponding Open pipe penetrations Open pipe penetrations Open pipe penetrations Deficiencies Did not walk Restors / Replace Peplace 2023 Replace Replace Replace 906 908 800 800 Appra. Sq 2022 Repair Ft Budgets 98 800 8 800 14,300 10,000 7,100 8,800 7,600 7,600 1,300 7,100 9.500 1,100 1,100 1,100 1,100 1,100 1,100 1,100 1,100 Rating 1-10 (1Foll, 10 Good) Tremco Warranty # Built Up Roof - Gravel 89231 (10 Yr / 2001) Built Up Roof - Gravel 89231 (10 Yr / 2001) 8uilt Up Roof - Gravel 892321 (10 Yr / 2001) Built Up Roof - Gravel 77571 (10 Yr / 1999) Built Up Roof - Gravel 77571 (10 Yr / 1999) Bult Up Roof - Gravel 89321 (10 Yr / 2001) Built Up Roof - Gravel 89321 (10 Yr / 2001) Bult Up Roof - Gravel 892321 (10 Yr / 2001) Built Up Roof - Gravel 29496 (10 Yr / 1998) Vandenberg MS Built Up Roof - Gravel Single Ply (Metal Deck) Single Ply (Metal Deck) Metal (Wood Deck) Metal (Wood Deck) Single Ply (Metal Deck) Single Ply (Metal Deck) Roof Type Metal hillding M3 / Snack Bar Lompoc USD uilding/section Portable T3 Portable T3 Portable 88 octable 89 Bullding B **Building H** Portable T2 ortable 74 Portable TS Portable T6

Good Condition Repair / or PM needed Restoration Replace Notes Granule loss, open pitch pockets, open pipe penetrations, open laps on perlimeter, previous repairs done by others, are membrane Deteriorated sealant around fasteners Deteriorated sealant around fasteners Deteriorated sealant around fasteners Continue to maintain Restore / Replace Replace 300 7,100 Apprix. Sq. 2022 Repair Ft Budgets 9,200 \$ 5,000 900 200 1,100 1,100 8,900 1,100 Tremto Warranty # (1fail, 10 Good) Built Up Roof - Gravel Roof Type Cap Sheet Metal Maple HS Metal Metal Lompoc USD wilding/section Main Building Main Building Portable 1 Portable 3 Portable 2



Lomooc USD	Cabrillo HS		25			20				
Building/section	Roof Type	Rating 1-10 Tremco Warranky # (1Foll, 10 Good)	Rating 1-10 (1Feil, 10 Good)	Appra. Sq.	2022 Repair Budgets	Restore / Replace	Deficiencies	Notes	Good Condition or PM needed	Restoration Restoration
Main Office	35			6,900	\$ 2,200	Restace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others			
Cohenda	Ruile Lio Roof - Grave	Ruile Lip Bracf - Grassel 188369 (10 Yr. / 2012)		09'6			Open pipe penetrations		28036	
l Person	Built In Bred Crave	Built In Red (2/2009) 188 169 (10 Vr / 2017)		14.300			Continue to maintain			
Building A	Cap Sheet				~	Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others			
Building AG	Co Sheet			- 1		Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others.			
M and piper	Anile Un Boof Gra-	Britte In Bood (572-4)					Open bipe peretrations			
Building Chi	D Sheet			7,500	~	Replace	Open perimeter laps, alligator cracking throughout, open pipe pemetrations, major granule loss, previous repairs done by others			
Building CB C	Built Un Roof - Gravel	137054 (10 % / 2010)		7,400	99	22	Open pipe penetrations			
a de la composition della comp	diam's			99.9	99		Open sine penetrations			
Building P.	TARKS OF THE STATE	10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	-	4,700	~	Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others			
Building IA	Co Special					Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others			
Milidre	Buff Up Roof - Grave	348369 10 tr / 2012)		9			Open pipe pertetrations	Coat single ply flashings		
Building MU	Cap Sheet		-	2,900	~	Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others.			
building P	Cae Sheet (Aluminum)		194			Replace	Coating failing, open pipe penetrations, previous repairs done by others, rust on perimeter			
building 55	Built Up Roof - Gravel	110016 (10 Yr / 2005)					Open pipe penetrations			
Bern & Girls Locker Room	Built Ltp Roof - Gravel		,		\$ 1,700		Open pape penetrations, previous repairs done by others	100		
Pool Building	Ald spirits		*		1 3		Deteriorated sealant around pipes, signs of ponding, dirty membrane			
Science Building	Built Up Roof - Grave	80506 (10 Yr / 2003)		14,100	99		Debris, debris in gutters, open gipe penetrations.			
Student Store	Con Sheet		-		\$ 2,200	Replace	Open perimeter laps, alligator cracking throughout, open pipe penetrations, major granule loss, previous repairs done by others			

tomboc USD	Lomboc HS									
Building/section	Roof Type	Tremco Warranty #	Rating 1-10 (1Foil, 10 Good)	Appril. Sq. Ft.	2022 Repair Budgets	Restore / Replace	Deficiencies	Notes	Good Condition or PM needed	Repair / Restoration Res
Administration Building	Built Up Roof - Gravel	23277 (10 🖛 / 1995)	4	7,800	\$ 1,200		Residential flashings, deteriorated sealant around pipes, previous repairs done by others, rusted vents,			
ALIS Building	Built In Roof - Gravel	23227 30 m/ 1995)		7.800	1 (Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane			
Library	Built 11 Roof Gravel	29554 (10 Yr / 1998)		14.500	\$ 2,000		Debris, rusted vents, deterlorated sealant around pipes			
Quan.	Built U Roof - Gravel			25,500		55	Did not walk			
Gym Stage / Girls & Boys Locker	Built Up Roof - Gravel	94434 (10 Yr / 2002)		7,400	\$ 1,200		Deteriorated sealant around piper, previous repairs done by others, rusted vents, aged membrane, debris			
Cafeteria	Built Up Roof - Gravel	94434 (10 Yr / 2002)	,	6,700	\$ 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, a ged membrane			
Building E	Built Up Roof - Gravel 23277 [10 w / 1995]	23277 [10 w / 1995]	,	006'9			Deteriorated sealant around pipes, previous repairs done by others, nusted vents, a god membrane			
Building 55	Built Up Roof - Gravel	23277 [10 w / 1995]	,	6,900	\$ 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane			
Building M (3-6)	Built Up Roof - Gravel		,	6,900	\$ 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane			
Building M (7-10)	Buth Up Reef - Gravel	23277 (10 w / 1995)	+	4,200	02'1 \$		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, a gred membrane			
Building SQ (1-4)	Built Up Roof - Gravet		,	8,600	\$ 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane			
Building 5G (9-11)	Bull Up Roof - Gravel		4	3,800	3 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane			
Parities is	Built Us Roof Grave		,	16,500	\$ 1,200		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aget membrane			
Building AG	Bulk Up Roof - Gravel						Deteriorated sealant around pipes, previous repairs done by others, rusted vents, algel membrane			
Snack Sar	Bulk Us Roof Gravel		,	2,806			Deteriorated sealant around pipes, previous repairs done by others, rusted wents, aged membrane, debris, blocks nakled into roof			
Building CS	Bull Up Roof - Gravel	29554 (10 Yr / 1998)	4	4,200	3 1,200		Detectorated sealant around pipes, previous repairs done by others, rusted vents, a red membrane			
Building MP	Built Up Roof - Gravel		4		\$ 1,300		Deteriorated sealant around pipes, previous repairs done by others, rusted vents, age membrane			
Building P	Built Up Roof - Gravel	25482 [10 Yr / 1996]	•	7,050	\$ 1,200		Detectorated sealant around pipes, grevious repairs done by others, usted wents, aged membrane, debris, nails in roof (no sealant), aged expansion joint			
Building Ft.	Built Up Roof - Gravel 29554 (10 Yr / 1998)	29554 (10 Yr / 1998)	-	- 0	1 1		Detentorated sealant around pipes, previous repairs done by others, rusted vents, agent membrane			

			_	_	_				_	_	_	_	_	_	_	_				
													:						:	
Deteriorated sealant around pipes, previous repairs done by others, rusted vents, aged membrane																				
	=		_																	Ш
\$ 1,200	\$ 23,600						-													
5,350			_																	П
•																				
25482 (10 Yr / 1996)																				
Built Up Roof - Gravel																				
Building MU									!											

Good Condition Repair / or PM needed Restoration Replace Notes Granule loss, open pitch pockets, open pipe penetrations, open laps on perimeter, previous repairs done by others, aged membrane Deteriorated sealant around fasteners Deteriorated sealant around fasteners Deteriorated sealant around fasteners Continue to maintain Restone / Replace Replace Apprix. Sq. 2022 Repair Ft Budgets 700 700 90 \$ 7,100 1,100 9,200 8,900 1,100 1,100 Rating 1-10 (1Foll, 10 Good) Tremco Warranty # Built Up Roof - Gravel Roof Type Maple HS Metal Metal Metal Building/section Lompoc USD Main Suilding Main Building Portable 1 Portable 3

	El Camino Adult School							Σ		
	Roof Type	Tremco Warranty #	Rating 1-10 (1fall, 10 Good)	Appril. Sq.	2022 Repair Budgets	Restors / Replace	Deficiencies	Notes	Good Condition or PM needed	Repair / Restoration Re
أ	Metal (Wood Deck)	89552 [10 Yr / 2001]	8		5 1,200		Deteriorated sealant around fasteners			
- 1	Angle Ptv (Metal Deck)	89552 (10 Yr / 2001)	75			Restore	Membrane dirty, signs of ponding			
3	Title					Replace	Multiple leaks reported			
	Built Up Roof - Gravel	82870 (10 Yr / 2000)		2,600	\$ 600		Deteriorated sealant around pilpes		20 //	
	Built U# Roof - Grave	82870 (10 Yr / 2000)		7,400	99		Deteriorated sealant around bibes			
1 3	Built Up Roof - Gravel	82870 (10 Yr / 2000)		7,400	\$ 600		Deteriorated sealant around place		_0	
	Shrigie		,				Reported leaks, shingle again			
	Built Up Roof Grave	89551 (10 Yr / 2001)	85	4,700	\$ 1,500		Previous repairs done in past by others, deteriorated sealant around pipes			
	Walls		+				Major cracks throughout / Foundation damage, multiple leaks reported, window damage with rust			
					\$ 4500					
									8	
									4777	
3										
1										