

LONG-RANGE FACILITIES PLAN

ROSEBURG PUBLIC SCHOOLS, OREGON

DECEMBER 13, 2024





Table of Contents

ACKNOWLEDGEMENTS	2
EXECUTIVE SUMMARY	
ENROLLMENT PROJECTIONS SUMMARY	
BOARD PRESENTATION: GRANT UPDATE	
COMMUNITY ENGAGEMENT	
LONG-RANGE PLANNING	
RECOMMENDATIONS	

APPENDICES



ACKNOWLEDGEMENTS

Woolpert, Inc. (formerly Cooperative Strategies) extends our appreciation to the Roseburg Public Schools for commissioning the development of enrollment projections, the facilities assessments, and the long-range facilities master plan. We also thank the following groups:

BOARD OF EDUCATION

Andrea Miner, Board Chair
Rodney Cotton, Board Vice-Chair
Keith Cubic, Director
Steve Hammerson, Director
Ann Krimetz, Director
Michael Leone, Director
Andrew Shirtcliff, Director

DISTRICT ADMINISTRATION

Jared Cordon, Superintendent
Michelle Knee, Assistant Superintendent
Cheryl Northam, Director of Finance & Operations
Tracy Grauf, Physical Plant Manager
Melissa Roberts, Director of Student Services
Chelsea Duncan, Communications Coordinator

WOOLPERT, INC.

David Sturtz, Vice President Ann Hoffsis, Vice President Susan Miller, Senior Director



EXECUTIVE SUMMARY

2022-23Update Building
Assessments

2023-24 Enrollment Projections

2023-24Facilities Master Plan Update

2024 Identify Priorities **2024**Board Review and
Approval Submit to State

Background Information

In November of 2023, Woolpert, Inc. (formerly Cooperative Strategies) was retained by Roseburg Public Schools (RPS) to update the enrollment projections and its **long-range facilities master plan (LRFP) that would align short-term and long-term facilities repairs and capital investment to support the educational needs of the district's students**. The LRFP incorporates information from the facility assessments that were completed in November of 2022. It also includes information from the enrollment report, utilization and capacity factors of its school facilities, community survey results, and engagement with school leadership and the Board of Education.

The November 2022 facilities' assessment tied to the Oregon Department of Education's parameters for school district assessments and incorporated additional facility needs that were in addition to ODE's requirements. The report is included in the Appendix.

The objective of this updated LRFP is to provide the district and the community a road map to improve facility conditions, learning environments, and functionality of the district's schools. The plan will allow Roseburg Public Schools and its community to prioritize investments in its facilities and school learning spaces to support its academic offerings.



Building Assessments

Woolpert assessed the Roseburg Public Schools' facilities in accordance with OAR 581-027-0035, utilizing the Oregon Department of Education "TAP" assessment workbook. The facilities assessed included:

Eastwood Elementary School	Sunnyslope Elementary School
Fir Grove Elementary School	Winchester Elementary School
Fullerton IV Elementary School	John C Fremont Middle School
Green Elementary School	Joseph Lane Middle School
Hucrest Elementary School	Rose Alternative High School
Melrose Elementary School	Roseburg High School

The assessments included an evaluation of the physical building systems, as identified with Uniformat Level III. This non-destructive assessment evaluated such major building systems as: foundations, roofing, flooring, doors, windows, walls, electrical, HVAC, plumbing, fire protection, communication systems, furniture, fixtures, and equipment. The facility site was also assessed to identify the condition of school site roadways, parking lots, pedestrian walkways, fencing, site lighting, and utilities.

In addition to the physical condition assessments, a school safety audit and ADA assessment were performed at each school site. The safety audit focused on presence of clearly defined drop-off / pick-up areas, adequacy of lighting on campuses, clear lines of site from administration to moderate entrances to buildings. The ADA assessments focused on ADA accessibility into the school, and ADA compliance throughout the facility. Appendix A depicts details related to these issues by site.

The table below provides a summary of building information, along with capacity, enrollment and utilization levels for the 2023-24 school year. Please note we incorporated cost escalation for deficiencies and replacement costs for 2024 that align with the 2022 assessments.

	Building Information Cap												Capacity, En	apacity, Enrollment & Utilization			
School	Grade	Orignal Build	Age	Sq. Ft	Deficiencies 2022		ficiencies w/ st escalation 2024	Rep	placement Cost 2022	F	Replacement Costs 2024	FCI with Escal (2024)	2013-14 Enrollment	2023-24 enrollment	Chg in Enrol	Util 23-24	
Eastwood ES	K-5	1957	67	38,000	\$ 2,184,452	\$	2,589,886	\$	19,429,020	\$	23,035,042	11.2%	451	384	-14.86%	76%	
Fir Grove ES	K-5	1960	64	30,690	\$ 1,813,627	\$	2,150,236	\$	15,691,490	\$	18,603,827	11.6%	290	262	-9.66%	77%	
Fullerton IV ES	K-5	1961	63	44,811	\$ 2,939,918	\$	3,485,567	\$	22,911,416	\$	27,163,770	12.8%	329	340	3.34%	68%	
Green ES	K-5	1949	75	33,993	\$ 1,957,643	\$	2,320,981	\$	17,380,281	\$	20,606,057	11.3%	309	251	-18.77%	50%	
Hucrest ES	K-5	1955	69	46,790	\$ 1,433,393	\$	1,699,430	\$	23,923,259	\$	28,363,410	6.0%	413	405	-1.94%	85%	
Melrose ES	K-5	1948	76	32,500	\$ 1,773,700	\$	2,102,898	\$	16,616,925	\$	19,701,022	10.7%	289	335	15.92%	82%	
Sunnyslope ES	K-5	1965	59	46,970	\$ 1,340,820	\$	1,589,676	\$	24,015,291	\$	28,472,524	5.6%	282	252	-10.64%	61%	
Winchester ES	K-5	1940	84	43,454	\$ 1,699,480	\$	2,014,903	\$	22,217,596	\$	26,341,176	7.6%	350	309	-11.71%	54%	
John C Fremont MS	6-8	1951	73	102,736	\$ 5,610,380	\$	6,651,665	\$	54,952,254	\$	65,151,379	10.2%	668	650	-2.69%	94%	
Joseph Lane MS	6-8	1954	70	98,504	\$ 5,023,242	\$	5,955,554	\$	52,688,608	\$	62,467,601	9.5%	664	566	-14.76%	76%	
Rose School				32,750	\$ 3,122,811	\$	3,702,404	\$	19,320,863	\$	22,906,810	16.2%					
Roseburg HS	9-12	1964	60	292,347	\$ 14,549,961	\$	17,250,430	\$	172,470,113	\$	204,480,525	8.4%	1772	1665	-6.04%	83%	
		1955	69	843,545	\$ 43,449,427	\$	51,513,630	\$	461,617,115	\$	547,293,143	9.4%	5,817	5,419	-6.84%	76%	



Recent Facility Capital Investments and Funding

Roseburg Public Schools completed their previous long-range facilities master plan in school year 2019-20. Since that time, the district has invested approximate \$25.3 million capital dollars to address several of the identified needs at school sites across the district. Investments included upgrades to security supports and infrastructure.

Security investments included security vestibules at eleven schools, fencing at primary and secondary schools, Raptor visitor management system and seismic upgrades to multipurpose/gymnasiums at Fremont and Joseph Lane middle schools and Winchester Elementary School.

Infrastructure investments included a new softball facility at Roseburg High School, new bathroom facilities at Hucrest Elementary, wireless controllers and Wi-Fi installed at each school, flooring replacement in classrooms and a cafeteria, cafeteria pocket tables installed at seven schools, and hand-washing stations and dishwashers placed at several schools.

These investments were funded through the leveraging of grant dollars made available through ESSER (Federal – Elementary and Secondary School Emergency Relief Fund) and Oregon's Seismic Rehabilitation Grant Program for seismic upgrades. The kitchen upgrades were funded through the Nutrition Services fund. The balance of the capital improvements was made with General Fund and Major Maintenance Fund dollars to compliment the grant dollars and meet Title IX requirements.

Over the past ten years the district has sought and secured over \$18 million in seismic grant awards. In addition, the district was recently awarded \$1.25 million grant dollars from the federal governments Renew America's Schools Programs. These dollars will be used to address a small portion of the indoor air quality upgrades needed in district schools.

ENROLLMENT PROJECTIONS SUMMARY


Woolpert developed 10-year enrollment projections for the Roseburg School District using the cohort survival methodology. The cohort survival method is a popular methodology used to project K-12 enrollment. This methodology uses historical live birth data and historical student enrollment to age a known population throughout the school grades. The percentage of students who move from grade to grade, year to year (survival ratios) are analyzed to determine a projection ratio that is applied to current and future enrollment to develop the enrollment projections. The cohort survival methodology inherently considers the net effects of historical trends in migration, housing, dropouts, transfers to and from charter schools, open enrollment, and deaths. This methodology does not assume changes in policies, program offerings, or future changes in housing and migration patterns.

Roseburg Public Schools serves over 5,600 students in 8 elementary schools, 2 middle schools, 1 high school, and a virtual campus in the 2023-24 school year.

From 2014-15 to the 2020-21 school year, K-12 enrollment decreased by 416 students. Since the 2020-21 school year, K-12 enrollment has increased by 46 students. Based on the cohort survival methodology, enrollment is projected to decrease over the next ten years.



The historic enrollment and recommended projections are depicted in the following table:



The following table depicts projections by grade levels:

Projected Enrollment - Recommended - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	399	384	355	313	351	351	351	351	351	351
1	409	417	402	371	327	367	367	367	367	367
2	421	414	423	407	376	331	372	372	372	372
3	418	419	412	421	405	375	330	370	370	370
4	426	416	416	410	419	403	372	328	368	368
5	435	427	417	417	411	420	404	373	329	368
6	433	437	429	418	419	413	421	405	375	330
7	467	434	438	431	420	420	414	423	407	376
8	412	462	429	433	425	415	415	409	418	402
9	367	409	459	426	430	422	412	412	406	415
10	423	356	397	445	413	417	409	399	400	394
11	429	399	336	374	419	389	393	386	376	377
12	442	436	405	341	380	426	395	399	392	382
Undefined	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,481	5,410	5,318	5,207	5, 195	5,149	5,055	4,994	4,931	4,872
Grand Total	5,621	5,550	5,458	5,347	5,335	5,289	5,195	5,134	5,071	5,012

The district has also experienced a loss of students due to families electing to attend school through on-line options. The ability to encourage families and students to return to in person learning could benefit future enrollment levels. Below is the table that depicts the *Transfers In* and the *Transfers Out* of the district.



Transfers In/Out

	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24*
Transfer In	161	211	206	169	239	273	124	117	124	136
Transfer Out	192	212	247	234	238	308	244	283	301	302
+/- Students	-31	-1	-41	-65	1	-35	-120	-166	-177	-166

Source: Roseburg Public Schools

Of note, according to the City of Roseburg's Community Development Department, they permit about 30 new single-family homes per year. There is also a development for 22 duplexes that is under review pending the submittal of a plat map, although it is uncertain if the project will move forward. It is important to track the development of this option and its potential student yield.

Since the completion of the enrollment report, the City of Roseburg, at their July 22, 2024, meeting, approved the land swap that allowed for a piece land with severe slopes inside the Urban Growth Boundary to be exchanged for a flat residential parcel. The Douglas County Commissioners approved this exchange at their September 11, 2024, meeting.

There are many factors that can influence student enrollment including, but not limited to, changes or additions in program offerings, student transfer policy changes, grade reconfigurations, housing and development activity, etc. It is important to keep a close eye on these trends as they are difficult to predict, and they can have an impact on projected enrollment. (The full enrollment projections report is available in Appendix).

BOARD PRESENTATION

The preliminary TAP Grant update was provided for the Roseburg Public Schools' board meeting on May 22, 2024. This presentation provided an overview of each of the facilities condition assessment and the review of both historic and projected enrollment for the district. The presentation included the process and proposed timeline for the development of the long-range facilities plan for the district. (This presentation is included in the Appendix).

The school board had a robust conversation about the priorities for the district. There was discussion about the recommendations from the prior Facilities Master Plan of 2019, that focused on school consolidations and changes to grade configurations. The recommendations to consolidate schools and reconfigure grades served at schools were not supported by the board. Therefore, the discussion moved toward addressing deficiencies and facility needs identified by leadership and staff. The board emphasized the need to work with the community to prioritize how to address those facility needs over the next several years.

COMMUNITY ENGAGEMENT

Roseburg Public Schools' administration and Woolpert reviewed the previous master plan, the 2022 facilities assessment data, and the enrollment projections. Also discussed were the two recent attempts to secure support for a bond that would provide funds to for identified upgrades and improvements.

Upon discussion with the board at the May 2024 meeting, it was decided to postpone any discussion of a bond until they understood the community's priorities. The school board met in September and determined the timing of investments based on immediate needs and life cycles. The school board directed staff to move forward with a survey to solicit input from the community regarding their investment priorities.



The survey was made available from October 22nd through November 2nd. Two video call options on October 24th and 25th were made available to the community. An in-person meeting was provided on November 1st, 2024.

The following questions were asked in the survey:

- 1. Please rank/prioritize the facility investments you want Roseburg Public Schools to make within the next two years.
- 2. Please rank/prioritize the facility site investments you want Roseburg Public Schools to consider within the next three to five years.
- 3. Please select your top three priorities for Roseburg Public Schools to consider for investment at five years and beyond. (Open option to submit other priorities)
- 4. Open question: Are there other improvements and/or renovations you would like Roseburg Public Schools to consider in the development of its long-range facilities plan?
- 5. Please indicate your affiliation to Roseburg Public Schools.
- 6. How many years have you lived in the district?
- 7. Your age.

The district had 533 respondents to the survey. The community's responses to survey questions and the openended questions, delineate the support for upgrades to schools' HVAC systems to ensure improved indoor air quality for students and staff. There is also strong support for upgrades to security systems district-wide.

As the district moves forward to formulate its building portfolio strategy to address deficiencies and upgrades to systems, it intends to engage with the community to understand the level of investment it is willing to make to address the priorities identified through the survey and through the comprehensive site assessments. A detailed report of the survey, responses and comments is found in the Appendix.

LONG-RANGE FACILITIES PLAN

Considerations

The purpose of the five to ten-year long-range facilities master plan is to prioritize the major capital investments that will be needed to support the district's educational vision. The plan takes into consideration current and desired educational plans, evaluates facility conditions and related capital needs, and provides guidance of capital investments aligned with budgets, capacity, and current/future enrollments.

The Roseburg Public Schools manages over 840,000 square feet across twelve campuses. The average age of its facilities that serve its current student population is sixty-nine years. The oldest building, Winchester Elementary School was built in 1940. It's newest building is Roseburg High School, built in 1964. The 2022 assessment identified \$44 million in deficiencies that need to be addressed at the district schools. That amount has escalated to over \$51 million in 2024.

Renovations and investments have been made in these facilities to maintain and operate in good standing, but it is important to understand the life-cycle of these facilities and the need to address deficiencies and invest in education spaces to support student learning in the 21st century.



Capacity and Utilization

One of the critical factors in long-range planning is to evaluate how the facilities are currently utilized and how they will be utilized in the future in alignment with enrollment projections. Utilization levels range from a low of 50% at Green Elementary School to a healthy 94% at John C. Fremont Middle School. Utilization is a critical component to the sustainability of providing quality education and experiences for students and staff.

Utilization levels can assist in the framing of a long-range facilities plan to afford consideration for grade reconfiguration and the repurposing of underutilized facilities for alternative learning needs. The board currently is not in support of consolidation or grade reconfigurations. There is an interest in maintaining the current structure of student learning. As the district moves forward with the evaluation of investment opportunities, it is critical to keep an eye on utilization of facilities to ensure capital investments are made in facilities that will serve the district well into the future.

RECOMMENDATIONS

Assessments by School

As noted earlier, Roseburg Public Schools completed the assessments of its school facilities in late 2022. Those assessments were used to identify facility needs by schools. This information was used to assist in the development and prioritization of investments in Roseburg Public Schools.

Requests to Support Investments in School Facilities

In 2022, the district asked its community to support a bond initiative of \$70 million dollars to address generators at schools, elementary school playground replacements, turf fields for middle schools, educational upgrades at all elementary and middle schools, and career and technology investments. The passage of the bond was not successful.

The following year, the district went forward with a bond for approximately \$83 million to address safety and security issues, indoor air quality, life cycle challenges, and removal of asbestos in buildings, and a rebuild of Old Main High School to provide updated learning spaces. This bond request was not supported by the community.

Long-range Facilities' Planning

The district wants to build on the experience of its past two attempts to garner support for a bond. Therefore, it is beginning the work to educate the community about pressing needs of its facilities. The district leadership and the school board worked through the needs identified in the assessments and broke them into categories of urgency.

The district brought these facility needs to the community in the form of a survey. As the district moves forward with the information it has gathered from the survey responses, it hopes to build support from its constituents to raise funds and secure grants to provide sufficient funds to make the necessary investments in its schools.

The board's categories presented to the community were as follows:

1) Investments within the next two years

- a. Air Quality Improvements
- b. Controlled Access Systems district-wide
- c. Technology and Infrastructure Upgrades



- d. Specialize Program Upgrades
- 2) Investments within the next three to five years
 - a. Plumbing upgrades district wide
 - b. Electrical upgrades district wide
- 3) Investments beyond, five to ten years
 - a. ADA upgrades
 - b. Asbestos removal district-wide
 - c. Fire Alarm detection and notification
 - d. Generators installed district-wide
 - e. New multi-purpose gymnasiums at middle schools
 - f. Roseburg High School upgrade
 - g. Outdoor spaces for middle schools
 - h. Roofing upgrades
 - i. Drop off/pick up upgrades for safety at elementary schools
 - j. Elementary school playground

The priorities identified by the board were evaluated by the community and their willingness to support certain investments. Indoor air quality is a top priority for the district as well as the community. There is agreement in the need to improve school sites, at the elementary and secondary levels. There is also alignment with upgrades to facilities. The next steps will be for the district administration and the board to work closely with community members to build and secure support to address the capital needs identified through the assessments and those priorities identified in the survey. The board will also need to keep an eye on enrollment and changes to utilization levels, particularly at the elementary school level. Enrollment will be a critical component in the investment strategy and implementation of the long-range facilities plan.



ENROLLMENT PROJECTIONS REPORT

ROSEBURG PUBLIC SCHOOLS

APRIL 3, 2024



TABLE OF CONTENTS

SECTION	PAGE
ACKNOWLEDGEMENTS	2
EXECUTIVE SUMMARY	3
ENROLLMENT PROJECTION METHODOLOGY	5
U.S. CENSUS	7
GENERAL DEMOGRAPHICS	17
ESTIMATED SCHOOL-AGED POPULATION CHANGE	18
HOUSING DATA	20
RESIDENT LIVE BIRTH DATA	22
SURVIVAL RATIOS	24
HISTORICAL ENROLLMENT	25
PROJECTED ENROLLMENT	28
CONCLUSION	37

ACKNOWLEDGMENTS

On behalf of Cooperative Strategies, we would like to extend our appreciation to Soderstrom Architects and Roseburg Public Schools for the opportunity to assist them in developing this Enrollment Projections Report. As a planning team, we hope that this document will serve Roseburg Public Schools for years to come.

COOPERATIVE STRATEGIES

Ann Hoffsis, REFP, Chief Operating Officer Galina Lyogky, Associate Director Cynthia Casarez, Associate

> One Easton Oval, Suite 400 Columbus, OH 43219

> > P. 614.798.8828

www.coopstrategies.com

EXECUTIVE SUMMARY

The district-wide enrollment projections for Roseburg Public Schools included in this report were developed using the cohort survival methodology and Cooperative Strategies' custom enrollment projection software, S.T.E.P. [Student Trends & Enrollment Projections]. This custom software was developed in collaboration with The Ohio State University and is based on industry best practices as well as the national experience Cooperative Strategies has with schools, school districts, and state agencies.




Roseburg Public Schools serves 5,667 students in 8 elementary schools, 2 middle schools, 1 high school, and a virtual campus in the 2023-24 school year.

The projections presented in this report are meant to serve as a planning tool for the future, representing the most likely direction of the District. Enrollment projections were developed using the cohort survival methodology and by analyzing the following data outlined in this report:

- Historical enrollment, by grade, by year
- Resident live birth data

- Census data
- Building permits

K-12 student enrollment in Roseburg Public Schools has decreased by 370 students. From the 2014 -15 to the 2020-21 school year, K-12 enrollment decreased by 416 students. Since the 2020-21 school year, K-12 enrollment has increased by 46 students. Based on the cohort survival methodology, enrollment is projected to decrease over the next ten years.



ROSEBURG PUBLIC SCHOOLS ENROLLMENT PROJECTIONS REPORT

As with any projection, the District should pay close attention to the variables associated with determining enrollment projections discussed in this document. Any one or more of these factors can increase or decrease enrollment within the Roseburg Public Schools. When projecting future enrollments, it is vital to track the number of live births, the amount of new housing activity, and the change in household composition. It is recommended that the data contained in this report be reviewed on an annual basis to determine how more recent trends and any new housing development will impact the enrollment. In addition, any of the following factors could cause a significant change in projected student enrollment:

- Boundary adjustments
- New school openings
- School closures
- Changes / additions in program offerings
- Preschool programs
- Policy Changes
- Changes in grade configuration
- Interest rates / unemployment shifts

- Intra- and inter-District transfers
- Magnet / charter / private school openings or closures
- Zoning changes
- Annexations
- Unplanned new housing activity
- Planned, but not built, housing
- School voucher programs
- Pandemics

Obviously, certain factors can be gauged and planned for far better than others. For instance, it may be relatively straightforward to gather housing data from local builders regarding the total number of lots in a planned subdivision and calculate the potential student yield. However, planning for changes in the unemployment rate, and how these may either boost or reduce public school enrollment, proves to be more difficult. In any case, it is essential to gather a wide variety of information in preparation for producing enrollment projections.


When looking ahead at a school district's enrollment over the next two, five, or ten years, it is helpful to approach the process from a global perspective. For example: How many new homes have been constructed each year? How many births have occurred each year in relation to the resident population? Is housing experiencing a turnover—if so, what is the composition of families moving in/out? Are more or less students attending private school or being home-schooled? What has the unemployment rate trend been over the past ten years? What new educational policies are in place that could affect student enrollment figures?

The cohort survival methodology is a standard methodology used throughout the educational planning industry to project enrollment. The enrollment projections developed for the Roseburg Public Schools were developed using the cohort survival method.


ENROLLMENT PROJECTION METHODOLOGY

Introduction

Tracing the landscape of the country's public school enrollment back over the past fifty years reveals demographic, economic, and social changes. The United States as a whole continues to undergo major shifts in public student enrollment, due in large part to past events including the baby boom, the availability and use of birth control, and the development of suburbs. The baby boom of the late 1940s and 50s was followed by the baby bust of the 1960s and 70s. This gave rise to the echo baby boom of the 1980s.



Source: CDC, National Vital Statistics Report




Nationwide, districts have experienced the effects of the echo baby bust of the 1990s. From the 1950s to the 1970s, a dramatic downsizing of the family unit occurred. A direct result was the declining school enrollment of the 1970s and 1980s. As of the 2010 Census, the size of a family was at an all-time low of 3.14 persons. The live birth rate increased for the first time in several years in 1998 and increased again in 2000 and 2006. However, the birth rate resumed a descending pattern in 2008 and reached an all-time low of 10.9 (per 1,000) in 2020 and remained at 11.0 in 2021.

Cohort Survival Method

The cohort survival methodology (sometimes referred to as the grade progression ratio method) is a widely used enrollment projection model that is used by many school districts and state and federal agencies to project K-12 enrollment.

A cohort is a group of persons [in this case, students]. The cohort survival enrollment projection methodology uses historic live birth data and historic student enrollment to "age" a known population or cohort throughout the school grades. For instance, a cohort begins when a group of kindergarteners enrolls in grade K and moves to first grade the following year, second grade the next year, and so on.



A "survival ratio" is developed to track how this group of students increased or decreased in number as they moved through the grade levels. By developing survival ratios for each grade transition [i.e. 2nd to 3rd grade] over a ten year period of time, patterns emerge. A projection ratio for each grade transition is developed based on analysis of the survival ratios. The projection ratios are used as a multiplier in determining future enrollment.

For example, if student enrollment has consistently increased from the 8th to the 9th grade over the past ten years, the survival ratio would be greater than 100% and could be multiplied by the current 8th grade enrollment to develop a projection for next year's 9th grade. This methodology can be carried through to develop ten years of projection figures. Because there is not a grade cohort to follow for students coming into kindergarten, resident live birth counts are used to develop a birth-to-kindergarten survival ratio. Babies born five years previous to the kindergarten class are compared in number, and a ratio can be developed to project future kindergarten enrollments.

The cohort survival method is useful in areas where population is stable [relatively flat, growing steadily, or declining steadily], and where there have been no significant fluctuations in enrollment, births, and housing patterns from year to year. The cohort survival methodology inherently considers the net effects of factors such as migration, housing, dropouts, transfers to and from charter schools, open enrollment, and deaths. This methodology does not assume changes in policies, program offerings, or future changes in housing and migration patterns.

U.S. CENSUS


This section presents data from the United States Census Bureau and estimates from the American Community Survey (ACS) to demonstrate the demographic characteristics and historic trends of the population within the District boundary. While the Census is conducted every 10 years, the American Community Survey collects social, housing, educational, occupational, financial, and other demographic data from over 3.5 million households throughout the nation monthly and is compiled yearly, as mandated by the U.S. Constitution. This data helps public officials, federal/state/local agencies, school districts, etc. assess historic trends and plan for the future.

The Roseburg Public Schools is located in Douglas County, Oregon. It serves parts or all of the Melrose CCD, Myrtle Creek-Riddle CCD, North Umpqua CCD, Roseburg CCD, Sutherlin CCD, Tenmile CCD, Green CDP*, Melrose CDP*, Roseburg North CDP*, and Roseburg City. The data on the following pages is aggregated and color-coordinated by the boundaries shown in the map on the following page.

According to the U.S. Census Bureau, Oregon is a state where minor civil divisions (such as townships, commissioner districts, towns, etc.) are not legally established, so Census County Divisions (CCDs) are formed and used by the Census Bureau to aggregate Census data. While CCDs are not used in legal or governmental functions, they dissolve counties into smaller sections for statistical purposes by following geographical or man-made features (such as mountain ranges, rivers, roads, etc.) and are named after local places or settlements that help identify their location.

It should be noted that the District does not necessarily serve whole municipalities but data presented by municipality is for the whole municipality.

Data for municipalities symbolized with hash marks is not excluded from the municipalities symbolized with solid colors.



Population

According to the 2020 Census, since the 2010 Census, the total population and median age increased in the District boundary.

Based on the 2020 Census, since the 2010 Census, the number of children under the age of 5 has decreased by 12 percent, the number of children ages 5 - 19 has increased by 10 percent, the number of adults ages 20 - 64 has decreased by 2 percent, and the number of adults ages 65 and over has increased by 32 percent in the District boundary.

The 2000, 2010, and 2020 population counts are shown in the table on the right.

5 10		Under 5	5 to 19	20 to 64	65 years	Total	Median
Population	n	years	years	years	and over	Population	Age
Danahaan Dahila	2000**	-	-	-	-	-	-
Roseburg Public	2010	2,670	8,293	26,341	9,391	46,695	44.0
Schools	2020	2,341	9,144	25,718	12,407	48,479	45.7
Boundary	Trend	/					
	2000	5,651	20,773	56,107	17,868	100,399	41.2
Douglas County	2010	5,648	18,999	60,450	22,570	107,667	46.1
Douglas County	2020	5,270	20,810	57,924	29,788	111,201	45.7
	Trend		<u> </u>	/			
	2000	202	1,013	2,873	766	4,854	45.1
Melrose CCD	2010	183	878	3,009	1,167	5,237	51.6
Mellose CCD	2020	205	905	2,788	1,758	5,550	45.7
	Trend	\rangle					
	2000	812	2,921	7,323	2,244	13,300	40.0
Myrtle Creek-	2010	769	2,688	7,956	2,831	14,244	44.8
Riddle CCD	2020	659	2,732	7,426	3,733	14,221	45.7
	Trend	/	\				_
	2000	212	1,264	3,077	688	5,241	41.7
North Umpqua	2010	166	875	3,171	1,006	5,218	49.6
CCD	2020	219	943	2,691	1,574	5,316	45.7
	Trend	\rangle		()	/
	2000	2,252	7,154	20,345	6,573	36,324	39.5
Roseburg CCD	2010	2,462	7,185	22,523	7,763	39,933	42.0
Roseburg CCD	2020	2,098	7,994	22,269	10,009	41,352	45.7
	Trend	<					
	2000**	-	1	-	-	-	-
Sutherlin CCD	2010	787	2,775	8,617	3,698	15,877	48.3
Sutileriiii CCD	2020	777	3,151	8,260	4,958	16,761	45.7
	Trend						
	2000	584	1,995	5,189	1,425	9,193	38.8
Tenmile CCD	2010	526	1,847	5,694	1,909	9,976	44.8
remine ccb	2020	555	2,125	5,676	2,520	10,607	45.7
	Trend	<u>\</u>	<u> </u>				
	2000	512	1,510	3,464	605	6,091	32.9
Green CDP	2010	530	1,568	4,319	1,098	7,515	37.1
	2020	458	1,687	4,226	1,474	7,614	45.7
	Trend	_					
	2000**	-	-	-	-	-	-
Melrose CDP	2010	15	148	423	149	735	49.2
	2020	25	160	415	248	834	45.7
	Trend			/			/
	2000	1,302	3,617	11,120	4,000	20,039	39.2
Roseburg North	2010	1,308	3,821	12,003	4,049	21,181	41.1
CDP	2020	1,218	4,582	12,906	5,577	23,683	45.7
	Trend		_/		_/		
	2000	279	1,015	3,159	1,039	5,492	43.0
Roseburg City	2010	371	991	3,260	1,290	5,912	45.4
	2020	210	741	2,298	1,218	4,375	45.7
	Trend	ot available)					

Source: U.S. Census (**data not available)

Race / Ethnicity & Language

The table below shows race and ethnic distribution throughout the Roseburg Public Schools boundary and the municipalities that are served by the District.

Race & Ethnicit	ty	White alone	Black or African American alone	American Indian and Alaska Native alone	Asian alone	Native Hawaiian and Other Pacific Islander alone	Some other race alone	Two or more races	Total Population	Hispanic Population
Bereit or B LE	2000**	-	-	-	-	-	-	-	-	-
Roseburg Public	2010	92.4%	0.4%	1.6%	1.3%	0.1%	1.2%	3.0%	46,695	5.0%
Schools Boundary	2020	86.3%	0.4%	1.4%	1.4%	0.2%	2.1%	8.2%	48,479	6.5%
	2000	93.7%	0.2%	1.6%	0.6%	0.0%	0.9%	3.0%	100,399	3.3%
Douglas County	2010	92.4%	0.3%	1.8%	1.0%	0.1%	1.2%	3.2%	107,667	4.7%
	2020	86.4%	0.4%	1.8%	1.1%	0.1%	1.9%	8.4%	111,201	6.0%
	2000	95.3%	0.0%	1.2%	0.5%	0.1%	0.1%	2.9%	4,854	2.6%
Melrose CCD	2010	95.3%	0.2%	1.1%	0.7%	0.0%	0.7%	2.0%	5,237	3.5%
	2020	88.5%	0.4%	1.1%	0.8%	0.2%	1.0%	7.9%	5,550	4.3%
Mountle Creek Biddle	2000	92.4%	0.1%	2.5%	0.5%	0.0%	0.8%	3.6%	13,300	2.9%
Myrtle Creek-Riddle CCD	2010	90.5%	0.2%	2.6%	1.2%	0.1%	1.0%	4.3%	14,244	4.3%
ССБ	2020	85.7%	0.3%	3.0%	1.2%	0.2%	1.8%	7.9%	14,221	5.6%
	2000	92.8%	0.1%	2.6%	0.6%	0.1%	0.0%	3.7%	5,241	2.3%
North Umpqua CCD	2010	94.2%	0.4%	2.0%	0.3%	0.1%	0.8%	2.3%	5,218	3.8%
	2020	85.6%	0.1%	1.7%	0.6%	0.1%	1.5%	10.3%	5,316	4.5%
	2000	93.9%	0.2%	1.5%	0.8%	0.0%	0.9%	2.6%	36,324	3.6%
Roseburg CCD	2010	91.9%	0.4%	1.7%	1.3%	0.2%	1.3%	3.2%	39,933	5.3%
	2020	85.7%	0.5%	1.6%	1.5%	0.2%	2.2%	8.4%	41,352	6.9%
	2000**	-	-	-	-	-	-	-	-	-
Sutherlin CCD	2010	93.4%	0.2%	1.7%	0.6%	0.1%	1.3%	2.7%	15,877	4.7%
	2020	87.0%	0.3%	1.6%	0.9%	0.1%	1.8%	8.3%	16,761	6.4%
	2000	94.3%	0.2%	2.0%	0.4%	0.0%	1.1%	2.1%	9,193	2.5%
Tenmile CCD	2010	92.6%	0.3%	1.8%	0.8%	0.1%	0.8%	3.7%	9,976	3.7%
	2020	87.2%	0.5%	1.8%	0.8%	0.1%	1.7%	7.9%	10,607	4.7%
	2000	92.9%	0.0%	1.6%	0.3%	0.1%	2.8%	2.3%	6,091	4.5%
Green CDP	2010	93.3%	0.2%	1.8%	0.8%	0.0%	1.1%	2.7%	7,515	5.8%
	2020	85.2%	0.3%	1.3%	1.0%	0.2%	2.4%	9.7%	7,614	6.8%
	2000**	-	-	-	-	-	-	-	-	-
Melrose CDP	2010	95.0%	0.1%	0.3%	1.1%	0.0%	1.0%	2.6%	735	3.9%
	2020	89.0%	0.4%	0.2%	1.4%	0.0%	1.8%	7.2%	834	4.7%
	2000	94.3%	0.4%	1.7%	1.0%	0.0%	0.5%	2.2%	20,039	5.8%
Roseburg North CDP	2010	91.0%	0.5%	1.7%	1.6%	0.3%	1.4%	3.5%	21,181	5.5%
_	2020	85.1%	0.5%	1.7%	1.6%	0.2%	2.5%	8.3%	23,683	7.6%
	2000	95.3%	0.0%	1.3%	0.9%	0.0%	0.8%	1.7%	5,492	3.1%
Roseburg City	2010	92.4%	0.4%	1.4%	1.1%	0.0%	1.6%	3.0%	5,912	5.8%
	2020	86.2%	0.4%	1.8%	2.0%	0.2%	1.5%	7.9%	4,375	6.3%

Source: U.S. Census (**data not available)

According to the 2022 ACS estimates, most of the population in the District boundary speaks only English. The table below shows the languages spoken at home.

Languages Spoken at Home (2022 Estimates)	Roseburg Public Schools Boundary	Douglas County	Melrose CCD	Myrtle Creek-Riddle CCD	North Umpqua CCD	Roseburg CCD	Sutherlin CCD	Tenmile CCD	Green CDP	Melrose CDP	Roseburg North CDP	Roseburg City
Population 5 years and over	46,921	105,934	5,186	13,581	5,487	39,104	16,655	9,897	7,799	749	22,483	4,101
Speak only English	94.7%	96.1%	92.9%	96.7%	95.8%	95.1%	97.6%	97.5%	95.7%	100.0%	95.6%	96.7%
Speak a language other than English	5.3%	3.9%	7.1%	3%	4.2%	4.9%	2.4%	2.5%	4.3%	0.0%	4.4%	3.3%
Spanish	1,509	2,449	346	243	231	1,061	138	180	221	0	390	85
Other Indo-European languages	632	991	19	96	0	507	144	39	85	0	364	0
Asian and Pacific Island languages	346	483	4	54	1	310	77	24	26	0	215	50
Other languages	23	164	0	57	0	23	34	0	0	0	23	0

Source: American Community Survey 5-Year Estimates (2022)

Housing & Families

According to the 2022 ACS estimates, approximately 71% of the homes in the Roseburg Public Schools boundary are single-unit structures while 13% of the homes are 2-or-more-unit structures. Nearly 27% of the District boundary's households have at least one school-aged (or younger) child in them.

Housing & Families (2022 Estimates)	Roseburg Public Schools Boundary	Douglas County	Melrose CCD	Myrtle Creek-Riddle CCD	North Umpqua CCD	Roseburg CCD	Sutherlin CCD	Tenmile CCD	Green CDP	Melrose CDP	Roseburg North CDP	Roseburg City
Total Households	20,095	46,242	2,043	5,888	2,185	17,127	7,371	4,218	3,200	335	9,954	1,967
1-unit structures	71.1%	70.6%	84.7%	72.3%	78.8%	67.7%	70.4%	69.1%	68.5%	95.8%	68.3%	51.6%
2-or-more-unit structures	13.2%	10.1%	0.7%	8.6%	6.7%	15.1%	8.3%	7.2%	0.3%	0.0%	24.1%	5.9%
Mobile homes and all other types	15.7%	19.3%	14.6%	19.0%	14.5%	17.1%	21.4%	23.7%	3 <mark>1.2%</mark>	4.2%	7.7%	42.5%
Owner occupied:	69.7%	71.5%	92.0%	70.3%	74.7%	65.5%	73.0%	79.1%	82.3%	88.7%	55.2%	80.8%
Renter occupied:	30.3%	28.5%	8.0%	29.7%	25.3%	34.5%	27.0%	20.9%	17.7%	11.3%	44.8%	19.2%
Households with one or more people under 18 years	26.7%	24.4%	24.4%	23.3%	23.6%	26.7%	22.9%	27.4%	25.2%	28.4%	29.5%	22.9%
Average Family Size	2.82	2.83	2.87	2.90	2.87	2.79	2.85	3.01	3.02	3.19	2.78	2.57
Average Household Size	2.39	2.36	2.70	2.38	2.49	2.33	2.35	2.47	2.53	2.38	2.27	2.28

According to the U.S. Census Bureau, "A family is a group of two people or more (one of whom is the householder) related by birth, marriage, or adoption and residing together."

A household consists of all persons (related and unrelated) living within a housing unit.

A housing unit is a single room, house, apartment, or other group of residential rooms that have direct outside access; group quarters are excluded.

According to the 2022 ACS Estimates, the average family size has decreased in the District boundary while the average household size has increased.

From the 2010 Census to the 2020 Census, the number of total and occupied housing units in the District boundary has increased while the number of vacant units has decreased.

Family/Househol	d Size	Average Family	Average
		Size	Household Size
	2000**	-	-
Roseburg Public	2010	2.84	2.35
Schools Boundary	2022*	2.82	2.39
	Trend	/	
	2000	2.90	2.48
Danielas Canada	2010	2.82	2.38
Douglas County	2022*	2.83	2.36
	Trend		
	2000	2.91	2.67
Malana CCD	2010	2.82	2.55
Melrose CCD	2022*	2.87	2.70
	Trend	<u></u>	
	2000	2.99	2.57
Myrtle Creek-	2010	2.87	2.48
Riddle CCD	2022*	2.90	2.38
	Trend		
	2000	2.95	2.60
North Umpqua	2010	2.68	2.32
CCD	2022*	2.87	2.49
	Trend		
	2000	2.89	2.41
	2010	2.85	2.33
Roseburg CCD	2022*	2.79	2.33
	Trend	/	
	2000**	-	-
	2010	2.81	2.42
Sutherlin CCD	2022*	2.85	2.35
	Trend		
	2000	2.98	2.64
	2010	2.85	2.49
Tenmile CCD	2022*	3.01	2.47
	Trend	\	
	2000	3.08	2.79
C CDD	2010	3.02	2.68
Green CDP	2022*	3.02	2.53
	Trend		
	2000**	-	-
Maluance	2010	2.93	2.63
Melrose CDP	2022*	3.19	2.38
	Trend		
	2000	2.88	2.32
Roseburg North	2010	2.84	2.23
CDP	2022*	2.78	2.27
	Trend	/	
	2000	2.79	2.31
	2010	2.76	2.24
Roseburg City	2022*	2.57	2.28
	Trend		
Courses II C Consus (7			~

Source: U.S. Census (2020 Census data not available)

Housing Occup	ancv	Total	Occupied	Vacant
		housing units	housing units	housing units
	2000**	-	-	-
Roseburg Public	2010	20,815	19,363	1,452
Schools Boundary	2020	21,170	19,949	1,221
,	Trend			
	2000	43,284	39,821	3,463
	2010	48,915	44,581	4,334
Douglas County	2020	49,774	45,817	3,957
	Trend			/
	2000	1,891	1,816	75
	2010	2,183	2,044	139
Melrose CCD	2020	2,287	2,167	120
	Trend			/
	2000	5,478	5,129	349
Myrtle Creek-	2010	6,196	5,705	491
Riddle CCD	2020	6,266	5,795	471
	Trend			
	2000	2,249	1,934	315
North Umpqua	2010	2,513	2,142	371
CCD	2020	2,434	2,170	264
	Trend			
	2000	15,667	14,651	1,016
	2010	17,924	16,678	1,246
Roseburg CCD	2020	18,178	17,107	1,071
	Trend			
	2000**	-	-	-
	2010	7,109	6,511	598
Sutherlin CCD	2020	7,276	6,786	490
	Trend			
	2000	3,720	3,477	243
	2010	4,320	3,985	335
Tenmile CCD	2020	4,523	4,257	266
	Trend			
	2000	2,322	2,162	160
	2010	2,979	2,796	183
Green CDP	2020	3,022	2,900	122
	Trend			
	2000**	-	-	-
	2010	304	278	26
Melrose CDP	2020	330	316	14
	Trend		/	/
	2000	8,868	8,240	628
Roseburg North	2010	9,732	9,081	651
CDP	2020	10,642	9,961	681
	Trend			
	2000	2,450	2,311	139
	2010	2,883	2,638	245
Roseburg City	2020	2,025	1,924	101
	Trend			
Courses IIC Consus				

Source: U.S. Census

**data not available

^{*}Source: American Community Survey 5-Year Estimates 2022

^{**}data not available

Industry & Occupation

The table below illustrates the types of industry and occupation categories in the Roseburg Public Schools boundary and the areas it serves. 2022 estimates are calculated for the civilian employed population 16 years and over.

Industry & Occupation for the Civilian Employed Population 16 Years and Over, (2022 Estimates)	Roseburg Public Schools Boundary	Douglas County	Melrose CCD	Myrtle Creek-Riddle CCD	North Umpqua CCD	Roseburg CCD	Sutherlin CCD	Tenmile CCD	Green CDP	Melrose CDP	Roseburg North CDP	Roseburg City
Total population	48,479	111,201	5,550	14,221	5,316	41,352	16,761	10,607	7,614	834	23,683	4,375
Civilian employed population, 16 years and over	20,317	43,613	2,223	5,158	2,042	16,738	7,227	4,247	3,877	433	9,324	1,583
	r	n		Industry	1		1	•			1	
Agriculture, forestry, fishing and hunting, and mining	5.5%	5.9%	12.5%	7.6%	5.1%	4.6%	4.2%	6.2%	5.0%	18.2%	3.5%	7.5%
Construction	6.1%	6.5%	2.4%	4.0%	9.6%	7.4%	7.0%	3.9%	6.9%	0.0%	7.7%	0.9%
Manufacturing	10.6%	11.4%	13.6%	14.9%	1.2%	9.8%	13.4%	14.0%	9.8%	5.1%	9.9%	8.3%
Wholesale trade	3.0%	2.4%	2.0%	1.6%	2.9%	3.2%	1.0%	3.3%	9.1%	3.5%	1.3%	1.9%
Retail trade	13.5%	12.6%	11.0%	15.0%	9.3%	13.6%	11.2%	10.9%	11.1%	1.6%	15.0%	13.6%
Transportation and warehousing, and utilities	2.9%	5.0%	3.2%	7.3%	11.7%	2.7%	2.7%	10.2%	2.2%	14.8%	3.2%	1.5%
Information	1.4%	1.1%	0.0%	0.5%	1.5%	1.7%	0.2%	1.9%	0.0%	0.0%	2.4%	2.3%
Finance and insurance, and real estate and rental and leasing	5.2%	4.0%	3.0%	4.0%	2.5%	5.6%	4.2%	1.6%	6.0%	0.0%	4.3%	6.8%
Professional, scientific, and management, and administrative and waste management services	10.0%	7.9%	13.0%	4.7%	10.0%	9.0%	8.8%	5.4%	11.5%	10.6%	8.7%	8.9%
Educational services, and health care and social assistance	23.9%	23.4%	21.7%	19.8%	29.6%	23.5%	29.0%	18.9%	20.5%	31.4%	25.5%	22.1%
Arts, entertainment, and recreation, and accommodation and food services	9.3%	10.6%	6.7%	12.9%	11.7%	10.4%	8.0%	13.1%	11.6%	2.1%	8.4%	16.5%
Other services, except public administration	3.4%	4.3%	7.6%	5.2%	2.8%	3.1%	5.0%	6.1%	1.3%	7.2%	4.4%	2.0%
Public administration	5.1%	4.8%	3.3%	2.4%	2.0%	5.6%	5.2%	4.6%	4.9%	5.5%	5.9%	7.7%
				Occupation								
Management, business, science, and arts occupations	33.0%	30.4%	37.7%	24.1%	40.6%	32.3%	29.6%	23.9%	30.9%	39.7%	34.5%	26.1%
Service occupations	18.4%	19.9%	10.3%	24.4%	18.7%	19.8%	21.0%	21.0%	20.3%	18.5%	16.2%	35.6%
Sales and office occupations	23.5%	22.2%	22.9%	19.4%	18.5%	22.8%	25.0%	19.5%	25.6%	24.5%	21.1%	23.9%
Natural resources, construction, and maintenance occupations	9.5%	11.1%	11.2%	11.9%	13.2%	9.4%	9.7%	12.8%	10.8%	9.5%	9.9%	3.5%
Production, transportation, and material moving occupations	15.6%	16.4%	17.9%	20.2%	9.1%	15.8%	14.7%	22.9%	12.4%	7.9%	18.4%	11.0%

Financial Status

According to the U.S. Census Bureau, earnings come from a job (salary/wages) while income also includes payments such as "Social Security, pensions, child support, public assistance, annuities, money derived from rental properties, interest and dividends." The table below shows income, earnings, poverty status, and unemployment rate in the ACS 2022 estimates.

Financial Status (2022 Estimates)	Roseburg Public Schools Boundary	Douglas County	Melrose CCD	Myrtle Creek-Riddle CCD	North Umpqua CCD	Roseburg CCD	Sutherlin CCD	Tenmile CCD	Green CDP	Melrose CDP	Roseburg North CDP	Roseburg City
					Earning	S						
Population 16 years and over with earnings	23,126	49,944	2,665	5,896	2,529	19,131	7,952	4,913	4,347	444	10,716	1,741
Full-time, year-round workers with earnings	13,162	28,266	1,410	3,261	1,369	10,889	4,450	2,936	2,574	254	6,018	1,011
\$1 to \$9,999 or loss	1.5%	2.0%	4.6%	0.9%	6.0%	1.1%	2.9%	2.5%	0.4%	0.0%	1.1%	2.1%
\$10,000 to \$14,999	3.9%	2.5%	4.3%	1.5%	0.1%	4.1%	1.2%	0.6%	4.2%	0.0%	4.3%	2.3%
\$15,000 to \$24,999	6.9%	7.7%	5.1%	11.6%	12.5%	7.1%	7.9%	6.4%	4.7%	15.7%	6.7%	2.3%
\$25,000 to \$34,999	12.4%	14.5%	7.4%	15.5%	12.3%	13.0%	16.8%	20.5%	9.2%	13.8%	13.8%	28.0%
\$35,000 to \$49,999	24.0%	23.3%	20.7%	21.2%	22.8%	24.8%	20.4%	21.0%	18.3%	0.0%	29.7%	25.9%
\$50,000 to \$64,999	18.1%	17.0%	15.2%	19.6%	8.4%	18.7%	18.1%	12.4%	29.0%	9.1%	17.0%	9.9%
\$65,000 to \$74,999	8.9%	9.9%	10.2%	8.2%	11.1%	9.3%	10.1%	18.2%	12.8%	12.6%	6.7%	7.0%
\$75,000 to \$99,999	13.6%	12.1%	21.3%	11.0%	8.2%	13.0%	8.0%	13.1%	13.2%	29.1%	12.0%	17.6%
\$100,000 or more	10.7%	11.0%	11.2%	10.4%	18.6%	9.0%	14.5%	5.2%	8.2%	19.7%	8.8%	4.9%
Median Earnings	\$36,039	\$34,914	\$40,987	\$33,483	\$33,308	\$35,161	\$35,394	\$33,733	\$42,099	\$31,838	\$34,238	\$33,175
				Н	lousehold I	ncome						
Total Households	20,095	46,242	2,043	5,888	2,185	17,127	7,371	4,218	3,200	335	9,954	1,967
Less than \$10,000	4.8%	4.5%	4.2%	5.4%	3.0%	4.8%	3.1%	3.1%	3.0%	20.0%	5.7%	6.0%
\$10,000 to \$14,999	6.0%	5.0%	0.0%	4.8%	2.6%	7.4%	3.9%	4.3%	5.2%	0.0%	8.4%	5.3%
\$15,000 to \$24,999	9.0%	10.7%	2.4%	15.3%	9.4%	9.5%	13.2%	10.0%	5.8%	0.0%	10.2%	9.5%
\$25,000 to \$34,999	8.0%	9.0%	9.4%	9.7%	6.5%	8.3%	7.7%	12.0%	6.6%	10.4%	8.2%	13.5%
\$35,000 to \$49,999	14.4%	14.7%	10.2%	12.9%	11.4%	15.8%	13.1%	15.9%	15.7%	10.4%	17.0%	13.6%
\$50,000 to \$74,999	19.7%	20.2%	11.9%	23.0%	21.1%	20.8%	18.7%	18.8%	23.4%	0.0%	19.5%	20.4%
\$75,000 to \$99,999	12.6%	11.9%	15.7%	8.7%	19.2%	12.4%	10.8%	12.3%	15.7%	9.9%	12.7%	9.8%
\$100,000 to \$149,999	14.9%	14.6%	26.3%	12.3%	13.7%	13.0%	16.6%	17.0%	17.3%	26.9%	10.5%	15.7%
\$150,000 to \$199,999	5.6%	5.7%	10.6%	5.2%	8.1%	5.2%	6.4%	4.7%	3.5%	4.8%	5.5%	6.2%
\$200,000 or more	5.0%	3.7%	9.3%	2.7%	4.9%	2.9%	6.5%	2.0%	3.8%	17.6%	2.3%	0.0%
Median income (dollars)	\$58,316	\$56,440	\$91,736	\$52,064	\$68,665	\$55,227	\$60,731	\$56,750	\$65,304	\$94,671	\$50,297	\$55,810
					Poverty St	atus						
% below poverty level	15.1%	14.9%	8.9%	15.3%	21.1%	16.9%	10.0%	13.6%	9.7%	13.3%	20.0%	13.9%
Under 18 years	14.0%	19.2%	12.7%	22.3%	31.1%	16.2%	14.1%	18.7%	1.4%	0.0%	19.4%	15.1%
18 to 64 years	16.6%	16.2%	10.0%	16.0%	23.5%	18.2%	10.0%	15.3%	9.9%	17.3%	21.7%	16.4%
65 years and over	12.3%	9.0%	4.4%	8.8%	8.6%	14.0%	7.3%	5.7%	16.9%	12.7%	15.6%	9.3%
				Ur	nemployme	nt Rate						
Population 20 to 64 years	4.6%	5.9%	3.3%	11.9%	4.2%	5.1%	5.6%	4.9%	4.5%	0.0%	4.3%	6.7%

Computer / Internet Access

The table below shows the presence of a computer and/or internet subscription in households in the geographies served by the District, according the 2022 ACS estimates. Percentages shown are based on total households.

% of Total Households with Internet/Computers (2022 Estimates)	Roseburg Public Schools Boundary	Douglas County	Melrose CCD	Myrtle Creek-Riddle CCD	North Umpqua CCD	Roseburg CCD	Sutherlin CCD	Tenmile CCD	Green CDP	Melrose CDP	Roseburg North CDP	Roseburg City
Has a Computer	92.5%	91.7%	89.9%	90.2%	96.3%	92.2%	93.6%	90.8%	92.5%	74.6%	92.4%	92.0%
Has an Internet subscription	87.4%	85.4%	82.6%	84.6%	87.9%	87.0%	90.0%	81.2%	86.1%	59.7%	89.5%	75.2%
Has no Internet Subscription	5.1%	6.3%	7.2%	5.6%	8.4%	5.2%	3.6%	9.6%	6.4%	14.9%	2.9%	16.7%
Has no Computer	7.5%	8.3%	10.1%	9.8%	3.7%	7.8%	6.4%	9.2%	7.5%	25.4%	7.6%	8.0%

School Enrollment

The tables below summarize the percentage of the population living within the Roseburg Public Schools boundary, by age group, enrolled in school; enrolled in school and attending public school; and enrolled in school and attending private school, based on U.S. Census American Community Survey (ACS) 5–Year Estimates. Home-schooled children are counted in the private school data. If anyone in these age groups had not attended any school in the 3 months before the survey was conducted, they were considered to not be enrolled in any school.

It should be noted that this data is not a survey of the students attending schools in the District; rather, it is based on monthly surveys sent out by the ACS to households in the District boundary. This survey data is then used to create the estimates shown in the tables below.

ROSEBURG PUBLIC SCHOOLS BOUNDARY % OF AGE GROUP ENROLLED IN SCHOOL

Age Group	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	Trend
3-4	27.5%	29.8%	25.3%	30.8%	39.8%	45.9%	54.7%	65.0%	58.9%	54.7%	~
5-9	95.6%	93.9%	91.4%	90.9%	94.0%	94.0%	95.2%	91.8%	92.0%	91.1%	V~
10-14	100.0%	99.6%	99.6%	99.7%	99.7%	99.7%	100.0%	97.5%	97.0%	97.0%	
15-17	94.4%	95.3%	92.4%	90.5%	92.4%	93.6%	95.3%	94.3%	96.8%	96.4%	~~~
18-19	66.5%	66.5%	63.1%	60.0%	62.8%	61.6%	64.5%	74.4%	59.9%	55.5%	$\sim \sim$

Source: U.S. Census American Community Survey 5-Year Estimates 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022

ROSEBURG PUBLIC SCHOOLS BOUNDARY % OF AGE GROUP ENROLLED IN SCHOOL ATTENDING PUBLIC SCHOOL

Age Group	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	Trend
3-4	26.5%	43.4%	55.6%	47.5%	62.4%	54.7%	63.0%	41.0%	41.6%	37.4%	___\\\\\\\\\\\\\\\\\\\\\\\\\
5-9	85.7%	92.5%	93.6%	94.2%	87.9%	88.5%	87.7%	84.9%	83.0%	83.8%	>
10-14	93.8%	93.2%	95.5%	95.5%	95.6%	95.2%	93.0%	94.6%	93.9%	89.8%	\sim
15-17	97.2%	96.5%	96.1%	97.8%	97.2%	96.9%	95.6%	97.0%	93.5%	89.3%	}
18-19	98.2%	94.3%	91.9%	89.2%	89.0%	90.5%	93.0%	88.7%	90.0%	90.3%	\~

Source: U.S. Census American Community Survey 5-Year Estimates 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022

ROSEBURG PUBLIC SCHOOLS BOUNDARY

% OF AGE GROUP ENROLLED IN SCHOOL ATTENDING PRIVATE SCHOOL

Age Group	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	Trend
3-4	73.5%	56.6%	44.4%	52.5%	37.6%	45.3%	37.0%	59.0%	58.4%	62.6%	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
5-9	14.3%	7.5%	6.4%	5.8%	12.1%	11.5%	12.3%	15.1%	17.0%	16.2%	{
10-14	6.2%	6.8%	4.5%	4.5%	4.4%	4.8%	7.0%	5.4%	6.1%	10.2%	~
15-17	2.8%	3.5%	3.9%	2.2%	2.8%	3.1%	4.4%	3.0%	6.5%	10.7%	~~/
18-19	1.8%	5.7%	8.1%	10.8%	11.0%	9.5%	7.0%	11.3%	10.0%	9.7%	\

Source: U.S. Census American Community Survey 5-Year Estimates 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022

GENERAL DEMOGRAPHICS

The following information represents block group estimates created from market research and U.S. Census data obtained from the Environmental Systems Research Institute [ESRI]. ESRI provides a yearly update to their demographic data in increments of five years. To make updates to their demographic data set, they use American Community Survey [ACS] data that takes a series of monthly sample surveys but only from areas with populations of 65,000 or more. One year of ACS data is a period estimate as a twelve-month average, rather than a single point in time.


According to the ESRI estimates, the total population of Douglas County is estimated to increase over the next five years. As illustrated in the table below, the number of children, ages 5-18, is estimated to decrease by 35 children, or approximately less than 1 percent.

DOUGLAS COUNTY
POPULATION ESTIMATES

Age Group	2023	2028	Change	% Change
Ages 0-2	3,067	3,049	-18	-0.6%
Ages 3-4	2,104	2,088	-16	-0.8%
Ages 5-10	6,542	6,498	-44	-0.7%
Ages 11-13	3,452	3,515	63	1.8%
Ages 14-18	5,757	5,703	-54	-0.9%
Ages 5-18	15,751	15,716	-35	-0.2%
Total Population	111,508	111,993	485	0.4%

Source: ESRI BIS


DOUGLAS COUNTY POPULATION ESTIMATES



ROSEBURG PUBLIC SCHOOLS BOUNDARY ESTIMATED SCHOOL-AGED POPULATION CHANGE 2023-2028

The map on the following page shows school-aged population change in the U.S. Census block groups within / around the Roseburg Public Schools boundary. Population changes are based on 2023 and 2028 estimates.

A block group is defined by the U.S. Census Bureau as, "a statistical district of a census tract, generally defined to contain between 600 and 3,000 people and 240 and 1,200 housing units, and the smallest geographic unit for which the Census Bureau tabulates sample data."



HOUSING DATA


Housing development and building permits are tracked to determine their effect on student enrollment. The table and graphs below illustrate the number of single- and multi-family building permits issued in Douglas County and Roseburg City since 2000.

BUILDING PERMITS


	DOUGLAS	COUNTY	ROSEBU	RG CITY
Year	Single-Family	Multi-Family	Single-Family	Multi-Family
2000	305	58	34	26
2001	311	94	57	14
2002	328	32	41	16
2003	303	45	61	25
2004	346	14	103	12
2005	438	59	103	41
2006	397	18	98	14
2007	373	9	30	9
2008	272	4	0	0
2009	170	12	0	0
2010	133	48	0	0
2011	96	4	0	0
2012	102	58	0	0
2013	150	14	0	0
2014	160	6	0	0
2015	170	2	0	0
2016	211	4	0	0
2017	238	6	0	0
2018	276	8	0	0
2019	268	2	0	0
2020	235	8	0	0
2021	325	112	0	0
2022	226	12	0	0
2023*	151	95	0	0

Source: SOCDS Building Permits Database (*preliminary through December 2023)

DOUGLAS COUNTY BUILDING PERMITS



ROSEBURG CITY BUILDING PERMITS



ROSEBURG PUBLIC SCHOOLS ENROLLMENT PROJECTIONS REPORT

PAGE 20 4/3/2024 According to the City of Roseburg's Community Development Department, they permit about 30 new single-family homes per year. There is also a development for 22 duplexes that is under review pending the submittal of a plat map, although they are not sure if the project is moving forward. The table below shows the residential development that is planned or occurring in the Roseburg Public Schools boundary.

Roseburg Public Schools - Residential Development

Development	Total Units	Unit Type	Location	Timeline
Indomitus Heights	22	SFA	Hurcrest Neighborhood	The subdivision has not yet submitted for final plat, and we are unsure if it is moving forward or not.

Source: City of Roseburg, Community Development Department

It should be noted that according to information found on the City of Roseburg's <u>Urban Growth Boundary (UGB) Swap Project</u> website, the UGB is currently under review and consideration. Should the UGB Swap be approved by the Roseburg City Council and the Douglas County Board of Commissioners, approximately 220 acres of land that is identified as suitable for urban development may create residential development opportunities.

RESIDENT LIVE BIRTH DATA


Utilization of resident live birth data is recommended when projecting future kindergarten enrollments. This data provides a helpful overall trend. Large bubbles in birth counts, either up or down, can also be planned for or anticipated by the District.

In addition, the live birth counts are used in determining a birth-to-kindergarten and birth-to-first grade survival ratio. This ratio identifies the percentage of children born in a representative area who attend kindergarten and first grade in the District five and six years later. The survival ratios for birth-to-kindergarten, birth-to-first grade, as well as grades 1-12 can be found on page 24 of this report.

Data is arranged by the residence of the mother. For example, if a mother lives in Roseburg City but delivers her baby in Portland, the birth is counted in Roseburg City. Live birth counts are different from live birth rates. The live birth count is simply the actual number of live births. A birth rate is the number of births per 1,000 women in a specified population group.

The table and graph include the resident live birth counts for ZIP codes 97457, 97462, 97470, 97471, 97479, 97486, and 97495. Upon analysis of the map on the following page, only live birth counts for ZIP codes 97470, 97471, 97486, and 97495 were used in the development of the enrollment projections.


ROSEBURG PUBLIC SCHOOLS ZIP CODES RESIDENT LIVE BIRTH COUNTS



ROSEBURG PUBLIC SCHOOLS ZIP CODES RESIDENT LIVE BIRTH COUNTS

Year	97457	97462	97470	97471	97479	97486	97495
2004	121	34	507	0	100	6	6
2005	114	22	535	0	99	4	7
2006	110	20	598	0	111	8	14
2007	100	25	569	0	98	3	17
2008	111	28	496	73	95	6	12
2009	105	37	274	240	96	9	9
2010	117	28	269	225	101	1	13
2011	111	31	263	245	100	4	18
2012	108	27	236	290	99	7	13
2013	86	25	250	268	85	7	14
2014	128	32	251	274	99	5	19
2015	104	28	236	287	99	5	11
2016	102	28	234	283	98	4	16
2017	116	39	252	249	90	3	17
2018	93	26	235	264	110	8	8
2019	119	21	219	282	76	6	19
2020	85	30	203	278	105	8	17
2021	103	35	201	251	107	2	14
2022	81	27	156	242	88	5	9

Source: Oregon Health Authority



SURVIVAL RATIOS

The chart below demonstrates the ten-year changes in enrollment as students move through the system. Percentages greater than 100 indicate that there are more students than there were in the previous grade the previous year. In other words, there was an increase in student population where new students were added to the system. Percentages less than 100 indicate that there was decline or students left the system. If the exact number of students in 1st grade during the 2015-16 school year were present in 2nd grade for the 2016-17 school year, the survival ratio would be 100 percent.

Birth-to-Kindergarten and Birth-to-First Grade: This ratio indicates the number of children born in the area who attend kindergarten and first grade in the district five and six years later. What is important to note is the trend in survival ratios, not necessarily the actual number.

The COVID-19 pandemic introduced an unforeseen level of volatility, nationwide, as seen in the survival ratios for the 2019-20 to 2020-21 and 2020-21 to 2021-22 school years. These ratios will need to be monitored closely over the next few years as new trends are established.

The following table illustrates the historical survival ratios in the Roseburg Public Schools over the past ten years by grade level.

Survival Ratios - District-wid	e
--------------------------------	---

from	to	Birth to K	K to 1	Birth to 1	1 to 2	2 to 3	3 to 4	4 to 5	5 to 6	6 to 7	7 to 8	8 to 9	9 to 10	10 to 11	11 to 12
2014-15	2015-16	78.94%	100.46%	82.14%	99.37%	98.13%	105.19%	102.50%	98.70%	96.23%	101.11%	101.80%	99.08%	89.57%	102.21%
2015-16	2016-17	79.81%	99.25%	78.35%	102.52%	99.37%	99.58%	101.85%	100.44%	96.71%	100.23%	98.90%	98.23%	96.07%	105.06%
2016-17	2017-18	83.33%	101.89%	81.32%	101.51%	95.76%	103.40%	103.62%	98.38%	102.21%	95.24%	99.77%	93.11%	91.44%	102.16%
2017-18	2018-19	86.83%	105.27%	87.73%	104.41%	101.24%	105.36%	101.44%	103.09%	96.51%	100.65%	99.52%	93.78%	94.27%	100.25%
2018-19	2019-20	81.60%	98.08%	85.16%	101.88%	96.89%	100.98%	101.11%	101.82%	98.00%	106.60%	100.64%	103.11%	91.89%	100.76%
2019-20	2020-21	68.65%	93.08%	75.96%	93.03%	91.60%	90.83%	91.53%	89.06%	91.85%	93.08%	90.22%	93.39%	94.66%	112.83%
2020-21	2021-22	74.30%	112.43%	77.18%	100.96%	99.77%	99.33%	103.03%	100.26%	104.67%	100.43%	103.28%	99.34%	94.06%	108.33%
2021-22	2022-23	76.20%	104.01%	77.28%	103.61%	104.51%	102.82%	104.50%	102.94%	103.96%	104.69%	102.37%	97.67%	93.99%	94.90%
2022-23	2023-24	75.92%	104.53%	79.65%	101.20%	99.54%	98.64%	98.40%	100.43%	99.29%	93.91%	97.76%	95.79%	94.36%	101.42%
mean simp	ole all years	78.40%	102.11%	80.53%	100.94%	98.53%	100.68%	100.89%	99.46%	98.82%	99.55%	99.36%	97.06%	93.37%	103.10%
std. dev. sim	nple all years	5.37%	5.42%	3.95%	3.32%	3.62%	4.45%	3.92%	4.23%	4.15%	4.65%	3.85%	3.34%	2.00%	5.14%
mean sim	ple 5 years	75.33%	102.43%	79.05%	100.14%	98.46%	98.52%	99.71%	98.90%	99.55%	99.74%	98.85%	97.86%	93.79%	103.65%
std. dev. sir	mple 5 years	4.64%	7.30%	3.67%	4.11%	4.72%	4.59%	5.12%	5.61%	5.18%	6.13%	5.27%	3.68%	1.10%	7.00%
mean sim	ple 3 years	75.47%	106.99%	78.04%	101.92%	101.27%	100.26%	101.98%	101.21%	102.64%	99.68%	101.14%	97.60%	94.14%	101.55%
std. dev. sir	mple 3 years	1.03%	4.72%	1.40%	1.46%	2.81%	2.24%	3.18%	1.50%	2.92%	5.43%	2.96%	1.77%	0.20%	6.72%
mean sim	ple 2 years	76.06%	104.27%	78.47%	102.41%	102.02%	100.73%	101.45%	101.69%	101.62%	99.30%	100.06%	96.73%	94.17%	98.16%
std. dev. sir	mple 2 years	0.20%	0.37%	1.68%	1.70%	3.52%	2.96%	4.32%	1.77%	3.30%	7.63%	3.26%	1.33%	0.26%	4.61%
mean weigh	ited all years	76.32%	103.71%	79.23%	101.06%	99.58%	99.65%	100.42%	99.90%	100.13%	98.78%	99.29%	96.95%	93.94%	102.25%
std. dev. weig	hted all years	4.30%	5.50%	3.20%	3.17%	3.87%	3.90%	4.10%	4.16%	4.18%	5.25%	4.00%	2.73%	1.09%	5.83%
mean weigl	hted 5 years	75.54%	104.53%	78.69%	101.34%	100.31%	99.40%	100.20%	100.44%	100.67%	97.74%	99.25%	96.76%	94.18%	101.23%
std. dev. wei	ghted 5 years	2.26%	4.50%	1.88%	2.57%	3.45%	3.07%	3.83%	3.36%	3.60%	5.53%	3.60%	2.02%	0.48%	5.48%
mean weigl	hted 3 years	75.91%	104.75%	79.14%	101.62%	100.42%	99.40%	99.65%	100.87%	100.32%	96.06%	98.78%	96.26%	94.28%	100.55%
std. dev. wei	ghted 3 years	0.42%	1.92%	1.20%	1.13%	2.31%	1.94%	2.95%	1.17%	2.42%	5.12%	2.41%	1.16%	0.18%	3.59%
mean weigl	hted 2 years	75.94%	104.51%	79.54%	101.32%	99.77%	98.84%	98.69%	100.55%	99.51%	94.42%	97.98%	95.88%	94.34%	101.11%
std. dev. wei	ghted 2 years	0.08%	0.16%	0.71%	0.72%	1.50%	1.26%	1.84%	0.76%	1.41%	3.25%	1.39%	0.57%	0.11%	1.96%

ROSEBURG PUBLIC SCHOOLS HISTORICAL ENROLLMENT

As indicated in the table below, K-12 student enrollment in Roseburg Public Schools has decreased by 370 students. From the 2014-15 to the 2020-21 school year, K-12 enrollment decreased by 416 students. Since the 2020-21 school year, K-12 enrollment has increased by 46 students.

Historical Enrollment - District-wide

Grade	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
PK	31	35	32	65	59	55	36	68	66	67
K	435	401	423	455	468	448	370	399	397	391
1	477	437	398	431	479	459	417	416	415	415
2	480	474	448	404	450	488	427	421	431	420
3	462	471	471	429	409	436	447	426	440	429
4	440	486	469	487	452	413	396	444	438	434
5	462	451	495	486	494	457	378	408	464	431
6	451	456	453	487	501	503	407	379	420	466
7	450	434	441	463	470	491	462	426	394	417
8	444	455	435	420	466	501	457	464	446	370
9	437	452	450	434	418	469	452	472	475	436
10	441	433	444	419	407	431	438	449	461	455
11	453	395	416	406	395	374	408	412	422	435
12	465	463	415	425	407	398	422	442	391	428
SpEd	29	38	52	63	67	62	4	80	70	73
K - 12 Total	5,897	5,808	5,758	5,746	5,816	5,868	5,481	5,558	5,594	5,527
Grand Total	5,957	5,881	5,842	5,874	5,942	5,985	5,521	5,706	5,730	5,667

Source: Roseburg Public Schools


Historical Enrollment - District-wide

Grade	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
PK	31	35	32	65	59	55	36	68	66	67
K - 5	2,756	2,720	2,704	2,692	2,752	2,701	2,435	2,514	2,585	2,520
6 - 8	1,345	1,345	1,329	1,370	1,437	1,495	1,326	1,269	1,260	1,253
9 - 12	1,796	1,743	1,725	1,684	1,627	1,672	1,720	1,775	1,749	1,754
SpEd	29	38	52	63	67	62	4	80	70	73
K - 12 Total	5,897	5,808	5,758	5,746	5,816	5,868	5,481	5,558	5,594	5,527
Grand Total	5,957	5,881	5,842	5,874	5,942	5,985	5,521	5,706	5,730	5,667

Source: Roseburg Public Schools

The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

HISTORICAL ENROLLMENT - DISTRICT-WIDE



Other Enrollment


The table and graphs below show transfers-in and transfers-out in the District, according to data provided by Roseburg Public Schools.

Transfers In/Out


	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24*
Transfer In	161	211	206	169	239	273	124	117	124	136
Transfer Out	192	212	247	234	238	308	244	283	301	302
+/- Students	-31	-1	-41	-65	1	-35	-120	-166	-177	-166

Source: Roseburg Public Schools

^{*} Most recent report pulled, January 31, 2024



ROSEBURG PUBLIC SCHOOLS +/-STUDENTS




The table and graphs below show charter and non-public students in the District, according to data provided by Roseburg Public Schools.

Charter and Non-Public Students

	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
Charter & Non-Public	95	127	156	100	91	91	274	237	211	194

Source: Roseburg Public Schools

ROSEBURG PUBLIC SCHOOLS CHARTER AND NON-PUBLIC STUDENTS



The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.


PROJECTED ENROLLMENT

Cooperative Strategies developed low, moderate, high, and recommended enrollment projections for the Roseburg Public Schools. The moderate enrollment projections are based on a selected average or weighted average of survival ratios (in this case, a 3-year weighted average). The low and high enrollment projections are developed using statistical distributional theory, providing the District with a more conservative (low) and more liberal (high) enrollment projection. The recommended enrollment projection is based on a detailed analysis of historical enrollment and resulting survival ratios over the past 10 years. Significant shifts in survival ratio patterns are realized and accounted for in determining projection ratios independently for each grade level. The recommended illustrates the most likely direction of the District based on more recent trends.

The range of enrollment projections from low (conservative) to high (liberal) are offered due to the limitations of the cohort survival method in factoring changes to policies, program offerings, and future changes in housing and migration patterns. For example, the low enrollment projection might be used if housing declines significantly more than anticipated; the high enrollment projection might be used if housing growth increases at a more rapid rate than seen in recent years.

It should be noted that the actual live birth counts are available through 2022 and project kindergarten enrollment through 2027-28. To project kindergarten through 2033-34, a simple average of the last 3 years of live birth counts was used.

Projected PK enrollment does not follow the cohort survival method but is based on the current 2023-24 enrollment of 67 PK students.



ROSEBURG PUBLIC SCHOOLS PROJECTED ENROLLMENT—RECOMMENDED

Based on the Recommended projected enrollment, student enrollment in the Roseburg Public Schools is projected to decrease from 5,667 in the 2023-24 school year to 5,012 students in the 2033-34 school year.

Projected Enrollment - Recommended - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	399	384	355	313	351	351	351	351	351	351
1	409	417	402	371	327	367	367	367	367	367
2	421	414	423	407	376	331	372	372	372	372
3	418	419	412	421	405	375	330	370	370	370
4	426	416	416	410	419	403	372	328	368	368
5	435	427	417	417	411	420	404	373	329	368
6	433	437	429	418	419	413	421	405	375	330
7	467	434	438	431	420	420	414	423	407	376
8	412	462	429	433	425	415	415	409	418	402
9	367	409	459	426	430	422	412	412	406	415
10	423	356	397	445	413	417	409	399	400	394
11	429	399	336	374	419	389	393	386	376	377
12	442	436	405	341	380	426	395	399	392	382
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,481	5,410	5,318	5,207	5,195	5,149	5,055	4,994	4,931	4,872
Grand Total	5,621	5,550	5,458	5,347	5,335	5,289	5,195	5,134	5,071	5,012

Source: Cooperative Strategies


Projected Enrollment - Recommended - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K - 5	2,508	2,477	2,425	2,339	2,289	2,247	2,196	2,161	2,157	2,196
6 - 8	1,312	1,333	1,296	1,282	1,264	1,248	1,250	1,237	1,200	1,108
9 - 12	1,661	1,600	1,597	1,586	1,642	1,654	1,609	1,596	1,574	1,568
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,481	5,410	5,318	5,207	5,195	5,149	5,055	4,994	4,931	4,872
Grand Total	5,621	5,550	5,458	5,347	5,335	5,289	5,195	5,134	5,071	5,012

Source: Cooperative Strategies

The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

PROJECTED ENROLLMENT - RECOMMENDED - DISTRICT-WIDE



ROSEBURG PUBLIC SCHOOLS PROJECTED ENROLLMENT—MODERATE

Based on the Moderate projected enrollment, student enrollment in the Roseburg Public Schools is projected to decrease from 5,667 in the 2023-24 school year to 4,981 students in the 2033-34 school year.

Projected Enrollment - Moderate - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	399	384	355	313	351	351	351	351	351	351
1	410	418	402	372	328	367	367	367	367	367
2	422	416	425	409	378	333	373	373	373	373
3	422	423	418	427	411	380	334	375	375	375
4	426	419	421	415	424	408	377	332	373	373
5	432	425	418	419	414	423	407	376	331	371
6	435	436	429	421	423	418	426	410	379	334
7	467	436	438	430	423	424	419	428	412	381
8	401	449	419	420	413	406	408	402	411	395
9	365	396	444	414	415	408	401	403	398	406
10	420	352	381	427	398	400	393	386	388	383
11	429	396	332	359	403	376	377	370	364	366
12	437	431	398	334	361	405	378	379	372	366
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,465	5,381	5,280	5,160	5,142	5,099	5,011	4,952	4,894	4,841
Grand Total	5,605	5,521	5,420	5,300	5,282	5,239	5,151	5,092	5,034	4,981

Source: Cooperative Strategies


Projected Enrollment - Moderate - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K - 5	2,511	2,485	2,439	2,355	2,306	2,262	2,209	2,174	2,170	2,210
6 - 8	1,303	1,321	1,286	1,271	1,259	1,248	1,253	1,240	1,202	1,110
9 - 12	1,651	1,575	1,555	1,534	1,577	1,589	1,549	1,538	1,522	1,521
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,465	5,381	5,280	5,160	5,142	5,099	5,011	4,952	4,894	4,841
Grand Total	5,605	5,521	5,420	5,300	5,282	5,239	5,151	5,092	5,034	4,981

Source: Cooperative Strategies

The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

PROJECTED ENROLLMENT - MODERATE - DISTRICT-WIDE



ROSEBURG PUBLIC SCHOOLS PROJECTED ENROLLMENT—LOW

Based on the Low projected enrollment, student enrollment in the Roseburg Public Schools is projected to decrease from 5,667 in the 2023-24 school year to 4,708 students in the 2033-34 school year.

Projected Enrollment - Low- District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	398	383	354	312	350	350	350	350	350	350
1	406	414	398	368	324	363	363	363	363	363
2	420	411	418	402	372	328	367	367	367	367
3	417	417	408	416	400	370	326	365	365	365
4	423	411	411	402	410	394	364	321	360	360
5	427	416	404	404	395	403	387	358	315	354
6	432	428	417	406	405	397	404	389	360	317
7	462	429	425	414	403	402	394	401	386	357
8	391	434	402	398	388	377	377	369	376	362
9	361	382	424	393	389	379	369	368	361	367
10	417	346	366	405	376	373	363	353	353	345
11	429	393	326	344	382	354	351	342	333	332
12	430	424	389	323	341	378	351	347	338	329
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,413	5,288	5,142	4,987	4,935	4,868	4,766	4,693	4,627	4,568
Grand Total	5,553	5,428	5,282	5,127	5,075	5,008	4,906	4,833	4,767	4,708

Source: Cooperative Strategies


Projected Enrollment - Low- District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K - 5	2,491	2,452	2,393	2,304	2,251	2,208	2,157	2,124	2,120	2,159
6 - 8	1,285	1,291	1,244	1,218	1,196	1,176	1,175	1,159	1,122	1,036
9 - 12	1,637	1,545	1,505	1,465	1,488	1,484	1,434	1,410	1,385	1,373
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,413	5,288	5,142	4,987	4,935	4,868	4,766	4,693	4,627	4,568
Grand Total	5,553	5,428	5,282	5,127	5,075	5,008	4,906	4,833	4,767	4,708

Source: Cooperative Strategies

The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

PROJECTED ENROLLMENT - LOW- DISTRICT-WIDE



ROSEBURG PUBLIC SCHOOLS PROJECTED ENROLLMENT—HIGH

Based on the High projected enrollment, student enrollment in the Roseburg Public Schools is projected to decrease from 5,667 in the 2023-24 school year to 5,272 students in the 2033-34 school year.

Projected Enrollment - High - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	400	385	356	314	352	352	352	352	352	352
1	413	423	407	376	331	371	371	371	371	371
2	424	422	432	415	384	338	379	379	379	379
3	426	430	428	438	421	390	343	385	385	385
4	430	427	431	429	439	422	391	344	386	386
5	438	434	431	435	433	443 427		395	347	390
6	437	444	440	437	441	439 450		433	400	352
7	473	443	451	447	444	448 445		456	439	406
8	410	465	436	443	439	436	440	438	449	431
9	370	410	464	435	443	439 436		440	438	448
10	422	358	396	449	421	428	425	422	426	423
11	429	398	337	374	424	398	404	401	398	402
12	444	439	407	345	382	433	406	413	409	407
SpEd	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,516	5,478	5,416	5,337	5,354	5,337	5,269	5,229	5,179	5,132
Grand Total	5,656	5,618	5,556	5,477	5,494	5,477	5,409	5,369	5,319	5,272

Source: Cooperative Strategies


Projected Enrollment - High - District-wide

Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34	
PK	67	67	67	67	67	67	67	67	67	67	
K - 5	2,531	2,521	2,485	2,407	2,360	2,316 2,263		2,226	2,220	2,263	
6 - 8	1,320	1,352	1,327	1,327	1,324	1,323 1,335		1,327	1,288	1,189	
9 - 12	1,665	1,605	1,604	1,603	1,670	1,698	1,671	1,676	1,671	1,680	
SpEd	73	73	73	73	73	73	73	73	73	73	
K - 12 Total	5,516	5,478	5,416	5,337	5,354	5,337	5,269	5,229	5,179	5,132	
Grand Total	5,656	5,618	5,556	5,477	5,494	5,477	5,409	5,369	5,319	5,272	

Source: Cooperative Strategies

The varying shades of color in the table represent statistically significant cohort sizes. The darker blue represents smaller cohorts, while the darker red represents larger cohorts, comparatively.

PROJECTED ENROLLMENT - HIGH - DISTRICT-WIDE



CONCLUSION

As with any projection, the District should pay close attention to live birth counts, enrollment in elementary schools, open enrollment, non-public enrollment, in / out migration patterns, and any housing growth. It is recommended that this document be reviewed on an annual basis to determine how more recent growth and enrollment trends will impact the enrollment projections.

Cooperative Strategies is pleased to have had the opportunity to provide Soderstrom Architects and Roseburg Public Schools with this demographic study. We hope this document will provide the necessary information to make informed decisions about the future of Roseburg Public Schools.



Roseburg Public Schools


Long-range Facilities Plan Board Study Session

May 22, 2024





Strategic Plan



All students will receive the care, support and instruction needed to graduate from high school with plans for their most successful futures.











- 1 Terms and Process
 - 2 District-Wide Enrollment

Agenda

- 3 Facilities Overview/District Portfolio
 - 1 Investment Considerations

5 Discussion

Long-Range Facilities Plan

What is a long-range facility plan?

- A district wide long-term plan for facilities
- Data collection on facility conditions and adequacy of learning environments
- Identification of greatest need across facilities and planning areas
- o Balance of short-term needs (five to ten years) and long-term objectives

Data considered includes:

- Facility Conditions (now and near-term)
- Facility Capacity (programmatic & square feet)
- Facility Adequacy (how the facility does/does not support desired programs and teaching methods)
- Enrollments (historic, present, projected)
- District strategic plans
- Community priorities, engagement, and feedback

Key questions:

- Are the facilities we operate now, the ones we should continue to operate for the next 5-10+ years?
- Which facilities are in good enough condition, relative to their replacement value, to maintain and which ones require major renovation or replacement?
- Do all our students have equitable access to high-quality learning environments in a warm/cool, safe and dry school and educationally adequate?
- What is the history of your district and community and how should that inform future facility investments?



Definition of Terms

Gross Square Feet (GSF): Total square feet of the facility, does not include portables that may be located at the school site.

Facility Condition Index (FCI): This is a standard management benchmark that is used to objectively assess the current and projected condition of a building.

Program Capacity: The number of students a school building can serve with the parameters of programs that may be offered at a school (e.g. Significant Support Needs (SSN) center program).

Utilization Factor: It is very difficult to schedule every teaching station every period of the day. There may be a specialized space such as a lab for which there is insufficient enrollment to conduct classes each period. At times it is not possible to maintain an average enrollment of 25 students and there needs to be some room to adjust. It is recommended that the average load factor be 85% for the secondary level, representing an approximate utilization of a space 6 out of 7 periods during a school day.



Process: Facilities' Components



- How facilities should support and enhance educational programming
- How teaching & learning should function in each space
- How individual spaces should work together within the school, and school program offerings work together district wide to serves RPS' vision
- What tools each space should have to serve its core functions and whether these need to be fixed or flexible



Overview of the Process



Schedule for Long-Range Facilities Plan

Two-day focus groups: Collect Data & Community members, Refine Options and Background Information teachers/staff, BOE and Recommendations (Jan-April 2024) (October 2024) administration (Sept – Oct 2024) **Discuss with District Costs Update Assessment** Discuss and Priorities to Discuss Data; Enrollment Recommendations with with Community Projects; Priorities District (November 2024) (April-May 2024) (Aug/Sept) Meet with School **Update Costs for Present Final** District Board of Identified Priorities and Recommendations to **Education and District Board of Education for** Assessments and Develop Approval and to State **Options** Leadership (June-July 2024) (November 2024) (May 2024)



Facilities Master Planning

Facilities Master Plan: A strategic plan for directing major capital decisions, usually over a 5 to 10-year horizon.

- Population growth/decline
- Building conditions
- Program supports
- Address capacity

New Construction / Rebuilding our Schools



- Systems (roof, HVACS, etc.,)
- Replacement of facilities
- Safety and security

Major Renovations



- Career and Technical Education (CTE) – Industry Certifications
- Advanced Manufacturing,
 Advanced Healthcare
 w/growth opportunities UCC
- Special Education
- Other**

Program Investments



- Efficient use of spaces
- Do we have the right number of schools, at the right sizes, in the right locations, with the right learning environments to sustainably serve all students?

Efficiency & Efficacy



**Continue to build business relationships for apprenticeships and mentorships.



Portfolio: Investment Considerations



Building age and assessed condition



Instructional programming



Site size and location



Flexibility for future needs



Building capacity



Operating efficiencies



Projected regional enrollment




Community feedback



Learning environment adequacy



Portfolio: How It Supports Strategic Plan





District-Wide Enrollment

RPSD: Historic Enrollment by Grade

Historical Enrollment - District-wide

Grade	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
PK	31	35	32	65	59	55	36	68	66	67
K	435	401	423	455	468	448	370	399	397	391
1	477	437	398	431	479	459	417	416	415	415
2	480	474	448	404	450	488	427	421	431	420
3	462	471	471	429	409	436	447	426	440	429
4	440	486	469	487	452	413	396	444	438	434
5	462	451	495	486	494	457	378	408	464	431
6	451	456	453	487	501	503	407	379	420	466
7	450	434	441	463	470	491 462		426	394	417
8	444	455	435	420	466	501	457	464	446	370
9	437	452	450	434	418	469	452	472	475	436
10	441	433	444	419	407	431	438	449	461	455
11	453	395	416	406	395	374	408	412	422	435
12	465	463	415	425	407	398	422	442	391	428
SpEd	29	38	52	63	67	62	4	80	70	73
K - 12 Total	5,897	5,808	5,758	5,746	5,816	5,868	5,481	5,558	5,594	5,527
Grand Total	5,957	5,881	5,842	5,874	5,942	5,985	5,521	5,706	5,730	5,667

Source: Enrollment Report Woolpert, Inc., 2024..

Boxed area: COVID "years".

The 2024 graduating class started 3rd grade with 460+ students.

K-12 enrollment declined over 370 students in the past 10 years, ~6.0% with a slight rebound from Covid years.

Over the past 10 years, enrollment seems to decline during transition years (elementary to middle to high school).

Approximately 90% of school aged children attend public school.



Roseburg SD Boundaries and Population Change

DOUGLAS COUNTY
POPULATION ESTIMATES

Ages 5-10

Ages 11-13

7,000 6.000


Ages 0-2

Ages 3-4

It is anticipated that the total population of Douglas County will increase over the next five years.

School-aged population (ages 5-18) is estimated to decrease by 35 children, or approximately less than 1% from 2023 to 2028.

DOUGLAS COUNTY POPULATION ESTIMATES													
Age Group 2023 2028 Change % Change													
Ages 0-2	3,067	3,049	-18	-0.6%									
Ages 3-4	2,104	2,088	-16	-0.8%									
Ages 5-10	6,542	6,498	-44	-0.7%									
Ages 11-13	3,452	3,515	63	1.8%									
Ages 14-18	5,757	5,703	-54	-0.9%									
Ages 5-18	15,751	15,716	-35	-0.2%									
Total Population	111,508	111,993	485	0.4%									
Source: ESRI BIS			•										



Projected Enrollment by Grade


Projected Enrollment - Recommended - District-wide


Grade	2024-25	2025-26	2026-27	2027-28	2028-29	2029-30	2030-31	2031-32	2032-33	2033-34
PK	67	67	67	67	67	67	67	67	67	67
K	399	384	355	313	351	351	351	351	351	351
1	409	417	402	371	327	367	367	367	367	367
2	421	414	423	407	376	331	372	372	372	372
3	418	419	412	421	405	375	330	370	370	370
4	426	416	416	410	419	403	372	328	368	368
5	435	427	417	417	411	420	404	373	329	368
6	433	437	429	418	419	413	421	405	375	330
7	467	434	438	431	420	420 414		423	407	376
8	412	462	429	433	425	415	415	409	418	402
9	367	409	459	426	430	422	412	412	406	415
10	423	356	397	445	413	417	409	399	400	394
11	429	399	336	374	419	389	393	386	376	377
12	442	436	405	341	380	426	395	399	392	382
Undefined	73	73	73	73	73	73	73	73	73	73
K - 12 Total	5,481	5,410	5,318	5,207	5,195	5,149	5,055	4,994	4,931	4,872
Grand Total	5,621	5,550	5,458	5,347	5,335	5,289	5,195	5,134	5,071	5,012

Source: Enrollment Report Woolpert, Inc., 2024.



Enrollment Trends








Other Enrollment Considerations

Transfers In/Out


	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24*
Transfer In	161	211	206	169	239	273	124	117	124	136
Transfer Out	192	212	247	234	238	308	244	283	301	302
+/- Students	-31	-1	-41	-65	1	-35	-120	-166	-177	-166

Source: Roseburg Public Schools


^{*} Most recent report pulled, January 31, 2024



Source: Enrollment Report Woolpert, Inc., 2024



Other Enrollment Factors / Considerations



It is projected the enrollment levels for the District are projected to decline over the next several years.


According to the City of Roseburg's Community Development Department, they permit about 30 new single-family homes per year. There is also a development for 22 duplexes that is under review pending the submittal of a plat map, although they are not sure if the project is moving forward.

Indomitus Heights is located in the Hucrest neighborhood, a final plat has yet to be submitted. Additional information may be found on the city of Roseburg's <u>Urban Growth</u> Boundary (UGB) Swap Project website.



Facilities Overview/District Portfolio

Portfolio: Return on Investment



Facility components (roofs, HVAC, MEP systems, finishes, etc.) have their own different lifecycles and need renovated or replaced at fairly predictable intervals. Carpet, for example, typically needs replaced before roofing systems. Performing these life cycle replacements can prolong the useful life of the facility as a whole; the inverse is also true.

Credit: HBA Architects



Portfolio: Facilities Condition Index

FACILITY CONDITION INDEX (FCI)

The Facility Condition Index (FCI) is an industry-standard metric that objectively measures the current condition of a facility, allowing comparison both within and among assets.

To determine FCI for any given set of assets, the total cost of remedying requirements is divided by the current replacement value. Generally, the higher the FCI, the poorer the condition of the facility.

Total \$\$ Cost of Deficiencies

DIVIDED BY

<u>Cost of \$\$ Current Replacement:</u>

FCI: __%

GOOD 0% - 40%

- Majority of systems still in good shape
- Good investment to extend the life of the building
- Good Return on Investment

FAIR 40% - 60%

- Major systems beginning to fail / beyond their useful life
- Large investments should be evaluated to determine if life of facility can be extended

POOR 60% - 100%

- Most systems are failing / beyond their useful life
- Investments in the facility may exceed the replacement cost and may only extend the life of the facility for a short time
- Typically not a good ROI



Roseburg District-wide

District-wide Portfolio

				Buildin	g Information						Capacity, E				
School	Grade	Orignal Build	Age	Sq. Ft	Deficiencies 2022	ficiencies w/ est escalation 2024	Replacement C	ost	eplacement Costs 2024	FCI with Escal (2024)	Capacity (2019)	2013-14 Enrollment	2023-24 enrollment	Chg in Enrol	Util 23-24
Eastwood ES	K-5	1957	67	38,000	\$ 2,184,452	\$ 2,589,886	\$ 19,429,0	20	\$ 23,035,042	11.2%	502	451	384	-14.86%	76%
Fir Grove ES	K-5	1960	64	30,690	\$ 1,813,627	\$ 2,150,236	\$ 15,691,4	90	\$ 18,603,827	11.6%	342	290	262	-9.66%	77%
Fullerton ES	K-5	1961	63	44,811	\$ 2,939,918	\$ 3,485,567	\$ 22,911,4	L6	\$ 27,163,770	12.8%	502	329	340	3.34%	68%
Green ES	K-5	1949	75	33,993	\$ 1,957,643	\$ 2,320,981	\$ 17,380,2	31	\$ 20,606,057	11.3%	502	309	251	-18.77%	50%
Hucrest ES	K-5	1955	69	46,790	\$ 1,433,393	\$ 1,699,430	\$ 23,923,2	59	\$ 28,363,410	6.0%	479	413	405	-1.94%	85%
Melrose ES	K-5	1948	76	32,500	\$ 1,773,700	\$ 2,102,898	\$ 16,616,9	25	\$ 19,701,022	10.7%	410	289	335	15.92%	82%
Sunnyslope ES	K-5	1965	59	46,970	\$ 1,340,820	\$ 1,589,676	\$ 24,015,2	91	\$ 28,472,524	5.6%	410	282	252	-10.64%	61%
Winchester ES	K-5	1940	84	43,454	\$ 1,699,480	\$ 2,014,903	\$ 22,217,5	96	\$ 26,341,176	7.6%	570	350	309	-11.71%	54%
John C Fremont MS	6-8	1951	73	102,736	\$ 5,610,380	\$ 6,651,665	\$ 54,952,2	54	\$ 65,151,379	10.2%	692	668	650	-2.69%	94%
Joseph Lane MS	6-8	1954	70	98,504	\$ 5,023,242	\$ 5,955,554	\$ 52,688,6	08	\$ 62,467,601	9.5%	748	664	566	-14.76%	76%
Rose School				32,750	\$ 3,122,811	\$ 3,702,404	\$ 19,320,8	53	\$ 22,906,810	16.2%					
Roseburg HS	9-12	1964	60	292,347	\$ 14,549,961	\$ 17,250,430	\$ 172,470,1	L3	\$ 204,480,525	8.4%	2000	1772	1665	-6.04%	83%
		1955	69	843,545	\$ 43,449,427	\$ 51,513,630	\$ 461,617,1	L5	\$ 547,293,143	9.4%	7,157	5,817	5,419	-6.84%	76%



Roseburg by Grade Configuration

Elementary Schools

	Building Information Ca								Capacity, Enrollment & Utilization						
School	Grade	Orignal Build	Age	Sq. Ft ▼	Deficiencies 2022		ficiencies w/ st escalation 2024	Replacement Cost 2022	Replacement Costs 2024	FCI with Escal (2024)	Capacity	2013-14 Enrollment	2023-24 enrollment	Chg in Enrol	Util 23-24
Eastwood ES	K-5	1957	67	38,000	\$ 2,184,452	\$	2,589,886	\$ 19,429,020	\$ 23,035,042	11.2%	502	451	384	-14.86%	76%
Fir Grove ES	K-5	1960	64	30,690	\$ 1,813,627	\$	2,150,236	\$ 15,691,490	\$ 18,603,827	11.6%	342	290	262	-9.66%	77%
Fullerton ES	K-5	1961	63	44,811	\$ 2,939,918	\$	3,485,567	\$ 22,911,416	\$ 27,163,770	12.8%	502	329	340	3.34%	68%
Green ES	K-5	1949	75	33,993	\$ 1,957,643	\$	2,320,981	\$ 17,380,281	\$ 20,606,057	11.3%	502	309	251	-18.77%	50%
Hucrest ES	K-5	1955	69	46,790	\$ 1,433,393	\$	1,699,430	\$ 23,923,259	\$ 28,363,410	6.0%	479	413	405	-1.94%	85%
Melrose ES	K-5	1948	76	32,500	\$ 1,773,700	\$	2,102,898	\$ 16,616,925	\$ 19,701,022	10.7%	410	289	335	15.92%	82%
Sunnyslope ES	K-5	1965	59	46,970	\$ 1,340,820	\$	1,589,676	\$ 24,015,291	\$ 28,472,524	5.6%	410	282	252	-10.64%	61%
Winchester ES	K-5	1940	84	43,454	\$ 1,699,480	\$	2,014,903	\$ 22,217,596	\$ 26,341,176	7.6%	570	350	309	-11.71%	54%
		1954	70	317,208	\$ 15,143,033	\$	17,953,576	\$ 162,185,278	\$ 192,286,828	9.3%	3,717	2,713	2,538	-6.45%	68%



Roseburg by Grade Configuration


Secondary Schools

	Building Information Cap									Capacity, E	Capacity, Enrollment & Utilization					
School	Grade	Orignal Build	Age	Sq. Ft	Deficiencies 2022		eficiencies w/ ost escalation 2024	Replacement Cost		Replacement Costs 2024	FCI with Escal (2024)	Capacity	2013-14 Enrollment	2023-24 enrollment	Chg in Enrol	Util 23-24
John C Fremont MS	6-8	1951	73	102,736	\$ 5,610,380	\$	6,651,665	\$ 54,952,254	\$	65,151,379	10.2%	692	668	650	-2.69%	94%
Joseph Lane MS	6-8	1954	70	98,504	\$ 5,023,242	\$	5,955,554	\$ 52,688,608	\$	62,467,601	9.5%	748	664	566	-14.76%	76%
Roseburg HS	9-12	1964	60	292,347	\$ 14,549,961	\$	17,250,430	\$ 172,470,113	\$	204,480,525	8.4%	2000	1772	1665	-6.04%	83%
		1956	68	493,587	\$ 25,183,583	\$	29,857,650	\$ 280,110,974	\$	332,099,505	9.0%	3,440	3,104	2,881	-7.18%	84%



District-Wide Portfolio

11 Schools Across the District



Excludes alternative learning spaces and PreK.



Investment Considerations

ELEMENTARY – MIDDLE – HIGH SCHOOL

Opportunity: Align Investment with Strategic Plan

Consider Previous Investments Priorities? How to reinvest in students and staff?



- New generators at 11 schools
- Controlled Access systems, district wide. Fencing around perimeters athletics/ secondary
- Fire alarm detection and notification system upgrade district-wide
- Drop-off safety at elementary schools (hug and go safety)



Facilities

- Old Main rebuild at Roseburg HS, connection of history with present day
- Asbestos removal, district wide and enhancements to building due to abatement
- Roofing (warm, safe and dry)



- Educational and facility updates at all elementary and middle schools
- Career and technical education/vocational educational resources
- New multipurpose facilities at five elementary schools

Opportunity: Align Investment with Strategic Plan

Consider Previous Investments Priorities? How to reinvest in students and staff?



Air quality upgrade and install heating/cooling/air exchange systems



Fixtures

- Electrical: panel upgrades district-wide, additional classroom circuits and outlets district wide and upgrade facility electrical service
- Plumbing: pipe, fixtures replacements district-wide



- Replacements for athletic, PE and community spaces including school tracks and new synthetic turf fields at middle schools
- Elementary school playground updates and replacements

Discussion

Facilities Master Planning

Facilities Master Plan: A strategic plan for directing major capital decisions, usually over a 5 to 10-year horizon.

- Population growth/decline
- Building conditions
- Program supports
- Address capacity

New Construction / Rebuilding our Schools



- Systems (roof, HVACS, etc.,)
- Replacement of facilities
- Safety and security

Major Renovations



- Career and Technical Education (CTE) – Industry Certifications
- Advanced Manufacturing,
 Advanced Healthcare
 w/growth opportunities UCC
- Special Education
- Other**

Program Investments



- Efficient use of spaces
- Do we have the right number of schools, at the right sizes, in the right locations, with the right learning environments to sustainably serve all students?

Efficiency & Efficacy



**Continue to build business relationships for apprenticeships and mentorships.



Group Discussion

This is also the line of inquiry we will have with the community in the fall.

What surprised you about the data that was presented to you today?

What data are we missing?

What additional information would you like to have related to campus needs?

Are there other issues related to facilities and programs that we need to incorporate in capital planning for the district?



How to Re-invest in Schools?

What issues do we need to discuss before we consider investments in student and teacher spaces?


With finite resources, what other investments in students and the portfolio do we need to consider and/or prioritize?

What constraints do we need to address?



How to Re-invest in Schools?

Other Questions?







Roseburg Public Schools

Survey Overview / Results
Long-range Facilities Plan

November 6, 2024





1 Survey Overview

Agenda

- 2 Questions Priorities with open-ended responses
 - 3 Demographics

Survey Overview

Community engagement is a critical component of the Longrange Facilities Master Plan. It affords the community to bring voice to their priorities for investments in school facilities and sites.

To provide context to the survey, the district provided an information sheet that depicted the investments made in district facilities over the past several years.

Roseburg Public Schools released the survey to the community on October 22, 2024. It was available through November 2, 2024. The district also held video conference calls on October 24th and October 25th. The district also held an in-person meeting on November 1, 2024.

The survey had 533 respondents. The results of the survey and related open responses are included in this document.

🎗 Capital Improvement Investments

Since Roseburg Public Schools completed its last Long-Range Facilities Plan in the 2019-20 school year, the district has taken steps to address some of our most critical building and infrastructure needs. Following is a summary of top projects completed over the past five years, along with an accounting of funding sources and allocations.

Safety and Security Investments

- Security entrances/vestibules at 11 schools.
- Full perimeter fencing at all elementary schools; partial fencing at secondary schools.
- Raptor visitor management system implemented at all schools.
- Seismic upgrades to gyms/multipurpose rooms at Fremont and Joseph Lane middle schools and Eastwood and Winchester elementary schools since 2020, with additional upgrades to nearby facilities.

Infrastructure Investments

- · New softball facility at Roseburg High School.
- · New bathroom facilities at Hucrest Elementary.
- · Some HVAC upgrades, including in the Melrose gym.
- New wireless controllers installed at each school, along with 400 new Wi-Fi 7 access points.
- · Flooring replacement in classrooms and cafeteria.
- · Cafeteria pocket tables installed at seven schools.
- Hand-washing stations and dishwashers replaced at several schools.





Project Funding

Roseburg Public Schools has invested approximately \$25,350,000 in grant and general fund dollars to complete capital projects aligned with our Strategic Coal focus of creating Safe & Inclusive Environments and ensuring Effective Operations in our district.

ESSER: \$7 million

The district received state and federal approval to use a portion of ESSER grant funding to improve security throughout our schools.

SRGP: \$10.5 million

The district applied for and received funding from the Seismic Rehabilitation Grant Program for seismic upgrades.

NS: \$1.6 million

The district made cafeteria and kitchen updates through the Nutrition Services fund.

GF/MM: \$5.25 million

The district used General Fund and Major Maintenance fund dollars to make efficient upgrades during grant-funded construction projects and to meet Title IX requirements.

Total: \$25,350,000

In the last 10 years, the district has been awarded over \$18 million in seismic grant awards.



The district has been notified of a \$1.252,727 grant award from the Renew America's Schools program.





Snapshot of Priorities



Indoor Air Quality (HVAC) and Asbestos



Security



Facility Upgrades: renovations to support learning to new school options




Site Improvements: playgrounds, playing fields and safety-sidewalks & parking areas, drop-off



Question 1: Please rank/prioritize the facility investments you want Roseburg Public Schools to make within the next two years.

Near Term Investment Priorities





Question 1: Please rank/prioritize the facility investments you want Roseburg Public Schools to make within the next two years.

Near Term Investment Priorities


	1	2	3	4	TOTAL	SCORE
Specialized program upgrades	11.82% 63	20.64% 110	25.89% 138	41.65% 222	533	2.03
Technology infrastructure upgrades district-wide	9.38% 50	31.14% 166	40.71% 217	18.76% 100	533	2.31
Controlled access systems district-wide	23.26% 124	25.52% 136	20.64% 110	30.58% 163	533	2.41
Air quality improvements district-wide	55.53% 296	22.70% 121	12.76% 68	9.01% 48	533	3.25

Indoor air quality had the highest number of respondents placing it first or second as an investment for the district to prioritize over the next two years.



Question 2: Please rank/prioritize the facility site investments you want Roseburg Public Schools to consider within the next three to five years.

Three to Five Year Investment Horizon





Question 2: Please rank/prioritize the facility site investments you want Roseburg Public Schools to consider within the next three to five years.

Three to Five Year Investment Horizon


	1	2	3	TOTAL	SCORE
Career and technical education/vocational education investments at middle schools and high school	51.22% 273	13.13% 70	35.65% 190	533	2.16
Electrical upgrades district-wide	36.59% 195	47.09% 251	16.32% 87	533	2.20
Plumbing upgrades district-wide	12.20% 65	39.77% 212	48.03% 256	533	1.64

In the next three to five years, electrical system upgrades were prioritized by survey respondents, followed by learning space investments.



Question 3: Please select your top **three** priorities for Roseburg Public Schools to consider for investment at five years and beyond.

Investments Five Years +





Question 3: Please select your top **three** priorities for Roseburg Public Schools to consider for investment at five years and beyond.

Investments Five Years +





ANSWER CHOICES	RESPONSES	
Americans with Disabilities Act upgrades district-wide	22.44%	114
Asbestos removal district-wide	42.32%	215
Fire alarm detection and notification system upgrade district-wide	20.67%	105
Generators installed district-wide	21.06%	107
New multi-purpose gymnasiums at five elementary schools	36.22%	184
Rebuild Old Main at Roseburg High School	38.19%	194
Upgrades for outdoor spaces at middle schools	29.72%	151
Roofing upgrades including immediate and long-term projects	23.23%	118
Drop-off safety projects at elementary schools	18.70%	95
Elementary school playground updates and replacements	29.53%	150
Other (please specify)	11.22%	57
TOTAL		1490



Question 3: Please select your top three priorities for Roseburg Public Schools to consider for investment at five years and beyond. [Open-ended Responses]

A/C for all schools

A/C unit or Mini splits in classrooms

AC and smoke filtration systems!!!

AC at middle schools

AC!

Ada parking for all high school sports facilities

Additional parking at Roseburg High School

Additional stalls in girls and boys bathrooms. We only have 2 stalls in each bathroom with 4 classes about 25 students each. We need more stalls.

Air conditioner upgrade

Air conditioning

Air conditioning

Air conditioning

Air conditioning

Air conditioning

Air conditioning

Air conditioning and heat at all school.

Air conditioning and heat in all classrooms

Air conditioning and heating systems for all schools!

Air conditioning and temperature control in the classrooms

Air conditioning for all elementary and middle schools

Air conditioning in ALL classrooms

Air conditioning in all classrooms

Air conditioning in all schools

Air conditioning in classrooms

Air conditioning units

Air conditioning, heating, hvac

Air purification to reduce respiratory infections and wildfire smoke exposure

Other Investments	No.
Bathroom Upgrades	3
Drop-offs	1
ES Playgrounds	2
Electrical Upgrades	1
Field Upgrades	2
HS Locker Upgrades	1
Indoor Air Quality	42
New Schools	1
Parking HS (ADA)	2
Rebuild Old Main	2
Reduce Admin	1
Rose Virtual Upgrade	1
Total	59



Question 3: Please select your top three priorities for Roseburg Public Schools to consider for investment at five years and beyond. Open-ended Responses

Air/heating systems upgrade

Central air and heat in all schools

Central air for the students and teachers

Central heater and air

climate control improvements district wide

DECREASE ADMIN PAYROLL -More money to kids, not oversight!!

DO NOT tear down the old main. Renovate only. Historic buildings should be preserved

drop- off safety projects at middle schools

ductless systems or HVAC upgrades for all classrooms

Heating and cooling

HVAC

HVAC AND AIR QUALITY SHOULD BE A TOP PRIORITY. Students and teachers cannot conduct a productive learning environment with temperatures like they've experienced in the early weeks of school and last few weeks of school each year

HVAC Systems

HVAC Systems for schools

HVAC Systems in all elementary classrooms

Hvac systems. It is to hot in buildings.

Install air conditioning or start cancelling school over 85 degrees

New AC in schools

New high school parking and fields

New schools built to replace old. Fremont is breaking down

Outdoor drinking fountains and additional bathrooms for children at Fullerton Elementary.

PLEASE just rebuild the Old Main.

Proper heating and cooling in all buildings

RHS locker room, classroom outlets and lighting, paint

Rose Virtual School - The layout of the facility is completely very disjointed. Needs completely revamped. Sell off the upper outdoor area and make the other areas more cohesive.

Sink and counter improvements at Green Elementary. Water should not be dripping on students shoes and mold should not be growing in the broken countertops. These needed fixed prior to

Sunnyslope playground equipment

Turf Fields all sites.

Update grass facilities to be used by all youth sports in the community.

Upgrade heating and cooling systems

Other Investments	No.
Bathroom Upgrades	3
Drop-offs	1
ES Playgrounds	2
Electrical Upgrades	1
Field Upgrades	2
HS Locker Upgrades	1
Indoor Air Quality	42
New Schools	1
Parking HS (ADA)	2
Rebuild Old Main	2
Reduce Admin	1
Rose Virtual Upgrade	1
Total	59



3 Super K-6 Schools, One Middle School 7-9 and District office at Current High School Site. 1 New High School at UCC property. Turn Fremont into K-6, JoLane K-6, Build new K-6 School at Sunny Slope or Charter Oaks. Close all other building sites. Cut down from 11 sites to 5 sites. Buildings have outlived life expectancy. All sites turf fields and Gym spaces.

A greenhouse or hoop house to grow food/flowers for the district or farmers market for school fundraising. USDA usually has grants as well.

A proper dental education program

A/C and air purifiers in all buildings is a top priority. Middle school outdoor areas (tracks, courts, etc.) should also be a priority as they'll benefit students and the community as a whole

A/C for all schools

A/c units in all schools

AC for all schools

AC units for ALL schools

Ac/heaters school wide!

Add armed security

Additional turf fields

Aides

Air and heating systems at every school

Air conditioners

Air conditioners in every building

Air Conditioning

Air conditioning and better heating

Air conditioning at all schools

Air conditioning at all schools. If it's too hot neither the teachers or students can focus and learn.

Air conditioning district wide

Air conditioning for all classrooms

air conditioning for classrooms

Air conditioning for classrooms

Air conditioning in all classrooms

Air conditioning in ALL classrooms

Air conditioning in all classrooms

Air conditioning in buildings with none. Testing and follow through to make sure water fountains have no adverse chemicals/metals.

Air conditioning should be a requirement!

Air conditioning should be available for any weather forecasts above 80°

Air conditioning units

Air conditioning!

Air conditioning!!!!!!

AIR CONDITIONING

Improvements/Renovations	Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222



Air conditioning. Better drop off and pickup lines/ areas. Should not have to arrive at a school 1 hour early to be at the front of the line. Drop off/ pickup lines are a nightmare for working parents who have to be multiple places at once.

Air purification to reduce respiratory infections and related absenteeism as well as reducing exposure to wildfire smoke

Air quality and temperature is the most important to me. The working environment we are asked to be in when it's freezing, excessively hot, smoky, and/or moldy are not acceptable for work professionals or just humans in general. Also, the tracks at the middle schools are horrendous and need an upgrade. Turf and rebuilt tracks at the middle schools are very much needed.

Air quality upgrades - heating and cooling systems

All outside doors to be scan in.

All schools need functional heating and cooling

Bathrooms in the elementary schools

Better bullying prevention and protocols

Better Fire Safety routes and security

Better heating/cooling systems for the classrooms.

Bring back JROTC quit forcing politics agendas. Don't adhere to the pronouns making kids choose

Build a new school

Building safety

Camera installation and upgrades

Classroom lockdown door devices or systems in place in an emergency

Classroom, office and meeting space for spec and other high needs populations.

Climate and flood control

Consider building a second High School

Cooling systems in schools that don't have any. Especially for the heat sensitive children and adults

Covered play areas outside at the elementary schools.

Create better food options for school lunches and more healthy clean food options less processed foods

CrisisAlert panic button for schools

Currently i feel like I'm not welcome at my kids school, feels like a prison.

Disability assistance: Time out/calm down sensory sensitive space for kids with disabilities and behavior issues, or for kids to take tests in quiet.

Easier accessibility for kids who get sick often, video chat set up so they can participate from home or the hospital

Eastwood Elementary bathrooms are atrocious, outdoor spaces are outdated and uninviting for students. Heating and cooling should so students and staff aren't missing valuable class time due to unsafe weather. Music and technology programs at the elementary level need updated, and invested in.

Eastwood Walking Bridge

Equality and cracking down on bullying it's getting out of control

Fewer administrators at central office to free up funding for necessary facility needs.

Field/track improvements with proper drainage so the students can actually use the space all year

Fix the parking situation at the high school

Focus on upgrading schools as community emergency shelters.

Following ADA compliance and asbestos abatement should be priorities as the safety of students and staff in the buildings should be a district priority.

Fullerton Elementary has only 1 drinking fountain for the entire school. The school needs additional drinking fountains on the playgrounds so children may get a drink of water during recess. There are also only 2 restrooms (of each gender) in the entire school for over 300 students to share.

further clarify in surveys

Gardens and garden class at all schools

Get rid of portable classrooms

Getting the literacy rate above 58 percent.

Good drinking water, no lead pipes

Gym updates and additions

gyms for elementary schools

Heat and air conditioning for the tough weather we have

Heating and air

Improvements/Renovation	s Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222



Heating and Air Conditioning

heating and air conditioning

Heating and air conditioning

Heating and air conditioning

heating and air conditioning at all school cites

heating and cooling in all classrooms

Heating and cooling systems

Heating and Cooling Systems should be prioritized. It impacts staff productivity and student learning when students are in sweltering hot schools and classrooms.

heating and cooling upgrades

Heating/cooling systems

high school drop off needs revamped

HVAC

HVAC

HVAC

HVAC and climate control in all classrooms

HVAC for schools!

HVAC in elementary schools

HVAC Systems

HVAC Systems in all elementary classrooms

HVAC systems in all parts of all buildings, starting with the middle and high schools.

HVAC systems in all schools, kitchen upgrades to provide scratch cooking

HVAC systems installed district wide

Hvac upgrades at elementary schools

HVAC/AC, ADA, Outdoor Classrooms

I feel like safe routes to schools could be maximized to help with drop off and safety improvements. I sent a proposal to Hucrest to move the pedestrian walkway from being intermingled with the car drop off area and buses to the south side of campus along the fence line that removes pedestrians from the drop off all together. they cleared out the planter and I don't know if they plan to pave that walkway but that would be a great and not too expensive thing to do to drastically improve safety there. The sidewalk repairs and curb cuts along Kline are a great change that happened in the last few years as well.

but that would be a great and not too expensive thing to do to drastically improve safety there. The sidewalk repairs and curb cuts along Kline are a great change that happened in the last few years as well

I know it was mentioned- but new HVAC systems are critical. Our boilers are a safety hazard and constantly breaking down. We are teaching in classrooms full of 30 students at 90+ degrees. It's inhumane. The air quality is terrible and affecting the health of many of my colleagues.

I think making playgrounds equitable at all schools is a main priority!

Improve practice fields for soccer (grass) because Fir Grove is not maintained and too many ankle injuries to count. City does nothing to maintain fields.

Improved security in each classroom to lock themselves in if needed and a fire extinguisher in every classroom

Improvements to RHS's VoTech Building/Facility (roof, electrical, HVAC, windows, etc.)

Improvements/installation of baseball fields at schools.

Improvements/Renovations	Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222



In the almost 25 years I've lived here our Roseburg Junior High schools have looked the same. They are in need of upgrades

Including Rose Campus in all facility upgrades

Increased bullying prevention. Its a major issue

Indoor Middle School Facility Improvements, Maintenance of current buildings so that they can continue to function well

Install and maintain baseball & softball fields in middle schools

Install metal detector at all school entrances

Inviting the community to participate in the curriculum would go a long way in earning support for these upgrades.

It's difficult to know w/o understanding the current condition of the facilities. For example, HVACs are not listed; I assume they must be in good condition. I would support technology upgrades for CTE and science classrooms, and all classrooms for that matter.

It's over 100 degrees in the classrooms in August, September, May and June. Need to make getting this fixed a priority for learning

Just emphasizing the need for AC and good ventilation at all schools- my kids would often come home with head aches after hot or smoky days when they were in middle school.

Keep trying to pass the bond.

Less remodel/upgrades at the admin office. Less employees at admin. Focus on kids, teachers, and teaching instead of parroting.

Locker rooms at Fremont and bathrooms too:)

Make one restroom for individuals who don't know and are still confused on their gender it's not our kids fault they are confused and feel the need to potentially hurt or impose on the opposite sex if school are making this a thing now days then they need their own restrooms keeping in mind that safety for all individuals need to be the top concern

mental health awareness

Metal detectors for entering school. Gun free zone signs don't do anything. Metal detectors do. Let's please use some common sense here. Walking through a Metal detector takes seconds and could save lives. Simple solution

Mold abatement at Fremont

More access to outdoor natural spaces in elementary and middle schools. More trees and natural elements. Let kids be outside for more hands on learning.

More buildings for more classes.

More gym space

More help for the kids

More parking at the high school for students

More programs that involve language and culture.

More rainy day/ smokey day recess type areas at the elementary school. Cooling systems in gym spaces.

More space for behavior and sensory support

More specialized teachers in SPED

More specialized trainings for teachers for Tag students

more storage options at Melrose

More turf fields

My teacher just delivers my food. They working 2 jobs. Maybe pay for them

need a new high school

New and/or improved HVAC in all buildings.

New blinds on windows and doors for safety

Improvements/Renovations	Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222



New heating and cooling systems for the schools. This is especially important for the Health and Well-being of staff and students to be able to learn. Our climate is changing and heating and cooling are more important than ever, now. Also, more custodians to help clean and sanitize, so we do not have Norovirus outbreaks. Years ago, the custodians took PRIDE in their schools and swept and mopped building, daily. They cleaned tables and desks. Bathrooms were cleaned and they made sure that you would not run out of toilet paper, paper towels, and soap. Now, you are lucky if your trash is taken out and a sweep with the dust mop. No tables or desks are cleaned unless teachers have cleaner and do it themselves. Staff and student bathrooms continually run out of soap, toilet paper and paper towels. Bathrooms are not mopped and stalls wiped down for days or months. Areas where mold is visible, just get covered up and not taken care of, so it becomes a health hazard for sensitive groups. All of these leads to more sickness because of all the bacteria, mold, and viruses that are not being taken care of. Unfortunately, this leads to more sickness in staff and students, which leads to more absences.

New middle school; new ekementary schools

New schools to replace old

No, but to add asbestos removal and ADA upgrades to the list of wants not needs is crazy. Those should be budgeted then other projects planned AFTER that is done.

Parenting programs

Parking for all students with licenses at the High School to no exclusion

Please focus on the elementary schools who have the least neighborhood tax funding that have not received equitable conditions in comparison to other elementary schools.

Please give priority to elementary!! Some playgrounds are so outdated and unsafe.

Potential add on buildings for schools with limited space; like Eastwood elementary

Preschools at each elementary school site

Proper heating and cooling in all buildings

properly functioning heat and ac

Purchase or lease vacant lot to create adequate student parking at RHS.

Put fencing and a vestibule at RVS.

Rebuild the Teepee at Roseburg high

Renovate and construct with a strong emphasis on passive heating/cooling as well as making awesome human-scale places.

Renovate or replace Fullerton IV Elementary

Repainting classrooms

RHS Campus

RHS campus needs major updates in buildings to avoid the same outcome as the heritage. Technology, electrical, pest control etc.

Roofing and structure is needed too

Safe routes for the high school - where crosswalks are actually safe

Safety improvement for drop off and pickup at jolane middle school. My suggestion, use the lower field next to the track to expand the parking lot and pickup drop off lanes. Anyone that has ever been to that school during afternoon pickup knows it's a tragic accident waiting to happen.

SAFETY MEASURES

Safety upgrades

Seasonal sports for Sunnyslope elementary. More field trips for Sunnyslope elementary. More volunteer opportunities for parents of sunnyslopers.

Separate gymnasium and cafeterias

Separating out grades more in high school. Jr. High 8-9

Improvements/Renovations	Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222



Shade should be a major priority at all the schools. When I saw the high school common area outside, I was surprised to see little to no trees or shade areas. Many school playgrounds have inadequate shade to protect children from the sun or sprinkles from rain. I'd love to see this considered and playgrounds opened up again for use in the summer. In my experience the space in the elementary schools is not adequate to host school events for parents to attend. There never seems to be nearly enough seating to accommodate the families that show. Either the use of the community center in Winston, or major upgrades to the existing space, should be implemented.

Solar panels and air conditioning

Specific Gifted & Talented Class and designated advanced classes in middle school

Sped programs available at hike schools. Behavior support at all schools.

Sports for elementary school

Sunnyslope playground equipment

Teachers, not admin, not people at the district office need updated equipment. They should have the newest tech. If it is really about kids, then Teachers is where we need to invest.

Tech/Chromebook updates

Temperature control ability

The athletic fields at the middle schools are not only embarrassing but the are dangerous.

Therapeutic programs and better programs for Students Services so those students can be properly placed

There is so much money seemingly being misspent by the RPS. All of our schools should be renovated and brought up-to-date. You hold citizens hostage with bond measures, but let's get real, that's not the only money available for restoring our school buildings.

This survey doesn't really have a lot of context, so I'm not sure how valid the responses will be.

To rebuild old main at rhs please

Turf facilities for sports and activities at all schools,

Turf fields at as many locations as possible

Turf fields at middle schools for multi uses

Update air conditioning for schools that don't have any

Updates to elementary and middle schools. RHS is the flagship but the rest of the fleet is sinking

Updating the look of many elementary schools and landscaping. Man windows need replacement.

Upgraded and additional security camera systems

Upgrading buildings to have ac

Virtual education is an area that appeals to homeschoolers. It could be a real competitor with other on-line programs.

Water filtration systems. Get those toxins out of our kids' water supplies.

ways to self defense for real lockdowns

We need turf fields with tracks at the Middle Schools

What about grants for Solar to off set our electrical costs?


Work on a deal with the city to make turf fields at fir grove so we can take advantage of that space with our school sports and host tournaments.

Improvements/Renovations	Number
ADA	3
Asbestos	2
Address Bullying	3
Community	5
Facility Upgrades	32
Fire / Safety	15
IAQ	83
New School(s)	8
Programs	14
Site Upgrades	31
Staff	5
Student Supports	16
System Upgrades	5
Total	222

Improvements/Penevetiens



Question 5: Please indicate your affiliation to the Roseburg Public School District. (Check all that apply)





Question 5: Please indicate your affiliation to the Roseburg Public School District. (Check all that apply)

ANSWER CHOICES	RESPONSES	
Parent/guardian of student	62.85%	318
Student	2.37%	12
Alumni	20.16%	102
Parent /guardian of former student	17.79%	90
Grandparent of current or former student	4.94%	25
Roseburg Public Schools' teacher or staff member	34.58%	175
Community member who resides Roseburg Public Schools boundaries	29.25%	148
Other (please specify)	4.15%	21
TOTAL		891

Other Touch-points

Former employee

Former RSD teacher who worked in all three secondary schools.

Former staff member

Local business owner

Married to a staff member

Parent of future students

Past employee

Previous staff

Previous staff & grandparent

Previous staff member

Previous student through 10th grade

Prior Employee

Retired employee


Retired teacher. Hence my knowledge is thrown out.

Substitute employee

Worked for the school district and own 6 properties located in the Roseburg public school district.



Question 6: How many years have you lived in the District?






Question 6: How many years have you lived in the District?

ANSWER CHOICES	RESPONSES	
0-5	16.67%	84
6-10	15.67%	79
11-15	13.29%	67
16 or more	54.37%	274
TOTAL		504

Over 54% of survey respondents have lived in the district sixteen years or longer. There is an acknowledgement about the needs of the district.



Question 7: Your Age





Question 7: Your Age

ANSWER CHOICES	RESPONSES	
Under 18	1.99%	10
18-24	3.19%	16
25-34	17.13%	86
35-44	41.04%	206
45-54	21.71%	109
55-64	9.16%	46
65+	5.78%	29
Choose not to respond	0.00%	0
TOTAL		502





Roseburg Public Schools

Assessments





 District Name:
 Douglas County SD 4

 Site Name:
 Eastwood ES

 Building Name:
 Main

19912692092

Building ID:

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

			Г			LEVEL OF ACTIO	NI .		1		
						LEVEL OF ACTIO	N I I				
								Replace as	% of		
			% of Building					part of	System or	Automated Budget	
Level 1 Leve		Type (as applicable)	or Number	None	Minor	Moderate	Major	Renovation	Finish	Estimate	Notes
A SUBSTRUC											
<u>A10</u>	Foundations			_			_				Library has a crawlspace, modular 6-plex classroom
	A1010 Standard Foundations		20%	x None	Minor	Moderate	Major	Replace		\$0	has wood foundation
	A1020 Special Foundations		2070	x None	Minor	Moderate	Major	Replace	1	\$0	
							 				Slab by music room/community room has shifted
											and sunk down - the cafeteria floor also has an issue
											with a long crack down the middle of the floor.
											Further investigation is needed.
											Main portion of the building is starting to sag / sink. District has completed slab jacking but issues
	A1030 Slab on Grade		80%	None	Minor	Moderate	x Major	Replace	10%	\$90,002	continue to occur.
A20	Basement Construction		5070	None	IVIIIIOI	Wioderate	X IVIUJOI	перисе	1070	\$30,00Z	
7.20	A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace			
	A2020 Basement Walls			o None	Minor	Moderate	Major	Replace		\$0	
B SHELL											
B10	<u>Superstructure</u>							_			
	2424251 2		2001			1				40	Library has a crawlspace, modular 6-plex classroom
	B1010 Floor Construction	Wood	20%	x None o None	Minor Minor	Moderate Moderate	Major	Replace	-	\$0 \$0	has wood flooring - no observed issues
		Steel Concrete	80%	x None	Minor	Moderate	Major Major	Replace Replace	-	\$0	No observed issues
	B1020 Roof Construction	Wood	100%	x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	B1020 NOOT CONSTRUCTION	Steel	100%	o None	Minor	Moderate	Major	Replace		\$0	
		Concrete		o None	Minor	Moderate	Major	Replace		\$0	
B20	Exterior Enclosure		_			_					
	B2010 Exterior Walls	Concrete Formed / Tilt	16%	x None	Minor	Moderate	Major	Replace		\$0	
		Masonry	30%	None	Minor	x Moderate	Major	Replace	6%	\$2,484	Minor paint needed on building C
	Previously Framed w/Panel Siding	Framed w/ Wood Siding	54%	None	Minor	Moderate	x Major	Replace	2%	\$2,668	Minor patch and paint needed on building D
New	New this year	Framed w/Metal Panel Framed w/Stucco	-	None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	
		Framed w/Masonry Veneer	H + +	None	Minor	Moderate	Major	Replace		\$0	
		Trained w/ wasoning veneer	1	- None	IVIIIIOI	Wioderate	Iviajoi	перисе		70	95 single pane wood windows were counted that
	B2020 Exterior Windows	Wood	24%	None	Minor	Moderate	x Major	Replace	100%	\$49,110	need to be replaced
											22 of the 294 aluminum/metal double pane
		Aluminum/Steel	76%	None	Minor	x Moderate	Major	Replace	7%	\$6,075	windows were fogged or damaged.
		Clad		None	Minor	Moderate	Major	Replace		\$0	
		Curtain Wall	1	None	Minor	Moderate	Major	Replace	-	\$0	
	B2030 Exterior Doors	Wood	2	x None	Minor	Moderate	Major	Replace		\$0	All exterior wood doors were in good working order
	DEGGG EXCENSI BOOKS		-	X III		- moderate		Періосе		, , ,	The state of the s
		Hollow Metal	31	x None	Minor	Moderate	Major	Replace		\$0	All exterior metal doors were in good working order
		Storefront		None	Minor	Moderate	Major	Replace		\$0	
B30	Roofing			_	_	_	_	_			
											Covered walkways have major ponding and need to
											be replaced. Roofs on buildings A,B,D,E,H are worn and cracking Percentage adjusted to reflect more
	B3010 Roof Coverings	Asphalt Shingle	100%	None	Minor	Moderate	Major	x Replace	61%	\$388,450	accurate costs
		Built-Up	100/0	None	Minor	Moderate	Major	Replace	02/0	\$0	
		Single Ply		None	Minor	Moderate	Major	Replace	1	\$0	
		Metal		None	Minor	Moderate	Major	Replace		\$0	
		Concrete Tile		None	Minor	Moderate	Major	Replace		\$0	
	B3020 Roof Openings	Skylights		None	Minor	Moderate	Major	Replace		\$0	By Building GSF
		Access Hatch		None	Minor	Moderate	Major	Replace		\$0	Per hatch

INTERIORS									
C10 Interior Construction									
C1010 Partitions	Framed	47% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Masonry	53% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
C1020 Interior Doors	Wood	39 x None	Minor	Moderate	Major	Replace		\$0	All interior wood doors were in good working orde
	Hollow Metal	21 x None	Minor	Moderate	Major	Replace		\$0	All interior metal doors were in good working orde
C1030 Fittings	NOT USED	None	Minor	Moderate	Major	Replace			
C20 Stairs									
C2010 Stair Construction	Wood	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Metal	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Concrete	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C2020 Stair Finishes	Concrete Fill	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Resilient	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Interior Finishes									
C3010 Wall Finishes	Paint on Masonry	53% None	x Minor	Moderate	Major	Replace	4%	\$2,031	Minor touch up paint needed in a few areas
	Wallboard	45% None	Minor	x Moderate	Major	Replace	8%	\$3,768	Minor patch and paint needed throughout
	Wainscot	1% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Ceramic Tile	1% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
C3020 Floor Finishes	Carpet / Soft Surface	16% None	Minor	Moderate	Major	x Replace	12%	\$5,581	Carpet is worn in music and community room
	Resilient Tile	75% None	x Minor	Moderate	Major	Replace	5%	\$1,597	Sporadic cracked tiles throughout
									Kitchen has damaged resilient sheet flooring that needs to be replaced. Entire floor would need to l replaced. Cost adjusted up to accurately reflect
	Resilient Sheet	3% None	Minor	Moderate	Major	x Replace	100%	\$13,246	estimated cost
	Polished Concrete	2% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Ceramic Tile	4% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Liquid Applied	1% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Wood Sports Floor	None	Minor	Moderate	Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	20% None	Minor	Moderate	Major	x Replace	1%	\$1,019	Water infiltration in workroom
	Lay-In Ceiling Tile	57% None	x Minor	Moderate	Major	Replace	5%	\$1,210	Stained tiles in multiple areas
	Glued-Up Ceiling Tile	24% None	x Minor	Moderate	Major	Replace	5%	\$331	Damaged / Stained tiles in multiple areas
	Painted Structure	None	Minor	Moderate	Major	Replace		\$0	
SERVICES									
D10 Conveying		None		DA - da - da		Danie.		ćo	
D1010 Elevators & Lifts D1020 Escalators & Moving Walks		None None	Minor Minor	Moderate Moderate	Major Major	Replace	\vdash	\$0 \$0	
D1020 Escalators & Moving Walks D1090 Other Conveying Systems		None	Minor	Moderate	Major	Replace Replace	\vdash	\$0 \$0	
D20 Plumbing		None	WIIIOI	Moderate	iviajui	Replace		ŞÜ	
D20 Fidinbing							$\overline{}$		All (N) fixtures must meet ADA requirements by
D2010 Plumbing Fixtures		100% None	Minor	x Moderate	Major	Replace	2%	\$1,189	code. 1 of 108 fixtures was non-functional
D2020 Domestic Water Distribution		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D2030 Sanitary Waste		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D2040 Rain Water Drainage		None	Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D30 HVAC									
D3010 Energy Supply		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D3020 Heat Generating Systems	Boiler	None	Minor	Moderate	Major	Replace		\$0	
	Air Handler	60% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
									MFIA Engineering priority 1 recommendation
									(2022) - Replace heating system in the original
									portion of the school. The new system will provide
									heat, ventilation, and filtration per OMSC and
						1 1			ASHRAE code and standards noted previously.
						1 1			Furnaces needed for 1957 classrooms and
	Forman	1000/		1	l I		4000/	£452.052	administration spaces. Cost escalated based on
	Furnace	100% x None	Minor	Moderate	Major	x Replace	100%	\$180,852	MFIA Engineering recommendation.
D2020 Cooling Conserting Systems	Heat Exchanger	40% x None	Minor	Moderate	Major	Replace	\vdash	\$0	No observed issues 6 plex has AC as do modulars
D3030 Cooling Generating Systems	Component of air handler Stand alone chiller	100% x None None	Minor Minor	Moderate	Major	Replace	\vdash	\$0 \$0	o piex rids AC as do modulais
			iviinor	Moderate	Major	Replace		SU	
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues

Discontinues Disc										original install - starting do deteriorate - hydronic
Abbreviolation Abbr			Hot water return & cupply	100% None	Minor	Madarata	y Poplace	100%	¢262 027	
Mode		D20E0 Torminal & Backago Units						100%		System beyond its useral me
Description		D3030 Terrifical & Package Offics	_							
Display Disp										
1995 1995			In-room radiant unit	None	Minor	Moderate	Replace		\$0	
Moderate										
Month Mont		D3060 Controls & Instrumentation			Minor					
Moderate		D3070 Systems Testing & Balancing		100% None	Minor	Moderate	x Replace	100%	\$61,982	Almost all zones need rebalancing
Part Cognotives		D3090 Other HVAC Systems & Equipment	NOT USED	None	Minor	Moderate Major	Replace			
March Moderate March Mod	D40 Fi	ire Protection								
Mode		D4010 Sprinklers		None	Minor	Moderate Major	Replace		\$0	
Moderate		D4020 Standpipes		None	Minor	Moderate Major	Replace		\$0	
Description Moderate									\$0	
Part			NOT LISED						γo	
March Marc	DE0 E		NOT USED	None	IVIIIIOI	ivioderate	Replace			
Description	D50 E						—		4	Outdated manufactures and a
Page										
Cock Intercon System 100K None Minor Moderate Major Major Moderate Major Moderate Major Moderate Major Major Moderate Major Moderat					Minor	Moderate x Major	Replace	1%		
Closed Cruck Surveillance		D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
Access Control System 1			Clock / Intercom System	100% None	Minor	Moderate Major	x Replace	100%	\$42,454	Major systematic issues throughout
Intrusion Amain's System Pack Amm / Decked to 120% X None			Closed Circuit Surveillance	100% None	Minor	Moderate Major	x Replace	100%	\$52,218	Closed Circuit Surveillance needed at this school
Intrusion Amain's System Pack Amm / Decked to 120% X None			Access Control System	o None	Minor	Moderate Major	Replace		\$0	
Fire Alarm / Decection 100% None 20% 1 None 20%										Offices and computer labs, no observed issues
Lighting Control System 20% 2 None N			•					100%		
E Coursett								100%		1 7 7 1 1 1 1
Food Service Food Service Food Service Food Service Vocational O. None Minor Moderate Major Moderate Major Replace 50 No observed issues		procedul florida							\$U	NO observed issues
E102 Description Food Service 100% x None Vocational 0 None Vocational Vocational Najor Najo		D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Replace			
E102 Description Food Service 100% x None Vocational 0 None Vocational Vocational Najor Najo										
Fig.										
Flo20 Institutional Equipment	E10 E									
E1020 Institutional Equipment Science O None Art O None O None Art		E1010 Commercial Equipment								No observed issues
Art Stage Performance Restroom Accessories/Stalls NOT USED None Restroom Accessories/Stalls None Restroom Accessories/Stalls Not USED None Restroom Accessories/Stalls None Restroom Accessories/Stalls Not USED None Restroom Accessories/Stalls None Restroom Accessories/Stalls None Restroom Accessories/Stalls None Not USED None Restroom Accessories/Stalls None Not USED None Restroom Accessories/Stalls None None None None None None None None			Vocational							
Stage Performance Restroom Accessories/Stalls 100% None Minor Mino		E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	
Restroom Accessories/Stalls NOT USED None Replace E1090 Other Equipment NOT USED None None NOT USED None None None E1090 Other Equipment NOT USED None None None None None None None E1090 Other Equipment NOT USED None None None None None None None None			Art	o None	Minor	Moderate Major	Replace		\$0	
Restroom Accessories/Stalls NOT USED None Replace E1090 Other Equipment NOT USED None None NOT USED None None None E1090 Other Equipment NOT USED None None None None None None None E1090 Other Equipment NOT USED None None None None None None None None			Stage Performance	o None	Minor	Moderate Major	Replace		\$0	
E1039 Other Equipment E1039 Other Equipment E201 Fixed Furnishings E201 Movable Furnishings E201 Fixed Furnishings E202 Fixed Construction & Detail Fixed Furnishings E202 Fixed Construction & Detail Fixed Furnishings E202 Fixed Furnishings E203 Fixed Furnishings E203 Fixed Furnishings E203 Fixed Furnishings E203 Fixed Furnishings E204 Fixed Furnishings E204 Fixed Furnishings E204 Fixed Furnishings E205 Fixed Furnishings E206 Fixed Furnishings E207 Fixed Furnishings E207 Fixed Furnishings E208 Fixed F								10%	\$5,392	Restrooms are not ADA compliant in building C
E109 Other Equipment NOT USED None Minor Moderate Major Replace E2010 Fixed Furnishings E2010 Movable Furnishing E2010 Movable Furnishings E2010 Movable Furnishing E2010 Movable Furnishi		E1030 Vehicular Equipment		None	Minor				. ,	
E20 Furnishings										
E2010 Fixed Furnishings	F20 F1					major	перисс			
E2020 Movable Furnishings F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED G BUILDING SITE WORK G10 Site Preparation NOT USED G20 Site Improvements G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2020 Parking Lots G2030 Facter from Provements G2030 Facter from Provements G2030 Facter from Provements G2030 Site Understand Provements Minor Moderate Major Moderate Major Moderate Major Moderate Major Replace Z5% S22,562 Roadways had some areas that were alligatoring Moderate Major Moderate Major Moderate Major Replace Z5% S22,562 Major Replace Z5% S13,2355 Damaged walkways identified over entire site Major Replace Z5% S22,562 Major Replace Z5% S22,562 Major Replace Z5% S22,562 Major Replace Z5% S13,241 Minor cracking observed issues Major Replace Z5% S22,562 Major Replace Z5% S22,562 Major Replace Z5% S13,2355 Major Replace Z5% S13,2351 And requiries replacement. A portion of the line has lost its structural integrity Moderate Major Modera	<u> </u>			100% v Nono	Minor	Madarata Majar	Poplace		ćn	
G BUILDING SITE WORK G10 Site Preparation NOT USED		<u> </u>								
GBUILDING SITE WORK G10 Site Preparation NOT USED G20 Site Improvements G20 Replace G2010 Readways G2020 Parking Lots G2020 Parking Lots G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2040 Site Development G2040 Site Development G2040 Site Development G2050 Site Mechanical Utilities NEW LF G3010 Water Supply New LF G3020 Sanitary Sewer G303 Site Mechanical Supply Domestic Fire G300 None Minor M		-		100% X None	IVIInor	Major	керіасе		\$0	
G10 Site Preparation G20 Site Improvements G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2020 Parking Lots G2030 Roadways G2040 Site Development G2040 Site Development G2040 Site Development G2040 Site Development G2050 Landscaping G2050 Landscaping G30 Site Mechanical Utilities New LF G3010 Water Supply Domestic Fire G3010 None Minor Moderate Minor Moderate Minor Minor Moderate Min	F SPECIAL COI	NSTRUCTION & DEMOLITION - NOT USED								
G10 Site Preparation G20 Site Improvements G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2020 Parking Lots G2030 Roadways G2040 Site Development G2040 Site Development G2040 Site Development G2040 Site Development G2050 Landscaping G2050 Landscaping G30 Site Mechanical Utilities New LF G3010 Water Supply Domestic Fire G3010 None Minor Moderate Minor Moderate Minor Minor Moderate Min	C DI III DING GI	FF MORK								
G20 Site Improvements G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2040 Site Development G2040 Site Development G2050 Landscaping G2050 Site Mechanical Utilities New LF G3010 Water Supply Domestic Fire None Minor Moderate Minor Moderate Minor Moderate Minor Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Replace S0 None Minor Moderate Major Replace S0 Entire site is irrigated - no observed issues Fire None Minor Moderate Major Replace S0 Enter Lef of pipe in cell E144 A portion of the line has lost its structural integrity Moderate Major Replace S0 Enter Lef of heating ducts in cell E147 Moderate Major Replace S0 Enter Lef of heating ducts in cell E147 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148 Moderate Major Replace S0 Enter Lef of heating ducts in cell E148			NOTHEED							
G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2030 Pedestrian Paving G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G2050 Landscaping G2050 Landscaping G2050 Site Mechanical Utilities New LF G3010 Water Supply New LF G3020 Sanitary Sewer New LF G3020 Sanitary Sewer New LF G3030 Storm Sewer New LF G3040 Storm Sewer New LF G3040 Major Supply None Minor Moderate Major Replace Major Replace Major Replace Minor Moderate Major Replace Major Replace Major Replace Major Replace Major Replace Major Replace Minor Moderate Major Replace Major Replace Major Replace Minor Moderate Major Replace Minor Moderate Major Replace Minor Moderate Major Replace Major Replace Minor Moderate Major Replace Major Replace Minor Moderate Major Replace Minor Moderate Major Re	·	·	NOT USED							
G2010 Roadways G2020 Parking Lots G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2040 Site Development G2050 Landscaping G305 Site Mechanical Utilities None LF G3010 Water Supply New LF G3020 Sanitary Sewer New LF G3020 Sanitary Sewer None LF G3030 Storm Sewer None LF G3030 Storm Sewer None LF G3030 Storm Sewer None LF G3030 Storm Sewer None LF G3030 Storm Sewer LF G3030 Storm Sewer None LF G3030 Storm Sewer LF G3030 Storm	G20 Si	ite Improvements						_		Dead was had a second but were like to see
G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2040 Site Development G2050 Landscaping G2050 Landsca										
G2030 Pedestrian Paving G2040 Site Development G2040 Site Development G2050 Landscaping G2050 Landscaping G30 Site Mechanical Utilities New LF G3010 Water Supply Domestic New LF G3020 Sanitary Sewer New LF G3020 Sanitary Sewer New LF G3030 Storm Sewer New LF G3050 Cooling Distribution New LF G3060 Fuel Distribution None Minor Moderate Najor x Replace 100% \$33,164 A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its structural integrity A portion of the line has lost its		' - '								
G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities New LF G3010 Water Supply Domestic New LF G3020 Sanitary Sewer New LF G3030 Storm Sewer New LF G3030 Storm Sewer New LF G3030 Storm Sewer New LF G3050 Cooling Site Mechanical Utilities None Minor Moderate None		G2020 Parking Lots			x Minor					Minor cracking observed
G2050 Landscaping G30 Site Mechanical Utilities New LF G3010 Water Supply Domestic New LF G3020 Sanitary Sewer New LF G3030 Storm Sewer New LF G3030 Storm Sewer New LF G3050 Cooling Distribution G30 Site Mechanical Utilities None Minor Moderate Major x Replace S0 Entire site is irrigated - no observed issues A portion of the line has lost its structural integrity and requires replacement. Moderate Major x Replace Major x Replace S0 Enter LF of pipe in cell E144 A portion of the line has lost its structural integrity and requires replacement. Moderate Major x Replace New LF G3030 Storm Sewer New LF G3040 Heating Distribution New LF G3050 Cooling Distribution X None Minor Moderate Major Replace S0 Enter LF of heating ducts in cell E147 Major Replace S0 Enter LF of beating ducts in cell E148 Major Replace S0 Enter LF of natural gas lines in cell E148 Major Replace S0 Enter LF of natural gas lines in cell E149		G2030 Pedestrian Paving		65,917 None	Minor	Moderate x Major	Replace	2%	\$13,256	Damaged walkways identified over entire site
G2050 Landscaping G305 Site Mechanical Utilities New LF G3010 Water Supply Domestic Fire Minor Moderate Major Moderate Major Replace S0 Entire site is irrigated - no observed issues A portion of the line has lost its structural integrity and requires replacement. None Minor Moderate Major Replace S0 Enter LF of pipe in cell E144 A portion of the line has lost its structural integrity and requires replacement. New LF G3020 Sanitary Sewer 600 None Minor Moderate Major x Replace S0 Enter LF of pipe in cell E144 A portion of the line has lost its structural integrity and requires replacement. New LF G3030 Storm Sewer Major x Replace S0 Enter LF of pipe in cell E144 A portion of the line has lost its structural integrity and requires replacement. Major x Replace S0 Enter LF of pipe in cell E144 A portion of the line has lost its structural integrity and requires replacement. New LF G3030 Storm Sewer Major Replace S0 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution A None Minor Moderate Major Replace S0 Enter LF of duct work in cell E148 New LF G3050 Firer LF of natural gas lines in cell E149		G2040 Site Development		2,421 x None	Minor	Moderate Major	Replace		\$0	No observed issues
New LF G3010 Water Supply Domestic 600 None Minor Moderate Major x Replace 100% \$43,571 and requires replacement. New LF G3020 Sanitary Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer Minor Moderate Major x Moderate Major x Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution X None Minor Moderate Major Replace 50 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution Moderate Major Replace 50 Enter LF of duct work in cell E148 New LF G3060 Fuel Distribution Moderate Major Replace 50 Enter LF of natural gas lines in cell E149		G2050 Landscaping		130,922 x None	Minor	Moderate Major	Replace		\$0	Entire site is irrigated - no observed issues
New LF G3010 Water Supply Domestic 600 None Minor Moderate Major x Replace 50 Enter LF of pipe in cell E144 New LF G3020 Sanitary Sewer 600 None Minor Moderate Major x Replace 100% \$43,571 and requires replacement. New LF G3030 Storm Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer Minor Moderate Major x Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution X None Minor Moderate Major Replace 50 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution X None Minor Moderate Major Replace 50 Enter LF of duct work in cell E148 New LF G3060 Fuel Distribution X None Minor Moderate Major Replace 50 Enter LF of natural gas lines in cell E149	G30 Si	ite Mechanical Utilities								
New LF G3020 Sanitary Sewer 600 None Minor Moderate Major Replace \$0 Enter LF of pipe in cell E144 New LF G3030 Storm Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor x Moderate Major Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution x None Minor Moderate Major Replace 50 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution x None Minor Moderate Major Replace 50 Enter LF of duct work in cell E148 New LF G3060 Fuel Distribution X None Minor Moderate Major Replace 50 Enter LF of natural gas lines in cell E149										A portion of the line has lost its structural integrity
New LF G3020 Sanitary Sewer 600 None Minor Moderate Major Replace \$0 Enter LF of pipe in cell E144 New LF G3030 Storm Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor x Moderate Major Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution x None Minor Moderate Major Replace 50 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution x None Minor Moderate Major Replace 50 Enter LF of duct work in cell E148 New LF G3060 Fuel Distribution X None Minor Moderate Major Replace 50 Enter LF of natural gas lines in cell E149	New LF	G3010 Water Supply	Domestic	600 None	Minor	Moderate	x Replace	100%	\$43,571	and requires replacement.
New LF G3020 Sanitary Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor x Moderate Major x Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution		,								Enter LF of pipe in cell E144
New LF G3020 Sanitary Sewer 600 None Minor Moderate Major x Replace 100% \$30,164 and requires replacement. New LF G3030 Storm Sewer 600 None Minor x Moderate Major x Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution						ajoi	Періасс		Ψ.	
New LF G3030 Storm Sewer New LF G3040 Heating Distribution New LF G3050 Cooling Distribution New LF G3060 Fuel Distribution New LF G3060 Fuel Distribution None Minor Moderate New LF G3060 Fuel Distribution None Minor Moderate None Minor Moderate None Minor Moderate Major Replace Major Replace \$0 Enter LF of heating ducts in cell E147 Major Replace \$0 Enter LF of duct work in cell E148 Major Replace \$0 Enter LF of duct work in cell E148 Major Replace \$0 Enter LF of natural gas lines in cell E149	Now IE	G2020 Sanitary Sower		600 None	Minor	Madarata	y Poplace	100%	¢20.164	
New LF G3030 Storm Sewer 600 None Minor x Moderate Major Replace 20% \$402 and requires replacement. New LF G3040 Heating Distribution X None Minor Moderate Major Replace \$0 Enter LF of heating ducts in cell E147 New LF G3050 Cooling Distribution X None Minor Moderate Major Replace \$0 Enter LF of duct work in cell E148 New LF G3060 Fuel Distribution X None Minor Moderate Major Replace \$0 Enter LF of natural gas lines in cell E149	New LF	G3020 Saliital y Sewel		000 None	IVIIIIOI	ivioderate	х керіасе	100%	\$30,104	
New LF G3040 Heating Distribution	No. 15	62020 Sharra Sarra		600			Davids.	200/	6402	
New LF G3050 Cooling Distribution								20%		
New LF G3060 Fuel Distribution x None Minor Moderate Major Replace \$0 Enter LF of natural gas lines in cell E149		_						\vdash		_
		=								
New LF G3090 Other Site Mechanical Utilities NOT USED None Minor Moderate Major Replace				x None		Moderate	Replace		\$0	Enter LF of natural gas lines in cell E149
	New LF	G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Moderate	Replace			

G40 Site	Electrical Utilities											
	G4010 Electrical Distribution	Service	100%	x None	Minor		Moderate		Major	Replace	\$0	No observed issues
		Generator		o None	Minor		Moderate		Major	Replace	\$0	
	G4020 Site Lighting		100%	x None	Minor		Moderate		Major	Replace	7.7	No observed issues
	G4030 Site Communications & Security		100%	x None	Minor		Moderate		Major	Replace	\$0	No observed issues
	G4090 Other Site Electrical Utilities	NOT USED		None	Minor		Moderate		Major	Replace		
G90 Othe	er Site Construction	NOT USED						_				•
OTHER												
							Unit of					
	Description of System						Measure		Quantity	Unit Budget	Extended	Notes
						_					\$0	
											\$0	
											\$0	
											\$0	
											\$0	
											\$0	

Physical Condition Budget Sub-Total	\$1,582,936
Budgeted Development Costs	\$601,516
Physical Condition Budget TOTAL	\$2,184,452
Cost with Escalation to June 2023	\$2,490,276
Cost with Escalation to June 2024	\$2,589,887
Cost with Escalation to June 2025	\$2,693,482
Replacement Budget	\$19,429,020

<u>Douglas County SD 4</u>

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

Site Name: Fit Grove ES An unused cell or system that should not receive direct user input

Building Name: Main An automatically populated cell from user input elsewhere in the file - do not overwrite **Building ID:** 19912702156 LEVEL OF ACTION Replace as % of % of Building part of **Automated Budget** System or Level 1 Level 2 Level 3 Type (as applicable) or Number None Minor Moderate Major Renovation Finish **Estimate** A SUBSTRUCTURE A10 Foundations Modulars have wood foundation - no observed issues A1010 Standard Foundations 10% x None Minor Moderate Major Replace \$0 A1020 Special Foundations Minor Moderate Replace \$0 None Major A1030 Slab on Grade 90% Moderate Major Replace \$0 No observed issues A20 Basement Construction A2010 Basement Excavation NOT USED None Moderate Replace A2020 Basement Walls None Minor Moderate Major Replace \$0 B SHELL B10 Superstructure B1010 Floor Construction Wood 10% \$0 No observed issues None /linor Moderate Majo Replace Steel None Minor Moderate Major Replace \$0 Concrete 90% None Minor Moderate Major Replace \$0 No observed issues Major No observed issues B1020 Roof Construction Wood 100% None Minor Moderate Replace \$0 Steel None Minor Moderate Major Replace \$0 \$0 Concrete None Minor Moderate Major Replace **B20 Exterior Enclosure** B2010 Exterior Walls \$0 Concrete Formed / Tilt None Minor Moderate Major Replace Masonry None Minor Moderate Major Replace \$0 Framed w/ Wood Siding None Minor Moderate Major Replace \$0 New Previously Framed w/Panel Siding Framed w/Metal Panel 100% None Minor x Moderate Major Replace 15% \$18,361 Minor paint needed on each building Framed w/Stucco None Minor Moderate Major Replace \$0 \$0 Framed w/Masonry Veneer None Minor Moderate Major Replace 73 single pane wood windows need to be replaced **B2020 Exterior Windows** 100% \$29,747 Wood 18% None Minor Moderate x Major Replace of the 338 aluminum/steel windows were fogged and i \$3,735 eed of replacement Aluminum/Steel 81% Minor Moderate Major Replace None Clad None Minor Moderate Replace 100% \$2,839 5 single pane clad windows need to be replaced 2% Major Curtain Wall None Minor Moderate Major Replace \$0 All wood doors were in good condition and operating B2030 Exterior Doors Wood 31 Minor Replace \$0 appropriately None Moderate Major All metal doors were in good condition and operating Hollow Metal None Minor Moderate Major Replace appropriately Storefront None Minor Moderate Major Replace \$0 **B30 Roofing B3010 Roof Coverings** Asphalt Shingle None Minor Moderate Maior Replace \$0 All walkway roof coverings had cracks and ponding water. The majority of roofs were worn and had cracks on them Built up system originally installed in sections between 1988 and 1997. Built-Up 100% Moderate x Replace 60% \$534.875 None Minor Major Single Ply \$0 None Minor Moderate Major Replace Metal Moderate \$0 None Minor Major Replace Concrete Tile None Minor Moderate Major Replace \$0 By Building GSF B3020 Roof Openings Skylights None Minor Moderate Major Replace \$0 \$0 Per hatch Access Hatch None Minor Moderate Major Replace C INTERIORS C10 Interior Construction C1010 Partitions No observed issues 100% x None \$0 Framed Minor Moderate Major Replace Minor Moderate Major Replace \$0 Masonry None C1020 Interior Doors All interior wood doors were in good working order Wood None Minor Moderate Major Replace \$0 All interior metal doors were in good working order **Hollow Metal** x None Minor Moderate Major Replace \$0 C1030 Fittings NOT USED Moderate Replace C20 Stairs

Moderate Major

Replace

No stairs were observed in any of the interior buildings

\$0

C2010 Stair Construction

Wood

	*****		F				D I	$\overline{}$	ćo	Cost /Elight
	Metal		lone	Minor	Moderate	Major	Replace		\$0	Cost/Flight
COOOL Challe Fields	Concrete		one	Minor	Moderate	Major	Replace	_	\$0	Cost/Flight
C2020 Stair Finishes	Concrete Fill		lone	Minor	Moderate	Major	Replace	_	\$0	Cost/Flight
C20 Interior Finishes	Resilient	No	lone	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Interior Finishes C3010 Wall Finishes	Paint on Masonry	N	lone	Minor	Moderate	Major	Replace		\$0	
C3010 Wall Fillishes	r aint on wason y	100	one	IVIIIIOI	Wioderate	iviajoi	Kepiace	 	30	Minor paint touch up and wall patching needed
	Wallboard	99% No	lone	x Minor	Moderate	Major	Replace	7%	\$4,800	throughout
	Wainscot		lone	Minor	Moderate	Major	Replace	770	\$0	
	waniscot	H	one	TVIIIIOI	Wioderate	iviajoi	Періасс		70	Grout is damaged in boys and girls restroom - cost
	Ceramic Tile	1% No	lone	x Minor	Moderate	Major	Replace	100%	\$309	increased to accurately reflect actual costs.
C3020 Floor Finishes	Carpet / Soft Surface		lone	Minor	Moderate	Major	x Replace	13%	\$8,337	Worn carpet observed in building 4 & 8
	Resilient Tile			x Minor	Moderate	Major	Replace	10%	\$2,009	Small number of cracked tiles observed throughout
	Resilient Sheet		lone	Minor	Moderate	Major	x Replace	6%	\$1,481	Minor damage observed SPED classroom
	Polished Concrete			x Minor	Moderate	Major	Replace	10%	\$208	Minor surface damage observed in two storage areas
	Ceramic Tile			x Minor	Moderate	Major	Replace	5%	\$327	Ceramic tile damaged in boys restroom
	Liquid Applied		lone	Minor	Moderate	Major	Replace		\$0	
	Wood Sports Floor		lone	Minor	Moderate	Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard		lone	Minor	x Moderate	Major	Replace	2%	\$1,200	Minor patch and paint needed in three areas
	Lay-In Ceiling Tile		-	x Minor	Moderate	Major	Replace	10%	\$754	Stained tiles observed in several classrooms
	Glued-Up Ceiling Tile			x Minor	Moderate	Major	Replace	10%	\$1,181	Damaged/Stained/Missing tiles found in several areas
	Painted Structure		lone	Minor	Moderate	Major	Replace		\$0	
D SERVICES								_	7-	
D10 Conveying										
D1010 Elevators & Lifts		No	one	Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Walks			lone	Minor	Moderate	Major	Replace		\$0	
D1090 Other Conveying Systems			lone	Minor	Moderate	Major	Replace		\$0	
D20 Plumbing						.,.				
D2010 Plumbing Fixtures		100% No	lone	Minor	x Moderate	Major	Replace	1%	\$480	All (N) fixtures must meet ADA requirements by code.
D2020 Domestic Water Distribution		100% x No	lone	Minor	Moderate	Major	Replace		\$0	No observed issues
D2030 Sanitary Waste		100% x No	lone	Minor	Moderate	Major	Replace		\$0	No observed issues
D2040 Rain Water Drainage			lone	Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	No	lone	Minor	Moderate	Major	Replace			
D30 HVAC			_		_					
D3010 Energy Supply										
20010 Lineigy Supply			lone	Minor	Moderate	Major	Replace		\$0	No observed issues
D3020 Heat Generating Systems	Boiler	o No	lone	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	No observed issues
	Boiler Air Handler		lone	_						
		o No	lone	Minor	Moderate	Major	Replace		\$0 \$0	Gas furnaces. Per facility manager - furnaces need to be
		0 No	lone	Minor	Moderate	Major	Replace	100%	\$0 \$0 \$146,062	
	Air Handler	0 No 0 No 100% x No	lone lone	Minor Minor	Moderate Moderate	Major Major	Replace Replace	100%	\$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms.
D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger	0 No	lone lone	Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace Replace x Replace Replace	100%	\$0 \$0 \$146,062 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and
	Air Handler Furnace Heat Exchanger Component of air handler	0 No	lone lone lone lone	Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major	Replace Replace x Replace Replace Replace	100%	\$0 \$0 \$146,062 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms.
D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger	0 No	lone lone lone lone	Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace Replace x Replace Replace	100%	\$0 \$0 \$146,062 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and
D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler	0 No	lone lone lone lone	Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major	Replace Replace x Replace Replace Replace	100%	\$0 \$0 \$146,062 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller	100% x No 100% x No 100% x No 0 No	lone lone lone lone lone	Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major	Replace Replace x Replace Replace Replace Replace		\$0 \$0 \$146,062 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork
D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork	0 No	lone lone lone lone lone	Minor Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major	Replace Replace X Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation.
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% x No	one lone lone lone lone lone lone	Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major Major	Replace Replace X Replace Replace Replace Replace Replace Replace Replace AReplace Replace		\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork
D3020 Heat Generating Systems D3030 Cooling Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit	100% x No	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace Replace x Replace		\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation.
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% x No	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace Replace X Replace		\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation.
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit	100% x No 100% x	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% x No 100% x	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace		\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D40 Fire Protection D4010 Sprinklers	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	ione ione ione ione ione ione ione ione	Minor	Moderate	Major	Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D40 Fire Protection D4010 Sprinklers D4020 Standpipes	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4016 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4016 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues No observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues No observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D401 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	100%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues No observed issues
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	50%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues No observed issues Older panels - some are maxed out requiring upgrades Some complaints from staff about not having enough outlets
D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D401 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	lone lone lone lone lone lone lone lone	Minor	Moderate	Major	Replace Replace X Replace	100%	\$0 \$0 \$146,062 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Gas furnaces. Per facility manager - furnaces need to be replaced as they each service 2 classrooms. Gas pack units on roof with A/C unit in special needs and library areas - no observed issues Per facility manager - office building needs new ductwork along with cleaning across new furnace installation. No observed issues Old and experiencing major issues No observed issues

D5030 Communications & Security D5090 Other Electrical Systems E EQUIPMENT & FURNISHINGS	Voice / Data System Clock / Intercom System Closed Circuit Surveillance Access Control System Intrusion Alarm System Fire Alarm / Detection Lighting Control System NOT USED	100% x None 100% x None 100% x None 100% x None 0 None 20% x None 100% x None 0 None None	Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major	Replace Replace x Replace Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$42,173 \$0 \$0 \$0 \$0	No observed issues No observed issues All are being decommissioned and need to be replaced Admin and IT areas - no observed issues No observed issues
E10 Equipment									
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate	Major	Replace		\$0	1 stove appears to be very old, but functioning
22020 Commercial Equipment	Vocational	None	Minor	Moderate	Major	Replace		\$0	
E1020 Institutional Equipment	Science	None	Minor	Moderate	Major	Replace		\$0	
• •	Art	None	Minor	Moderate	Major	Replace		\$0	
	Stage Performance	None	Minor	Moderate	Major	Replace		\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	100% x None	Minor	Moderate	Major	Replace		\$0	All stalls and hardware were in good working order
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E20 Furnishings			_						
									Worn casework found in several classrooms, along with a
									few damaged cabinet doors that need to be
E2010 Fixed Furnishings		100% None	Minor	x Moderate	Major	Replace	8%	\$6,446	fixed/replaced
F0000 44 . 11 . F . 111							201	445.450	One classroom had extremely outdated furniture that should be replaced.
E2020 Movable Furnishings F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED		100% None	Minor	Moderate	Major	x Replace	2%	\$16,458	stidulu be replaced.
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED									
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements									
G2010 Roadways		4000 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G2020 Parking Lots		23000 None	Minor	Moderate	x Major	Replace	100%	\$167,021	Needs to be replaced
G2030 Pedestrian Paving		16181 None	Minor	Moderate	x Major	Replace	15%	\$24,405	Pedestrian pathways cracked in multiple areas
G2040 Site Development		2719 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G2050 Landscaping		169271 x None	Minor	Moderate	Major	Replace		\$0	Whole site with river irrigation, no observed issues
G30 Site Mechanical Utilities			_						
New LF G3010 Water Supply	Domestic	600 None	Minor	Moderate	_	x Replace	100%	\$43,571	System is beyond its useful life and should be replaced
New LF	Fire	None	Minor	Moderate	Major	Replace		\$0	Enter LF of pipe in cell E144
New LF G3020 Sanitary Sewer		600 None	Minor	Moderate	- ''	x Replace	100%	\$30,164	System is beyond its useful life and should be replaced
New LF G3030 Storm Sewer		100 x None	Minor	Moderate	Major	Replace		\$0	Enter SF of area to be drained
New LF G3040 Heating Distribution		100 x None	Minor	Moderate	Major	Replace		\$0	Enter LF of heating ducts in cell E147
New LF G3050 Cooling Distribution		100 x None	Minor	Moderate	Major	Replace		\$0	Enter LF of duct work in cell E148
New LF G3060 Fuel Distribution		100 x None	Minor	Moderate	Major	Replace		\$0	Enter LF of natural gas lines in cell E149
New LF G3090 Other Site Mechanical Utilities	NOT USED	100 None	Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities	Comine	100 x None	Minor	Madarata		Danlass		\$0	No observed issues
G4010 Electrical Distribution	Service Generator	100 x None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	no observed issues
G4020 Site Lighting	Generator	100 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G4030 Site Communications & Security		100 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G4090 Other Site Electrical Utilities	NOT USED	100 X None	Minor	Moderate	Major	Replace		30	TO ODDE. Ved IDDGES
G90 Other Site Construction	NOT USED	100		ode.dte	.v.ajo.	періосс			-
255 255 255 255 355 355									
OTHER									
Description of System				Unit of Measure	Quantity	Unit Budget		Extended	Notes
								\$(
	· · · · · · · · · · · · · · · · · · ·	-						\$(
								\$0	
								\$(
								\$(\$(<u> </u>
								\$(

Physical Condition Budget Sub-Total	\$1,314,223
Budgeted Development Costs	\$499,405
Physical Condition Budget TOTAL	\$1,813,627
Cost with Escalation to June 2023	\$2,067,535
Cost with Escalation to June 2024	\$2,150,236
Cost with Escalation to June 2025	\$2,236,246
Replacement Budget	\$15,691,490

 District Name:
 Douglas County SD 4

 Site Name:
 Fullerton ES

 Building Name:
 Main

 Building ID:
 0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

									LEVE	L OF ACTIO	N						
Level 1			Type (as applicable)	% of Building or Number		None		Minor		Moderate		Major		Replace as part of Renovation	% of System or Finish	Automated Budget Estimate	Notes
A SUBS																	
	A10 Four						_						_				
		A1010 Standard Foundations			_	one	_	1inor		/loderate	_	Major		Replace		\$0	
		A1020 Special Foundations			_	one	_	1inor		/loderate		Major		Replace		\$0	
		A1030 Slab on Grade		100%	No	one	N	linor		∕loderate	Ш	Major	F	Replace		\$0	
	A20 Base	ement Construction									_						
			NOT USED			one		1inor	_	/loderate	_	Major		Replace		40	
		A2020 Basement Walls			No	one		1inor	ш	∕loderate	ш	Major	Н	Replace		\$0	
B SHELI		a salan salan sa															
	BTO Sub	erstructure B1010 Floor Construction	Wood		N/	one	N	1inor		∕loderate		Major		Replace	1	\$0	
			Steel	-	_	one		1inor	_	/loderate	-	Major	-	Replace		\$0	
			Concrete		_	one		1inor		/loderate		Major		Replace		\$0	
			Wood	100%	_	one		linor	_	/loderate		Major		Replace	20%	\$76,296	Roof decks in Rooms #22, #7, #4.
			Steel	100%	_	one		1inor		/loderate	_	Major		Replace	2070	\$0	
			Concrete		_	one		1inor		/loderate	-	Major		Replace		\$0	
	B20 Exte	rior Enclosure			———————————————————————————————————————								ш.			7.	
			Concrete Formed / Tilt		N	one	N	linor		∕loderate	П	Major	F	Replace		\$0	
			Masonry	60%	_	one		linor	_	∕loderate	_	Major		Replace		\$0	
			,									.,.		.,			The wood boards are deteriorating in parts and
		Framed w/Panel Siding (Previous)	Framed w/ Wood Siding	40%	No	one	N	linor	N	/loderate	x	Major	F	Replace	30%	\$34,964	need to be replaced before re-painting.
			Framed w/Metal Panel		No	one	N	1inor	N	∕loderate		Major		Replace		\$0	
			Framed w/Stucco		No	one	N	1inor	N	∕loderate		Major	F	Replace		\$0	
			Framed w/Masonry Veneer		No	one	N	1inor	N	∕loderate		Major	F	Replace		\$0	
		B2020 Exterior Windows	Wood		No	one	N	1inor	N	∕loderate		Major	F	Replace		\$0	
																	Single pane original steel and aluminum windows.
			Aluminum/Steel	100%	x No			linor		∕loderate		Major		Replace	100%	\$190,739	Not energy efficient. Operation is difficult.
			Clad		_	one		1inor	_	∕loderate	_	Major	-	Replace		\$0	
			Curtain Wall		No	one	N	1inor		∕loderate		Major	F	Replace		\$0	
																	All doors are original, present signs of damage and rot specially on the bottom and the hardware
		B2030 Exterior Doors	Wood	24	No	one	N	linor	^	/loderate	х	Major	F	Replace	100%	\$40,219	does not comply with accessibility requirements.
																	All doors are original, present signs of rust and
			Hallam Madal	4.4	- I			41	١.				l I.		4000/	ć20.222	the hardware does not comply with accessibility requirements.
			Hollow Metal Storefront	14	_	one one		1inor 1inor	_	Moderate Moderate		Major Major		Replace Replace	100%	\$20,333 \$0	requirements.
	B30 Roo		Storenont		INC	one	IV	111101	Ш'	viouerate		iviajui	ш'	replace		ŞU	
	<u> </u>		Asphalt Shingle	г	N/	one		linor		/loderate	т	Major		Replace	T	\$0	
		23010 Roof coverings	Aspirate stringle		⊣'''	one	Hï	111101	H'	viouciate	\vdash	iviajoi	H"	replace		Ψ0	No observed deficiencies. Replacements from
			Built-Up	100%	x No	one	l l	1inor		∕loderate		Major	F	Replace		\$0	2019 - 2022.
			Single Ply		_	one	_	1inor	_	/loderate	_	Major	-	Replace		\$0	
			Metal		_	one	_	1inor	_	/loderate	_	Major		Replace		\$0	
			Concrete Tile		_	one		1inor	_	/loderate		Major		Replace		\$0	
			Skylights		_	one		linor	_	∕loderate		Major		Replace		\$0	By Building GSF
			Access Hatch			one		linor		∕loderate		Major		Replace		\$0	Per hatch
C INTER	IORS																
		rior Construction															
		C1010 Partitions	Framed	40%	x No	one	N	1inor	N	∕loderate		Major	F	Replace		\$0	
			Masonry	60%	x No	one	N	1inor	N	∕loderate		Major	F	Replace		\$0	
									П				П	ľ			Hardware does not meet accessibility
		C1020 Interior Doors	Wood	8	No	one	N	linor	N	∕loderate	х	Major	F	Replace		\$0	requirements.

04000 5777	Hollow Metal	No		Moderate Majo			\$0	
C1030 Fittings	NOT USED	No	one Minor	Moderate	Replace			
C20 Stairs	Weed			NA - double Date to			ćo	Cost/Flight
C2010 Stair Construction	Wood Metal		one Minor one Minor	Moderate Majo Moderate Majo		-	\$0 \$0	Cost/Flight
			one Minor	Moderate Majo		—	\$0	Cost/Flight
C2020 Stair Finishes	Concrete Concrete Fill		one Minor	Moderate Majo		-	\$0	Cost/Flight
C2020 Stall Fillishes	Resilient		one Minor	Moderate Majo		-	\$0	Cost/Flight
C30 Interior Finishes	Resilient	INC	one	Moderate	керіасе		\$U	Cost/Tilgitt
C3010 Wall Finishes	Paint on Masonry	95% No	one x Minor	Moderate	Replace	100%	\$106,534	Wall surfaces need re-painting.
C3010 Wall Fillisties	Wallboard		one Minor	Moderate Majo		100%	\$100,334	wall surfaces freed re-painting.
	Wainscot		one Minor			-	\$0	
	Ceramic Tile		one Minor			—	\$0	
C3020 Floor Finishes	Carpet / Soft Surface		one Minor	Moderate Majo Moderate Majo		50%	\$50,163	
C3020 Flooi Fillisties	carpet / Soft Surface	30% INC	one willor	iviouerate	x Replace	30%	\$30,103	
	Resilient Tile	65% No	one Minor	Moderate Majo	x Replace	25%	\$55,319	9x9 possibly ACT. Replace with polished concrete.
	Resilient Sheet		one Minor	Moderate Majo		23/0	\$0	3x3 possibly her neplace with polished condicter
	Polished Concrete		one Minor	Moderate Majo			\$0	
	Ceramic Tile		one Minor	Moderate Majo			\$0	
	Liquid Applied		one Minor	Moderate Majo			\$0	
	Wood Sports Floor		one Minor	Moderate Majo		+	\$0	
C3030 Ceiling Finishes	Wallboard		one Minor	Moderate Majo			\$0	
C3030 Celling Fillishes	Lay-In Ceiling Tile		one x Minor	Moderate Majo		20%	\$3,004	Some tiles are stained or damaged.
	Glued-Up Ceiling Tile		one x Minor	Moderate Majo		10%	\$2,278	Some tiles are stained or damaged.
	Painted Structure		one Minor	Moderate Majo		10%	\$0	Some thes are stamed or damaged.
D SERVICES	Tunited Structure		JIIC IVIIIIOI	ividuciate	перисс		70	
D10 Conveying								
D1010 Elevators & Lifts		No	one Minor	Moderate Majo	Replace		\$0	
D1020 Escalators & Moving Walks			one Minor	Moderate Majo			\$0	
D1090 Other Conveying Systems			one Minor	Moderate Majo			\$0	
D20 Plumbing								
D20 Plumbing								All (N) fixtures must meet ADA requirements by
D20 Plumbing					П			All (N) fixtures must meet ADA requirements by code. Plumbing fixtures are original, not water
		100% No	one Minor	Moderate Majo	x Replace	100%	\$450,566	All (N) fixtures must meet ADA requirements by code. Plumbing fixtures are original, not water efficient.
D2010 Plumbing Fixtures		100% No	one Minor	Moderate Majo		100%	\$450,566 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution			one Minor	Moderate	Replace	100%		code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures		100% x No 100% x No	one Minor	Moderate	Replace Replace	100%	\$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste	NOT USED	100% x No 100% x No No	one Minor Minor	Moderate Majo Moderate Majo	Replace Replace Replace	100%	\$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage	NOT USED	100% x No 100% x No No	one Minor one Minor one Minor	Moderate Majo Moderate Majo Moderate Majo	Replace Replace Replace	100%	\$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems	NOT USED	100% X No 100% X No No No	one Minor one Minor one Minor	Moderate Majo Moderate Majo Moderate Majo	Replace Replace Replace Replace	100%	\$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC	NOT USED Boiler	100% X No. 100% X No.	one Minor one Minor one Minor one Minor	Moderate Majo Moderate Majo Moderate Majo Moderate Majo	Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply		100% x Nc 100% x Nc Nc Nc	one Minor one Minor one Minor one Minor	Moderate Majo Moderate Majo Moderate Majo Moderate Majo Moderate Majo	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler	100% x Nc 100% x Nc Nc Nc	one Minor one Minor one Minor one Minor one Minor one Minor	Moderate Majo	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler	100% x Nc	one Minor one Minor one Minor one Minor one Minor one Minor	Moderate Majo	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler Air Handler	100% x No	one Minor	Moderate Majo	Replace		\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply	Boiler Air Handler Furnace	100% x No	one Minor	Moderate Majo	Replace		\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$213,268	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger	100% x No	one Minor	Moderate Majo	Replace X Replace Replace Replace Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger Component of air handler	100% x No	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller	100% x No	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork	100% x No	one Minor	Moderate Majo	Replace Replace Replace Replace Replace Replace Replace Replace Replace X Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% x No 100% x No N	one Minor	Moderate Majo	Replace Replace Replace Replace Replace Replace Replace Replace Replace X Replace Replace X Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit	100% x NC 100% x NC NC NC 100% NC NC 100% NC 100% NC 100% NC 100% NC NC 100% NC N	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$13,268 \$0 \$19,324 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% x No	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$19,324 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$13,268 \$0 \$19,324 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% x No.	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$19,324 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No.	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$13,268 \$0 \$19,324 \$0 \$0 \$0 \$0 \$0 \$134,669 \$73,092	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% X NC	one Minor	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$0 \$19,324 \$0 \$0 \$0 \$0 \$134,669 \$73,092	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D40 Fire Protection D4010 Sprinklers D4020 Standpipes	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% X No	one Minor	Moderate	Replace Replace Replace Replace Replace Replace Replace Replace Replace X Replace X Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$19,324 \$0 \$0 \$0 \$19,324 \$0 \$0 \$134,669 \$73,092	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D40 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	one Minor Mi	Moderate Majo	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$0 \$19,324 \$0 \$0 \$0 \$0 \$134,669 \$73,092	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.
D2010 Plumbing Fixtures D2020 Domestic Water Distribution D2030 Sanitary Waste D2040 Rain Water Drainage D2090 Other Plumbing Systems D30 HVAC D3010 Energy Supply D3020 Heat Generating Systems D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D40 Fire Protection D4010 Sprinklers D4020 Standpipes	Boiler Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% x No	one Minor	Moderate	Replace	100%	\$0 \$0 \$0 \$0 \$0 \$0 \$213,268 \$0 \$19,324 \$0 \$0 \$0 \$19,324 \$0 \$0 \$134,669 \$73,092	code. Plumbing fixtures are original, not water efficient. Furnaces are obsolete and parts are not longer available. Compressors for DX units, obsolete. Blowers for DX units, obsolete.

D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D5030 Communications & Security D5090 Other Electrical Systems	Voice / Data System Clock / Intercom System Closed Circuit Surveillance Access Control System Intrusion Alarm System Fire Alarm / Detection Lighting Control System NOT USED	100%	Minor Minor Minor Minor Minor Minor Minor Minor	Moderate	Major	x Replace	60%	\$243,606 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Most panels are original and obsolete with not extra capacity.
E EQUIPMENT & FURNISHINGS									
E10 Equipment									
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate	Major	Replace		\$0	No observed deficiencies.
	Vocational	None	Minor	Moderate	Major	Replace		\$0	
E1020 Institutional Equipment	Science Art	None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	
	Stage Performance	None	Minor	Moderate	Major	Replace		\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	12% x None	Minor	Moderate	Major	Replace		\$0	No observed deficiencies.
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E20 Furnishings					_				Most cabinets are old and present damage in
E2010 Fixed Furnishings		100% x None	Minor	Moderate	x Major	Replace	100%	\$187,235	their surface and hardware.
E2020 Movable Furnishings		100% x None	Minor	Moderate	Major	Replace		\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED									
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements									
G2010 Roadways		None	Minor	Moderate	Major	Replace		\$0	Cost/SF of surface area
G2020 Parking Lots		20500 x None	Minor		x Major	Replace	100%	\$148,867	Surface is cracked and in poor condition.
G2030 Pedestrian Paving		2500 x None	Minor	Moderate	Major	Replace		\$0	concrete sidewalks are in good condition
G2040 Site Development		1000 x None	Minor	Moderate	Major	Replace		\$0	Fencing around playing areas is in good condition.
G2050 Landscaping		70300 None	Minor	Moderate	Major	Replace		\$0	Mature landscaping in good condition.
G30 Site Mechanical Utilities					,			7-	
G3010 Water Supply	Domestic	100 x None	Minor	Moderate	Major	Replace		\$0	
	Fire	None	Minor	Moderate	Major	Replace		\$0	
G3020 Sanitary Sewer		100 x None	Minor	Moderate	Major	Replace		\$0	
G3030 Storm Sewer		100 x None	Minor	Moderate	Major	Replace		\$0 \$0	
G3040 Heating Distribution G3050 Cooling Distribution		None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	
G3060 Fuel Distribution		None	Minor	Moderate	Major	Replace		\$0	
G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities									
G4010 Electrical Distribution	Service	100% x None	Minor	Moderate	Major	Replace		\$0	Overhead pole feed.
C4030 Site Lighting	Generator	None 100% x None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	Lighting is functional and adequate.
G4020 Site Lighting G4030 Site Communications & Security		100% x None 100% x None	Minor	Moderate	Major	Replace		\$0	Lighting is functional and adequate.
G4090 Other Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace		Şū	
G90 Other Site Construction	NOT USED								
OTHER				Unit of		T T			Т
Description of System				Measure	Quantity	Unit Budget		Extended	Notes
								\$0	
				\perp				\$0	
				→ 	-	↓		\$0	
				┥┝──┤	-	1		\$0 \$0	
				┥┝──┤		1		\$0	
						-			•

Physical Condition Budget Sub-Total	\$2,130,376
Budgeted Development Costs	\$809,543
Physical Condition Budget TOTAL	\$2,939,918
Cost with Escalation to June 2023	\$3,351,507
Cost with Escalation to June 2024	\$3,485,567
Cost with Escalation to June 2025	\$3,624,990
Replacement Budget	\$22.911.416

 District Name:
 Douglas County SD 4

 Site Name:
 Green ES

 Building Name:
 Main

 Building ID:
 0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

				ſ				LEV	EL OF ACTIO	N			Ī		
Level 1			Type (as applicable)	% of Building or Number		None	Minor		Moderate		Major	Replace as part of Renovation	% of System or Finish	Automated Budget Estimate	Notes
A SUBS															
	A10 Fou	ndations			—		—		l					4-	Destable buildings with an absenced in
		A1010 Standard Foundations		7%	_	ne	Minor		Moderate	-	Major	Replace	-	\$0	Portable buildings with no observed issues.
		A1020 Special Foundations A1030 Slab on Grade		93%	_	ne	Minor Minor		Moderate	_	Major	Replace		\$0 \$0	
	A 20 Pac	ement Construction		93%	INC	ne	IVIIIIVI	ш	Moderate	ш	Major	Replace		ŞU	
	AZU Base	A2010 Basement Excavation	NOT USED		No	ne	Minor		Moderate		Major	Replace			
		A2020 Basement Walls	NOT USED		No		Minor		Moderate		Major	Replace		\$0	
B SHELL		AZOZO BUSCITICITE WUIIS		<u></u>			IVIIIIOI	ш	Moderate	ш	iviajoi	перисс		, JO	
		<u>erstructure</u>													
		B1010 Floor Construction	Wood	7%	x No	ne	Minor		Moderate		Major	Replace		\$0	Portable buildings with no observed issues.
			Steel		_	ne	Minor		Moderate		Major	Replace		\$0	
			Concrete		No	ne	Minor		Moderate		Major	Replace		\$0	
		B1020 Roof Construction	Wood	100%	x No	ne	Minor		Moderate		Major	Replace		\$0	Seismic upgrade project was completed in 2018.
			Steel		No	ne	Minor		Moderate		Major	Replace		\$0	
			Concrete		No	ne	Minor		Moderate	Ш	Major	Replace		\$0	
	B20 Exte	rior Enclosure					_		Ī						
		B2010 Exterior Walls	Concrete Formed / Tilt		_	ne	Minor		Moderate	-	Major	Replace		\$0	
			Masonry	60%	x No		Minor	ш	Moderate	-	Major	Replace		\$0	No observed or reported issues.
		Previously Framed w/Panel Siding	Framed w/ Wood Siding		_	ne	Minor	Н	Moderate		Major	Replace		\$0	
			Framed w/Metal Panel		_	ne	Minor	Н	Moderate	-	Major	Replace		\$0	
			Framed w/Stucco	400/	_	ne	Minor		Moderate	-	Major	Replace	-	\$0	Doutoble electronic and building siding
		D2020 Futorior Windows	Framed w/Masonry Veneer	40%	_	ne	Minor	Н	Moderate		Major	Replace		\$0 \$0	Portable classrooms and building siding.
		B2020 Exterior Windows	Wood	1000/	_	ne	Minor Minor	Н	Moderate	-	Major	Replace		\$0 \$0	Installed with the seismic upgrade project.
			Aluminum/Steel Clad	100%	x No	one one	Minor		Moderate Moderate		Major Major	Replace		\$0 \$0	installed with the seismic upgrade project.
			Curtain Wall		_	ne	Minor	\vdash	Moderate		Major	Replace Replace		\$0	
			Cui tairi waii		-	nie	WIIIOI	\vdash	iviouerate	\vdash	iviajui	Керіасе		ŞŪ	Doors are original age of construction and they
															are beyond their useful life. Some doors were
		B2030 Exterior Doors	Wood	8	No	ne	Minor		Moderate		Major	x Replace	100%	\$17,875	being replaced during the site visit.
			Hollow Metal	13	_	ne	Minor		Moderate		Major	x Replace	100%	\$26,142	
			Storefront		No	ne	Minor		Moderate	-	Major	Replace		\$0	
	B30 Roo	fing				_									
		B3010 Roof Coverings	Asphalt Shingle	7%	No	ne	Minor		Moderate		Major	x Replace	100%	\$39,876	At portable classrooms. Replacement needed.
			Built-Up	33%	No	ne	Minor		Moderate		Major	Replace		\$0	
															PVC roofs are in good condition, newly installed
			Single Ply	60%	x No	ne	Minor		Moderate	ш	Major	Replace		\$0	in 2018.
			Metal		_	ne	Minor	ш	Moderate		Major	Replace		\$0	
			Concrete Tile		_	ne	Minor		Moderate		Major	Replace		\$0	D. D. II II
		B3020 Roof Openings	Skylights		_	ne	Minor		Moderate		Major	Replace		\$0	By Building GSF
			Access Hatch		No	ne	Minor		Moderate		Major	Replace		\$0	Per hatch
C INTER		dan Canatan atlan													
	C10 Inte	rior Construction	Framod	60%	u Na		Minor		Madazaka		Maior	Donlass		ćo	
		C1010 Partitions	Framed	40%	x No		Minor Minor		Moderate Moderate		Major Major	Replace		\$0 \$0	
			Masonry	40%	X INC	me	IVIIIIVI		ivioderate	Н	iviajor	Replace		ŞU	Doors are original from the 60's and 70's beyond
										ll					their useful life. The door hardware does not
		C1020 Interior Doors	Wood	64	No	ne	Minor	x	Moderate		Major	Replace	90%	\$51,481	meet current accessibility standards.
			Hollow Metal		No		Minor	-	Moderate	\vdash	Major	Replace		\$0	·
		C1030 Fittings	NOT USED			ne	Minor		Moderate		Major	Replace			
	C20 Staiı					•			ı		-				
		C2010 Stair Construction	Wood		No	ne	Minor		Moderate		Major	Replace		\$0	Cost/Flight

	Metal		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Concrete		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C2020 Stair Finishes	Concrete Fill		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Resilient		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Interior Finishes		-						-		
C3010 Wall Finishes	Paint on Masonry	85%	None	x Minor	Moderate	Major	Replace	100%	\$72,308	
	Wallboard	5% x	None	Minor	Moderate	Major	Replace		\$0	
	Wainscot	5% x	None	Minor	Moderate	Major	Replace		\$0	Wood panels in the multipurpose room.
	Ceramic Tile	5% x	None	Minor	Moderate	Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	5%	None	Minor	Moderate	Major	x Replace	100%	\$12,684	Beyond useful life and should be replaced.
	Resilient Tile	85% x	None	Minor	Moderate	Major	Replace		\$0	
	Resilient Sheet		None	Minor	Moderate	Major	Replace		\$0	
	Polished Concrete	2% x	None	Minor	Moderate	Major	Replace		\$0	
	Ceramic Tile	5% x	None	Minor	Moderate	Major	Replace		\$0	
	Liquid Applied		None	Minor	Moderate	Major	Replace		\$0	
	Wood Sports Floor	3% x	None	Minor	Moderate	Major	Replace		\$0	Wood flooring in the stage.
C3030 Ceiling Finishes	Wallboard		None	Minor	Moderate	Major	Replace		\$0	
	Lay-In Ceiling Tile	70%	None	x Minor	Moderate	Major	Replace	15%	\$3,988	Ceiling stains and physical damage
	Glued-Up Ceiling Tile	30%	None	x Minor	Moderate	Major	Replace	15%	\$1,111	Ceiling stains and physical damage
	Painted Structure		None	Minor	Moderate	Major	Replace		\$0	
D SERVICES		-	_							
D10 Conveying										
D1010 Elevators & Lifts			None	Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Walks			None	Minor	Moderate	Major	Replace	i i	\$0	
D1090 Other Conveying Systems			None	Minor	Moderate	Major	Replace		\$0	
D20 Plumbing										
			1							All (N) fixtures must meet ADA requirements by
D2010 Plumbing Fixtures		100%	None	Minor	Moderate	Major	x Replace	60%	\$205,076	code. Older fixtures not water efficient.
									·	Systemic issues throughout. Water filtration is an
D2020 Domestic Water Distribution		100%	None	x Minor	Moderate	Major	Replace	100%	\$46,712	issue.
										Systemic issues throughout. Water filtration is an
D2030 Sanitary Waste		100%	None	x Minor	Moderate	Major	Replace	100%	\$59,624	issue.
D2040 Rain Water Drainage			None	Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED		None	Minor	Moderate	Major	Replace			
D30 HVAC			_			_				
D3010 Energy Supply		100% x	None	Minor	Moderate	Major	Replace		\$0	
D3020 Heat Generating Systems	Boiler		None	Minor	Moderate	Major	Replace		\$0	
	Air Handler		None	Minor	Moderate	Major	Replace		\$0	
	Furnace	100% x	None	Minor	Moderate	Major	Replace		\$0	
	Heat Exchanger		None	Minor	Moderate	Major	Replace		\$0	
D3030 Cooling Generating Systems	Component of air handler	30% x	None	Minor	Moderate	Major	Replace		\$0	
	Stand alone chiller		None	Minor	Moderate	Major	Replace		\$0	
			1							MFIA Engineering priority 1 recommendation
										(2022) - Revise heating system to include
										ventilation and filtration per OMSC Chapter 4 and
										ASHRAE 62.1-2019. Add improvements to the
										heating systems in classroom building B and
										Library to provide ventilation and filtration per
										previous noted code and standard. Escalated
D3040 Distribution Systems	Ductwork	100% x	None	Minor	Moderate	Major	x Replace	100%	\$195,581	based on MFIA engineering recommendations.
	Hot water return & supply		None	Minor	Moderate	Major	Replace		\$0	
										PTAC units at Portables. Dated to 1980, obsolete
D3050 Terminal & Package Units	Above ceiling VAV unit	20%	None	Minor	Moderate	Major	x Replace	100%	\$30,609	and energy inefficient.
	In-room ventilator unit	30% x	None	Minor	Moderate	Major	Replace		\$0	Ventilator for DX system in the office and library.
	In-room radiant unit	15% x	None	Minor	Moderate	Major	Replace		\$0	Reznor unit heaters in the multipurpose room.
D3060 Controls & Instrumentation		100%	None	Minor	Moderate	Major	x Replace	40%	\$40,863	Some thermostats are obsolete.
D3070 Systems Testing & Balancing		100%	None	Minor	Moderate	Major	x Replace	100%	\$55,446	Throughout the building.
D3090 Other HVAC Systems & Equipment	NOT USED		None	Minor	Moderate	Major	Replace			
D40 Fire Protection			7		_		_		,	
D4010 Sprinklers			None	Minor	Moderate	Major	Replace		\$0	
D4020 Standpipes			None	Minor	Moderate	Major	Replace		\$0	
D4030 Fire Protection Specialties			None	Minor	Moderate	Major	Replace		\$0	

D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate	Major	Replace			
<u>D50 Electrical</u>				П					Main service is dated 1950's with 1980's feed, the parts are obsolete and difficult to obtain. A new 400A was installed for the Minisplt units in 2014.
D5010 Electrical Service & Distribution		100% None	Minor	Moderate	Major	x Replace	80%	\$246,395	No additional capacity.
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate	Major	Replace		\$0	
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate	Major	Replace		\$0	
	Clock / Intercom System	100% None	Minor	Moderate	Major	Replace		\$0	No observed deficiencies.
	Closed Circuit Surveillance	None	Minor	Moderate	Major	Replace		\$0	
	Access Control System	None		Moderate	Major	Replace		\$0	
	Intrusion Alarm System	None	Minor	Moderate	Major	Replace	\vdash	\$0	D. II stations at success with and fire along
	Fire Alarm / Detection	100% x None	Minor Minor	Moderate	Major	Replace	—	\$0 \$0	Pull stations at every exit and fire alarm.
D5090 Other Electrical Systems	Lighting Control System NOT USED	None None		Moderate Moderate	Major Major	Replace Replace		\$ 0	
	NOT OSED	None	IVIIIIOI	Wiodelate	IVIAJOI	періасе			
E EQUIPMENT & FURNISHINGS E10 Equipment									
									The kitchen equipment is functional but beyond
E1010 Commercial Equipment	Food Service	100% x None		Moderate	Major	x Replace	100%	\$89,246	its useful life. Walk-in cooler is obsolete.
	Vocational	None		Moderate	Major	Replace		\$0	
E1020 Institutional Equipment	Science	None		Moderate	Major	Replace		\$0	
	Art	None		Moderate	Major	Replace	\vdash	\$0	Contict of Store Designation Association
	Stage Performance	600 x None	Minor	Moderate	Major	Replace	220/	\$0	Cost/SF of Stage Performance Area Five wood stalls need to be replaced.
E1030 Vehicular Equipment	Restroom Accessories/Stalls NOT USED	100% x None None		Moderate Moderate	Major Major	x Replace	33%	\$24,814	rive wood stalls fleed to be replaced.
E1090 Other Equipment	NOT USED	None		Moderate	Major	Replace Replace			
E20 Furnishings		None		Moderate	···ajo:	перисс			
E2010 Fixed Furnishings		100% None	x Minor	Moderate	Major	Replace	100%	\$52,788	Outdated with damaged surfaces.
E2020 Movable Furnishings		100% None	Minor	Moderate	Major	Replace		\$0	No observed deficiencies.
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED					_				
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements G2010 Roadways		15000 None	x Minor	Moderate	Major	Replace	100%	\$26,310	Crack fill and seal.
G2020 Parking Lots		30000 None		Moderate	Major	Replace	100%	\$52,620	Crack fill and seal.
G2030 Pedestrian Paving		14000 x None		Moderate	Major	Replace	100%	\$0	Cost/SF of surface area
G2040 Site Development		1000 x None		Moderate	Major	Replace		\$0	Cost/LF of fencing
G2050 Landscaping		10000 x None		Moderate	Major	Replace		\$0	Cost/SF of irrigated area
G30 Site Mechanical Utilities		·			_				
G3010 Water Supply	Domestic	100 x None	Minor	Moderate	Major	Replace		\$0	Enter LF of pipe in cell E143
	Fire	100 x None	Minor	Moderate	Major	Replace		\$0	Enter LF of pipe in cell E144
G3020 Sanitary Sewer		100 x None		Moderate	Major	Replace		\$0	Enter LF of sewer lines in cell E145
G3030 Storm Sewer		15000 None		Moderate	x Major	Replace	100%	\$67,032	Beyond useful life and should be replaced.
G3040 Heating Distribution		None		Moderate	Major	Replace	\vdash	\$0	Enter LF of heating ducts in cell E147
G3050 Cooling Distribution		None		Moderate	Major	Replace	\vdash	\$0	Enter LF of duct work in cell E148
G3060 Fuel Distribution	NOT LICED	100 x None		Moderate	Major	Replace		\$0	Enter LF of natural gas lines in cell E149
G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G4010 Electrical Distribution	Service	100% x None	Minor	Moderate	Major	Replace		\$0	
G-616 Electrical Distribution	Generator	None None		Moderate	Major	Replace	\vdash	\$0	
G4020 Site Lighting		100% x None		Moderate	Major	Replace	\vdash	\$0	
G4030 Site Communications & Security		None		Moderate	Major	Replace		\$0	
G4090 Other Site Electrical Utilities	NOT USED	None		Moderate	Major	Replace			
G90 Other Site Construction	NOT USED								
OTHER									
Description of System				Unit of Measure	Quantity	Unit Budget	t	Extended	Notes
								\$0	
] [\$(
] [\$0	

]	1	\$0	
				\$0	
]	\$0	
				\$0	

Replacement Budget \$17,380,281

 District Name:
 Douglas County SD 4

 Site Name:
 Hucrest ES

 Building Name:
 0

 Building ID:
 0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

									LEVE	LEVEL OF ACTION							
Level 1			Type (as applicable)	% of Building or Number		None		Minor		Moderate		Major		Replace as part of Renovation	% of System or Finish	Automated Budget Estimate	Notes
A SUBS																	
	<u>Α10 Fou</u>	ndations		50/		1	— .		_	l						40	Doutoblo huildings
		A1010 Standard Foundations		6%	_	None		1inor 1inor		Moderate		Major		Replace		\$0 \$0	Portable buildings.
		A1020 Special Foundations A1030 Slab on Grade		94%	_	None None	_	/inor		Moderate Moderate		Major Major		Replace Replace		\$0	
	Δ2Ω Ras	ement Construction		3470	^	vone	10	111101	Ш	woderate	ш	iviajoi		Replace		Şū	
	AZO DUS		NOT USED			None	N	/linor		Moderate		Major		Replace			
		A2020 Basement Walls				None		/linor		Moderate		Major		Replace		\$0	
B SHEL									_			,				,-	
		<u>erstructure</u>															
		B1010 Floor Construction	Wood	6%	x	None	N	/linor		Moderate		Major		Replace		\$0	Portable buildings.
			Steel			None	N	/linor		Moderate		Major		Replace		\$0	
			Concrete		_	None		/linor	_	Moderate		Major	Ш	Replace		\$0	
			Wood	100%	_	None		/linor		Moderate		Major		Replace		\$0	
			Steel		_	None		/linor		Moderate		Major	Ш	Replace		\$0	
			Concrete		Ш	None	N	/linor		Moderate	Ш	Major	Ш	Replace		\$0	
	BZU EXT	erior Enclosure B2010 Exterior Walls	Concrete Formed / Tilt	r 1	_	None		linor	П	Modorato	П	Major		Poplaco		\$0	
			Concrete Formed / Tilt Masonry	75%	_	None None		Ainor Ainor	-	Moderate Moderate	_	Major Major		Replace Replace		\$0	
			Framed w/ Wood Siding	7370	_	None		/linor		Moderate		Major	H	Replace		\$0	
			Trained w/ Wood Stains		=1	vonc			Н	Wioderate	H	iviajoi		перисс		70	Siding at the portable buildings in good condition.
																	The wood panels by the gym present damage
		Previously Framed w/Panel Siding	Framed w/Metal Panel	25%	1	None	N	/linor		Moderate	х	Major		Replace	20%	\$17,825	specially at the bottom.
			Framed w/Stucco			None	N	/linor		Moderate		Major		Replace		\$0	
			Framed w/Masonry Veneer		ı	None	N	/linor		Moderate		Major		Replace		\$0	
		B2020 Exterior Windows	Wood			None	N	/linor		Moderate		Major		Replace		\$0	
			Aluminum/Steel	100%	x	None	N	/linor		Moderate		Major		Replace		\$0	
			Clad			None	N	/linor		Moderate		Major		Replace		\$0	
			Curtain Wall			None	N	/linor		Moderate		Major		Replace		\$0	
		B2030 Exterior Doors	Wood	4		None	N	/linor		Moderate		Major	х	Replace	100%	\$8,938	Exterior wood doors are damaged and need replacement.
																	Door hardware is from the 60's and 70's and does
			Hollow Metal	20	_	None		/linor	-	Moderate	_	Major	х	Replace	100%	\$40,219	not comply with accessibility standards.
			Storefront		I	None	N	/linor		Moderate		Major		Replace		\$0	
	B30 Roc			120/		1							_		-	40	Chinalas installed in the early 2000's
		B3010 Roof Coverings	Asphalt Shingle	12%	Х	None	IV	/linor	_	Moderate	ш	Major		Replace		\$0	Shingles installed in the early 2000's.
																	Many cracks and organic growth on the roofing system. Leaks were observed on the ceiling tiles.
																	Majority of the roofing system has been replaced.
			Built-Up	88%	L	None	N	/linor		Moderate		Major	×	Replace	4%	\$47,841	Only 1800 SF needs to be replaced.
			Single Ply		_	None	_	/linor	-	Moderate	_	Major		Replace		\$0	
			Metal		_	None		/linor	-	Moderate	_	Major		Replace		\$0	
			Concrete Tile		_	None		/linor	-	Moderate		Major		Replace		\$0	
			Skylights			None	N	/linor	П	Moderate		Major		Replace		\$0	By Building GSF
			Access Hatch			None		/linor		Moderate		Major		Replace		\$0	Per hatch
C INTER	IORS																
	C10 Inte	rior Construction															
		C1010 Partitions	Framed	40%		None		/linor		Moderate		Major	Ш	Replace		\$0	
			Masonry	60%	Х	None	N	/linor		Moderate	Ш	Major	Щ	Replace		\$0	
																	Door hardware is from the 60's and 70's and does
																	not comply with accessibility standards. Door
		C1030 Interior Deers	Mond	30	[].	Nana		dinar	I ., I	Madarat -		Maiar		Danlasa	1000/	¢26 812	panels present scuffing and minor impact damage.
		C1020 Interior Doors	Wood	50	ш'	None	IV	/linor	Х	Moderate	ш	Major	ш	Replace	100%	\$26,813	aumage.

			_						Door hardways is from the CO's and 70's and door
									Door hardware is from the 60's and 70's and does not comply with accessibility standards. Door
	Hollow Metal	6 None	Minor	x Moderate	Major	Replace	100%	\$5,363	panels need paint.
C1030 Fittings	NOT USED	None	Minor	Moderate	Major	Replace	10070	\$3,303	paries need paries
C20 Stairs									
C2010 Stair Construction	Wood	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Metal	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Concrete	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C2020 Stair Finishes	Concrete Fill	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	Resilient	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Interior Finishes			_		_				
C3010 Wall Finishes	Paint on Masonry	80% None	x Minor	Moderate	Major	Replace	100%	\$93,675	
	Wallboard	None	Minor	Moderate	Major	Replace	1000/	\$0	
	Wainscot Ceramic Tile	20% None None	x Minor Minor	Moderate Moderate	Major Major	Replace Replace	100%	\$21,119 \$0	
C3020 Floor Finishes	Carpet / Soft Surface	None	Minor	Moderate	Major	Replace	\rightarrow	\$0	
C3020 Floor Fillishes	carpet / Soft Surface	None	Willion	Wioderate	iviajoi	Replace	\vdash	 	
									Most VCT is separating form the seams and many
									areas are cracked. There are 9x9 tiles, possibly
	Resilient Tile	85% None	Minor	Moderate	Major	x Replace	100%	\$302,142	ACT, in the classrooms that seam to be original.
	Resilient Sheet	10% x None	Minor	Moderate	Major	Replace		\$0	
	Polished Concrete	None	Minor	Moderate	Major	Replace		\$0	
	Ceramic Tile	3% x None	Minor	Moderate	Major	Replace		\$0	
	Liquid Applied	2% x None	Minor	Moderate	Major	Replace		\$0	
	Wood Sports Floor	None	Minor	Moderate	Major	Replace	\vdash	\$0	
C3030 Ceiling Finishes	Wallboard	None None	Minor x Minor	Moderate	Major	Replace	20%	\$0 \$3,136	Some panels present damage or stains.
	Lay-In Ceiling Tile Glued-Up Ceiling Tile	30% None 70% None	x Minor x Minor	Moderate Moderate	Major Major	Replace Replace	20%	\$3,136	Some panels present damage or stains.
	Painted Structure	70% None None	Minor	Moderate	Major	Replace	20%	\$4,737	Some panels present damage of stains.
O SERVICES	T diffica 5ti detaile	None	IVIIIIOI	Wioderate	iviajoi	перисс	\vdash	70	
D10 Conveying									
D1010 Elevators & Lifts		None	Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Walks		None	Minor	Moderate	Major	Replace		\$0	
D1090 Other Conveying Systems		None	Minor	Moderate	Major	Replace		\$0	
D20 Plumbing			_	_	_	_			
									All (N) fixtures must meet ADA requirements by
									code. Many plumbing fixtures have been updated, but there remain original fixtures that
									need to be replaced, in particular in the staff
D2010 Plumbing Fixtures		100% None	Minor	Moderate	Major	x Replace	60%	\$282,278	restrooms and classroom sinks.
52020 Hambing Fixed Co		100/0		- Moderate	iviajo:	х перисс	00/0	\$202,270	The system had minor repairs as needed, but
D2020 Domestic Water Distribution		100% x None	Minor	Moderate	Major	Replace		\$0	there are not issues reported.
									The system had minor repairs as needed, but
D2030 Sanitary Waste		100% x None	Minor	Moderate	Major	Replace		\$0	there are not issues reported.
D2040 Rain Water Drainage		None	Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D30 HVAC			<u> </u>			<u> </u>		4-	
D3010 Energy Supply	Delle :	None	Minor	Moderate	Major	Replace	\vdash	\$0	
D3020 Heat Generating Systems	Boiler	None	Minor	Moderate	Major	Replace	\vdash	\$0	All now system
	Air Handler Furnace	100% x None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace	\vdash	\$0 \$0	All new system.
	Heat Exchanger	None	Minor	Moderate	Major	Replace	\vdash	\$0	
D3030 Cooling Generating Systems	Component of air handler	100% x None	Minor	Moderate	Major	Replace	$\overline{}$	\$0	All new system.
	Stand alone chiller	None	Minor	Moderate	Major	Replace		\$0	·
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate	Major	Replace		\$0	All new system.
•	Hot water return & supply	None	Minor	Moderate	Major	Replace		\$0	
D3050 Terminal & Package Units	Above ceiling VAV unit	None	Minor	Moderate	Major	Replace		\$0	
	In-room ventilator unit	None	Minor	Moderate	Major	Replace		\$0	
	In-room radiant unit	None	Minor	Moderate	Major	Replace		\$0	
D3060 Controls & Instrumentation		100% None	Minor	Moderate	Major	Replace		\$0	All new system.
D3070 Systems Testing & Balancing		100% None	Minor	Moderate	Major	Replace		\$0	All new system.
D3090 Other HVAC Systems & Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
D40 Fire Protection									

		 1.		—		— .		4-	
D4010 Sprinklers		None	Minor	Moderate	Major	Replace		\$0	
D4020 Standpipes		None	Minor	Moderate	Major	Replace	\longmapsto	\$0 \$0	
D4030 Fire Protection Specialties	NOTUCED	None	Minor	Moderate	Major	Replace		\$0	
D4090 Other Fire Protection Systems <u>D50 Electrical</u>	NOT USED	None	Minor	Moderate	Major	Replace			
D5010 Electrical Service & Distribution		100% None	Minor	Moderate	Major	Replace		\$0	
D3010 Electrical Service & Distribution		100/0 Notice	IVIIIIOI	Wioderate	Iviajoi	Періасе		 	Upgrades with T8 fixtures. Replacements and
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate	Major	Replace		\$0	upgrades.
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate	Major	Replace		\$0	
boos communications a security	Clock / Intercom System	100% x None	Minor	Moderate	Major	Replace	\vdash	\$0	
	Closed Circuit Surveillance	None	Minor	Moderate	Major	Replace		\$0	
	Access Control System	None	Minor	Moderate	Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor	Moderate	Major	Replace		\$0	
	Fire Alarm / Detection	100% x None	Minor	Moderate	Major	Replace		\$0	
	Lighting Control System	None	Minor	Moderate	Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Major	Replace		7-	
E EQUIPMENT & FURNISHINGS									
E10 Equipment				_		_			
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate	Major	Replace		\$0	
	Vocational	None	Minor	Moderate	Major	Replace		\$0	
E1020 Institutional Equipment	Science	None	Minor	Moderate	Major	Replace		\$0	
	Art	None	Minor	Moderate	Major	Replace		\$0	
	Stage Performance	None	Minor	Moderate	Major	Replace		\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	100% x None	Minor	Moderate	Major	Replace		\$0	
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E20 Furnishings			_			— .			15.6
E2010 Fixed Furnishings		100% None	Minor	x Moderate	Major	Replace	100%	\$122,843	Surfaces and hardware need to be repaired.
E2020 Movable Furnishings		None	Minor	Moderate	Major	Replace	lder	\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED									
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
	1101 0020								
G20 Site Improvements									
G20 Site Improvements G2010 Roadways		12000 None	x Minor	Moderate	Major	Replace	100%	\$21.048	Several temperature cracks on the asphalt
G2010 Roadways		12000 None	x Minor	Moderate	Major	Replace	100%	\$21,048 \$40,693	Several temperature cracks on the asphalt.
G2010 Roadways G2020 Parking Lots		23200 None	x Minor	Moderate	Major	Replace	100%	\$40,693	Several temperature cracks on the asphalt. Several temperature cracks on the asphalt.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving		23200 None 5000 x None	x Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$40,693 \$0	
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development		23200 None 5000 x None 1000 x None	x Minor Minor Minor	Moderate Moderate Moderate	Major Major Major	Replace Replace Replace		\$40,693 \$0 \$0	Several temperature cracks on the asphalt.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping		23200 None 5000 x None	x Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$40,693 \$0	
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities	Domestic	23200 None 5000 x None 1000 x None 12400 x None	x Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace Replace Replace Replace		\$40,693 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping	Domestic Fire	23200 None 5000 x None 1000 x None 12400 x None 100 x None	x Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace Replace Replace Replace Replace		\$40,693 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply	Domestic Fire	23200 None 5000 x None 1000 x None 12400 x None 100 x None None	x Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major	Replace Replace Replace Replace Replace Replace Replace		\$40,693 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer		23200 None 5000 x None 1000 x None 12400 x None 100 x None 100 x None 100 x None	x Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major	Replace Replace Replace Replace Replace Replace Replace Replace Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer		23200 None 5000 x None 1000 x None 12400 x None 100 x None 100 x None 100 x None 100 x None	x Minor Minor Minor Minor Minor Minor Minor Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution		23200 None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution		23200 None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3060 Fuel Distribution	Fire	23200 None	x Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities		23200 None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3090 Other Site Mechanical Utilities	Fire NOT USED	23200 None S000 X None 1000 X None 12400 X None 100 X None 100 X None 100 X None None None None 100 X None No	x Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major Major Major Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities	NOT USED Service	23200 None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3090 Other Site Mechanical Utilities	Fire NOT USED	23200 None S000 X None 1000 X None 12400 X None 100 X None 100 X None 100 X None None None None 100 X None No	x Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major Major Major Major Major Major Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3090 Other Site Mechanical Utilities G4010 Electrical Distribution	NOT USED Service	23200 None S000 X None 1000 X None 12400 X None 100 X None 100 X None 100 X None None None None 100 X None 100 X None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution	NOT USED Service	23200 None S000 X None 1000 X None 12400 X None 100 X None 100 X None 100 X None None None None 100 X None 100 X None	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution	NOT USED Service	23200 None S000 X None 1000 X None 12400 X None 100 X None 100 X None 100 X None None None None 100 X None None 100 X None None 100 X None Non	x Minor	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution	NOT USED Service Generator	23200	x Minor Mino	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution	NOT USED Service Generator	23200	x Minor Mino	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G4010 Electrical Utilities G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities	NOT USED Service Generator	23200	x Minor Mino	Moderate	Major	Replace		\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of duct work in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities G90 Other Site Electrical Utilities	NOT USED Service Generator	23200	x Minor Mino	Moderate	Major	Replace	100%	\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of natural gas lines in cell E148 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was sufficient and working properly.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Fuel Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G4010 Electrical Utilities G4010 Electrical Distribution G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities	NOT USED Service Generator	23200	x Minor Mino	Moderate	Major	Replace	100%	\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was sufficient and working properly.
G2010 Roadways G2020 Parking Lots G2030 Pedestrian Paving G2040 Site Development G2050 Landscaping G30 Site Mechanical Utilities G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities G4010 Electrical Distribution G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities G90 Other Site Construction	NOT USED Service Generator	23200 None S000 X None 1000 X None 12400 X None 100 X None 100% X None 10	x Minor Mino	Moderate	Major	Replace	100%	\$40,693 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Several temperature cracks on the asphalt. Mature landscape in fair condition. Enter LF of pipe in cell E143 Enter LF of pipe in cell E144 Enter LF of sewer lines in cell E145 Enter SF of area to be drained Enter LF of heating ducts in cell E147 Enter LF of natural gas lines in cell E149 No reported issues. New underground service. It was reported that the site lighting was sufficient and working properly.

]	1	\$0	
				\$0	
]			\$0	
]			\$0	
	1		1	\$0	
]]	\$0	_

Physical Condition Budget Sub-Total	\$1,038,690
Budgeted Development Costs	\$394,702
Physical Condition Budget TOTAL	\$1,433,393
Cost with Escalation to June 2023	\$1,634,068
Cost with Escalation to June 2024	\$1,699,430
Cost with Escalation to June 2025	\$1,767,408
Replacement Budget	\$23,923,259

District Name:	Douglas County SD 4
Site Name:	Melrose ES
Building Name:	0
Building ID:	0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

							LEVEL OF ACTIO	ON					
										Replace as	% of		
				% of Building						part of	System or	Automated Budget	
Level 1	Level 2	Level 3	Type (as applicable)	or Number	None	Minor	Moderate	1 1 1	Major	Renovation	Finish	Estimate	Notes
A SUBS			71- 4										
	A10 Fou												
	M10 1 00			400/			N 4 - d 4 -	<u> —</u>		Davidson		ćo	1909 building. CMU
		A1010 Standard Foundations		10%	x None	Minor	Moderate		ajor	Replace		\$0	1909 building. Civio
		A1020 Special Foundations			None	Minor	Moderate		ajor	Replace		\$0	
		A1030 Slab on Grade		90%	x None	Minor	Moderate	Ma	ajor	Replace		\$0	
	A20 Base	ement Construction							_				
		A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Ma	ajor	Replace			
		A2020 Basement Walls		10%	None	Minor	Moderate	Ma	ajor	Replace		\$0	small area in 1909 building. Not used.
B SHELL					_	_		_				•	
		erstructure											
	DIO Sup		Wood	10%	x None	Minor	Moderate	N4-	ajor	Replace		\$0	10% - 1909
				10%			_						10% 1303
			Steel		None	Minor	Moderate		ajor	Replace		\$0	
			Concrete		x None	Minor	Moderate		ajor	Replace		\$0	
		B1020 Roof Construction	Wood	100%	x None	Minor	Moderate	Ma	ajor	Replace		\$0	
			Steel		None	Minor	Moderate	Ma	ajor	Replace		\$0	
			Concrete		None	Minor	Moderate	Ma	ajor	Replace		\$0	
	B20 Exte	rior Enclosure				_	_		-				
		B2010 Exterior Walls	Concrete Formed / Tilt	90%	None	Minor	Moderate	Ma	ajor	Replace		\$0	İ
				30%	None	Minor	Moderate	-	ajo: ajor	Replace		\$0	
			Masonry		None	IVIIIIOI	iviouerate	IVIC	aj01	Replace		ŞU	1909 building wood siding in good condition,
													gym, top 1/2 wood paneling is bowing,
													presenting damage. District is getting an seismic
			Framed w/ Wood Siding	10%	x None	Minor	Moderate			x Replace	35%	\$32,418	upgrade that will address this issue
			Framed w/Metal Panel		None	Minor	Moderate		ajor	Replace		\$0	
			Framed w/Stucco		None	Minor	Moderate	Ma	ajor	Replace		\$0	
			Framed w/Masonry Veneer		None	Minor	Moderate	Ma	ajor	Replace		\$0	
		B2020 Exterior Windows	Wood		x None	Minor	Moderate	Ma	ajor	Replace		\$0	
			Aluminum/Steel	100%	x None	Minor	Moderate	_	ajor	Replace		\$0	1980s full replacement. No sign of seal failures.
			Clad		None	Minor	Moderate	_	ajor	Replace		\$0	
			Curtain Wall		_	Minor	Moderate	-				\$0	
			Curtain waii	-	None	IVIIIIOI	iviouerate	IVIC	ajor	Replace		ŞU	Wood doors and hardware needs to be replaced
		B0000 5 4 1 B		4.0			l I.,	l I.,			4000/	400.440	1
		B2030 Exterior Doors	Wood	12	x None	Minor	Moderate	X IVI	ajor	Replace	100%	\$20,110	across 12 doors.
													Metal door is corroded in the boiler room across
													from the SPED building. Other metal doors
			Hollow Metal	20	None	Minor	x Moderate	Ma	ajor	Replace	20%	\$4,469	showing minor corrosion
			Storefront		None	Minor	Moderate	Ma	ajor	Replace		\$0	
	B30 Roo	fing											
													1909 and 1945 building. 1909 building is close to
		B3010 Roof Coverings	Asphalt Shingle	50%	x None	x Minor	Moderate	Ma	ajor	Replace	25%	\$6,127	useful life.
		=	Built-Up		None	Minor	Moderate	_	ajor	Replace		\$0	
			Single Ply	50%	None	Minor	Moderate		ajor	Replace		\$0	
			Metal	30%	None	Minor	Moderate		ajor	Replace		\$0	
			Concrete Tile		None	Minor	Moderate	_	ajor	Replace		\$0	Du Building CCF
			Skylights		None	Minor	Moderate		ajor	Replace		\$0	By Building GSF
			Access Hatch		None	Minor	Moderate	Ma	ajor	Replace		\$0	Per hatch
C INTER	IORS												
	C10 Inte	rior Construction											
		C1010 Partitions	Framed		None	Minor	Moderate	Ma	ajor	Replace		\$0	
			Masonry		None	Minor	Moderate		ajor	Replace		\$0	
			Wood	33	x None	Minor	Moderate	-	ajor	Replace		\$0	Most interior doors are accordion partitions
			Hollow Metal	- 55	None	Minor	Moderate		ajor	Replace		\$0	
			NOT USED		None	Minor	Moderate		ajor	Replace		, , , , , , , , , , , , , , , , , , ,	
	C20 C+-!	=	NOT OSED		None	IVIIIIOI	woderate	iVic	ujoi	Replace			
	C20 Stair	5											

Metal Concrete Major Moderate Major Mod				_	_		_			
Commonweight Comm	C2010 Stair Construction	Wood	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
Cappar February		Metal	None	Minor	Moderate	Major	Replace			
Columnitary Section Column Colu		Concrete	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
Columnitary Section Column Colu	C2020 Stair Finishes	Concrete Fill	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
Color March Final Color March		Resilient		Minor					\$0	Cost/Flight
Color Part of Miscory SSS System Part of Miscory Well-based SS System Part of Miscory Part of Miscor	C30 Interior Finishes						·		·	
Wellboard Well		Paint on Masonry	95% None	x Minor	Moderate	Major	Replace	33%	\$25,498	1940s building needs repainted
Warrant To Carper for Studies	cools want mishes	•						3370		0 1111
CHRISTO Floor Finalments								—		
CADA Floor Fischles								-		
Resilient Title								H		Country of tile 4000/ and because
Recition Title 2015 None Monter and Moderate Major Register Moderate Major Register Sci	C3020 Floor Finishes	Carpet / Soft Surface	10% None	Minor	Moderate	Major	x Replace	100%	\$24,254	
Recilion Short Polished Concrete 10										
Polithed Correte Care Ca								75%		replaced with polished concrete.
Camin Tile		Resilient Sheet	None	Minor	Moderate	Major	Replace			
Ligida Applied Wood Sports From 100		Polished Concrete	10% None	Minor	Moderate	Major	Replace		\$0	
Moderate		Ceramic Tile	None	Minor	Moderate	Major	Replace		\$0	
Moderate		Liquid Applied	None	Minor	Moderate	Major	Replace		\$0	
Column C										
Lay-in Celling Tile 65% None 1 Minor Moderate Major Replace 10% \$2,179 Some tiles are damaged or discolored. During the moderate Major Modera	C3030 Ceiling Finishes									Wood panel ceiling in office, gym
Services Superior	esoso cening runshes							10%		
Stanuces Since Line Content Line Since Line Since Line Since Line Since Line Since Line L		Lay-III Celling The	140116	× IVIIIIOI	Wioderate	iviajoi	Replace	1070	J2,173	
District		Chard He Celline Tile	200/		0 4 - d t -		Davidada	4000/	ć7.000	=
Discretions Discretions & Uffs D								100%		HVAC isuses with viriyi pipes in 1940s building.
D10 Groweying D100 Flextor's & Lifts D100 Flextor's & Lifts D100 Cher Conveying Systems D100 Cher Conveying Systems D220 Plumbing D200 Cher Conveying Systems D200 Demaster Water Distribution D200 Demaster Water D200 Demaster Water D200 Demaster Water D200 Demaster Water D200 Demaster D20		Painted Structure	None	Minor	Moderate	Major	Replace		\$0	
Disposition										
D1202 Isolators & Moving Walks D1209 Other Conveying Systems D1006 Moderate Major Moderate Maj	D10 Conveying						_			
D200 Plumbing D2010 Plumbing Fixtures	D1010 Elevators & Lifts		None							
D209 Plumbing Fixtures D2002 Demestic Water Distribution D2003 Sanitary Waste D2003 Sanitary Waste D2004 Rain Water Change D2004 Rain Water Change D2004 Rain Water Change D2004 Change D3005 Ferminal & Package Units D3006 Controls & Instrumentation D3007 Systems D3007 Controls & Instrumentation D3007 Systems D3008 Controls & Instrumentation D3009 Other Horsels D4009 Fer Protection D4010 Sprinklers D4009 Other Fire Protection D4010 Sprinklers D4009 Other Fire Protection D4010 Sprinklers D4000 Systems D4010 Sprinklers D4000 Sp	D1020 Escalators & Moving	Valks	None	Minor	Moderate	Major	Replace		\$0	
100% x None 20200 Demestic Water Distribution 100% x None 20200 Demestic Water Distribution 100% x None 20200 Demestic Water Distribution 100% x None 20200 Read plaing that is in need of minor repairs 20200 Repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor repairs 20200 Read plaing that is in need of minor rep	D1090 Other Conveying Syst	ems	None	Minor	Moderate	Major	Replace		\$0	
D2020 Obmestic Water Distribution D2030 Shaltany Waster D2040 Shail Water Drainage D2090 Other Plumbing Systems D3010 Energy Supply D3020 Heat. Generating Systems D3010 Feergrass Boiler D3020 Heat. Generating Systems D3020 Heat. Generating Systems D3020 Heat. Generating Systems D3020 Heat. Generating Systems D3030 Cooling Generating Systems Component of air handler Stand alone chiller Stand alone chiller D3030 Cooling Generating Systems D4030 Cooling Generat	D20 Plumbing									
D2020 Domestic Water Distribution D2030 Sanitary Wastes D2040 Pain Water Drainage D2040 Data Water Drainage D2040 Data Water Drainage D2040 Data Water Drainage D30 HVAC D301 Draing Systems D301 Draing Systems D3020 Heat Generating Systems D3020 Heat Generating Systems D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units In-room ventilator unit In-room rediant unit In-room ventilator unit In-room rediant unit In-room ventilator unit In-room rediant unit										
D2030 Sanitary Waste D2030 Other Plumbing Systems NOT USED None D300 Minor D300 Energy Supply D3020 Head Generating Systems Boiler Air Handler Air Handler Air Handler Air Handler Furnace Heat Exchanger Heat Exchanger Heat Exchanger D3030 Cooling Generating Systems D3040 Distribution Systems D3040 Distribution Systems D4040 Distribution Systems D4050 Terminal & Package Units Allow ceiling VAV unit In-room ventilator unit D3030 Fire Protection D3030 Fire Protection Specialites D4030 Fire Protection Specialites D4030 Fire Protection Specialites D4030 Fire Protection Specialites D4030 Fire Protection Systems NOT USED None None None None None None None None	D2010 Plumbing Fixtures		100% x None	Minor	Moderate	Major	x Replace	33%	\$107,838	Some fixtures beyond useful life, showing distress
D2090 Other Plumbing Systems NOT USED None D2090 Other Plumbing Systems NOT USED None D2090 Other Plumbing Systems NOT USED None D3010 Energy Supply D3010 Energy D3010 Energy Supply D3010 Energy D3010 Energy Supply D3010 Energy D3010 E	D2020 Domestic Water Distr	ibution	100% None	x Minor	Moderate	Major	Replace	100%	\$44,660	Aged piping that is in need of minor repairs
D2004 Distribution Systems D3004 Design Supply D3020 Heat Generating Systems D304 Distribution Systems D304 Distribution Systems D305 Design Supply D3020 Heat Generating Systems D304 Distribution Systems D305 Terminal & Package Units D305 Terminal & Package Units D305 Octorros & Instrumentation D306 Controls & Instrumentation D307 Systems Sequipment D405 Fire Protection D405 Fire Protection D405 Fire Protection D405 D405 Fire Protection Specialites D405 D405 Price Protection D405 D405 Price Protection D405 D50 Detertrial D500 Detertrial										
DOUBT Plumbing Systems NOT USED None Minor D300 Hiser Protection Systems NOT USED None D300 Colorlo Sprinklers DOUBT Energy Supply D300 Colorlo Specialities D400 D500 Centrol Sprinklers DOUBT Energy Supply D300 Colorlo Specialities D400 D500 Chetr Protection D400 D500 Chetr Protection Systems NOT USED None Minor D500 Clettrical Ferotection D500 Clettrical Ferotection Systems NOT USED None D400 None D400 D500 Clettrical Ferotection Systems NOT USED None D500 Clettrical Ferotection D500 Clettrical Ferotection Systems NOT USED None D500 Clettrical Ferotection D500 Clettrical Ferotecti								h + +		
D30 HAXC D3010 Energy Supply D3020 Heat Generating Systems Boiler Air Handler 100% x None Minor Furnace Heat Exchanger Heat Exchanger Heat Exchanger How water return & supply D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units Above celling VAV unit In-room rediation unit In-room rediation unit In-room rediation unit In-room rediation unit D3070 Systems Testing & Balancing D3070 Systems Testing & Balancing D3070 Systems Testing & Balancing D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Systems NOT USED None D5050 Electrical D5050 Electrical D5050 Electrical D5050 Dielectrical D5050 Dielectrical Service & Distribution D5050 Dielectrical Service & Distribution D5050 Dielectrical Service & Distribution D5050 Dielectrical D5050 Dielectric	=	ma NOT LISED							ŞÜ	
D3010 Energy Supply D3020 Heat Generating Systems Boiler Air Handler 100% x None 100% x None 100% x None Minor Moderate		ms NOT USED	None	IVIInor	ivioderate	iviajor	керіасе			
Boiler None Minor Moderate Major Replace S0 10 classrooms are starting to have issues with the moderate Major			None		N 4 - d 4 -		Don't con		ćo	
Air Handler Air Handler 100% x None Minor Moderate x Major Replace 25% \$21,876 gas pack units. Minor repairs needed. Sold strating to have issues with 1 Major Moderate Major Replace 50% \$12,164 furnace systems. Minor repairs needed. Sold strating to have issues with 1 Major Moderate Major Replace 50% \$12,164 furnace systems. Minor repairs needed. Sold strating to have issues with 1 Moderate Major Moderate Major Replace 50% \$12,164 furnace systems. Minor repairs needed. Sold strating to have issues with 1 Moderate Major Moderate Major Replace 50 Moderate								-		
Air Handler Air Handler Furnace Heat Exchanger D3030 Cooling Generating Systems Component of air handler Stand alone chiller D3040 Distribution Systems Ductwork Hot water return & supply D3050 Terminal & Package Units Above celling VAV unit In-room ventilator unit D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3070 Systems & Equipment D406 Fire Protection D406 Syrinklers D4030 Fire Protection Specialties D4030 Fire Protection Specialties D4030 Fire Protection Specialties D506 Electrical D5010 E	D3020 Heat Generating Syst	ems Boiler	None	Minor	Moderate	Major	Replace		\$0	
Furnace Heat Exchanger D3030 Cooling Generating Systems Component of air handler Stand alone chiller D3040 Distribution Systems Ductwork Hot water return & supply Above celling VAV unit In-room radiant unit D3050 Controls & Instrumentation D3070 Systems Testing & Balancing D3070 Systems Testing & Balancing D3070 Systems Testing & Balancing D3070 Systems & Equipment D400 Fire Protection D400 Sprinklers D4000 Standpipes S4000 Standpipes None None None None None None None None										
Furnace 50% x None Minor Minor Moderate Major Moderate Moder		Air Handler	100% x None	Minor	Moderate	x Major	Replace	25%	\$21,876	
Heat Exchanger D3030 Cooling Generating Systems Component of air handler Stand alone chiller D3040 Distribution Systems Ductwork Hot water return & supply Above celling VAV unit In-room ventilator unit In-room radiant unit D3050 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standpipes D4020 Standpipes D4020 Standpipes D4030 Fire Protection Specialties D4030 Terminal & Package Units D501 Electrical D5010 Electrical Service & Distribution D5010 Electrical D5010 Electrical Service & Distribution D5010 Electrical Service & Distribution D5010 Electrical Service & Distribution D5010 Electrical D5010 Electrical Service & Distribution D5010 Electrical Service & Dis										
D3030 Cooling Generating Systems Component of air handler Stand alone chiller D3040 Distribution Systems Ductwork Hot water return & supply D3050 Terminal & Package Units Above celling VAV unit In-room ventilator unit In-room radiant unit D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standapipes D4020 Standapipes D4090 Other Fire Protection Systems D5050 Electrical D5050 Lighting and Branch Wiring Component of air handler Stand alone chiller None None Minor None Minor Moderate Major Replace S0 In-sprinkler system Major Replace S0 In-sprinkler system Major Replace S0 In-sprinkler system Major Replace Major Replace Major Replace Major Replace Major Replace Major Replace S0 In-sprinkler system S0 In-sprinkler system S0 In-sprinkler		Furnace	50% x None	Minor	x Moderate	Major	Replace	50%	\$12,164	furnace systems. Minor repairs needed.
Stand alone chiller D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units D3050 Terminal & Pa		Heat Exchanger	None	Minor	Moderate	Major	Replace		\$0	
Stand alone chiller D3040 Distribution Systems D3040 Distribution Systems D3050 Terminal & Package Units D3050 Terminal & Pa	D3030 Cooling Generating S	stems Component of air handler	None	Minor	Moderate	Major	Replace		\$0	
D3040 Distribution Systems Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4010 Sprinklers D4020 Standpipes D4020 Standpipes D4030 Fire Protection Specialties D4030 Other Fire Protection Systems D4030 Other Fire Protection Systems D5020 Lighting and Branch Wiring D5020 Lighting and Branch Wiring D3050 Terminal & Package Units D406 water teturn & supply None Hoth water return & supply None Minor None Minor Moderate Major Mod	9					_				
Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	D3040 Distribution Systems									
D3050 Terminal & Package Units Above ceiling VAV unit In-room ventilator unit In-room ventilator unit In-room radiant unit In-room rad	25040 Distribution Systems							H +		
In-room ventilator unit In-room rentilator unit In-room radiant In-room	D20E0 Torminal & Backago I					1	_	\vdash		
In-room radiant unit D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D400 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Systems NOT USED D4090 Other Fire Protection Systems NOT USED D500 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D5030 Lighting and Branch Wiring D5040 Fire Protection Systems D5040 Fire Protection Systems NOT USED D5050 Fire Protection Systems D5060 Fire Protection Systems D5070 Fire Protection Systems	D3030 Tellillial & Package C	_						H		
D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems D4090 Other Fire Protection Systems D4090 Other Fire Protection Systems D5010 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D3090 Other HVAC Systems & Equipment NOT USED None None None None None None None None								_		
D3090 Other HVAC Systems & Equipment NOT USED None Minor Moderate D3090 Other HVAC Systems & Equipment NOT USED None Minor Moderate Major Replace So No observed issues So No observed issues So No observed issues										
D3090 Other HVAC Systems & Equipment NOT USED None Minor Moderate Major Replace D401 Fire Protection D4010 Sprinklers D4020 Standpipes D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems D5010 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D50 Electrical D5020 Lighting and Branch Wiring D50 Electrical D503 More Minor Moderate Major Moderate Major Replace Major Replace Major Moderate Major Replace Major Replace Major Moderate Major Replace S0 Minor Moderate Major Replace S0 Minor Moderate Major Replace S0 None Minor Moderate Major Replace S0 None Minor Moderate Major Replace S0 No No observed issues No No observed issues No No observed issues	D3060 Controls & Instrumer									
D401 Sprinklers D402 Standpipes D403 Fire Protection None D403 Fire Protection None D403 Standpipes D4030 Fire Protection Specialties D4030 Other Fire Protection Systems NOT USED D50 Electrical D501 Electrical Service & Distribution D502 Lighting and Branch Wiring D503 Lighting and Branch Wiring D504 Standard Branch Wiring D505 Lighting and Branch Wiring D506 Standard Branch Wiring D506 Standard Branch Wiring D507 Mone D508 Minor Moderate Major Replace S0 No observed issues		ancing	None	Minor	Moderate	Major	Replace		\$0	
D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4030 Other Fire Protection Systems D500 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D503 Distribution D503 Distribution D504 Distribution D505 Distribution D506 Distribution D507 Distribution D508 Distribution D508 Distribution D509 Distribution		ancing			Moderate	Major	Replace			
D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4030 Other Fire Protection Systems D500 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring D503 Distribution D503 Distribution D504 Distribution D505 Distribution D506 Distribution D507 Distribution D508 Distribution D508 Distribution D509 Distribution	D3070 Systems Testing & Ba	=	None	Minor	moderate					
D4020 Standpipes D4030 Fire Protection Specialties D4030 Fire Protection Systems NOT USED None Minor Moderate Major Moderate M	D3070 Systems Testing & Ba D3090 Other HVAC Systems	=	None	Minor	Moderate	_				
D4030 Fire Protection Specialties D4090 Other Fire Protection Systems NOT USED None None None None None None None None	D3070 Systems Testing & Ba D3090 Other HVAC Systems D40 Fire Protection	=				Major	Replace		\$0	no sprinkler system
D4090 Other Fire Protection Systems NOT USED None Minor Moderate Major Replace D50 Electrical Service & Distribution D5020 Electrical Service & Distribution D5020 Lighting and Branch Wiring None Minor Moderate Major Replace S0 No observed issues Minor Moderate Major Replace \$0 No observed issues Major Replace \$0 No observed issues Major Replace \$0 No observed issues	D3070 Systems Testing & Ba D3090 Other HVAC Systems <u>D40 Fire Protection</u> D4010 Sprinklers	=	None	Minor	Moderate					no sprinkler system
D50 Electrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	D3070 Systems Testing & Ba D3090 Other HVAC Systems <u>D40 Fire Protection</u> D4010 Sprinklers D4020 Standpipes	& Equipment NOT USED	None None	Minor Minor	Moderate Moderate	Major	Replace		\$0	no sprinkler system
D5010 Electrical Service & Distribution 100% x None Minor Moderate Major Replace \$0 No observed issues D5020 Lighting and Branch Wiring 100% x None Minor Moderate Major Replace \$0 No observed issues	D3070 Systems Testing & Ba D3090 Other HVAC Systems <u>D40 Fire Protection</u> D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specia	& Equipment NOT USED	None None None	Minor Minor	Moderate Moderate Moderate	Major Major	Replace Replace		\$0	no sprinkler system
D5020 Lighting and Branch Wiring 100% x None Minor Moderate Major Replace \$0 No observed issues	D3070 Systems Testing & Ba D3090 Other HVAC Systems <u>D40 Fire Protection</u> D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specion	& Equipment NOT USED	None None None	Minor Minor	Moderate Moderate Moderate	Major Major	Replace Replace		\$0	no sprinkler system
	D3070 Systems Testing & Ba D3090 Other HVAC Systems D40 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Special D4090 Other Fire Protection D50 Electrical	& Equipment NOT USED Ities Systems NOT USED	None None None None	Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major	Replace Replace Replace		\$0 \$0	
U5U3U Communications & Security Voice / Data System 100% x None Minor Moderate Major Replace \$0 No observed issues	D3070 Systems Testing & Ba D3090 Other HVAC Systems D4010 Sprinklers D4020 Standpipes D4030 Fire Protection D4090 Other Fire Protection D50 Electrical D5010 Electrical Service & D	& Equipment NOT USED Ilties Systems NOT USED stribution	None None None None None	Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major	Replace Replace Replace Replace		\$0 \$0 \$0	No observed issues
	D3070 Systems Testing & Ba D3090 Other HVAC Systems D40 Fire Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specion D4090 Other Fire Protection D50 Electrical D5010 Electrical Service & D D5020 Lighting and Branch N	& Equipment NOT USED Ilties Systems NOT USED stribution Viring	None None	Minor Minor Minor Minor Minor	Moderate Moderate Moderate Moderate Moderate Moderate Moderate	Major Major Major Major Major	Replace Replace Replace Replace Replace		\$0 \$0 \$0 \$0 \$0	No observed issues No observed issues

		Clock / Intercom System	100% x Nor	Minor		Moderate		Major	$\overline{}$	Replace	- 1	\$0	No observed issues
		Closed Circuit Surveillance	100% X Nor			Moderate		Major		Replace		\$0	140 Observed issues
			Nor			Moderate						\$0	
		Access Control System				Moderate		Major	-	Replace		\$0	Present in the office only
		Intrusion Alarm System			_			Major	_	Replace		\$0	Present in the office only
		Fire Alarm / Detection				Moderate		Major	_	Replace			rresent in the office only
DE	5090 Other Electrical Systems	Lighting Control System NOT USED	Nor Nor			Moderate Moderate		Major		Replace		\$0	
כט	5090 Other Electrical Systems	NOT USED	NOI	Willion		woderate		Major		Replace			
E EQUIPMENT & FUF	PNICHINGS												
E10 Equipme													
	010 Commercial Equipment	Food Service	100% x Nor	e Minor		Moderate		Major	\Box	Replace	T	\$0	kitchen appears in good condition
	010 commercial Equipment	Vocational	Nor			Moderate		Major		Replace		\$0	
F1:	020 Institutional Equipment	Science	Nor			Moderate		Major	_	Replace		\$0	
	ozo montational zquipment	Art	Nor			Moderate		Major	-	Replace		\$0	
		Stage Performance	Nor			Moderate		Major		Replace		\$0	Cost/SF of Stage Performance Area
		Restroom Accessories/Stalls	Nor			Moderate		Major		Replace		\$0	, ,
F1	030 Vehicular Equipment	NOT USED	Nor			Moderate		Major		Replace		, .	
	090 Other Equipment	NOT USED	Nor			Moderate		Major		Replace			
E20 Furnishi					_			.,.		.,			
·	<u> </u>					Г				Γ			Some surfaces and doors present damage and
E2	010 Fixed Furnishings		100% Nor	e x Minor		Moderate		Major		Replace	10%	\$5,047	require replacement.
										•			most furniture is dated, not uniform class-class,
E2	020 Movable Furnishings		100% x Nor	e Minor		Moderate		Major		Replace		\$0	but in decent condition
F SPECIAL CONSTRU	ICTION & DEMOLITION - NOT USED					-					•		
G BUILDING SITE WO	PRK												
G10 Site Pre		NOT USED											
G20 Site Imp										-			
G2	2010 Roadways		10000 Nor	e x Minor		Moderate		Major		Replace	100%	\$17,540	Minor temperature cracking.
													Minor temperature cracking. One graverl parking
G2	2020 Parking Lots		60000 Nor	e Minor		Moderate		Major	х	Replace	45%	\$241,315	lot needs to be asphalt paved.
													Minor-moderate cracking. Large central
	2030 Pedestrian Paving		38000 x Nor			Moderate		Major		Replace		\$0	courtyard, play courts are paved.
	2040 Site Development		2000 x Nor			Moderate		Major		Replace		\$0	
	2050 Landscaping		180000 x Nor	Minor		Moderate	ш	Major	Щ	Replace		\$0	
	chanical Utilities				_				—		-	4-	good condition
G3	8010 Water Supply	Domestic	1 x Nor			Moderate		Major		Replace		\$0	good condition
	1000 5 11 5	Fire	Nor			Moderate		Major		Replace	1000/	\$0	
	3020 Sanitary Sewer		1000 Nor		_	Moderate		Major	Х	Replace	100%	\$50,274	
	8030 Storm Sewer		1 x Nor 1 x Nor			Moderate		Major		Replace		\$0 \$0	gas heat
	8040 Heating Distribution					Moderate Moderate		Major		Replace		\$0 \$0	main building, SPED & Library have AC
	3050 Cooling Distribution 3060 Fuel Distribution		0 x Nor 1 x Nor			Moderate		Major Major		Replace Replace		\$0	main building, 3r LD & Library have AC
		NOT USED										ŞU	
	3090 Other Site Mechanical Utilities ctrical Utilities	NOT USED	Nor	Minor		Moderate		Major		Replace			
	1010 Electrical Distribution	Service	100% x Nor	e Minor		Moderate		Major	$\overline{}$	Replace	- 1	\$0	
04	1010 Electrical Distribution	Generator	Nor			Moderate		Major Major	-	Replace		\$0	
		Generator	INOI	le Willion	-	iviouerate		iviajui		neplace		ŞU	Light poles are needed across the current gravel
G4	1020 Site Lighting		100% x Nor	e Minor		Moderate		Major	v	Replace	25%	\$11,800	parking lot.
	1030 Site Communications & Security		100% x Nor			Moderate		Major		Replace	23/0	\$0	F
	1090 Other Site Electrical Utilities	NOT USED	Nor			Moderate		Major		Replace		Ψ	
	ite Construction	NOT USED	11.01		_	Moderate		ajo.		перисс			
<u>oso otner s</u>	nte construction												
OTHER													
						Unit of							
De	escription of System					Measure		Quantity		Unit Budget		Extended	Notes
Du	ictwork open, exposed through roof (see day	ylight) in boiler room near CR 11	(across from SPED)			square feet		10		250		\$2,500	Repair will require roof and ceiling patches
Scl	hool has its own septic tank. Water runs to a	a pump hpouse that is pumped a	ll around campus, uphilld	, and out to a leach	7 [ļ		Septic system needs replaced; smell is constant,
fie	ld					linear feet		1000		500		\$500,000	original to construction.
												\$0	
												\$0	
					[\$0	
	-									_		\$0	

Physical Condition Budget Sub-Total	\$1,285,290
Budgeted Development Costs	\$488,410
Physical Condition Budget TOTAL	\$1,773,700
Cost with Escalation to June 2023	\$2,022,018
Cost with Escalation to June 2024	\$2,102,898
Cost with Escalation to June 2025	\$2,187,014
Replacement Budget	\$16,616,925

District Name:	Douglas County SD 4
ite Name:	Sunnyslope ES
Building Name:	0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

								LEVEL OF ACTION							
Level 1			Type (as applicable)	% of Building or Number	N	one	Minor		Moderate		Major	Replace as part of Renovation	System or	Automated Budget Estimate	Notes
A SUBS															
	A10 Fou					_	_	_		_					F=
		A1010 Standard Foundations		5%	x Non	_	Minor		Moderate	-	Major	Replace		\$0	Portable building.
		A1020 Special Foundations			Non		Minor		Moderate		Major	Replace		\$0	
		A1030 Slab on Grade		95%	x Non	e	Minor	1	Moderate	Ш	Major	Replace		\$0	
	A20 Base	ement Construction			_	_	_	_		_					
		A2010 Basement Excavation	NOT USED		Non		Minor	_	Moderate		Major	Replace			
		A2020 Basement Walls			Non	e	Minor		Moderate	ш	Major	Replace		\$0	
B SHEL															
	B10 Sup	erstructure						—.		_		-			Dentalda kuildia a
		B1010 Floor Construction	Wood	5%	Non		Minor	-	Moderate		Major	Replace		\$0	Portable building.
			Steel		Non		Minor	-	Moderate		Major	Replace	-	\$0	
		D4020 Daref Comptonetter	Concrete	4000/	Non		Minor	_	Moderate		Major	Replace	-	\$0	
		B1020 Roof Construction	Wood	100%	x Non		Minor		Moderate	-	Major	Replace		\$0	
			Steel	l	Non		Minor		Moderate	$\overline{}$	Major	Replace		\$0 \$0	
	D20 F: +-	olen Forderung	Concrete	l l	Non	e	Minor	,	Moderate	Ш	Major	Replace		ŞU	
	BZU EXLE	rior Enclosure B2010 Exterior Walls	Concrete Formed / Tilt	r - r	Non		Minor	П.	Moderate	П	Major	Replace		\$0	
		B2010 Exterior Walls	Masonry	95%	x Non		Minor	-	Moderate	-	Major		-	\$0	
			Framed w/ Wood Siding	5%	x Non		Minor	-	Moderate	-	Major	x Replace	100%	\$66,932	Cedar shingles are damaged and soft.
			Framed w/Metal Panel	370	Non		Minor	-	Moderate	-	Major	Replace	10070	\$0	ecaar similgres are admaged and sore
			Framed w/Stucco	l l	Non		Minor	-	Moderate		Major	Replace		\$0	
			Framed w/Masonry Veneer		Non		Minor	-	Moderate		Major	Replace		\$0	
		B2020 Exterior Windows	Wood		Non		Minor	-	Moderate	$\overline{}$	Major	Replace		\$0	
		BEGEG Exterior Williams						П	···ouciute	\vdash	.v.ajo.	перисе		ţ.	About 20% of the windows are steel original and
			Aluminum/Steel	100%	Non	ie	Minor	r	Moderate		Major	x Replace	20%	\$104,950	beyond their expected useful life.
			Clad		Non		Minor	-	Moderate		Major	Replace		\$0	
			Curtain Wall		Non	ie	Minor	ı	Moderate		Major	Replace		\$0	
		B2030 Exterior Doors	Wood		Non	ie	Minor	1	Moderate		Major	Replace		\$0	
															Most hardware is obsolete, original to the
			Hollow Metal	36	Non	ie	Minor	r	Moderate	х	Major	Replace	60%	\$31,371	building construction date.
			Storefront		Non	ie	Minor	1	Moderate		Major	Replace		\$0	
	B30 Roo	fing													
															Flashing is damaged on top of the sloped shingle
		B3010 Roof Coverings	Asphalt Shingle	10%	Non	ie	x Minor		Moderate	-	Major	Replace	20%	\$1,417	roof.
			Built-Up	90%	x Non	e	Minor	-	Moderate	-	Major	Replace		\$0	Mod Bit roof installed in 2000 in fair condition.
			Single Ply		Non		Minor	-	Moderate		Major	Replace		\$0	
			Metal		Non		Minor	-	Moderate		Major	Replace		\$0	
			Concrete Tile		Non		Minor	-	Moderate		Major	Replace		\$0	
		B3020 Roof Openings	Skylights	100%	x Non		Minor	_	Moderate		Major	Replace		\$0	
			Access Hatch	1	x Non	e	Minor	1	Moderate		Major	Replace		\$0	
C INTE		rior Construction													
	C10 inte	rior Construction C1010 Partitions	Franced	60%	u Non		Minor		Moderate		Maior	Danlage		\$0	
		C1010 Fai titions	Framed		x Non		Minor Minor		Moderate		Major Major	Replace		\$0	
		C1020 Interior Doors	Masonry Wood	55	Non		Minor		Moderate	-	Major	Replace Replace	50%	\$24,578	Hardware is obsolete and require replacement.
		CIOZO IIILEIIOI DOOIS	Hollow Metal	10	Non		Minor	-	Moderate		Major	Replace	50%	\$4,469	Hardware is obsolete and require replacement.
		C1030 Fittings	NOT USED	10	Non		Minor		Moderate		Major	Replace	3070	ÿ 4 , 4 03	2 2 3000 ictc and require replacement
	C20 Stair				IVOI		14111101	' کے	ouciate			періасе			
		C2010 Stair Construction	Wood	ı	Non	e	Minor	1	Moderate	П	Major	Replace		\$0	Cost/Flight
			Metal	1	x Non		Minor		Moderate	-	Major	Replace		\$0	No observed issues.
			Concrete	i	Non		Minor		Moderate		Major	Replace		\$0	Cost/Flight
		C2020 Stair Finishes	Concrete Fill	1	x Non	e	Minor		Moderate	-	Major	Replace		\$0	No observed issues.
						-		_		_					

	Resilient	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Interior Finishes	Resilient	None	IVIIIIOI	iviouerate	viajui	Replace		3 0	COSTITUENT
C3010 Wall Finishes	Paint on Masonry	80% x None	x Minor	Moderate	Major	Replace	100%	\$94,035	
	Wallboard	15% x None	Minor		Major	Replace		\$0	
	Wainscot	None	Minor	Moderate	Major	Replace		\$0	
	Ceramic Tile	5% x None	Minor	Moderate	Major	Replace		\$0	
C3020 Floor Finishes	Carpet / Soft Surface	30% None	Minor	Moderate	Major	Replace		\$0	Carpets are in good condition.
	Resilient Tile	15% None	Minor	Moderate	Major	x Replace	60%	\$32,115	Portions of the VCT are original and cracked.
	Resilient Sheet	None	Minor		Major	Replace		\$0	
	Polished Concrete	50% None	Minor		Major	Replace		\$0	
	Ceramic Tile	4% None	Minor		Major	Replace		\$0	Ceramic tile and grouting in good condition.
	Liquid Applied	1% None	Minor		Major	x Replace	100%	\$7,404	Located at the mechanical room.
	Wood Sports Floor	None	Minor		Major	Replace		\$0	
C3030 Ceiling Finishes	Wallboard	5% x None	Minor		Major	Replace	450/	\$0	Como tilos ara damagad ar disaalarad
	Lay-In Ceiling Tile	80% None 15% None	x Minor x Minor		Major	Replace	15% 20%	\$6,297 \$1,023	Some tiles are damaged or discolored. Some tiles are damaged or discolored.
	Glued-Up Ceiling Tile		Minor		Major	Replace	20%	\$1,023	Some thes are damaged or discolored.
D SERVICES	Painted Structure	None	IVIIIIVI	Moderate	Major	Replace		\$0	
D10 Conveying									
D1010 Elevators & Lifts		None	Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Walks		None	Minor		Major	Replace		\$0	
D1090 Other Conveying Systems		None	Minor		Major	Replace		\$0	
D20 Plumbing					•	<u> </u>		·	
D2010 Plumbing Fixtures		100% x None	Minor	Moderate	Major	Replace		\$0	
D2020 Domestic Water Distribution		100% None	x Minor	Moderate	Major	Replace	100%	\$64,544	Aged piping that is in need of minor repairs
D2030 Sanitary Waste		100% None	x Minor	Moderate	Major	Replace	100%	\$82,386	Aged sewer that is in need of minor repairs
D2040 Rain Water Drainage		100% x None	Minor	Moderate	Major	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D30 HVAC									
D3010 Energy Supply		100% x None	Minor		Major	Replace		\$0	
D3020 Heat Generating Systems	Boiler	100% x None	Minor		Major	x Replace	50%	\$249,780	Boiler system is at end of useful life.
	Air Handler	100% x None	Minor		Major	Replace		\$0	
	Furnace	None	Minor		Major	Replace		\$0 \$0	
D3030 Cooling Generating Systems	Heat Exchanger Component of air handler	None 100% x None	Minor Minor		Major Major	Replace Replace		\$0	
D3030 C00iiiig Generatiiig Systems	Stand alone chiller	None None	Minor		Major	Replace		\$0	
D3040 Distribution Systems	Ductwork	100% x None	Minor		Major	Replace		\$0	
	Hot water return & supply	None	Minor		Major	Replace		\$0	
D3050 Terminal & Package Units	Above ceiling VAV unit	90% None	Minor		Major	Replace		\$0	
· ·	In-room ventilator unit	10% None	Minor		Major	Replace		\$0	
	In-room radiant unit	10% x None	Minor	Moderate	Major	Replace		\$0	Unit heater in the mechanical room.
D3060 Controls & Instrumentation		100% x None	Minor	Moderate	Major	Replace		\$0	Pneumatic controls with no reported issues.
D3070 Systems Testing & Balancing		100% x None	Minor	Moderate	Major	Replace		\$0	
D3090 Other HVAC Systems & Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
<u>D40 Fire Protection</u>			_						
D4010 Sprinklers		None	Minor		Major	Replace		\$0	
D4020 Standpipes		None	Minor		Major	Replace		\$0	
D4030 Fire Protection Specialties	NOTUSES	None	Minor		Major	Replace		\$0	
D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D50 Electrical		100% x None	Minor	Moderate	Major	Replace		\$0	
D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring		100% x None	Minor		Major Major	Replace		\$0	
D5030 Communications & Security	Voice / Data System	100% x None	Minor		Major	Replace		\$0	
	Clock / Intercom System	100% x None	Minor		Major	Replace		\$0	
	Closed Circuit Surveillance	100% x None	Minor		Major	Replace		\$0	
	Access Control System	None	Minor		Major	Replace		\$0	
	Intrusion Alarm System	100% x None	Minor		Major	Replace		\$0	
	Fire Alarm / Detection	100% x None	Minor	Moderate N	Major	Replace		\$0	
	Lighting Control System	None	Minor	Moderate	Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Major	Replace			

E EQUIPMENT & FURNISHINGS

E10 Equipment										
E1010 Commercial Equipment	Food Service	100% x None	Minor	Mode	erate	Major	Replace		\$0	
	Vocational	None	Minor	Mode		Major	Replace		\$0	
E1020 Institutional Equipment	Science	None	Minor	Mode		Major	Replace		\$0	
	Art	None	Minor	Mode		Major	Replace		\$0	
	Stage Performance	None	Minor	Mode		Major	Replace		\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	100% x None	Minor	Mode		Major	Replace		\$0	_
E1030 Vehicular Equipment	NOT USED	None	Minor	Mode		Major	Replace			
E1090 Other Equipment	NOT USED	None	Minor	Mode		Major	Replace			
E20 Furnishings					_					
										Some surfaces and doors present damage and
E2010 Fixed Furnishings		100% None	Minor	x Mode	erate	Major	Replace	80%	\$98,653	require replacement.
E2020 Movable Furnishings		100% x None	Minor	Mode	erate	Major	Replace		\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED		•								
G BUILDING SITE WORK	NOT USED									
G10 Site Preparation G20 Site Improvements	MOT OPEN									
		6200 None	x Minor	Mode	orato	Major	Replace	100%	\$10,875	Minor temperature cracking.
G2010 Roadways G2020 Parking Lots		51756 None	x Minor	Mode		Major	Replace	100%	\$10,875	Minor temperature cracking. Minor temperature cracking.
G2030 Pedestrian Paving		3500 x None	Minor	Mode		Major	Replace	100%	\$90,780	No observed issues.
G2040 Site Development		600 x None	Minor	Mode	_	Major	Replace		\$0	No observed issues.
G2050 Landscaping		10000 x None	Minor		erate	Major	Replace		\$0	No observed issues.
G30 Site Mechanical Utilities		10000 X None	Willion	IVIOUC	crute	iviajoi	перисе		70	No observed issues.
G3010 Water Supply	Domestic	100 x None	Minor	Mode	erate	Major	Replace		\$0	
	Fire	None	Minor	Mode		Major	Replace		\$0	
G3020 Sanitary Sewer		100 x None	Minor	Mode		Major	Replace		\$0	
G3030 Storm Sewer		100 x None	Minor	Mode	erate	Major	Replace		\$0	
G3040 Heating Distribution		None	Minor	Mode	erate	Major	Replace		\$0	
G3050 Cooling Distribution		None	Minor	Mode	erate	Major	Replace		\$0	
G3060 Fuel Distribution		100 x None	Minor	Mode	erate	Major	Replace		\$0	
G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Mode	erate	Major	Replace			
G40 Site Electrical Utilities			_							
G4010 Electrical Distribution	Service	100% x None	Minor	Mode	erate	Major	Replace		\$0	
	Generator	None	Minor	Mode		Major	Replace		\$0	
G4020 Site Lighting		100% x None	Minor	Mode		Major	Replace		\$0	
G4030 Site Communications & Security		None	Minor	Mode		Major	Replace		\$0	
G4090 Other Site Electrical Utilities	NOT USED	None	Minor	Mode	erate	Major	Replace			
G90 Other Site Construction	NOT USED									
OTHER										
5 <u>.</u>				Uni	it of					
Description of System					asure	Quantity	Unit Budget		Extended	Notes
									\$0	
				1				ľ	\$0	
									\$0	
									\$0	
									\$0	
								[\$0	
									\$0	

Physical Condition Budget Sub-Total	\$971,609
Budgeted Development Costs	\$369,211
Physical Condition Budget TOTAL	\$1,340,820
Cost with Escalation to June 2023	\$1,528,535
Cost with Escalation to June 2024	\$1,589,676
Cost with Escalation to June 2025	\$1,653,263
Replacement Budget	\$24,015,291

 District Name:
 Douglas County SD 4

 Site Name:
 Winchester ES

 Building Name:
 Main

19912772123

Building ID:

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

					LEVEL OF ACTION										
Level 1			Type (as applicable)	% of Building or Number		None	Minor		Moderate		Major	Replace as part of Renovation	% of System or Finish	Automated Budget Estimate	Notes
A SUBST															
4	A10 Four						_								T
		A1010 Standard Foundations		100%	x No	_	Minor		Moderate		Major	Replace		\$0	Wood spread footers - no observed issues
		A1020 Special Foundations			o No		Minor		Moderate		Major	Replace		\$0	
		A1030 Slab on Grade			o No	ne	Minor		Moderate	Ш	Major	Replace		\$0	
	A20 Base	ment Construction				_		_		_	ı,				
		A2010 Basement Excavation	NOT USED		No	ne	Minor		Moderate		Major	Replace			
															Building C and D have a basement, no observed
		A2020 Basement Walls		30%	x No	ne	Minor	ш	Moderate	ш	Major	Replace		\$0	issues
B SHELL															
!	B10 Supe	erstructure P1010 Floor Construction	Weed	1000/								Donales e		ćo	No observed issues
			Wood	100%	x No		Minor		Moderate		Major	Replace		\$0	No observed issues
			Steel		o No		Minor		Moderate		Major	Replace		\$0 \$0	
			Concrete	1000/	o No		Minor		Moderate		Major	Replace			No observed issues
			Wood	100%	x No		Minor Minor		Moderate		Major	Replace		\$0 \$0	NO Observed issues
			Steel		o No				Moderate	\vdash	Major	Replace			
	DOO Futo		Concrete		o No	ne	Minor		Moderate	ш	Major	Replace		\$0	
	bzu Exte	rior Enclosure B2010 Exterior Walls	Consests Formed / Tilt		o No		Minor		Madarata		Maior	Danlage		\$0	Г
			Concrete Formed / Tilt Masonry	2%	x No		Minor Minor	_	Moderate Moderate	\vdash	Major Major	Replace Replace		\$0	All masonry walls were in good shape
			ividsoffry	270	X NO	ne	IVIIIIOI		woderate	\vdash	iviajor	керіасе		\$0	All Hasoniy walls were in good shape
															Minor painting needed on 7 of the buildings. The
			Framed w/ Wood Siding	98%	No	no	Minor		Moderate		Major	Replace	9%	\$13,145	gym had some panels that need to be replaced.
			Framed w/Metal Panel	3870	No		Minor	^	Moderate		Major	Replace	370	\$13,143	gym nad some panels that need to be replaced.
			Framed w/Stucco		o No		Minor	\vdash	Moderate	\vdash	Major	Replace		\$0	
			Framed w/Masonry Veneer		o No		Minor		Moderate		Major	Replace		\$0	
			Wood	12%	No		Minor	-	Moderate	_	Major	Replace	100%	\$28,079	
			Aluminum/Steel	88%	_	ne	Minor	$\overline{}$	Moderate	^	Major	Replace	11%	\$12,641	
			Clad	0070	o No		Minor	_	Moderate		Major	Replace	11/0	\$0	
			Curtain Wall		o No		Minor		Moderate		Major	Replace		\$0	
			Wood	24	No		Minor	\vdash	Moderate	_	Major	Replace	8%	\$3,218	
			Hollow Metal	41	x No		Minor		Moderate	Ĥ	Major	Replace	070	\$0	
			Storefront		o No		Minor	-	Moderate	Н	Major	Replace		\$0	
	B30 Root									ш,	,			**	
		<u></u>			П		7								All covered walkways have major ponding / leaks
															and need to be replaced. Issues observed on
															multiple roofs - cost adjusted up to provide a
		B3010 Roof Coverings	Asphalt Shingle	35%	No	ne	Minor		Moderate		Major	x Replace	75%	\$191,153	more accurate estimate
			Built-Up	65%	x No	ne	Minor		Moderate		Major	Replace		\$0	No observed issues
			Single Ply		o No	ne	Minor		Moderate		Major	Replace		\$0	
			Metal		o No	ne	Minor		Moderate		Major	Replace		\$0	
			Concrete Tile		o No	ne	Minor		Moderate		Major	Replace		\$0	
		B3020 Roof Openings	Skylights		o No	ne	Minor		Moderate		Major	Replace		\$0	By Building GSF
			Access Hatch		o No	ne	Minor		Moderate		Major	Replace		\$0	Per hatch
C INTER	IORS			_			_					<u> </u>			
9	C10 Inter	ior Construction				_	_								
		C1010 Partitions	Framed	97%	x No		Minor		Moderate		Major	Replace		\$0	No observed issues
			Masonry	3%	x No	ne	Minor		Moderate	\Box	Major	Replace		\$0	No observed issues
												1 1			All interior wood doors were in functioning
		C1020 Interior Doors	Wood	48	x No	ne	Minor		Moderate	Ш	Major	Replace		\$0	properly
														40	All interior metal doors were in good operating
			Hollow Metal	7	x No		Minor		Moderate		Major	Replace		\$0	order
		C1030 Fittings	NOT USED		No	ne	Minor		Moderate		Major	Replace			

C20 Stairs					_				All
C2010 Stair Construction	Wood	1 x None	Minor	Moderate	Major	Replace		\$0	All stairs were in good condition with no observed structural integrity issues
C2010 Stall Collstituction							\vdash		Cost/Flight
	Metal	o None	Minor	Moderate	Major	Replace	\vdash	\$0	Cost/Flight
00000 01 1 51 1 1	Concrete	o None	Minor	Moderate	Major	Replace	_	\$0	
C2020 Stair Finishes	Concrete Fill	o None	Minor	Moderate	Major	Replace	\vdash	\$0	Cost/Flight
C30 Interior Finishes	Resilient	1 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
C3010 Wall Finishes	Paint on Masonry	1% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	•							•	Moderate patch and paint was needed
	Wallboard	97% None	Minor	x Moderate	Major	Replace	11%	\$12,743	throughout
	Wainscot	o None	Minor	Moderate	Major	Replace		\$0	
									Minor grout damage noted in boys restroom -
	Ceramic Tile	2% None	x Minor	Moderate	Major	Replace	50%	\$437	cost adjusted up reflect more accurate costs
									Carpet is severely worn in small spots
									throughout. Major areas that need to be replace
									include the Library / Media center and offices
C3020 Floor Finishes	Carpet / Soft Surface	37% None	Minor	Moderate	Major	x Replace	21%	\$25,198	next to that area.
									There were several spots throughout where the
									majority of the space needed to be replaced -
	Resilient Tile	50% None	Minor	Moderate	x Major	Replace	18%	\$20,797	mainly in the cafeteria and a few classrooms.
									Minimal replacement needed in a classroom and
	Resilient Sheet	3% None	Minor	Moderate	Major	x Replace	16%	\$2,796	the kitchen
									Damaged surface in custodian closets, boiler
	Polished Concrete	7% None	x Minor	Moderate	Major	Replace	22%	\$1,510	rooms and storage areas.
	Ceramic Tile	3% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Liquid Applied	o None	Minor	Moderate	Major	Replace		\$0	
	Wood Sports Floor	o None	Minor	Moderate	Major	Replace		\$0	
									Patch and paint needed primarily in the gym are
C3030 Ceiling Finishes	Wallboard	22% None	Minor	x Moderate	Major	Replace	26%	\$19,438	(wood paneling).
	Lay-In Ceiling Tile	54% None	x Minor	Moderate	Major	Replace	7%	\$1,835	Stained and damaged tiles observed throughout
	, segs		H-1			H		7-/	Small portion of glue up tiles damaged in 4
	Glued-Up Ceiling Tile	23% None	x Minor	Moderate	Major	Replace	5%	\$363	different areas.
	Painted Structure	o None	Minor	Moderate	Major	Replace		\$0	
SERVICES									
D10 Conveying									
D1010 Elevators & Lifts		o None	Minor	Moderate	Major	Replace		\$0	
D1020 Escalators & Moving Walks		o None	Minor	Moderate	Major	Replace		\$0	
D1090 Other Conveying Systems		o None	Minor	Moderate	Major	Replace		\$0	
D20 Plumbing					_				<u> </u>
D2010 Plumbing Fixtures		100% None	Minor	x Moderate	Major	Replace	2%	\$1,203	2 of 113 fixtures were not functioning.
									A majority of the system is beyond its useful life
D2020 Domestic Water Distribution		100% None	Minor	Moderate	Major	x Replace	80%	\$282,737	and should be replaced
									A majority of the system is beyond its useful life
D2030 Sanitary Waste		100% None	Minor	Moderate	Major	x Replace	80%	\$80,394	and should be replaced
D2040 Rain Water Drainage		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D30 HVAC						_	-		
D3010 Energy Supply		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D3020 Heat Generating Systems	Boiler	50% x None	Minor	Moderate	Major	Replace		\$0	Main building - no issues observed.
	Air Handler	50% x None	Minor	Moderate	Major	Replace		\$0	Modulars - no issues noted.
	Furnace	o None	Minor	Moderate	Major	Replace		\$0	
	Heat Exchanger	o None	Minor	Moderate	Major	Replace		\$0	
D3030 Cooling Generating Systems	Component of air handler	50% x None	Minor	Moderate	Major	Replace		\$0	Half of the buildings have cooling
5 5,	Stand alone chiller	o None	Minor	Moderate	Major	Replace		\$0	
D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Hot water return & supply	100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
D3050 Terminal & Package Units	Above ceiling VAV unit	o None	Minor	Moderate	Major	Replace		\$0	
	In-room ventilator unit	75% None	Minor	Moderate	Major	Replace		\$0	
	In-room radiant unit	75% None	Minor	Moderate	Major	Replace	H +	\$0	

D3060 Controls & Instrumentation		100% None	Minor	Moderate Major	x Replace	100%	\$130,591	The system is obsolete and experiencing some issues across the facility. Nuematic controls are not functioning properly.
D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment	NOT USED	100% x None None	Minor Minor	Moderate Major Moderate Major	Replace Replace		\$0	No observed issues
D40 Fire Protection	NOT OSED	None	Willion	Widerate	Керіасе			
D4010 Sprinklers		o None	Minor	Moderate	Replace		\$0	
D4020 Standpipes		o None	Minor	Moderate	Replace		\$0	
D4030 Fire Protection Specialties		o None	Minor	Moderate	Replace		\$0	
D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate	Replace			
D50 Electrical		1000/			- Paralana	_	ćo	No observed issues
D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring		100% x None 100% x None	Minor Minor	Moderate Major Moderate Major	Replace Replace	-	\$0 \$0	No observed issues No observed issues
D5030 Communications & Security	Voice / Data System	100% x None	Minor	Moderate Major	Replace		\$0 \$0	No observed issues
23030 communications & Security	Clock / Intercom System	100% X None	Minor	Moderate Major	Replace		\$0	No observed issues
	Closed Circuit Surveillance	100% None	Minor	Moderate Major	Replace		\$0	No observed issues
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	
	Intrusion Alarm System	25% x None	Minor	Moderate Major	Replace		\$0	Admin and IT areas, No observed issues
	Fire Alarm / Detection	100% None	Minor	Moderate Major	x Replace	100%	\$103,405	New system needs to be installed
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Replace			
E EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	o None	Minor	Moderate Major	Replace		\$0	
	Art	o None	Minor	Moderate Major	Replace		\$0	
	Stage Performance	o None	Minor	Moderate Major	Replace		\$0	Cost/SF of Stage Performance Area
								3 stall doors are not functioning properly in girls restroom and do not meet ADA. ADA not being
	Restroom Accessories/Stalls	100% None	Minor	x Moderate Major	Replace	10%	\$6,165	met in boys restroom.
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate Major	Replace	2070	V 0,203	,.
E1090 Other Equipment	NOT USED	None	Minor	Moderate Major	Replace			
E20 Furnishings			_					
								Casework is worn in various areas - mainly in
E2010 Fixed Furnishings		100% None	Minor	x Moderate Major	Replace	25%	\$28,521	classrooms.
E2020 Movable Furnishings		100% None	Minor	Moderate	x Replace	1%	\$11,651	Outdated furniture needed in 1 classroom.
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED								
G BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements			_					
G2010 Roadways		2470 None	x Minor	Moderate Major	Replace	5%	\$217	Minor cracking on roadways
G2020 Parking Lots		26220 None	x Minor	Moderate Major	Replace	25%	\$11,497	Minor cracks observed in parking lot areas
G2030 Pedestrian Paving		53838 None	Minor	Moderate x Major	Replace	30%	\$162,399	Multiple sections of the pedestrian walkway are damaged and need to be replaced
G2040 Site Development		2229 x None	Minor	Moderate X Major	Replace	30%	\$102,333	No observed issues
G2050 Landscaping		164329 x None	Minor	Moderate Major	Replace		\$0	Entire site is irrigated, no observed issues
G30 Site Mechanical Utilities					Ш "			g,
								Finding rust in system when it gets turned off and
G3010 Water Supply	Domestic	700 None	Minor	Moderate	x Replace	75%	\$38,124	turned back on
	Fire	o None	Minor	Moderate	Replace		\$0	
		I I I					4	A majority of the system is beyond its useful life
G3020 Sanitary Sewer		1000 None	Minor	Moderate Major	x Replace	75%	\$37,706 \$0	and should be replaced No observed issues
G3030 Storm Sewer G3040 Heating Distribution		1 x None 1 x None	Minor	Moderate Major Moderate Major	Replace Replace		\$0	No observed issues
G3050 Cooling Distribution		1 x None	Minor	Moderate Major	Replace		\$0	No observed issues
G3060 Fuel Distribution		1 x None	Minor	Moderate Major	Replace		\$0	No observed issues
G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Moderate Major	Replace			·
G40 Site Electrical Utilities								
G4010 Electrical Distribution	Service	100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
	Generator	o None	Minor	Moderate Major	Replace		\$0	

0	54020 Site Lighting 54030 Site Communications & Security 54090 Other Site Electrical Utilities Site Construction	NOT USED NOT USED	100% None 100% x None None	Minor Minor Minor	Moderate Moderate Moderate	Major Major Major		Replace Replace Replace	10%	1 - 7 -	Some lights were non functional No observed issues
OTHER											
	Description of System				Unit of Measure	Quantity		Unit Budget		Extended	Notes
										\$0	
										\$0 \$0	
										\$0 \$0 \$0	
							-			\$0 \$0 \$0 \$0	
							-			\$0 \$0 \$0 \$0 \$0	
										\$0 \$0 \$0 \$0 \$0 \$0	

Physical Condition Budget Sub-Total	\$1,231,507
Budgeted Development Costs	\$467,973
Physical Condition Budget TOTAL	\$1,699,480
Cost with Escalation to June 2023	\$1,937,407
Cost with Escalation to June 2024	\$2,014,904
Cost with Escalation to June 2025	\$2,095,500
Replacement Budget	\$22,217,596

 District Name:
 Douglas County SD 4

 Site Name:
 John C Fremont MS

 Building Name:
 Main

19912782162

Building ID:

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

			LEVEL OF ACTION													
												Replac		% of		
		_ ,,	% of Building									part		System or	Automated Budget	
Level 1 Level 2		Type (as applicable)	or Number		None		Minor		Moderate	<u> </u>	Major	Renova	ition	Finish	Estimate	Notes
A SUBSTRUCTU																
ATO FOL	undations A1010 Standard Foundations				None		Minor		Moderate		Major	Replace	. г		\$0	_
	A1010 Standard Foundations A1020 Special Foundations				None		Minor		Moderate		Major	Replace			\$0	
	A1020 Special Foundations			Ŭ	None		IVIIIIOI		Wioderate		iviajoi	перисс	•		70	Boys restroom in building B is sunk down in far
	A1030 Slab on Grade		100%		None		Minor		Moderate	x	Major	Replace		1%	\$30,416	corner
A20 Bas	sement Construction												L		, , ,	
-	A2010 Basement Excavation	NOT USED			None		Minor		Moderate		Major	Replace				
	A2020 Basement Walls				None		Minor		Moderate		Major	Replace			\$0	
B SHELL									•		,					
B10 Sup	<u>perstructure</u>															
	B1010 Floor Construction	Wood			None		Minor		Moderate		Major	Replace			\$0	
		Steel			None		Minor		Moderate		Major	Replace			\$0	
		Concrete	100%	_	None		Minor		Moderate		Major	Replace			\$0	No observed issues
	B1020 Roof Construction	Wood	100%		None		Minor		Moderate		Major	Replace			\$0	No observed issues
		Steel		_	None		Minor		Moderate		Major	Replace			\$0	
		Concrete		0	None		Minor		Moderate		Major	Replace	· [\$0	
B20 Ext	erior Enclosure				ì		i .	_	1 .	_	7					
	B2010 Exterior Walls	Concrete Formed / Tilt	66%		None		Minor	х			Major	Replace		22%	\$54,163	Paint needed on the all exterior concrete walls
		Masonry		0	None		Minor		Moderate		Major	Replace			\$0	
																Replacement of metal panels is needed.
		Franced / Wood Siding	2.40/		Nana		Minor		Madarata		Maior	Donloos		25%	ĆEC 700	Degrading across several sections of the facility.
		Framed w/ Wood Siding Framed w/Metal Panel	34%		None None		Minor		Moderate Moderate	Х	Major Major	Replace Replace		25%	\$56,780 \$0	Patch and paint needed in multiple areas
		Framed w/Stucco			None		Minor		Moderate		Major	Replace			\$0	rateriana paint needed in multiple areas
		Framed w/Masonry Veneer		_	None		Minor		Moderate		Major	Replace			\$0	
		Framed W/Wasoni y Veneer		U	None		IVIIIIOI		Moderate		iviajui	Neplace	· -		ŞÜ	All 5 single pane wood windows need to be
	B2020 Exterior Windows	Wood	1%		None		Minor		Moderate	х	Major	Replace		100%	\$2,877	replaced
	BEDEG Exterior Williams		270						moderate		iviajo.	Перис	ŀ	10070	ψ2,077	89 of the 960 aluminum / steel windows are
																single pane, fogged, or have damaged
																sashes/frames that need to be repaired or
		Aluminum/Steel	99%		None		Minor		Moderate		Major	x Replace		9%	\$102,762	replaced
		Clad		0	None		Minor		Moderate		Major	Replace	. [\$0	
		Curtain Wall		0	None		Minor		Moderate		Major	Replace	. [\$0	
	B2030 Exterior Doors	Wood	2	х	None		Minor		Moderate		Major	Replace	٠ [\$0	All exterior wood doors are in good condition
																A door on the east side of building C needs to be
		Hollow Metal	64		None		Minor		Moderate	х	Major	Replace		2%	\$1,859	replaced - door and hardware only
		Storefront		0	None		Minor		Moderate		Major	Replace	L		\$0	
<u>B30 Roc</u>	ofing		_			_		_	-	_	7	_				
																Minor damage on buildings F, J, H, B, G, & I -
																Major damage on building A South walkway needs to be replaced - major
																ponding and damaged torch down - cost adjusted
	B3010 Roof Coverings	Asphalt Shingle	96%		None		Minor		Moderate		Major	x Replace	.	15%	\$247,143	up to reflect more accurate estimate
		Built-Up	50%		None	H	Minor		Moderate	Н	Major	Replace		1370	\$0	
		Single Ply	4%		None	H	Minor		Moderate		Major	Replace			\$0	No observed issues
		Metal			None		Minor		Moderate		Major	Replace		<u> </u>	\$0	
		Concrete Tile		_	None		Minor		Moderate		Major	Replace		t	\$0	
	B3020 Roof Openings	Skylights			None		Minor		Moderate		Major	Replace			\$0	By Building GSF
		Access Hatch		0	None		Minor		Moderate		Major	Replace		Ì	\$0	Per hatch
C INTERIORS									•		•					

C10 Interior Construction

				_							
	C1010 Partitions	Framed	78%	x None	Minor	Moderate	Major	Replace		\$0	One crack observed above a door in a classroom
	0101010101010	Masonry		x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	C1020 Interior Doors	Wood		x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	didio michor books	Hollow Metal	81	None	Minor	Moderate	x Major	Replace	1%	\$995	One door was damaged that needs new glass
	C1030 Fittings	NOT USED	01	None	Minor	Moderate	Major	Replace	170	ψσσσ	g and a good and a good
C20 Sta						moderate	Major	періасс			-
	C2010 Stair Construction	Wood		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
		Metal		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
		Concrete		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	C2020 Stair Finishes	Concrete Fill		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
		Resilient		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Inte	erior Finishes									·	_
	C3010 Wall Finishes	Paint on Masonry	21%	None	x Minor	Moderate	Major	Replace	26%	\$13,770	Paint needed in multiple areas - buildings F & J
											Patch and paint needed in numerous areas
		Wallboard	77%	None	Minor	x Moderate	Major	Replace	12%	\$26,225	throughout
		Wainscot	1%	x None	Minor	Moderate	Major	Replace		\$0	No observed issues
											Minor grout damage in two restrooms - cost
		Ceramic Tile	2%	None	x Minor	Moderate	Major	Replace	3%	\$63	adjusted up
											Worn carpet in weight room, library and faculty
	C3020 Floor Finishes	Carpet / Soft Surface	12%	None	Minor	Moderate	Major	x Replace	7%	\$6,440	room
											Sporadic lifting and cracked tiles throughout -
											some very large cracks across entire floor in
											building E - floor is shrinking and swelling - some rooms need all tile replaced. Several sections
		Resilient Tile	58%	None	Minor	Moderate	Major	x Replace	40%	\$181,072	have ACT flooring.
		Resilient Sheet	9%	None	Minor	Moderate	Major	x Replace	2%	\$2,479	Minor damage observed in three areas
		Polished Concrete	8%	None	x Minor	Moderate	Major	Replace	23%	\$4,266	Minor damage observed in four areas
		rollshed concrete	870	None	_ IVIIIIOI	Wioderate	iviajoi	Періасе	23/6	Ş4,200	Tile needs repair in two restrooms and in girls
		Ceramic Tile	4%	None	Minor	Moderate	Major	x Replace	7%	\$8,079	locker room
		Liquid Applied		o None	Minor	Moderate	Major	Replace	770	\$0	
		Wood Sports Floor	7%	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	C3030 Ceiling Finishes	Wallboard	15%	None	x Minor	Moderate	Major	Replace	4%	\$2,162	Minor paint needed in a few rooms
	5	Lay-In Ceiling Tile	6%	None	x Minor	Moderate	Major	Replace	10%	\$689	Water stained tiles found in four rooms
		, ,						H '			Water damage found in multiple areas. Sagging
											and bulging tiles found in multiple areas. Major
		Glued-Up Ceiling Tile	77%	None	x Minor	Moderate	Major	Replace	7%	\$4,021	water damage in north hallway.
		Painted Structure		o None	Minor	Moderate	Major	Replace		\$0	
D SERVICES											
D10 Co											
	D1010 Elevators & Lifts			None	Minor	Moderate	Major	Replace		\$0	
	D1020 Escalators & Moving Walks			None	Minor	Moderate	Major	Replace		\$0	
	D1090 Other Conveying Systems			None	Minor	Moderate	Major	Replace		\$0	
D20 Plu	mbing			_			_				240 first and a second all and all areas in a second
						1 1		I L .			210 fixtures were counted and all were in good
	D2010 Plumbing Fixtures		100%	x None	Minor	Moderate	Major	Replace		\$0	working order
	D2020 Daniel Water Distribution		4000/			NA		Davida	65%	\$543,123	A majority of the system is beyond its useful life and should be replaced
	D2020 Domestic Water Distribution		100%	None	Minor	Moderate	Major	x Replace	05%	\$545,125	A majority of the system is beyond its useful life
	D2030 Sanitary Waste		100%	None	Minor	Moderate	Major	x Replace	65%	\$154,432	and should be replaced
	D2040 Rain Water Drainage			o None	Minor	Moderate	Major	Replace	0376	\$0	and should be replaced
	D2090 Other Plumbing Systems	NOT USED		None	Minor	Moderate	Major	Replace		γo	
D30 HV						moderate	Major	періасс			
	D3010 Energy Supply		100%	x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	<i>5.</i>							H '		·	3 boilers - no observed issues. Starting to have
				1							failure issues over the last year. Minor repairs
	D3020 Heat Generating Systems	Boiler	100%	x None	x Minor	Moderate	Major	Replace	25%	\$57,962	needed.
		Air Handler		o None	Minor	Moderate	Major	Replace		\$0	
		Furnace		o None	Minor	Moderate	Major	Replace		\$0	
		Heat Exchanger		o None	Minor	Moderate	Major	Replace		\$0	
	D3030 Cooling Generating Systems	Component of air handler		o None	Minor	Moderate	Major	Replace		\$0	
		Stand alone chiller		x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	D3040 Distribution Systems	Ductwork	100%	x None	Minor	Moderate	Major	Replace		\$0	No observed issues

	Hot water return & supply	100% X	None	Minor	Moderate	Major	Replace		\$0	NO observed issues
D3050 Terminal & Package Units	Above ceiling VAV unit	0	None	Minor	Moderate	Major	Replace		\$0	
	In-room ventilator unit		None	Minor	Moderate	Major	Replace	1	\$0	
	In-room radiant unit								\$0	
	III-room radiant unit	0	None	Minor	Moderate	Major	Replace	\vdash	ŞU	Contain has need as because and manda to be
										System has major issues and needs to be
D3060 Controls & Instrumentation		100%	None	Minor	Moderate	Major	x Replace	100%	\$308,749	replaced
										Complaints from staff of major issues depending
										on the time of year - building E on the west side -
D3070 Systems Testing & Balancing		100%	None	Minor	Moderate	Major	x Replace	20%	\$33,515	heat trap issues with classrooms at 90+ degrees
	NOT USED	10070		Minor				2070	755,515	
D3090 Other HVAC Systems & Equipment	NOT USED		None	IVIIIIOI	Moderate	Major	Replace			
<u>D40 Fire Protection</u>				_	_					
										Issues observed with dry system that leaks during
D4010 Sprinklers		100%	None	Minor	Moderate	Major	x Replace	50%	\$208,894	its yearly test
D4020 Standpipes		100% x	None	Minor	Moderate	Major	Replace		\$0	No observed issues
D4030 Fire Protection Specialties		0		Minor	Moderate	Major	Replace	—	\$0	
	NOTUSES	0							ŞŪ	
D4090 Other Fire Protection Systems	NOT USED		None	Minor	Moderate	Major	Replace			
D50 Electrical			_							
										Electrical system needs to be upgraded. Full and
D5010 Electrical Service & Distribution		100% x	None	Minor	Moderate	x Major	Replace	25%	\$179,912	outdated based on campus needs.
						\rightarrow	H ''		,-	8 light fixtures in the kitchen are damaged or not
DECCO Links and Broad Wining		4000/	Maria				Davidson.	10/	ć7.600	working
D5020 Lighting and Branch Wiring		100%	None	Minor	Moderate	x Major	Replace	1%	\$7,688	_
D5030 Communications & Security	Voice / Data System	100% x	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Clock / Intercom System	100%	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Closed Circuit Surveillance	100%	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Access Control System		None	Minor	Moderate	Major	Replace	1	\$0	
								-		Admin and IT areas - No observed issues
	Intrusion Alarm System	20% x	None	Minor	Moderate	Major	Replace		\$0	
										System is beyond its useful life and should be
	Fire Alarm / Detection	100%	None	Minor	Moderate	Major	x Replace	100%	\$244,474	replaced - cost adjusted down
	Lighting Control System	20% x	None	Minor	Moderate	Major	Replace		\$0	Exterior lighting sensors - No observed issues
D5090 Other Electrical Systems	NOT USED		None	Minor	Moderate		Replace			
55050 Galet Electrical Systems					Moderate	ajo:	перисс			
E EQUIPMENT & FURNISHINGS										
E10 Equipment			_							
										No observed issues - staff complained about
E1010 Commercial Equipment	Food Service	100% x	None	Minor	Moderate	Major	Replace		\$0	warming rack not working very well
1.1.	Vocational	0	None	Minor	Moderate	Major	Replace	1	\$0	
54000 L. W. W. LE. L								-		No observed issues
E1020 Institutional Equipment	Science	7800 x	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Art	4474 x	None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Stage Performance	0	None	Minor	Moderate	Major	Replace		\$0	
	Restroom Accessories/Stalls	100%	None	Minor	Moderate	x Major	Replace	3.00%	\$1,343	One stall is damaged in boys locker room
E1030 Vehicular Equipment	NOT USED	100%	None	Minor		Major	Replace	5.0070	ψ1,5 i5	
					Moderate					
E1090 Other Equipment	NOT USED		None	Minor	Moderate	Major	Replace			<u></u>
E20 Furnishings			_							
										Some lockers are beyond their useful life,
										casework in a few classrooms is damaged and
E2010 Fixed Furnishings		100%	None	Minor	Moderate	Major	x Replace	100%	\$1,069,718	worn, gym bleachers are worn and damaged
LZOTO FIXEU FUTILISTINIGS		10076	None	IVIIIIOI	Wioderate	iviajoi	x Replace	100%	\$1,005,710	
										Desks in one classroom are beyond their useful
E2020 Movable Furnishings		100%	None	Minor	Moderate	Major	x Replace	1%	\$27,546	life
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED										
G BUILDING SITE WORK										
G10 Site Preparation	NOT USED									
	NOT OSED									
G20 Site Improvements										
G2010 Roadways		3040	None	x Minor	Moderate	Major	Replace	5%	\$267	Minor cracks on north roadway - cost adjusted up
•			1	П		\Box				
						1 1				Cracks and alligatoring found in all parking areas
C2020 Paylin - 1 - +-		41460	New-		N 4		D 1	200/	600.340	East parking lot is in rough shape
G2020 Parking Lots		41468	None	Minor	Moderate	x Major	Replace	30%	\$90,340	
			1			1 1	1 1			Broken and cracked sections of pedestrian
G2030 Pedestrian Paving		40851	None	Minor	Moderate	x Major	Replace	14%	\$57,505	pavement found around entire site
G2040 Site Development		173 x	None	Minor	Moderate	Major	Replace		\$0	No observed issues
G2050 Landscaping			None	Minor	Moderate		Replace		\$0	Entire site is irrigated - No observed issues
G2030 Lunuscaping		373003 X	.40116	WIIIIOI	wioderate	iviajoi	періасе		γu	

G3010 Water Supply Domestic 1800	G30 Site Mechanical Utilities						_		_		_			
Fire 4000 None Minor Moderate Major X Replace 50% \$145,236 of replacement. G3020 Sanitary Sewer 2400 None Minor G3304 Orderate Major X Replace Major Moderate Major Moderate Major Replace Major Replace Major Moderate Major Replace Major Moderate Major Replace Major Replace Major Replace Major Replace Major Moderate Major Replace Major Replace Major Replace Major Moderate Major Replace S0 No observed issues Major Moderate Major Replace S0 No observed issues S0 Moderate Major Replace S0 No No observed issues S0 Moderate Major Replace S0 No No observed issues S0 Moderate Major S0 No														Beyond useful life. Needs repairs and/or sections
Fire 4000 None Minor Moderate Major x Replace 50% \$145,236 of replacement. G3020 Sanitary Sewer 2400 None Minor Moderate G3030 Storm Sewer 100 x None Minor G3030 Storm Sewer 100 x None Minor G3030 Storm Sewer 100 x None Minor G3030 Cooling Distribution 100 x None Minor Moderate Major Replace 50 Enter £ of heating ducts in cell £147 moderate Major Replace 50 Enter £ of duct work in cell £148 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Enter £ of heating ducts in cell £149 moderate Major Replace 50 Moderate Major Replace 50 No observed issues 50 Moderate Major Settle £ observed for the first firs	G3010 Water Supply	Domestic	1800	None	Minor		Moderate	r	∕lajor	x R	eplace	75%	\$98,034	•
G3020 Sanitary Sewer G3030 Storm Sewer G3030 Storm Sewer G3040 Heating Distribution G3040 Heating Distribution G3050 Cooling Distribution G3060 Fall D														
G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Full Lighting G3050 Full Lighting G4020 Site Lighting G4020 Site Lighting G4030 Site Communications & Security G4030 Other Site Electrical Utilities NOT USED None G4030 Site Communications & Security G4030 Other Site Electrical Utilities NOT USED NOT USED NOT USED NOT USED NOT USED NOT USED NONE Minor None Minor Mino		Fire	4000	None	Minor		Moderate	r	∕lajor	x R	eplace	50%	\$145,236	
G3030 Storm Sewer G3040 Heating Distribution G3040 Heating Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3050 Fuel Distribution G4010 Fleetrical Distribution G4010 Fleetrical Distribution G4010 Fleetrical Distribution G4020 Site Lighting G4020 Site Lighting G4030 Stee Communications & Security G4030 Other Site Electrical Utilities NOT USED OTHER Description of System 1000 x None Minor Moderate Major Replace S0 Enter IF of duct work in cell E148 Feeplace S0 No observed issues S0														
G3040 Heating Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3050 Cooling Distribution G3090 Other Site Mechanical Utilities G4020 Site Lighting G4020 Site Lighting G4020 Site Lighting G4030 Site Electrical Utilities NOT USED Description of System Moderate Minor Moderate Major Replace S0 Enter LF of heating ducts in cell E147 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E149 S0 Enter LF of natural gas lines in cell E149 S0 Enter LF of natural gas lines in cell E149 Major Replace Major Replace Major Replace Major Replace S0 No observed issues S0 No observed	G3020 Sanitary Sewer		2400	None	Minor		Moderate	r	∕lajor	x R	eplace	75%	\$90,493	-
G3050 Cooling Distribution G3060 Fuel Distribution G3060 Fuel Distribution G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G4010 Electrical Utilities G402 Site Lighting G4020 Site Lighting G4020 Site Lighting G40305 Other Site Electrical Utilities NOT USED Minor Moderate Major Replace S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E149 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 S0 Enter LF of duct work in cell E148 Major Replace Major Replace S0 No observed issues Major Replace	G3030 Storm Sewer		100	x None	Minor		Moderate		∕lajor	Re	eplace		\$0	
G3060 Fuel Distribution G3090 Other Site Mechanical Utilities G40 Site Electrical Distribution Generator G402 Site Lighting G403 Site Communications & Security G403 Site Communications & Security G409 Other Site Electrical Utilities NOT USED Description of System Description of System Minor Moderate Major Moderate	G3040 Heating Distribution		100	x None	Minor		Moderate	r	∕lajor	Re	eplace		\$0	S .
G3090 Other Site Mechanical Utilities NOT USED None Minor Moderate Major Replace G4010 Electrical Distribution Service Generator G4020 Site Lighting Generator G4020 Site Lighting G4030 Site Communications & Security 100% x None Minor Moderate G4030 Site Communications & Security 100% x None Minor Moderate Major Replace S0 No observed issues G4090 Other Site Electrical Utilities NOT USED None Minor Moderate Major Replace S0 No observed issues G4090 Other Site Construction NOT USED None Minor Moderate Major Replace S0 No observed issues Major Replace S0 No observed issues Major Replace Major Replace Major Replace S0 No observed issues Major Replace Major Replace Major Replace Major Replace Major Replace S0 No observed issues Major Replace S0 No observed issues Major Replace Major Replace Major Replace Major Replace Major Replace Major Replace S0 No observed issues Major Replace Major Replace Major Replace Major Replace Major Replace S0 No observed issues Major Replace Major Replace Major Replace S0 No observed issues Major Replace Major Replace S0 No observed issues Major Replace S0 No observed issues S0 No observed S0 No observed issues S0 No observed S0 No obs	G3050 Cooling Distribution		100	x None	Minor		Moderate	r	∕lajor	Re	eplace		\$0	
G4010 Electrical Utilities G4010 Electrical Distribution Service Generator Generator G4020 Site Lighting G4030 Site Communications & Security G4030 Site Communications & Security G4090 Other Site Electrical Utilities NOT USED Description of System Description of S	G3060 Fuel Distribution		100	x None	Minor		Moderate	r	∕lajor	Re	eplace		\$0	Enter LF of natural gas lines in cell E149
G4010 Electrical Distribution Generator Generator G4020 Site Lighting G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities NOT USED Description of System Minor Moderate Major Moderate Mojor Mojor Mojor Mojor Mojo	G3090 Other Site Mechanical Utilities	NOT USED		None	Minor		Moderate	r	∕lajor	R	eplace			
Generator G4020 Site Lighting G4020 Site Lighting G4030 Site Communications & Security G4090 Other Site Electrical Utilities NOT USED None Minor None Minor Moderate Major Moderate Major Moderate Major Moderate Major Replace S0 No observed issues S0 No observed i	G40 Site Electrical Utilities								-		_			
G4020 Site Lighting G4030 Site Communications & Security G4030 Site Communications & Security G4030 Site Communications & Security G4090 Other Site Electrical Utilities NOT USED NOT USED NOT USED Description of System Descrip	G4010 Electrical Distribution	Service	100%	x None	Minor		Moderate	ı	∕lajor	Re	eplace		\$0	No observed issues
G4030 Site Communications & Security G4090 Other Site Electrical Utilities NOT USED Mone Minor Moderate Major Replace Replace Replace Replace Replace Replace Replace Replace Replace SO No observed issues Unit of Measure Major Moderate Major Replace Replace Replace So No observed issues Unit of Measure Vunit Budget So No observed issues Unit Budget So No observed issues None So N		Generator		o None	Minor		Moderate	ı	∕lajor	Re	eplace		\$0	
G4090 Other Site Electrical Utilities NOT USED None Minor Moderate Major Replace G90 Other Site Construction NOT USED OTHER Description of System Description of System Unit of Measure Quantity Unit Budget Extended Notes \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 50 \$ 5	G4020 Site Lighting		100%	x None	Minor		Moderate	r	∕lajor	Re	eplace		\$0	No observed issues
G90 Other Site Construction NOT USED Description of System	G4030 Site Communications & Security		100%	x None	Minor		Moderate	r	∕lajor	Re	eplace		\$0	No observed issues
Description of System	G4090 Other Site Electrical Utilities	NOT USED		None	Minor		Moderate	r	∕lajor	R	eplace			
Description of System Unit of Measure Quantity Unit Budget So	G90 Other Site Construction	NOT USED					•		-		-			
Description of System Unit of Measure Quantity Unit Budget So														
Description of System Measure Quantity Unit Budget Extended Notes 50	OTHER													
\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0							Unit of							
\$0 \$0 \$0 \$0 \$0 \$0	Description of System						Measure		Quantity	U	nit Budget		Extended	Notes
\$0 \$0 \$0 \$0 \$0													\$0	
\$0 \$0 \$0													\$0	
\$0 \$0													\$0	
50						T F							\$0	
						1 I							\$0	
\$0						1 I						İ	\$0	
						1						İ	\$0	

Physical Condition Budget Sub-Total	\$4,065,493
Budgeted Development Costs	\$1,544,887
Physical Condition Budget TOTAL	\$5,610,380
Cost with Escalation to June 2023	\$6,395,833
Cost with Escalation to June 2024	\$6,651,666
Cost with Escalation to June 2025	\$6,917,733
Replacement Budget	\$54,952,254

 District Name:
 Douglas County SD 4

 Site Name:
 Joseph Lane MS

 Building Name:
 Main

19912792167

Building ID:

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

			ı				LEVEL OF A	CTION			I		
							T T	CHOIL					
										Replace as	% of		
			% of Building							part of	System or	Automated Budget	
Level 1 Level 2	Level 3	Type (as applicable)	or Number	No	one	Minor	Mode	rate	Major	Renovation	Finish	Estimate	Notes
A SUBSTRUCTU	JRE												
A10 For	undations					_							
	A1010 Standard Foundations		60%	x None	e	Minor	Mode	ate	Major	Replace		\$0	No observed issues
	A1020 Special Foundations			o None	e	Minor	Mode	ate	Major	Replace		\$0	
													Major heaving and separating along west side of
													building D. Significant crack on corner of building
													due to settling issues. Can be fixed with
	A1030 Slab on Grade		40%	None	e	Minor	Mode	ate >	Major	Replace	4%	\$46,661	TerraFirma foundation system
A20 Bas	sement Construction			_	_		_	_	_				
	A2010 Basement Excavation	NOT USED		None		Minor	Mode		Major	Replace			
	A2020 Basement Walls		100%	x None	e	Minor	Mode	ate	Major	Replace		\$0	No observed issues
B SHELL													
B10 Sup	perstructure					1	—		-	<u> </u>		4-	No observed forms
	B1010 Floor Construction	Wood	60%	x None		Minor	Mode		Major	Replace		\$0	No observed issues
		Steel	400/	o None		Minor	Mode		Major	Replace		\$0	No observed issues
	P4020 Paraf Caracteristics	Concrete	40%	x None		Minor	Mode		Major	Replace		\$0	No observed issues
	B1020 Roof Construction	Wood	100%	x None		Minor	Mode	_	Major	Replace		\$0 \$0	INO Observed issues
		Steel		o None		Minor	Mode	_	Major	Replace		\$0	
D20 Fv4	torior Fuelosuro	Concrete		o None	e	Minor	Mode	ate	Major	Replace		\$0	
BZU EXL	terior Enclosure	Community Former of / Tilk		o None		Minor			7	Davidson.		ćo.	
	B2010 Exterior Walls	Concrete Formed / Tilt	ļ	0 INOIN	e	IVIIIIVI	Mode	ate _	Major	Replace		\$0	Exterior masonry walls need paint in multiple
		Masonry	55%	None		Minor	x Mode	ate	Major	Replace	9%	\$17,704	areas
		Framed w/ Wood Siding	3370	None		Minor	Model	_	Major	Replace	370	\$0	a.cus
		Framed w/Metal Panel	45%	None		Minor	x Moder		Major	Replace	19%	\$33,591	Exterior siding needs paint in multiple areas
		Framed w/Stucco	4570	o None		Minor	Moder		Major	Replace	1370	\$0	Executor starting needs paint in matapie areas
		Framed w/Masonry Veneer		o None		Minor	Mode	_	Major	Replace		\$0	
		rianica nymasomy veneer					H	_		перисс	-	Ψ.	12 single pane windows need to be replaced
	B2020 Exterior Windows	Wood	2%	None	e	Minor	Mode	ate >	Major	Replace	100%	\$10,609	(building F) - cost adjusted down
							H		┪ "			,	169 of 664 aluminum / steel windows were single
		Aluminum/Steel	98%	None	e	Minor	Mode	ate >	Major	Replace	26%	\$106,834	pane or fogged and need to be replaced
		Clad		o None	e	Minor	Mode	ate	Major	Replace		\$0	
		Curtain Wall		o None	e	Minor	Mode	ate	Major	Replace		\$0	
	B2030 Exterior Doors	Wood	1	x None	e	Minor	Mode	ate	Major	Replace		\$0	All exterior wood doors were in good condition
		Hollow Metal	63	x None	e	Minor	Mode	ate	Major	Replace		\$0	All exterior metal doors were in good condition
		Storefront		o None	e	Minor	Mode	ate	Major	Replace		\$0	
B30 Ro	oofing					•							
						1	П		1				
													Minor to Major issues found on every shingle and
													torch down roof. Standing water was on multiple
													roofs and all walkways. Numerous flashing and
													cracks found on torch down roofs and shingle
							1			l L		4	roof system is showing sings of wear. Adjusted
	B3010 Roof Coverings	Asphalt Shingle	45%	None		Minor	Mode	_	Major	x Replace	20%	\$148,566	cost up to more accurately reflect cost estimate
		Built-Up	55%	o None		Minor	Mode	_	Major	Replace		\$0	No observed issues.
		Single Ply	3%	x None		Minor	Mode		Major	Replace	——	\$0 \$0	Roofs on modulars are in good shape
		Metal	—	o None		Minor	Mode		Major	Replace		\$0 \$0	
	D2020 Book Openings	Concrete Tile		o None		Minor	Mode		Major	Replace			By Building GSF
	B3020 Roof Openings	Skylights		o None		Minor Minor	Mode		Major	Replace		\$0 \$0	Per hatch
C INTERIORS		Access Hatch		o None	e	IVIIIIOF	Mode	are	Major	Replace		ŞU	i ci nuccii
	terior Construction												
CIOINU	C1010 Partitions	Framed	91%	x None	e =	Minor	Mode	ate	Major	Replace	ı	\$0	No observed issues
			32/0		-						L	70	

	Masonry	9% x None	Minor	Moderate Major	Replace		\$0	No observed issues
				\square . \square				
C1020 Interior Doors	Wood	132 None	Minor	x Moderate Major		1%	\$1,180	Door hardware was non-functional on one door.
04000 5:44	Hollow Metal	20 x None	Minor	Moderate Major			\$0	No observed issues
C1030 Fittings	NOT USED	None	Minor	Moderate	Replace			
C20 Stairs	Mand	3 x None	Minor	Madarata	. Donland		\$0	No observed issues
C2010 Stair Construction	Wood		Minor Minor	Moderate Major		\vdash	\$0	INO ODSELVEU ISSUES
	Metal Concrete		Minor	Moderate Major			\$0	No observed issues
C2020 Stair Finishes						-	\$0	No observed issues
C2020 Stair Finishes	Concrete Fill	1 x None 1 x None	Minor	Moderate Major		-	\$0	No observed issues
C30 Interior Finishes	Resilient	1 x None	Minor	Moderate	Replace		ŞU	INO ODSELVEU ISSUES
C3010 Wall Finishes	Paint on Masonry	9% None	x Minor	Moderate	Replace	18%	\$3,993	Paint needed in multiple areas
C3010 Wall Fillishes	Wallboard	87% None	x Minor	Moderate Major		12%	\$23,208	Patch and paint needed throughout
			Minor			12/0	\$23,208	raterrana paint needed tinoughout
	Wainscot	o None	IVIIIIOI	Moderate	Replace		\$0	Minor grout damage found in 3 restrooms and
	Ceramic Tile	4% None	x Minor	Moderate Major	Replace	10%	\$396	locker rooms - cost adjusted up
	Ceramic Tile	4% None	X IVIIIOI	Moderate	керіасе	10%	\$390	locker rooms - cost adjusted up
C3020 Floor Finishes	Carpet / Soft Surface	23% None	Minor	Moderate Major	x Replace	10%	\$16,908	Worn and stained carpet found in multiple rooms
C3020 FI001 FIIIISHES	Carpet / Soft Surface	25%	IVIIIIOI	iviouerate	x Replace	10%	\$10,508	Tiles were found cracked and lifting in multiple
	Resilient Tile	42% None	x Minor	Moderate Major	Replace	10%	\$4,668	areas
	Resilient Sheet	11% x None	Minor	Moderate Major		1070	\$0	No observed issues
	Resilient Sheet	1170 X None	Willion	Wildjoi	Періасс	-	70	Lower Gym & Storage area, and Locker room's
	Polished Concrete	12% None	Minor	Moderate Major	x Replace	43%	\$51,107	flooring needs to be replaced
	Ceramic Tile	5% None	x Minor	Moderate Major		5%	\$1,048	Damaged grout in boys and girls restroom
	Liquid Applied	o None	Minor	Moderate Major		3,0	\$0	
	Eldara / Applica			inioderate iniajer	Періосс	h + + + + + + + + + + + + + + + + + + +	ŢŪ.	Wood flooring in custodial need to be repaired /
	Wood Sports Floor	8% None	Minor	x Moderate Major	Replace	2%	\$1,233	refinished
					H		7-)	Patch and paint needed in lower gym & storage
C3030 Ceiling Finishes	Wallboard	13% None	Minor	x Moderate Major	Replace	6%	\$6,147	area
g	Lay-In Ceiling Tile	15% None	x Minor	Moderate Major		5%	\$836	Stained tiles found in multiple areas
	, , ,				\Box		,	Stained and damaged tiles found in multiple
	Glued-Up Ceiling Tile	69% None	x Minor	Moderate	Replace	5%	\$2,479	areas
	Painted Structure	1% x None	Minor	Moderate			\$0	No observed issues
D SERVICES							·	
D10 Conveying								
D1010 Elevators & Lifts		None	Minor	Moderate Major	Replace	T T	\$0	
D1020 Escalators & Moving Walks		None	Minor	Moderate Major			\$0	
D1090 Other Conveying Systems		None	Minor	Moderate			\$0	
D20 Plumbing								
						ī		Could not test ~55 fixtures as they were tagged
								out due to lead being found in water. 4 fixtures
								were found not to work - district is finding lead in
D2010 Plumbing Fixtures		100% None	Minor	x Moderate Major	Replace	55%	\$84,737	~50% of fixtures tested
								Lead has spread throughout a majority of the
D2020 Domestic Water Distribution		100% x None	Minor	Moderate	x Replace	70%	\$560,808	school and should be replaced
								System is beyond its useful life and should be
D2030 Sanitary Waste		100% x None	Minor	Moderate	x Replace	100%	\$227,801	replaced
D2040 Rain Water Drainage		o None	Minor	Moderate	Replace		\$0	
D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Replace			
D30 HVAC								
D3010 Energy Supply		100% x None	Minor	Moderate	Replace		\$0	

D3020 Heat Generating Systems	Boiler Air Handler Furnace Heat Exchanger	100% x None O None O None	Minor Minor Minor Minor	Moderate Major Moderate Major Moderate Major Moderate Major	x Replace Replace Replace Replace	100%	\$1,047,663 \$0 \$0 \$0	Minor repairs are needed. Boilers are in poor condition and need to be replaced. MFIA Engineering priority 1 recommendation (2022) - Replace heating system in the original portion, the 1960 addition portion, and the Band / Choir room portion of the school. The new system will provide heat, ventilation, and filtration per OMSC and ASHRAE code and standards noted previously. Replace heating system in all the Modular classroom buildings. The new system will provide heat, ventilation, and filtration per OMSC and ASHRAE code and standards noted previously. Replace the heating system for the Shop / Home Ec. Classroom building MFIA Engineering priority 1 recommendation (2022) - Replace heating system in the original portion, the 1960 addition portion, and the Band / Choir room portion of the school. The new system will provide heat, ventilation, and filtration per OMSC and ASHRAE code and standards noted previously. Replace heating system in all the Modular classroom buildings. The new system will provide heat, ventilation, and filtration per OMSC and ASHRAE code and standards noted previously. Replace the heating system in all the Modular classroom buildings.
D3030 Cooling Generating Systems	Component of air handler Stand alone chiller	100% x None 100% x None	Minor Minor	Moderate Major Moderate Major	x Replace Replace	100%	\$424,788 \$0	building
D3040 Distribution Systems	Ductwork	100% x None	Minor	x Moderate Major	Replace	25%	\$49,247	Add ventilation to the campus.
D3050 Terminal & Package Units	Hot water return & supply Above ceiling VAV unit	100% x None o None	Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	
55050 reminar a radiage omes	In-room ventilator unit	o None	Minor	Moderate Major	Replace		\$0	
	In-room radiant unit	o None	Minor	Moderate Major	Replace		\$0	
D3060 Controls & Instrumentation		100% None	Minor	Moderate Major	Replace		\$0	
D3070 Systems Testing & Balancing		100% None	Minor	Moderate	Replace		\$0	
D3090 Other HVAC Systems & Equipment	NOT USED	None	Minor	Moderate	Replace			
D40 Fire Protection		Nana	Minor	Madarata	Danlass		ćo	
D4010 Sprinklers D4020 Standpipes		None None	Minor Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	
D4030 Fire Protection Specialties		None	Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate Major	Replace			
D50 Electrical								
D5010 Electrical Service & Distribution		100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
D5020 Lighting and Branch Wiring		100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
D5030 Communications & Security	Voice / Data System Clock / Intercom System	100% x None 100% None	Minor Minor	Moderate Major Moderate Major	Replace Replace	-	\$0 \$0	No observed issues No observed issues
	Closed Circuit Surveillance	100% None	Minor	Moderate Major	Replace		\$0	No observed issues
	Access Control System	o None	Minor	Moderate Major	Replace		\$0	No observed issues
	Intrusion Alarm System	20% x None	Minor	Moderate Major	Replace		\$0	Admin and IT areas - no observed issues
	Fire Alarm / Detection	100% x None	Minor	Moderate Major	Replace		\$0	No observed issues
	Lighting Control System	o None	Minor	Moderate Major	Replace		\$0	
D5090 Other Electrical Systems	NOT USED	None	Minor	Moderate	Replace			
E EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	100% x None	Minor	Moderate Major	Replace		\$0	All equipment is in good working order
	Vocational	o None	Minor	Moderate Major	Replace		\$0	
E1020 Institutional Equipment	Science	3272 None	Minor	x Moderate Major	Replace	100%	\$5,337	Rooms had eyewash station, but no fume hoods
E1020 moditational Equipment	Art	4352 x None	Minor	Moderate Major	Replace	100/0	\$0	No observed issues
	•						+-	

E1030 Vehicular Equipment E1090 Other Equipment <u>E20 Furnishings</u>	Stage Performance Restroom Accessories/Stalls NOT USED NOT USED	100% x None None None	Minor Minor Minor Minor	Moderate Moderate Moderate Moderate	Major Major Major Major	Replace Replace Replace Replace		\$0 \$0	No performance stage or auditorium ADA and restroom partitions were good throughout Bleachers in gym are old and worn and could be replaced- they are still functional - very few
E2010 Fixed Furnishings E2020 Movable Furnishings F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED		100% None	Minor Minor	Moderate Moderate	Major Major	x Replace	25%	\$256,413 \$264,117	problems, standalone set works fine Main locker rooms: many damaged lockers & benches need to be replaced - Lower gym lockers: all lockers need to be replaced - been on replaced list for 3 years - Majority of lockers in building D need to be replaced - staff wants these replaced Cafeteria tables are beyond useful life and need to be replaced.
G BUILDING SITE WORK G10 Site Preparation G20 Site Improvements	NOT USED								
G2010 Roadways		14348 None	x Minor	Moderate	x Major	Replace	4%	\$5,174	Some minor cracking and alligatoring noted in two separate areas
G2020 Parking Lots		76800 None	x Minor	Moderate	Major	Replace	23%	\$30,983	Minor cracks observed in all three parking areas
G2030 Pedestrian Paving G2040 Site Development		26749 None 2714 x None	Minor Minor	Moderate Moderate	x Major	Replace	16%	\$43,033 \$0	Damaged walkways identified over entire site No observed issues
G2050 Landscaping		477088 x None	Minor	Moderate	Major Major	Replace Replace	-	\$0	Entire site is irrigated - no observed issues
G30 Site Mechanical Utilities		477000 X NONE	Willion	Woderate	iviajoi	перисс		ŢŪ.	
G3010 Water Supply	Domestic	1500 None	Minor	Moderate	Major	x Replace	75%	\$81,695	A majority of the system is beyond its useful life and should be replaced
	Fire	o None	Minor	Moderate	Major	Replace	-	\$0	A majority of the system is beyond its useful life
G3020 Sanitary Sewer		2150 None	Minor	Moderate	Major	x Replace	75%	\$81,067	and should be replaced
G3030 Storm Sewer		100 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G3040 Heating Distribution		100 x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G3050 Cooling Distribution G3060 Fuel Distribution		100 x None 100 x None	Minor Minor	Moderate Moderate	Major Major	Replace Replace	-	\$0 \$0	No observed issues No observed issues
G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Moderate	Major	Replace		40	
G40 Site Electrical Utilities G4010 Electrical Distribution	Service	100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
	Generator	o None	Minor	Moderate	Major	Replace		\$0	
G4020 Site Lighting		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G4030 Site Communications & Security		100% x None	Minor	Moderate	Major	Replace		\$0	No observed issues
G4090 Other Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G90 Other Site Construction	NOT USED								
OTHER									
Description of System				Unit of Measure	Quantity	Unit Budget	:	Extended	Notes
								\$0	
				┦ ├ ──┤		┨ ┣━━━		\$0	
				┦ ├──┤	-	┥ ┝──		\$0 \$0	
				┥ ├──┤		1	-	\$0	
				7		1	1	\$0	
								\$0	
							_		

Physical Condition Budget Sub-Total \$3,640,030
Budgeted Development Costs \$1,383,212

 Physical Condition Budget TOTAL
 \$5,023,242

 Cost with Escalation to June 2023
 \$5,726,496

 Cost with Escalation to June 2024
 \$5,955,556

 Cost with Escalation to June 2025
 \$6,193,778

Replacement Budget \$52,688,608

District Name:	Douglas County SD 4
Site Name:	Rose Alt
Building Name:	0
Building ID:	0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTION							
Level 1			Type (as applicable)	% of Building or Number	None	Minor	Moderate	Major	Replace as part of Renovation	% of System or Finish	Automated Budget Estimate	Notes
A SUBS												
	A10 Fou	ndations			_							
		A1010 Standard Foundations			None	Minor	Moderate	Major	Replace		\$0	
		A1020 Special Foundations			None	Minor	Moderate	Major	Replace		\$0	
												Some cracking was observed at a few partitions,
		A1030 Slab on Grade		100%	None	Minor	x Moderate	Major	Replace	25%	\$19,483	indicating differential settlement.
	A20 Bas	ement Construction				_				Re-		
		A2010 Basement Excavation	NOT USED		None	Minor	Moderate	Major	Replace			
		A2020 Basement Walls			None	Minor	Moderate	Major	Replace		\$0	
B SHEL	L											
		erstructure										
			Wood		None	Minor	Moderate	Major	Replace		\$0	
			Steel	1	None	Minor	Moderate	Major	Replace		\$0	
			Concrete	H +	None	Minor	Moderate	Major	Replace		\$0	
			Wood		None	Minor	Moderate	Major	Replace		\$0	
			Steel	100%	x None	Minor	Moderate	Major	Replace		\$0	No reported issues.
				100%	None						\$0	No reported issues.
	D20 F: 4		Concrete		None	Minor	Moderate	Major	Replace		ŞÜ	<u> </u>
	BZU EXTE	erior Enclosure	0 . 5 . 1/70				<u> —</u>				40	
			Concrete Formed / Tilt		None	Minor	Moderate	Major	Replace		\$0	
			Masonry		x None	Minor	Moderate	Major	Replace		\$0	
			Framed w/ Wood Siding	21%	None	Minor	Moderate	Major	Replace		\$0	
			Framed w/Metal Panel		None	Minor	Moderate	Major	Replace		\$0	
			Framed w/Stucco	30%	x None	Minor	Moderate	Major	Replace		\$0	
			Framed w/Masonry Veneer		None	Minor	Moderate	Major	Replace		\$0	
		B2020 Exterior Windows	Wood		None	Minor	Moderate	Major	Replace		\$0	
												A few windows are still original and need
			Aluminum/Steel	100%	None	Minor	Moderate	Major	x Replace	20%	\$73,177	replacement.
			Clad		None	Minor	Moderate	Major	Replace		\$0	
			Curtain Wall		None	Minor	Moderate	Major	Replace		\$0	
		B2030 Exterior Doors	Wood		None	Minor	Moderate	Major	Replace		\$0	
												Most doors are original, discolored, scuffed and
			Hollow Metal	14	None	Minor	Moderate	x Major	Replace	100%	\$20,333	with sighs of rust. Hardware is not accessible.
			Storefront		None	Minor	Moderate	Major	Replace		\$0	
	B30 Roo											
		B3010 Roof Coverings	Asphalt Shingle	20%	None	Minor	Moderate	Major	Replace		\$0	No observed issues. Gymnasium space.
			Built-Up	80%	None	Minor	Moderate	Major	Replace		\$0	No observed issues.
			Single Ply		None	Minor	Moderate	Major	Replace		\$0	
			Metal		None	Minor	Moderate	Major	Replace		\$0	
			Concrete Tile		None	Minor	Moderate	Major	Replace		\$0	
		B3020 Roof Openings	Skylights		None	Minor	Moderate	Major	Replace		\$0	By Building GSF
			Access Hatch		None	Minor	Moderate	Major	Replace		\$0	Per hatch
C INTER	RIORS				_							
	C10 Inte	rior Construction										
		C1010 Partitions	Framed	60%	None	Minor	Moderate	Major	Replace		\$0	
			Masonry	40%	None	Minor	Moderate	Major	Replace		\$0	
		C1020 Interior Doors	Wood	30	None	Minor	x Moderate	Major	Replace	70%	\$18,769	
			Hollow Metal	4	x None	Minor	Moderate	Major	Replace		\$0	
		C1030 Fittings	NOT USED		None	Minor	Moderate	Major	Replace			
	C20 Stai	=			_			 ·				
		C2010 Stair Construction	Wood		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
			Metal		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
			Concrete		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
			Concrete Fill		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
								,				

		Resilient	None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Inte	erior Finishes			-			-			I
	C3010 Wall Finishes	Paint on Masonry	95% None	x Minor	Moderate	Major	Replace	100%	\$77,860	Wall surfaces need paint.
		Wallboard	None	Minor	Moderate	Major	Replace		\$0	
		Wainscot	None	Minor	Moderate	Major	Replace		\$0	
		Ceramic Tile	5% x None	Minor	Moderate	Major	Replace		\$0	
	C3020 Floor Finishes	Carpet / Soft Surface	40% None	Minor	Moderate	Major	x Replace	100%	\$97,764	Carpets are stained and worn.
		Resilient Tile	35% None	Minor	Moderate	Major	x Replace	80%	\$69,664	9x9 tiles, possibly ACT, and cracked VCT
		Resilient Sheet	None	Minor	Moderate	Major	Replace		\$0	
		Polished Concrete	20% None	Minor	Moderate	Major	Replace		\$0	
		Ceramic Tile	5% x None	Minor	Moderate	Major	Replace		\$0	
		Liquid Applied	None	Minor	Moderate	Major	Replace		\$0	
		Wood Sports Floor	x None	Minor	Moderate	Major	Replace		\$0	
	C3030 Ceiling Finishes	Wallboard	50% None	x Minor	Moderate	Major	Replace	100%	\$57,444	Ceilings need paint.
		Lay-In Ceiling Tile	30% None	x Minor	Moderate	Major	Replace	10%	\$1,098	
		Glued-Up Ceiling Tile	None	Minor	Moderate	Major	Replace		\$0	
		Painted Structure	20% None	Minor	Moderate	Major	x Replace	100%	\$23,490	Exposed structure at the Gym need repainting
D SERVICES										
D10 Cor										
	D1010 Elevators & Lifts		None	Minor	Moderate	Major	Replace		\$0	
	D1020 Escalators & Moving Walks		None	Minor	Moderate	Major	Replace		\$0	
	D1090 Other Conveying Systems		None	Minor	Moderate	Major	Replace		\$0	
D20 Plui	mbing									
										The majority of the fixtures at the lower level are
	D2010 Plumbing Fixtures		100% None	Minor	Moderate	Major	x Replace	70%	\$230,506	original and inefficient.
	D2020 Domestic Water Distribution		100% x None	Minor	Moderate	Major	Replace		\$0	
	D2030 Sanitary Waste		100% x None	Minor	Moderate	Major	Replace		\$0	
	D2040 Rain Water Drainage		None	Minor	Moderate	Major	Replace		\$0	
	D2090 Other Plumbing Systems	NOT USED	None	Minor	Moderate	Major	Replace			<u>.</u>
D30 HV	<u>AC</u>				_					
	D3010 Energy Supply		100% x None	Minor	Moderate	Major	Replace		\$0	
	D3020 Heat Generating Systems	Boiler	100% None	Minor	Moderate	Major	x Replace	100%	\$348,321	The boiler is obsolete, parts are difficult to obtain.
		Air Handler	None	Minor	Moderate	Major	Replace		\$0	
		Furnace	None	Minor	Moderate	Major	Replace		\$0	
		Heat Exchanger	None	Minor	Moderate	Major	Replace		\$0	
	D3030 Cooling Generating Systems	Component of air handler	None	Minor	Moderate	Major	Replace		\$0	
		Stand alone chiller	None	Minor	Moderate	Major	Replace		\$0	
	D3040 Distribution Systems	Ductwork	100% x None	Minor	Moderate	Major	Replace		\$0	
		Hot water return & supply	None	Minor	Moderate	Major	Replace		\$0	
	D3050 Terminal & Package Units	Above ceiling VAV unit	None	Minor	Moderate	Major	Replace		\$0	
		In-room ventilator unit	100% None	Minor	Moderate	Major	x Replace	100%	\$583,949	Inefficient and obsolete.
		In-room radiant unit	None	Minor	Moderate	Major	Replace		\$0	
	D3060 Controls & Instrumentation		100% None	Minor	Moderate	Major	x Replace	100%	\$98,423	Controls are obsolete.
	D3070 Systems Testing & Balancing		None	Minor	Moderate	Major	Replace		\$0	
	D3090 Other HVAC Systems & Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
D40 Fire	Protection								40	
	D4010 Sprinklers		None	Minor	Moderate	Major	Replace	\vdash	\$0	
	D4020 Standpipes		None	Minor	Moderate	Major	Replace		\$0	
	D4030 Fire Protection Specialties		None	Minor	Moderate	Major	Replace		\$0	
25251	D4090 Other Fire Protection Systems	NOT USED	None	Minor	Moderate	Major	Replace			
D50 Elec	ULICAL				_					Most panels are original and sheelets. Same
										Most panels are original and obsolete. Some Federal Pacific panels still in service at the lower
	D5010 Flactrical Sanges 9 Distribution		100% None	Minor	Moderate	Major	y Ponlace	60%	\$178,039	section.
	D5010 Electrical Service & Distribution						x Replace	00%		Jeeu Jii.
	D5020 Lighting and Branch Wiring D5030 Communications & Security	Voice / Data Custom	100% x None 100% x None	Minor Minor	Moderate	Major	Replace	-	\$0 \$0	
	DOUGO COMMUNICATIONS & SECURITY	Voice / Data System	100% X None 100% None		Moderate Moderate	Major	Replace	100%	\$36,588	System is obsolete and needs to be replaced.
		Clock / Intercom System		Minor		Major	x Replace	100%	\$36,588	System is obsolete and needs to be replaced. System is obsolete and needs to be replaced.
		Closed Circuit Surveillance		Minor	Moderate	Major	x Replace	100%		System is obsolete and needs to be replaced. System is obsolete and needs to be replaced.
		Access Control System	100% None	Minor	Moderate	Major	x Replace	100%	\$36,588 \$26,709	System is obsolete and needs to be replaced. System is obsolete and needs to be replaced.
		Intrusion Alarm System	100% x None	Minor	Moderate	Major	x Replace	100%		System is obsolete and needs to be replaced. System is obsolete and needs to be replaced.
		Fire Alarm / Detection	100% x None	Minor	Moderate	Major	x Replace	100%	\$77,933	System is obsolete and needs to be replaced.

D5090 Other Electrical Systems	Lighting Control System NOT USED	200% x None None	Minor Minor	Moderate Moderate	Major Major	x Replace Replace	100%	\$61,468	System is obsolete and needs to be replaced.
E EQUIPMENT & FURNISHINGS									
E10 Equipment									
E1010 Commercial Equipment	Food Service Vocational	100% x None	Minor Minor	Moderate Moderate	Major Major	Replace Replace		\$0 \$0	Kitchen is only used to re-heat food, no preparation on site.
E1020 Institutional Equipment	Science	None	Minor	Moderate	Major	Replace	-	\$0	
E1020 Institutional Equipment	Art	None	Minor	Moderate	Major	Replace	-	\$0	
	Stage Performance	None	Minor	Moderate	Major	Replace		\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	None	Minor	Moderate	Major	Replace		\$0	cost, s. o. stage remormance rueu
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace		γo	
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E20 Furnishings	1101 0325	None	Willion	Wioderate	iviajoi	перисс			
LZO i umismigs					-	\Box			Most of the cabinets are original. The early
E2010 Fixed Furnishings		100% None	Minor	x Moderate	Major	Replace	70%	\$60,188	education area has been renovated.
E2020 Movable Furnishings		100% x None	Minor	Moderate	Major	Replace	7070	\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED								**	
G BUILDING SITE WORK									
G10 Site Preparation	NOT USED								
G20 Site Improvements									
G2010 Roadways		None	Minor	Moderate	Major	Replace		\$0	
G2020 Parking Lots		16000 None	Minor	Moderate	Major	Replace		\$0	
									portions of the concrete pedestrian surface are
G2030 Pedestrian Paving		2500 None	Minor	Moderate	x Major	Replace	80%	\$20,110	broken and uneven.
G2040 Site Development		None	Minor	Moderate	Major	Replace		\$0	
G2050 Landscaping		9500 x None	Minor	Moderate	Major	Replace		\$0	
G30 Site Mechanical Utilities			_						
G3010 Water Supply	Domestic	100 None	Minor	Moderate	Major	Replace		\$0	No reported issues.
	Fire	None	Minor	Moderate	Major	Replace		\$0	No second discussion
G3020 Sanitary Sewer		100 None	Minor	Moderate	Major	Replace		\$0	No reported issues.
G3030 Storm Sewer		100 None	Minor	Moderate	Major	Replace		\$0	No reported issues.
G3040 Heating Distribution		None	Minor	Moderate	Major	Replace		\$0	
G3050 Cooling Distribution		None	Minor	Moderate	Major	Replace		\$0	
G3060 Fuel Distribution	NOTUCED	None	Minor	Moderate	Major	Replace		\$0	
G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G4010 Electrical Distribution	Service	100% x None	Minor	Moderate	Major	Replace		\$0	No reported issues.
G4010 Electrical Distribution	Generator	None	Minor	Moderate	Major	Replace		\$0	No reported issues.
G4020 Site Lighting	denerator	100% x None	Minor	Moderate	Major	Replace		\$0	No reported issues.
G4030 Site Communications & Security		None	Minor	Moderate	Major	Replace		\$0	
G4090 Other Site Electrical Utilities	NOT USED	None	Minor	Moderate	Major	Replace		ΨO	
G90 Other Site Construction	NOT USED	wone		moderate	.v.ajo.	перисс			
OTHER									
Description of System				Unit of Measure	Quantity	Unit Budget		Extended	Notes
								\$0	
]	\$0	
] [\$0	
	<u> </u>		<u> </u>] [\$0	
] [\$0	
				↓ 				\$0	
						<u> </u>	j l	\$0	

Cost with Escalation to June 2024 \$3,702,405 Cost with Escalation to June 2025 \$3,850,501

Replacement Budget \$19,320,863

District Name:	Douglas County SD 4
Site Name:	Roseburg HS
Building Name:	0
Building ID:	0

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTIO	N		1		
					LIVE OF ACTIO		T			
							Replace as	% of		
		% of Building					part of	System or	Automated Budget	
Level 1 Level 2 Level 3	Type (as applicable)	or Number	None	Minor	Moderate	Major	Renovation	Finish	Estimate	Notes
A SUBSTRUCTURE										
A10 Foundations			_	_						
A1010 Standard Foundations		13% x	None	Minor	Moderate	Major	Replace		\$0	Heritage building.
A1020 Special Foundations			None	Minor	Moderate	Major	Replace		\$0	
										All buildings have good structural integrity, no
A1030 Slab on Grade		97% x	None	Minor	Moderate	Major	Replace		\$0	cracks or settlement was observed.
A20 Basement Construction										
A2010 Basement Excavation	NOT USED	420/	None	Minor	Moderate	Major	Replace		40	Havitage building has a half basement
A2020 Basement Walls		13%	None	Minor	Moderate	Major	Replace		\$0	Heritage building has a half basement.
B SHELL										
B10 Superstructure B1010 Floor Construction	Wood		None	Minor	Moderate	Major	Replace		\$0	
B1010 Fl001 Collstituction	Wood		None	WIIIOI	Wioderate	Major	Replace		ŞÜ	The main and arts building have a metal
	Steel	68% x	None	Minor	Moderate	Major	Replace		\$0	structure.
	Concrete	32% x	_	Minor	Moderate	Major	Replace		\$0	
B1020 Roof Construction	Wood	3270	None	Minor	Moderate	Major	Replace		\$0	
	Steel	68% x	None	Minor	Moderate	Major	Replace		\$0	
	Concrete		None	Minor	Moderate	Major	Replace		\$0	
B20 Exterior Enclosure										
B2010 Exterior Walls	Concrete Formed / Tilt	16% x	None	Minor	Moderate	Major	Replace		\$0	VoTech building.
	Masonry	72%	None	Minor	Moderate	Major	Replace		\$0	
	Framed w/ Wood Siding		None	Minor	Moderate	Major	Replace		\$0	
	Framed w/Metal Panel		None	Minor	Moderate	Major	Replace		\$0	
	Framed w/Stucco	12% x	None	Minor	Moderate	Major	Replace		\$0	
	Framed w/Masonry Veneer		None	Minor	Moderate	Major	Replace		\$0	
B2020 Exterior Windows	Wood		None	Minor	Moderate	Major	Replace		\$0	
										Windows at the Commons, VoTech and some at
	Aluminum/Steel	100%	None	Minor	Moderate	Major	x Replace	35%	\$1,143,135	the Heritage buildings.
	Clad		None	Minor	Moderate	Major	Replace		\$0	
	Curtain Wall	30% x	None	Minor	Moderate	Major	Replace		\$0	At the Main building and Arts building.
B2030 Exterior Doors	Wood	6	None	Minor	Moderate	Major	x Replace	100%	\$13,406	The exterior wood doors are in poor condition.
										Exterior doors at the older buildings, specially at
										the commons and the Technical building are
										damaged and in need of replacement. Most hardware does not comply with accessibility
	Hollow Metal	95	None	Minor	Moderate	x Major	Replace	20%	\$27,595	standards.
	Storefront		None	Minor	Moderate	Major	Replace	2070	\$0	standa ds.
B30 Roofing	Storenont	14 /	None	IVIIIIOI	Wioderate	Iviajoi	Replace		Ç0	
B3010 Roof Coverings	Asphalt Shingle		None	Minor	Moderate	Major	Replace		\$0	
25010 11001 2012111185	7 Spriate Stringle		-1.0	H	- Inductate		- nepiace		Ψ	
										Vo Tech Building and Commons Building systems
										are beyond their expected life and in danger of
	Built-Up	95%	None	Minor	Moderate	x Major	Replace	31%	\$1,131,155	failing. Replacement should be scheduled.
										Heritage building has a portion of TPO roofing
	Single Ply	5% x	None	Minor	Moderate	Major	Replace		\$0	installed in 2015.
	Metal		None	Minor	Moderate	Major	Replace		\$0	
	Concrete Tile		None	Minor	Moderate	Major	Replace		\$0	
B3020 Roof Openings	Skylights		None	Minor	Moderate	Major	Replace		\$0	By Building GSF
	Access Hatch	7 x	None	Minor	Moderate	Major	Replace	لـــــــا	\$0	Per hatch
C INTERIORS										
C10 Interior Construction	Franced	000/	Non-	N.C	Medera	N 4 - 1	Douters	1	ćo	
C1010 Partitions	Framed		None	Minor Minor	Moderate	Major	Replace	 	\$0 \$0	
	Masonry	10% X	None	ivilnor	Moderate	Major	Replace		\$0	
					•					

	C1020 Interior Doors	Wood	168	None	Minor	Moderate	x Major	Replace	24%	\$58,559	Doors at the commons and VoTech are damaged and the hardware is not accessible.
							П				Doors at the commons and VoTech are damaged
		Hollow Metal	40	None	Minor	Moderate	x Major	Replace	50%	\$24,578	and the hardware is not accessible.
C20 Sto	C1030 Fittings	NOT USED		None	Minor	Moderate	Major	Replace			
C20 Sta	C2010 Stair Construction	Wood		None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	CZOTO Stali Construction	Metal	148	x None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
		Concrete		x None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
	C2020 Stair Finishes	Concrete Fill		x None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
		Resilient		x None	Minor	Moderate	Major	Replace		\$0	Cost/Flight
C30 Into	erior Finishes			_			_				
	C3010 Wall Finishes	Paint on Masonry		None	Minor	Moderate	Major	Replace		\$0	
		Wallboard		None	Minor	Moderate	Major	Replace		\$0	
		Wainscot		None	Minor	Moderate	Major	Replace		\$0	
		Ceramic Tile		None	Minor	Moderate	Major	Replace		\$0	
	C3020 Floor Finishes	Carpet / Soft Surface	10%	None	Minor	Moderate	Major	x Replace	90%	\$196,358	Most carpet is showing signs of wear.
											There are still 9x9 tiles throughout the campus
											and many VCT tiles are cracked with separated seams. Specially in the Commons building and Vo
		Resilient Tile	73%	None	Minor	Moderate	Major	x Replace	40%	\$648,517	Tech Building.
		Resilient Sheet		x None	Minor	Moderate	Major	Replace	4070	\$048,517	Portions of the hallway and a few classrooms.
		Polished Concrete		x None	Minor	Moderate	Major	Replace		\$0	Some class rooms and vocational areas.
		Ceramic Tile		x None	Minor	Moderate	Major	Replace		\$0	Bathrooms.
										7-	Basement of the heritage building, in poor
		Liquid Applied	2%	None	Minor	Moderate	Major	x Replace	100%	\$92,169	condition.
		Wood Sports Floor	8%	x None	Minor	Moderate	Major	Replace		\$0	Gymnasiums, in good condition.
	C3030 Ceiling Finishes	Wallboard	2%	None	Minor	Moderate	Major	Replace		\$0	
											Mostly the ceilings at the Commons building, and
		Lay-In Ceiling Tile	63%	None	Minor	Moderate	Major	x Replace	36%	\$592,601	the Vo Tech building.
											Small portions of the glued ceilings present stains
					1 1			1 L .			and damage, but most are in overall good
		Glued-Up Ceiling Tile	30%	None	x Minor	Moderate	Major	Replace	20%	\$12,738	condition. portions of the structure need a coat of paint in
		Painted Structure	5%	None	Minor	Moderate	Major	x Replace	16%	\$8,387	particular in the VoTech building.
D SERVICES		Tainted Structure	370	Ivone	IVIIIIOI	Wioderate	iviajoi	х перисе	10/0	70,307	F
	nveying										
											Some improvements need to be done at the
	D1010 Elevators & Lifts		13	None	x Minor	Moderate	Major	Replace	20%	\$13,763	Commons elevator.
	D1020 Escalators & Moving Walks			None	Minor	Moderate	Major	Replace		\$0	
	D1090 Other Conveying Systems			None	Minor	Moderate	Major	Replace		\$0	
D20 Plu	umbing			_	_	_		_			
											While the majority of fixtures have been replaced
											through the years, many old outdated and non-
	D2010 Plumbing Fixtures		100%	None	Minor	Moderate	Major	x Replace	38%	\$1,117,006	water efficient fixtures remain in the site.
	D2010 Flumbling Fixtures		100%	- None	Willion	Wioderate	iviajoi	х перисс	3070	\$1,117,000	piping at the Heritage and Commons buildings is
	D2020 Domestic Water Distribution		100%	None	x Minor	Moderate	Major	Replace	38%	\$152,658	original and will need minor repairs.
								\Box			piping at the Heritage and Commons buildings is
	D2030 Sanitary Waste		100%	None	x Minor	Moderate	Major	Replace	38%	\$194,856	original and will need minor repairs.
	D2040 Rain Water Drainage		100%	None	Minor	Moderate	Major	Replace		\$0	
	D2090 Other Plumbing Systems	NOT USED		None	Minor	Moderate	Major	Replace			
D30 HV	<u>/AC</u>			_	_	_	_	_			In
	D2010 Farana Guarda		4000/	N		NA - d		Davidada		\$0	No reported issues. Feeding gas boilers and RTU's.
	D3010 Energy Supply		100%	None	Minor	Moderate	Major	Replace	-	ŞU	The boilers that serve the Stu Gym and the
											Heritage buildings were installed in 1987 and are
			1				1 1	1 1			obsolete. Replacement parts are difficult to
	D3020 Heat Generating Systems	Boiler	48%	None	Minor	Moderate	Major	x Replace	100%	\$1,492,477	obtain.
	<i>.</i>	Air Handler	42%	None	Minor	Moderate	Major	x Replace	60%	\$479,019	Most AHU's are obsolete.
		Furnace		None	Minor	Moderate	Major	Replace		\$0	
		Heat Exchanger		None	Minor	Moderate	Major	Replace		\$0	
	D3030 Cooling Generating Systems	Component of air handler		None	Minor	Moderate	Major	Replace		\$0	

	Chandalana shillan			Nandausta Dasias	D la		ćo	
D2040 Distribution Contactor	Stand alone chiller	Non		Moderate Major	Replace	240/	\$0	Commons and VoTech buildings.
D3040 Distribution Systems	Ductwork	100% Non		Moderate Major	x Replace	31%	\$521,433	Commons and votech buildings.
	Hot water return & supply	Non		Moderate	Replace		\$0	
D3050 Terminal & Package Units	Above ceiling VAV unit	50% Non		Moderate Major	Replace		\$0	
	In-room ventilator unit	Non		Moderate Major	Replace		\$0	
	In-room radiant unit	10% Non	e Minor	Moderate Major	Replace		\$0	High open spaces
								MFIA Engineering priority 1 recommendation
								(2022) - Replace digital controls at AHUs at Main
D3060 Controls & Instrumentation		100% Non		Moderate Major	x Replace	20%	\$175,716	and Student CTR
D3070 Systems Testing & Balancing		100% Non	e Minor	Moderate	x Replace	31%	\$147,824	Commons and VoTech buildings.
D3090 Other HVAC Systems & Equipment	NOT USED	Non	e Minor	Moderate Major	Replace			
D40 Fire Protection								
D4010 Sprinklers		48% Non	e Minor	Moderate Major	Replace		\$0	Main and Arts buildings.
D4020 Standpipes		48% Non		Moderate Major	Replace		\$0	Main and Arts buildings.
D4030 Fire Protection Specialties		Non	e Minor	Moderate Major	Replace		\$0	
D4090 Other Fire Protection Systems	NOT USED	Non		Moderate Major	Replace			
D50 Electrical				.,,				
DO LICCUITOR								Most electrical services are original with the
								exception of the Main and Arts building. With no
D5010 Electrical Service & Distribution		100% Non	e Minor	Moderate Major	x Replace	52%	\$1,377,380	extra capacity for major projects.
D3010 Electrical Service & Distribution		10076	e iviiioi	ividuerate	x Replace	3270	\$1,377,380	Wiring on the Heritage building it does not meet
DECCO Lighting and Branch Wining		1000/ Non	e Minor	Madarata y Majar	Replace	20%	¢250.610	code standards and is mostly original.
D5020 Lighting and Branch Wiring	Value / Data Sustana	100% Non		Moderate x Major		20%	\$358,618	code standards and is mostly original.
D5030 Communications & Security	Voice / Data System	80% Non		Moderate Major	Replace		\$0	
	Clock / Intercom System	80% Non		Moderate Major	Replace		\$0	
	Closed Circuit Surveillance	Non		Moderate Major	Replace		\$0	
	Access Control System	Non		Moderate Major	Replace		\$0	
	Intrusion Alarm System	48% Non	e Minor	Moderate Major	Replace		\$0	Main and Arts buildings.
	Fire Alarm / Detection	100% Non	e Minor	Moderate Major	Replace		\$0	
	Lighting Control System	48% Non	e Minor	Moderate Major	Replace		\$0	Main and Arts buildings.
D5090 Other Electrical Systems	NOT USED	Non	e Minor	Moderate Major	Replace			
			<u> </u>					_
E EQUIPMENT & FURNISHINGS								
E10 Equipment								
E1010 Commercial Equipment	Food Service	20% x Non	e Minor	Moderate Major	Replace		\$0	
	Vocational	16% Non	e x Minor	Moderate Major	Replace	100%	\$23,516	
E1020 Institutional Equipment	Science	31200 x Non	e Minor	Moderate Major	Replace		\$0	
1	Art	37000 x Non		Moderate Major	Replace		\$0	
	Stage Performance	6600 x Non		Moderate Major	Replace		\$0	
	Restroom Accessories/Stalls	100% Non		x Moderate Major	Replace	33%	\$136,882	Commons and VoTech buildings.
F1030 Vahiaulas Fauinment	NOT USED			Moderate Major	Replace	3370	\$130,882	commons and vorcen bandings.
E1030 Vehicular Equipment		Non						
E1090 Other Equipment	NOT USED	Non	e Minor	Moderate	Replace			
E20 Furnishings			—		— .		4	Commence and Mattack buildings
E2010 Fixed Furnishings		100% Non		Moderate x Major	Replace	33%	\$403,102	Commons and VoTech buildings.
E2020 Movable Furnishings		100% x Non	e Minor	Moderate	Replace		\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED								
G BUILDING SITE WORK								
G10 Site Preparation	NOT USED							
G20 Site Improvements					_			
G2010 Roadways		42390 x Non		Moderate Major	Replace		\$0	
G2020 Parking Lots		141426 x Non	e Minor	Moderate Major	Replace		\$0	
G2030 Pedestrian Paving		75000 x Non	e Minor	Moderate Major	Replace		\$0	
G2040 Site Development		2500 x Non	e Minor	Moderate Major	Replace		\$0	
G2050 Landscaping		45000 x Non		Moderate Major	Replace		\$0	
G30 Site Mechanical Utilities								
G30 Site Mechanical Utilities G3010 Water Supply	Domestic	100 x Non	Minor	Moderate Major	Renlace		50	
G30 Site Mechanical Utilities G3010 Water Supply	Domestic Eiro	100 x Non		Moderate Major	Replace	-	\$0 \$0	
G3010 Water Supply	Domestic Fire	100 x Non	e Minor	Moderate	Replace		\$0	
G3010 Water Supply G3020 Sanitary Sewer		100 x Non 100 x Non	e Minor e Minor	Moderate Major Moderate Major	Replace Replace		\$0 \$0	
G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer		100 x Non 100 x Non 100 x Non	e Minor e Minor e Minor	Moderate Major Moderate Major Moderate Major	Replace Replace Replace		\$0 \$0 \$0	
G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution		100 x Non 100 x Non 100 x Non 100 x Non Non	e Minor e Minor e Minor e Minor	Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace Replace Replace		\$0 \$0 \$0 \$0	
G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution		100 x Non 100 x Non 100 x Non Non Non	e Minor e Minor e Minor e Minor e Minor e Minor	Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace Replace Replace Replace		\$0 \$0 \$0 \$0 \$0 \$0	
G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution		100 x Non 100 x Non 100 x Non 100 x Non Non	e Minor e Minor e Minor e Minor e Minor e Minor	Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace Replace Replace		\$0 \$0 \$0 \$0	
G3010 Water Supply G3020 Sanitary Sewer G3030 Storm Sewer G3040 Heating Distribution G3050 Cooling Distribution		100 x Non 100 x Non 100 x Non Non Non	e Minor e Minor e Minor e Minor e Minor e Minor	Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major Moderate Major	Replace Replace Replace Replace Replace		\$0 \$0 \$0 \$0 \$0 \$0	

G3090 Other Site Mechanical Utilities G40 Site Electrical Utilities	NOT USED		None	Minor		Moderate		Major	Replace		
G4010 Electrical Distribution	Service	100%	x None	Minor		Moderate	可	Major	Replace	\$0	
	Generator	48%	x None	Minor		Moderate		Major	Replace	\$0	100A 3 phase for the Main and Arts buildings.
G4020 Site Lighting		100%	x None	Minor		Moderate		Major	Replace	\$0	
G4030 Site Communications & Security		100%	x None	Minor		Moderate		Major	Replace	\$0	
G4090 Other Site Electrical Utilities	NOT USED		None	Minor		Moderate		Major	Replace		
G90 Other Site Construction	NOT USED					_					
OTHER											
Description of System						Unit of Measure		Quantity	Unit Budget	Extended	Notes
										\$0	
										\$0	
										\$0	
							L			\$0	
										\$0	
							L			\$0	
]		Ĺ			\$0	

Physical Condition Budget Sub-Total	\$10,543,450
Budgeted Development Costs	\$4,006,511
Physical Condition Budget TOTAL	\$14,549,961
Cost with Escalation to June 2023	\$16,586,955
Cost with Escalation to June 2024	\$17,250,434
Cost with Escalation to June 2025	\$17,940,451
Replacement Budget	\$172,470,113