



Dashboard Home Search

School Name & Location



SAU Name RSU 63/MSAD 63
School Name Eddington School
School Address 440 Main Road
Eddington
ME
04428

School CountyPenobscotSchool Phone Number207-843-6010GradesPK-01School TypePublic

Notes/Comments:

Site & Infrastructure

of Acres 8
Water System Public/Muncipal
Sewage Waste Disposal System On Site Septic
Site Connected to Public Sidewalks No
Separate Bus/Car Traffic loops Yes
In the 100 Year Floodplain No
Recreational field / area funded through the federal LWCF program No
Notes/Comments:

School Building Features

Building StatusOpenShared BuildingSingle SchoolYear of Original Construction1955Historical StatusNo

Year Addition Constructed	1972, 1994
Year of Substantial Renovations (>50%)	2022
# of Stories	1
# of Students	128
Square Footage Per Student	178
Square Footage of Building	22800
# of Additional Spaces	0
Total Square Footage of Additional Spaces	0
Notes/Comments:	

HVAC System & Air Quality

Mechanical Ventilation Building Coverage 67% to 100% Type of Mechanical Ventilation Energy Recovery Ventilation (ERV) >13 MERV (Min Efficiency Reporting Values) Yes Air Conditioning Building Coverage 1% to 33% Type of Air Conditioning Window Unit Heating System Steam/Hot Water Heating System **Heating Energy Source** Propane Age of Heating System Over 20 Years Control System Building Management System/Building Automated System (BAS) On-Site Power Generation Source None **Electrical Power System** Three Phase Back-Up Generator No % of Building w/ LED Lighting 0% % of Building w/ Lighting Controls 0% Notes/Comments:

Building Type

Roof StructureWoodRoof PitchPitchedBuilding Exterior SidingVinylExterior Wall StructureWood FrameInterior Wall StructureWood StudDocumented Structural DeficienciesUnknownNotes/Comments:

Site & Building Accessibility

ADA Accessible Site

Parking and Passenger Loading Zones	No
Building Approach/Ramps	No
Building Entrance	Yes
Playgrounds	No

Ballfield(s)

N/A

ADA Building Accessibility

Alternative Accessible Entrance	N/A
Emergency Exits	Yes
Door Clearance	Yes
Room and Exit Signs	No
Interior Signs	No
Restrooms	Yes
Drinking Fountains	Yes
Water Bottle Filling Station	Yes

Notes/Comments: No ballfields at this school. The vestibule has an intercom system and is accessible. No way finder signs in this building

Hazardous Materials & Environmental Conditions

Hazardous Material/Condition	Identified in Survey and Remediated	Identified in Survey and Not Remediated	Not Identified in Survey	Not Surveyed	Unknown
Radon					\
Mold				√	
Air Quality				√	
Lead					✓
Asbestos	√				
PCBS			√		
PFAS			√		

Recurring Flooding

Notes/Comments: Would survey mold and air quality if asked.

Educational Program & Planning

SAU Reported Sufficient Space

PreK/Early Childhood

General Classrooms

Science Classrooms

N/A

Yes

Special Ed Yes
Health Clinic Yes

Kitchen/Cafeteria Yes

Physical Education Yes

Library Yes
Music Yes
Art Yes

STEM/STEAM N/A

Guidance/Career Prep

Gender Neutral Facilities

Bathrooms Yes

Locker/Changing Rooms

N/A
Showers

N/A

SAU Long-Term Plan (10 Years)

Consolidation

Notes/Comments:

Fire Protection System

% of Fire Alarm Coverage 67% to 100%

% of Sprinkler System Coverage 67% to 100%

% of Smoke Alarm Coverage 67% to 100%

Water Source Used for Fire Protection Public

Notes/Comments:

Security/Safety

Single Point of Entry No

Location of Office at Main Entrance

Security Features of Main Entrance Camera/Video Surveillance System, Intercom Communications System

Security Features Building Zoned & Able to be Electronically Locked Down, Classroom Doors with Lockable Hardware, School Emergency Alert/Panic Button, Exterior of Building Speaker System, Exterior Door Numbering Clearly Visible from Inside & Outside of Door

Notes/Comments:

Back to Search