

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM	5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM
-----------------------------------	--	--

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
27 CAD #:	B3A	Pre-Formed Pipe Insulation 1954 Original Building	ROOM 1506B (DISTRICT KITCHEN DOCK OFFICE)	2 Lin Ft	N	10 CH, 15 AM, 5 CR	5
Comments: IN WALL PENETRATION ABOVE EAST ENTRANCE. INACCESSIBLE FOR REMOVAL.					Sample #:		
31 CAD #:	B3A	Pre-Formed Pipe Insulation 1954 Original Building	ROOM 1508 (FOOD SERVICE KITCHEN AREA)	205 Lin Ft	N	10 CH, 15 AM, 5 CR	5
Comments: ABOVE CEILING. 20' FROM FLOOR.					Sample #:		
32 CAD #:	A3A	Mudded Pipe Joints on Pre-formed Insulation 1954 Original Building	ROOM 1508 (FOOD SERVICE KITCHEN AREA)	14 Joints	N	ASSUMED	5
Comments: ABOVE CEILING. 20' FROM FLOOR.					Sample #:		
33 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation	ROOM 1508 (FOOD SERVICE KITCHEN AREA)	16 Joints	N	20 CH, 5 AM	5
Comments: ABOVE CEILING. 20' FROM FLOOR.					Sample #: 2001-1501-8A		
34 CAD #:	X0E	Miscellaneous Material Red Duct Caulk	ROOM 1508 (FOOD SERVICE KITCHEN AREA)	300 Sq Ft	N	2 CH	5
Comments: ABOVE CEILING.					Sample #: 022410ML-48		
35 CAD #:	X1C	Miscellaneous Material 6" Red Quarry Tile	ROOM 1508 (FOOD SERVICE KITCHEN AREA)	2400 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
38 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation	ROOM 1084 (FOOD SERVICE DISHWASHING ROOM)	4 Joints	N	20 CH, 5 AM	5
Comments: ABOVE CEILING. ON ROOF DRAIN LINE. 20' FROM FLOOR.					Sample #: 065-JJT-2		
44 CAD #:	B3A	Pre-Formed Pipe Insulation 1954 Original Building	ROOM 1522 (CUSTODIAL CLOSET/PIPE CHASE)	6 Lin Ft	N	10 CH, 15 AM, 5 CR	5
Comments: ABOVE PLASTER CEILING. 20' FROM FLOOR.					Sample #:		
45 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation	ROOM 1522 (CUSTODIAL CLOSET/PIPE CHASE)	5 Joints	N	20 CH, 5 AM	5
Comments:					Sample #:		
47 CAD #:	B3A	Pre-Formed Pipe Insulation 1954 Original Building	KITCHEN MEN'S RESTROOM 1078/1079	10 Lin Ft	N	10 CH, 15 AM, 5 CR	5
Comments: ABOVE CEILING. 20' FROM FLOOR.					Sample #: 065-JJT-7, 8, 9		
49 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation	KITCHEN WOMEN'S RESTROOM 1081/1081A	8 Joints	N	20 CH, 5 AM	5
Comments: ACCESS THROUGH WALL HATCH. 20' FROM FLOOR. BETWEEN LOCKERS & RESTROOM.					Sample #: 065-JJT-1		
50 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	ROOM 1516 (DISTRICT KITCHEN BOILER ROOM)	35 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
54 CAD #:	V0B	Sink Undercoating Black	ROOM 1064 (WORK ROOM IN IMT)	8 Sq Ft	N	6 CH	5
Comments: ONE (1) DOUBLE SINK.					Sample #: 022410ML-33		
60 CAD #:	R0P	Baseboard/Mopboard Adhesive 6" Gray	ROOM 1404A (COMPUTER LAB B)	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
171 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Tan w/Gray & White Speckles	ROOM 1612A (ELECTRICIAN'S SHOP OFFICE)	80 Sq Ft	N	15 CH (MASTIC ONLY)	5
Comments:					Sample #: 022410ML-20; 065-JJT-34		
173 CAD #:	K2Z	12" x 12" Vinyl Floor Tile & Mastic Kentile Miscellaneous Colored Tile	TRADES MEZZANINE STORAGE	50 Sq Ft	N	ASSUMED	5
Comments: STORED.					Sample #:		
174 CAD #:	K1M	Sheet Vinyl Flooring & Adhesive Brown w/Red and Cream Streaks	TRADES MEZZANINE STORAGE	25 Sq Ft	N	ASSUMED	5
Comments: STORED, 2 BOXES.					Sample #:		
175 CAD #:	K1N	Sheet Vinyl Flooring & Adhesive Red w/Cream Streaks	TRADES MEZZANINE STORAGE	10 Sq Ft	N	ASSUMED	5
Comments: STORED.					Sample #:		
178 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic White w/Brown Streaks	ROOM 1609A (CARPENTER'S OFFICE)	160 Sq Ft	N	3 CH (TILE), 3 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 022410ML-19; 2001-1501-AL-7A		
187 CAD #:	P0B	Fire Doors Metal - 3 Hr Rating (Underwriter's Laboratories)	ROOM 1620B	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
188 CAD #:	P0B	Fire Doors Metal - 3 Hr Rating (Underwriter's Laboratories)	ROOM 1626 (MOTOR OIL)	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		