

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM	5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM
-----------------------------------	--	--

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
11 CAD #:	X1L	Miscellaneous Material 2" Tan Ceramic Floor Tile System	CUSTODIAL OFFICE RESTROOM 1313B	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
21 CAD #:	P0G	Fire Doors Wood -1.5 Hr Rating (Weyerhaeuser)	ELECTRICAL ROOM 0102	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
22 CAD #:	B1A	Air Cell Pipe Insulation 1929 Original Building	1929 ORIGINAL BUILDING UNEXCAVATED AREA	1 Lin Ft	Y	ASSUMED	1
Comments: DIRT CRAWL SPACE W/POTENTIAL FOR CONTAMINATION. MONITOR.					Sample #:		
23 CAD #:	A1A	Mudded Pipe Joints on Air Cell Insulation 1929 Original Building	1929 ORIGINAL BUILDING UNEXCAVATED AREA	1 Joints	Y	ASSUMED	1
Comments: DIRT CRAWL SPACE W/POTENTIAL FOR CONTAMINATION. MONITOR.					Sample #:		
27 CAD #:	X1F	Miscellaneous Material 6" Red Quarry Tile	STORAGE 1310	130 Sq Ft	N	ASSUMED	5
Comments: HALLWAY TO BOILER ROOM STAIRS.					Sample #:		
28 CAD #:	P0I	Fire Doors Wood -1 Hr Rating (Universal)	STORAGE 1310	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
32 CAD #:	U0A	Light Pad Insulation Round	STORAGE CLOSET 1011A	1 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
43 CAD #:	X0A	Miscellaneous Material Slate Chalkboard Adhesive (1952)	THROUGHOUT 1952 ADDITION	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
44 CAD #:	X0B	Miscellaneous Material Tackboard Adhesive (1952)	THROUGHOUT 1952 ADDITION	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
50 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1952 Addition	CAFETERIA STAGE STORAGE ROOMS 1102 & 1103	600 Sq Ft	N	ASSUMED	5
Comments: ON CONCRETE. UNDER CARPET IN ROOM 1103.					Sample #:		
56 CAD #:	X0I	Miscellaneous Material Exterior Door/Window Caulking	LOBBY/Common Area 1000	2 Sq Ft	N	4 CH	5
Comments: NEXT TO MAIN OFFICE. ORIGINAL BUILDING ENTRANCE.					Sample #: 072915BV-06		
57 CAD #:	X1I	Miscellaneous Material 1" Gray Ceramic Floor Tile System	BOYS' RESTROOM 1402	180 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
58 CAD #:	X1I	Miscellaneous Material 1" Gray Ceramic Floor Tile System	GIRLS' RESTROOM 1401	180 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
62 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 1311	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
65 CAD #:	X1A	Miscellaneous Material Beige Terrazzo-Look Countertops	ROOM 1304	15 Sq Ft	N	25 CH	5
Comments: AROUND SINK. PEELING AT SOUTHWEST CORNER. MONITOR.					Sample #: 121508-MA-07		
68 CAD #:	P0I	Fire Doors Wood -1 Hr Rating (Universal)	STORAGE ROOM 1306	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
69 CAD #:	X1A	Miscellaneous Material Beige Terrazzo-Look Countertops	ROOM 1309	15 Sq Ft	N	25 CH	5
Comments: AROUND SINK. SCRATCHES THROUGHOUT. MONITOR.					Sample #:		
70 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 1309	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
73 CAD #:	X0C	Miscellaneous Material Chalkboard Adhesive (1969)	THROUGHOUT 1969 ADDITION	900 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
74 CAD #:	X0D	Miscellaneous Material Tackboard Adhesive (1969)	THROUGHOUT 1969 ADDITION	250 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
79 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Light Gray w/Gray & White Flecks (201x)	ROOM 1302	138 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
80 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Beige w/Black Streaks (1969)	ROOM 1302	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET. NORTH END OF ROOM.					Sample #: 2001-01118-17		
90 CAD #:	X1J	Miscellaneous Material 6" Red Quarry Tile (1969)	STAIRWELL 1399C	600 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
94 CAD #:	X1J	Miscellaneous Material 6" Red Quarry Tile (1969)	LOWER LEVEL STORAGE 1303A OFF 1969 ADDITION STAIRWELL	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
95 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & Beige Streaks (1969)	LOWER LEVEL STORAGE 1303A OFF 1969 ADDITION STAIRWELL	45 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: ONE (1) BOX OF STORED TILE ON GRAY METAL SHELF.					Sample #:		
97 CAD #:	X0E	Miscellaneous Material Chalkboard/Tackboard Adhesive (1991)	THROUGHOUT 1991 ADDITION	700 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
101 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Beige w/Black Streaks (1969)	ROOM 1303	580 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET IN 1969 ADDITION WEST PORTION OF ROOM.					Sample #:		
102 CAD #:	P0B	Fire Doors Wood Composite - 1 Hr Rating (Weldwood)	1969 ADDITION 2ND FLOOR STAIRWELL 2399C	40 Sq Ft	N	40 CH, 5 AM	5
Comments: TWO (2) DOORS.					Sample #: 121508-MA-12		
104 CAD #:	P0J	Fire Doors Wood -1.5 Hr Rating (Eggers Industries)	ENTRANCE 1200A	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
106 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Light Gray w/Gray & White Flecks (201x)	ROOM 1202	125 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
110 CAD #:	P0B	Fire Doors Wood Composite - 1 Hr Rating (Weldwood)	STAIRWELL 2399C	40 Sq Ft	N	40 CH, 5 AM	5
Comments: TWO (2) DOORS.					Sample #:		
114 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & Beige Streaks (1969)	1969 ADDITION 2ND FLOOR HALLWAY	725 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: SCRATCHES THROUGHOUT. EXPOSED MASTIC NEAR 1305A AND 2302. SEALED WITH WAX. MONITOR.					Sample #: 2001-1501-AK-1		
115 CAD #:	X1B	Miscellaneous Material Light Green & Beige Terrazzo-Look Countertop	ROOM 2307	40 Sq Ft	N	25 CH	5
Comments: AT WINDOWS. CHIPPED AT RADIATOR COVER & CRACKING AT OTHER LOCATIONS.					Sample #: 121508-MA-15		
119 CAD #:	X1B	Miscellaneous Material Light Green & Beige Terrazzo-Look Countertop	ROOM 2309	40 Sq Ft	N	25 CH	5
Comments: AT WINDOWS. CRACKING AT RADIATOR COVER.					Sample #:		
122 CAD #:	X1B	Miscellaneous Material Light Green & Beige Terrazzo-Look Countertop	ROOM 2302	40 Sq Ft	N	25 CH	5
Comments: AT WINDOWS. CHIPPED AND CRACKED AT RADIATOR COVER. MONITOR.					Sample #:		
128 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 2311	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
131 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 2304	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
134 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 2313	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
137 CAD #:	K0H	9" x 9" Vinyl Floor Tile & Mastic Tan w/Black & Red Marbling (1952)	ROOM 2306	625 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments:					Sample #: 2001-01118-14		
138 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Beige w/Black Streaks (1969)	ROOM 2306	10 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments: REPLACEMENT TILES AT RADIATOR.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
147 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Solid Army Green	1929 ORIGINAL BUILDING 2ND FLOOR HALLWAY	135 Sq Ft	N	5 CH	5
Comments: CRACKS & SCRATCHES THROUGHOUT. CHIPS IN TILE OUTSIDE ROOM 2101 AND ROOM 2102. SEALED WITH WAX. MONITOR.					Sample #: 2001-01118-18		
148 CAD #:	K0E	9" x 9" Vinyl Floor Tile & Mastic Solid Black	1929 ORIGINAL BUILDING 2ND FLOOR HALLWAY	135 Sq Ft	N	3 CH (TILE)	5
Comments: ONE (1) TILE CHIPPED WITH PIECE MISSING ON EAST END. CRACKS & SCRATCHES THROUGHOUT. SEALED WITH WAX.					Sample #: 2001-0301-JC-18		
149 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & Beige Streaks (1969)	1929 ORIGINAL BUILDING 2ND FLOOR HALLWAY	8 Sq Ft	N	5 CH (TILE & MASTIC)	5
Comments:					Sample #:		
150 CAD #:	K3B	Miscellaneous Flooring 9" x 27" Army Green Border Tiles	1929 ORIGINAL BUILDING 2ND FLOOR HALLWAY	70 Sq Ft	N	ASSUMED	5
Comments: CRACKS, DENTS & SCRATCHES THROUGHOUT. SEALED WITH WAX.					Sample #:		
152 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1929 Original Building	ROOM 2101	700 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
155 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1929 Original Building	ROOM 2102	700 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
160 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1929 Original Building	THROUGHOUT 1929 ORIGINAL BUILDING 3RD FLOOR	1400 Sq Ft	N	ASSUMED	5
Comments: SOME UNDER CARPET.					Sample #:		
161 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Solid Army Green	1929 ORIGINAL BUILDING 3RD FLOOR HALLWAY	135 Sq Ft	N	5 CH	5
Comments: UNDER CARPET. PRESENCE VERIFIED. QUANTITY ASSUMED TO BE THE SAME AS 2ND FLOOR HALLWAY.					Sample #:		
162 CAD #:	K0E	9" x 9" Vinyl Floor Tile & Mastic Solid Black	1929 ORIGINAL BUILDING 3RD FLOOR HALLWAY	135 Sq Ft	N	3 CH (TILE)	5
Comments: UNDER CARPET. PRESENCE VERIFIED. QUANTITY ASSUMED TO BE THE SAME AS 2ND FLOOR HALLWAY.					Sample #:		
163 CAD #:	K3B	Miscellaneous Flooring 9" x 27" Army Green Border Tiles	1929 ORIGINAL BUILDING 3RD FLOOR HALLWAY	70 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
168 CAD #:	P0K	Fire Doors Metal -1.5 Hr Rating (Underwriters Laboratories)	STAIRWELL 3399B	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		