

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM		5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM			
IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assessment Category
20 CAD #:	D2A	Interior Boiler Insulation Interior Refractory (Boiler #1)	BOILER ROOM 0110	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
22 CAD #:	D2B	Interior Boiler Insulation Interior Refractory (Boiler #2)	BOILER ROOM 0110	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
28 CAD #:	P0A	Fire Doors Wood Composite - Weldwood	ENTRANCE HALLWAY TO BOILER ROOM	40 Sq Ft	N	20 CH	5
Comments: TWO (2) DOORS.					Sample #: 031709-MA-19		
29 CAD #:	P0A	Fire Doors Wood Composite - Weldwood	CUSTODIAL OFFICE 0109	20 Sq Ft	N	20 CH	5
Comments: ONE (1) DOOR.					Sample #:		
32 CAD #:	X1A	Miscellaneous Material 1" Beige Ceramic Floor Tile System	BASEMENT RESTROOM 0101	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
39 CAD #:	X1B	Miscellaneous Material 6" Tan Quarry Tile	STAIRWELL 0199A	160 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
41 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	GYMNASIUM 1108	550 Sq Ft	N	3 CH	5
Comments:					Sample #: 031709-MA-15, 20		
43 CAD #:	T0A	Light Cord Insulation White	GYMNASIUM 1108	12 Lin Ft	N	ASSUMED	5
Comments: FOUR (4) LIGHTS.					Sample #:		
44 CAD #:	P0C	Fire Doors Wood w/White Interior (No Tag)	GYMNASIUM STORAGE 1105	20 Sq Ft	N	10 CH, 5 AM	5
Comments: ONE (1) DOOR. WEST DOOR. AREA COVERED UP WITH CARDBOARD.					Sample #: 031709-MA-12		
46 CAD #:	T0A	Light Cord Insulation White	STAGE 1106	6 Lin Ft	N	ASSUMED	5
Comments: TWO (2) LIGHTS.					Sample #:		
47 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1952 Original Building (Elevated)	STAGE 1106	320 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
50 CAD #:	X0O	Miscellaneous Material Carpet Tackboard Adhesive	HALLWAY 1100	170 Sq Ft	N	ASSUMED	5
Comments: OUTSIDE ROOMS 1114 & 1115 ON WALL.					Sample #:		
52 CAD #:	P0B	Fire Doors Wood - 1 Hr Rating (Algoma)	CAFETERIA 1103	80 Sq Ft	N	ASSUMED	5
Comments: FOUR (4) DOORS.					Sample #:		
55 CAD #:	X0R	Miscellaneous Material Milkboard Adhesive	KITCHEN 1104	250 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
60 CAD #:	X1F	Miscellaneous Material 1" Gray Ceramic Floor Tile System	RESTROOM 1102B	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
66 CAD #:	X1F	Miscellaneous Material 1" Gray Ceramic Floor Tile System	RESTROOM 1101B	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
68 CAD #:	X1F	Miscellaneous Material 1" Gray Ceramic Floor Tile System	BOYS' RESTROOM 1110	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
70 CAD #:	X1G	Miscellaneous Material 1" Blue Ceramic Floor Tile System	GIRLS' RESTROOM 1112	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
90 CAD #:	X1J	Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System	BOYS' RESTROOM 1210	165 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
91 CAD #:	X1K	Miscellaneous Material Multi-Sized Yellow Ceramic Floor Tile System	GIRLS' RESTROOM 1211	145 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
94 CAD #:	X0P	Miscellaneous Material Interior Window Glazing	THROUGHOUT 1956 ADDITION CLASSROOMS	6 Sq Ft	N	4 CH	5
Comments: AT CLASSROOM ENTRANCES.					Sample #: 072815BV-01		
95 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1301	10 Sq Ft	N	8 CH	5
Comments: NORTH WALL. BEHIND WHITEBOARDS.					Sample #:		
96 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1301	10 Sq Ft	N	5 CH	5
Comments: NORTH WALL.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
98 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1302	10 Sq Ft	N	8 CH	5
Comments: SOUTH WALL.					Sample #:		
99 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1302	10 Sq Ft	N	5 CH	5
Comments: SOUTH WALL.					Sample #:		
101 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1303	10 Sq Ft	N	8 CH	5
Comments: NORTH WALL.					Sample #:		
102 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1303	R Sq Ft	N	5 CH	5
Comments: NORTH WALL.					Sample #:		
105 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1304	10 Sq Ft	N	8 CH	5
Comments: SOUTH WALL.					Sample #: 112812MV-02		
106 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1304	10 Sq Ft	N	5 CH	5
Comments: SOUTH WALL.					Sample #: 112812MV-03		
108 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1305	10 Sq Ft	N	8 CH	5
Comments: NORTH WALL.					Sample #:		
109 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1305	10 Sq Ft	N	5 CH	5
Comments: NORTH WALL.					Sample #:		
111 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)	ROOM 1306	10 Sq Ft	N	8 CH	5
Comments: SOUTH WALL.					Sample #:		
112 CAD #:	X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)	ROOM 1306	10 Sq Ft	N	5 CH	5
Comments: SOUTH WALL.					Sample #:		