

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM	5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM
-----------------------------------	--	--

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
6 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	THROUGHOUT 1970 ORIGINAL BUILDING	30 Joints	N	30 CH	5
Comments: ESTIMATED AMOUNTS IN WALL CHASES. INACCESSIBLE.					Sample #:		
9 CAD #:	J2A	Transite Piping/Ducting Supplied Air Ducts	THROUGHOUT 1970 ORIGINAL BUILDING	6600 Sq Ft	N	20 CH, 3 CR	5
Comments: VISIBLE IN LOWER MECHANICAL ROOMS.					Sample #: 041024-BF-35, 37		
10 CAD #:	X0N	Miscellaneous Material Caulk around Transite Duct Penetrations	THROUGHOUT 1970 ORIGINAL BUILDING	6600 Sq Ft	N	2 CH	5
Comments:					Sample #: 041024-BF-36, 37		
11 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	THROUGHOUT 1970 ORIGINAL BUILDING	15000 Sq Ft	Y	1.25 CH	5
Comments: WATER DAMAGE NEAR DOOR 13.					Sample #: 041024-BF-95, 96, 97, 98, 99, 100; 010710ML-01, 02, 03; 5091-1-7; 2001-1901-XX-29B		
14 CAD #:	X0H	Miscellaneous Material Wire Window Side Light Glazing Compound	THROUGHOUT 1970 ORIGINAL BUILDING	100 Sq Ft	N	7 CH	5
Comments:					Sample #: 041024-BF-78, 79; 041212MV-02		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
15 CAD #:	X0P	Miscellaneous Material Side Light Glazing Compound	THROUGHOUT 1970 ORIGINAL BUILDING	100 Sq Ft	N	2 CH	5
Comments: SAMPLE NUMBER 041024-BF-74 COLLECTED IN MEDIA CENTER WAS ANALYZED AS NONE DETECTED.					Sample #: 041024-BF-74, 75		
16 CAD #:	X0Q	Miscellaneous Material Glass Panel Glazing Compound above Demountable Walls	THROUGHOUT 1970 ORIGINAL BUILDING	200 Sq Ft	N	2 CH	5
Comments:					Sample #: 041024-BF-76, 77		
23 CAD #:	X1B	Miscellaneous Material 4" X 8" Quarry Tile System	THROUGHOUT 1970 ORIGINAL BUILDING RESTROOMS	5000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
24 CAD #:	X0A	Miscellaneous Material Pipe/Valve Flange Gaskets	WATER HEATER ROOM 1317B (OFF CUSTODIAL OFFICE)	4 Sq Ft	N	ASSUMED	5
Comments: FOUR (4) OLD FLANGES.					Sample #:		
25 CAD #:	P0A	Fire Doors Metal Jacket -1.5 Hr Rating (Curries)	WATER HEATER ROOM 1317B (OFF CUSTODIAL OFFICE)	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
27 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	FAN ROOM 1318	1 Joints	N	30 CH	5
Comments: INACCESSIBLE ABOVE DUCTWORK NEAR CEILING AT EAST WALL.					Sample #: 2001-1901-EC-01, 02		
30 CAD #:	P0A	Fire Doors Metal Jacket -1.5 Hr Rating (Curries)	FAN ROOM 1318	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. NORTH ENTRANCE.					Sample #:		
32 CAD #:	V0G	Sink Undercoating Stainless Steel Counter Undercoating	THROUGHOUT KITCHEN AREA	40 Sq Ft	N	12 CH	5
Comments:					Sample #: 041024-BF-50, 51		
33 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1321	8 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: AT WEST WALL.					Sample #:		
39 CAD #:	K3C	Miscellaneous Flooring Black Mastic	CAFETERIA 1311	10 Sq Ft	N	5 CH	5
Comments: AMOUNT ESTIMATED. RESIDUAL AROUND FLOOR VENTS.					Sample #: 122109-ML-08		
41 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1209B PIPE CHASE	8 Joints	N	30 CH	5
Comments: SIX (6) VISIBLE THROUGH SMALL HATCH. INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
42 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1209A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
43 CAD #:	V0D	Sink Undercoating Black	ROOM 1213	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
44 CAD #:	V0D	Sink Undercoating Black	ROOM 1214	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
45 CAD #:	V0D	Sink Undercoating Black	ROOM 1215	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
46 CAD #:	V0D	Sink Undercoating Black	ROOM 1212	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
47 CAD #:	V0D	Sink Undercoating Black	ROOM 1210	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
48 CAD #:	V0C	Sink Undercoating Coarse Gray	ROOM 1310	4 Sq Ft	N	10 CH	5
Comments: ONE (1) SINK.					Sample #:		
49 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1201B PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
50 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1201A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
51 CAD #:	V0D	Sink Undercoating Black	ROOM 1206	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
54 CAD #:	P0B	Fire Doors Wood -1.5 Hr Rating (Marshfield)	ROOM 0206 (MECHANICAL)	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
55 CAD #:	V0D	Sink Undercoating Black	ROOM 1208	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
56 CAD #:	V0D	Sink Undercoating Black	ROOM 1204	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 122109-ML-13		
57 CAD #:	V0D	Sink Undercoating Black	ROOM 1203	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
58 CAD #:	V0D	Sink Undercoating Black	ROOM 1202	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
59 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1306 (COPY ROOM)	350 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: TILES WEARING UNDER & AROUND COPY MACHINE & CABINETS. MAT INSTALLED NEAR COPIER.					Sample #:		
61 CAD #:	V0D	Sink Undercoating Black	ROOM 1306 (COPY ROOM)	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
62 CAD #:	V0D	Sink Undercoating Black	ROOM 1307/1308 (COMPUTER LAB)	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
63 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1109B PIPE CHASE	8 Joints	N	30 CH	5
Comments: PARTIALLY VISIBLE THROUGH SMALL WALL PANEL. INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
64 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1109A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
65 CAD #:	V0D	Sink Undercoating Black	ROOM 1113	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
66 CAD #:	V0D	Sink Undercoating Black	ROOM 1114	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
67 CAD #:	V0D	Sink Undercoating Black	ROOM 1115	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
68 CAD #:	V0D	Sink Undercoating Black	ROOM 1112	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
69 CAD #:	V0D	Sink Undercoating Black	ROOM 1110	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
75 CAD #:	K3B	Miscellaneous Flooring Black Mastic	ROOM 1604	500 Sq Ft	N	10 CH	5
Comments: UNDER CARPET.					Sample #:	122109-ML-06	
76 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1603	180 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: SCRATCHED THROUGHOUT. TILES BECOMING LOOSE NEAR DOOR. MONITOR.					Sample #:		
77 CAD #:	V0C	Sink Undercoating Coarse Gray	ROOM 1607	4 Sq Ft	N	10 CH	5
Comments: ONE (1) SINK.					Sample #:	122109-ML-10	
79 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1101B PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
80 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1101A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
81 CAD #:	V0D	Sink Undercoating Black	ROOM 1106	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
85 CAD #:	P0B	Fire Doors Wood -1.5 Hr Rating (Marshfield)	ROOM 0106 (MECHANICAL)	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
86 CAD #:	V0D	Sink Undercoating Black	ROOM 1108	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
87 CAD #:	V0D	Sink Undercoating Black	ROOM 1106	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
88 CAD #:	V0D	Sink Undercoating Black	ROOM 1104	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
89 CAD #:	V0D	Sink Undercoating Black	ROOM 1102	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
112 CAD #:	P0C	Fire Doors Wood -1 Hr Rating (Underwriters Laboratories)	MECHANICAL ROOM 1011	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
113 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	WOMEN'S RESTROOM 1501A PIPE CHASE	10 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
114 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	MEN'S RESTROOM 1501B PIPE CHASE	10 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
115 CAD #:	V0D	Sink Undercoating Black	ROOM 1502	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
116 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1502	110 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments:					Sample #:		
117 CAD #:	K2PP	12" x 12" Vinyl Floor Tile & Mastic White w/Tan Mottle	ROOM 1502	5 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments:					Sample #: 041024-BF-85		
118 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1503	150 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: CIRCULAR INDENT IN TILE BY SINK					Sample #:		
119 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1504	90 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: MISSING 1/2 TILE AT AIR VENT.					Sample #:		
120 CAD #:	V0D	Sink Undercoating Black	ROOM 1504	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
121 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1505	225 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: MOST UNDER CARPET.					Sample #:		
122 CAD #:	V0D	Sink Undercoating Black	ROOM 1505	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
126 CAD #:	P0B	Fire Doors Wood - 1.5 Hr Rating (Marshfield)	ROOM 0508 (MECHANICAL)	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
127 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1506	325 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: CHIPPED IN MIDDLE OF ROOM. SEALED WITH WAX.					Sample #:		
128 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1507	225 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: MOST UNDER CARPET. SMALL GOUGE 10' FROM SINK.					Sample #:		
129 CAD #:	V0D	Sink Undercoating Black	ROOM 1507	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
133 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	GYMNASIUM STORAGE 1601B	50 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments:					Sample #:		
135 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	STAIRWELL 1699A TO GYMNASIUM MECHANICAL ROOM	120 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: INCLUDES REPLACEMENT TILES.					Sample #: 449-1		
136 CAD #:	K3A	Miscellaneous Flooring Brown w/Pink, Tan & Black Marbled Stair Treads & Mastic	STAIRWELL 1699A TO GYMNASIUM MECHANICAL ROOM	100 Sq Ft	N	3 CH (STAIR TREAD), NONE DETECTED (ADHESIVE)	5
Comments:					Sample #: 041024-BF-82; 122109-ML-04		
138 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BASEMENT LOCKER ROOM 0602	14 Joints	N	30 CH	5
Comments: ABOVE PLASTER CEILING. FOURTEEN (14) FITTINGS VISIBLE FROM HATCH ABOVE TOILET. INACCESSIBLE FOR REMOVAL.					Sample #:		
140 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	BASEMENT LOCKER ROOM STORAGE 0601	100 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
146 CAD #:	P0A	Fire Doors Metal Jacket -1.5 Hr Rating (Curries)	GYMNASIUM MECHANICAL ROOM 0603	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
147 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BASEMENT LOCKER ROOM 0604	1 Joints	N	30 CH	5
Comments: ABOVE PLASTER CEILING. VISIBLE FROM HATCH IN SHOWER AREA. INACCESSIBLE FOR REMOVAL.					Sample #:		
149 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	BASEMENT LOCKER ROOM STORAGE 0605	100 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments:					Sample #: 449-2		
151 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	STAIRWELL 1699B TO GYMNASIUM MECHANICAL ROOM	120 Sq Ft	N	5 CH (TILE), 8 CH (MASTIC)	5
Comments: INCLUDES REPLACEMENT TILES. CHIPPED ON MECHANICAL ROOM LANDING WITH MASTIC EXPOSED.					Sample #:		
152 CAD #:	K3A	Miscellaneous Flooring Brown w/Pink, Tan & Black Marbled Stair Treads & Mastic	STAIRWELL 1699B TO GYMNASIUM MECHANICAL ROOM	80 Sq Ft	N	3 CH (STAIR TREAD), NONE DETECTED (ADHESIVE)	5
Comments:					Sample #: 041024-BF-83		
153 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1509A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
154 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1509B PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED. SOME VISIBLE FROM SMALL HATCH.					Sample #:		
155 CAD #:	V0D	Sink Undercoating Black	ROOM 1510	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
156 CAD #:	V0D	Sink Undercoating Black	ROOM 1514	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
157 CAD #:	V0D	Sink Undercoating Black	ROOM 1515	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
158 CAD #:	V0D	Sink Undercoating Black	ROOM 1516	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
159 CAD #:	V0D	Sink Undercoating Black	ROOM 1517	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
160 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1401A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
161 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1401B PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
162 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Red Brick Pattern	TEACHERS' LOUNGE 1408	600 Sq Ft	N	3 CH (TILE), 10-15 CH (MASTIC)	5
Comments: SOME CHIPPING BY SMALL HEATER.					Sample #: 041024-BF-88, 89; 2001-1901-JC36		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
164 CAD #:	V0D	Sink Undercoating Black	ROOM 1402	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
165 CAD #:	V0D	Sink Undercoating Black	ROOM 1403	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
166 CAD #:	V0D	Sink Undercoating Black	ROOM 1404	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
167 CAD #:	V0D	Sink Undercoating Black	ROOM 1405/1406	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
171 CAD #:	P0B	Fire Doors Wood -1.5 Hr Rating (Marshfield)	ROOM 0406 (MECHANICAL)	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
173 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	BOYS' RESTROOM 1410B PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
174 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1970 Original Building	GIRLS' RESTROOM 1410A PIPE CHASE	8 Joints	N	30 CH	5
Comments: INACCESSIBLE IN WALL CHASE. ESTIMATED.					Sample #:		
176 CAD #:	V0D	Sink Undercoating Black	ROOM 1417	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
177 CAD #:	V0D	Sink Undercoating Black	ROOM 1418	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
179 CAD #:	V0D	Sink Undercoating Black	ROOM 1419	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
180 CAD #:	V0D	Sink Undercoating Black	ROOM 1420	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		