


INSPECTION CERTIFICATION for Saint Paul Public Schools -- Harding Senior High School

STATEMENT OF BUILDING ACCESS

On behalf of Saint Paul Public Schools for Harding Senior High School, I certify that I have provided access to all areas within the building to IEA's inspector identified below for the purpose of inspecting for asbestos-containing building materials (ACBM) as mandated by 40 CFR 763.85, "Inspections and Reinspections."


Additionally, I have discussed any concerns I have regarding identified or non-identified ACBM within this building.


Signature

8-6-24
Date of Inspection

INSPECTOR

As mandated by 40 CFR 763.85, "Inspections and Reinspections," I certify that I have inspected all accessible areas in Harding Senior High School for the purpose of identifying and assessing asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Inspector. A copy of my certification/accreditation is attached.


Signature
Grant Gervais
Print Name

8/6/24
Date of Inspection
A715101
State Certification/Accreditation Number

MANAGEMENT PLANNER

I certify that I have reviewed all of the inspection data for Harding Senior High School and have appropriately provided assessments and response actions for identified asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Management Planner. A copy of my certification/accreditation is attached.


Signature
Matt Lundberg
Print Name

10/3/2024
Date of Review
Am3896
State Certification/Accreditation Number

Inspector State Certification/Accreditation



m ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR

Certified by:

State of Minnesota
Department of Health

Expires: 05/16/2025

Grant O. Gervais
1031 13th Ave Se
Minneapolis, MN 55414

SPH

Director, Env. Health Div.

No. AI15101

Issued: 06/06/2024

Management Planner State Certification/Accreditation



m ASBESTOS
DEPARTMENT OF HEALTH MANAGEMENT
PLANNER

Certified by:

State of Minnesota
Department of Health

Expires: 08/02/2025

Matt A Lindberg
11816 Ghia St NE
Blaine, MN 55449

SPH

Director, Env. Health Div.

No. AM3896

Issued: 08/20/2024

Inspector State Certification/Accreditation



[Signature]
Director, Env. Health Div.

m ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR

Certified by:
State of Minnesota
Department of Health
Expires: 08/04/2024

Matt A Lindberg
11816 Ghia St NE
Blaine, MN 55449

No AI3896

Issued: 08/23/2023

Inspector State Certification/Accreditation



[Signature]
Director, Env. Health Div.

m ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR

Certified by:
State of Minnesota
Department of Health
Expires: 08/04/2024

Branden D Voigt
15784 Okapi St NW
Ramsey, MN 55303

No AI10892

Issued: 08/23/2023

Chart A - Immediate Response Situations

The following is a list of those events that contain damaged asbestos material and should be considered to be potential hazards. It is imperative that the following immediate response situations are corrected as soon as possible but no later than six months from the date of this inspection to avoid increased risk of exposure to airborne asbestos fibers. The district should take extra precaution to ensure that properly trained personnel use appropriate techniques to implement these responses.

Following is an explanation of the immediate Response Action codes identified in this report.

EPA ASSESSMENT CATEGORY				RESPONSE ACTION			
1 = Damaged or significantly damaged TSI ACM.				A = Cleanup ACM debris.			
2 = Damaged friable surfacing ACM.				B = Encapsulate slight damage on TSI.			
3 = Significantly damaged friable surfacing ACM.				C = Patch TSI and/or repair ACM cover.			
4 = Damaged or significantly damaged friable miscellaneous ACM.				D = Enclose or protect accessible sections with protective barrier.			
5 = ACBM with potential for damage.				E = Remove section of damaged ACM.			
6 = ACBM with potential for significant damage.				F = Remove ACM and replace with non-ACM.			
7 = Remaining friable ACBM or friable suspected ACBM.				G = Isolate area until repaired/removed.			
				H = Encapsulate slight damage.			
				I = Remove and replace damaged or loose tile section.			
				J = Monitor condition of material(s).			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Amount of Damage	EPA Assess.	Immediate Response Action	Comments
39 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Gray Marble w/Black Flecks	AUDITORIUM	2700 Sq Ft	10 Sq Ft	5	D	AISLE AREAS. SMALL PIECES MISSING IN AISLE THAT RUNS EAST/WEST, BY METAL RAILING LEGS. TILES CHIPPED W/PIECES MISSING NEXT TO SEATS C1 M15/16, N16 F1, M1, Z15, M31, N29, M33, M45, B1, T1, B12, Q13-15, Q33, Q35. RECOMMEND SEALING WITH WAX. MASTIC EXPOSED AND WEARING.
99 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray w/White & Black Streaks	ROOM 1301	900 Sq Ft	3 Sq Ft	5	I	TILE WEAR AT TEACHERS DESK. ONE MISSING TILE AND ONE CHIPPED TILE BY FIRE EXTINGUISHER. SEALED WITH WAX. FIVE TILES MISSING IN CENTER OF ROOM. MORE TILES COMING LOOSE
137 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Light Swirls	ROOM 1308A (STORAGE)	130 Sq Ft	3 Sq Ft	5	D	TILE IS WEARING. RECOMMEND SEALING WITH WAX.
140 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Light Swirls	ROOM 1308B (OFFICE)	130 Sq Ft	2 Sq Ft	5	D	CHIPPED TILES AND WORN TILES. RECOMMEND SEALING WITH WAX AND INSTALLING A CHAIR MAT.
210 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Light Swirls	ROOM 1327 (OFFICE)	150 Sq Ft	2 Sq Ft	5	D	WORN TILE. RECOMMEND SEALING WITH WAX AND INSTALLING A CHAIRMAT.
399 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Light Gray w/Light Swirls	GYMNASIUM STORAGE 1108	1 Sq Ft	3 Sq Ft	5	E	FOUR (4) PARTIAL TILES REMAINING ONLY AT ENTRANCE. MASTIC THROUGHOUT. RECOMMEND REMOVAL.

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Amount of Damage	EPA Assess.	Immediate Response Action	Comments
664 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray w/White & Black Streaks	ROOM 1459	800 Sq Ft	2 Sq Ft	5	D	SMALL CHIP AT ENTRANCE AND 8 FT IN FRONT OF ENTRANCE. WEARING UNDER TEACHERS DESK. RECOMMEND SEALING WITH WAX AND INSTALLING A CHAIR MAT.