

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
10 CAD #:	X1A	Miscellaneous Material Pipe/Valve Flange Gaskets	MIDDLE SCHOOL - BOILER ROOM 0114	4 Sq Ft	N	ASSUMED	5
Comments: FOUR (4) GASKETS. TWO (2) OLD VALVES.					Sample #:		
13 CAD #:	X1A	Miscellaneous Material Pipe/Valve Flange Gaskets	MIDDLE SCHOOL - TUNNELS OFF ROOM 0113	14 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
31 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1957 Original Building	MIDDLE SCHOOL - GIRLS' LOCKER ROOM SHOWER ROOM 0107C	10 Joints	N	20 CH, 35 AM	5
Comments: ESTIMATED IN WALLS AT FIXTURES FOR SHOWERS.					Sample #: 010709-MA-04		
43 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1957 Original Building	MIDDLE SCHOOL - BOYS' LOCKER ROOM SHOWER ROOM 0105A	6 Joints	N	20 CH, 35 AM	5
Comments: ESTIMATED IN WALLS AT FIXTURES FOR SHOWERS.					Sample #:		
44 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1957 Original Building	MIDDLE SCHOOL - BOYS' LOCKER ROOM SHOWER ROOM 0104B	10 Joints	N	20 CH, 35 AM	5
Comments: ESTIMATED IN WALLS AT FIXTURES FOR SHOWERS.					Sample #:		
50 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1957 Original Building (On-Grade)	MIDDLE SCHOOL - ROOM 0101 (GYMNASIUM)	7200 Sq Ft	N	10 CH	5
Comments:					Sample #: 010509-MA-06		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
67 CAD #:	V0L	Sink Undercoating White	MIDDLE SCHOOL - KITCHEN 1107	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
68 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1957 Original Building	MIDDLE SCHOOL - KITCHEN LOCKER ROOM 1103	1 Joints	N	20 CH, 35 AM	5
Comments: ABOVE CEILING. VISIBLE THROUGH HATCH OUTSIDE ROOM. INACCESSIBLE FOR REMOVAL.					Sample #:		
71 CAD #:	T0A	Light Cord Insulation Fuzzy, White	MIDDLE SCHOOL - AUDITORIUM CATWALK	6 Lin Ft	N	ASSUMED	5
Comments: TWO (2) CORDS ON ONE (1) FIXTURE. DIFFICULT TO ACCESS.					Sample #:		
72 CAD #:	T0A	Light Cord Insulation Fuzzy, White	MIDDLE SCHOOL - AUDITORIUM STAGE	32 Lin Ft	N	ASSUMED	5
Comments: SIXTEEN (16) CORDS ON FOUR (4) FIXTURES.					Sample #:		
73 CAD #:	S0AA	Wood Floor Felt / Vapor Barrier 1957 Original Building (Elevated)	MIDDLE SCHOOL - AUDITORIUM STAGE	2400 Sq Ft	N	ASSUMED	5
Comments: ROOM 1206 STORAGE GOOD PLACE FOR SAMPLING.					Sample #:		
84 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray/Green w/Black & White Streaks (1957)	MIDDLE SCHOOL - MAIN OFFICE LARGE RESTROOM	40 Sq Ft	N	5-10 CH (TILE & MASTIC)	5
Comments: UNDER SHEET VINYL FLOORING.					Sample #:		
87 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray/Green w/Black & White Streaks (1957)	MIDDLE SCHOOL - MAIN OFFICE NURSE'S RESTROOM	20 Sq Ft	N	5-10 CH (TILE & MASTIC)	5
Comments: UNDER SHEET VINYL FLOORING.					Sample #:		
94 CAD #:	V0L	Sink Undercoating White	MIDDLE SCHOOL - ROOM 1209	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
109 CAD #:	K3C	Miscellaneous Flooring Black Flooring Mastic	MIDDLE SCHOOL - ROOM 1215	80 Sq Ft	N	5-10 CH	5
Comments: UNDER 2' X 2' FLOORING (K3D) ON WOOD STAGE.					Sample #:	2001-1901-HPJH-4C	
110 CAD #:	S0AA	Wood Floor Felt / Vapor Barrier 1957 Original Building (Elevated)	MIDDLE SCHOOL - ROOM 1216	300 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
111 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray/Green w/Black & White Streaks (1957)	MIDDLE SCHOOL - ROOM 1216	300 Sq Ft	N	5-10 CH (TILE & MASTIC)	5
Comments: UNDER CARPET.					Sample #:	010509-MA-12B; 2001-01128-1; 2001-1901-HPJS-4C	
284 CAD #:	X1C	Miscellaneous Material 1" X 1" Maroon Ceramic Floor Tile System	SENIOR HIGH - THROUGHOUT RESTROOMS	4000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
286 CAD #:	X0H	Miscellaneous Material Slate Chalkboard Adhesive (1963)	SENIOR HIGH - THROUGHOUT 1963 ADDITION	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
287 CAD #:	X0I	Miscellaneous Material Tackboard Adhesive (1963)	SENIOR HIGH - THROUGHOUT 1963 ADDITION	3200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
295 CAD #:	J1B	Cementitious Panels Gray Table Tops	SENIOR HIGH - ROOM 0159	80 Sq Ft	N	ASSUMED	5
Comments: ON BUILT-IN COUNTER.					Sample #:		
297 CAD #:	X0E	Miscellaneous Material Wood Paneling Adhesive	SENIOR HIGH - OFFICE 0158	20 Sq Ft	N	5 CH	5
Comments: ONE (1) PANEL SECTION MISSING UNDER CHALKBOARD.					Sample #:	010709-MA-15	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
301 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - 1ST FLOOR GYMNASIUM 0401 WEST STORAGE	7 Joints	N	35 CH, 20 AM	5
Comments: ENTRANCE IS IN THE SOUTH WEST CORNER.					Sample #:		
303 CAD #:	X1C	Miscellaneous Material 1" X 1" Maroon Ceramic Floor Tile System	SENIOR HIGH - BOYS' LOCKER ROOM SHOWER & RESTROOM (NORTH & SOUTH)	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
304 CAD #:	X1C	Miscellaneous Material 1" X 1" Maroon Ceramic Floor Tile System	SENIOR HIGH - GIRLS' LOCKER ROOM SHOWER & RESTROOM (NORTH & SOUTH)	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
312 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 2ND FLOOR NORTH HALLWAY 1300	360 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING. ABOVE WINDOWS AT ENTRY & OUTSIDE FITNESS CENTER.					Sample #:		
322 CAD #:	K0E	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & White Streaks (1963)	SENIOR HIGH - OFFICE AREAS 1303-1311	3000 Sq Ft	N	3-5 CH (TILE), 10 CH (MASTIC)	5
Comments: MOST UNDER CARPET.					Sample #: 2001-1501-AA5		
326 CAD #:	K0E	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & White Streaks (1963)	SENIOR HIGH - ROOM 1314	215 Sq Ft	N	3-5 CH (TILE), 10 CH (MASTIC)	5
Comments: UNDER NEW WOOD FLOOR (2009 INSTALLATION).					Sample #:		
361 CAD #:	T0B	Light Cord Insulation Fuzzy, White (1970)	SENIOR HIGH - AUDITORIUM STAGE 1102	90 Lin Ft	N	ASSUMED	5
Comments: TEN (10) LIGHT FIXTURES W/THREE (3) CORDS EACH.					Sample #:		
362 CAD #:	X0D	Miscellaneous Material Coarse White Proscenium Curtains	SENIOR HIGH - AUDITORIUM STAGE 1102	1100 Sq Ft	N	ASSUMED	5
Comments: TWO (2) CURTAINS.					Sample #:		
363 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Weyerhaeuser)	SENIOR HIGH - AUDITORIUM STAGE 1102	80 Sq Ft	N	10 CH, 25 AM	5
Comments: FOUR (4) DOORS.					Sample #: 010709-MA-01		
366 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Weyerhaeuser)	SENIOR HIGH - AUDITORIUM BOILER ROOM 1110	20 Sq Ft	N	10 CH, 25 AM	5
Comments: ONE (1) DOOR.					Sample #:		
367 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Weyerhaeuser)	SENIOR HIGH - AUDITORIUM ELECTRICAL ROOM (1105)	20 Sq Ft	N	10 CH, 25 AM	5
Comments: ONE (1) DOOR.					Sample #:		
376 CAD #:	K0E	9" x 9" Vinyl Floor Tile & Mastic Gray w/Black & White Streaks (1963)	SENIOR HIGH - ROOM 1206 OFF ROOM 1208 (MEDIA CENTER)	50 Sq Ft	N	3-5 CH (TILE), 10 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 011209-MA-03		
378 CAD #:	X0G	Miscellaneous Material Chalkboard Adhesive (1970)	SENIOR HIGH - ROOM 1401	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
381 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 2ND FLOOR SOUTH HALLWAY OUTSIDE ROOM 1401	160 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING.					Sample #:		
388 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Multi-Shaded Gray Marble	SENIOR HIGH - ROOM 1215	10 Sq Ft	N	8 CH	5
Comments: BELOW WEST WALL.					Sample #:		
392 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Multi-Shaded Gray Marble	SENIOR HIGH - ROOM 1217	10 Sq Ft	N	8 CH	5
Comments: BELOW SOUTH WALL.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
402 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 3RD FLOOR NORTH HALLWAY	360 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING. ABOVE NORTH LINK ENTRANCE & FITNESS CENTER WINDOWS.					Sample #:		
432 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Weyerhaeuser)	SENIOR HIGH - 1970 ADDITION 3RD FLOOR MECHANICAL ROOM 2402	24 Sq Ft	N	10 CH, 25 AM	5
Comments: ONE (1) DOOR.					Sample #:		
434 CAD #:	X0J	Miscellaneous Material McQuay AHU Tar Gaskets	SENIOR HIGH - 1970 ADDITION 3RD FLOOR MECHANICAL ROOM 2402	10 Sq Ft	N	5 CH	5
Comments:					Sample #: 080111-JC-01		
435 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 3RD FLOOR SOUTH HALLWAY OUTSIDE ROOM 2401 & MECHANICAL ROOM 2402	160 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING.					Sample #: 220-14		
456 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 4TH FLOOR NORTH HALLWAY	360 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING.					Sample #:		
465 CAD #:	K0D	9" x 9" Vinyl Floor Tile & Mastic Multi-Shaded Gray Marble	SENIOR HIGH - ROOM 3306A	290 Sq Ft	N	8 CH	5
Comments: UNDER CARPET.					Sample #: 220-21		
475 CAD #:	J1F	Cementitious Panels Pegboard	SENIOR HIGH - ROOM 3311 STORAGE ROOMS A & B	100 Sq Ft	N	ASSUMED	5
Comments: ON WALLS.					Sample #:		
479 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3312	2 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
484 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3201	2 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
486 CAD #:	J3F	Miscellaneous Cementitious Material Black Drying Rack	SENIOR HIGH - ROOM 3201	5 Sq Ft	N	25 CH	5
Comments: ON WALL.					Sample #: 011209-MA-10		
493 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3202	4 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT INSIDE WALL.					Sample #:		
494 CAD #:	J3F	Miscellaneous Cementitious Material Black Drying Rack	SENIOR HIGH - ROOM 3202	5 Sq Ft	N	25 CH	5
Comments:					Sample #:		
497 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3203	4 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
499 CAD #:	J1C	Cementitious Panels Sandwich Panels	SENIOR HIGH - 4TH FLOOR SOUTH HALLWAY OUTSIDE ROOMS 3203 & 3204	160 Sq Ft	N	25 CH	5
Comments: ABOVE CEILING.					Sample #:		
500 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3204	3 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
507 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3205	4 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
508 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3206	2 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
512 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3207	3 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
520 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3210	3 Joints	N	35 CH, 20 AM	5
Comments: BEHIND COUNTER AT OUTSIDE WALL.					Sample #:		
523 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1963 Addition	SENIOR HIGH - ROOM 3211	2 Joints	N	35 CH, 20 AM	5
Comments: IN RADIATOR AT OUTER WALL.					Sample #: 450-FC-8		