

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM	5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM
-----------------------------------	--	--

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
14 CAD #:	B1A	Air Cell Pipe Insulation 1930 Original Building	1930 ORIGINAL BUILDING TUNNEL	10 Lin Ft	N	ASSUMED	5
Comments: <u>VISIBLE AT PIPE PENETRATIONS TO CRAWL SPACE. SOME ESTIMATED IN CRAWL SPACE.</u>					Sample #:		
23 CAD #:	X1H	Miscellaneous Material 6" X 6" Brownish Red Quarry Tile System	THROUGHOUT 1954 ADDITION STAIRWELLS	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
26 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 1204	5 Sq Ft	N	ASSUMED	5
Comments: <u>BEHIND WHITEBOARDS.</u>					Sample #:		
37 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1939)	ROOM 2202	20 Sq Ft	N	ASSUMED	5
Comments: <u>BEHIND WHITEBOARDS.</u>					Sample #:		
39 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1101	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
40 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1102	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
41 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1103	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
42 CAD #:	B2C	Millboard Pipe Insulation 1954 Addition	1954 ADDITION 2ND FLOOR HALLWAY 2100	1 Lin Ft	N	5 CH	5
Comments: ABOVE CEILING. AT WALL PENETRATION ABOVE DRINKING FOUNTAIN. INACCESSIBLE TO OBSERVE AND FOR REMOVAL.					Sample #: 2001-1501-MN-4, 5		
43 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2103	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
44 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2104	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
45 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2105	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		