

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM	5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM
-----------------------------------	--	--

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
11 CAD #:	P0A	Fire Doors Wood -1.5 Hr Rating (Warnock Hersey)	BOILER ROOM 1205	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. DOOR TO ROOM 1305.					Sample #:		
23 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1204	40 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
28 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1203	40 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
34 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1202	40 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #: 092712MV-29		
40 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1201	40 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
62 CAD #:	X0C	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1103	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
71 CAD #:	X0H	Miscellaneous Material Red Fire Stop	LIBRARY ELECTRICAL ROOM 1104A	3 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
72 CAD #:	P0C	Fire Doors Wood Jacket -1.5 Hr Rating (Intertek)	LIBRARY ELECTRICAL ROOM 1104A	30 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
74 CAD #:	P0C	Fire Doors Wood Jacket -1.5 Hr Rating (Intertek)	LIBRARY FAN ROOM 1104A	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
75 CAD #:	X0H	Miscellaneous Material Red Fire Stop	LIBRARY FAN ROOM 1104A	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
82 CAD #:	B1A	Air Cell Pipe Insulation	ROOM 1502	20 Lin Ft	N	ASSUMED	5
Comments: INACCESSIBLE. ONE (1) LINE IN WALL FEEDING CUH IN HALLWAY.					Sample #:		
83 CAD #:	B2A	Millboard Pipe Insulation	ROOM 1502	10 Lin Ft	N	20 CH	5
Comments: INACCESSIBLE. ONE (1) LINE IN WALL FEEDING WATER FOUNTAIN IN HALLWAY. WRAP STARTING TO PEEL. NO EXPOSED ACM. MONITOR.					Sample #: 032513JD-01		
84 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation	ROOM 1502	2 Joints	N	15 CH, 5 AM	5
Comments: ABOVE CEILING.					Sample #: 032513JD-02		
87 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1502	10 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARD.					Sample #:		
90 CAD #:	B2A	Millboard Pipe Insulation	ROOM 1502B RESTROOM	10 Lin Ft	N	20 CH	5
Comments: INACCESSIBLE. IN SOUTH WALL (COLD WATER LINE).					Sample #:		
91 CAD #:	B1A	Air Cell Pipe Insulation	ROOM 1502B RESTROOM	10 Lin Ft	N	ASSUMED	5
Comments: INACCESSIBLE. IN SOUTH WALL (HOT WATER LINE).					Sample #:		
93 CAD #:	X1F	Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System	ROOM 1502B RESTROOM	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
96 CAD #:	B1A	Air Cell Pipe Insulation	ROOM 1503 ENTRANCE	20 Lin Ft	N	ASSUMED	5
Comments: INACCESSIBLE. TWO (2) LINES IN WALL FEEDING CUH.					Sample #:		
99 CAD #:	B2A	Millboard Pipe Insulation	ROOM 1504	25 Lin Ft	N	20 CH	5
Comments: INACCESSIBLE. IN WALL BY ENTRANCE & UNDER CABINETS FEEDING SINK.					Sample #:		
100 CAD #:	B1A	Air Cell Pipe Insulation	ROOM 1504	25 Lin Ft	N	ASSUMED	5
Comments: INACCESSIBLE. IN WALL BY ENTRANCE & UNDER CABINETS FEEDING SINK.					Sample #:		
102 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 1504	10 Sq Ft	N	2 CH	5
Comments: BEHIND WHITEBOARD.					Sample #:		
106 CAD #:	X1G	Miscellaneous Material Multi-Sized Blue Ceramic Floor Tile System	ROOM 1504 RESTROOM (1504B)	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
120 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive	ROOM 1304	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
129 CAD #:	X0G	Miscellaneous Material Metal Frame Corkboard Adhesive	ROOM 1303	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
134 CAD #:	P0E	Fire Doors Metal -45/90 Rating (Intertek)	LOADING DOCK 1407	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
150 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2204	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
156 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2203	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
162 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2205	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
170 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2202	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
176 CAD #:	X1I	Miscellaneous Material Black/Brown Marble-Look Countertop	ROOM 2206	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
177 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2206	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
182 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2201	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
189 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive	ROOM 2207	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
191 CAD #:	X1I	Miscellaneous Material Black/Brown Marble-Look Countertop	ROOM 2207	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
198 CAD #:	X1F	Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System	STAFF RESTROOM 2102A	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
201 CAD #:	X1G	Miscellaneous Material Multi-Sized Blue Ceramic Floor Tile System	2ND FLOOR GIRLS' SOUTH RESTROOM	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
204 CAD #:	X1J	Miscellaneous Material Multi-Sized Brown Ceramic Floor Tile System	2ND FLOOR BOYS' SOUTH RESTROOM	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
206 CAD #:	X1K	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System	2ND FLOOR BOYS' SOUTH RESTROOM	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		